

001 - 225

**PATTISON AGRICULTURE LIMITED**

Hwy 5 East, Box 2109
Humboldt, SK S0K 2A0
Phone: (306) 682-2572
Fax: (306) 682-2510
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	

**JOHN DEERE****SERVICE INVOICE**

Deliver To:

Invoice Number: **2582080**
Invoice Date: 2/18/2021
Location: 08
Work Order Number: 337466
Payment Type:
Page: 1 of 8

Bus Phone:
Prv Phone:

Bus Phone:
Prv Phone:

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE S790	1123	1H0S790SLJ0800443	835649	

JGLC JD S790**COMPLAINT:**

01 S SERIES COMBINE VALUEMAX GREEN LIGHT SERVICE INSPECTION CHECKOVER

CORRECTION:

VALUEMAX GREEN LIGHT SELF PROPELLED COMBINE CHECKLIST

HEADER SERIAL # _____
ENGINE HOURS _____
SEPERATOR HOURS _____

DOES THIS UNIT GET A VALUEMAX STICKER __ YES __X__ NO
HAS THE STICKER BEEN INSTALLED __ YES __X__ NO
THIS UNIT HAS HAD THE CAB CLEANED _____ (INITIAL)
THIS UNIT HAS HAD A FINAL CHECKOVER _____ (INITIAL)
THIS UNIT HAS HAD A COMPLETE GREASE JOB __SU____ (INITIAL)

THINGS NOTED BUT NOT REPAIRED ON CUSTOMERS INSTRUCTIONS:

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
TY26860	INSPECTION+ 4 FLUID TEST KIT	1.00	127.24	127.24	\$127.24	N
TY6341	SD POLYUREA GREASE	2.00	5.68	5.68	\$11.36	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
DISI	LAB DISC INTERN	-2.00	541.80	541.80	(\$1,083.60)	N

Labor: \$2,945.00 Parts: \$138.60 OL&M: \$0.00 Misc: (\$1,083.60) Sub-Total: \$2,000.00

JSOFTWARE JD S790**COMPLAINT:**

02 UPDATE ALL CONTROLLER SOFTWARE

CORRECTION:

UPDATED SOFTWARE ON _____ CONTROLLERS.
HAD TO PREFORM THE FOLLOWING CALIBRATIONS.

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED

Hwy 5 East, Box 2109
Humboldt, SK S0K 2A0
Phone: (306) 682-2572
Fax: (306) 682-2510
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351 Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233 Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683 Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302 Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889 Russell, MB (204) 773-2149
Unity, SK (306) 228-2696 Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468 Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572 Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355
Shaunavon, SK (306) 297-2639

**JOHN DEERE**

Deliver To:

SERVICE INVOICE

Bus Phone:	Bus Phone:	Invoice Number:	2582080
Prv Phone:	Prv Phone:	Invoice Date:	2/18/2021
		Location:	08
		Work Order Number:	337466
		Payment Type:	
		Page:	2 of 8

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE S790	1123	1H0S790SLJ0800443	835649	

JSOFTWARE JD S790

Labor: \$310.00 Parts: \$0.00 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$310.00

J10171080 JD S790**COMPLAINT:**

03 REPLACE FEEDERHOUSE CONVEYOR DRIVE CHAIN

CORRECTION:

REMOVED DRIVE CHAIN.
INSTALLED NEW DRIVE CHAIN.
ADJUSTED TO PROPER TENSION.
RAN MACHINE WITH FEEDERHOUSE ENGAGED, RECHECKED AND ADJUSTED
CHAIN AS NECESSARY.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AXE80366	60H@189link FH RH Drive	1.00	226.41	226.41	\$226.41	N
Labor: \$232.50	Parts: \$226.41	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$458.91		

S790F1194908**COMPLAINT:**

04 SHOE PITMAN ARM BEARING, R&RPER SIDE

CORRECTION:

Remove counter weight.
Remove drive arm.
Split drive arm, remove and replace bearing.
Assemble in reverse order.
Test run and check operation.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
-------------	-------------	----------	------------	-----------	----------------	-----------

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
Hwy 5 East, Box 2109
Humboldt, SK S0K 2A0
Phone: (306) 682-2572
Fax: (306) 682-2510
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Deliver To:

Invoice Number:	2582080
Invoice Date:	2/18/2021
Location:	08
Work Order Number:	337466
Payment Type:	
Page:	3 of 8

Bus Phone:
Prv Phone:

Bus Phone:
Prv Phone:

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE S790	1123	1H0S790SLJ0800443	835649	

S790F1194908

AH125975	CHAFFER PITMAN BEARING	4.00	109.55	109.55	\$438.20	N
----------	------------------------	------	--------	--------	----------	---

Labor: \$310.00	Parts: \$438.20	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$748.20
------------------------	------------------------	-------------------------	---------------------	----------------------------

S790F1194903

COMPLAINT:
05 CONCAVE LEVEL, ADJUST

CORRECTION:
Place rotor gearcase in neutral.
Remove rotor covers.
Level concave.

Labor: \$465.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$465.00
------------------------	----------------------	-------------------------	---------------------	----------------------------

JKNIFEFLIP JD S790

COMPLAINT:
06 FLIP OVER CHOPPER KNIFE BANK

CORRECTION:
REMOVE KNIFE BANK.
CLEAN AREA.
INSTALL KNIFE BANK.

Labor: \$116.25	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$116.25
------------------------	----------------------	-------------------------	---------------------	----------------------------

J06172012 JD S790

COMPLAINT:
07 REPLACE POWERCAST SPREADER PLASTIC PADDLES.--ONLY TOP

CORRECTION:

PATTISON AGRICULTURE LIMITED
Hwy 5 East, Box 2109
Humboldt, SK S0K 2A0
Phone: (306) 682-2572
Fax: (306) 682-2510
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: 2582080 Invoice Date: 2/18/2021 Location: 08 Work Order Number: 337466 Payment Type: Page: 4 of 8
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE S790	1123	1H0S790SLJ0800443	835649	

J06172012 JD S790

-REMOVE POWERCAST SPREADER DISKS WITH PLASTIC PADDLES
-REPLACE ONLY TOP PADDLES
-INSTALL BACK ON DISKS

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
H214211	DEFLECTOR	12.00	16.63	16.63	\$199.56	N
Labor: \$310.00		Parts: \$199.56	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$509.56	

J06175004 JD S790

COMPLAINT:
08 REPLACE ACTIVE TAILINGS DRIVE CHAIN.

CORRECTION:
REMOVED SAFETY SHIELDS
REMOVED OLD ACTIVE TAILINGS DRIVE CHAIN.
INSTALLED NEW ACTIVE TAILINGS DRIVE CHAIN.
ADJUSTED CHAIN TO PROPER TENSION.
RAN UNIT, CHECK AND ADJUSTED CHAIN AS NECESSARY.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AXE54619	60@ 114links Rethresher	1.00	241.10	241.10	\$241.10	N
Labor: \$124.00		Parts: \$241.10	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$365.10	

JGEN09-

COMPLAINT:
09 WELD

CORRECTION:
-WELD CRACK ON CLEAN GRAIN ELEVATOR BOOT

Labor: \$153.45	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$153.45
------------------------	----------------------	-------------------------	---------------------	----------------------------

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED

Hwy 5 East, Box 2109
Humboldt, SK S0K 2A0
Phone: (306) 682-2572
Fax: (306) 682-2510
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

**JOHN DEERE****SERVICE INVOICE**

Deliver To:

Bus Phone:
Prv Phone:

Bus Phone:
Prv Phone:

Invoice Number: **2582080**
Invoice Date: 2/18/2021
Location: 08
Work Order Number: 337466
Payment Type:
Page: 5 of 8

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE S790	1123	1H0S790SLJ0800443	835649	

JGEN10-

COMPLAINT:
10 GENERAL REPAIRS

CORRECTION:

-REPLACE ENGINE PRIMARY AIR FILTER
-CLEAN AND CALIBRATE VARIABLE STREAM VANES

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AXE68457	Knob	1.00	216.32	216.32	\$216.32	N
HXE11090	Primary Engine Air Filter	1.00	272.90	272.90	\$272.90	N
JD29980	NEEDLE BEA	2.00	5.64	5.64	\$11.28	N
JD8535	Ball Bearing	1.00	7.94	7.94	\$7.94	N
Labor: \$168.95		Parts: \$508.44	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$677.39	

J10171050 JD S790

COMPLAINT:
11 REPLACE FEEDERHOUSE DRUM

CORRECTION:

REMOVED CONVEYOR CHAIN.
FIX DENT ON A DRUM
REINSTALLED CONVEYOR CHAIN AND ADJUSTED TENSION TO SPEC.
TEST RAN AND RECHECKED TENSION.

Labor: \$195.30	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$195.30
------------------------	----------------------	-------------------------	---------------------	----------------------------

J06171404 JD S790

COMPLAINT:
12 INSTALL WELD IN FEEDERHOUSE FLOOR SHEET

CORRECTION:

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED

Hwy 5 East, Box 2109
Humboldt, SK S0K 2A0
Phone: (306) 682-2572
Fax: (306) 682-2510
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	

**JOHN DEERE****SERVICE INVOICE**

Deliver To:

Bus Phone:

Prv Phone:

Bus Phone:

Prv Phone:

Invoice Number:	2582080
Invoice Date:	2/18/2021
Location:	08
Work Order Number:	337466
Payment Type:	
Page:	6 of 8

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE S790	1123	1H0S790SLJ0800443	835649	

J06171404 JD S790

REMOVED CONVEYOR CHAIN.
REMOVED FRONT DRUM.
INSTALLED FITTED STEEL FLOOR SHEET AND WELD IN PLACE.
ASSEMBLED IN REVERSE ORDER AND MADE ADJUSTMENTS AS NEEDED.
TEST RUN AND CHECKED OPERATION.
RE-ADJUSTED CHAINS AS REQUIRED.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AXE29353	Feeder House Floor 775-	1.00	2,042.48	2,042.48	\$2,042.48	N

Labor: \$1,085.00	Parts: \$2,042.48	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$3,127.48
--------------------------	--------------------------	-------------------------	---------------------	------------------------------

JGEN13-

COMPLAINT:
13 REPLACE BELT TIGHTENER FOR PICKUP HEADER

CORRECTION:
-REPLACE ALL TIGHTENERS WITH NEW
-ADJUST BELTS TENSION

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
14M7299	M12-1.75 FLG NUT	1.00	2.29	2.29	\$2.29	N
19M8219	M12x170 HH 8.8 BOLT	1.00	8.23	8.23	\$8.23	N
H228419	BRACKET	4.00	95.15	95.15	\$380.60	N
M93897	BUSHING	12.00	2.38	2.38	\$28.56	N

Labor: \$620.00	Parts: \$419.68	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$1,039.68
------------------------	------------------------	-------------------------	---------------------	------------------------------

J07171016 JD 615F

COMPLAINT:
14 REPLACE ALL PICKUP BELTS.

CORRECTION:

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
Hwy 5 East, Box 2109
Humboldt, SK S0K 2A0
Phone: (306) 682-2572
Fax: (306) 682-2510
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Deliver To:		Invoice Number: 2582080 Invoice Date: 2/18/2021 Location: 08 Work Order Number: 337466 Payment Type: Page: 7 of 8
Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE S790	1123	1H0S790SLJ0800443	835649	

J07171016 JD 615P

- REMOVE ALL PICK UP BELTS
- CHECK THE ROLLERS, FRONT ROLLER WAS BAND
- REMOVE FRONT ROLLER AND STRAIGHT
- INSTALL BACK ON ROLLER
- REPLACE BEARINGS FOR ROLLER
- INSTALL NEW BELTS AND ADJUST TENSION

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AXE60849	BELT SET	4.00	677.16	677.16	\$2,708.64	N
H216409	WASHER	7.00	7.67	7.67	\$53.69	N
H85934	1/4" X 0.787" SQR NECK BOLT	24.00	0.74	0.74	\$17.76	N
JD9397	BALL BEARI	2.00	66.33	66.33	\$132.66	N



PATTISON AGRICULTURE LIMITED

Hwy 5 East, Box 2109
Humboldt, SK S0K 2A0
Phone: (306) 682-2572
Fax: (306) 682-2510
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351 Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233 Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683 Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302 Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889 Russell, MB (204) 773-2149
Unity, SK (306) 228-2696 Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468 Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572 Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355
Shaunavon, SK (306) 297-2639

**JOHN DEERE****SERVICE INVOICE**

Deliver To:

Bus Phone:	Bus Phone:	Invoice Number: 2582080
Prv Phone:	Prv Phone:	Invoice Date: 2/18/2021
		Location: 08
		Work Order Number: 337466
		Payment Type:
		Page: 8 of 8

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE S790	1123	1H0S790SLJ0800443	835649	

J07171016 JD 615P

N10217 1/4 SERR FLG NUT 6.00 0.84 0.84 \$5.04 N

OL&M Charges:

Description	Value
MOLLENBECK IND INVOICE 09317	\$112.78

Labor: \$496.00 Parts: \$2,917.79 OL&M: \$112.78 Misc: \$0.00 Sub-Total: \$3,526.57

Miscellaneous Charges:

SERVICE ACCESSORIES \$150.00

Customer PO No:
Tax Exempt No:
Advisor: Sheila Lefebvre

Labor: \$7,531.45
Parts: \$7,132.26
OL&M: \$112.78
Misc: (\$933.60)
Grand Total: \$13,842.89

*** DOCUMENT COPY ***

ALL QUOTES ISSUED ARE VALID FOR 7 DAY FROM ISSUE -- MIN \$35 ON EMERGENCY/UNIT DOWN ORDERS -- 25% RESTOCKING FOR RET

TERMS AND CONDITIONS

I hereby authorize the above repair work be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery. I agree to pay cash for such repair parts and labour on delivery of machine(s) or on terms satisfactory to you, and until paid in full, any such unpaid balance shall constitute a lien on this machinery. I further agree that you will not be held responsible for loss or damage to said machinery from fire, theft or other causes beyond your control

Received by: Date:

001 - 225

PATTISON AGRICULTURE LIMITED

Hwy 5 East, Box 2109
Humboldt, SK S0K 2A0
Phone: (306) 682-2572
Fax: (306) 682-2510
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351 Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233 Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683 Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302 Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889 Russell, MB (204) 773-2149
Unity, SK (306) 228-2696 Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468 Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572 Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355
Shaunavon, SK (306) 297-2639



JOHN DEERE

SERVICE INVOICE

Deliver To:

Bus Phone:	Bus Phone:	Invoice Number:	3568654
Prv Phone:	Prv Phone:	Invoice Date:	4/30/2026
		Location:	08
		Work Order Number:	532546
		Payment Type:	
		Page:	1 of 21

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE S790	2579	1H0S790SLJ0800443	835649	

JGLC JD S SERIES ALL

COMPLAINT:

01 S SERIES COMBINE VALUEMAX GREEN LIGHT SERVICE INSPECTION CHECKOVER

CORRECTION:

VALUEMAX GREEN LIGHT SELF PROPELLED COMBINE CHECKLIST

HEADER SERIAL # _____

ENGINE HOURS _____ 2579 _____

SEPERATOR HOURS _____ 1921 _____

DOES THIS UNIT GET A VALUEMAX STICKER _Y_ YES ___ NO


HAS THE STICKER BEEN INSTALLED _Y_ YES ___ NO

THIS UNIT HAS HAD THE CAB CLEANED _____Y_____ (INITIAL)

THIS UNIT HAS HAD A FINAL CHECKOVER _____Y_____ (INITIAL)

THIS UNIT HAS HAD A COMPLETE GREASE JOB _____Y_____ (INITIAL)

THINGS NOTED BUT NOT REPAIRED ON CUSTOMERS INSTRUCTIONS:



Job Total: **\$3,307.00**

JSOFTWARE JD S790

COMPLAINT:

02 UPDATE ALL CONTROLLER SOFTWARE

CORRECTION:

UPDATED SOFTWARE ON _____ CONTROLLERS.

HAD TO PREFORM THE FOLLOWING CALIBRATIONS.

Labor: \$420.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$420.00
-----------------	---------------	--------------	--------------	---------------------

J06171083 JD S790

COMPLAINT:

03 FEEDERHOUSE CONVEYOR DRIVE CHAIN IDLER SPROCKET, REPLACE

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
Hwy 5 East, Box 2109
Humboldt, SK S0K 2A0
Phone: (306) 682-2572
Fax: (306) 682-2510
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		



JOHN DEERE

SERVICE INVOICE

Deliver To:

Invoice Number:	3568654
Invoice Date:	4/30/2026
Location:	08
Work Order Number:	532546
Payment Type:	
Page:	2 of 21

Bus Phone:
Prv Phone:

Bus Phone:
Prv Phone:

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE S790	2579	1H0S790SLJ0800443	835649	

J06171083 JD S790

CORRECTION:
LOOSEN OFF DRIVE CHAIN
REMOVER IDLER, REPLACE
TIGHTEN CHAIN TO SPEC

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AXE19940	IDLER SPRO	1.00	71.77	71.77	\$71.77	N
Labor: \$210.00	Parts: \$71.77	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$281.77		

J06171104 JD S790

COMPLAINT:
04 FEEDERHOUSE BACKSHAFT BEARING, REPLACE

CORRECTION:
-FEEDERHOUSE RH BACKSHAFT BEARING AND TONE WHEEL REPLACE WITH NEW

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AXE68018	BEARING WI	1.00	342.40	342.40	\$342.40	N
Labor: \$315.00	Parts: \$342.40	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$657.40		

J06171152 JD S790

COMPLAINT:
05 REPLACE FEEDERHOUSE CONVEYOR CHAIN WEAR GUIDES.

CORRECTION:
-REPLACE FEEDERHOUSE CONVEYOR CHAIN WEAR GUIDES WITH NEW

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
H171960	FH ConveyChain Return Strip	4.00	32.81	32.81	\$131.24	N
Labor: \$210.00	Parts: \$131.24	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$341.24		

PATTISON AGRICULTURE LIMITED

Hwy 5 East, Box 2109
 Humboldt, SK S0K 2A0
 Phone: (306) 682-2572
 Fax: (306) 682-2510
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

**JOHN DEERE**

Deliver To:

SERVICE INVOICE

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number:	3568654
		Invoice Date:	4/30/2026
		Location:	08
		Work Order Number:	532546
		Payment Type:	
		Page:	3 of 21

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE S790	2579	1H0S790SLJ0800443	835649	

J06171013 JD S790**COMPLAINT:**

06 REPLACE FEEDERHOUSE REVERSER DRIVE BELT

CORRECTION:

-REPLACED FEEDERHOUSE REVERSER DRIVE BELT

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
HXE50398	FH FixedSpd Belt 775-	1.00	928.46	928.46	\$928.46	N
Labor: \$178.50		Parts: \$928.46	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$1,106.96	

J10171050 JD S790**COMPLAINT:**

07 REPLACE FEEDERHOUSE DRUM

CORRECTION:

REMOVED CONVEYOR CHAIN.
 REMOVED AND REPLACED FRONT DRUM.
 REINSTALLED CONVEYOR CHAIN AND ADJUSTED TENSION TO SPEC.
 TEST RAN AND RECHECKED TENSION.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AXE87970	drum	1.00	1,601.31	1,601.31	\$1,601.31	N
Labor: \$840.00		Parts: \$1,601.31	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$2,441.31	

JSHAUGADJUST JD S790**COMPLAINT:**

08 ADJUST SHOE AUGER BACKLASH

CORRECTION:

REMOVE FINAL DRIVE SHAFT IF REQUIRED.
 ADJUST SHOE AUGER BEVEL GEARS TO SPEC.
 RUN UNIT WITH SEPARATOR ENGAGED.
 CHECK AND ADJUST AS REQUIRED.

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED

Hwy 5 East, Box 2109
Humboldt, SK S0K 2A0
Phone: (306) 682-2572
Fax: (306) 682-2510
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351 Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233 Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683 Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302 Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889 Russell, MB (204) 773-2149
Unity, SK (306) 228-2696 Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468 Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572 Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355
Shaunavon, SK (306) 297-2639

**JOHN DEERE****SERVICE INVOICE**

Deliver To:

Invoice Number: **3568654**
Invoice Date: 4/30/2026
Location: 08
Work Order Number: 532546
Payment Type:
Page: 4 of 21

Bus Phone:
Prv Phone:

Bus Phone:
Prv Phone:

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE S790	2579	1H0S790SLJ0800443	835649	

JSHAUGADJUST JD S790

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
M48583	SHAFT KEY	4.00	12.34	12.34	\$49.36	N
Labor: \$283.50		Parts: \$49.36	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$332.86	

J06174180 JD S790

COMPLAINT:

09 REPLACE REAR SHOE AUGER BEARING. (PER ONE) X2

CORRECTION:

REMOVED SHIELDS AND SEPARATOR COVERS.
REMOVED LOCKING COLLAR.
REMOVED BEARING HOLDER AND BEARING.
INSTALLED NEW BEARING.
INSTALLED ALL REMOVED COMPONENTS.
FUNCTION CHECKED.

-REPLACE BEARINGS FOR LH AND RH OUT AUGERS

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
34H119	Spring Pin	2.00	1.38	1.38	\$2.76	N
34H286	3/16x1.5 Spring Pin	2.00	1.16	1.16	\$2.32	N
AH163056	PILLOW BLOCK BRG HOUSING W/ BRG	2.00	75.12	75.12	\$150.24	N
AXE39453	SPERICAL BALL BEARING	2.00	60.76	60.76	\$121.52	N
Labor: \$357.00		Parts: \$276.84	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$633.84	

J10171100 JD S790

COMPLAINT:

10 REPLACE FEEDERHOUSE CONVEYOR CHAIN TOP SHAFT SPROCKETS

CORRECTION:

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED

Hwy 5 East, Box 2109
Humboldt, SK S0K 2A0
Phone: (306) 682-2572
Fax: (306) 682-2510
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351 Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233 Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683 Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302 Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889 Russell, MB (204) 773-2149
Unity, SK (306) 228-2696 Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468 Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572 Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355
Shaunavon, SK (306) 297-2639

**JOHN DEERE****SERVICE INVOICE**

Deliver To:

Bus Phone: Prv Phone:		Invoice Number: 3568654 Invoice Date: 4/30/2026 Location: 08 Work Order Number: 532546 Payment Type: Page: 5 of 21	
--------------------------	--	--	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE S790	2579	1H0S790SLJ0800443	835649	

J10171100 JD S790

REMOVED FEEDERHOUSE SHIELDS.
REMOVED DRIVE BELT.
REMOVED DRIVE CHAIN AND SLIP CLUTCH.
DISCONNECTED CONVEYOR CHAIN.
REMOVED LEFT HAND SIDE PULLEY.
REMOVED FEEDERHOUSE TOP SHAFT.
FLIPPED OR REPLACED TOP SHAFT SPROCKETS.
INSTALLED NEW BEARING IF REQUIRED.
INSTALLED ALL REMOVED COMPONENTS.
ADJUSTED CHAINS AND BELTS.
RAN UNIT FUNCTION AND LEAK CHECKED.
ADJUSTED CHAINS AND BELTS AS REQUIRED.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
11M7032	M5x50 COTTER PIN	1.00	1.00	1.00	\$1.00	N
H156580	SET SCREW	16.00	5.13	5.13	\$82.08	N
H229470	SHAFT KEY	4.00	16.28	16.28	\$65.12	N
HXE123463	FH CONVEYOR CHAIN TOP SPROCKET	4.00	190.60	190.60	\$762.40	N
Labor: \$2,184.00		Parts: \$910.60	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$3,094.60	

J06171030 JD S790

COMPLAINT:
11 REPLACE FEED ACCELERATOR BELT

CORRECTION:
REPLACED FEED ACCELERATOR BELT

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
HXE54503	FEED ACCEL BELT-HI SPEED/CAPACITY	1.00	333.23	333.23	\$333.23	N
Labor: \$327.60		Parts: \$333.23	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$660.83	

J06171002 JD S790

COMPLAINT:

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
Hwy 5 East, Box 2109
Humboldt, SK S0K 2A0
Phone: (306) 682-2572
Fax: (306) 682-2510
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Deliver To:

Invoice Number:	3568654
Invoice Date:	4/30/2026
Location:	08
Work Order Number:	532546
Payment Type:	
Page:	6 of 21

Bus Phone:
Prv Phone:

Bus Phone:
Prv Phone:

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE S790	2579	1H0S790SLJ0800443	835649	

J06171002 JD S790

12 REPLACE FEED ACCELERATOR WING. (EACH) X2

CORRECTION:

-REPLACE TWO FEED ACCELERATOR WING WITH NEW

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
H137329	M12x1.75 Flg DT Lock	1.00	2.96	2.96	\$2.96	N
HXE84113	BEATER WING RH	1.00	329.04	329.04	\$329.04	N
HXE84114	BEATER WING LH	1.00	329.04	329.04	\$329.04	N
L215374	M12x35 CarrSN10.9	1.00	4.77	4.77	\$4.77	N
Labor: \$252.00		Parts: \$665.81	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$917.81	

J10180360 JD S790

COMPLAINT:

13 REPLACE PRIMARY COUNTERSHAFT GEARCASE OIL.

CORRECTION:

DRAINED OIL AND REFILLED WITH NEW 80W90 OIL.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
TY6296	80W90 946ml GL5	2.00	15.85	15.85	\$31.70	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
EF15	ENVIRO FEE	2.00	0.15	0.15	\$0.30	N
Labor: \$231.00		Parts: \$31.70	OL&M: \$0.00	Misc: \$0.30	Sub-Total: \$263.00	

JGEN14-

COMPLAINT:

14 REPLACE FAST SPEED SENSOR

CORRECTION:

PATTISON AGRICULTURE LIMITED
Hwy 5 East, Box 2109
Humboldt, SK S0K 2A0
Phone: (306) 682-2572
Fax: (306) 682-2510
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Deliver To:

Invoice Number:	3568654
Invoice Date:	4/30/2026
Location:	08
Work Order Number:	532546
Payment Type:	
Page:	7 of 21

Bus Phone:
Prv Phone:

Bus Phone:
Prv Phone:

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE S790	2579	1H0S790SLJ0800443	835649	

JGEN14-

-HAVE A CODE F.A.S.T. ZERO SPEED
-REPLACE SPEED SENSOR WITH NEW AND RUN MACHINE

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
14M7264	M4-0.75 NYLOCK NUT	1.00	0.50	0.50	\$0.50	N
AH221249	SENSOR-SHAFT SPEED	1.00	174.77	174.77	\$174.77	N
H232150	M4x20 TRX20 SCREW	1.00	0.86	0.86	\$0.86	N

Labor: \$210.00	Parts: \$176.13	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$386.13
------------------------	------------------------	-------------------------	---------------------	----------------------------

JGEN15-

COMPLAINT:
15 REPLACE BOLT IN SPERATOR FRONT WALL

CORRECTION:
-REPLACE BOLT IN SPERATOR FRONT WALL WITH NEW

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
14M7396	M8-1.25 FLG NYLOCK NUT	2.00	1.67	1.67	\$3.34	N
H174755	M10x30 CB 10.9 SN	2.00	3.50	3.50	\$7.00	N

Labor: \$210.00	Parts: \$10.34	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$220.34
------------------------	-----------------------	-------------------------	---------------------	----------------------------

J06180021 JD S790

COMPLAINT:
16 CONCAVE REPAIR 1.0 HRS PER CONCAVE X2

CORRECTION:
REPAIR CONCAVES AS NEEDED.
(STRAIGHTENING AND WELDING)

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
--------------------	--------------------	-----------------	-------------------	------------------	-----------------------	------------------

PATTISON AGRICULTURE LIMITED

Hwy 5 East, Box 2109
Humboldt, SK S0K 2A0
Phone: (306) 682-2572
Fax: (306) 682-2510
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	

**JOHN DEERE****SERVICE INVOICE**

Deliver To:

Invoice Number:	3568654
Invoice Date:	4/30/2026
Location:	08
Work Order Number:	532546
Payment Type:	
Page:	8 of 21

Bus Phone:
Prv Phone:

Bus Phone:
Prv Phone:

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE S790	2579	1H0S790SLJ0800443	835649	

J06180021 JD S790

AXE28964	ConcaveLgWireRear	1.00	1,574.98	1,574.98	\$1,574.98	N
----------	-------------------	------	----------	----------	------------	---

Labor: \$420.00	Parts: \$1,574.98	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$1,994.98
------------------------	--------------------------	-------------------------	---------------------	------------------------------

J06180261 JD S790**COMPLAINT:**

17 PERFORM FACTORY CALIBRATION AND LEVELING OF ACTIVE CONCAVES.

CORRECTION:

INSTALLED CONCAVES. (ENSURE THAT THE CONCAVES ARE TIGHT TO ONE ANOTHER AND THERE IS ADEQUATE BULKHEAD CLEARANCE)

LEVELED CONCAVES AS PER SERVICE ADVISOR.

PERFORMED CONCAVE CALIBRATION.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
HXE82903	PIN FASTEN	2.00	39.66	39.66	\$79.32	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
FRT	FREIGHT	1.00	35.00	35.00	\$35.00	N

Labor: \$462.00	Parts: \$79.32	OL&M: \$0.00	Misc: \$35.00	Sub-Total: \$576.32
------------------------	-----------------------	-------------------------	----------------------	----------------------------

J06180110 JD S790**COMPLAINT:**

18 REPLACE THRESHING ELEMENTS (3 MATCHED SET)

CORRECTION:

REMOVED CONCAVES AS NECESSARY TO ACCESS ELEMENTS.

REMOVED ELEMENTS AND DISCARDED HARDWARE.

INSTALLED SET OF THREE TO MAINTAIN BALANCE.

INSTALLED NEW ELEMENTS USING NEW HARDWARE.

INSTALLED CONCAVES.

TEST RAN AND CHECKED BALANCE.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
14M7573	M8-1.25 FLG STOVER LOCK NUT	2.00	1.67	1.67	\$3.34	N

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED

Hwy 5 East, Box 2109
Humboldt, SK S0K 2A0
Phone: (306) 682-2572
Fax: (306) 682-2510
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

**JOHN DEERE****SERVICE INVOICE**

Deliver To:

Invoice Number:	3568654
Invoice Date:	4/30/2026
Location:	08
Work Order Number:	532546
Payment Type:	
Page:	9 of 21

Bus Phone:
Prv Phone:

Bus Phone:
Prv Phone:

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE S790	2579	1H0S790SLJ0800443	835649	

J06180110 JD S790

KXE10034	Threshing Element Set STD	1.00	786.13	786.13	\$786.13	N
----------	---------------------------	------	--------	--------	----------	---

Labor: \$409.50	Parts: \$789.47	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$1,198.97
------------------------	------------------------	-------------------------	---------------------	------------------------------

J06180031 JD S790**COMPLAINT:**

19 REBUILD ROTOR VARIABLE SHEAVE PISTON.

CORRECTION:

CLAMPED SHEAVES AND REMOVED PISTON ASSEMBLY. REMOVED O'RINGS, CLEAN ALL COMPONENTS, INSTALL NEW O'RINGS WITH LUBRICANT AND REINSTALL ALL OTHER COMPONENTS.
RUN MACHINE ROTOR SPEED UP AND DOWN.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AHC11303	HydCyl Seal Kit	1.00	152.81	152.81	\$152.81	N
R1225R	O-RING	2.00	5.30	5.30	\$10.60	N

Labor: \$546.00	Parts: \$163.41	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$709.41
------------------------	------------------------	-------------------------	---------------------	----------------------------

J06172030 JD S790**COMPLAINT:**

20 REMOVE AND INSTALL DISCHARGE BEATER BELT.

CORRECTION:

-REPLACE DISCHARGE BEATER BELT WITH NEW AND ADJUST TENSION

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
HXE124870	Discharge Beater 2HC V-Belt	1.00	412.06	412.06	\$412.06	N

Labor: \$252.00	Parts: \$412.06	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$664.06
------------------------	------------------------	-------------------------	---------------------	----------------------------

J06001012 JD S790**COMPLAINT:**

21 REPLACE AFTERTREATMENT BLOWER DRIVE BELT TENSIONER AND IDLER.

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED

Hwy 5 East, Box 2109
Humboldt, SK S0K 2A0
Phone: (306) 682-2572
Fax: (306) 682-2510
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	

**JOHN DEERE**

Deliver To:

SERVICE INVOICE

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: 3568654 Invoice Date: 4/30/2026 Location: 08 Work Order Number: 532546 Payment Type: Page: 10 of 21
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE S790	2579	1H0S790SLJ0800443	835649	

J06001012 JD S790**CORRECTION:**

-AFTERTREATMENT BLOWER DRIVE BELT TENSIONER AND IDLER REPLACE BEARINGS WITH NEW

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
JD8535	Ball Bearing	2.00	9.67	9.67	\$19.34	N
Labor: \$315.00		Parts: \$19.34	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$334.34	

J06172060 JD S790**COMPLAINT:**

22 REPLACE LOWER JACKSHAFT STRAW CHOPPER DRIVE BELT

CORRECTION:

LOOSENED CHOPPER BELT TENSION ADJUSTER.
REMOVED CHOPPER BELT.
INSTALLED ONE NEW BELT AND ADJUSTED TENSION.
RAN UNIT.
ADJUSTED TENSION AS REQUIRED.



Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
HXE124869	LowerChopperDrv 2V-belt	1.00	685.09	685.09	\$685.09	N
Labor: \$409.50		Parts: \$685.09	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$1,094.59	

JKNIFEFLIP JD S790**COMPLAINT:**

23 FLIP OVER CHOPPER STATIONARY KNIFE BANK

CORRECTION:

REMOVE KNIFE BANK.
CLEAN AREA.
INSTALL KNIFE BANK.

PATTISON AGRICULTURE LIMITED

Hwy 5 East, Box 2109
Humboldt, SK S0K 2A0
Phone: (306) 682-2572
Fax: (306) 682-2510
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	

**JOHN DEERE****SERVICE INVOICE**

Deliver To:

Invoice Number:	3568654
Invoice Date:	4/30/2026
Location:	08
Work Order Number:	532546
Payment Type:	
Page:	11 of 21

Bus Phone:
Prv Phone:

Bus Phone:
Prv Phone:

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE S790	2579	1H0S790SLJ0800443	835649	

JKNIFEFLIP JD S790

Labor: \$157.50	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$157.50
-----------------	---------------	--------------	--------------	---------------------


J06172021 JD S790

COMPLAINT:

24 STRAW CHOPPER JACKSHAFT BEARINGS, REPLACE

CORRECTION:

REMOVED SHIELDING.
REMOVED CHOPPER DRIVE BELT.
REMOVED JACKSHAFT DRIVE BELT.
REMOVED JACKSHAFT ASSEMBLY.
REMOVED PULLEYS AND DISASSEMBLED.
CLEANED ALL COMPONENTS.
INSTALLED NEW BEARINGS.
REASSEMBLED JACKSHAFT.
GREASED UNIT.
FUNCTION CHECKED.



Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AH221427	BALL BEARI	1.00	143.81	143.81	\$143.81	N
AH221431	BALL BEARI	1.00	273.31	273.31	\$273.31	N

Labor: \$1,218.00	Parts: \$417.12	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$1,635.12
-------------------	-----------------	--------------	--------------	-----------------------

J06172012 JD S790

COMPLAINT:

25 REPLACE POWERCAST SPREADER PLASTIC PADDLES.

CORRECTION:

REPLACE POWERCAST SPREADER PLASTIC PADDLES ALL UPPER AND LOWER.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
H214211	DEFLECTOR	12.00	19.01	19.01	\$228.12	N

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED

Hwy 5 East, Box 2109
 Humboldt, SK S0K 2A0
 Phone: (306) 682-2572
 Fax: (306) 682-2510
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

**JOHN DEERE****SERVICE INVOICE**

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: 3568654 Invoice Date: 4/30/2026 Location: 08 Work Order Number: 532546 Payment Type: Page: 12 of 21
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE S790	2579	1H0S790SLJ0800443	835649	

J06172012 JD S790

H221044	BLADE	6.00	89.49	89.49	\$536.94	N
H221045	BLADE	6.00	89.49	89.49	\$536.94	N

Labor: \$420.00	Parts: \$1,302.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$1,722.00
------------------------	--------------------------	-------------------------	---------------------	------------------------------

JGEN26-**COMPLAINT:**

26 REPLACE SPREADER RIGHT HAND HUB

CORRECTION:

REPLACE SPREADER RIGHT HAND HUB AND BOTH BOLTS

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
H137328	M8x1.25 FLGDT LOCK NUT	2.00	1.49	1.49	\$2.98	N
HXE144772	Hub	1.00	297.70	297.70	\$297.70	N
HXE92569	M8x50 FLG 12.9 BOLT	2.00	5.89	5.89	\$11.78	N
Labor: \$105.00		Parts: \$312.46	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$417.46	

J06174011 JD S790**COMPLAINT:**

27 REPLACE CHAFFER LOUVERS.

CORRECTION:

REMOVED CHAFFER ACTUATOR.
 REMOVED CHAFFER RETAINERS.
 REMOVED CHAFFER.
 REMOVED LOUVER SPRING RETAINERS.
 REPLACED LOUVER SECTIONS AS REQUIRED.
 REASSEMBLED ALL COMPONENTS.
 CALIBRATED CHAFFER.
 FUNCTION TESTED.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
-------------	-------------	----------	------------	-----------	----------------	-----------

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED

Hwy 5 East, Box 2109
Humboldt, SK S0K 2A0
Phone: (306) 682-2572
Fax: (306) 682-2510
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

**JOHN DEERE****SERVICE INVOICE**

Deliver To:

Invoice Number:	3568654
Invoice Date:	4/30/2026
Location:	08
Work Order Number:	532546
Payment Type:	
Page:	13 of 21

Bus Phone:
Prv Phone:

Bus Phone:
Prv Phone:

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE S790	2579	1H0S790SLJ0800443	835649	

J06174011 JD S790

14M7400	M10-1.5 FLG NYLOCK NUT	1.00	2.39	2.39	\$2.39	N
AH170119	GEN. PURP. ELEC. ADJ. LOUVERS	2.00	63.13	63.13	\$126.26	N

Labor: \$367.50	Parts: \$128.65	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$496.15
------------------------	------------------------	-------------------------	---------------------	----------------------------

JWELD3 JD ALL

COMPLAINT:
28 MISC WELDING. (2HR)

CORRECTION:
REPAIR CHOPPER HOUSING, WELD IN 50MM FLAT BAR, TOUCHUP PAINT.

Labor: \$420.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$420.00
------------------------	----------------------	-------------------------	---------------------	----------------------------

J06174043 JD S790

COMPLAINT:
29 REPLACE FRONT COUNTERSHAFT BELT SET.

CORRECTION:
-REPLACE FRONT COUNTERSHAFT BELT SET AND ADJUST TENSION

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
HXE88564	RH FRONT SEP JACKSHAFT BELT	1.00	391.73	391.73	\$391.73	N

Labor: \$231.00	Parts: \$391.73	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$622.73
------------------------	------------------------	-------------------------	---------------------	----------------------------

J06175004 JD S790

COMPLAINT:
30 REPLACE ACTIVE TAILINGS DRIVE CHAIN.

CORRECTION:

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED

Hwy 5 East, Box 2109
Humboldt, SK S0K 2A0
Phone: (306) 682-2572
Fax: (306) 682-2510
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351 Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233 Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683 Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302 Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889 Russell, MB (204) 773-2149
Unity, SK (306) 228-2696 Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468 Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572 Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355
Shaunavon, SK (306) 297-2639

**JOHN DEERE****SERVICE INVOICE**

Deliver To:

Bus Phone:	Bus Phone:	Invoice Number: 3568654
Prv Phone:	Prv Phone:	Invoice Date: 4/30/2026
		Location: 08
		Work Order Number: 532546
		Payment Type:
		Page: 14 of 21

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE S790	2579	1H0S790SLJ0800443	835649	

J06175004 JD S790

REMOVED SAFETY SHIELDS
REMOVED OLD ACTIVE TAILINGS DRIVE CHAIN.
INSTALLED NEW ACTIVE TAILINGS DRIVE CHAIN.
ADJUSTED CHAIN TO PROPER TENSION.
RAN UNIT, CHECK AND ADJUSTED CHAIN AS NECESSARY.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AXE54619	60@ 114links Rethresher	1.00	264.84	264.84	\$264.84	N
Labor: \$168.00		Parts: \$264.84	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$432.84	

JGEN31-**COMPLAINT:**

31 REPLACE TAILINGS ELEVATOR PADDLE SUPPORT--BROKEN

CORRECTION:

REPLACE TAILINGS ELEVATOR PADDLE SUPPORT--BROKEN.
REPLACE HALF LINKS AND COTTER PIN-WORN

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
11M7015	M3.2x25 COTTER PIN	1.00	0.42	0.42	\$0.42	N
AH166638	CA550HD CONNECTOR LINK	1.00	16.80	16.80	\$16.80	N
AH166639	CA550HD OFFSET LINK	2.00	19.53	19.53	\$39.06	N
AH173906	CA550HD Paddle Link Kit	1.00	88.29	88.29	\$88.29	N
Labor: \$210.00		Parts: \$144.57	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$354.57	

JGEN32-**COMPLAINT:**

32 REPLACE AND CALIBRATE VARIBALE STREAM VANES ACTUATOR

CORRECTION:

-REPLACE VARIBALE STREAM VANES ACTUATOR AND CALIBRATE

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED

Hwy 5 East, Box 2109
Humboldt, SK S0K 2A0
Phone: (306) 682-2572
Fax: (306) 682-2510
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351 Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233 Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683 Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302 Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889 Russell, MB (204) 773-2149
Unity, SK (306) 228-2696 Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468 Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572 Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355
Shaunavon, SK (306) 297-2639

**JOHN DEERE****SERVICE INVOICE**

Deliver To:

Invoice Number: **3568654**
Invoice Date: 4/30/2026
Location: 08
Work Order Number: 532546
Payment Type:
Page: 15 of 21

Bus Phone:
Prv Phone:

Bus Phone:
Prv Phone:

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE S790	2579	1H0S790SLJ0800443	835649	

JGEN32-

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AH170291	ACTUATOR	1.00	1,404.24	1,404.24	\$1,404.24	N
Labor: \$210.00		Parts: \$1,404.24	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$1,614.24	

JENGAIRFIL JD S790

COMPLAINT:
33 REPLACE PRIMARY AND SECONDARY ENGINE AIR FILTERS

CORRECTION:
-REPLACE PRIMARY ENGINE AIR FILTERS WITH NEW

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
HXE11090	Primary Engine Air Filter	1.00	446.48	446.48	\$446.48	N
Labor: \$105.00		Parts: \$446.48	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$551.48	

J06020131 JD S790

COMPLAINT:
34 REMOVE AND INSTALL VACUUM FAN DRIVE BELT.

CORRECTION:
-REMOVE AND INSTALL VACUUM FAN DRIVE BELT
-REPLACE BELT IDLER BEARING WITH NEW

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
HXE38073	Vacuum Fan Drive V-belt	1.00	31.34	31.34	\$31.34	N
JD8535	Ball Bearing	1.00	9.67	9.67	\$9.67	N
Labor: \$126.00		Parts: \$41.01	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$167.01	

JENGOILCHNG JD S790

COMPLAINT:

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
Hwy 5 East, Box 2109
Humboldt, SK S0K 2A0
Phone: (306) 682-2572
Fax: (306) 682-2510
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		



JOHN DEERE

SERVICE INVOICE

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: 3568654 Invoice Date: 4/30/2026 Location: 08 Work Order Number: 532546 Payment Type: Page: 16 of 21
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE S790	2579	1H0S790SLJ0800443	835649	

JENGOILCHNG JD S790

35 REPLACE ENGINE OIL AND FILTER

CORRECTION:

DRAIN ENGINE OIL AND REMOVE FILTER.
 CLEAN AREA.
 INSTALL NEW OIL AND FILTER.
 RUN UNIT AND LEAK CHECK
 ADJUST OIL LEVEL AS REQUIRED.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
RE572785	ENGINE OIL FILTER	1.00	133.36	133.36	\$133.36	N
TY26673	15W40 3.78L Plus-50II CK4/SN	1.00	39.78	39.78	\$39.78	N
TY26679	PLUS-50 II 15W-40 CK4/SN 18.9L PAIL	2.00	183.28	183.28	\$366.56	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
EF100	ENVIRO FEE	1.00	1.25	1.25	\$1.25	N
EF300	ENVIRO FEE	2.00	3.00	3.00	\$6.00	N
EF60	ENVIRO FEE	1.00	0.60	0.60	\$0.60	N
Labor: \$125.00		Parts: \$539.70	OL&M: \$0.00	Misc: \$7.85	Sub-Total: \$672.55	

J10030100 JD S790

COMPLAINT:

36 REPLACE ENGINE FUEL FILTERS

CORRECTION:

REPLACED PRIMARY AND SECONDARY FUEL FILTERS.
 REMOVED AND CLEANED FUEL STRAINER.
 BLED FUEL SYSTEM.
 FUNCTION AND LEAK CHECKED.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
DZ112918	FINAL FUEL FILTER	1.00	239.53	239.53	\$239.53	N

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED

Hwy 5 East, Box 2109
Humboldt, SK S0K 2A0
Phone: (306) 682-2572
Fax: (306) 682-2510
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351 Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233 Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683 Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302 Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889 Russell, MB (204) 773-2149
Unity, SK (306) 228-2696 Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468 Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572 Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355
Shaunavon, SK (306) 297-2639

**JOHN DEERE****SERVICE INVOICE**

Deliver To:

Invoice Number: **3568654**
Invoice Date: 4/30/2026
Location: 08
Work Order Number: 532546
Payment Type:
Page: 17 of 21

Bus Phone:
Prv Phone:

Bus Phone:
Prv Phone:

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE S790	2579	1H0S790SLJ0800443	835649	

J10030100 JD S790

DZ130550	FILTER ELE	1.00	208.76	208.76	\$208.76	N
----------	------------	------	--------	--------	----------	---

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
EF100	ENVIRO FEE	2.00	1.25	1.25	\$2.50	N

Labor: \$168.00 Parts: \$448.29 OL&M: \$0.00 Misc: \$2.50 Sub-Total: \$618.79

J06070005 JD S790

COMPLAINT:
37 REPLACE HYDRAULIC FILTER

CORRECTION:
REPLACE TRANSMISSION FILTER.
REPLACE HYDRO CHARGE FILTER.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AH128449	HYDRAULIC FILTER	1.00	149.47	149.47	\$149.47	N
AXE12964	HYDRAULIC	1.00	180.20	180.20	\$180.20	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
EF100	ENVIRO FEE	1.00	1.25	1.25	\$1.25	N
EF50	ENVIRO FEE	1.00	0.55	0.55	\$0.55	N

Labor: \$105.00 Parts: \$329.67 OL&M: \$0.00 Misc: \$1.80 Sub-Total: \$436.47

JPRODRFILT JD S790

COMPLAINT:
38 REPLACE PRODRIVE HYDRAULIC FILTER

CORRECTION:
- REPLACE RH FRONT CORNER PRODRIVE HYDRAULIC FILTER

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AN207368	Hydro Charge Filter	1.00	197.81	197.81	\$197.81	N

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED

Hwy 5 East, Box 2109
Humboldt, SK S0K 2A0
Phone: (306) 682-2572
Fax: (306) 682-2510
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	

**JOHN DEERE****SERVICE INVOICE**

Deliver To:

Invoice Number:	3568654
Invoice Date:	4/30/2026
Location:	08
Work Order Number:	532546
Payment Type:	
Page:	18 of 21

Bus Phone:
Prv Phone:

Bus Phone:
Prv Phone:

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE S790	2579	1H0S790SLJ0800443	835649	

JPRODRFILT JD S790

N309233	O-RING	1.00	27.74	27.74	\$27.74	N
---------	--------	------	-------	-------	---------	---

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
EF100	ENVIRO FEE	1.00	1.25	1.25	\$1.25	N

Labor: \$52.50	Parts: \$225.55	OL&M: \$0.00	Misc: \$1.25	Sub-Total: \$279.30
-----------------------	------------------------	-------------------------	---------------------	----------------------------

JGEN39-

COMPLAINT:

39 TIGHTEN OIL CLAMPS FOR COOLANT CLAMPS

CORRECTION:

-TIGHTEN ALL CLAMPS FOR COOLANT HOSES CLAMPS
-REPLACE COOLANT SYSTEM EXTENSION TANK

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AT372656	Coolant Surge Tank S-series	1.00	410.01	410.01	\$410.01	N
TY26575	COOL-GARDII 3.78L 50/50 PREMIX	2.00	26.38	26.38	\$52.76	N

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
EF25	ENVIRO FEE	2.00	0.25	0.25	\$0.50	N

Labor: \$210.00	Parts: \$462.77	OL&M: \$0.00	Misc: \$0.50	Sub-Total: \$673.27
------------------------	------------------------	-------------------------	---------------------	----------------------------

J06040070 JD S790

COMPLAINT:

40 REPLACE MASS FLOW IMPACT PLATE.

CORRECTION:

REPLACE MASS FLOW IMPACT PLAT.
REPLACE NYLON WEAR STRIP.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
14M7397	M6-1.0 FLG NYLOCK NUT	2.00	1.13	1.13	\$2.26	N
19M7077	M6x20 HH 8.8 BOLT	2.00	0.89	0.89	\$1.78	N

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED

Hwy 5 East, Box 2109
Humboldt, SK S0K 2A0
Phone: (306) 682-2572
Fax: (306) 682-2510
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351 Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233 Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683 Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302 Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889 Russell, MB (204) 773-2149
Unity, SK (306) 228-2696 Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468 Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572 Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355
Shaunavon, SK (306) 297-2639

**JOHN DEERE****SERVICE INVOICE**

Deliver To:

Bus Phone:	Bus Phone:	Invoice Number: 3568654
Prv Phone:	Prv Phone:	Invoice Date: 4/30/2026
		Location: 08
		Work Order Number: 532546
		Payment Type:
		Page: 19 of 21

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE S790	2579	1H0S790SLJ0800443	835649	

J06040070 JD S790

24M7139	Washer M6.4x18	2.00	0.69	0.69	\$1.38	N
AXE13668	Sensor	1.00	126.77	126.77	\$126.77	N
DZ122933	SCREW	2.00	2.77	2.77	\$5.54	N
HXE18618	SHEET	1.00	163.93	163.93	\$163.93	N

Labor: \$220.50 Parts: \$301.66 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$522.16

JCABFILTER JD S790**COMPLAINT:**

41 REPLACE CAB AIR FILTERS

CORRECTION:

REMOVE CAB AIR FILTERS
CLEAN FILTER HOUSING
INSTALL NEW AIR FILTERS

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
L214634	CabRecirc AirFilter 2/pkg	1.00	50.87	50.87	\$50.87	N
TA32591	Cab FreshAir Filter	1.00	117.71	117.71	\$117.71	N

Labor: \$105.00 Parts: \$168.58 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$273.58

JGEN42-**COMPLAINT:**

42 TIGHTEN 3 PLATES

CORRECTION:

-615 P REPLACE BELTS TIGHT PLATES WITH NEW

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
03M7185	M8x25 CB 8.8 SN	2.00	0.66	0.66	\$1.32	N
14M7298	M8 1 25 FLG NUT	2.00	1.47	1.47	\$2.94	N

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED

Hwy 5 East, Box 2109
Humboldt, SK S0K 2A0
Phone: (306) 682-2572
Fax: (306) 682-2510
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		



JOHN DEERE

SERVICE INVOICE

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: 3568654 Invoice Date: 4/30/2026 Location: 08 Work Order Number: 532546 Payment Type: Page: 20 of 21
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE S790	2579	1H0S790SLJ0800443	835649	

JGEN42-

H228419	BRACKET	3.00	117.40	117.40	\$352.20	N
M93897	BUSHING	12.00	3.20	3.20	\$38.40	N

Labor: \$525.00	Parts: \$394.86	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$919.86
-----------------	-----------------	--------------	--------------	---------------------

J07180010 JD 615P
COMPLAINT:

43 REMOVE AND INSTALL AUGER DRIVE CHAIN.

CORRECTION:

LOOSENE CHAIN TENSION.
REMOVED DRIVE CHAIN AND REMOVE LINK.
INSTALLED DRIVE CHAIN.
ADJUSTED CHAIN TENSION.
RAN UNIT AND FUNCTION CHECKED.
READJUSTED CHAIN TENSION AS REQUIRED.

Labor: \$310.80	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$310.80
-----------------	---------------	--------------	--------------	---------------------

JGEN44-
COMPLAINT:

44 DIAGNOSE CODE RCI 523616.04

CORRECTION:

-HAVE A CODE CODE RCI 523616.04 DISCHARGE BEATER SPEED SENSOR
-CHECK WIRES FOR SENSOR
-REPLACE SENSOR WITH NEW

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
-------------	-------------	----------	------------	-----------	----------------	-----------

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
Hwy 5 East, Box 2109
Humboldt, SK S0K 2A0
Phone: (306) 682-2572
Fax: (306) 682-2510
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Deliver To:

Invoice Number:	3568654
Invoice Date:	4/30/2026
Location:	08
Work Order Number:	532546
Payment Type:	
Page:	21 of 21

Bus Phone:
Prv Phone:

Bus Phone:
Prv Phone:

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE S790	2579	1H0S790SLJ0800443	835649	

JGEN44-

AH221249	SENSOR-SHAFT SPEED	1.00	174.77	174.77	\$174.77	N
----------	--------------------	------	--------	--------	----------	---

Labor: \$218.40	Parts: \$174.77	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$393.17
------------------------	------------------------	-------------------------	---------------------	----------------------------

Miscellaneous Charges:
SERVICE ACCESSORIES

\$150.00

Customer PO No:
Tax Exempt No:
Advisor: Sheila Lefebvre

Job Total: \$35,478.81
Grand Total: \$35,478.81

*** DOCUMENT COPY ***

ALL QUOTES ISSUED ARE VALID FOR 7 DAY FROM ISSUE -- MIN \$35 ON EMERGENCY/UNIT DOWN ORDERS -- 25% RESTOCKING FOR RET

TERMS AND CONDITIONS

I hereby authorize the above repair work be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery. I agree to pay cash for such repair parts and labour on delivery of machine(s) or on terms satisfactory to you, and until paid in full, any such unpaid balance shall constitute a lien on this machinery. I further agree that you will not be held responsible for loss or damage to said machinery from fire, theft or other causes beyond your control

Received by: Date: