

001-226



PATTISON AGRICULTURE LIMITED
 Hwy 21 North, Box 1810
 Maple Creek, SK S0N 1N0
 Phone: (306) 662-2233
 Fax: (306) 662-3049
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351 Yorkton, SK (306) 783-9459
 Maple Creek, SK (306) 662-2233 Balcarres, SK (306) 334-2492
 Kindersley, SK (306) 463-2683 Moosomin, SK (306) 435-3301
 Kyle, SK (306) 375-2302 Preeceville, SK (306) 547-2007
 Leader, SK (306) 628-3889 Russell, MB (204) 773-2149
 Unity, SK (306) 228-2696 Wynyard, SK (306) 554-2536
 North Battleford, SK (306) 445-4468 Kamsack, SK (306) 542-2814
 Humboldt, SK (306) 682-2572 Swan River, MB (204) 734-3466
 Kelvington, SK (306) 327-4355
 Shaunavon, SK (306) 297-2639



JOHN DEERE

SERVICE INVOICE

Deliver To:

Bus Phone:	Bus Phone:	Invoice Number: 3534102
Prv Phone:	Prv Phone:	Invoice Date: 2/3/2026
		Location: 02
		Work Order Number: 520698
		Payment Type:
		Page: 1 of 18

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE S780	460	1H0S780SPRT831400	263013	

JGLC JD S SERIES ALL

COMPLAINT:

01 S SERIES COMBINE VALUEMAX GREEN LIGHT SERVICE INSPECTION CHECKOVER

CORRECTION:

VALUEMAX GREEN LIGHT SELF PROPELLED COMBINE CHECKLIST

HEADER SERIAL # _____

ENGINE HOURS _____ 460 _____

SEPERATOR HOURS _____
*****DOES THIS UNIT GET A VALUEMAX STICKER ☒ YES ☐ NOHAS THE STICKER BEEN INSTALLED ☒ YES ☐ NO

THIS UNIT HAS HAD THE CAB CLEANED _____ COREY _____ (INITIAL)

THIS UNIT HAS HAD A FINAL CHECKOVER _____ MT _____ (INITIAL)

THIS UNIT HAS HAD A COMPLETE GREASE JOB _____ MT _____ (INITIAL)

THINGS NOTED BUT NOT REPAIRED ON CUSTOMERS INSTRUCTIONS:

VMC IN SEASON OF USE 2026

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
TY26860	INSPECTION+ 4 FLUID TEST KIT	1.00	125.67	0.00	\$0.00	N
TY6341	SD POLYUREA GREASE	2.00	10.76	10.76	\$21.52	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
DISI	LAB DISC INTERN	-1.00	1,229.52	1,229.52	(\$1,229.52)	N
Labor: \$4,515.00		Parts: \$21.52	OL&M: \$0.00	Misc: (\$1,229.52)	Sub-Total: \$3,307.00	

JWASH1 JD ALL

COMPLAINT:

02 WASH USED COMBINE. READY FOR DISPLAY.

WASH / BLOW OUT COOLER PACKAGES

WASHING REQUIRED TO PERFORM INSPECTION

CLEAN OUT UNLOAD AUGER SUMP

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED

Hwy 21 North, Box 1810
 Maple Creek, SK S0N 1N0
 Phone: (306) 662-2233
 Fax: (306) 662-3049
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	

**JOHN DEERE****SERVICE INVOICE**

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: 3534102 Invoice Date: 2/3/2026 Location: 02 Work Order Number: 520698 Payment Type: Page: 2 of 18
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE S780	460	1H0S780SPRT831400	263013	

JWASH1 JD ALL

CORRECTION:

Labor: \$358.16	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$358.16
-----------------	---------------	--------------	--------------	---------------------

JSOFTWARE JD S780

COMPLAINT:

03 UPDATE ALL CONTROLLER SOFTWARE

CORRECTION:

updated software on all controllers

Labor: \$420.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$420.00
-----------------	---------------	--------------	--------------	---------------------

JELECDIAG2 JD ALL

COMPLAINT:

05 LC2 522097.12 Spreader System Problem - Left shroud failed to return to initial position during cleanout operation, possibly due to material buildup. Check for proper shroud movement and perform shroud calibration.

GRAIN QUALITY MONITOR CODE

CORRECTION:

removed rear cover
 removed motor for shroud
 cleaned out
 reinstalled
 calibrated unit
 code went away
 installed cover
 glm code has not come back

Labor: \$217.40	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$217.40
-----------------	---------------	--------------	--------------	---------------------

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
Hwy 21 North, Box 1810
Maple Creek, SK S0N 1N0
Phone: (306) 662-2233
Fax: (306) 662-3049
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Deliver To:

		Invoice Number:	3534102
		Invoice Date:	2/3/2026
		Location:	02
		Work Order Number:	520698
		Payment Type:	t
		Page:	3 of 18
Bus Phone:	Bus Phone:		
Prv Phone:	Prv Phone:		

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE S780	460	1H0S780SPRT831400	263013	

JGEN02-

COMPLAINT:

06 MISC REPAIRS:

FRONT PLASTIC TOP COVER BROKEN .50
LINE RUBBING ON HYDRAULIC STACK, INSTALL GUARD .50
SHROUD MOVEMENT COVER NEEDS NEW WEATHER STRIP .50
REPAIR BROKEN CONNECTOR ON CONCAVE POSITION SENSOR 1.0
AIR INTAKE PIPE ABOUT TO FALL OFF .50

NOTE: REAR OF ROTOR MAKING NOISE, PREVIOUS ISSUE AND WAS NEVER FIXED

CORRECTION:

replaced front cover
installed gaurd on hose
replaced broken connector on concaves
installed intake pipe on further and tightened clamp

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
57M9786	Housing 6pin Male Red Tyco	1.00	11.39	11.39	\$11.39	N
HXE13354	DEFLECTOR MLPF	1.00	308.61	308.61	\$308.61	N
Z68980	Weatherstrip	1.00	139.35	139.35	\$139.35	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
EF100	ENVIRO FEE	1.00	1.25	1.25	\$1.25	N

Labor: \$568.06	Parts: \$459.35	OL&M: \$0.00	Misc: \$1.25	Sub-Total: \$1,028.66
------------------------	------------------------	-------------------------	---------------------	------------------------------

EXPERT-1000000279262

COMPLAINT:

07 REPLACE FEEDER HOUSE DRIVE CHAIN AND PLASTIC GUIDES

CORRECTION:

removed drive chain
removed and replaced plastic guides
replaced with new chain
installed half link
tightened chain

PATTISON AGRICULTURE LIMITED

Hwy 21 North, Box 1810
 Maple Creek, SK S0N 1N0
 Phone: (306) 662-2233
 Fax: (306) 662-3049
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351 Yorkton, SK (306) 783-9459
 Maple Creek, SK (306) 662-2233 Balcarres, SK (306) 334-2492
 Kindersley, SK (306) 463-2683 Moosomin, SK (306) 435-3301
 Kyle, SK (306) 375-2302 Preeceville, SK (306) 547-2007
 Leader, SK (306) 628-3889 Russell, MB (204) 773-2149
 Unity, SK (306) 228-2696 Wynyard, SK (306) 554-2536
 North Battleford, SK (306) 445-4468 Kamsack, SK (306) 542-2814
 Humboldt, SK (306) 682-2572 Swan River, MB (204) 734-3466
 Kelvington, SK (306) 327-4355
 Shaunavon, SK (306) 297-2639

**JOHN DEERE**

Deliver To:

SERVICE INVOICE

Invoice Number: 3534102 Invoice Date: 2/3/2026 Location: 02 Work Order Number: 520698 Payment Type: Page: 4 of 18	
Bus Phone: Prv Phone:	Bus Phone: Prv Phone:

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE S780	460	1H0S780SPRT831400	263013	

EXPERT-1000000279262

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AXE80368	FH Drv 60H@181 llinks	1.00	330.29	330.29	\$330.29	N
HXE47183	GUIDE	1.00	103.50	103.50	\$103.50	N
HXE47186	GUIDE	1.00	63.41	63.41	\$63.41	N
SW60HCOUS	60H Chain Connector Link	2.00	10.09	10.09	\$20.18	N
SW60OLUS	60 Chain Offset Link	2.00	12.10	12.10	\$24.20	N
Labor: \$252.00		Parts: \$541.58	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$793.58	

J06171153 JD S780**COMPLAINT:**

08 REPLACE FEEDERHOUSE CONVEYOR CHAIN AND PLASTIC GUIDES.
 CHAIN DROVE CROOKED AND STRETCHED BAD
 REPLACE FEEDER HOUSE TOP SHAFT SPROCKETS (WORN DUE TO CROOKED CHAIN), BEARINGS AND KEYS

CORRECTION:

removed front shield
 loosened feederhouse chain and removed
 removed bottom curved feed plate
 loosened drive sprockets
 removed drive clutch
 removed bearings and lifted shaft out
 replaced sprockets, and keyways and bearings
 installed shaft and tightened bearings
 installed clutch
 installed feederhouse chain
 set sprockets
 tightened chain and turned over and checked again

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AH220541	CA557 conn link	4.00	24.59	24.59	\$98.36	N
AXE27247	4-CHAIN FEEDER CHAIN S-SER 775001-	1.00	3,833.72	3,833.72	\$3,833.72	N
H171960	FH ConveyChain Return Strip	4.00	42.12	42.12	\$168.48	N

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
Hwy 21 North, Box 1810
Maple Creek, SK S0N 1N0
Phone: (306) 662-2233
Fax: (306) 662-3049
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number:	3534102
		Invoice Date:	2/3/2026
		Location:	02
		Work Order Number:	520698
		Payment Type:	
		Page:	5 of 18

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE S780	460	1H0S780SPRT831400	263013	

J06171153 JD S780

H229470	SHAFT KEY	4.00	20.89	20.89	\$83.56	N
HXE123463	FH CONVEYOR CHAIN TOP SPROCKET	4.00	244.67	244.67	\$978.68	N
JD10020	BALL BEARING	1.00	67.26	67.26	\$67.26	N
JD9373	BALL BEARING	1.00	68.20	68.20	\$68.20	N

Labor: \$1,785.00	Parts: \$5,298.26	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$7,083.26
--------------------------	--------------------------	-------------------------	---------------------	------------------------------

EXPERT-1000000020214

COMPLAINT:

09 STONE TRAP DOOR, REMOVE AND REPLACE
DAMAGED, NOT FIXABLE, REPLACE COVER. WILL NOT OPEN

CORRECTION:

Open stone trap door and remove pins.
Remove door.
Install new door.
Reinstall pins.
Install new cotter pins.



Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
11M7030	M5x40 COTTER PIN	2.00	1.04	1.04	\$2.08	N
AH223286	DOOR ML	1.00	1,361.98	1,361.98	\$1,361.98	N
AXE63441	BRACKET	1.00	641.66	641.66	\$641.66	N
H118068	PIN FASTEN	2.00	65.56	65.56	\$131.12	N
HXE113298	Linkage	1.00	58.22	58.22	\$58.22	N

Labor: \$315.00	Parts: \$2,195.06	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$2,510.06
------------------------	--------------------------	-------------------------	---------------------	------------------------------

EXPERT-1000000088576

COMPLAINT:

10 REPLACE TOP DOOR SEALS AND REPAIR DOOR

PATTISON AGRICULTURE LIMITED
Hwy 21 North, Box 1810
Maple Creek, SK S0N 1N0
Phone: (306) 662-2233
Fax: (306) 662-3049
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: 3534102 Invoice Date: 2/3/2026 Location: 02 Work Order Number: 520698 Payment Type: Page: 6 of 18
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE S780	460	1H0S780SPRT831400	263013	

EXPERT-1000000088576

CORRECTION:

replaced damaged doors and swapped seal to new

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AH160360	CHANNEL	1.00	438.91	438.91	\$438.91	N
Labor: \$210.00		Parts: \$438.91	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$648.91	

JHOSEREPLACE JD ALL

COMPLAINT:

11 WORN CONTOUR MASTER HOSES AXE47237, AXE47236

HYDRAULIC STACK VALVE - LINE RUBBING, INSTALL GUARD

CORRECTION:

NOTE HOSE PART NUMBERS WHEN REPLACING HOSE(S).

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
X1JS43-4-4	-4fFF SlideNeck	2.00	21.02	21.02	\$42.04	N
X1JS43-6-4	-6fFF slideneck	2.00	19.68	19.68	\$39.36	N
X487-4-RL	-4 HOSE (1/4") 4000 PSI	203.00	0.59	0.59	\$119.77	N
Labor: \$315.00		Parts: \$201.17	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$516.17	

JGEN03-

COMPLAINT:

12 RIGHT SIDE DRIVE HAS A SPLINE ISSUE, REMOVE AND INSPECT

CORRECTION:

after further inspection, no issue was found but better safe than sorry

Labor: \$82.89	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$82.89
-----------------------	----------------------	-------------------------	---------------------	---------------------------

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
Hwy 21 North, Box 1810
Maple Creek, SK S0N 1N0
Phone: (306) 662-2233
Fax: (306) 662-3049
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: 3534102 Invoice Date: 2/3/2026 Location: 02 Work Order Number: 520698 Payment Type: Page: 7 of 18
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE S780	460	1H0S780SPRT831400	263013	

J06001001 JD S690

COMPLAINT:
13 TOP UP ALL FLUIDS.

FINAL DRIVES
COOLANT LOW
WASHER FLUID

CORRECTION:
topped up finals
topped up coolant
topped up washer fluid

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
TY27865	Windshield Washer Fluid	1.00	9.27	9.27	\$9.27	N
TY27928	Winter Fuel Conditioner 946ml	1.00	34.11	34.11	\$34.11	N
Labor: \$100.00		Parts: \$43.38	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$143.38	

J01001510 JD 9470R

COMPLAINT:
14 TORQUE ALL WHEEL HARDWARE

CORRECTION:

Labor: \$210.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$210.00
-----------------	---------------	--------------	--------------	---------------------

J06171001 JD S780

COMPLAINT:
15 REPLACE ALL FEED ACCELERATOR WINGS - 6 WINGS BENT

CORRECTION:

PATTISON AGRICULTURE LIMITED
Hwy 21 North, Box 1810
Maple Creek, SK S0N 1N0
Phone: (306) 662-2233
Fax: (306) 662-3049
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: 3534102 Invoice Date: 2/3/2026 Location: 02 Work Order Number: 520698 Payment Type: Page: 8 of 18
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE S780	460	1H0S780SPRT831400	263013	

J06171001 JD S780

REMOVED ALL WEAR STRIPS.
 REMOVED ALL WINGS.
 INSTALLED ALL NEW WINGS.
 TORQUED ALL BOLTS TO SPEC.
 INSTALLED WEAR STRIPS ONTO WINGS.
 TIGHTENED BOLTS TO SPEC.
 TEST RAN OPERATION.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
HXE84113	BEATER WING RH	4.00	306.08	306.08	\$1,224.32	N
HXE84114	BEATER WING LH	4.00	306.08	306.08	\$1,224.32	N
L215374	M12x35 CarrSN10.9	6.00	4.99	4.99	\$29.94	N
Labor: \$1,050.00		Parts: \$2,478.58	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$3,528.58	

J06040002 JD S780

COMPLAINT:
 16 REPLACE BATTERIES - 12.5V 850 CCA
 12.5V 830CCA
 BATTERIES MAY NEED TO BE CHANGED, CHARGE AND RETEST

CORRECTION:
 REMOVED SHIELD.
 PUT CHARGER ON BATTERIES
 REMOVED BATTERY CONNECTIONS
 TESTED BATTERIES AND THEY TESTED 1250CCA AFTER CHARGE
 BATTERIES GOOD
 NO NEED TO REPLACE

Labor: \$63.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$63.00
-----------------------	----------------------	-------------------------	---------------------	---------------------------

J10180360 JD S780

COMPLAINT:
 18 REPLACE PRIMARY COUNTERSHAFT GEARCASE OIL.

PATTISON AGRICULTURE LIMITED

Hwy 21 North, Box 1810
 Maple Creek, SK S0N 1N0
 Phone: (306) 662-2233
 Fax: (306) 662-3049
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

**JOHN DEERE****SERVICE INVOICE**

Deliver To:

Bus Phone: Prv Phone:		Invoice Number: 3534102 Invoice Date: 2/3/2026 Location: 02 Work Order Number: 520698 Payment Type: Page: 9 of 18	

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE S780	460	1H0S780SPRT831400	263013	

J10180360 JD S780

CORRECTION:

DRAINED OIL AND REFILLED WITH NEW OIL.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
TY6296	80W90 946ml GL5	2.00	15.99	15.99	\$31.98	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
EF15	ENVIRO FEE	2.00	0.15	0.15	\$0.30	N
Labor: \$110.00		Parts: \$31.98	OL&M: \$0.00	Misc: \$0.30	Sub-Total: \$142.28	

JSUNNY JD S780

COMPLAINT:

19 INSTALL SUNNY BROOK CONCAVES - REPLACE MISSING HARDWARE,
 MISSING 1 SUNNYBROOK HANGER, LEVEL AND CALIBRATE

CORRECTION:

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
14M7296	M10-1.5 FLG NUT	9.00	2.16	2.16	\$19.44	N
19M7786	M10x30 FLG 10.9 BOLT	7.00	2.58	2.58	\$18.06	N
19M7835	M10x35 FLG 10.9 BOLT	2.00	0.72	0.72	\$1.44	N
HXE82903	PIN FASTEN	2.00	36.89	36.89	\$73.78	N
SBJ07PC	STS PIN AND CLIP SET (SINGLE)	1.00	15.75	15.75	\$15.75	N
Labor: \$882.00		Parts: \$128.47	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$1,010.47	

J06001020 JD S780

COMPLAINT:

20 ENGINE DEBRIS MANAGEMENT AIR FILTERS, REPLACE

CORRECTION:

PATTISON AGRICULTURE LIMITED
Hwy 21 North, Box 1810
Maple Creek, SK S0N 1N0
Phone: (306) 662-2233
Fax: (306) 662-3049
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Deliver To:

Bus Phone:	Bus Phone:	Invoice Number: 3534102
Prv Phone:	Prv Phone:	Invoice Date: 2/3/2026
		Location: 02
		Work Order Number: 520698
		Payment Type:
		Page: 10 of 18

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE S780	460	1H0S780SPRT831400	263013	

J06001020 JD S780

REMOVED AIR FILTERS.
CLEANED FILTER HOUSING AND COVER.
INSTALLED NEW FILTERS.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AXE42065	DMS Secondary Air Filter	1.00	155.14	155.14	\$155.14	N
AXE42066	DMS Primary Air Filter	1.00	242.92	242.92	\$242.92	N
Labor: \$50.00		Parts: \$398.06	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$448.06	

J06172010 JD S780

COMPLAINT:
21 REPLACE CHOPPER HAMMERS.

CORRECTION:
REMOVED SHIELD TO ACCESS HAMMERS EASIER
REMOVED OLD HAMMERS AND INSTALLED NEW HAMMERS, TORQUED TO SPEC
REINSTALLED SHIELD

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
KXE10255	Fine Cut Chopper Blade kit S-series	6.00	361.04	361.04	\$2,166.24	N
Labor: \$651.00		Parts: \$2,166.24	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$2,817.24	

JKNIFEFLIP JD S780

COMPLAINT:
22 REPLACE CHOPPER STATIONARY KNIFE BANK, MISSING 2 M8 BOLTS AND NUTS ON CHOPPER HOUSING

CORRECTION:
REMOVE KNIFE BANK.
CLEAN AREA.
INSTALL KNIFE BANK.
installed missing bolts in housing

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
-------------	-------------	----------	------------	-----------	----------------	-----------

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED

Hwy 21 North, Box 1810
 Maple Creek, SK S0N 1N0
 Phone: (306) 662-2233
 Fax: (306) 662-3049
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

**JOHN DEERE****SERVICE INVOICE**

Deliver To:

Invoice Number:	3534102
Invoice Date:	2/3/2026
Location:	02
Work Order Number:	520698
Payment Type:	
Page:	11 of 18

Bus Phone:
 Prv Phone:

Bus Phone:
 Prv Phone:

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE S780	460	1H0S780SPRT831400	263013	

JKNIFEFLIP JD S780

H215004	CHOPPER STATIONARY BLADES	39.00	16.66	16.66	\$649.74	N
---------	---------------------------	-------	-------	-------	----------	---

Labor: \$210.00	Parts: \$649.74	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$859.74
------------------------	------------------------	-------------------------	---------------------	----------------------------

JADJPADCHAIN JD S780**COMPLAINT:**

24 ADJUST TAILINGS ELEVATOR PADDLE CHAIN

CORRECTION:

tried to adjust chain
 had to removed half link
 removed belt and turned over until i could see link
 removed link
 set chain

Labor: \$105.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$105.00
------------------------	----------------------	-------------------------	---------------------	----------------------------

J06001201 JD S780**COMPLAINT:**

25 ADJUST CLEAN GRAIN ELEVATOR PADDLE CHAIN AND REMOVE HALF LINK.

CORRECTION:

REMOVE HALF LINK (IF REQUIRED) AND ADJUST CLEAN GRAIN ELEVATOR PADDLE CHAIN.
 TURN CHAIN UNTIL CONNECTING LINK IS VISIBLE.
 DISCONNECT CONNECTING LINK. REMOVE HALF LINK.
 RECONNECT CONNECTING LINK.
 ADJUST TENSION TO SPEC.
 RUN UNIT AND READJUST TENSION AS REQUIRED.

Labor: \$105.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$105.00
------------------------	----------------------	-------------------------	---------------------	----------------------------

J06030050 JD S780**COMPLAINT:**

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED

Hwy 21 North, Box 1810
 Maple Creek, SK S0N 1N0
 Phone: (306) 662-2233
 Fax: (306) 662-3049
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

**JOHN DEERE****SERVICE INVOICE**

Deliver To:

		Invoice Number:	3534102
		Invoice Date:	2/3/2026
		Location:	02
		Work Order Number:	520698
		Payment Type:	
Bus Phone:	Bus Phone:	Page:	12 of 18
Prv Phone:	Prv Phone:		

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE S780	460	1H0S780SPRT831400	263013	

J06030050 JD S780

26 REBUILD ROTARY SCREEN JACKSHAFT ASSEMBLY - JACKSHAFT BAD, REPLACE BEARINGS

CORRECTION:

REMOVED PULLEY, USED A PULLER TO GET OFF
 REMOVED BEARING MOUNT BOLTS, HAD TO REMOVE ANOTHER SHIELD TO GET TO THEM
 WENT TO OTHER SIDE AND REMOVED BELT OFF PULLEY
 PULLEY WAS STUCK ON, HAD TO HAMMER OFF PULLEY COULD NOT GET PULLER ON
 REMOVED BEARING SET SCREWS AND PULLED OLD SHAFT OUT
 INSTALLED NEW SHAFT
 PUT LOCTITE ON BEARING SET SCREWS TO AVOID THEM COMING LOOSE AGAIN
 REINSTALLED PULLEY AND BELT
 INSTALLED PULLEY ON OTHER SIDE AND BELT

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
19M7798	M8x40 FLG 10.9 BOLT	1.00	2.91	2.91	\$2.91	N
AXE70716	Bearing with Housing	1.00	144.84	144.84	\$144.84	N
HXE140222	RtyScreen Jackshaft MLPF	1.00	677.25	677.25	\$677.25	N
Labor: \$892.50		Parts: \$825.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$1,717.50	

J10030100 JD S780

COMPLAINT:

27 REPLACE ENGINE FUEL FILTERS AND FUEL TANK VENT

CORRECTION:

REPLACED PRIMARY AND SECONDARY FUEL FILTERS.
 REMOVED AND CLEANED FUEL STRAINER.
 BLED FUEL SYSTEM.
 FUNCTION AND LEAK CHECKED.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
DZ112918	FINAL FUEL FILTER	1.00	247.52	247.52	\$247.52	N
DZ130550	Filter Element	1.00	243.60	243.60	\$243.60	N

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED

Hwy 21 North, Box 1810
 Maple Creek, SK S0N 1N0
 Phone: (306) 662-2233
 Fax: (306) 662-3049
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	

**JOHN DEERE****SERVICE INVOICE**

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: 3534102 Invoice Date: 2/3/2026 Location: 02 Work Order Number: 520698 Payment Type: Page: 13 of 18
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE S780	460	1H0S780SPRT831400	263013	

J10030100 JD S780

H216169	BREATHER	1.00	43.28	43.28	\$43.28	N
---------	----------	------	-------	-------	---------	---

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
EF100	ENVIRO FEE	2.00	1.25	1.25	\$2.50	N

Labor: \$120.00	Parts: \$534.40	OL&M: \$0.00	Misc: \$2.50	Sub-Total: \$656.90
------------------------	------------------------	-------------------------	---------------------	----------------------------

J10030113 JD S780

COMPLAINT:

28 REPLACE DEF TANK VENT, AND DEF DOSING FILTER, DEF HEADER FILTER

CORRECTION:

REPLACED DEF BREATHER
 REMOVED OLD DEF FILTER
 INSTALLED NEW ONE

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
DZ114640	Def Dosing Pump Filter	1.00	215.23	215.23	\$215.23	N
H216169	BREATHER	1.00	43.28	43.28	\$43.28	N

Labor: \$90.00	Parts: \$258.51	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$348.51
-----------------------	------------------------	-------------------------	---------------------	----------------------------

JENGOILCHNG JD S780

COMPLAINT:

29 REPLACE ENGINE OIL AND FILTER

CORRECTION:

DRAIN ENGINE OIL AND REMOVE FILTER.
 CLEAN AREA.
 INSTALL NEW OIL AND FILTER.
 RUN UNIT AND LEAK CHECK
 ADJUST OIL LEVEL AS REQUIRED.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
RE572785	ENGINE OIL FILTER	1.00	137.80	137.80	\$137.80	N

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED

Hwy 21 North, Box 1810
 Maple Creek, SK S0N 1N0
 Phone: (306) 662-2233
 Fax: (306) 662-3049
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

**JOHN DEERE**

Deliver To:

SERVICE INVOICE

		Invoice Number:	3534102
		Invoice Date:	2/3/2026
		Location:	02
		Work Order Number:	520698
		Payment Type:	
Bus Phone:	Bus Phone:	Page:	14 of 18
Prv Phone:	Prv Phone:		

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE S780	460	1H0S780SPRT831400	263013	

JENGOILCHNG JD S780

TY26675	PLUS-50 II 15W-40 CK4/SN JUG 9.46L	1.00	89.73	89.73	\$89.73	N
TY26679	PLUS-50 II 15W-40 CK4/SN 18.9L PAIL	2.00	170.86	170.86	\$341.72	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
EF100	ENVIRO FEE	1.00	1.25	1.25	\$1.25	N
EF150	ENVIRO FEE	1.00	1.50	1.50	\$1.50	N
EF300	ENVIRO FEE	2.00	3.00	3.00	\$6.00	N

Labor: \$125.00 Parts: \$569.25 OL&M: \$0.00 Misc: \$8.75 Sub-Total: \$703.00

JENGAIRFILT JD S780**COMPLAINT:**

30 REPLACE PRIMARY AND SECONDARY ENGINE AIR FILTERS

CORRECTION:

removed and replaced air filters as well as cleaned housing

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
HXE11090	Primary Engine Air Filter	1.00	461.37	461.37	\$461.37	N
HXE11091	Secondary EngAir Filter	1.00	325.55	325.55	\$325.55	N

Labor: \$50.00 Parts: \$786.92 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$836.92

JCABFILTER JD S780**COMPLAINT:**

31 REPLACE CAB AIR FILTERS

CORRECTION:

REMOVE CAB AIR FILTERS
 CLEAN FILTER HOUSING
 INSTALL NEW AIR FILTERS

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
--------------------	--------------------	-----------------	-------------------	------------------	-----------------------	------------------

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
Hwy 21 North, Box 1810
Maple Creek, SK S0N 1N0
Phone: (306) 662-2233
Fax: (306) 662-3049
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Deliver To:

Invoice Number: 3534102 Invoice Date: 2/3/2026 Location: 02 Work Order Number: 520698 Payment Type: Page: 15 of 18	
Bus Phone: Prv Phone:	Bus Phone: Prv Phone:

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE S780	460	1H0S780SPRT831400	263013	

JCABFILTER JD S780

L214634	CabRecirc AirFilter 2/pkg	1.00	52.56	52.56	\$52.56	N
TA32591	Cab FreshAir Filter	1.00	121.63	121.63	\$121.63	N

Labor: \$50.00	Parts: \$174.19	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$224.19
-----------------------	------------------------	-------------------------	---------------------	----------------------------

JENGEARCSEPD JD S780

COMPLAINT:

32 REPLACE MAIN ENGINE GEARCASE OIL AND PRO DRIVE FILTER.

CORRECTION:

DRAIN OIL AND REMOVE PRO DRIVE FILTER.

DRAIN TRANSMISSION OIL.

INSTALL NEW OIL AND FILTER.

RUN UNIT AND LEAK CHECK.

CHECK OIL LEVEL AND ADJUST AS REQUIRED.

1000HR

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AH128449	HYDRAULIC FILTER	1.00	154.45	154.45	\$154.45	N
AN207368	Hydro Charge Filter	1.00	204.40	204.40	\$204.40	N
AR69444	HY-GARD J20C 18.9L PAIL	2.00	158.46	158.46	\$316.92	N
N309233	O-RING	1.00	29.41	29.41	\$29.41	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
EF100	ENVIRO FEE	1.00	1.25	1.25	\$1.25	N
EF300	ENVIRO FEE	2.00	3.00	3.00	\$6.00	N

Labor: \$200.00	Parts: \$705.18	OL&M: \$0.00	Misc: \$7.25	Sub-Total: \$912.43
------------------------	------------------------	-------------------------	---------------------	----------------------------

JLDAUGER JD S780

COMPLAINT:

33 REPLACE GRAIN TANK LOADING AUGER, GETTING SHARP, REPLACE DRIVER

PATTISON AGRICULTURE LIMITED

Hwy 21 North, Box 1810
 Maple Creek, SK S0N 1N0
 Phone: (306) 662-2233
 Fax: (306) 662-3049
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	

**JOHN DEERE**

Deliver To:

SERVICE INVOICE

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: 3534102 Invoice Date: 2/3/2026 Location: 02 Work Order Number: 520698 Payment Type: Page: 16 of 18
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE S780	460	1H0S780SPRT831400	263013	

JLDAUGER JD S780**CORRECTION:**

REMOVE LOADING AUGER TOP BEARING AND SUPPORT.
 REPLACE LOADING AUGER DRIVER IF NECESSARY.
 INSTALL ALL REMOVED COMPONENTS.
 ADJUST LOADING AUGER TOP BEARING AND SUPPORT FOR PROPER
 CLEARANCE.
 FUNCTION CHECK.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
03M7375	M10x30 CB 10.9 SN	1.00	2.32	2.32	\$2.32	N
14M7400	M10-1.5 FLG NYLOCK NUT	1.00	2.50	2.50	\$2.50	N
14M7589	M16-2.0 FLG STOVER LOCK NUT	1.00	5.69	5.69	\$5.69	N
49M4821	Shaft Key M6x32	1.00	3.89	3.89	\$3.89	N
AXE69563	Loading Auger 400bu	1.00	2,502.11	2,502.11	\$2,502.11	N
HXE84650	S-series Pea Driver	1.00	221.05	221.05	\$221.05	N
JD10384	BEARING	1.00	73.72	73.72	\$73.72	N
Labor: \$252.00		Parts: \$2,811.28	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$3,063.28	

J06500020 JD S780**COMPLAINT:**

34 GRAIN TANK CAMERA DOESN'T FUNCTION (DIAGNOSE), AUGER CAMERA IS FOGGY

CORRECTION:

CAMERAS BOTH WORK BUT ARE FOGGY

Labor: \$0.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$0.00
----------------------	----------------------	-------------------------	---------------------	--------------------------

JTAILINGCAL JD S780**COMPLAINT:**

35 PERFORM ALL OTHER FACTORY CALIBRATIONS AT RUN UP

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED

Hwy 21 North, Box 1810
 Maple Creek, SK S0N 1N0
 Phone: (306) 662-2233
 Fax: (306) 662-3049
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

**JOHN DEERE**

Deliver To:

SERVICE INVOICE

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: 3534102 Invoice Date: 2/3/2026 Location: 02 Work Order Number: 520698 Payment Type: Page: 17 of 18
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE S780	460	1H0S780SPRT831400	263013	

JTAILINGCAL JD S780

CORRECTION:

Labor: \$420.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$420.00
-----------------	---------------	--------------	--------------	---------------------

JGEN52-

COMPLAINT:

36 SOFTWARE FOR CROSS AUGER SHUT OFF

CORRECTION:

installed sftware

ran but still did not run

had some one run unit while i watched from bottom to confirm it did not run



double checked all connectors and all were good

found dtac where an adress should be changed

changed adress and they worked properly

parked combine

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
--------------------	--------------------	-----------------	-------------------	------------------	-----------------------	------------------



CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED

Hwy 21 North, Box 1810
Maple Creek, SK S0N 1N0
Phone: (306) 662-2233
Fax: (306) 662-3049
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preaceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3456
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	


JOHN DEERE

Deliver To:

SERVICE INVOICE

Invoice Number: 3534102 Invoice Date: 2/3/2026 Location: 02 Work Order Number: 520698 Payment Type: Page: 18 of 18	
Bus Phone: Prv Phone:	Bus Phone: Prv Phone:

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE S780	460	1H0S780SPRT831400	263013	

JGEN52-

HXE184767	SOFTWARE	1.00	0.00	0.00	\$0.00	N
-----------	----------	------	------	------	--------	---

Labor: \$105.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$105.00
------------------------	----------------------	-------------------------	---------------------	----------------------------

INVOICE CONTAINS \$125.67 DISCOUNT

Miscellaneous Charges:
SERVICE ACCESSORIES

\$150.00

Customer PO No: Tax Exempt No: Advisor: Rae Anne Stimson
--

Labor:	\$14,879.01
Parts:	\$21,717.03
OL&M:	\$0.00
Misc:	(\$1,059.47)
Grand Total:	\$35,536.57

*** DOCUMENT COPY ***

ALL QUOTES ISSUED ARE VALID FOR 7 DAY FROM ISSUE -- MIN \$35 ON EMERGENCY/UNIT DOWN ORDERS -- 25% RESTOCKING FOR RET

TERMS AND CONDITIONS

I hereby authorize the above repair work be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery. I agree to pay cash for such repair parts and labour on delivery of machine(s) or on terms satisfactory to you, and until paid in full, any such unpaid balance shall constitute a lien on this machinery. I further agree that you will not be held responsible for loss or damage to said machinery from fire, theft or other causes beyond your control

Received by: Date: