

001-231



PATTISON AGRICULTURE LIMITED
 Hwy 38 South, Box 1057
 Kelvington, SK S0A 1W0
 Phone: (306) 327-4355
 Fax: (306) 327-4314
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		



JOHN DEERE

SERVICE INVOICE

Deliver To:

Bus Phone:	Bus Phone:	Invoice Number:	3684324
		Invoice Date:	9/21/2026
Prv Phone:	Prv Phone:	Location:	09
		Work Order Number:	555028
		Payment Type:	
		Page:	1 of 5

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE S680	2711	1H0S680STF0775554	085554U	

JGLC JD S SERIES ALL

COMPLAINT:

01 S SERIES COMBINE VALUEMAX GREEN LIGHT SERVICE INSPECTION CHECKOVER


CORRECTION:

VALUEMAX GREEN LIGHT SELF PROPELLED COMBINE CHECKLIST

 HEADER SERIAL # _____ N/A _____
 ENGINE HOURS _____ 2711 _____
 SEPERATOR HOURS _____ 1979 _____

DOES THIS UNIT GET A VALUEMAX STICKER __ YES __X__ NO
 HAS THE STICKER BEEN INSTALLED __ YES __X__ NO
 THIS UNIT HAS HAD THE CAB CLEANED _____JA_____ (INITIAL)
 THIS UNIT HAS HAD A FINAL CHECKOVER _____AK_____ (INITIAL)
 THIS UNIT HAS HAD A COMPLETE GREASE JOB _____AK_____ (INITIAL)

THINGS NOTED BUT NOT REPAIRED ON CUSTOMERS INSTRUCTIONS:
 - VMI LIST ATTACHED WITH EVERYTHING THAT HAS TO BE DONE.



Job Total: \$3,321.56

JFCC JD ALL

COMPLAINT:

02 FREE CLEANUP OF CAB

CORRECTION:

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
---------------	-------------	----------	------------	-----------	----------------	-----------

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED

Hwy 38 South, Box 1057
 Kelvington, SK S0A 1W0
 Phone: (306) 327-4355
 Fax: (306) 327-4314
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

**JOHN DEERE**

Deliver To:

SERVICE INVOICE

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: 3684324 Invoice Date: 9/21/2026 Location: 09 Work Order Number: 555028 Payment Type: t Page: 2 of 5
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE S680	2711	1H0S680STF0775554	085554U	

JFCC JD ALL

LABDIS	LAB DISC CUST	-1.00	172.50	172.50	(\$172.50)	N
Labor: \$172.50		Parts: \$0.00	OL&M: \$0.00	Misc: (\$172.50)	Sub-Total: \$0.00	


J06180300 JD S680

COMPLAINT:

03 REPLACE FEEDERHOUSE STONE TRAP DOOR AND HOUSING.

CORRECTION:

REMOVED DOOR PINS AND HARDWARE.
 REMOVED STONE TRAP DOOR.
 INSTALLED NEW STONE TRAP DOOR WITH OLD PINS, WONT LATCH.
 REMOVED PIN AND LOWERED STONE TRAP DOOR.
 LOOSENED HARDWARE FOR TOP STONE TRAP DOOR PLATE.
 MOVED PLATE HIGHER AND TIGHTENED ALL HARDWARE BACK.
 BENT LIP IN FRONT OF TOP STONE TRAP PLATE.
 SLIGHT BENT CURVED FEED PLATE JUST TO MAKE IT FIT.
 REASSEMBLED IN REVERSE ORDER.
 GRAINED SHARP EDGES TO MAKE DOOR FIT.
 INSTALLED NEW STONE TRAP DOOR SEAL.
 CHECKED FUNCTION OF STONE TRAP DOOR.
 VERIFY REPAIRS.



Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AH219192	Stone Trap Door	1.00	1,169.07	1,169.07	\$1,169.07	N
AH80335	Weatherstrip /ft	5.00	6.99	6.99	\$34.95	N
Labor: \$472.50		Parts: \$1,204.02	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$1,676.52	

J06180110 JD S680

COMPLAINT:

04 REPLACE THRESHING ELEMENTS

CORRECTION:

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
Hwy 38 South, Box 1057
Kelvington, SK S0A 1W0
Phone: (306) 327-4355
Fax: (306) 327-4314
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Deliver To:

Invoice Number: 3684324 Invoice Date: 9/21/2026 Location: 09 Work Order Number: 555028 Payment Type: Page: 3 of 5	
Bus Phone: Prv Phone:	Bus Phone: Prv Phone:

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE S680	2711	1H0S680STF0775554	085554U	

J06180110 JD S680

REMOVED DAMAGED THRESHING ELEMENTS.
 INSTALLED NEW KIT FOLLOWED INSTALLATION PROCEDURE.
 TORQUED ALL BOLTS TO THE SPEC

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
KXE10034	Threshing Element Set STD	1.00	805.78	805.78	\$805.78	N
Labor: \$163.80		Parts: \$805.78	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$969.58	

J06180261 JD S680

COMPLAINT:
 05 PERFORM FACTORY CALIBRATION AND LEVELING OF ACTIVE CONCAVES.

CORRECTION:

DROPPED DOWN CONCAVES.
 LOOSENED HARDWARE.
 REMOVED CONCAVES PINS ON RH SIDE.
 REMOVED FULL SET OF CONCAVES.
 LOOSENED HANGER BAR HARDWARE.
 REMOVED AND REPLACED HANGER BAR WITH A NEW ONE.
 INSTALLED FRONT NEW CONCAVE.
 REASSEMBLED EVERYTHING IN REVERSE ORDER.
 LEVELED CONCAVES.
 ATTEMPTED TO CALIBRATE THRESHING CLEARANCE AND IT FAILED.
 CHECKED FOR ANY DAMAGE, FOUND THAT ONE CYLINDER TURN BUCKLE WAS SIEZED.
 REMOVED CYLINDER SEAL.
 APPLIED PENETRATING OIL AND WORK BACK AND FORWARD UNTIL MOVED ALL THE WAY TO THE TOP.
 WITH CONCAVES ALL THE WAY UP IT STILL HAS 1/2 INCH GAP.
 LOOSENED CONCAVES AND RE TIGHTENED ALL OF THEM TO Z-BAR.
 LOOSENED CYLINDER ROD IN Z-BAR MOUND TO GET AND EXTRA ROOM FOR CONCAVES.
 LEVELED CONCAVES AND LOCKED CYLINDERS.
 DID THRESHING CALIBRATION AND IT PASSED.
 REINSTALLED SEPARATION GRATES BACK.
 VERIFY REPAIRS.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
14M7299	M12-1.75 FLG NUT	6.00	2.86	2.86	\$17.16	N

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED

Hwy 38 South, Box 1057
Kelvington, SK S0A 1W0
Phone: (306) 327-4355
Fax: (306) 327-4314
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	

**JOHN DEERE****SERVICE INVOICE**

Deliver To:

		Invoice Number:	3684324
		Invoice Date:	9/21/2026
		Location:	09
		Work Order Number:	555028
		Payment Type:	
Bus Phone:	Bus Phone:	Page: 4 of 5	
Prv Phone:	Prv Phone:		

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE S680	2711	1H0S680STF0775554	085554U	

J06180261 JD S680

19M7590	M12x100 HH 8.8 BOLT	2.00	7.93	7.93	\$15.86	N
19M7835	M10x35 FLG 10.9 BOLT	2.00	0.72	0.72	\$1.44	N
AH214026	PIN FASTEN	1.00	11.01	11.01	\$11.01	N
AH218464	ConcaveRH Hanger Bar	1.00	1,291.97	1,291.97	\$1,291.97	N
AXE28812	Concave SM Wire Front	1.00	2,453.04	2,453.04	\$2,453.04	N
H135891	M10x1.5 FlgLck	3.00	2.32	2.32	\$6.96	N
HXE83040	LOCKING CO	1.00	38.58	38.58	\$38.58	N

Labor: \$714.00 Parts: \$3,836.02 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$4,550.02

J06180027 JD S680**COMPLAINT:**

06 REPLACE FRONT SEPARATOR TOP COVER.

CORRECTION:

CLEANED SPOT FROM PAINT.
CUT AND BENT PIECE TO MATCH TOP COVER.
WELT PATCH AND GRAINED IT FLAT.
TOUCH PAINTED WELDING SPOT.

CLEANED SPOT AROUND CRACK ON CHAFFER CROSS BAR.
WELDED CRACK AND CLEANED SPOT.
TOUCH PAINTED.

REMOVED CONCAVE CYLINDER REAR SHIELD, THAT WAS BROKEN.
CLEANED SPOT AND WELDED.
GRAINED FLAT AND TOUCH PAINTED.
REINSTALLED IN REVERSE ORDER.

Labor: \$630.00 Parts: \$0.00 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$630.00

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
Hwy 38 South, Box 1057
Kelvington, SK S0A 1W0
Phone: (306) 327-4355
Fax: (306) 327-4314
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351 Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233 Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683 Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302 Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889 Russell, MB (204) 773-2149
Unity, SK (306) 228-2696 Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468 Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572 Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355
Shaunavon, SK (306) 297-2639



JOHN DEERE

SERVICE INVOICE

Deliver To:

Bus Phone: Prv Phone:		Invoice Number: 3684324 Invoice Date: 9/21/2026 Location: 09 Work Order Number: 555028 Payment Type: Page: 5 of 5	
--------------------------	--	---	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE S680	2711	1H0S680STF0775554	085554U	

J06174011 JD S680

COMPLAINT:
07 REPLACE CHAFFER LOUVERS.

CORRECTION:
LOOSENED TAIL BOARD.
REMOVED CHAFFER.
DISCONNECTED ADJUSTING RODS.
REMOVED LOUVERS AND REPLACED THEM WITH A NEW ONES.
REASSEMBLED IN REVERSE ORDER.
VERIFY REPAIRS.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AH170119	GEN. PURP. ELEC. ADJ. LOUVERS	4.00	64.70	64.70	\$258.80	N
AXE42167	GEN PURP. MANUAL ADJ. LOUVERS	1.00	101.38	101.38	\$101.38	N
Labor: \$367.50		Parts: \$360.18	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$727.68	
Miscellaneous Charges:						
SERVICE ACCESSORIES						\$150.00

Customer PO No:
Tax Exempt No:
Advisor: MATTHEW HRYTZAK

Job Total: \$12,025.36
Grand Total: \$12,025.36

*** DOCUMENT COPY ***

ALL QUOTES ISSUED ARE VALID FOR 7 DAY FROM ISSUE -- MIN \$35 ON EMERGENCY/UNIT DOWN ORDERS -- 25% RESTOCKING FOR RET

TERMS AND CONDITIONS

I hereby authorize the above repair work be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery. I agree to pay cash for such repair parts and labour on delivery of machine(s) or on terms satisfactory to you, and until paid in full, any such unpaid balance shall constitute a lien on this machinery. I further agree that you will not be held responsible for loss or damage to said machinery from fire, theft or other causes beyond your control

Received by: Date: