

001-238



PATTISON AGRICULTURE LIMITED
 Hwy 14 West, Box 599
 Unity, SK S0K 4L0
 Phone: (306) 228-2696
 Fax: (306) 228-2776
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

Invoice To Account No:

Deliver To:

SERVICE INVOICE

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number:	3384489
		Invoice Date:	5/29/2025
		Location:	06
		Work Order Number:	488567
		Payment Type:	
		Page:	1 of 10

Make/Model:

Meter:

Serial Number:

Eq ID:

Fleet No:

JOHN DEERE 9RX 640 30" PTO

1800

1RW9640DTPJ822563

159129

JGL4WD JD ALL

COMPLAINT:

01 4WD TRACTOR VALUEMAX GREEN LIGHT SERVICE INSPECTION CHECKOVER

CORRECTION:

VALUEMAX GREEN LIGHT SERVICE INSPECTION CHECKLIST

HOURS: _1800_

DOES THIS UNIT GET A VALUEMAX STICKER X YES NOHAS STICKER BEEN INSTALLED X YES NOCAB HAS BEEN COMPLETELY CLEANED MSTHIS UNIT HAS HAD A FINAL CHECKOVER GTTHIS UNIT HAS HAD A COMPLETE GREASE JOB GT

THINGS NOTED BUT NOT REPAIRED ON CUSTOMER'S INSTRUCTIONS:

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
TY26859	INSPECTION+ 3 FLUID TEST KIT	1.00	87.56	87.56	\$87.56	N
TY6341	SD POLYUREA GREASE	1.00	11.14	11.14	\$11.14	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
LABDIS	LAB DISC CUST	-1.00	625.00	625.00	(\$625.00)	N

Labor: \$2,500.00

Parts: \$98.70

OL&M: \$0.00

Misc: (\$625.00)

Sub-Total: \$1,973.70

JWASH10 USED 4WD

COMPLAINT:

02 WASH USED 4WD TRACTOR. READY FOR DISPLAY.

CORRECTION:

INCLUDES THE FOLLOWING:

-WASH COMPLETE EXTERIOR.

-WASHING OUT RADIATOR AND ALL COOLERS.

-VACUUM CAB AND WASH FLOOR MAT.

-WASH ALL CAB INTERIOR SURFACES

-CLEAN WINDOWS

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
Hwy 14 West, Box 599
Unity, SK S0K 4L0
Phone: (306) 228-2696
Fax: (306) 228-2776
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		



JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number:	3384489
		Invoice Date:	5/29/2025
		Location:	06
		Work Order Number:	488567
		Payment Type:	
		Page:	2 of 10

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9RX 640 30" PTO	1800	1RW9640DTPJ822563	159129	

JWASH10 USED 4WD

Labor: \$1,150.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$1,150.00
-------------------	---------------	--------------	--------------	-----------------------

JGEN03-

COMPLAINT:

03 TIGHTEN CAB SUSPENSION BOLT UNDER DOOR

CORRECTION:

REMOVED BOLT FROM UPPER STABILIZER BAR.
INSPECTED THREADS, WAS SLIGHT DAMAGE.
CLEANED OUT INNER THREADS ON STABILIZER.
INSTALLED NEW BOLT WITH LOCTITE AND TORQUED TO SPEC.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
19M7832	M20x100 FLG 10.9 BOLT	1.00	24.30	24.30	\$24.30	N
Labor: \$210.00	Parts: \$24.30	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$234.30		

JGEN04-

COMPLAINT:

04 INSTALL HVAC VENT BEHIND SEAT

CORRECTION:

INSTALLED VENT.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
TR119164	LOUVER	1.00	94.23	94.23	\$94.23	N
Labor: \$100.00	Parts: \$94.23	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$194.23		

JSOFTWARE JD 9RX 640

COMPLAINT:

06 UPDATE ALL CONTROLLER SOFTWARE

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
Hwy 14 West, Box 599
Unity, SK S0K 4L0
Phone: (306) 228-2696
Fax: (306) 228-2776
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosemin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2636
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		



JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number:	3384489
		Invoice Date:	5/29/2025
		Location:	06
		Work Order Number:	488567
		Payment Type:	
		Page:	3 of 10

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9RX 640 30" PTO	1800	1RW9640DTPJ822563	159129	

JSOFTWARE JD 9RX 640

CORRECTION:

HAD TO PREFORM THE FOLLOWING CALIBRATIONS.

WENT ON SERVICE ADVISOR AND DOWNLOADED UPDATED SOFTWARE FOR ECU AND DEF HEADER.

HOOKED UP EDL TO TRACTOR AND TO LAPTOP AND DOWNLOADED NEW SOFTWARE FOR BOTH CONTROLLERS.

BOTH DOWNLOADED SUCCESSFULLY.

Labor: \$400.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$400.00
-----------------	---------------	--------------	--------------	---------------------

JGEN07-

COMPLAINT:

07 CALIBRATE TRANSMISSION

CORRECTION:

DROVE TRACTOR AND SHIFTED TRANSMISSION TO WARM UP OIL.

WARMED OIL TO 120 DEGREES.

WENT INTO PTP CONTROLLER AND SELECTED ADDRESS 25.

TRANSMISSION CALIBRATED WITH NO CODES.

Labor: \$300.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$300.00
-----------------	---------------	--------------	--------------	---------------------

JGEN08-

COMPLAINT:

08 REPLACE BROKEN SCV DRAIN HOSE

CORRECTION:

FITTING IN BOTTOM OF SCV STACK HAD COME OUT.

CLEANED UP AND APPLIED RETAINING COMPOUND AND INSTALLED IN SCV.

Labor: \$100.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$100.00
-----------------	---------------	--------------	--------------	---------------------

J21001020 JD R4060

COMPLAINT:

09 ADJUST CAB DOOR LATCH.

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
Hwy 14 West, Box 599
Unity, SK S0K 4L0
Phone: (306) 228-2696
Fax: (306) 228-2776
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Prescaveville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Bus Phone:

Prv Phone:

Bus Phone:

Prv Phone:

Invoice Number:	3384489
Invoice Date:	5/29/2025
Location:	06
Work Order Number:	488567
Payment Type:	
Page:	4 of 10

Make/Model:

Meter:

Serial Number:

Eq ID:

Fleet No:

JOHN DEERE 9RX 640 30" PTO

1800

1RW9640DTPJ822563

159129

J21001020 JD R4060

CORRECTION:

ADJUST CAB DOOR LATCH.

ENSURE CAB DOOR SEALS.

ENSURE CAB DOOR OPENS AND CLOSES PROPERLY.

Labor: \$100.00

Parts: \$0.00

OL&M: \$0.00

Misc: \$0.00

Sub-Total: \$100.00

JGEN10-

COMPLAINT:

10 INSTALL NEW EITHER CAN

CORRECTION:

REMOVED BOTTOM OF HOLDER.

REMOVED SPRAY NOZZLE FROM CAN.

INSTALLED NEW CAN.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
RE556468	PREMIUM ETHER STARTING FLUID	1.00	14.95	14.95	\$14.95	N

Labor: \$50.00

Parts: \$14.95

OL&M: \$0.00

Misc: \$0.00

Sub-Total: \$64.95

JENGOILCH JD 9RX 640

COMPLAINT:

11 REPLACE ENGINE OIL AND FILTER

CORRECTION:

DRAIN ENGINE OIL AND REMOVE FILTER.

CLEAN AREA.

INSTALL NEW OIL AND FILTER.

RUN UNIT AND LEAK CHECK.

MARK ENGINE HOURS ON NEW FILTER.

ADJUST OIL LEVEL AS REQUIRED.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
-------------	-------------	----------	------------	-----------	----------------	-----------

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
Hwy 14 West, Box 599
Unity, SK S0K 4L0
Phone: (306) 228-2696
Fax: (306) 228-2776
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

		Invoice Number: 3384489 Invoice Date: 5/29/2025 Location: 06 Work Order Number: 488567 Payment Type: . Page: 5 of 10
Bus Phone:	Bus Phone:	
Prv Phone:	Prv Phone:	

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9RX 640 30" PTO	1800	1RW9640DTPJ822563	159129	

JENGOILCH JD 9RX 640

RE572785	ENGINE OIL FILTER	1.00	156.67	156.67	\$156.67	N
TY26673	15W40 3.78L Plus-50II CK4/SN	1.00	37.78	37.78	\$37.78	N
TY26679	PLUS-50 II 15W-40 CK4/SN 18.9L PAIL	3.00	170.86	170.86	\$512.58	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
EF100	ENVIRO FEE	1.00	1.25	1.25	\$1.25	N
EF300	ENVIRO FEE	3.00	3.00	3.00	\$9.00	N
EF60	ENVIRO FEE	1.00	0.60	0.60	\$0.60	N

Labor: \$250.00 Parts: \$707.03 OL&M: \$0.00 Misc: \$10.85 Sub-Total: \$967.88

JENGAIRFI JD 9RX 640

COMPLAINT:
12 REPLACE PRIMARY AND SECONDARY ENGINE AIR FILTERS

CORRECTION:
UNFASTEN AIR FILTER HOUSING CLIPS.

CHECK COVER SEAL AND HOUSING FOR DAMAGE.

REMOVE AND REPLACE BOTH ENGINE AIR FILTERS.

ASSEMBLE IN THE REVERSE ORDER.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
RE230985	SECONDARY ENG AIR FILTER	1.00	176.70	176.70	\$176.70	N
TA17973	Primary EngAir Filter 13.6	1.00	352.57	352.57	\$352.57	N

Labor: \$100.00 Parts: \$529.27 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$629.27

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
Hwy 14 West, Box 599
Unity, SK S0K 4L0
Phone: (306) 228-2696
Fax: (306) 228-2776
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: 3384489 Invoice Date: 5/29/2025 Location: 06 Work Order Number: 488567 Payment Type: Page: 6 of 10
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9RX 640 30" PTO	1800	1RW9640DTPJ822563	159129	

JCABFILTER JD 9RX640

COMPLAINT:

13 REPLACE CAB AIR FILTERS

CORRECTION:

FOR THE RECIRCULATION FILTER, REMOVE COVER AT BOTTOM LEFT INNER CORNER OF CAB.

REMOVE AND DISCARD OLD RECIRCULATION FILTER AND INSTALL NEW FILTER.

FOR THE FRESH AIR FILTER, TURN KNOB FULLY COUNTERCLOCKWISE TO UNLATCH COVER.

SWING DOWN COVER.

MARK HOURS AND DATE ON FILTERS.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
RE593819	CAB RECIRC AIR FILTER	1.00	70.43	70.43	\$70.43	N
TA32591	Cab FreshAir Filter	1.00	125.95	125.95	\$125.95	N
Labor: \$100.00		Parts: \$196.38	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$296.38	

JHYDOILCHG JD 9620RX

COMPLAINT:

14 REPLACE HYDRAULIC / TRANSMISSION OIL AND FILTERS

CORRECTION:

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
Hwy 14 West, Box 599
Unity, SK S0K 4L0
Phone: (306) 228-2696
Fax: (306) 228-2776
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number:	3384489
		Invoice Date:	5/29/2025
		Location:	06
		Work Order Number:	488567
		Payment Type:	
		Page:	7 of 10

Make/Model:

Meter:

Serial Number:

Eq ID:

Fleet No:

JOHN DEERE 9RX 640 30" PTO

1800

1RW9640DTPJ822563

159129

JHYDOILCHG JD 9620RX

DRAIN ALL HYDRAULIC AND TRANSMISSION FLUID.
REMOVE SUMP SCREEN AND CLEAN.
REPLACE ALL HYDRAULIC AND TRANSMISSION FILTERS.
INSTALL SUMP SCREEN.
INSTALL NEW HYDRAULIC AND TRANSMISSION FLUID.
RUN UNIT.
LEAK CHECK.
CHECK AND ADJUST FLUID LEVELS.
TEST DRIVE UNIT TO INSURE AXLE AND FINAL DRIVE FLUID LEVELS.
CHECK AND ADJUST FLUID LEVELS.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AR69445	HY-GARD J20C 208L BARREL	1.00	1,628.19	1,628.19	\$1,628.19	N
R319585	Oil Filter Seal Ring	1.00	10.90	10.90	\$10.90	N
R564922	Oil Filter Seal Ring	4.00	16.30	16.30	\$65.20	N
R567277	RING	1.00	18.41	18.41	\$18.41	N
RE577250	HYDRAULIC OIL FILTER	1.00	161.70	161.70	\$161.70	N
RE577612	Hydraulic Oil Filter	4.00	206.11	206.11	\$824.44	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
EF100	ENVIRO FEE	5.00	1.25	1.25	\$6.25	N
EF1025	ENVIRO FEE	1.00	10.25	10.25	\$10.25	N

Labor: \$1,040.00

Parts: \$2,708.84

OL&M: \$0.00

Misc: \$16.60

Sub-Total: \$3,765.34

J01001701 JD 9620RX

COMPLAINT:

15 REPLACE OIL IN ALL TRACK MID ROLLERS AND IDLERS. (32 TOTAL)

CORRECTION:

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
Hwy 14 West, Box 599
Unity, SK S0K 4L0
Phone: (306) 228-2696
Fax: (306) 228-2776
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number:	3384489
		Invoice Date:	5/29/2025
		Location:	06
		Work Order Number:	488567
		Payment Type:	
		Page:	8 of 10

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9RX 640 30" PTO	1800	1RW9640DTPJ822563	159129	

J01001701 JD 9620RX

REPLACED OIL IN ALL TRACK IDLERS AND ROLLERS. (32 TOTAL)
REMOVED COVERS TO DRAIN OILS.
CLEANED UP SEALING SURFACES OF COVER AND HUB.
REPLACED O-RINGS IF REQUIRED.
REINSTALLED COVERS AND TORQUES HARDWARE.
REFILLED WITH OIL.
DROVE TRACTORS AND RECHECKED OIL LEVELS.
CHECKED FOR LEAKS.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
R254440	O-RING	16.00	20.58	20.58	\$329.28	N
R254441	O-Ring	16.00	33.88	33.88	\$542.08	N
TY22062	HY-GARD J20C 9.46L	2.00	85.28	85.28	\$170.56	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
EF150	ENVIRO FEE	2.00	1.50	1.50	\$3.00	N
Labor: \$1,900.00		Parts: \$1,041.92	OL&M: \$0.00	Misc: \$3.00	Sub-Total: \$2,944.92	

J100300 JD 9RX 640

COMPLAINT:

16 REPLACE ENGINE FUEL FILTERS

CORRECTION:

REPLACED PRIMARY AND SECONDARY FUEL FILTERS.
REMOVED AND CLEANED FUEL STRAINER/WATER SEPARATOR.
BLED FUEL SYSTEM.
FUNCTION AND LEAK CHECKED.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
DZ124761	Primary Fuel Filter 13.6L	1.00	168.89	168.89	\$168.89	N
DZ124786	Secondary Fuel Filter 13.6L	1.00	162.25	162.25	\$162.25	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
Hwy 14 West, Box 599
Unity, SK S0K 4L0
Phone: (306) 228-2696
Fax: (306) 228-2776
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number:	3384489
		Invoice Date:	5/29/2025
		Location:	06
		Work Order Number:	488567
		Payment Type:	
		Page:	9 of 10


Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9RX 640 30" PTO	1800	1RW9640DTPJ822563	159129	

J100300 JD 9RX 640
EF100 ENVIRO FEE 2.00 1.25 1.25 \$2.50 N

Labor: \$160.00 Parts: \$331.14 OL&M: \$0.00 Misc: \$2.50 Sub-Total: \$493.64

JGEN17-
COMPLAINT:
17 REPAIR GREASE ZERK

CORRECTION:
LIFT LEFT REAR TRACK UP AND PLACE ON SUPPORT STAND.
HOOK UP HOSE TO TENSION CYLINDER AND RUN TRACTOR AND RELEASE TENSION ON TRACK.
REMOVE LEFT FRONT OUTER IDLER WHEEL AND INNER IDLER WHEEL.
REMOVE LOCK PLATE FROM CYLINDER AND REMOVE PIN.
LIFT AND SUPPORT END OF CYLINDER AND REMOVE REST OF BROKEN GREASE ZERK.
CLEAN UP PIN AND SUPPORT BRACKET AND BUSHING IN CYLINDER.
RE-INSTALL PIN AND NEW ZERK AND GREASED PIN.
COULD NOT GET FRONT IDLERS TO FIT BACK ON
LOOSENED FITTING ON CYLINDER AND PULLED CYLINDER IN TO GAIN MORE CLEARANCE BETWEEN TRACK.
INSTALLED BOTH IDLERS AND RE-TENSIONED TRACK AND TORQUED HARDWARE ON BOTH IDLERS.



CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
Hwy 14 West, Box 599
Unity, SK S0K 4L0
Phone: (306) 228-2696
Fax: (306) 228-2776
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number:	3384489
		Invoice Date:	5/29/2025
		Location:	06
		Work Order Number:	488567
		Payment Type:	
		Page:	10 of 10

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9RX 640 30" PTO	1800	1RW9640DTPJ822563	159129	

JGEN17-

Labor: \$1,215.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$1,215.00
-------------------	---------------	--------------	--------------	-----------------------

Miscellaneous Charges:
SERVICE ACCESSORIES

\$150.00

Customer PO No:
Tax Exempt No:
Advisor:

Labor: \$9,675.00
Parts: \$5,746.76
OL&M: \$0.00
Misc: (\$442.15)
Grand Total: \$14,979.61

*** DOCUMENT COPY ***

ALL QUOTES ISSUED ARE VALID FOR 7 DAY FROM ISSUE -- MIN \$35 ON EMERGENCY/UNIT DOWN ORDERS -- 25% RESTOCKING FOR RET

TERMS AND CONDITIONS

I hereby authorize the above repair work be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery. I agree to pay cash for such repair parts and labour on delivery of machine(s) or on terms satisfactory to you, and until paid in full, any such unpaid balance shall constitute a lien on this machinery. I further agree that you will not be held responsible for loss or damage to said machinery from fire, theft or other causes beyond your control

Received by: _____ Date: _____