T. Yardley Contracting Ltd

4908 48th Avenue
PO Box 2838
High Prairie, Alberta T0G 1E0
(780) 523-0602

INVOICE

Invoice No.: 6025
Date: 02/18/2026
Page: 1

Sold to:
PVT ENERGY GROUP INC.

Business No.: 795410281

Quantity	Description	Unit Price	Amount
1.0	TRAILER CVIP- FEE- UNIT - T1090 - VIN - 1T9ZL4544ES588945 - 2014 - 333166 KMS	200.00	200.00
1.0	LICENCE PLATE LIGHT KIT- LLP2101	15.90	15.90
2.0	PIGTAIL- WIRING - PT6020	5.55	11.10
5.0	S-CAM TUBE KIT- INTRAAX- ARCK448	65.99	329.95
2.0	S-CAM- BRAKE RH - E11867- AR2033R-	65.99	131.98
3.0	S-CAM BRAKE LH- INTRAAX - AR2032L-	65.99	197.97
6.0	BRAKE SHOES- Q - PLUS NEW- C/W HDWE	103.30	619.80
7.0	BRAKE DRUM, 16.5 X 7 HEAVY DUTY DRUM	178.87	1,252.09
1.0	IRONHEAD - 11R24.5 TIRE- 0210543	425.00	425.00
1.0	TIRE ENVIRO FEE	15.00	15.00
1.0	TIRE CHANGE OVER FEE	43.00	43.00
1.0	LEVELING VALVE- FS6585	95.89	95.89
2.0	1/4 X 1 NC BOLT- 074141	0.76	1.52
4.0	1/4 FLAT WASHER	0.34	1.36
1.0	LINKAGE LEVELING VALVE- S14187	26.84	26.84
1.0	ABS SENSOR - 90 DEGREE - .9M- ABS09009M	55.33	55.33
1.0	ABS SENSOR EXTENSION HARNESS- ABSE18030M	37.75	37.75
1.0	LIGHT- ABS - 2-1/2 - 10212Y-	14.14	14.14
1.0	PIGTAIL- WIRING - PT6020	5.55	5.55
2.0	GROMMET , ROUND 2-1/2"- GR2500	3.30	6.60
8.0	WH GUARD - 22MM HUB PILOT- 5903	9.39	75.12
1.0	HUBCAP - FS34195- 1869C16	57.11	57.11
2.0	75W90, GL5, 1L- 30096-1L	19.39	38.78
2.0	BRAKE AND PARTS CLEANER- 313	9.45	18.90
1.0	SLACK ADJUSTER- BR801074	122.88	122.88
2.0	PIGTAIL- WIRING - 94707-3	7.36	14.72
2.0	TAIL-LIGHT S/T/T - LED - LO-COUNT- 44302R3	49.70	99.40
2.0	GROMMET- ROUND- 407003	6.50	13.00
4.0	GREASE, HD, MOLY 3 %- 50580-MC	11.78	47.12
8.0	3/8 X 1-1/2 NC GR8 BOLT- 10508P	3.26	26.08
	Discount 49.39%	-1.61	-12.88
8.0	3/8 NUT NC- 091018B	0.53	4.24
8.0	3/8 FLAT WASHER	0.41	3.28
4.0	TRAILER CVIP WHEELS OFF FEE- PRICE PER AXLE REMOVED-	120.00	480.00
2.0	CONTRACT WELDER- HIRED BY T.YARDLEY - MISC WORK ON TRAILER HITCH - INSTALLED EXPANDED METAL- ON WAGON HITCH ON TRAILER -	135.00	270.00
120.0	UNIT WASH JOB- PRICE INCLUDES HIRED WASHER- PRICE PER MINUTE TOURQUE ALL WHEELS SUPPLY TOURQUE TAG JACK UP ALL WHEELS- INSPECT BEARINGS FULL "A" INSPECTION- ALL WHEELS REMOVED- CLEANED RIMS WHILE REMOVED FULL UNIT GREASE JOB SET UP BRAKES- ON ALL AXLES REPAIR MINOR AIR LEAKS AS NEEDED	2.50	300.00

All WHEELS MUST BE RETORQUED!

As a free service to all clients come back and have them retorqued within 50-100 kms of use. This is clients responsibility, should you choose to have them retorqued elsewhere, T. Yardley Contracting Ltd. is not liable for any consequences. **Total invoice amount is due within 30 days**
All overdue accounts are subject to 2% interest monthly. (24% per annum)
Thank you for your business!

Continue...

T. Yardley Contracting Ltd

4908 48th Avenue
PO Box 2838
High Prairie, Alberta T0G 1E0
(780) 523-0602

INVOICE

Invoice No.: 6025
Date: 02/18/2026

Sold to:
PVT ENERGY GROUP INC.

Business No.: 795410281

Quantity	Description	Unit Price	Amount
	FRONT ABS LIGHT OUT - REPLACED CORRODED LIGHT AND PIGTAIL -REPLACED GROMMET- NO LICENCE PLATE LIGHT- REPLACED MISSING LIGHT BRACKET AND PIGTAIL REAR TOP INSIDE- TAILIGHTS OUT- REPLACED LIGHTS AND PIGTAILS AND GROMMETS REAR LEVELING VALVE LEAKS- REPLACED VALVE AND LINKAGE REAR SUSPENSION- DUMP VALVE BROKEN REPLACED S-CAM AND TUBE- WORE BEYOND SPEC- REMOVED SLACK- AXLE - 4LHS REPLACED S-CAM AND TUBE- WORE BEYOND SPEC- REMOVED SLACK- AXLE - 4RHS REPLACED S-CAM AND TUBE- WORE BEYOND SPEC- REMOVED SLACK- AXLE - 3LHS REPLACED S-CAM AND TUBE- WORE BEYOND SPEC- REMOVED SLACK- AXLE - 3RHS BRAKE SHOES- REPLACED- WORE BEYOND SPEC- AXLE - 4LHS BRAKE DRUM- WORE BEYOND SPEC.- REPLACED AXLE 4LHS BRAKE SHOES- REPLACED- WORE BEYOND SPEC- AXLE - 4RHS BRAKE DRUM- WORE BEYOND SPEC.- REPLACED AXLE 4RHS BRAKE SHOES- REPLACED- WORE BEYOND SPEC- AXLE - 3LHS BRAKE DRUM- WORE BEYOND SPEC.- REPLACED AXLE 3LHS BRAKE SHOES- REPLACED- WORE BEYOND SPEC- AXLE - 3RHS BRAKE DRUM- WORE BEYOND SPEC.- REPLACED AXLE 3RHS BRAKE SHOES- REPLACED- WORE BEYOND SPEC- AXLE - 2RHS BRAKE DRUM- WORE BEYOND SPEC.- REPLACED AXLE 2RHS BRAKE SHOES- REPLACED- WORE BEYOND SPEC- AXLE - 1RHS BRAKE DRUM- WORE BEYOND SPEC.- REPLACED AXLE 1RHS BRAKE DRUM- WORE BEYOND SPEC.- REPLACED AXLE 1LHS HUB CAP LEAKS- AXLE 1RHS- REMOVED AND REPLACED HUB CAP REPLACED S-CAM AND TUBE- WORE BEYOND SPEC- REMOVED SLACK- AXLE - 2LHS FRONT ABS- REPLACED ABS SENSOR AND EXTENSION AXLE 2RHS ABS CODES- DIAGNOSED- PLUGGED IN ABS COMPUTER- READ CODES- JACKED UP WHEELS RE-PLUGGED IN ABS COMPUTER- CLEARED CODES- LIGHT CYCLED PROPERLY REMOVED AND REPLACED SLACK ADJUSTER AXLE 2LHS		
18.5	LABOUR	145.00	2,682.50
1.0	SHOP SUPPLIES- MISC PARTS	95.00	95.00
	Subtotal:		7,822.02
	G - GST 5% GST/HST		391.14

All WHEELS MUST BE RETORQUED!

As a free service to all clients come back and have them retorqued within 50-100 kms of use. This is clients responsibility, should you choose to have them retorqued elsewhere, T. Yardley Contracting Ltd. is not liable for any consequences. **Total invoice amount is due within 30 days**
All overdue accounts are subject to 2% interest monthly. (24% per annum)
Thank you for your business!

Total Amount	8,213.16
Amount Paid	0.00
Amount Owing	**8,213.16**

Northwest Machine and Welding (1994) Ltd. INVOICE

Box 1387
High Prairie, Alberta T0G 1E0

Invoice No.: 104519
Date: 03/23/2026
Ship Date:
Page: 1
Re: Order No.

Sold to:

PVT ENERGY GROUP INC.
93-721071 RANGE ROAD 53
COUNTY OFGRANDE PRAIRIE, ALBERTA

Ship to:

PVT ENERGY GROUP INC.
93-721071 RANGE ROAD 53
COUNTY OFGRANDE PRAIRIE, ALBERTA

Business No.: 13971-9462RP

Item No.	Unit	Quantity	Description	Tax	Unit Price	Amount
			1090 WAGON BARREL LIFT TO REBUILD SUBFRAME AND FISHPLATE, FAB NEW UPPER PLATE FOR TURN TABLE, INSTALL SAFETY CHAINS	G5		
TANK REPAIR LABOUR	Hour	84	TANK REPAIR LABOUR	G5	140.00	11,760.00
SHOP SUPPLIES	Each		SHOP SUPPLIES	G5		986.28
PLATE44W1/2	FT SQ	20	44W PLATE 1/2" HOT ROLLED	G5	35.65	713.00
5454-H321/4	FT	12	ALUMINUM PLATE 1/4" , 5454-H32	G5	35.99	431.88
1/2CHAIN	FT	4	1/2" CHAIN , GRADE 70	G5	7.99	31.96
66076	Each	2	CLEVIS SLIP HOOK 1/2"	G5	42.56	85.12
66140	Each	2	MID LINK 7/16" - 1/2" 11250 LLB	G5	15.99	31.98
5/8 X 2 UNC GR.8	Each	12	5/8" X 2" , COARSE THREAD , GRADE 8 , BOLT	G5	2.67	32.04
5/8 H.B	Each	68	5/8 HARD BACK WASHER GRADE 8	G5	0.85	57.80
5/8 UNC S.L.N	Each	46	5/8" COARSE THREAD STOVER LOCKING NUT	G5	1.99	91.54
5/8 X 2 3/4 UNC GR.8	Each	22	5/8" X 2 3/4" , COARSE THREAD , GRADE 8 , BOLT	G5	1.40	30.80
3/8 X 1 1/2 UNC GR.8	Each	8	3/8" X 1 1/2" , COARSE THREAD , GRADE 8 , BOLT	G5	0.35	2.80
3/8 X 1 1/2 F.W	Each	8	3/8 X 1 1/2 FENDER WASHER	G5	0.35	2.80
3/8 F.W GR.5	Each	8	3/8" , FLAT WASHER , GRADE 5	G5	0.15	1.20
3/8 UNC N.N	Each	8	3/8" , COARSE THREAD , NYLOCK NUT	G5	0.15	1.20
		1	ELECTRICAL AND AIR FITTINGS PICKED UP AT NAPA	G5	410.85	410.85
			G5 - GST @ 5%			
			GST			733.56

Shipped By: Tracking Number:

Comment:

Sold By:

Total Amount	15,404.81
Amount Paid	0.00
Amount Owing	**15,404.81**

T. Yardley Contracting Ltd

4908 48th Avenue
PO Box 2838
High Prairie, Alberta T0G 1E0
(780) 523-0602

INVOICE

Invoice No.: 7177
Date: 10/26/2026
Page: 1

Sold to:
PVT ENERGY GROUP INC.

Business No.: 795410281

Quantity	Description	Unit Price	Amount
1	TRAILER CVIP- FEE- UNIT - T1090 - VIN- 1T9ZL4544ES588945 - 2014 - 333166 KMS	200.00	200.00
12	WIRE TIE- 15 " 836029	0.52	6.24
1	MARKER LIGHT - 2-1/2 LED AMB- 1050A3	13.26	13.26
1	LIGHT- ABS - 2-1/2 - 10212Y-	14.14	14.14
2	GROMMET , ROUND 2-1/2"- GR2500	3.75	7.50
2	PIGTAIL- WIRING - PT6020	4.30	8.60
2	75W90, GL5, 1L- 30096-1L	21.82	43.64
1	LINKAGE LEVELING VALVE- S14187	28.55	28.55
1	DRAIN VALVE W / 5 FT CABLE- 12105	15.33	15.33
2	BRA TEE 3/8 FPT X 3/8 MPT X 3/8 FP- X107C	9.11	18.22
4	5/16 X 1 - 1/2 NC BOLT	4.03	16.12
8	5/16 FLAT WASHER	0.35	2.80
4	5/16 STOVER LOCK NC	0.67	2.68
1	AIR TANK - 12 X 29.5 2 PORT- RQ1280	325.60	325.60
2	110ED- BUSHING	3.14	6.28
8	WH GUARD - 22MM HUB PILOT- 5903	10.95	87.60
4	TRAILER CVIP WHEELS OFF FEE- PRICE PER AXLE REMOVED-	125.00	500.00
80	UNIT WASH JOB- PRICE INCLUDES HIRED WASHER- PRICE PER MINUTE TOURQUE ALL WHEELS SUPPLY TOURQUE TAG JACK UP ALL WHEELS INSPECT BEARINGS TIE UP LOOSE WIRES AND AIR LINES WHERE NEEDED SET UP BRAKES- ON ALL AXLES FULL UNIT GREASE JOB FULL "A" INSPECTION- ALL WHEELS REMOVED- CLEANED RIMS WHILE REMOVED REPAIR MINOR AIR LEAKS AS NEEDED TIGHTENED LOOSE SHOCKS AXLE 1LHS AXLE 1RHS REMOVE AND REPLACE LHS FRONT MARKER LIGHT AND GROMMET ABS CODES- DIAGNOSED- PLUGGED IN ABS COMPUTER- READ CODES- JACKED UP WHEELS REMOVED AND REPLACED REAR ABS LIGHT GROMMET AND PIGTAIL FOUND LOOSE CONNECTION BETWEEN WHIP AND SENSOR- REPAIRED RE-PLUGGED IN ABS COMPUTER- CLEARED CODES TOPPED UP HUBS AS NEEDED REMOVED AND REPLACED FRONT AIR TANK- ROTTED THROUGH- RE-INSTALLED VALVES AND BRASS AS NEEDED TESTED AIR SYSTEM TIE UP LOW HANGING AIR LINES AND ABS WIRING FOUND UNPLUGGED ABS WIRE ON FRONT OF TRAILER REMOVED AND REPLACED LEVELING VALVE LINKAGE TIGHTENED BRAKE POT FITTINGS AXLE 3LHS AXLE 2RHS	2.50	200.00
8	LABOUR	145.00	1,160.00
1	SHOP SUPPLIES- MISC PARTS	95.00	95.00
	Subtotal:		2,751.56

All WHEELS MUST BE RETORQUED!

As a free service to all clients come back and have them retorqued within 50-100 kms of use. This is clients responsibility, should you choose to have them retorqued elsewhere, T. Yardley Contracting Ltd. is not liable for any consequences. **Total invoice amount is due within 30 days**
All overdue accounts are subject to 2% interest monthly. (24% per annum)
Thank you for your business!

Continue...

T. Yardley Contracting Ltd

4908 48th Avenue
PO Box 2838
High Prairie, Alberta T0G 1E0
(780) 523-0602

INVOICE

Invoice No.: 7177
Date: 10/26/2026

Sold to:
PVT ENERGY GROUP INC.

Business No.: 795410281

Quantity	Description	Unit Price	Amount
	G - GST 5% GST/HST		137.58

All WHEELS MUST BE RETORQUED!

As a free service to all clients come back and have them retorqued within 50-100 kms of use. This is clients responsibility, should you choose to have them retorqued elsewhere, T. Yardley Contracting Ltd. is not liable for any consequences. **Total invoice amount is due within 30 days**
All overdue accounts are subject to 2% interest monthly. (24% per annum)
Thank you for your business!

Total Amount	2,889.14
Amount Paid	0.00
Amount Owing	**2,889.14**

T. Yardley Contracting Ltd

4908 48th Avenue
PO Box 2838
High Prairie, Alberta T0G 1E0
(780) 523-0602

INVOICE

Invoice No.: 4185
Date: 01/30/2025
Page: 1

Sold to:
PVT ENERGY GROUP INC.

Business No.: 795410281

Quantity	Description	Unit Price	Amount
1.0	TRAILER CVIP- FEE- - T10909 - VIN - 1T9ZL4544ES588945 - 2014- 331166 KMS-	175.00	175.00
1.0	LIGHT- ABS - 2-1/2 - 10212Y-	11.89	11.89
2.0	PIGTAIL- WIRING - PL10- 949023	6.42	12.84
2.0	GROMMET ROUND - 107003	4.95	9.90
6.0	BUTT- CONN, BLUE HT SHRINK	1.35	8.10
12.0	CABLE - TWO WIRE - ELEC - LOW TEMP- 825822	1.99	23.88
2.0	ABS SENSOR EXTENSION- ABSE09018M	24.20	48.40
2.0	ABS SENSOR - 90 DEGREE - .9M- ABS09009M	53.99	107.98
1.0	ECU - VALVE - ABS- S4005001010	1,257.14	1,257.14
1.0	VALVE SEALCO - SE110800N	132.68	132.68
8.0	90 DEGREE STREET ELBOW- X115C	9.37	74.96
12.0	45 DEGREE STREET ELBOW- X124C	9.43	113.16
2.0	1/2 " PTC X 3/8 MNPT- PC14698C	17.56	35.12
2.0	ADAPTER 3/8 SYN X 1/4 MNPT - PC14696B	15.75	31.50
2.0	PC1469SW10D - 90 DEGREE ELBOW-	33.95	67.90
2.0	ADAPTER - 90 DEGREE - 3/8 T X 3 MPT- PC 14696C	15.19	30.38
4.0	BUSHING - 110ED	6.04	24.16
2.0	FITTING- BRASS- 90 DEGREE- PTC- PC146912D	24.50	49.00
	Discount 11.63%	-2.85	-5.70
8.0	HAB846C - HOSE BRAKE 46 "	33.26	266.08
30.0	HOSE SEPARATOR , 1/2 - FS473A	3.00	90.00
8.0	WH GUARD - 22MM HUB PILOT- 5903	9.39	75.12
6.0	BRAKE SHOES- Q - PLUS NEW- C/W HDWE	103.30	619.80
6.0	BRAKE DRUM, 16.5 X 7 HEAVY DUTY DRUM	178.87	1,073.22
2.0	DRAIN VALVE W / 5 FT CABLE- 12105	13.95	27.90
2.0	S-CAM- BRAKE RH - E11867- AR2033R-	69.25	138.50
2.0	S-CAM BRAKE LH- INTRAAX - AR2032L-	69.25	138.50
4.0	S-CAM TUBE KIT- INTRAAX- ARCK448	59.25	237.00
4.0	SLACK ADJUSTER- R802487	160.24	640.96
2.0	SCOTSEAL PRO- 42627 PRO	53.99	107.98
2.0	PRO TORQ STR NUT- 4474723-	110.00	220.00
3.0	HUBCAP - FS34195- 1869C16	46.90	140.70
4.0	75W90, GL5, 1L- 30096-1L	19.39	77.56
5.0	BRAKE AND PARTS CLEANER- 313	9.45	47.25
2.0	SENSOR ABS - 90 DEGREE- ABS09018M	55.33	110.66
2.0	GREASE, HD, MOLY 3 %- 50580-MC	11.78	23.56
4.0	SHOCK ABSORBER- AR65419	89.15	356.60
4.0	3/4 X 6" NC BOLT 074346	11.82	47.28
8.0	3/4 " FLAT WASHER	1.17	9.36
8.0	BUTT- CONN, BLUE HT SHRINK	1.35	10.80
36.0	WIRE TIE - 03 " X 15 "- 55359001	0.52	18.72
4.0	TRAILER CVIP WHEELS OFF FEE- PRICE PER AXLE REMOVED-	120.00	480.00
150.0	UNIT WASH JOB- PRICE INCLUDES HIRED WASHER- PRICE PER MINUTE	2.50	375.00

All WHEELS MUST BE RETORQUED!

As a free service to all clients come back and have them retorqued within 50-100 kms of use. This is clients responsibility, should you choose to have them retorqued elsewhere, T. Yardley Contracting Ltd. is not liable for any consequences. **Total invoice amount is due within 30 days**
All overdue accounts are subject to 2% interest monthly. (24% per annum)
Thank you for your business!

Continue...

T. Yardley Contracting Ltd

4908 48th Avenue
PO Box 2838
High Prairie, Alberta T0G 1E0
(780) 523-0602

INVOICE

Invoice No.: 4185
Date: 01/30/2025

Sold to:
PVT ENERGY GROUP INC.

Business No.: 795410281

Quantity	Description	Unit Price	Amount
3.5	CONTRACT WELDER- HIRED BY T.YARDLEY- MECHANICS REMOVED AIR TANK - WELDER REPAIRED AIR TANK BRACKET - REPAIRED LIGHT BOX DRIVER SIDE REAR- MULTIPLE CRACKS FULL UNIT GREASE JOB SET UP BRAKES- ON ALL AXLES REPAIR MINOR AIR LEAKS AS NEEDED TOURQUE ALL WHEELS SUPPLY TOURQUE TAG JACK UP ALL WHEELS- INSPECT BEARINGS FULL "A" INSPECTION- ALL WHEELS REMOVED- CLEANED RIMS WHILE REMOVED TOP LHS TAIL LIGHT OUT- TRACED AND REPAIRED WIRING ABS CODES- DIAGNOSED- PLUGGED IN ABS COMPUTER- READ CODES- JACKED UP WHEELS REMOVED AND REPLACED ABS LIGHT - PIGTAIL AND GROMMET - RAN NEW TWO WIRE CORD FOR ABS LIGHT ABS LIGHT ON IN FRONT CONVERTER - REMOVED AND REPLACED SENSOR AXLE 2LHS REMOVED AND REPLACED SENSOR AXLE 2RHS REMOVED AND REPLACED ABS EXTENSION AXLE 2LHS REMOVED AND REPLACED ABS EXTENSION AXLE 2RHS FRONT AIR TANK DAMAGED- MECHANICS REMOVED FROM UNIT WELDER REPAIRED BRAKE SHOES- REPLACED- WORE BEYOND SPEC- AXLE - 2LHS BRAKE SHOES- REPLACED- WORE BEYOND SPEC- AXLE - 2RHS BRAKE DRUM- WORE BEYOND SPEC.- REPLACED AXLE 2LHS BRAKE DRUM- WORE BEYOND SPEC.- REPLACED AXLE 2RHS LOOSE WHEEL BEARINGS AXLE 1LHS - SET BEARINGS AND REPLACED HUB CAP ABS - VALVE - CORRODED TERMINALS ON FRONT CONVERTER - WOULD NOT CLICK PROPERLY- REMOVED AND REPLACED ABS VALVE WITH ALL NEW BRASS RE-PLUGGED IN ABS COMPUTER- LIGHTS CYCLED PROPLERLY REMOVED AND REPLACED FAILED PRIORITY VALVE FRONT TIED UP WIRES AND AIR LINES AXLE 2 - HANGING REMOVED AND REPLACED WORN BRAKE HOSES AXLE 2LHS REMOVED AND REPLACED WORN BRAKE HOSES AXLE 2RHS BRAKE SHOES- REPLACED- WORE BEYOND SPEC- AXLE - 3RHS BRAKE DRUM- WORE BEYOND SPEC.- REPLACED AXLE 3RHS BRAKE SHOES- REPLACED- WORE BEYOND SPEC- AXLE - 4RHS BRAKE DRUM- WORE BEYOND SPEC.- REPLACED AXLE 4RHS BRAKE SHOES- REPLACED- WORE BEYOND SPEC- AXLE - 3LHS BRAKE DRUM- WORE BEYOND SPEC.- REPLACED AXLE 3LHS BRAKE SHOES- REPLACED- WORE BEYOND SPEC- AXLE - 4LHS BRAKE DRUM- WORE BEYOND SPEC.- REPLACED AXLE 4LHS REPLACED S-CAM AND TUBE- WORE BEYOND SPEC- REMOVED SLACK- AXLE - 3LHS REPLACED S-CAM AND TUBE- WORE BEYOND SPEC- REMOVED SLACK- AXLE - 3RHS REPLACED S-CAM AND TUBE- WORE BEYOND SPEC- REMOVED SLACK- AXLE - 4RHS	140.00	490.00

All WHEELS MUST BE RETORQUED!

As a free service to all clients come back and have them retorqued within 50-100 kms of use. This is clients responsibility, should you choose to have them retorqued elsewhere, T. Yardley Contracting Ltd. is not liable for any consequences. **Total invoice amount is due within 30 days**
All overdue accounts are subject to 2% interest monthly. (24% per annum)
Thank you for your business!

Continue...

T. Yardley Contracting Ltd
4908 48th Avenue
PO Box 2838
High Prairie, Alberta T0G 1E0
(780) 523-0602

INVOICE

Invoice No.: 4185
Date: 01/30/2025
Page: 3

Sold to:
PVT ENERGY GROUP INC.

Business No.: 795410281

Quantity	Description	Unit Price	Amount
	REPLACED S-CAM AND TUBE- WORE BEYOND SPEC- REMOVED SLACK- AXLE - 4LHS WHEEL SEAL LEAK- REMOVED HUB-REMOVED SEAL- INSPECTED HUB- INSTALLED SEAL 3LHS WHEEL SEAL LEAK- REMOVED HUB-REMOVED SEAL- INSPECTED HUB- INSTALLED SEAL 4LHS INSTALLED PRO TOURQUE AXLE NUT AXLE 3LHS INSTALLED PRO TOURQUE AXLE NUT AXLE 4LHS INSTALLED NEW HUB CAP AXLE 3LHS INSTALLED NEW HUB CAP AXLE 4LHS REPLACED WORN AND LEAKING SHOCK AXLE 4LHS REPLACED WORN AND LEAKING SHOCK AXLE 4RHS REMOVED AND REPLACED WORN BRAKE HOSE AXLE 4LHS REMOVED AND REPLACED WORN BRAKE HOSE AXLE 4RHS REMOVED AND REPLACE ABS SENSOR AXLE 4LHS REMOVED AND REPLACED ABS SENSOR AXLE 4RHS REMOVED AND REPLACED AIR TANK DRAIN REMOVED AND REPLACED WORN SLACK ADJUSTER 3LHS REMOVED AND REPLACED WORN SLACK ADJUSTER 3RHS REMOVED AND REPLACED WORN SLACK ADJUSTER AXLE 4LHS REMOVED AND REPLACED WORN SLACK ADJUSTER AXLE 4RHS		
30.0	LABOUR - JOB PERFORMED OVER 4 DAYS -	145.00	4,350.00
	Discount 3.45%	-5.00	-150.00
1.0	SHOP SUPPLIES- MISC PARTS	113.00	113.00
	Subtotal:		12,343.84
	G - GST 5%		
	GST/HST		617.24

All WHEELS MUST BE RETORQUED!

As a free service to all clients come back and have them retorqued within 50-100 kms of use. This is clients responsibility, should you choose to have them retorqued elsewhere, T. Yardley Contracting Ltd. is not liable for any consequences. **Total invoice amount is due within 30 days**
All overdue accounts are subject to 2% interest monthly. (24% per annum)
Thank you for your business!

Total Amount	12,961.08
Amount Paid	0.00
Amount Owing	**12,961.08**

T. Yardley Contracting Ltd

4908 48th Avenue
PO Box 2838
High Prairie, Alberta T0G 1E0
(780) 523-0602

INVOICE

Invoice No.: 4186
Date: 01/30/2025
Page: 1

Sold to:
PVT ENERGY GROUP INC.

Business No.: 795410281

Quantity	Description	Unit Price	Amount
	- T10909 - VIN - 1T9ZL4544ES588945 - 2014- 331166 KMS- TIRE INVOICE- DURRING CVIP -		
12	TIRE- IRON HEAD- 11R24.5 - 0210543 -	408.99	4,907.88
12	ENVIRO FEE- PER TIRE	14.00	168.00
12	TIRE CHANGE OVER FEE	37.00	444.00
	-ALL TIRES FAILED CVIP- EITHER CORDS SHOWING OR TRED BELOW SPEC		
	REMOVED AND REPLACED TIRES AXLE 1LHS		
	REMOVED AND REPLACED TIRES AXLE 1RHS		
	REMOVED AND REPLACED TIRES AXLE 2LHS		
	REMOVED AND REPLACED TIRES AXLE 2RHS		
	REMOVED AND REPLACED TIRES AXLE 3LHS		
	REMOVED AND REPLACED TIRES AXLE 3RHS		
	SUPPLIED TOURQUE TAG		
	TOURQUED ALL WHEELS TO SPEC		
	Subtotal:		5,519.88
	G - GST 5%		
	GST/HST		275.99

All WHEELS MUST BE RETORQUED!

As a free service to all clients come back and have them retorqued within 50-100 kms of use. This is clients responsibility, should you choose to have them retorqued elsewhere, T. Yardley Contracting Ltd. is not liable for any consequences. **Total invoice amount is due within 30 days**
All overdue accounts are subject to 2% interest monthly. (24% per annum)
Thank you for your business!

Total Amount	5,795.87
Amount Paid	0.00
Amount Owing	**5,795.87**