



Maintenance Log for EX.0284 - 323FL Excavator

		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
32437	Prep for sale	17-Sep-26	17-Sep-26	11795		
1	Prep for sale					
32347	Swivel guards punched up on rock hammering (J381)	02-Sep-26	02-Sep-26	11760		
1	Swivel guards punched up on rock hammering (J381)					
32345	Replace Broken track load roller x 1	02-Sep-26	02-Sep-26	11760		
1	Replace Broken track load roller x 1					
32230	250hr service	17-Aug-26	17-Aug-26	11682		
	250hr Service					
32132	Repair boom crack on RHS	31-Jul-26	31-Jul-26	11606		
1	Repair boom crack on RHS					
32103	Reseal Leaking LHS track adjuster assy	27-Jul-26	27-Jul-26	11595		
1	Reseal track adjuster					
31903	Monitor/ repair excess movement in boom to chassis pin	18-Jun-26	18-Jun-26	11516		
1	Monitor/ repair excess movement in boom to chassis pin					
31902	Replace U/S remote engine oil filter hoses	18-Jun-26	18-Jun-26	11516		
1	Replace U/S remote engine oil filter hoses					
31901	Replace U/S LHS attachment hose valve to boom	18-Jun-26	18-Jun-26	11516		
1	Replace U/S LHS attachment hose valve to boom					
31900	Replace OOD fire extinguisher	18-Jun-26	18-Jun-26	11516		
1	Replace OOD fire extinguisher					



Maintenance Log for EX.0284 - 323FL Excavator

		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
31899	Replace cracked window washer bottle	18-Jun-26	18-Jun-26	11516		
1	Replace cracked window washer bottle					
31898	Replace OOD seat belt	18-Jun-26	18-Jun-26	11516		
1	Replace OOD seat belt					
31840	500hr service	01-Jun-26	01-Jun-26	11439		
	500hr Service					
31680	Replace blown hammer hose	09-Apr-26	09-Apr-26	11256		
1	Replace blown hammer hose					
31672	Hammer Operation Check	31-Mar-26	31-Mar-26	11220		
1	Hammer Operation Check					
31635	Replace blown hose	24-Mar-26	24-Mar-26			
1	Replace blown hose					
31632	250hr Service	24-Mar-26	24-Mar-26			
	250hr Service					
31578	Install hammer	11-Mar-26	11-Mar-26			
1	Install hammer					
31255	Replace damaged quick connect hyd fittings	08-Jan-26	19-Dec-25			
1	Replace damaged fittings					
31223	1000hr Service	16-Dec-25	16-Dec-25	10978		
	1000hr Service					
30954	Blown hose	11-Nov-25	11-Nov-25	10848		
1	Blown hose					

Maintenance Log for EX.0284 - 323FL Excavator

		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
30773	Tilt hitch cracks	17-Oct-25	17-Oct-25	10744		
1	Tilt hitch cracks					
30758	250hr Service	14-Oct-25	14-Oct-25	10710		
	250hr Service					
30754	Hydraulic leak on boom	13-Oct-25	13-Oct-25			
1	Hydraulic leak on boom					
30702	Intermittent emissions fault	03-Oct-25	03-Oct-25			
1	Intermittent emissions fault					
30655	A/C repairs	30-Sep-25	30-Sep-25			
1	A/C repairs					
30576	Tracking fault	22-Sep-25	22-Sep-25	10533		
1	Tracking fault					
30516	Replace rusted out exhaust stack	11-Sep-25	11-Sep-25	10532		
1	Replace rusted out exhaust stack					
30465	Crack repairs to bucket	01-Sep-25	01-Sep-25	10505		
1	Crack repairs to bucket					
30446	Carry out Fire RA 5 yearly review	26-Aug-25	26-Aug-25	10483		
1	Complete RA					
30423	Replace u/s grease nipples	21-Aug-25	21-Aug-25	10483		
1	Replace u/s grease nipples					
30422	Inspect tilt bucket operation	21-Aug-25	21-Aug-25	10483		
1	Inspect tilt bucket operation					



Maintenance Log for EX.0284 - 323FL Excavator

		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
30387	Repair emission fault drain Ad Blue tank	18-Aug-25	18-Aug-25	10464		
1	Drain and clean ad blue tank					
30376	Replace Failed bucket cylinder	14-Aug-25	14-Aug-25	10461		
1	Replace Failed bucket cylinder					
2	Bypass sensor					
30368	500hr service	13-Aug-25	13-Aug-25	10461		
500hr Service						
30360	Replace Batteries	13-Aug-25	13-Aug-25	10461		
1	Replace Batteries					
30300	Bucket cylinder fault	28-Jul-25	28-Jul-25	10461		
1	Repair cylinder					
30298	Inspect tracks and adjust	28-Jul-25	28-Jul-25	10461		
1	Adjust tracks					
30044	Replace U/S hyd hose in pump room	18-Jun-25	18-Jun-25	10335		
1	Replace U/S hyd hose in pump room					
29838	Repair door latch	12-May-25	12-May-25	10277		
1	Repair latch					
2	Repair latch					
29824	Repair broken hammer grease line	08-May-25	08-May-25	10267		
1	Repair grease line					
29810	Replace broken hose bracket on back of boom	05-May-25	05-May-25	10248		
1	Replace broken hose bracket on back of boom					



Maintenance Log for EX.0284 - 323FL Excavator

		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
29788	Replace U/S crank without inject switch guard	30-Apr-25	30-Apr-25	10248		
1	Replace U/S crank without inject switch guard					
29760	Fabricate mesh screen and frame	22-Apr-25	22-Apr-25			
1	Fabricate mesh screen and frame					
29745	Repair boom light wiring	16-Apr-25	16-Apr-25	10243		
1	Repair boom light wiring					
29737	Replace U/S hydraulic hoses	15-Apr-25	15-Apr-25	10243		
1	Replace U/S hydraulic hoses					
29707	250 hour service	09-Apr-25	09-Apr-25	10227		
250hr Service						
29633	Repair stick crack	31-Mar-25	31-Mar-25	10185		
1	Repair stick crack					
29537	Stick sensor fault	18-Mar-25	18-Mar-25	10127		
1	Stick sensor fault					
29349	2000 hour service	11-Feb-25	11-Feb-25			
2000hr Service						
29341	12 Monthly pressure vessel inspection	10-Feb-25	10-Feb-25	9953		
1	12 Monthly pressure vessel inspection					
29338	2 way fault	10-Feb-25	10-Feb-25			
1	2 way fault					
29302	Replace missing fuel cap lock	05-Feb-25	05-Feb-25			
1	Replace missing fuel cap lock					

Maintenance Log for EX.0284 - 323FL Excavator

		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
29275	Counterweight damage (Hornsby 332)	30-Jan-25	30-Jan-25			
1	Repair damage					
29189	Replace u/s A/C compressor	14-Jan-25	14-Jan-25	9892		
1	Replace u/s A/C compressor					
29188	Replace blown boom hose	14-Jan-25	14-Jan-25			
1	Replace blown boom hose					
29179	Bucket repairs	13-Jan-25	13-Jan-25	9886		
1	Bucket repairs					
29148	Repair A/C	07-Jan-25	07-Jan-25	9886		
1	Repair A/C					
29147	Replace blown/ u/s drive motor hoses	07-Jan-25	07-Jan-25			
1	Replace blown/ u/s drive motor hoses					
29034	Inspect LH track tension	29-Nov-24	29-Nov-24			
1	Inspect LH track tension					
29033	Inspect fuel gauge	29-Nov-24	29-Nov-24			
1	Inspect fuel gauge					
28951	Front window damage (354.0100.045)	14-Nov-24	14-Nov-24	9770		
1	Front window damage (354.0100.045)					
28905	Replace u/s engine oil cap O'ring	11-Nov-24	11-Nov-24			
1	Replace u/s engine oil cap O'ring					
28863	Replace blown hose	06-Nov-24	06-Nov-24			
1	Replace blown hose					



Maintenance Log for EX.0284 - 323FL Excavator

		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
28832	Stick cylinder leak	04-Nov-24	04-Nov-24	9747		
1	Stick cylinder leak					
28804	250 hour service	28-Oct-24	28-Oct-24			
	250hr Service					
28797	Reseal quick hitch fitting	25-Oct-24	25-Oct-24	9707		
1	Reseal quick hitch fitting					
28492	Install hammer	30-Jul-24	30-Jul-24			
1	Plumb up hammer					
28491	500 hour service	30-Jul-24	30-Jul-24	9477		
	500hr Service					
28300	Reinstall belly guard	28-May-24	28-May-24			
1	Reinstall belly guard					
28290	Reseal swivel motor	23-May-24	23-May-24			
1	Reseal swivel motor					
28267	Repair tilt bucket	15-May-24	15-May-24			
1	Repair tilt bucket					
28266	500 hr service	15-May-24	15-May-24			
	500hr Service					
28253	Install hammer rock guard	09-May-24	09-May-24			
1	Install hammer rock guard					
28213	Replace u/s electric lift pump	19-Apr-24	19-Apr-24			
1	Replace u/s electrical lift pump					
28115	Replace faulty EGR valve	03-Apr-24	03-Apr-24			
1	Replace faulty EGR valve					



Maintenance Log for EX.0284 - 323FL Excavator

		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
28058	Diagnose RH track not holding tension	20-Mar-24	20-Mar-24			
	1 Diagnose RH track not holding tension					
28057	9000 hour service defects	20-Mar-24	20-Mar-24			
	1 Replace adblue door latch					
	2 Replace hose in pump room					
27998	Swap tilt buckets	27-Feb-24	27-Feb-24	8960		
	1 Replace fittings to swap buckets					
27972	1000hr Service	22-Feb-24	22-Feb-24	8915		
	1000hr Service					
27895	Tilt bucket pin retainer broken	01-Feb-24	01-Feb-24			
	1 Replace retainer bolts					
27849	Bucket repairs	22-Jan-24	22-Jan-24			
	1 Bucket repairs					
	2 Bucket repairs					
27805	Replace worn GP bucket tips	11-Jan-24	11-Jan-24			
	1 Replace worn GP bucket tips					
27800	Complete a 103 inspection	10-Jan-24	10-Jan-24			
	1 Complete a 103 inspection					
27799	Replace cracked out front access step panel	10-Jan-24	10-Jan-24			
	1 Replace cracked out front access step panel					
	2 replace Unit number on panel					
27767	250hr Service	19-Dec-23	19-Dec-23	8749		
	250hr Service					



Maintenance Log for EX.0284 - 323FL Excavator

		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
27731	Replace u/s extinguishers	12-Dec-23	12-Dec-23			
1	Replace u/s extinguishers					
27576	Replace Failed RHS Track adjuster recoil group	06-Nov-23	06-Nov-23			
1	Replace Failed RHS Idler					
2	Reolace U/S RHS Track adjuster recoil assy					
27470	Replace U/S tilt bucket hose/ Fitting	10-Oct-23	10-Oct-23			
1	Replace U/S tilt bucket hose/ Fitting					
27424	500hr service	27-Sep-23	27-Sep-23	8522		
	500hr Service					
27393	Replace U/S Pump to control valve hoses	19-Sep-23	19-Sep-23	8522		
1	Replace U/S Pump to control valve hoses					
27392	Replace out of date seat belt	19-Sep-23	19-Sep-23	8522		
1	Replace out of date seat belt					
27391	Repair fuel priming pump	19-Sep-23	19-Sep-23	8522		
1	Repair fuel priming pump					
27290	Replace failed LHS track adjuster recoil assy	29-Aug-23	29-Aug-23			
1	Replace failed LHS track adjuster recoil assy					
27217	Replace 1 x worn out carrier roller	09-Aug-23	09-Aug-23			
1	Replace 1 x worn out carrier roller					
27213	Repair blown tilt bucket hose	07-Aug-23	07-Aug-23			
1	Repair blown tilt bucket hose					



Maintenance Log for EX.0284 - 323FL Excavator

		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
27193	12 Monthly pressure vessel inspection	01-Aug-23	01-Aug-23	8372		
12 Monthly pressure vessel inspection						
27164	284 250hr service	25-Jul-23	25-Jul-23	8262		
250hr Service						
27141	Replace Failed DEF pump	21-Jul-23	21-Jul-23			
1 Replace Failed DEF pump						
27105	Repair worn out tilt bucket	12-Jul-23	12-Jul-23			
1 Repair worn out tilt bucket						
2 Repair worn out tilt bucket						
3 Repair worn out tilt bucket						
27053	Fittings for hyd hammer	06-Jul-23	06-Jul-23			
1 Fittings for hyd hammer						
26991	Replace unserviceable tilt hitch hose & fitting	22-Jun-23	22-Jun-23			
1 Replace unserviceable tilt hitch hose & fitting						
26923	Fire extinguisher u/s	01-Jun-23	01-Jun-23			
1 Fire extinguisher u/s						
26913	Upgrade GPS to 5G Modem	30-May-23	30-May-23			
1 5G Modem						
26860	2000hr	16-May-23	18-May-23			
2000hr Service						
26733	750hr service	28-Mar-23	28-Mar-23			
250hr Service						

Maintenance Log for EX.0284 - 323FL Excavator

		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
26578	Cutting edges	15-Feb-23	15-Feb-23			
1	Cutting edges					
26473	500hr service	09-Jan-23	09-Jan-23			
	500hr Service					
26337	Blown hyd hose - stick cylinder	17-Nov-22	17-Nov-22			
1	Blown hose					
26319	Nox fault code - Westrac W/O 26031	08-Nov-22	08-Nov-22	6797		
1	Nox code					
26312	250hr service	08-Nov-22	08-Nov-22	7240		
	250hr Service					
26249	Tilt bucket repair	10-Oct-22	10-Oct-22			
1	Tilt bucket repairs					
26210	Fit up grabs	23-Sep-22	23-Sep-22	7059		
1	Grabs					
26203	Add elc extender	21-Sep-22	21-Sep-22	7059		
1	Bad elc sample					
26179	Repair a/c	14-Sep-22	14-Sep-22	7042		
1	Repair a/c					
26150	Windscreen washers u/s	01-Sep-22	01-Sep-22	7011		
1	windscreen washers					
26120	Bucket edge	23-Aug-22	23-Aug-22	6960		
1	Bucket edge					



Maintenance Log for EX.0284 - 323FL Excavator

		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
26111	1000hr service	19-Aug-22	19-Aug-22	6946		
1000hr Service						
26067	Replace blown tilt hoses	09-Aug-22	09-Aug-22	6884		
1 Replace blown tilt hoses						
26031	Nox fault code	20-Jul-22	20-Jul-22			
1 Nox fault code						
25975	12 Monthly pressure vessel inspection	30-Jun-22	08-Jun-22			
12 Monthly pressure vessel inspection						
25953	750hr service	21-Jun-22	21-Jun-22		6771	
250hr Service						
25927	Pressure vessel inspection	09-Jun-22				
1 Pressure bvessel inspection						
25809	500hr service	10-May-22	10-May-22	6489		
500hr Service						
25800	Adjust tracks	09-May-22	09-May-22			
1 Adjust tracks						
25713	Slew fault	11-Apr-22	11-Apr-22			
1 Slew fault						
25684	Fire extinguisher bracket cracked	05-Apr-22	05-Apr-22			
1 Inspect fire extinguisher bracket and repair as needed						
25662	Link assemblies	29-Mar-22	29-Mar-22			
1 Link assemblies						



Maintenance Log for EX.0284 - 323FL Excavator

		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
25644	Replace worn track assemblies	24-Mar-22	24-Mar-22	6346		
1	Replace worn track assemblies					
25625	Refit body pannel	18-Mar-22	17-Mar-22			
1	Refit body pannel					
25599	Repair flashing light	08-Mar-22	08-Mar-22	6248		
1	Repair flashing light					
25597	Replace batteries	07-Mar-22	07-Mar-22	6248		
1	Replace batteries					
25577	250hr service	28-Feb-22	28-Feb-22		6242	
	250hr Service					
25467	Replace load roller	25-Jan-22	25-Jan-22			
1	Replace load roller					
25464	Replace cutting edge	25-Jan-22	25-Jan-22	6086		
1	Replace cutting edge					
25463	2000hr Service	25-Jan-22	25-Jan-22		6077	
	2000hr Service					
25454	Repair eng hood	21-Jan-22	21-Jan-22	6077		
1	Repair eng hood					
25393	1000hr service	15-Dec-21	15-Dec-21		6077	
	1000hr Service					
25335	Bucket repairs	16-Nov-21	16-Nov-21			
1	Bucket repairs					
2	Cylinder repair					



Maintenance Log for EX.0284 - 323FL Excavator

		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
25289	750hr service	01-Nov-21	01-Nov-21		5828	
250hr Service						
25277	Replace blown hyd hose	28-Oct-21	28-Oct-21			
1 Replace blown hyd hose						
25267	Repair bonnet stay	25-Oct-21	25-Oct-21	5764		
1 Repair bonnet stay						
25266	Repair coolant leak	25-Oct-21	25-Oct-21	5764		
1 Repair coolant leak						
25223	Replace stick GPS harness	07-Oct-21	14-Oct-21			
1 Replace stick GPS harness						
25207	Replace blown hyd hose	29-Sep-21	29-Sep-21			
1 Replace blown hyd hose						
25193	Replace cutting edge	22-Sep-21	22-Sep-21			
1 Replace cutting edge						
25114	Re-sample rh f/drive	23-Aug-21	23-Aug-21	5502		
1 rh f/drive re-sample						
25096	Repair seized quick hitch	12-Aug-21	12-Aug-21			
1 Repair seized quick hitch						
25086	500hr service	09-Aug-21	09-Aug-21		5486	
500hr Service						
24988	250hr service	18-Jun-21	18-Jun-21		5290	
250hr Service						
24970	EGR Fault	08-Jun-21	08-Jun-21	5244		
1 EGR fault						

Maintenance Log for EX.0284 - 323FL Excavator

		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
24965	Repair oil leak stick cylinder	03-Jun-21	03-Jun-21	5226		
1	Repair oil leak at stick cylinder					
24945	Replace pilot hose	27-May-21	27-May-21			
1	Replace pilot hose					
24922	Inspect quick hitch	20-May-21	20-May-21	5190		
1	Inspect quick hitch					
24899	Diaognose engine fault code	12-May-21	12-May-21	5130		
1	Diaognose engine fault code					
24852	Repair hyd oil leak	30-Apr-21	30-Apr-21	5101		
1	Repair hyd oil leak					
24832	Pressure vessel inspection	23-Apr-21	23-Apr-21	5062		
12	Monthly pressure vessel inspection					
24812	Replace carrier roller job cost 317.0100.045	19-Apr-21	19-Apr-21			
1	Replace carrier roller job cost					
24787	Repair quick hitch not releasing	14-Apr-21	14-Apr-21	5019		
1	Repair quick hitch not releasing					
24725	1000hr service	16-Mar-21	16-Mar-21	4978	4978	
1000hr	Service					
24649	Repair track adjuster	18-Feb-21	18-Feb-21	4877		
1	Repair track adjuster					
24641	Linebore tilt bucket centre pin ears	16-Feb-21	16-Feb-21			
1	Linebore tilt bucket centre pin ears					

Maintenance Log for EX.0284 - 323FL Excavator

		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
24601	Diagnose DPF fault	05-Feb-21	05-Feb-21	4820		
1	Diaognose DPF fault					
24532	250hr service	14-Jan-21	14-Jan-21	4769	4810	
	250hr Service					
24488	Bucket repairs	06-Jan-21	06-Jan-21			
1	Bucket repairs					14/01 Repair cracks in tilt bucket 15/01 Continue with repairing cracks in tilt bucket 18/01 Continue with repairs to cracks in tilt bucket
24337	Grease & fuel machine, repair leaks from tilt bucket hoses	11-Nov-20	11-Nov-20	4683		
1	Grease & fuel machine					
2	Repair oil leaks from tilt bucket hoses					
24245	500hr Service	16-Oct-20	16-Oct-20	3616	3616	
	500hr Service					
24176	Calibrate tilt bucket	28-Sep-20	28-Sep-20	4460		
1	Calibrate tilt bucket					
24158	Replace GPS connections for cable repairs	18-Sep-20	18-Sep-20			
1	Replace GPS connections for cable repairs					
24121	Replace faulty tilt bucket cable	14-Sep-20	14-Sep-20	4406		
1	Replace faulty tilt bucket cable					
24118	Top up ad blue & grease machine	11-Sep-20	11-Sep-20	4406		
1	Top up ad blue & grease machine					

Maintenance Log for EX.0284 - 323FL Excavator

		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
24035	Jump start machine - faulty battery isolator	19-Aug-20	19-Aug-20	4388		
1	Jump start machine					
2	Replace faulty battery isolator					19/8 Diagnosed no- start - faulty isolator
23991	Inspect machine	10-Aug-20	10-Aug-20	4384		
1	Inspect machine					
23939	Inspect machine & change out filters	29-Jul-20	29-Jul-20	4383		
1	Inspect machine & change out filters					
23886	Adblue low	20-Jul-20	20-Jul-20			
1	Adblue low					took adblue to machine as was getting low.
23721	Clean tilt bucket & prepare for wear strip replacement	17-Jun-20	17-Jun-20	4288		
1	Clean tilt bucket & prepare for wear strip replacement					18/6 weld wear strips to bottom of tilt bucket
23716	Replace tilt bucket quick connects	17-Jun-20	17-Jun-20	4288		
1	Replace tilt bucket quick connects					
23715	Check over machine, repair liights & replace cab filters	17-Jun-20	17-Jun-20	4288		
1	Check over machine, repair liights & replace cab filters					
23630	Wash machine	03-Jun-20	03-Jun-20	4276		
1	Wash machine					
23597	Check emission fault - run purge cycle for adblue	28-May-20	28-May-20	4281	4281	
1	Check emission fault - run purge cycle for adblue					Isolate & test.



Maintenance Log for EX.0284 - 323FL Excavator

		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
23586	Replace crushed/pinched tilt bucket hose	28-May-20	28-May-20	4281		
1	Replace crushed/pinched tilt bucket hose					
23454	Replace leaking fittings on tilt bucket cylinders & hoses	13-May-20	13-May-20	4273		
1	Replace leaking fittings on tilt bucket cylinders & hoses					
23447	Diagnose GPS sensor fault - repaired tilt bucket sensor leak	12-May-20	12-May-20	4273		
1	Diagnose GPS sensor fault - repaired tilt bucket sensor leak					cleaned connections
23434	Repair oil leaks in tilt bucket	12-May-20	12-May-20	4270		
1	Repair oil leaks in tilt bucket					11/05 Repair hyd leak from tilt bucket cyl hose fittings - replace worn hose - ID Parts.
23428	Remove battery terminals & clean	08-May-20	08-May-20	4273		
1	Remove battery terminals & clean					
23427	Adjust tracks	08-May-20	08-May-20	4273		
1	Adjust tracks					
23407	Inspect machine	05-May-20	05-May-20			
1	Inspect machine					
23337	Replace blown tilt bucket hose	24-Apr-20	24-Apr-20	4232		
1	Replace blown tilt bucket hose					
2	Grease machine & fill adblue					

Maintenance Log for EX.0284 - 323FL Excavator

		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
23331	Fill adblue tank, grease machine, repair hyd leaks & hyd iss	21-Apr-20	21-Apr-20	4232		
	1 Fill adblue tank & test system					
	2 Grease machine					
	3 Repair hyd leak fron tilt bucket cyl hoses					re-orientate bucket hoses & measure up hose.
	4 Check hyd issue - cancel out preset bench height in screen					
23329	Replace tilt bucket hoses	22-Apr-20	22-Apr-20			
	1 Replace tilt bucket hoses					
23223	250hr Service	30-Mar-20	30-Mar-20	4136	4273	
	250hr Service					
23139	Replace faulty EC250	09-Mar-20	09-Mar-20	4011		
	1 Replace faulty EC250					19/3 inspect radio not working properly
23130	March maintenance work order	05-Mar-20	05-Mar-20	3994		
	1 GPS					4/03 Check connections at control module - 3994hrs 11/03 Disconnect tilt bucket sensor cable - 4033hrs
	2 Hyd work					9/03 Re-sealed loose/leaking fitting on LHS tilt bucket hose - 4022hrs
	3 Engine					12/03 Inspect emissions fault - run diagnostic test, fault cleared.
	4 Body work					3/03 Clean out tilt bucket - gouge out cracks in bottom side plates & repair, weld chocki bar up face face.
	5 GET					16/03 Remove tilt bucket - 4052hrs
23113	Defects from 4000hr service	03-Mar-20	03-Mar-20	3978		
	1 Dent in C Channel below pump room door					
23043	2000hr Service	17-Feb-20	17-Feb-20	3940	3978	
	2000hr Service					
23011	Feb maintenance work order	01-Feb-20	01-Feb-20	3865		

Maintenance Log for EX.0284 - 323FL Excavator

		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
1	GPS					4/02 Repair faulty GPS cable on tilt bucket 10/02 Replace connectors from GPS tilt bucket repair
2	GET					7/2 Replace worn GP bucket tips 13/02 Remove bucket teeth on GP & measure - refit, Re-installed old bucket teeth - new incorrect, Replace incorrect bucket teeth 19/02 Replace bucket teeth 23/2 Straighten tilt bucket center pin ears. Gouge out cracks and repair. Cut out gussets and weld on front of bucket to stop flex.
3	Safety					10/02 6 monthly fire extinguisher inspection
4	Body work					10/02 Check broken tilt bucket cylinder pin - change bucket, Replace cylinder pin on tilt bucket 17/02 Removed snapped pin from tilt cylinders- clean & fit new pin, tap out retaining bolt hole & refit. 18/02 Fit up tilt bucket
22957	Jan maintenace work order	06-Jan-20	06-Jan-20	3732		
1	Inspection & maintenance					13/01 Inspect machine
2	GET					14/01 Turn tilt bucket edge 15/01 Remove tilt bucket edge, clean - rotate & re-fit. 20/1 disassemble tilt bucket and inspect 23/01 Assemble bucket, install bucket hitch
3	Electrical					15/01 Inspected in-op door alarm - unplugged, plugged in and tested ok.
4	Body work					21/01 Pick up press kit for bucket repairs 22/01 bucket repairs, Set-up press & try to press bent centre pin ear straight on tilt bucket 23/01 Straighten centre pin ears, gouge out cracks in top of bucket & weld. Cut new gussets & weld on front ear to stop flex - re-fit hitch & cylinders
5	Hyd work					23/01 Repair leak fron tilt bucket fitting
22952	250hr Service	13-Jan-20	13-Jan-20	3731	3752	
1	250hr Service					

Maintenance Log for EX.0284 - 323FL Excavator

		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
22895	Defects from 500hr Service	11-Dec-19	27-Nov-19	3516		
1	Safety					27/11 Door alarm inop
2	Hydraulic					27/11 Oil found around swing breather
22880	Dec maintenance work order	01-Dec-19	01-Dec-19	3557		
1	Inspection & maintenance					2/12 Replace final drive oils
2	Hyd work					2/12 Repair leak from tilt bucket hose fitting. 5/12 Fit tilt bucket fittings on new bucket - test ok. 10/12 Replace leaking quick hitch pipe - cracked 16/12 Remove & replace blown quick hitch pipe on boom
3	Body work					4/12 Inspect damage to bucket - centre pin walked out. 5/12 Fill swing gear grease
4	GET/Attachments					5/12 Unload spare bucket to replace broken bucket. 10/12 Replace leaking tilt bucket elbows.
22784	November Maintenance Work Order	01-Nov-19	01-Nov-19	3418		
1	Hydraulics					7/11 change bucket flow direction
22768	500hr Service	05-Nov-19	05-Nov-19	3400	3516	
1	500hr Service					
22731	Man new Rod for tilt cylinder on bucket	22-Oct-19	22-Oct-19	3314		
1	Man new Rod for tilt cylinder on bucket					

Maintenance Log for EX.0284 - 323FL Excavator

		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
22697	Oct maintenance work order	09-Oct-19	09-Oct-19	3254		
1	replace failed quick hitch couplers					3/10 Replaced cracked hyd fitting on hyd block
2	Fit new real in ram gland					
3	Electrical Work					21/10 Inspect electrical fault 22/10 Inspect wiring & connectors - found dirty plug t back of cab.
4	Inspection & maintenance					21/10 Clean radiator.
5	Reduce tilt bucket flow rate					
6	Engine works					
22673	250hr Service	02-Oct-19	02-Oct-19	3228	3261	
1	250hr Service					
22669	Fitment of hammer	12-Sep-19	12-Sep-19	3120		
1	Fit hammer					17/9 Inspect flow rate on hyd, adjust to spec for hammer.
22555	Aug maintenance work order	01-Aug-19	01-Aug-19			
1	Engine work					1/08 Inspect for minor vibration coming through machine.
2	Body work					8/8 Inspect tilt bucket for leaking cylinder & pin movement 19/8 Load buckets for transport
3	Hyd work					20/8 Replace short tilt bucket hoses & fittings. Slow flow rate on tilt bucket. 28/8 Repair leaking tilt ram cylinder due to pitting of ram rod.
22549	1000hr Service	12-Aug-19	12-Aug-19	3020	3020	
1	1000hr Service					
22484	July Maintenance work order	01-Jul-19	01-Jul-19	2730		
1	Hyd work					11/7 Replace hyd hose 29/7 Replace blown tilt bucket hose
2	Inspection & service work					19/7 Inspect machine & top up hyd oil 26/7 Supply grease gun for machine & ad blue

Maintenance Log for EX.0284 - 323FL Excavator

		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
22456	250 Hr Service	27-Jun-19	27-Jun-19	2717	2750	
1	250 Hr Service					Completed 2/7/19 2750 Hrs B Avery
22394	May Pressure Vessell Checks	20-May-19	20-May-19	2553		
1	May Pressure Vessell Check					12/6 Pressure vessel inspection.
22390	Inspect tilt bucket cyinder leak	17-May-19	17-May-19	2553		
1	Inspect tilt bucket cyinder leak					
22365	500 Hr Service	08-May-19	08-May-19	2496		
1	500 Hr Service					Completed 20/5/19 2560Hrs J Nash
2	Replace window wiper blade					
22347	Replace hyd leak on stick cylinder	18-Apr-19	18-Apr-19	2394		
1	Replace hyd leak on stick cylinder					
22268	Swap tilt buckets	13-Mar-19	13-Mar-19	2210		
1	Swap tilt buckets					
2	Re-hose tilt bucket					
22214	250 Hr Service	25-Feb-19	25-Feb-19	2205		
1	250 Hr Service					
22168	Fit tilt bucket to machine	31-Jan-19	31-Jan-19			
1	Fit tilt bucket to machine					
22060	Replace air cleaners	11-Dec-18	11-Dec-18	2103		
1	Replace air cleaners					
2	Exchange fire extinguisher					

Maintenance Log for EX.0284 - 323FL Excavator

		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
22058	Fit retaining straps	30-Nov-18	30-Nov-18	2058		
1	Fit retaining straps to hyd hoses					
2	Fix step & check bucket					
22048	Bucket repairs	19-Nov-18	19-Nov-18	2000		
1	Weld chocky bars on bucket					
21943	2000 Hr Service	25-Oct-18	25-Oct-18	1850		
1	2000 Hr Service					Completed 17/11/18 2010 Hrs D McCarthy
2	Replace flashing light					
21897	250 Hr Service	04-Oct-18	04-Oct-18	1725		
1	250 Hr Service					Completed 11/10/18 1773 hrs D McCarthy
21828	Inspect tilt bucket	12-Sep-18	12-Sep-18	1604		
1	Inspect tilt bucket					Inspect tilt bucket. Westrac inspect cracks. 8/10/18 Inspected by R Newman AB Engineering - Hard face front edge on tilt bucket .
2	Replace cutting edge					Replace cutting edge & wear strips
21732	500 Hr Service	09-Aug-18	09-Aug-18	1410		
1	500 Hr Service					Completed 21/8/18 1500 Hrs S Budden
21639	250 Hr Service	06-Jul-18	06-Jul-18	1238		
1	250 Hr Service					Completed 17/7/18 1286 Hrs D McCarthy
2	Remove,clean & refit loose bucket edge					
21564	June Adblue	14-Jun-18	05-Jun-18	997		
1	June Adblue					5/6/18 Ad blue. 20/6/18 Ad Blue 26/6/18 Ad Blue 29/6/18 Ad Blue

Maintenance Log for EX.0284 - 323FL Excavator

		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
21480	Prep for Mine	08-May-18	08-May-18	997		
1	Safety work					Mine spec, burst & segregation work. Fit door alarm. Fit bowless fuel filter Replace travel alarm to squawker. Adept conduct Pressure Vessel inspection. Double insulate battery. Total Fire conduct FRA. Fit inclinometer. make & fit fan & exhaust manifold guards. Fit FOPS to cabin. Whip check. Paint tie down points. Fit decals & Hi Vis.Fit extinguisher. Fit new UHF aerial
2	Body work					Fit handrails & paint. Weld clamp bases on tilt bucket.
3	Inspect & wash machine					
4	Engine work					Make L bracket for exhaust manifold shield.
21478	1000 Hr Service	07-May-18	07-May-18	997		
1	1000 Hr Service					Completed 8/5/18 998 Hrs M Lane
2	Turn bucket edge					
21322	250 Hr Service	01-Mar-18	01-Mar-18	757		
1	250 Hr Service					Completed 1/3/18 757 Hrs R Connor
21282	Replace bucket GET	08-Feb-18	08-Feb-18	669		
1	Replace bucket GET					
21274	Remove hand rails	06-Feb-18	06-Feb-18	637		
1	Remove hand rails					
21252	500 Hr Service	18-Jan-18	18-Jan-18	572		
1	500 Hr Service					Completed 18/1/18 572 Hrs R Connor
21233	Inspect tilt bucket fittings	12-Jan-18	12-Jan-18	540		
1	Inspect tilt bucket fittings					
21156	Fit GPS aerial to machine	03-Nov-17	03-Nov-17	303		
1	Fit GPS aerial to machine					



**Maintenance Log for
EX.0284 - 323FL Excavator**

		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
21130	250 Hr Service	23-Oct-17	23-Oct-17	247		
1	250 Hr Service					Completed 23/10/17 247 Hrs R Connor
21033	Receive & install ripper	12-Sep-17	12-Sep-17	20		
1	Receive & install ripper					No job numbers available
2	Replace ripper boot					
3	Repair log grab retainer & fit missing panel bolts					
21018	Commission New Excavator	06-Sep-17		12		
1	Commission New Excavator					
2	Install safety equipment					
3	Body work					