

P11-1

No Limit Automotive & Performance Inc.

6-73022 Township Road 704
County of Grande Prairie No. 1, AB T8W 5G5
service@nolimitautomotive.ca
accounting@nolimitautomotive.ca
780-532-6472

Home (780) 814-1111
Email
Work Order # 48847
Service Advisor BA
Technician CJ

Plate AB
Description 2022 Chevrolet Silverado 3500 HD High Country V8
6.6L 6599CC 403CID VIN Y
VIN
Unit 1GC4YTEY3NF284514
Odometer 242,382 In / 0 Out
Appointment 10/9/2025 12:39 PM
Promised 10/10/2025 5:00 PM

Concern

Engine Camshaft/ Lifter Failure

remove cab to work on engine. remove cylinder heads and front cover to replace camshaft and lifters, clean parts and reassemble engine. install delete kit. Install cab, do oil change, top up rest of fluids. Test drive. Done!!!!

Labor	45 Hour
Engine Cylinder Head Stud- No Limit Brand Gator Fasteners- 2017-2024 L5P Dmax	1 Unit
Engine Camshaft- 2017-2025 L5P DURAMAX	1 Unit
Engine Valve Lifter 2017-2024 L5P	16 Unit
Engine Valve Lifter Guide L5P	4 Unit
Engine Valve Cover Gasket - 2017+ GMC L5P	2 Unit
Fuel Injector Seal - 2017+ GMC L5P	8 Unit
Fuel Injector O-Ring - 2017+ GMC L5P (12647790)	8 Unit
Injector Return Line Seal (Engine Valve Cover Bolt Seal) - 2017+ GMC L5P	16 Unit
Engine Cylinder Head Gasket - 2017+ GMC (12676859)	2 Unit
Up-Pipe to Manifold Gasket - 2017+ GMC L5P	2 Unit
Up Pipe to Turbocharger Gasket - 2017+ GMC L5P	2 Unit
Turbocharger Mounting Gasket - 2017-2022 Chev 2500/3500HD 6.6L	1 Unit
turbo gasket - 2017-2019 GMC L5P Coolant pipe	3 Unit
Engine Front Main (Crankshaft) Seal, Duramax 6.6L, 2001+ (29606) (no substitution)	1 Unit
Engine Coolant Crossover Pipe Gasket - 2017-2021 GMC L5P(2/engine)	1 Unit
Diesel Glow Plug - 2017+ GMC L5P	8 Unit
Engine Water Pump Cover Seal- 2015-2025 L5P	1 Unit
Engine Water Pump Metal Gasket - 2001-2016 GMC Duramax (Pump to heat exchanger pipe) (251-2032)	1 Unit
Engine Coolant bypass Pipe Gasket	1 Unit
Engine Oil Filter, Duramax (88917036)	1 Unit
Engine Oil (Synthetic Diesel); Max Duty, 5W40, 10L	1 Unit
Engine Oil (Synthetic Diesel); Max Duty, 5W40, 1L	3 Unit
Dex-Cool Extended Life Antifreeze Coolant	3 Unit
Fuel Pressure Sensor - 2017+ GMC Duramax L5P (904-074 / FPS121)	1 Unit
Fuel Pressure Sensor Pigtail - 2017+ GMC/Chevy L5P (PT3744) (19367009)	1 Unit

No Limit Automotive is not liable for any parts or component failure resulting from misuse, lack of maintenance, or customer-modified performance upgrades. All new parts are covered by the manufacturer's warranty, with any warranty claim being subject to the manufacturer's discretion (labor charges excluded). Warranty work must be completed at No Limit, we will not be responsible for charges incurred through third parties.

Performance tuning is carried out at the owners own risk due to varying operational conditions.

A 25% non-refundable fee will apply to all special orders and is due upon cancellation. Returns are subject to No Limit's discretion. Any dispute regarding the invoice must be raised within 5 days, after this period, the invoice will be considered final and non-negotiable.

No Limit is not responsible for any personal property that is damaged, lost, or stolen from vehicles stored on the premises.

Warranties and their terms are in effect after 100 kilometers. If applicable, the warranty will be voided after 30 days.

10/21/2025 1:23 PM

Fasteners Heavy Duty Up-Pipe Bolt Kit for Chevy/GMC (7-25) 6.6L L5P Duramax Diesel	1 Unit
Engine Coolant Crossover Pipe Gasket - 2017-2021 GMC L5P(2/engine)	2 Unit
Air Filter - 2020+ GMC L5P (A3459C) (B4554703/A3248C)	1 Unit
Sub	\$11,404.67

Inspection

CVI Complete Vehicle Inspection

front brakes are good, rear brakes are 30% Front diff and rear diff oils are good, t case was a little low, topped up with fluid, transmission should be serviced, oil is very dark, lower ball joints have slight play, inner and outer tie rods and idler and pitman have play.

Labor	1 Hour
Sub	\$156.00

Service

EGR - GMC L5P 2020+

Full EGR for Emissions System Service and Calibration Update
Down Pipe with EGR Delete - 2020+ GMC L5P (PL-G-1720 / PL-G-20)

1 Unit

Turbocharger Gasket - 2017-2019 GMC L5P (Oil Inlet Tube/Return Pipe/WaterFeed Tube/Oil Feed Tube/Water Return Tube)

1 Unit

Sub \$1,139.96

Power Steering Pump

Remove and Replace components as required to access and install materials, and/or perform needed service. Additional fluids may be required to complete this service. Retest and verify repair as required. Perform final road test where applicable.

Labor	2 Hour
Power Steering Pump	1 Unit
Power Steering Fluid	2 Unit

Sub \$901.56

Automatic Transmission Service Diesel 10-Speed

Remove and Replace components as required to access and install materials, and/or perform needed service, adjustments as required. Additional fluids may be required to complete this service. Retest and verify repair as required. Perform final road test where applicable.

Labor	4 Hour
Transmission Filter/Screen (Internal) - 2020+ (FOR 10 SPD) (TF938)	1 Unit
Automatic Transmission Fluid - 2020+ ULV (MUST BE USED IN 10 SPD)	15 Unit
All 10L1000	
Gen 2 Low limit feed valve	1 Unit

Sub \$1,221.25

Total Parts

Total Labor

Total Before Taxes & Miscellaneous Charges

\$6,711.44

\$8,112.00

\$14,823.44

(*) Shop Supplies

(G) Canadian Goods and Services Tax (GST)

Grand Total

5 %

\$100.00 G

\$746.17

\$15,669.61

hereby authorize the repairs to be done along with the required materials and agree that you are not responsible for loss or damage to the vehicle or contents in the case of fire or theft or causes beyond your control. I hereby grant you and your employees' permission to operate the vehicle on the streets and highways or elsewhere for the purpose of testing and or inspection. I acknowledge my indebtedness for the amount of this invoice and acknowledge and agree that in the event of non-payment that the repairer is entitled to liens under any available Repair Liens or Storage Liens Legislation. This information and any other information we have in our data base is restricted to authorized personnel only. This information will be used solely for the current and future service of your vehicle, warranty registration, and any other use required by law. You have a right to a written estimate. A repairer may not charge an amount that is more than ten (10) per cent above that estimate. If you waived your right to an estimate, the repairer must have your authorization of the maximum amount that you will pay for the repairs. The repairer may not charge more than the maximum amount you authorized. In either case, the repairer may not charge for any work you did not authorize.

No Limit Automotive is not liable for any parts or component failure resulting from misuse, lack of maintenance, or customer-modified performance upgrades. All new parts are covered by the manufacturers warranty, with any warranty claims being subject to the manufacturers discretion (labor charges excluded). Warranty work must be completed at No Limit, we will not be responsible for charges incurred through third parties.

Performance tuning is carried out at the owners own risk due to varying operational conditions.

A 25% non-refundable fee will apply to all special orders and is due upon cancellation. Returns are subject to No Limit's discretion.

Any disputes regarding this invoice must be raised within 5 days, after this period, the invoice will be considered final and non-negotiable.

No Limit is not responsible for any personal property that is damaged, lost, or stolen from vehicles stored on the premises.

Please ensure that wheels are re-torqued after 100 kilometers, if applicable.

Interest will accrue on unpaid invoices after 30 days.

10/21/2025 1:23 PM

No Limit Automotive & Performance Inc.

6-73022 Township Road 704
County of Grande Prairie No. 1, AB T8W 5G5
service@nolimitautomotive.ca
accounting@nolimitautomotive.ca
780-532-6472
GST # 84166 9609

Plate AB
Description 2022 Chevrolet Silverado 3500 HD High Country V8
6.6L 6599CC 403CID VIN Y
VIN
Unit 1GC4YTEY3NF284514
Odometer 254,000
Invoice Date 12/19/2025 5:27 PM
Appointment 12/10/2025 8:49 AM
Promised 12/11/2025 5:00 PM

Invoice # 27120
Work Order # 49584
Service Advisor DT
Technician DZ

Service

Diagnose Electrical Concern

Initial diagnosis, testing and inspection of the specific vehicle system as required. Perform road test where applicable. Report test result(s), system fault(s), component(s) failure and required repair(s). Additional diagnosis and testing time may be required at additional charges.

Labor	3 Hour	\$468.00 G
Fuel Tank fuel Pump Module Kit W/Level Sensor & Seal - 2020+ GMC Silverado, Sierra 2500 HD In fuel tank. Long box. Silverado, Sierra 3500 HD Single tank 6.6L diesel, tank & mounting, 8 ft box, double, crew cab.	1 Unit	\$419.99 G
Sub		\$887.99

Total Parts	\$419.99
Total Labor	\$468.00
Total Before Taxes & Miscellaneous Charges	\$887.99
(*) Shop Supplies	\$23.40 G
(G) Canadian Goods and Services Tax (GST)	5 %
Grand Total	\$956.96

[REDACTED] - COD (Payment Due Upon Delivery)

Thanks for the Business!
I acknowledge receipt of the vehicle and the indebtedness indicated herein.

Customer Signature: _____

No Limit Automotive is not liable for any parts or component failure resulting from misuse, lack of maintenance, or customer-modified performance upgrades. All new parts are covered by the manufacturers warranty with any warranty claims being subject to the manufacturers discretion (labor charges excluded). Warranty work must be completed at No Limit, we will not be responsible for charges incurred through third party.

Performance tuning is carried out at the owners own risk due to varying operational conditions.

A 25% non-refundable fee will apply to all special orders and is due upon cancellation. Returns are subject to No Limit's discretion.

Any disputes regarding the invoice must be raised within 5 days; after this period, the invoice will be considered final and non-negotiable.

No Limit is not responsible for any personal property that is damaged, lost, or stolen from vehicles stored on the premises.

Please ensure that wheels are re-torqued after 100 kilometers, if applicable.

Interest will accrue on unpaid invoices after 30 days.

Page