

Work Order

CORNWALL

Number:

297



MINIMAX EXPRESS TRANSPORTATION INC

VIN: 3ALACXDT6HDJC2910

Make: FRHT

Model:

Year: 2017

Unit N°

374

Plate:

3235PV

☐ SCHEDULED WORK

Kilometer:

462142

Engine hours:

9107

Date opened:

2025-12-01

Date closed:

2025-12-02

T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	*\$/u*	Total
REP	045				CHRIS CHITAMBARA, 2025-12-01						
REP	045				Comment / Request						
REP	045				EGR Fault code						
REP	045				*****						
REP	045				(5427) >> TTALENT 2025-12-01 22:18:50:63						
REP	045				Diagnosed engine light with cummins insight (5427) (5427) >> OK						
REP	045				(5428) >> TTALENT 2025-12-01 22:19:38:69						
REP	045				Checked and test delta p differential sensor wiring (5428) (5428) >> OK						
REP	014				SEBASTIEN AUBIN, 2025-12-01						
REP	014				Comment / Request						
REP	014				replaced all rivets at top of box truck						
REP	014				Causes						
REP	014				wall caved in						
REP	014				Corrections						
REP	014				pushed wall out installed new rivets and silicone						
REP	014				*****						
REP	014				** START ** Source : PO# 2054						
REP	014				Transferred by : SEGUN, DANIEL - 1/13/2026						

Comment:

ENGINE

Signature :

Date :

Subtotal-parts:

362.48 +

0.00

Subtotal labor:

128.35

0.00

Shop supply:

19.25

TOTAL (\$):

510.08

Hrs. 1.51

Work Order

CORNWALL

Number:

297

MINIMAX EXPRESS TRANSPORTATION INC

Unit No

05. WORK FINISHED

VIN: 3ALACXDT6HDJC2910

Make: FRHT

Model:

Year: 2017

462142
Kilometer:

Engine hours: 9107

Date opened:	
Date closed:	

2025-12-01	2025-12-02
------------	------------



SCHEDULED WORK

[illegible]

Comment:

ENGINE

Subtotal-parts:

362.48 +

Subtotal labor:

128 35

Shop Supply.

1925

Signature :

Date :

FREE

[illegible]

L

Minimax Express Transportation

Printed: 2026-10-06 by: ST DENIS, ROLLAND

Work Order

CORNWALL

Number:

306



MINIMAX EXPRESS TRANSPORTATION INC

VIN: 3ALACXDT6HDJC2910

Make: FRHT

Model:

Year: 2017

Unit N°

374

Plate:

3235PV

☐ SCHEDULED WORK

Kilometer: 463231

Engine hours: 9132

Date opened: 2025-12-02

Date closed: 2025-12-11

T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	*\$/u*	Total
REP	045				TALENT TAMBAOGA, 2025-12-03						
REP	045				Comment / Request						
REP	045				engine light						
REP	045				Derate						
REP	045				Causes						
REP	045				egr delta p invalid signal						
REP	045				Corrections						
REP	045				plugged scan tool, derate active and egr fault code						
REP	045				performed turbo fuction test -passed						
REP	045				load Tested wiring and performed wiggle test connectors for egr sensors-passed						
REP	045				replaced egr delta p sensor and ran verification process and cleared fault codes						
REP	045				Initiated Regen and monitored values-completed						
REP	045				*****						
REP	045				(5421) >> TTALENT 2025-12-03 22:19:12:30						
REP	045				Replace Delta P sensor (5421) (5421) >> OK						
REP	045				(5894) >> TTALENT 2025-12-03 22:19:38:97						
REP	045				load test and wiggle test egr wiring (5894) (5894) >> OK						
REP	045				(5895) >> TTALENT 2025-12-03 22:19:54:20						

Comment:

safety inspection

Signature :

Date :

Subtotal-parts:

1554.57 +

0.00

Subtotal labor:

2133.50

0.00

Shop supply:

320.03

TOTAL (\$) :

4008.10

Hrs. 25.10

Work Order

CORNWALL

Number:

306



MINIMAX EXPRESS TRANSPORTATION INC

VIN: 3ALACXD6HDJC2910

Make: FRHT

Model:

Year: 2017

Unit N°

374

Plate:

3235PV

☐ SCHEDULED WORK

Kilometer:

463231

Engine hours:

9132

Date opened:

2025-12-02

Date closed:

2025-12-11

T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	*\$/u*	Total
REP	045				Regen (5895) (5895) >> OK						
REP	SAFETY	PTS1			SAFETY						
REP	051				>> VBRENNER 2025-12-08 14:18:34:03						
REP	051				@NOT317:Wire and install tablet mount						
INS	SAFETY				TERRY CLEROUX, 2025-12-08						
INS	SAFETY				Comment / Request						
INS	SAFETY				took over from vince who ordered water pump belt and tentioneer						
INS	SAFETY				*****						
INS	SAFETY				TERRY CLEROUX, 2025-12-08						
INS	SAFETY				Comment / Request						
INS	SAFETY				01-35643-065 v belt						
INS	SAFETY				5270678 tentioneer						
INS	SAFETY				pac15326614 plug						
INS	SAFETY				pac15317832b connector lock						
INS	SAFETY				pac15304719l connectors x3						
INS	SAFETY				pac12191234b seals x3a06-40131-001 turn signal clear						
INS	SAFETY				x2 one stock one ordered						
INS	SAFETY				*****						
INS	SAFETY	UF106			DEF FILTER		PTS1		1.00	127.800	127.800

Comment:

safety inspection

Signature :

Date :

Subtotal-parts: 1554.57 +

0.00

Subtotal labor: 2133.50

0.00

Shop supply: 320.03

TOTAL (\$) : 4008.10

Hrs. 25.10

Work Order

CORNWALL

Number:

306



MINIMAX EXPRESS TRANSPORTATION INC

VIN: 3ALACXDT6HDJC2910

Make: FRHT

Model:

Year: 2017

Unit No

374

Plate:

3235PV

☐ SCHEDULED WORK

Kilometer:

463231

Engine hours:

9132

Date opened:

2025-12-02

Date closed:

2025-12-11

T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	*\$/u*	Total
INS	SAFETY	HF35387			HYDRAULIC FILTERS		PTS1		1.00	12.770	12.770
INS	SAFETY				(6406) >> TCLEROUX 2025-12-08 19:04:00:49						
INS	SAFETY				replace wiring for left side of hood wires and plugs rotten and rubbed threw (64						
INS	SAFETY				TERRY CLEROUX, 2025-12-08						
INS	SAFETY				Comment / Request						
INS	SAFETY				tenioner on truck is new returning the one that vince ordered						
INS	SAFETY				powersteering was serviced						
INS	SAFETY				def pump was serviced						
INS	SAFETY				*****						
INS	SAFETY				(6403) >> TCLEROUX 2025-12-08 20:24:52:45						
INS	SAFETY				possible belt tenioner issue (6403) (6403) >> OK						
INS	SAFETY				(6407) >> TCLEROUX 2025-12-08 20:22:54:65						
INS	SAFETY				service def pump (6407) (6407) >> OK						
INS	SAFETY				TERRY CLEROUX, 2025-12-08						
INS	SAFETY				Comment / Request						
INS	SAFETY				wabco 925 380 007 disc brake maxi on drives						
INS	SAFETY										
INS	SAFETY										
INS	SAFETY										

Comment:
safety inspection

Signature : _____ Date : _____

Subtotal-parts:	1554.57 +	0.00
Subtotal labor:	2133.50	0.00
Shop supply:	320.03	
TOTAL (\$):	4008.10	Hrs. 25.10

Work Order

CORNWALL

Number:

306



MINIMAX EXPRESS TRANSPORTATION INC

VIN: 3ALACXDT6HDJC2910

Make: FRHT

Model:

Year: 2017

Unit N° 374

Plate: 3235PV

☐ SCHEDULED WORK

Kilometer: 463231

Engine hours: 9132

Date opened: 2025-12-02

Date closed: 2025-12-11

T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	*\$/u*	Total
	INS	SAFETY			power steering lines ordered be in tues dec 9						
	INS	SAFETY			trans speed sensor and pigtail ordered						
	INS	SAFETY			def pump filter ordered						
	INS	SAFETY			def pump cover ordered						
	INS	SAFETY			water pump was ordered its not in yet						
	INS	SAFETY			the tentioner is being returned the one on truck is brand new and dosnt need it						
	INS	SAFETY			Causes						
	INS	SAFETY			safety inspection i took over from vince						
	INS	SAFETY			*****						
	INS	SAFETY	107796PG		AIR FILTER DRYER		PTS1		1.00	326.680	326.680
	INS	SAFETY	343-4024		HUB CAPS		PTS1		2.00	18.590	37.180
	INS	SAFETY	WIPER 22"		WIPER BLADES		PTS1		2.00		
	INS	SAFETY			BLAKE VOLPI, 2025-12-08						
	INS	SAFETY			Comment / Request						
	INS	SAFETY			Left rear maxi has been changed by Blake.						
	INS	SAFETY			New brass used for it also.						
	INS	SAFETY			Uncaged the maxi once installed						
	INS	SAFETY			*****						

Comment:

safety inspection

Signature :

Date :

Subtotal-parts:	1654.57	+	0.00
Subtotal labor:	2133.50		0.00
Shop supply:	320.03		
TOTAL (\$):	4008.10	Hrs.	25.10

WORK ORDER



MINIMAX EXPRESS TRANSPORTATION INC

VIN: 3ALACXDT6HDJC2910

Make: FRHT

Model:

Year: 2017

CORNWALL

Unit N°

374

Plate:

3235PV

Number: 306
05. WORK FINISHED
☐ SCHEDULED WORK

Kilometer:

463231

Engine hours:

9132

Date opened: 2025-12-02
Date closed: 2025-12-11

T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	*\$/u*	Total
INS		SAFETY			(6412) >> BVOLPI 2025-12-08 22:20:37:56						
INS		SAFETY			replace left rear maxi (broken spring) service ad9						
INS		SAFETY	75W90		airdryer (6412) >> OK						
INS		SAFETY	343-4024		LUCAS GEAR OIL						
INS		SAFETY			HUB CAPS						
INS		SAFETY			(6408) >> BVOLPI 2025-12-09 05:01:19:82						
INS		SAFETY			replace both front oil hubs (6408) (6408) >> OK						
INS		SAFETY	848.093221		MAXCURVE WIPERBLADE 22IN (558MM)						
INS		SAFETY			(6409) >> BVOLPI 2025-12-09 05:38:53:12						
INS		SAFETY			tie up wires hanging all over under motor (6409) (6409) >> OK						
INS		SAFETY			(6401) >> TCLEROUX 2025-12-09 16:28:53:20						
INS		SAFETY			water pump leaking (6401) (6401) >> OK						
INS		SAFETY			(6402) >> TCLEROUX 2025-12-09 16:28:56:78						
INS		SAFETY			fan belts no good (6402) (6402) >> OK						
INS		SAFETY			(6413) >> TCLEROUX 2025-12-09 16:30:02:92						
INS		SAFETY			replace def pump cover (6413) (6413) >> OK						
INS		SAFETY			(6414) >> TCLEROUX 2025-12-09 16:30:05:91						
INS		SAFETY			replace def pump filter (different than the ones in stock) (6414) (6414) >> OK						

Comment:

safety inspection

Signature :

Date :

Minimax Express Transportation

Printed: 2026-10-06 by: ST DENIS, ROLLAND

Subtotal-parts:	1554.57	+	0.00
Subtotal labor:	2133.50		0.00
Shop supply:	320.03		
TOTAL (\$):	4008.10	Hrs.	25.10



Work Order

CORNWALL

Number:

306

MINIMAX EXPRESS TRANSPORTATION INC

Unit N°

374

05. WORK FINISHED

VIN: 3ALACXDT6HDJC2910

Make: FRHT

Model:

Plate:

3235PV

☐ SCHEDULED WORK

Year: 2017

Kilometer:
463231

Engine hours:
9132

Date opened:

2025-12-02

Date closed:

2025-12-11

T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	*\$/u*	Total
INS	SAFETY				(679.687) >> TCLEROUX 2025-12-09 16:29:15:34						
INS	SAFETY				VEHICLE LIGHTING & TRAILER, AIR & ELECTRICAL CONNECTIONS: TO REPAIR (679.687) >>						
INS	SAFETY				(717.720) >> TCLEROUX 2025-12-09 16:29:25:36						
INS	SAFETY				BELTS & HOSES: TO CHANGE (717.720) >> OK						
INS	SAFETY				(717.723) >> TCLEROUX 2025-12-09 16:29:27:97						
INS	SAFETY				ELECTRICAL WIRING, CONNECTIONS, ROUTING, SECURITY: TO CHANGE (717.723) >> OK						
INS	SAFETY				(717.727) >> TCLEROUX 2025-12-09 16:29:34:17						
INS	SAFETY				SERVICE POWER STEERING FILTER & FLUID: TO REPAIR (717.727) >> OK						
REP	SAFETY				>> TCLEROUX 2025-12-09 16:29:37:48						
REP	SAFETY				@NOT315:Annual safety						
INS	SAFETY				>> TCLEROUX 2025-12-09 16:29:47:17						
INS	SAFETY				@NOT320:What was done so far						
INS	SAFETY				Rear driver side maxi						
INS	SAFETY				Installed new fittings on it						
INS	SAFETY				Reinstalled and ensured was secured.						
INS	SAFETY				Did the air dryer filter						
INS	SAFETY				Changed with new						

Comment:

safety inspection

Signature : _____ Date : _____

Subtotal-parts:	1554.57	+	0.00
Subtotal labor:	2133.50		0.00
Shop supply:	320.03		
TOTAL (\$):	4008.10		
Hrs.	25.10		

Work Order

CORNWALL Number: 306



MINIMAX EXPRESS TRANSPORTATION INC

Unit N° 374

05. WORK FINISHED

VIN: 3ALACXDT6HDC2910

Make: FRHT

Model:

Plate: 3235PV

☐ SCHEDULED WORK

Year: 2017

Kilometer: 463231

Engine hours: 9132

Date opened: 2025-12-02

Date closed: 2025-12-11

T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	*\$/u*	Total
	INS	SAFETY			Torqued filter to 50lbs						
	INS	SAFETY			Reinstalled each bolt with new washers.						
	INS	SAFETY			One bolt broke replaced with new bolt.						
	INS	SAFETY			Ensured was secure then reinstalled band to keep in place at top.						
	INS	SAFETY			Front hubs have been changed due too cant see in.						
	INS	SAFETY			Changed both gave both new hardware bolts and washers						
	INS	SAFETY			Filled both to appropriate line.						
	INS	SAFETY			22 inch wiper blades installed						
	INS	SAFETY			Old ones broken.						
	INS	SAFETY			TERRY CLEROUX, 2025-12-09						
	INS	SAFETY			Comment / Request						
	INS	SAFETY			UF 101 DEF FILTER						
	INS	SAFETY			*****						
	INS	SAFETY	GRT 40073		REFLECTOR 2.5" YELLOW RO STICK-ON AMBER		PTS1		4.00	0.113	0.450
	INS	SAFETY			(679.686) >> TOLEROUX 2025-12-09 16:41:02:01						
	INS	SAFETY			WIRING, AIR LINES & VALVES, ROUTING & SECURITY. TO REPAIR (679.686) >> OK						
	INS	SAFETY			FUEL TREATMENT		PTS1		1.00		

Comment:
safety inspection

Signature : _____ Date : _____

Subtotal-parts:	1554.57	+	0.00
Subtotal labor:	2133.50		0.00
Shop supply:	320.03		
TOTAL (\$):	4008.10		
Hrs.	25.10		

CORNWALL	Number:	306
----------	---------	-----



VIN: 3ALACXDT6HDJC2910

Make: FRHT

Model:

Year: 2017

Unit N° 374

Plate: 3235PV

☐ SCHEDULED WORK

Kilometer:

463231

Engine hours:

9132

Date opened:

Date closed:

2025-12-02

2025-12-11

T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	*\$/u*	Total
	INS	SAFETY			(6410) >> TOLEROUX 2025-12-09 17:56:21:92						
	INS	SAFETY			replace both power steering lines off power steering pump (6410) (6410) >> OK						
	INS	SAFETY			TERRY CLEROUX, 2025-12-09						
	INS	SAFETY			Comment / Request						
	INS	SAFETY			DEF PUMP COVER 04-31628-001						
	INS	SAFETY			WATER PUMP 5473237						
	INS	SAFETY			POWER STEERING HOSE 14-17797-000						
	INS	SAFETY			POWER STEERING HOSE 14-18662-000						
	INS	SAFETY			DEF PUMP FILTER FG UF101						
	INS	SAFETY									
	INS	SAFETY			*****						
	INS	PMA	PTS2		SERVICE A						
	INS	PMB	PTS3		SERVICE B						
	INS	PMB			CHRIS CHITAMBARA, 2025-12-09						
	INS	PMB			Comment / Request						
	INS	PMB			Carry out B service						
	INS	PMB			Torque all wheels and issue torque tag						
	INS	PMB			Causes						

Comment:

safety inspection

Signature : _____

Date: _____

Subtotal-parts:	1554.57 +
-----------------	-----------

0.00

Subtotal labor:	2133.50
-----------------	---------

0.00 測試

Shop supply:	320.03
--------------	--------

TOTAL (\$):	4008.10
-------------	---------

Hrs. 25.10



Work Order		CORNWALL		Number:	306
MINIMAX EXPRESS TRANSPORTATION INC		Unit N°	374	05. WORK FINISHED	

VIN: 3ALACXDT6HJJC2910
Make: FRHT
Model:
Year: 2017

Plate: 3235PV
☐ SCHEDULED WORK
Kilometer: 463231
Engine hours: 9132
Date opened: 2025-12-02
Date closed: 2025-12-11

T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	*\$/u*	Total
INS	PMB				Due						
INS	PMB				Corrections						
INS	PMB				Carries out B Service						
INS	PMB				Torqued all wheels to recommended spec and issued torque tag						
INS	PMB				*****						
INS	PMB				CHRIS CHITAMBARA, 2025-12-09						
INS	PMB				Corrections						
INS	PMB				Drained engine oil and added new oil						
INS	PMB				Replaced engine oil filter						
INS	PMB				Replaced Fuel filter						
INS	PMB				Replaced air filter						
INS	PMB				*****						
INS	PMB				MOTOR OIL		PTS3		19.00	4.630	87.970
INS	PMB				OIL FILTER		PTS3		1.00	21.540	21.540
INS	PMB				FUEL FILTER		PTS3		1.00	40.300	40.300
INS	PMB				CHRIS CHITAMBARA, 2025-12-09						
INS	PMB				Corrections						
INS	PMB				Replaced Cabin Filter						

Comment:
safety inspection

Signature : _____ Date : _____

Subtotal-parts:	1554.57	+	0.00
Subtotal labor:	2133.50		0.00
Shop supply:	320.03		
TOTAL (\$):	4008.10	Hrs.	25.10

Work Order

CORNWALL

Number:

306

MINIMAX EXPRESS TRANSPORTATION INC

Unit N°

374

05. WORK FINISHED

VIN: 3ALACXD16HDJC2910

Make: FRHT

Plate:

3235PV

☐ SCHEDULED WORK



Model:

Year: 2017

Kilometer:

463231

Engine hours:

9132

Date opened:

Date closed:

2025-12-02

2025-12-11

T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	\$/u*	Total
INS	PMB				*****						
INS	PMB	ABP N10G 36000006			CABIN AIR FILTER		PTS3		1.00	11.380	11.380
INS	PMB				(6527) >> CCHITAMBARA 2025-12-09 22:17:28:46						
INS	PMB				NEEDS A&B SERVICE (6527) (6527) >> OK						
INS	PMB				CHRIS CHITAMBARA, 2025-12-09						
INS	PMB				Corrections						
INS	PMB				Greased all grease points						
INS	PMB				*****						
INS	PMB				(717.726) >> CCHITAMBARA 2025-12-09 23:07:43:29						
INS	PMB				REMOVE & INSPECT AIR FILTER: TO CHANGE						
INS	PMB				(717.726) >> OK						
INS	PMB				(731.732) >> CCHITAMBARA 2025-12-09 23:07:44:63						
INS	PMB				FROM WARM ENGINE, DRAIN OIL: TO CHANGE						
INS	PMB				(731.732) >> OK						
INS	PMB				(731.734) >> CCHITAMBARA 2025-12-09 23:07:47:22						
INS	PMB				REMOVE & REPLACE ENGINE OIL & FUEL FILTERS:						
INS	PMB				TO CHANGE (731.734) >> OK						
INS	PMB				** START ** Source : PO# 2058						
INS	PMB				Transferred by : SEGUN, DANIEL - 1/15/2026						
REP	042	5473237			WATER PUMP		09P21469		1.00	347.010	347.010

Comment:

safely inspection

Signature :

Date :

Subtotal-parts:	1554.57	+	0.00
Subtotal labor:	2133.50		0.00
Shop supply:	320.03		
TOTAL (\$):	4008.10		
Hrs.	25.10		

Work Order



MINIMAX EXPRESS TRANSPORTATION INC

VIN: 3ALACXDT6HJJC2910

Make: FRHT

Model:

Year: 2017

CORNWALL

Number:

306

Unit N°

374

Plate:

3235PV

☐ SCHEDULED WORK

Kilometer: 463231

Engine hours: 9132

Date opened: 2025-12-02
Date closed: 2025-12-11

T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	*\$/u*	Total
REP	043		04-31628-001		DEF PUMP COVER		09P21469		1.00	106.090	106.090
REP	045		5270678		TENTIONER		09P21469		1.00	313.800	313.800
REP	045		01-35643-065		BELT		09P21469		1.00	65.440	65.440
					** END **						
REP	014		SAUBIN		SEBASTIEN AUBIN				5.96	85.00	506.60
REP	045		TALENT		TALENT TAMBAOGA				5.62	85.00	477.70
REP			SAFETY VBRENNER		VINCE BRENNER				3.33	85.00	283.05
INS			SAFETY TCLEROUX		TERRY CLEROUX				2.50	85.00	212.50
INS			SAFETY BVOLPI		BLAKE VOLPI				3.98	85.00	338.30
REP			SAFETY SAUBIN		SEBASTIEN AUBIN				0.08	85.00	6.80
INS	PMB		CCCHITAMBARA		CHRIS CHITAMBARA				3.63	85.00	308.55

Comment:

safety inspection

Signature :

Date :

Subtotal-parts:	1554.57	+	0.00
Subtotal labor:	2133.50		0.00
Shop supply:	320.03		
TOTAL (\$):	4008.10		
		Hrs.	25.10

Work Order

CORNWALL

Number:

528

MINIMAX EXPRESS TRANSPORTATION INC

Unit N°

374

05. WORK FINISHED



VIN: 3ALACXDT6HJJC2910

Make: FRHT

Model:

Year: 2017

Plate:

3235PV

☐ SCHEDULED WORK

Kilometer:

463231

Engine hours:

9132

Date opened:

2025-12-30

Date closed:

2026-01-07

T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	*\$/u*	Total
	PNE	017			TERRY CLEROUX, 2025-12-30						
	PNE	017			Comment / Request						
	PNE	017			retorque						
	PNE	017			*****						
	PNE	017			(6411) >> TCLEROUX 2025-12-30 08:25:37:07						
	PNE	017			replace trans speed sensor (6411) (6411) >> OK						
	PNE	017	TCLEROUX		TERRY CLEROUX				0.71	85.00	60.35

Comment:

TIRES

Signature :

Date :

Subtotal-parts:	0.00	+	0.00
Subtotal labor:	60.35		0.00
Shop supply:	9.05		
TOTAL (\$) :	69.40		
Hrs.	0.71		

Work Order

CORNWALL

Number:

1100

MINIMAX EXPRESS TRANSPORTATION INC

VIN: 3ALACXD16HDJC2910

Make: FRHT

Model:

Year: 2017

Unit N°

374

Plate:

3235PV

☐ SCHEDULED WORK

Kilometer:

464130

Engine hours:

9158

Date opened:

2026-03-18

Date closed:

2026-05-15



T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	*\$/u*	Total
REP	052				BLAKE VOLPI, 2026-03-18						
REP	052				Comment / Request						
REP	052				Changed both quarter fenders as one was missing the other wouldnt of been matching						
REP	052				Used 2 instock - western star models						
REP	052				Fixed antenna holder						
REP	052				Corrections						
REP	052				Quarter fender on drive side was completely missing.						
REP	052				Replaced with new						
REP	052				Also replaced passenger side with new quarter fender.						
REP	052				Driver brought to my attention that the antenna was hanging due to broken rivets for its clip.						
REP	052				Rerivettet it back on and made sure was secure.						
REP	052				*****						
REP	026				VINCE BRENNER, 2026-04-20						
REP	026				Comment / Request						
REP	026				Remove transmission and replace clutch.						

Comment:
ACCESSORIES

Signature : _____ Date : _____

Subtotal-parts:	0.00	+	0.00
Subtotal labor:	1365.10		0.00
Shop supply:	204.77		
TOTAL (\$):	1569.87		
Hrs.	17.31		



Work Order

MINIMAX EXPRESS TRANSPORTATION INC

CORNWALL

Number:

1100

VIN: 3ALACXDT6HDJC2910

Unit N° 374

05. WORK FINISHED

Make: FRHT

Plate:

3235PV

☐ SCHEDULED WORK

Model:

Year: 2017

Kilometer: 464130

Engine hours: 9158

Date opened:

2026-03-18

Date closed:

2026-05-15

T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	*\$/u*	Total
REP	026				*****						
REP	023				SEBASTIEN AUBIN, 2026-04-20						
REP	023				Comment / Request						
REP	023				remove transmission						
REP	023				Causes						
REP	023				worn						
REP	023				Corrections						
REP	023				removed transmission torque converter and flywheel						
REP	023				*****						
REP	026				VINCE BRENNER, 2026-05-14						
REP	026				Corrections						
REP	026				Replaced transmission output shaft speed sensor.						
REP	026				Test drove vehicle.						
REP	026				*****						
INS	PMA		PTS2		SERVICE A						
REP	052		BVOLPI		BLAKE VOLPI				4.78	85.00	406.30
INS	PMA		AQUESNEL		ANTHONY QUESNEL				1.25		
REP	023		SAUBIN		SEBASTIEN AUBIN				4.77	85.00	405.45

Comment:
ACCESSORIES

Signature : _____

Date : _____

Subtotal-parts:	0.00	+	0.00
Subtotal labor:	1365.10		0.00
Shop supply:	204.77		
TOTAL (\$):	1569.87		
Hrs.	17.31		

Work Order

CORNWALL

Number:

1100

MINIMAX EXPRESS TRANSPORTATION INC

Unit N°

374

05. WORK FINISHED



VIN: 3ALACXDT6HDJC2910

Make: FRHT

Model:

Year: 2017

Plate:

3235PV

☐ SCHEDULED WORK

Kilometer:

464130

Engine hours:

9158

Date opened:

Date closed:

2026-03-18

2026-05-15

T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	*\$/u*	Total
REP	026	VBRENNER			VINCE BRENNER				6.51	85.00	553.35

Comment:
ACCESSORIES

Signature : _____

Date : _____

Subtotal-parts:	0.00	+	0.00
Subtotal labor:	1365.10		0.00
Shop supply:	204.77		
TOTAL (\$) :	1569.87		
Hrs.	17.31		

Work Order

CORNWALL

Number:

1506

MINIMAX EXPRESS TRANSPORTATION INC

VIN: 3ALACXDT6HDJC2910

Unit N°

374

05. WORK FINISHED

Make: FRHT

Plate:

3235PV

☐ SCHEDULED WORK

Model:

Year: 2017

Kilometer:

464130

Engine hours:

9158

Date opened:

Date closed:

2026-06-01

2026-06-24



T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	*\$/u*	Total
🔧	REP	003			VINCE BRENNER, 2026-06-01						
🔧	REP	003			Comment / Request						
🔧	REP	003			Tachometer not working.						
🔧	REP	003			*****						
🔧	REP	045			VINCE BRENNER, 2026-06-03						
🔧	REP	045			Comment / Request						
🔧	REP	045			Replaced turbo EGR valve.						
🔧	REP	045			Repaired wiring for transmission output shaft speed sensor.						
🔧	REP	045			*****						
🔧	INS	PMA	PTS2		SERVICE A						
🔧	REP	003	VBRENNER		VINCE BRENNER				7.90	85.00	671.50
🔧	REP	045	VBRENNER		VINCE BRENNER				9.23	85.00	784.55
🔧	INS	PMA	VBRENNER		VINCE BRENNER				2.00	85.00	170.00

Comment:

INSTRUMENT PANEL, INSTRUMENT CLUSTER, GAUGES, DASHBOARD

Signature : _____ Date : _____

Subtotal-parts:	0.00	+	0.00
Subtotal labor:	1626.05	+	0.00
Shop supply:	243.91		
TOTAL (\$) :	1869.96		
		Hrs.	19.13

1807



SCHEDULED WORK

2026-07-20

2026-07-28

	0.00
	0.00
Hrs.	0.00

Date:

Page : 1



MINIMAX EXPRESS TRANSPORTATION INC
VIN: 3ALACXD16HDJC2910
Make: FRHT
Model:
Year: 2017

Unit N° 374
Plate: 3235PV

Kilometer: 0

Engine hours: 0

CORNWALL **Number: 2236**
05. WORK FINISHED
☐ SCHEDULED WORK
☐ UNSCHEDULED WORK
☐ EMERGENCY / ROAD CALL
☐ Other:
Date opened: 2026-09-01
Date closed: - - -

T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	*\$/u*	Total
					** START ** Source : PO# 2912						
					Transferred by : ST DENIS, ROLLAND - 2026-09-01						
			A06-40578-000		MARKER LIGHT		09P31000		3.00	67.010	201.030
					** END **						
	REP	034			SEBASTIEN AUBIN, 2026-09-01						
	REP	034			Comment / Request						
	REP	034			replaced top marker light						
	REP	034			adjusted wiper blade						
	REP	034			Causes						
	REP	034			burnt						
	REP	034			Corrections						
	REP	034			replaced markerlight						
	REP	034			adjusted wiper blade						
	REP	034			*****						
	REP	037			JOHN HAMILTON, 2026-09-22						
	REP	037			Corrections						
	REP	037			scanned vehicle and found all codes to be inactive took a picture of the codes						
	REP	037			and then cleared them as per garry and then parked the unit outside						

Comment:

Signature :

Date :

Subtotal-parts:	201.03	+	0.00
Subtotal labor:	268.60		0.00
Shop supply:	40.29		
TOTAL (\$):	509.92		
Hrs.	16.18		

Work Order

CORNWALL

Number:

2236



MINIMAX EXPRESS TRANSPORTATION INC

VIN: 3ALACXDT6HDJC2910

Make: FRHT

Model:

Year: 2017

Unit N°

374

Plate:

3235PV

Kilometer:

0

Engine hours:

0

05. WORK FINISHED

- ☐ SCHEDULED WORK
☐ UNSCHEDULED WORK
☐ EMERGENCY / ROAD CALL
☐ Other: _____

Date opened:

2026-09-01

Date closed:

____ - ____ - ____

T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	*\$/u*	Total
REP	037				*****						
REP	002				AARON ANDERSON, 2026-09-29						
REP	002				Comment / Request						
REP	002				starting to de sticker truck then clear out interior and detail						
REP	002				*****						
REP	002				AARON ANDERSON, 2026-09-29						
REP	002				Comment / Request						
REP	002				continuing on power wash						
REP	002				*****						
REP	002				AARON ANDERSON, 2026-09-29						
REP	002				Comment / Request						
REP	002				finished job from earlier removing stickers on body, previously washed truck						
REP	002				and cleared out cab except fire extinguisher, cleaned up and painted lower						
REP	002				steps both sides 2 coats, wire wheeled front bumper to paint later, painted						
REP	002				grille plate infront of rad at bumper opening, put away tools and paint, still						
REP	002				needs fire extinguisher removed, interior detailed, front bumper painted 2						
REP	002										

Comment:

Signature :

Date :

Subtotal-parts:	201.03	+	0.00
Subtotal labor:	268.60		0.00
Shop supply:	40.29		
TOTAL (\$):	509.92		
Hrs.	16.18		

Work Order

CORNWALL

Number:

2236



MINIMAX EXPRESS TRANSPORTATION INC

VIN: 3ALACXDT6HDJC2910

Make: FRHT

Model:

Year: 2017

Unit N°

374

Plate:

3235PV

Kilometer:

0

Engine hours:

0

05. WORK FINISHED

- ☐ SCHEDULED WORK
☐ UNSCHEDULED WORK
☐ EMERGENCY / ROAD CALL
Other: _____

Date opened:

2026-09-01

Date closed:

_____-_____-____-

T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	*\$/u*	Total
REP	002				coats and will need some sticker glue removed with brake clean and rag *****						
REP	002				AARON ANDERSON, 2026-09-30 Comment / Request						
REP	002				painting bumper, then clean and detail *****						
REP	002				AARON ANDERSON, 2026-09-30						
REP	002				Comment / Request						
REP	002				Painted front bumper 2 coats, removed fire extinguisher, cleaned out and vacuumed cab, started detail, stopping for lunch *****						
REP	002				AARON ANDERSON, 2026-09-30						
REP	002				Comment / Request						
REP	002				continuing on detail *****						
REP	002				SEBASTIEN AUBIN				1.20	85.00	102.00
REP	034		SAUBIN		JOHN HAMILTON				1.96	85.00	166.60
REP	037		#2TECK		AARON ANDERSON				0.01		

Comment:

Signature : _____ Date : _____

Subtotal-parts:	201.03	+	0.00
Subtotal labor:	268.60		0.00
Shop supply:	40.29		
TOTAL (\$):	509.92		
Hrs.	16.18		

Work Order

CORNWALL

Number:

2236



MINIMAX EXPRESS TRANSPORTATION INC

Unit N°

374

05. WORK FINISHED

VIN: 3ALACXDT6HDJC2910

Make: FRHT

Plate:

3235PV

Model:

Year: 2017

Kilometer:

0

Engine hours:

0

Date opened: 2026-09-01

Date closed: - - -

- ☐ SCHEDULED WORK
- ☐ UNSCHEDULED WORK
- ☐ EMERGENCY / ROAD CALL
- ☐ Other: _____

T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	*\$/u*	Total
	REP	002	AANDERSON		AARON ANDERSON				2.30		
	REP	002	AANDERSON		AARON ANDERSON						
	REP	002	AANDERSON		AARON ANDERSON				4.10		
	REP	002	AANDERSON		AARON ANDERSON				0.01		
	REP	002	AANDERSON		AARON ANDERSON				3.56		
	REP	002	AANDERSON		AARON ANDERSON				3.04		

Comment:

Signature :

Date :

Subtotal-parts:	201.03	+	0.00
Subtotal labor:	268.60		0.00
Shop supply:	40.29		
TOTAL (\$) :	509.92		
Hrs.	16.18		