

292



VIN: 3ALACXDTXHDJC2909

Make: FRHT

Model:

Year: 2017

373

PA62366

SCHEDULED WORK

Kilometer:

407616

Engine hours:

11358

Date opened:

Date closed:

2025-11-26

2025-12-01

[illegible]

safety completed 26 november

Signature:

Date :

Subtotal-parts:

0.00

Subtotal labor:

0.00

Shop supply:

44.63

TOTAL (\$):

342.13

Hrs. 3.50



Work Order

CORNWALL

Number:

1186

MINIMAX EXPRESS TRANSPORTATION INC

VIN: 3ALACXDTXHDJC2909

Unit No 373

05. WORK FINISHED

Make: FRHT

Plate: PA62366

☐ SCHEDULED WORK

Model:

Year: 2017

Kilometer: 420467

Engine hours: 11746

Date opened:

Date closed:

2026-04-01

2026-06-26

T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	*\$/u*	Total
INS	065				BLAKE VOLPI, 2026-04-01						
INS	065				Corrections						
INS	065				Driver from belleville came to pick up truck						
INS	065				Driver stated we must test tailgate before it leaves lot.						
INS	065				Tailgate is a folding gate.						
INS	065				Tested it by bringing the tailgate down						
INS	065				Opening up tailgate						
INS	065				Bringing tailgate up to the deck						
INS	065				Made sure it aligns						
INS	065				Made sure tailgate goes up and down while being open						
INS	065				It also actuates at ground to become flush also						
INS	065				It works perfectly fine.						
INS	065				Driver was witness to this.						
INS	065				Driver is on way to belleville with truck.						
INS	065				*****						
REP	052				BLAKE VOLPI, 2026-04-21						
REP	052				Comment / Request						
REP	052				came in with broken door cable.						

Comment:
HYDRAULIC SYSTEM

Signature : _____ Date : _____

Subtotal-parts:	20.13	+	0.00
Subtotal labor:	364.65		0.00
Shop supply:	54.70		
TOTAL (\$):	439.48	Hrs.	4.29



Work Order

CORNWALL

Number:

1186

MINIMAX EXPRESS TRANSPORTATION INC

Unit N°

373

05. WORK FINISHED

VIN: 3ALACXDTXHDJC2909

Make: FRHT

Model:

Year: 2017

Plate:

PA62366

☐ SCHEDULED WORK

Kilometer:

420467

Engine hours:

11746

Date opened:

2026-04-01

Date closed:

2026-06-26

T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	*\$/u*	Total
REP	052				*****						
REP	052				BLAKE VOLPI, 2026-04-21						
REP	052				Comment / Request						
REP	052				After getting door up.						
REP	052				Door spring is broken.						
REP	052				We have no extras.						
REP	052				Will have to order.						
REP	052				LOCKED OUT TILL DOOR SPRING ARRIVES.						
REP	052				*****						
REP	052				BLAKE VOLPI, 2026-04-23						
REP	052				Comment / Request						
REP	052				Door spring removal and installation.						
REP	052				*****						
REP	052				BLAKE VOLPI, 2026-04-23						
REP	052				Corrections						
REP	052				Removed old door spring.						
REP	052				Removal was a bit more complicated as the door spring shaft rusted to both ends						
REP	052				and the center brace.						

Comment:
HYDRAULIC SYSTEM

Signature : _____ Date : _____

Subtotal-parts:	20.13	+	0.00
Subtotal labor:	364.65		0.00
Shop supply:	54.70		
TOTAL (\$):	439.48		
Hrs.	4.29		



Work Order

CORNWALL

Number:

1186

MINIMAX EXPRESS TRANSPORTATION INC

Unit N° 373

05. WORK FINISHED

VIN: 3ALACXDTXHDJC2909

Make: FRHT

Model:

Year: 2017

Plate: PA62366

☐ SCHEDULED WORK

Kilometer: 420467

420467

Engine hours: 11746

11746

Date opened:

Date closed:

2026-04-01

2026-06-26

T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	*\$/u*	Total
🔧	REP	052			Careful cutting and removal had to be preformed						
🔧	REP	052			Installed new spring						
🔧	REP	052			put double cotter pin at drive side.						
🔧	REP	052			Installed 2 new cables.						
🔧	REP	052			Old method with U bolt through it.						
🔧	REP	052			Had to clean up both U bolts.						
🔧	REP	052			Had to re drill hole size on cables.						
🔧	REP	052			Installed cables						
🔧	REP	052			7 turns each side.						
🔧	REP	052			Door is functioning up and down.						
🔧	REP	052			Returning truck to service.						
🔧	REP	052			*****						
🔧	REP	052			BLAKE VOLPI, 2026-04-23						
🔧	REP	052			Comment / Request						
🔧	REP	052			Parts used						
🔧	REP	052			Door spring						
🔧	REP	052			Door cables package (130 pair)						
🔧	REP	052			cotter pins						

Comment:

HYDRAULIC SYSTEM

Signature :

Date :

Subtotal-parts: 20.13 +
Subtotal labor: 364.65
Shop supply: 54.70

0.00
0.00

TOTAL (\$) : 439.48

Hrs. 4.29

1837



VIN: 3ALACXDTXHBJC2909

Make: FRHT

Model:

Year: 2017

Unit No.

373

Plate:

PA62366

☐ SCHEDULED WORK

Kilometer:

429034

Engine hours:

11920

Date opened:

Date closed:

2026-07-22

2026-08-05

Comment:


Date: _____

Minimax Express Transportation

Printed: 2026-10-06 by: ST DENIS, ROLLAND

Work Order

CORNWALL **Number:** 2554



MINIMAX EXPRESS TRANSPORTATION INC

VIN: 3ALACXDTXHDJC2909

Make: FRHT

Model:

Year: 2017

Unit N° 373

Plate: PA62366

☐ SCHEDULED WORK

Kilometer: 430034

Engine hours: 11938

Date opened: 2026-09-22

Date closed: 2026-09-30

T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	*\$/u*	Total
	REP	002			AARON ANDERSON, 2026-09-22						
	REP	002			Comment / Request						
	REP	002			de sticker truck then detail						
	REP	002			*****						
	REP	002			AARON ANDERSON, 2026-09-22						
	REP	002			Comment / Request						
	REP	002			stopping for lunch						
	REP	002			*****						
	REP	002			AARON ANDERSON, 2026-09-23						
	REP	002			Comment / Request						
	REP	002			de stickered driver side of truck and most of passenger side, red stripes						
	REP	002			spider webbed, came off in small pieces during removal, spent most time on						
	REP	002			driver side scraping stickers off with plastic razor blades, heat gun and small						
	REP	002			butane torch, towards end found pressure washer very effective, pressure washed						
	REP	002			stripes on driver side off and most of passenger side, still not finished,						
	REP	002			parked truck for now, picked up loose pieces of stickers, changed out of wet						
	REP	002			clothes						

Comment:

CAB, SLEEPER AND SHEET METAL

Signature : _____ **Date :** _____

Subtotal-parts:	0.00 +	0.00
Subtotal labor:	531.25	0.00
Shop supply:	79.69	
TOTAL (\$) :	610.94	Hrs. 6.25



MINIMAX EXPRESS TRANSPORTATION INC

Unit No 373

05. WORK FINISHED

VIN: 3ALACXDTXHDJC2909

Make: FRHT

☐ SCHEDULED WORK

Model:

Plate: PA62366

Year: 2017

Kilometer: 430034

Engine hours: 11938

Date opened: 2026-09-22

Date closed: 2026-09-30

T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	*\$/u*	Total
	REP	002			*****						
	REP	002			AARON ANDERSON, 2026-09-23						
	REP	002			Comment / Request						
	REP	002			finishing de stickering of truck then starting detail						
	REP	002			*****						
	REP	002			AARON ANDERSON, 2026-09-23						
	REP	002			Comment / Request						
	REP	002			finished removing stickers on passenger side (had to wait for driver to finish						
	REP	002			using pressure washer and scissor lift died had to charge to finish passenger						
	REP	002			side), while waiting de stickered roll up door by hand due to paint coming off						
	REP	002			with stickers, cleared garbage out of cab, removed (GO) from 1012 van, picked						
	REP	002			up pieces of stickers off floor, brought truck in, de scaled and wire wheeled						
	REP	002			bottom steps both sides, painted 2 coats of spray silver, wire wheeled front						
	REP	002			bumper and sprayed coat of paint, took Chris to Globocam, put another coat on						
	REP	002			front bumper, stopping for lunch while paint dries						
	REP	002			*****						

Comment:

CAB, SLEEPER AND SHEET METAL

Signature : _____ Date : _____

Subtotal-parts:	0.00	+	0.00
Subtotal labor:	531.25		0.00
Shop supply:	79.69		
TOTAL (\$):	610.94	Hrs.	6.25

Work Order

CORNWALL

Number:

2554

MINIMAX EXPRESS TRANSPORTATION INC

Unit No

373

05. WORK FINISHED

VIN: 3ALACXDTXHDJC2909

Make: FRHT

Plate:

PA62366

☐ SCHEDULED WORK

Model:

Year: 2017

Kilometer:

430034

Engine hours:

11938

Date opened:

Date closed:

2026-09-22

2026-09-30



T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	*\$/u*	Total
	REP	002			AARON ANDERSON, 2026-09-23						
	REP	002			Comment / Request						
	REP	002			starting detail						
	REP	002			*****						
	REP	002			AARON ANDERSON, 2026-09-24						
	REP	002			Comment / Request						
	REP	002			worked on detailing, removed safety equipment, cleaned spilled oil out of						
	REP	002			floor, cleaned back wall and both door panels and back and door window, did a						
	REP	002			few passes on the floor, needs also more work to finish detail, parked truck,						
	REP	002			put away tools						
	REP	002			*****						
	REP	002			AARON ANDERSON, 2026-09-24						
	REP	002			Comment / Request						
	REP	002			continuing on detail						
	REP	002			*****						
	REP	002			AARON ANDERSON, 2026-09-24						
	REP	002			Comment / Request						

Comment:

CAB, SLEEPER AND SHEET METAL

Signature :

Date :

Subtotal-parts:	0.00	+	0.00
Subtotal labor:	531.25		0.00
Shop supply:	79.69		
TOTAL (\$):	610.94		
Hrs.	6.25		

Work Order

CORNWALL

Number:

2554

MINIMAX EXPRESS TRANSPORTATION INC

VIN: 3ALACXDTXHJJC2909

Unit N°

373

05. WORK FINISHED

Make: FRHT

Plate:

PA62366

☐ SCHEDULED WORK

Model:

Year: 2017

Kilometer:

430034

Engine hours:

11938

Date opened:

2026-09-22

Date closed:

2026-09-30



T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	*\$/u*	Total
	REP	002			finished detail, reinstalled broken vent pivot with gasket maker, firmly in						
	REP	002			place now, once gasket maker set parked truck outside						
	REP	002			*****						
	REP	002	AANDERSON		AARON ANDERSON				6.25	85.00	531.25

Comment:

CAB, SLEEPER AND SHEET METAL

Signature : _____ Date : _____

Subtotal-parts:	0.00	+	0.00
Subtotal labor:	531.25		0.00
Shop supply:	79.69		
TOTAL (\$) :	610.94		
		Hrs.	6.25



Work Order

CORNWALL Number: 297

MINIMAX EXPRESS TRANSPORTATION INC

Unit N° 374 05. WORK FINISHED

VIN: 3ALACXDT6HDJC2910

Make: FRHT

Model:

Year: 2017

Plate: 3235PV

☐ SCHEDULED WORK

Kilometer: 462142

Engine hours: 9107

Date opened: 2025-12-01
Date closed: 2025-12-02

T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	*\$/u*	Total
REP		045			CHRIS CHITAMBARA, 2025-12-01						
REP		045			Comment / Request						
REP		045			EGR Fault code						
REP		045			*****						
REP		045			(5427) >> TTALENT 2025-12-01 22:18:50:63						
REP		045			Diagnosed engine light with cummins insight (5427)						
REP		045			(5427) >> OK						
REP		045			(5428) >> TTALENT 2025-12-01 22:19:38:69						
REP		045			Checked and test delta p differential sensor wiring						
REP		045			(5428) (5428) >> OK						
REP		014			SEBASTIEN AUBIN, 2025-12-01						
REP		014			Comment / Request						
REP		014			replaced all rivets at top of box truck						
REP		014			Causes						
REP		014			wall caved in						
REP		014			Corrections						
REP		014			pushed wall out installed new rivets and silicone						
REP		014			*****						
REP		014			** START ** Source : PO# 2054						
REP		014			Transferred by : SEGUIN, DANIEL - 1/13/2026						

Comment: ENGINE

Signature : _____ Date : _____

Subtotal-parts:	362.48 +	0.00
Subtotal labor:	128.35	0.00
Shop supply:	19.25	
TOTAL (\$):	510.08	Hrs. 1.51