

Work Order

CORNWALL

Number:

95



MINIMAX EXPRESS TRANSPORTATION INC

Unit N°

357

05. WORK FINISHED

VIN: 3AKJGEDV2GDDHE2248

Make: FRHT

Model:

Year: 2016

Plate:

PA75573

☐ SCHEDULED WORK

Kilometer:

804589

Engine hours:

17281

Date opened:

2025-11-07

Date closed:

2025-11-12

T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	*/u*	Total
REP	051				>> VBRENNER 2025-11-07 20:18:34:79						
REP	051				@NOT90:Install in cab tablet bracket and wiring						
INS	PMA	PTS2			SERVICE A						
INS	SAFETY	PTS1			SAFETY						
REP	051	VBRENNER			VINCE BRENNER				3.50	85.00	297.50
INS	PMA	TTALENT			TALENT TAMBAOGA				2.50	85.00	212.50
INS	SAFETY	VBRENNER			VINCE BRENNER				1.20	85.00	102.00

Comment:

COMMUNICATION, NAVIGATION OR SECURITY SYSTEMS

Signature :

Date :

Subtotal-parts:	0.00	+	0.00
Subtotal labor:	612.00		0.00
Shop supply:	91.80		
TOTAL (\$) :	703.80		
Hrs.	7.20		

Minimax Express Transportation

Printed: 2026-10-06 by: ST DENIS, ROLLAND

Work Order

CORNWALL

Number:

126



MINIMAX EXPRESS TRANSPORTATION INC

VIN: 3AKJGEDV2GDHE2248

Make: FRHT

Model:

Year: 2016

Unit N°

357

Plate:

PA75573

☐ SCHEDULED WORK

Kilometer:

804869

Engine hours:

17286

Date opened:

Date closed:

2025-11-13

2025-11-20

T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	*\$/u*	Total
✓	INS	PMA	PTS2		SERVICE A						
🔧	INS	PMA			BLAKE VOLPI, 2025-11-13						
🔧	INS	PMA			Comment / Request						
🔧	INS	PMA			Had to						
🔧	INS	PMA			*****						
🔧	INS	PMA			BLAKE VOLPI, 2025-11-13						
🔧	INS	PMA			Comment / Request						
🔧	INS	PMA			Noticed when moving truck for the driver 480 that truck is 4000km over due for						
🔧	INS	PMA			an A service.						
🔧	INS	PMA			Causes						
🔧	INS	PMA			Driver not reporting service is due						
🔧	INS	PMA			Corrections						
🔧	INS	PMA			By catching it before it gets way over due.						
🔧	INS	PMA			*****						
🔧	REP	PMB			>> VBRENNIER 2025-11-13 13:35:26:01						
🔧	REP	PMB			@NOT128:B Service						
🔧	REP	PMB			completed a service						
🔧	REP	PMB			Complete unit has been greased.						

Comment:
SERVICE A

Signature :

Date :

Subtotal-parts:	0.00	+	0.00
Subtotal labor:	746.30	🔧	0.00
Shop supply:	111.95		
TOTAL (\$) :	858.25	Hrs.	8.78

CORNWALL	Number: 126
----------	-------------



Unit N° 357

05. WORK FINISHED

Plate: PA/55/3

☐ SCHEDULED WORK

Kilometers:

Engine hours:

Date opened: 2025-11-13

17286

Date closed: 2025-11-20

[illegible]

Subtotal-parts:	0.00	0.00
Subtotal labor:	746.30	0.00
Shop supply:	111.95	

Date: _____	
TOTAL (\$) :	858 25
Hrs	8 78

Printed: 2026-10-06 by: ST DENIS, ROLLAND

Work Order

CORNWALL

Number:

303



MINIMAX EXPRESS TRANSPORTATION INC

Unit N°

357

05. WORK FINISHED

VIN: 3AKJGEDV2GDHE2248

Make: FRHT

Plate:

PA75573

Model:

Year: 2016

Kilometer:

804904

Engine hours:

17291

Date opened:

Date closed:

2025-12-02

2025-12-09

☐ SCHEDULED WORK

T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	\$/u*	Total
☒	REP	DPF	PTS4		DPF MAINTENANCE						
☒	REP	DPF			CHRIS CHITAMBARA, 2025-12-02						
☒	REP	DPF			Comment / Request						
☒	REP	DPF			Check engine light						
☒	REP	DPF			*****						
☒	REP	DPF			CHRIS CHITAMBARA, 2025-12-02						
☒	REP	DPF			Comment / Request						
☒	REP	DPF			Check engine light						
☒	REP	DPF			Corrections						
☒	REP	DPF			Diagnosed Aftertreatment system and needs SCR Inlet temperature sensor						
☒	REP	DPF			*****						
☒	REP	DPF			(5548) >> VBRENNER 2025-12-03 10:31:18:09						
☒	REP	DPF			Check engine light (5548) (5548) >> OK						
☒	REP	DPF			VINCE BRENNER, 2025-12-03						
☒	REP	DPF			Comment / Request						
☒	REP	DPF			New DOC Inlet temp sensor and bung fitted						
☒	REP	DPF			*****						
☒	REP	DPF			>> VBRENNER 2025-12-03 11:07:31:54						

Comment:

DPF MAINTENANCE

Signature : _____ Date : _____

Subtotal-parts:	0.00	+	0.00
Subtotal labor:	802.40		0.00
Shop supply:	120.36		
TOTAL (\$):	922.76		
Hrs.	9.44		

Work Order

CORNWALL

Number:

303



MINIMAX EXPRESS TRANSPORTATION INC

VIN: 3AKJGEDV2GDHE2248

Make: FRHT

Model:

Year: 2016

Unit No

357

Plate:

PA75573

☐ SCHEDULED WORK

Kilometer:

804904

Engine hours:

17291

Date opened:

2025-12-02

Date closed:

2025-12-09

T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	*\$/u*	Total
	REP	DPF			@NOT288:Replace DPF temp sensor-weld bung						
	REP	DPF			>> VBRENNER 2025-12-03 11:08:14:61						
	REP	DPF			@NOT291:Perform a regen						
	REP	DEF	PTSS		DEF MAINTENANCE						
	REP	DEF			TALENT TAMBAOGA, 2025-12-03						
	REP	DEF			Comment / Request						
	REP	DEF			engine light						
	REP	DEF			Causes						
	REP	DEF			verification not completed						
	REP	DEF			Corrections						
	REP	DEF			performed verification procedure						
	REP	DEF			Initiated a Regen - completed successfully 89% efficiency						
	REP	DEF			fault codes inactive and delete						
	REP	DEF			*****						
	REP	DEF			(5889) >> TALENT 2025-12-03 16:42:13:10						
	REP	DEF			engine light (5889) >> OK						
	REP	DPF	CCHITAMBARA		CHRIS CHITAMBARA				5.29	85.00	449.65
	REP	DPF	TALENT		TALENT TAMBAOGA				0.39	85.00	33.15

Comment:

DPF MAINTENANCE

Signature :

Date :

Subtotal-parts:	0.00 +	0.00
Subtotal labor:	802.40	0.00
Shop supply:	120.36	
TOTAL (\$):	922.76	Hrs. 9.44

303



05. WORK FINISHED

☐ SCHEDULED WORK

2025-12-02
2025-12-09

Printed: 2026-10-06 by: ST DENIS, ROLLAND

[illegible]

DPF MAINTENANCE

Date :

Subtotal-parts:	0.00	 0.00
Subtotal labor:	802.40	 0.00
Shop supply:	120.36	
TOTAL (\$) :	922.76	Hrs. 9.44

Work Order

CORNWALL

Number:

556



MINIMAX EXPRESS TRANSPORTATION INC

VIN: 3AKJGEDV2GDDHE2248

Make: FRHT

Model:

Year: 2016

Unit N°

357

Plate:

PA75573

☐ SCHEDULED WORK

Kilometer:

809695

Engine hours:

17383

Date opened:

Date closed:

2026-01-06

2026-01-12

T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	*\$/u*	Total
	REP	042			CHRIS CHITAMBARA, 2026-01-06						
	REP	042			Comment / Request						
	REP	042			Overheating						
	REP	042			*****						
	REP	042			CHRIS CHITAMBARA, 2026-01-06						
	REP	042			Causes						
	REP	042			Drive belts broken						
	REP	042			*****						
	REP	042			CHRIS CHITAMBARA, 2026-01-06						
	REP	042			Comment / Request						
	REP	042			Replace belt tensioner						
	REP	042			Causes						
	REP	042			Seized						
	REP	042			Corrections						
	REP	042			Removed belt tensioner (No tensioner in stock)						
	REP	042			*****						
	INS	PMA	PTS2		SERVICE A						
	INS	PMB	PTS3		SERVICE B						

Comment:
COOLING SYSTEM

Signature : _____ Date : _____

Subtotal-parts:	841.14	+	0.00
Subtotal labor:	731.85		0.00
Shop supply:	109.78		
TOTAL (\$):	1682.77	Hrs.	8.61

Work Order

CORNWALL

Number:

556



MINIMAX EXPRESS TRANSPORTATION INC

VIN: 3AKJGEDV2GDHE2248

Make: FRHT

Model:

Year: 2016

Unit N°

357

Plate:

PA75573

☐ SCHEDULED WORK

Kilometer:

809695

Engine hours:

17383

Date opened:

2026-01-06

Date closed:

2026-01-12

T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	*\$/u*	Total
INS		PMB			TALENT TAMBAOGA, 2026-01-06						
INS		PMB			Comment / Request						
INS		PMB			change drive belts						
INS		PMB			engine lights						
INS		PMB			B service						
INS		PMB			Causes						
INS		PMB			open circuit on def line 4						
INS		PMB			ceased belt tensioner						
INS		PMB			Corrections						
INS		PMB			repaired def line4 wiring and changed the pigtail						
INS		PMB			replaced drive belts and belt tensioner and secured fan hub wiring						
INS		PMB			completed AB service						
INS		PMB			repaired and secured quarter fender						
INS		PMB			*****						
INS		PMB	FK11011		FUEL FILTER KIT						
INS		PMB	LF17810		OIL FILTER						
INS		PMB	10W30		MOTOR OIL						
INS		PMB	GREASE PREMALUBE		GREASE PREMALUBE						

Comment:

COOLING SYSTEM

Signature :

Date :

Subtotal-parts:	841.14	+	0.00
Subtotal labor:	731.85		0.00
Shop supply:	109.78		
TOTAL (\$):	1682.77		
Hrs.	8.61		

Work Order

CORNWALL

Number:

556



MINIMAX EXPRESS TRANSPORTATION INC

VIN: 3AKJGEDV2GDDHE2248

Make: FRHT

Model:

Year: 2016

Unit N°

357

Plate:

PA75573

☐ SCHEDULED WORK

Kilometer:

809695

Engine hours:

17383

Date opened:

2026-01-06

Date closed:

2026-01-12

T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	*\$/u*	Total
INS		PMB	MDS-82-6707		1GA BATTERY CABLE RED		PTS3		1.00	262.870	262.870
INS		PMB	MDS-82-5707		1GA BATTERY CABLE BLACK		PTS3		1.00	262.870	262.870
INS		PMB			(8390) >> TTALENT 2026-01-06 13:53:32:84						
INS		PMB			Needs belt tensioner (8390) >> OK						
INS		PMB			(8391) >> TTALENT 2026-01-06 13:53:29:84						
INS		PMB			Needs drive belts (8391) >> OK						
INS		PMB			(8394) >> TTALENT 2026-01-06 13:53:55:24						
INS		PMB			engine lights (8394) >> OK						
INS		PMB			(8395) >> TTALENT 2026-01-06 13:54:12:04						
INS		PMB			B service (8395) >> OK						
INS		PMB			(679.686) >> TTALENT 2026-01-06 14:00:03:76						
INS		PMB			WIRING, AIR LINES & VALVES, ROUTING & SECURITY: TO REPAIR (679.686) >> OK						
INS		PMB			(688.728) >> TTALENT 2026-01-06 14:00:05:51						
INS		PMB			BATTERY BOX SECURITY, HOLD DOWNS, TERMINAL CONNECTIONS & CABLES, ELECTROLYTE LEV						
INS		PMB			(688.729) >> TTALENT 2026-01-06 14:00:07:62						
INS		PMB			REMOVE, CLEAN & REPAIR BATTERY CONNECTIONS AS REQUIRED. LOAD TEST BATTERIES EVER						
INS		PMB			(717.720) >> TTALENT 2026-01-06 14:00:09:68						

Comment:

COOLING SYSTEM

Signature :

Date :

Subtotal-parts:	841.14	+	0.00
Subtotal labor:	731.85		0.00
Shop supply:	109.78		
TOTAL (\$):	1682.77		
Hrs.	8.61		

Work Order

CORNWALL

Number:

556



MINIMAX EXPRESS TRANSPORTATION INC

VIN: 3AKJGEDV2GDHE2248

Make: FRHT

Model:

Year: 2016

Unit N°

357

Plate:

PA75573

☐ SCHEDULED WORK

Kilometer:
809695

Engine hours:
17383

Date opened:
Date closed:

2026-01-06
2026-01-12

T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	*\$/u*	Total
INS	INS	PMB			BELTS & HOSES: TO CHANGE (717.720) >> OK						
INS	INS	PMB			(717.723) >> TTALENT 2026-01-06 14:00:13:09						
INS	INS	PMB			ELECTRICAL WIRING, CONNECTIONS, ROUTING, SECURITY: TO REPAIR (717.723) >> OK						
REP	REP	042			CHITAMBARA				3.98	85.00	338.30
REP	REP	045			TTALENT				2.28	85.00	193.80
INS	INS	PMB			TTALENT				2.35	85.00	199.75

Comment:
COOLING SYSTEM

Signature : _____ Date : _____

Subtotal-parts:	841.14	+	0.00
Subtotal labor:	731.85		0.00
Shop supply:	109.78		
TOTAL (\$) :	1682.77		Hrs. 8.61



Work Order

CORNWALL

Number:

799

MINIMAX EXPRESS TRANSPORTATION INC

Unit N°

357

05. WORK FINISHED

VIN: 3AKJGEDV2GDHE2248

Make: FRHT

Plate:

PA75573

☐ SCHEDULED WORK

Model:

Year: 2016

Kilometer:

809695

Engine hours:

17383

Date opened:

Date closed:

2026-01-29

2026-02-23

T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	*\$/u*	Total
REP	013		FLS-F3030LSP		3030 LS PIGGYBACK KIT				1.00	8.710	8.710
REP	013				CHRIS CHITAMBARA, 2026-02-20						
REP	013				Corrections						
REP	013				Replaced second axle passenger side piggy back						
REP	013				*****						
REP	013				(12871) >> CCHITAMBARA 2026-02-20 02:39:26:76						
REP	013				Brake chamber air leak (12871) (12871) >> OK						
REP	002		AQUESNEL		ANTHONY QUESNEL				1.60		
REP	013										
REP	013		CCHITAMBARA		CHRIS CHITAMBARA				1.49	85.00	126.65

Comment:

CAB, SLEEPER AND SHEET METAL

Signature : _____

Date : _____

Subtotal-parts:	8.71	+	0.00
Subtotal labor:	126.65		0.00
Shop supply:	19.00		
TOTAL (\$) :	154.36		
		Hrs.	3.09

Work Order



MINIMAX EXPRESS TRANSPORTATION INC

VIN: 3AKJGEDV2GDHE2248

Make: FRHT

Model:

Year: 2016

Unit N° 357

Plate: PA75573

Kilometer: 822176

Engine hours: 17484

CORNWALL

Number:

1066

05. WORK FINISHED

☐ SCHEDULED WORK

Date opened:

Date closed:

2026-03-12

2026-06-26

T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	*\$/u*	Total
REP	DEF	PTSS			DEF MAINTENANCE						
REP	DEF				(14613) >> TTALENT 2026-03-12 22:54:02:87						
REP	DEF				engine light diagnosis (14613) (14613) >> OK						
REP	DEF				TALENT TAMBAOGA, 2026-03-12						
REP	DEF				Corrections						
REP	DEF				plugged a scan tool and found a derate for Aftertreatment						
REP	DEF				Initiated diagnostic procedure and started a regen-completed						
REP	DEF				Initiated Nox verification - passed						
REP	DEF				initiated SCR efficiency test- compiled- derate lifted and cleared fault codes						
REP	DEF				*****						
REP	DEF				AARON ANDERSON, 2026-03-25						
REP	044				Comment / Request						
REP	044				Forgot to punch on at 4:30PM brought truck in for fuel tanks not equal levels,						
REP	044				both tanks full to the caps, looked over fuel system, removed lines at 2 brass						
REP	044				T fittings where supply and return go from 2 lines, one each tank, to 1 line						
REP	044				for supply to water separator and 1 line for return from fuel filter housing.						

Comment:

DEF MAINTENANCE

Signature :

Date :

Subtotal-parts:	348.95 +	0.00
Subtotal labor:	2289.05	0.00
Shop supply:	343.36	
TOTAL (\$):	2981.36	Hrs. 26.93



Work Order

CORNWALL

Number:

1066

MINIMAX EXPRESS TRANSPORTATION INC

Unit N°

357

05. WORK FINISHED

VIN: 3AKJGEDV2GDHE2248

Make: FRHT

Model:

Year: 2016

Plate:

PA75573

☐ SCHEDULED WORK

Kilometer:

822176

Engine hours:

17484

Date opened:

2026-03-12

Date closed:

2026-06-26

T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	*\$/u*	Total
REP	044				no obstructions in any fuel tank lines or the brass T itself, unable to remove						
REP	044				brass from bracket on top of transmission, Globocam Cornwall didn't have parts						
REP	044				in stock, put absorbal down for spit fuel, reinstalled lines to brass T's ran,						
REP	044				no fuel prime loss or leaks at fittings, power washed fuel off truck and						
REP	044				parked, cleaned up old absorbal, put fresh stuff down, will clean pit again						
REP	044				later after absorbal has absorbed the fuel						
REP	044				*****						
REP	013				GARY ROLLAND, 2026-03-26						
REP	013				Comment / Request						
REP	013				ADJUST BRAKES						
REP	013				REPLACE LEAKING AIR LINE ON 3RD AXLE LEFT						
REP	013				SIDE EMERGENCY LINE						
REP	013				REPLACED SLACK ADJUSTER ADJUSTING PAUL ON						
REP	013				3RD AND LEFT SIDE SLACK.						
REP	013				Corrections						
REP	013				USED 1 PART NUMBER 4120R-6C-RK						
REP	013				USED 2 FEET OF 3/8 RUBBER AIR LINE						
REP	013				USED ONE SLACK ADJUSTER PAUL						

Comment:

DEF MAINTENANCE

Signature :

Date :

Subtotal-parts:	348.95	+	0.00
Subtotal labor:	2289.05		0.00
Shop supply:	343.36		
TOTAL (\$):	2981.36		
Hrs.	26.93		

Work Order

CORNWALL

Number:

1066

MINIMAX EXPRESS TRANSPORTATION INC

Unit N°

357

05. WORK FINISHED



VIN: 3AKJGEDV2GDHE2248

Make: FRHT

Model:

Year: 2016

Plate:

PA75573

☐ SCHEDULED WORK

Kilometer:
822176

Engine hours:
17484

Date opened:
Date closed:

2026-03-12
2026-06-26

T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	*\$/u*	Total
REP	013				*****						
REP	002				GARY ROLLAND, 2026-04-01						
REP	002				Corrections						
REP	002				replaced right side convex mirror part number H 28717A.						
REP	002										
REP	002										
REP	002										
REP	002				*****						
REP	100				(15898) >> GROLLAND 2026-04-01 09:04:30:69						
REP	100				replace right side convex mirror. (15898) >> OK						
REP	100				SERVICE A						
INS	PMA	PTS2			(10890) >> TALENT 2026-04-08 17:47:37:18						
INS	PMA				replaced wiper blade motor (10890) (10890) >> OK						
INS	PMA				TALENT TAMBAOGA, 2026-04-08						
INS	PMA				Corrections						
INS	PMA				Drained coolant						
INS	PMA				replaced cabin heater supply and return steel lines						
INS	PMA				replaced fittings						

Comment:

DEF MAINTENANCE

Signature : _____ Date : _____

Subtotal-parts:	348.95	+	0.00
Subtotal labor:	2289.05		0.00
Shop supply:	343.36		
TOTAL (\$):	2981.36		
Hrs.	26.93		

Work Order

CORNWALL

Number:

1066

MINIMAX EXPRESS TRANSPORTATION INC

Unit N°

357

05. WORK FINISHED



VIN: 3AKJGEDV2GDHE2248

Make: FRHT

Model:

Year: 2016

Plate:

PA75573

☐ SCHEDULED WORK

Kilometer:
822176

Engine hours:
17484

Date opened:

Date closed:

2026-03-12

2026-06-26

T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	*\$/u*	Total
	INS	PMA			Performed pressure test to confirm coolant leak repair						
	INS	PMA			Troubleshoot SCR efficiency fault codes, removed def doser and found						
	INS	PMA			crystallization at the port						
	INS	PMA			cleaned and ran a def quantity test-passsed, initiated a Regen- passed						
	INS	PMA			Initiated SCR efficiency test -passed						
	INS	PMA			changed mud flap bracket (used)						
	INS	PMA			Completed A service						
	INS	PMA			*****						
	INS	PMA			TUBE-COOLANT DD13 RETURN		PTS2		1.00	157.080	157.080
	INS	PMA			TUBE-COOLANT DD13 SUPPLY		PTS2		1.00	146.050	146.050
	INS	PMA			DEF DOSER GASKET		PTS2		1.00	22.790	22.790
	INS	PMA			GREASE PREMALUBE		PTS2		1.00		
	INS	PMA			(679.686) >> TTALENT 2026-04-08 22:49:32:97						
	INS	PMA			WIRING, AIR LINES & VALVES, ROUTING & SECURITY: TO REPAIR (679.686) >> OK						
	INS	PMA			(717.725) >> TTALENT 2026-04-08 22:49:27:42						
	INS	PMA			FLUID LEVELS, LEAKS ETC.: TO REPAIR (717.725) >> OK						
	INS	PMA			(16165) >> TTALENT 2026-04-08 22:49:58:47						

Comment:

DEF MAINTENANCE

Signature :

Date :

Subtotal-parts:	348.95	+	0.00
Subtotal labor:	2289.05		0.00
Shop supply:	343.36		
TOTAL (\$):	2981.36		
Hrs.	26.93		



Work Order

CORNWALL

Number:

1066

MINIMAX EXPRESS TRANSPORTATION INC

Unit N°

357

05. WORK FINISHED

VIN: 3AKJGEDV2GDHE2248

Make: FRHT

Model:

Year: 2016

Plate:

PA75573

☐ SCHEDULED WORK

Kilometer:

822176

Engine hours:

17484

Date opened:

2026-03-12

Date closed:

2026-06-26

T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	*\$/u*	Total
INS		PMA			Engine light SCR related issues (16165) (16165) >> OK						
REP		GREASE			CHRIS CHITAMBARA, 2026-04-09						
REP		GREASE			Comment / Request						
REP		GREASE			Grease all grease points						
REP		GREASE			Corrections						
REP		GREASE			Greased all grease points						
REP		GREASE			*****						
REP		GREASE			(691.699) >> CCHITAMBARA 2026-04-09 01:45:30:68						
REP		GREASE			LUBRICATE DRIVE/CLUTCH LINKAGE & RELEASE BEARING: TO ADJUST (691.699) >> OK						
REP		GREASE			(717.724) >> CCHITAMBARA 2026-04-09 01:45:30:13						
REP		GREASE			LUBRICATE LINKAGE ON ENTIRE VEHICLE AS REQUIRED: TO REPAIR (717.724) >> OK						
REP		GREASE			CHRIS CHITAMBARA, 2026-04-14						
REP		013			Comment / Request						
REP		013			Change font brakes						
REP		013			Corrections						
REP		013			Removed and replaced front brake drums and brake shoes						
REP		013			*****						

Comment:

DEF MAINTENANCE

Signature :

Date :

Subtotal-parts:	348.95	+	0.00
Subtotal labor:	2289.05		0.00
Shop supply:	343.36		
TOTAL (\$):	2981.36		
Hrs.	26.93		



MINIMAX EXPRESS TRANSPORTATION INC

VIN: 3AKJGEDV2GDHE2248

Unit N° 357

05. WORK FINISHED

Make: FRHT

Model:

Year: 2016

Plate: PA75573

☐ SCHEDULED WORK

Kilometer: 822176

Engine hours: 17484

Date opened: 2026-03-12

Date closed: 2026-06-26

T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	*\$/u*	Total
🔧	REP	013			CHRIS CHITAMBARA, 2026-04-14						
🔧	REP	013			Comment / Request						
🔧	REP	013			Front axle passenger side wheel seal leaking						
🔧	REP	013			Corrections						
🔧	REP	013			Removed and replaced Front axle passenger side wheel seal						
🔧	REP	013			*****						
🔧	REP	013			CHRIS CHITAMBARA, 2026-04-14						
🔧	REP	013			Corrections						
🔧	REP	013			Torqued steer wheels to 500lbs and issued a torque tag						
🔧	REP	013			*****						
🔧	REP	013			CHRIS CHITAMBARA, 2026-04-14						
🔧	REP	013			Corrections						
🔧	REP	013			Front brake drums not in stock - Part 37BD588						
🔧	REP	013			Brake shoes not in stock - Part ALR048						
🔧	REP	013			Front wheel seal not in stock - Part ABP10045885						
🔧	REP	013			*****						
🔧	REP	013			(16383) >> CCHITAMBARA 2026-04-14 03:25:20:55						
🔧	REP	013			Change font brakes (16383) (16383) >> OK						

Comment:

DEF MAINTENANCE

Subtotal-parts:

348.95 +

0.00

Subtotal labor:

2289.05

0.00

Shop supply:

343.36

TOTAL (\$):

2981.36

Hrs. 26.93

Signature : _____ Date : _____

Work Order

CORNWALL

Number:

1066

MINIMAX EXPRESS TRANSPORTATION INC

Unit N°

357

05. WORK FINISHED



VIN: 3AKJGEDV2GDHE2248

Make: FRHT

Model:

Year: 2016

Plate:

PA75573

☐ SCHEDULED WORK

Kilometer:

822176

Engine hours:

17484

Date opened:

2026-03-12

Date closed: 2026-06-26

T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	*\$/u*	Total
REP		013			(16384) >> CCHITAMBARA 2026-04-14 03:25:22:11						
REP		013			Front axle passenger side wheel seal leaking (16384) (16384) >> OK						
REP		042			AARON ANDERSON, 2026-04-21						
REP		042			Comment / Request						
REP		042			about to bring truck in to swap coolant thermostat and change AC lines						
REP		042			*****						
REP		042			AARON ANDERSON, 2026-04-22						
REP		042			Comment / Request						
REP		042			cleaned bay, brought truck in, drained coolant from block, fitting seized, got						
REP		042			AC machine out, recovered what was in system, less than 1 pound, no R134 in						
REP		042			machine, started filling machine, removed old lines, everything seized and						
REP		042			corroded, cleaned surfaces and installed new lines, don't know how this AC						
REP		042			machine works, disconnected AC compressor until it can be filled, noticed						
REP		042			change air pipe on passenger side had 2 holes in it, changed with new pipe and						
REP		042			2 "411" charge air clamps, swapped thermostat, filled system, pressure tested						
REP		042			no leaks, took outside power washed and ran at high idle to burp system,						

Comment:

DEF MAINTENANCE

Signature :

Date :

Subtotal-parts:	348.95	+	0.00
Subtotal labor:	2289.05		0.00
Shop supply:	343.36		
TOTAL (\$):	2981.36		
Hrs.	26.93		

Work Order

CORNWALL

Number:

1066



MINIMAX EXPRESS TRANSPORTATION INC

VIN: 3AKJGEDV2GDHE2248

Make: FRHT

Model:

Year: 2016

Unit N°

357

Plate:

PA75573

☐ SCHEDULED WORK

Kilometer:

822176

Engine hours:

17484

Date opened:

2026-03-12

Date closed:

2026-06-26

T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	*\$/u*	Total
	REP	042			brought back in, fixed misaligned wipers, will need coolant top up once cool,						
	REP	042			cleaned bay and put away tools						
	REP	042			*****						
	REP	DEF			TALENT TAMBAOGA, 2026-04-24						
	REP	DEF			Corrections						
	REP	DEF			initiated regen completed						
	REP	DEF			initiated scr efficiency test-passed						
	REP	DEF			*****						
	REP	DEF			TALENT TAMBAOGA, 2026-05-06						
	REP	DEF			Comment / Request						
	REP	DEF			engine light						
	REP	DEF			Corrections						
	REP	DEF			plugged scan tool and found active fault codes						
	REP	DEF			scr efficiency low ,initiated diagnostic procedure						
	REP	DEF			execute regen as required - completed						
	REP	DEF			performed nox verification - passed						
	REP	DEF			initiated scr efficiency test						
	REP	DEF			*****						

Comment:

DEF MAINTENANCE

Signature : _____ Date : _____

Subtotal-parts:	348.95 +	0.00
Subtotal labor:	2289.05	0.00
Shop supply:	343.36	
TOTAL (\$):	2981.36	Hrs. 26.93

Work Order

CORNWALL

Number:

1066

MINIMAX EXPRESS TRANSPORTATION INC

Unit N°

357

05. WORK FINISHED

VIN: 3AKJGEDV2GDHE2248

Make: FRHT

Plate:

PA75573

☐ SCHEDULED WORK

Model:

Year: 2016

Kilometer:

822176

Engine hours:

17484

Date opened:

2026-03-12

Date closed:

2026-06-26



T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	*\$/u*	Total
REP	DEF				(18310) >> TTALENT 2026-05-06 01:12:43:78						
REP	DEF				engine light (18310) (18310) >> OK						
REP	DPF	PTS4			DPF MAINTENANCE						
REP	DPF				CHRIS CHITAMBARA, 2026-05-26						
REP	DPF				Corrections						
REP	DPF				Initiated DEF quantity test - test passed						
REP	DPF				Carried out parked regen						
REP	DPF				*****						
REP	DEF				(19957) >> TTALENT 2026-06-02 22:29:15:18						
REP	DEF				Engine check light (19957) (19957) >> OK						
REP	DEF				TALENT TAMBAOGA, 2026-06-02						
REP	DEF				Corrections						
REP	DEF				plugged scan tool and found a previously incomplete troubleshooting procedure						
REP	DEF				initiated completion and scr efficiency was carried out						
REP	DEF				passed and engine light cleared						
REP	DEF				*****						
REP	DEF										
REP	042	05-32313-000			RAD CAP-SURGE TANK,FILL				1.00	14.590	14.590
REP	042	STN ACA2724			RAD CAP				1.00	8.440	8.440

Comment:

DEF MAINTENANCE

Signature : _____ Date : _____

Subtotal-parts:	348.95	+	0.00
Subtotal labor:	2289.05		0.00
Shop supply:	343.36		
TOTAL (\$):	2981.36		
		Hts.	26.93

Work Order

CORNWALL

Number:

1066

MINIMAX EXPRESS TRANSPORTATION INC

Unit N°

357

05. WORK FINISHED



VIN: 3AKJGEDV2GDHE2248

Make: FRHT

Model:

Year: 2016

Plate:

PA75573

☐ SCHEDULED WORK

Kilometer:

822176

Engine hours:

17484

Date opened:

2026-03-12

Date closed: 2026-06-26

T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	*\$/u*	Total
REP	042				TALENT TAMBAOGA, 2026-06-08						
REP	042				Corrections						
REP	042				DRAINED OVER FILLED COOLANT AND CHANGED SURGE TANK CAPS						
REP	042				*****						
REP	002				GARY ROLLAND, 2026-06-15						
REP	002				Corrections						
REP	002				PRESSURE TEST AND CHARGE A/C SYSTEM. LINES WERE REPLACED AHEAD.						
REP	002				*****						
REP	002				GARY ROLLAND, 2026-06-15						
REP	002				Corrections						
REP	002				GARY. PRESSURE TESTED A/C SYSTEM AND REFILLED. 2.88LBS. OF FREON.						
REP	002				*****						
REP	002				(21193) >> GROLLAND 2026-06-15 16:53:11:13						
REP	002				PRESSURE TEST A/C AND REFILL. (21193) (21193)						
REP	002				>> OK						
REP	DPF				TALENT TAMBAOGA, 2026-06-19						
REP	DPF				Corrections						
REP	DPF				initiated regen -completed						

Comment:

DEF MAINTENANCE

Signature : _____ Date : _____

Subtotal-parts:	348.95	+	0.00
Subtotal labor:	2289.05		0.00
Shop supply:	343.36		
TOTAL (\$):	2981.36		
Hrs.	26.93		



MINIMAX EXPRESS TRANSPORTATION INC

VIN: 3AKJGEDV2GDHE2248

Make: FRHT

Model:

Year: 2016

Unit N°

357

Plate:

PA75573

Kilometer:

822176

Engine hours:

17484

Date opened:

2026-03-12

Date closed: 2026-06-26

CORNWALL

Number:

1066

05. WORK FINISHED

☐ SCHEDULED WORK

T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	*\$/u*	Total
REP	DPF				initiated scr efficiency - completed						
REP	DPF				*****						
REP	DPF				(21648) >> TALENT 2026-06-19 22:56:33:01						
REP	DPF				engine light (21648) (21648) >> OK						
REP	DEF		TTALENT		TALENT TAMBAOGA				5.62	85.00	477.70
REP	044		AANDERSON		AARON ANDERSON				0.10	85.00	8.50
REP	013		GROLLAND		GARY ROLLAND				0.91	85.00	77.35
REP	002		GROLLAND		GARY ROLLAND				3.27	85.00	277.95
INS	PMA		TTALENT		TALENT TAMBAOGA				5.07	85.00	430.95
REP	GREASE		CCHITAMBARA		CHRIS CHITAMBARA				1.92	85.00	163.20
REP	013		CCHITAMBARA		CHRIS CHITAMBARA				2.00	85.00	170.00
REP	042		AANDERSON		AARON ANDERSON				3.25	85.00	276.25
REP	DPF		CCHITAMBARA		CHRIS CHITAMBARA				4.37	85.00	371.45
REP	042		TTALENT		TALENT TAMBAOGA				0.38	85.00	32.30
REP	DPF		TTALENT		TALENT TAMBAOGA				0.04	85.00	3.40

Comment:

DEF MAINTENANCE

Signature : _____ Date : _____

Subtotal-parts:	348.95	+	0.00
Subtotal labor:	2289.05		0.00
Shop supply:	343.36		
TOTAL (\$) :	2981.36		Hrs. 26.93

Work Order

CORNWALL

Number:

1695



MINIMAX EXPRESS TRANSPORTATION INC

VIN: 3AKJGEDV2GDHE2248

Make: FRHT

Model:

Year: 2016

Unit No

357

Plate:

PA75573

☐ SCHEDULED WORK

Kilometer:
842908

Engine hours:
18163

Date opened:

2026-07-08

Date closed:

2026-10-05

T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	*\$/u*	Total
✓	REP	DPF	PTS4		DPF MAINTENANCE						
✓	REP	DPF			TALENT TAMBAOGA, 2026-07-08						
✓	REP	DPF			Corrections						
✓	REP	DPF			Disassembled One box removed DPF filters to assess condition						
✓	REP	DPF			found exhaust leaks around dpf v-clamps						
✓	REP	DPF			Prepared surfaces for installation						
✓	REP	DPF			Installed DPF filters with new hardware						
✓	REP	DPF			Initiated diagnostic procedure and was lead to a Regen-complete						
✓	REP	DPF			Initiated SCR efficiency test - completed with 80 to 90%						
✓	REP	DPF			Brought vehicle in the shop and assembled all covers and steps						
✓	REP	DPF			Check lights and derate got lifted						
✓	REP	DPF			*****						
✓	REP	DPF	1410		DPF GASKET		PTS4		2.00		
✓	REP	DPF			(22666) >> TALENT 2026-07-08 15:25:43:79						
✓	REP	DPF			engine lights (22666) (22666) >> OK						
✓	REP	DPF			(22667) >> TALENT 2026-07-08 15:25:42:17						
✓	REP	DPF			One box leak (22667) (22667) >> OK						

Comment:

DPF MAINTENANCE

Signature : _____ Date : _____

Subtotal-parts:	0.00	+	0.00
Subtotal labor:	948.60		0.00
Shop supply:	142.29		
TOTAL (\$):	1090.89	Hrs.	13.72



Work Order

MINIMAX EXPRESS TRANSPORTATION INC

CORNWALL

Number:

1695

Unit N°

357

05. WORK FINISHED

VIN: 3AKJGEDV2GDHE2248

Make: FRHT

Model:

Year: 2016

Plate:

PA75573

☐ SCHEDULED WORK

Kilometer:

842908

Engine hours:

18163

Date opened:

2026-07-08

Date closed:

2026-10-05

T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	*\$/u*	Total
🔧	GAR	002			AARON ANDERSON, 2026-08-27						
🔧	GAR	002			Comment / Request						
🔧	GAR	002			starting sticker removal for auction						
🔧	GAR	002			*****						
🔧	GAR	002			AARON ANDERSON, 2026-08-27						
🔧	GAR	002			Comment / Request						
🔧	GAR	002			starting sticker removal for auction						
🔧	GAR	002			*****						
🔧	REP	DEF	PTS5		DEF MAINTENANCE						
🔧	REP	DEF			TALENT TAMBAOGA, 2026-08-27						
🔧	REP	DEF			Corrections						
🔧	REP	DEF			initiated regen-completed						
🔧	REP	DEF			initiated SCR efficiency test and completed and passed 88%						
🔧	REP	DEF			cleared inactive fault codes						
🔧	REP	DEF			*****						
🔧	REP	002			AARON ANDERSON, 2026-09-17						
🔧	REP	002			Comment / Request						
🔧	REP	002			removing unit numbers then starting detail						

Comment:

DPF MAINTENANCE

Signature : _____ Date : _____

Subtotal-parts:	0.00	+	0.00
Subtotal labor:	948.60		0.00
Shop supply:	142.29		
TOTAL (\$):	1090.89		Hrs. 13.72

Work Order

CORNWALL

Number:

1695

MINIMAX EXPRESS TRANSPORTATION INC

Unit N°

357

05. WORK FINISHED

VIN: 3AKJGEDV2GDHE2248

Make: FRHT

Plate:

PA75573

☐ SCHEDULED WORK

Model:

Year: 2016

Kilometer:

842908

Engine hours:

18163

Date opened:

2026-07-08

Date closed:

2026-10-05



T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	*\$/u*	Total
REP	002				*****						
REP	002				AARON ANDERSON, 2026-09-18						
REP	002				Comment / Request						
REP	002				removed safety equipment, only binder and owners manuals left in truck.						
REP	002				vacuumed, air blew out cab and vacuumed again, gave interior a wipe down with hot water, will need another wipe down with hot water then detailed with						
REP	002				cleaners, parked truck, put away tools						
REP	002				*****						
REP	002				AARON ANDERSON, 2026-09-18						
REP	002				Comment / Request						
REP	002				Detailing interior						
REP	002				*****						
REP	002				AARON ANDERSON, 2026-09-18						
REP	002				Comment / Request						
REP	002				finished detail, parked truck						
REP	002				*****						
REP	002				SAFETY						

Comment:

DPF MAINTENANCE

Signature : _____ Date : _____

Subtotal-parts:	0.00	+	0.00
Subtotal labor:	948.60		0.00
Shop supply:	142.29		
TOTAL (\$):	1090.89		
Hrs.	13.72		



Work Order

CORNWALL

Number:

1695

MINIMAX EXPRESS TRANSPORTATION INC

VIN: 3AKJGEDV2GDHE2248

Make: FRHT

Model:

Year: 2016

Unit N°

357

Plate:

PA75573

☐ SCHEDULED WORK

Kilometer:

842908

Engine hours:

18163

Date opened:

2026-07-08

Date closed:

2026-10-05

T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	*\$/u*	Total
☒	INS	PMA	PTS2		SERVICE A						
	INS	SAFETY			(691.698) >> GROLLAND 2026-09-22 15:33:29:15						
	INS	SAFETY			DRIVELINE, UNIVERSAL JOINTS, HANGER BEARINGS: TO ADJUST (691.698) >> OK						
	INS	SAFETY			>> GROLLAND 2026-09-22 15:33:26:24						
	INS	SAFETY			@NOT537:injector harness passthrough leaking						
	REP	SAFETY			JOHN HAMILTON, 2026-09-22						
	REP	SAFETY			Corrections						
	REP	SAFETY			did safety inspection and made a list of repairs						
	REP	SAFETY			*****						
	REP	DPF	TTALENT		TALENT TAMBAOGA				3.65	85.00	310.25
	GAR	002	AANDERSON		AARON ANDERSON				2.56		
	REP	DEF	TTALENT		TALENT TAMBAOGA				0.04	85.00	3.40
	REP	002	AANDERSON		AARON ANDERSON				2.25	85.00	191.25
	INS	PMA	GROLLAND		GARY ROLLAND				0.04	85.00	3.40
	INS	SAFETY	GROLLAND		GARY ROLLAND				2.75	85.00	233.75
	REP	SAFETY #2TECK			JOHN HAMILTON				2.43	85.00	206.55

Comment:

DPF MAINTENANCE

Signature : _____ Date : _____

Subtotal-parts:	0.00	+	0.00
Subtotal labor:	948.60		0.00
Shop supply:	142.29		
TOTAL (\$) :	1090.89		Hts. 13.72

Work Order

CORNWALL

Number:

1846

MINIMAX EXPRESS TRANSPORTATION INC

Unit N°

357

05. WORK FINISHED



VIN: 3AKJGEDV2GDE2248

Make: FRHT

Model:

Year: 2016

Plate:

PA75573

☐ SCHEDULED WORK

Kilometer:

838919

Engine hours:

18077

Date opened:

2026-07-23

Date closed:

2026-08-05

T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	\$/u*	Total
					** START ** Source : PO# 2507						
					Transferred by : ST DENIS, ROLLAND - 2026-07-23						
	REP	042	DDE A4712007515		Thermostat		09P26165		1.00	230.990	230.990
	REP	042	DDE A4722033480		SEAL		09P26165		1.00	9.130	9.130
					** END **						
	REP	DPF			CHRIS CHITAMBARA, 2026-07-29						
	REP	DPF			Comment / Request						
	REP	DPF			Check light						
	REP	DPF			Corrections						
	REP	DPF			Carried out parked regen and cleared error code						
	REP	DPF			*****						
	REP	DPF			DPF MAINTENANCE						
	REP	DPF	PTS4								
	REP	DPF	CCHITAMBARA		CHRIS CHITAMBARA				2.50	85.00	212.50

Comment:
installed thermostat and gasket

Signature : _____ Date : _____

Subtotal-parts:	240.12 +	0.00
Subtotal labor:	212.50	0.00
Shop supply:	31.88	
TOTAL (\$):	484.50	Hrs. 2.50

Work Order

CORNWALL

Number:

1908

MINIMAX EXPRESS TRANSPORTATION INC

Unit N°

357

05. WORK FINISHED



VIN: 3AKJGEDV2GPDHE2248

Make: FRHT

Model:

Year: 2016

Plate:

PA75573

☐ SCHEDULED WORK

Kilometer:

840123

Engine hours:

18101

Date opened:

2026-07-30

Date closed:

2026-08-05

T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	\$/u*	Total
					** START ** Source : PO# 2430						
					Transferred by : ST DENIS, ROLLAND - 2026-07-30						
	REP	002	TL 28717A		GLASS CONVEX MIRROR		09P25437		1.00	24.340	24.340
	REP	018	STM 372 7097		TRAILER WHEEL SET		09P25437		2.00	69.406	138.810
	REP	014	GRN NF30P7		PAINTED BRACKET		09P25437		1.00	68.330	68.330
	REP	013	WAB 925 347 027 0		BRAKE CHAMBER WAB,ADB,D1824,090,270		09P25437		6.00	101.991	611.950
	REP	032	STM 372 7097		TRAILER WHEEL SET		09P25437		6.00	69.406	416.440
	REP	031	EPN DD1131XME		BATTERIE GRP31 1000CCA		09P25437		6.00	138.637	831.820
	REP	014	EPN DD1131XME-C		CONSIGNE TYPE,AMD		09P25437		6.00	37.334	224.000
	REP	005	A05-31253-001		PIPE-HEATER,3/4,STRAIGHT,150MM		09P25437		1.00	27.270	27.270
	REP	013	GC3030		3030 COMBO 2. 50IN STROKE		09P25437		3.00	112.212	336.640
	REP	018	SET414SKF		TAPERED BEARING SET-INNER N TRAILER AXLE		09P25437		4.00	84.030	336.120
					** END **						

Comment:
parts for truck

Signature : _____ Date : _____

Subtotal-parts:	3015.72 +	0.00
Subtotal labor:	0.00	0.00
Shop supply:	0.00	
TOTAL (\$):	3015.72	Hts. 0.00

1913



05. WORK FINISHED

☐ SCHEDULED WORK

2026-07-30
2026-08-05

[illegible]

engine check light

Date : _____

Subtotal-parts:	431.64	 0.00
Subtotal labor:	2.55	 0.00
Shop supply:	0.38	
TOTAL (\$) :	434.57	Hrs. 0.03

2085



☐ SCHEDULED WORK

2026-08-19

Date closed:

Hrs. 985.11

Printed: 2026-10-06 by: ST DENIS, ROLLAND