69527

Sales Invoice

S04-1

Number: 26773
Reference: 2021 Kenworth
Issued: 05/02/2026
Due: 06/01/2026

Deliver To
Box 969
Grande Prairie AB T8V 3Y1

Moffatt Resources Inc (BJ Moffat)
Box 969
Grande Prairie AB T8V 3Y1

MVR Mechanical Ltd.
RR#1 Site 4, Box 25
Sexsmith AB T0H3C0
Canada
7805186291
mike@mvrmechanical.com
GST/HST 851918615 RT 0001

Item	Qty/Hrs	Price/Rate	Sales Tax	Net
SHOP TIME - April 29-May 2, 2026	22.50	140.00	GST 5.00%	3,150.00
CLUTCH BRAKE	1.00	42.42	GST 5.00%	42.42
K2468 - Clutch Install Kit	1.00	345.54	GST 5.00%	345.54
4965569 - ISX Rear Crank Seal	1.00	217.68	GST 5.00%	217.68
SW50A3 - Clamp, Westfalia, 5" SS	3.00	32.28	GST 5.00%	96.84
SF536 - 5x36" Flex Exhaust Hose	0.33	200.28	GST 5.00%	66.09
SW40A3 - CLAMP, WESTFALIA 4" SS	1.00	25.02	GST 5.00%	25.02
2507018X - SPL 250 STRAP KITS	2.00	32.16	GST 5.00%	64.32
E80-1012-008 - Spacer-Round 7.2x50x8 ACE	2.00	20.60	GST 5.00%	41.20
Brass, Push Connect	1.00	8.44	GST 5.00%	8.44
Brass	1.00	4.22	GST 5.00%	4.22

Total Net	4,061.77
GST 5.00%	203.08
Invoice Total	**4,264.85**
Total to Pay	[redacted]

Comments
April 29-May 2, 2026
Mileage: 473818
Hours: 11763
VIN: 1NKWL40X2NR985814
License: 0DL524
Year: 2022
Unit:
Make: Kenworth
Model: T800
Removed crossmember and pulled down exhaust pipe.
Removed steady bearing and section of driveline between trans and bearing. Disconnected air lines from shifter and removed shifter out. Put cover on.
Disconnected all wires, air line and other lines from transmission. Unbolted clutch from fly wheel and unbolted transmission.
Remove shaft that clutch sits on and replaced bearing, shaft snap rings and plate.
Removed flywheel. Replaced rear engine seal behind fly wheel.
Bolted flywheel on and torques bolts. Torqued clutch bolts, bolted transmission in and hooked up all lines and sensors.
Put bar on top of transmission.
Bolted driveline back up and hydraulic pump back into the PTO.
Put exhaust back together.
Fixed air leak on air tank.
Torqued U-joint bolts.
Installed shifter back in and adjusted clutch.

Terms and Conditions
Payment due upon pickup.