

www.girardgraderhire.com
accounts@girardgraderhire.com.au
0267526462
01/11/2023 - 06/11/2026

aquipa

Comprehensive Plant Management
https://aquipa.com

Upload Maintenance Form - 2348M26

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	05/06/2026
Date submitted:	09/06/2026

Plant Details

Owner	S & L Girard Grader Hire	Plant Image is not available
Make	Toyota	
Model	Hilux	
Type	4WD	
VIN / Serial	MR0FZ22G201156283	
Registration	DA39YP	
Plant Internal ID	DA39YP	
Aquipa Plant ID	2348M26	

Maintenance Upload Details	
Maintenance Description:	1 x Bridgestone tyre Submitted By Scott Girard - 09/06/2026 02:09 pm
Upload Files:	

Upload Maintenance Form - 2348M26

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	13/03/2026
Date submitted:	13/03/2026

Plant Details

Owner	S & L Girard Grader Hire	Plant Image is not available
Make	Toyota	
Model	Hilux	
Type	4WD	
VIN / Serial	MR0FZ22G201156283	
Registration	DA39YP	
Plant Internal ID	DA39YP	
Aquipa Plant ID	2348M26	

Maintenance Upload Details	
Maintenance Description:	480,083kms Next service at 490,000kms Submitted By Scott Peters - 13/03/2026 12:50 pm
Upload Files:	Basic Service Checklist.docx Submitted By Scott Peters - 13/03/2026 12:51 pm

Upload Maintenance Form - 2348M26

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	24/03/2025
Date submitted:	01/04/2025

Plant Details

Owner	S & L Girard Grader Hire	Plant Image is not available
Make	Toyota	
Model	Hilux	
Type	4WD	
VIN / Serial	MR0FZ22G201156283	
Registration	DA39YP	
Plant Internal ID	DA39YP	
Aquipa Plant ID	2348M26	

Maintenance Upload Details	
Maintenance Description:	Check bulbar lights due to not working found blown bulbs need to be replaced check the spiral cable due to horn not working all okay found that the horn was unplugged, plug the horn in went off straight away due to the steering wheel air bag horn pad being faulty and needs to be replaced fix seat belt not retracting properly repair bulbar lights by replacing bulbs and repairing damaged harness remove and replace L/H front upper and lower control arms Replace lower control arm pins Remove and replace broken wheel stud when removing found spilt brake line order replacement Remove and replace R/H upper control arm Remove and replace RH lower control arm and pins remove gearbox remove and replace clutch and flywheel remove and replace rear main seal due to leak present clean bell housing Remove and replace spigot bearing and release bearing remove and replace LH front brake line Replenish brake fluid remove and replace park light and LH indicator bulb tech note: When removing gear box noticed the front differential pinion bearing has too much play recommend replacing front differential centre tube wheel cylinder cleaning headlight with restoration kit Sand and polish headlights clean radiator bleed brake system and clutch fluid adjust clutch Submitted By Scott Girard - 01/04/2025 12:55 pm
Upload Files:	

Upload Maintenance Form - 2348M26

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	05/03/2025
Date submitted:	06/03/2025

Plant Details

Owner	S & L Girard Grader Hire	Plant Image is not available
Make	Toyota	
Model	Hilux	
Type	4WD	
VIN / Serial	MR0FZ22G201156283	
Registration	DA39YP	
Plant Internal ID	DA39YP	
Aquipa Plant ID	2348M26	

Details	
Maintenance Description:	Replaced 4x tyres 4x Yokohama LT265/60R18 tyres fitted and supplied by Jukes & Sons Tyre Centre Moree INV-320918 Submitted By Scott Girard - 06/03/2025 11:31 am
Upload Files:	

Upload Maintenance Form - 2348M26

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	25/11/2024
Date submitted:	05/12/2024

Plant Details

Owner	S & L Girard Grader Hire
Make	Toyota
Model	Hilux
Type	4WD
VIN / Serial	MR0FZ22G201156283
Registration	DA39YP
Plant Internal ID	DA39YP
Aquipa Plant ID	2348M26

Plant Image is not available

Details	
Maintenance Description:	REGO: DA39YP Inspect vehicle for no horn and cruise control not working Found spiral cable to be U/S Order replacement part Remove and replace Spiral cable Test operation, all ok Submitted By Scott Girard - 05/12/2024 11:08 am
Upload Files:	Invoice INV-0207.pdf Submitted By Scott Girard - 05/12/2024 11:08 am

Upload Maintenance Form - 2348M26

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	21/11/2024
Date submitted:	21/11/2024

Plant Details

Owner	S & L Girard Grader Hire	Plant Image is not available
Make	Toyota	
Model	Hilux	
Type	4WD	
VIN / Serial	MR0FZ22G201156283	
Registration	DA39YP	
Plant Internal ID	DA39YP	
Aquipa Plant ID	2348M26	

Details	
Maintenance Description:	NS 480,000kms Submitted By Scott Peters - 21/11/2024 01:06 pm
Upload Files:	Basic Service Checklist.docx

Upload Maintenance Form - 2348M26

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	31/05/2024
Date submitted:	31/05/2024

Plant Details

Owner	S & L Girard Grader Hire	Plant Image is not available
Make	Toyota	
Model	Hilux	
Type	4WD	
VIN / Serial	MR0FZ22G201156283	
Registration	DA39YP	
Plant Internal ID	DA39YP	
Aquipa Plant ID	2348M26	

Details	
Maintenance Description:	468,244kms Replaced steering rack Topped up power steering fluid Submitted By Scott Peters - 31/05/2024 12:28 pm
Upload Files:	

Upload Maintenance Form - 2348M26

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	22/05/2024

Plant Details

Owner	S & L Girard Grader Hire	Plant Image is not available
Make	Toyota	
Model	Hilux	
Type	4WD	
VIN / Serial	MR0FZ22G201156283	
Registration	DA39YP	
Plant Internal ID	DA39YP	
Aquipa Plant ID	2348M26	

Details	
Maintenance Description:	Replaced both tie rod ends Replaced left cv shaft Submitted By Scott Peters - 22/05/2024 01:16 pm
Upload Files:	

Basic Maintenance Form - 2348M26

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	07/03/2024
Date submitted:	07/03/2024

Plant Details

Owner	S & L Girard Grader Hire	Plant Image is not available
Make	Toyota	
Model	Hilux	
Type	4WD	
VIN / Serial	MR0FZ22G201156283	
Registration	DA39YP	
Plant Internal ID	DA39YP	
Aquipa Plant ID	2348M26	

Usage Log	
Odometer Reading (km)	467604 Submitted By Scott Peters - 07/03/2024 08:49 am

Details	
Maintenance Performed Date:	07/03/2024 Submitted By Scott Peters - 07/03/2024 08:49 am
Maintenance Description:	Fitted new front shocks Rewired rear taillights Submitted By Scott Peters - 07/03/2024 08:49 am
Upload Files:	

Upload Maintenance Form - 2348M26

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	20/12/2023

Plant Details

Owner	S & L Girard Grader Hire	Plant Image is not available
Make	Toyota	
Model	Hilux	
Type	4WD	
VIN / Serial	MR0FZ22G201156283	
Registration	DA39YP	
Plant Internal ID	DA39YP	
Aquipa Plant ID	2348M26	

Details	
Maintenance Performed Date:	20/12/2023 Submitted By Scott Peters - 20/12/2023 07:39 am
Maintenance Description:	Basic service Was serviced last at 462,000km Next service 470,000km Submitted By Scott Peters - 20/12/2023 07:40 am
Upload Files:	Basic Service Checklist.docx

Basic Maintenance Form - 2348M26

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	20/11/2023

Plant Details

Owner	S & L Girard Grader Hire	Plant Image is not available
Make	Toyota	
Model	Hilux	
Type	4WD	
VIN / Serial	MR0FZ22G201156283	
Registration	DA39YP	
Plant Internal ID	DA39YP	
Aquipa Plant ID	2348M26	

Usage Log	
Odometer Reading (km)	460576 Submitted By Scott Peters - 20/11/2023 11:34 am

Details	
Maintenance Performed Date:	20/11/2023 Submitted By Scott Peters - 20/11/2023 11:35 am
Maintenance Description:	Basic service Submitted By Scott Peters - 20/11/2023 11:35 am
Upload Files:	