www.girardgraderhire.com
accounts@girardgraderhire.com.au
0267526462
01/11/2023 - 06/11/2026

Comprehensive Plant Management
https://aquipa.com

Upload Maintenance Form - 2348M49

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	17/07/2026
Date submitted:	29/07/2026

Plant Details

Owner	S & L Girard Grader Hire
Make	Kenworth
Model	T409 SAR
Type	Prime Mover
VIN / Serial	6F5000000HA459103
Registration	XO22KK
Plant Internal ID	XO22KK
Aquipa Plant ID	2348M49



Maintenance Upload Details	
Maintenance Description:	inspect truck for engine light on dash connect diagnostic interface found codes logged for ABS and ECM communication codes advise customer of codes present as requested Submitted By Scott Girard - 29/07/2026 02:22 pm
Upload Files:	

Upload Maintenance Form - 2348M49

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	24/07/2026
Date submitted:	29/07/2026

Plant Details

Owner	S & L Girard Grader Hire
Make	Kenworth
Model	T409 SAR
Type	Prime Mover
VIN / Serial	6F5000000HA459103
Registration	XO22KK
Plant Internal ID	XO22KK
Aquipa Plant ID	2348M49



Maintenance Upload Details	
Maintenance Description:	1 x linglong 225/75R16 Submitted By Scott Girard - 29/07/2026 02:20 pm
Upload Files:	

Upload Maintenance Form - 2348M49

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	17/06/2026
Date submitted:	09/07/2026

Plant Details

Owner	S & L Girard Grader Hire
Make	Kenworth
Model	T409 SAR
Type	Prime Mover
VIN / Serial	6F5000000HA459103
Registration	XO22KK
Plant Internal ID	XO22KK
Aquipa Plant ID	2348M49



Maintenance Upload Details	
Maintenance Description:	replaced engine Submitted By Scott Girard - 09/07/2026 10:02 am
Upload Files:	

Upload Maintenance Form - 2348M49

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	14/04/2026
Date submitted:	28/04/2026

Plant Details

Owner	S & L Girard Grader Hire
Make	Kenworth
Model	T409 SAR
Type	Prime Mover
VIN / Serial	6F5000000HA459103
Registration	XO22KK
Plant Internal ID	XO22KK
Aquipa Plant ID	2348M49



Maintenance Upload Details	
Maintenance Description:	repairs to wiring on flashing lights Submitted By Scott Girard - 28/04/2026 01:46 pm
Upload Files:	

Upload Maintenance Form - 2348M49

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	15/04/2026
Date submitted:	16/04/2026

Plant Details

Owner	S & L Girard Grader Hire
Make	Kenworth
Model	T409 SAR
Type	Prime Mover
VIN / Serial	6F5000000HA459103
Registration	XO22KK
Plant Internal ID	XO22KK
Aquipa Plant ID	2348M49



Maintenance Upload Details	
Maintenance Description:	Serviced 955350kms 975000kms for next service Submitted By Scott Peters - 16/04/2026 10:04 am
Upload Files:	Basic Service Checklist.docx Submitted By Scott Peters - 16/04/2026 10:04 am

Upload Maintenance Form - 2348M49

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	10/04/2026
Date submitted:	13/04/2026

Plant Details

Owner	S & L Girard Grader Hire
Make	Kenworth
Model	T409 SAR
Type	Prime Mover
VIN / Serial	6F5000000HA459103
Registration	XO22KK
Plant Internal ID	XO22KK
Aquipa Plant ID	2348M49



Maintenance Upload Details	
Maintenance Description:	Replaces RH mirror Submitted By Scott Girard - 13/04/2026 01:35 pm
Upload Files:	

Upload Maintenance Form - 2348M49

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	22/03/2026
Date submitted:	26/03/2026

Plant Details

Owner	S & L Girard Grader Hire
Make	Kenworth
Model	T409 SAR
Type	Prime Mover
VIN / Serial	6F5000000HA459103
Registration	XO22KK
Plant Internal ID	XO22KK
Aquipa Plant ID	2348M49



Maintenance Upload Details	
Maintenance Description:	inspect truck for ad system not working blow out and pressure clean connect gauges found system to be low on refrigerant add 500g of refrigerant to system inspect sleeper ac system for not working found ac compressor to be cutting out too soon to low voltage Submitted By Scott Girard - 26/03/2026 02:31 pm
Upload Files:	

Upload Maintenance Form - 2348M49

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	14/03/2026
Date submitted:	19/03/2026

Plant Details

Owner	S & L Girard Grader Hire
Make	Kenworth
Model	T409 SAR
Type	Prime Mover
VIN / Serial	6F5000000HA459103
Registration	XO22KK
Plant Internal ID	XO22KK
Aquipa Plant ID	2348M49



Maintenance Upload Details	
Maintenance Description:	for worked completed on front end to improve handling control and complying and exceeding Australian standards 2670-1990 and in accordance with iso 2631-1 1985 for light and heavy commercial vehicles Submitted By Scott Girard - 19/03/2026 03:44 pm
Upload Files:	

Upload Maintenance Form - 2348M49

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	03/03/2026
Date submitted:	11/03/2026

Plant Details

Owner	S & L Girard Grader Hire
Make	Kenworth
Model	T409 SAR
Type	Prime Mover
VIN / Serial	6F5000000HA459103
Registration	XO22KK
Plant Internal ID	XO22KK
Aquipa Plant ID	2348M49



Maintenance Upload Details	
Maintenance Description:	repairs to RH blinker Submitted By Scott Girard - 11/03/2026 10:01 am
Upload Files:	

Upload Maintenance Form - 2348M49

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	11/12/2025
Date submitted:	12/12/2025

Plant Details

Owner	S & L Girard Grader Hire
Make	Kenworth
Model	T409 SAR
Type	Prime Mover
VIN / Serial	6F5000000HA459103
Registration	XO22KK
Plant Internal ID	XO22KK
Aquipa Plant ID	2348M49



Maintenance Upload Details	
Maintenance Description:	Diagnose sleeper AC system for not functioning correctly connect gauges found compressor to engage although low side is not pulling down enough for system to run efficiently due to worn compressor source and order compressor remove and replace compressor rewire compressor into system evacuate system charge system with 900g of refrigerant Submitted By Scott Girard - 12/12/2025 03:01 pm
Upload Files:	

Upload Maintenance Form - 2348M49

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	02/12/2025
Date submitted:	11/12/2025

Plant Details

Owner	S & L Girard Grader Hire
Make	Kenworth
Model	T409 SAR
Type	Prime Mover
VIN / Serial	6F5000000HA459103
Registration	XO22KK
Plant Internal ID	XO22KK
Aquipa Plant ID	2348M49



Maintenance Upload Details	
Maintenance Description:	8 haulmax tyres Submitted By Scott Girard - 11/12/2025 02:10 pm
Upload Files:	

Upload Maintenance Form - 2348M49

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	29/09/2025
Date submitted:	11/11/2025

Plant Details

Owner	S & L Girard Grader Hire
Make	Kenworth
Model	T409 SAR
Type	Prime Mover
VIN / Serial	6F5000000HA459103
Registration	XO22KK
Plant Internal ID	XO22KK
Aquipa Plant ID	2348M49



Maintenance Upload Details	
Maintenance Description:	ac not working correctly made new hose with fittings fit hose to truck evacuate system found second hose to have blown cut damaged hose to have blown evacuate system chareg system with 2500g of refrigerant Submitted By Scott Girard - 11/11/2025 10:58 am
Upload Files:	

Upload Maintenance Form - 2348M49

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	15/10/2025
Date submitted:	11/11/2025

Plant Details

Owner	S & L Girard Grader Hire
Make	Kenworth
Model	T409 SAR
Type	Prime Mover
VIN / Serial	6F5000000HA459103
Registration	XO22KK
Plant Internal ID	XO22KK
Aquipa Plant ID	2348M49



Maintenance Upload Details	
Maintenance Description:	2 x tyres BF goodtech 385-65R22.5 Submitted By Scott Girard - 11/11/2025 10:15 am
Upload Files:	

Upload Maintenance Form - 2348M49

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	29/10/2025
Date submitted:	11/11/2025

Plant Details

Owner	S & L Girard Grader Hire
Make	Kenworth
Model	T409 SAR
Type	Prime Mover
VIN / Serial	6F5000000HA459103
Registration	XO22KK
Plant Internal ID	XO22KK
Aquipa Plant ID	2348M49



Maintenance Upload Details	
Maintenance Description:	Replace the pinion shaft seals and the through shaft seals on the 2nd and 3rd axles tighten all mounting nuts and driveline bolts to the manufacturers specifications 7 out of 8 airbags have minor leaks recommend replacing all 8 replaced the shocks and mounting rubbers, along with the front shocks an axle 1, as they were beginning to weep oil adjust the clutch , which was out of adjustment on the pressure plate side, by modifying the linkages to increase clutch fork travel. advise the customer that the clutch will need replacing. remove the engine mount bolts and lift the engine with a forklift. replace the front engine mounts and tighten the bolts to the manufacturers specifications. lower the truck to the ground and diagnose the wiper issue. found the internal spline on the wiper arm was stripped and seized onto the shaft, twisting the actuator arm and preventing proper function. replace the necessary parts, test and confirm the repair remove the steering shaft note slight markings on the sealing surface where the sealing lip runs. replace the seal, reassemble the dust shield and snap ring and align the steering shaft with the marking. fill with 3 litres of ATF fluid operate the steering circuit and confirm the repair wash down the oil and debris Submitted By Scott Girard - 11/11/2025 10:05 am
Upload Files:	

Upload Maintenance Form - 2348M49

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	03/10/2025
Date submitted:	07/10/2025

Plant Details

Owner	S & L Girard Grader Hire
Make	Kenworth
Model	T409 SAR
Type	Prime Mover
VIN / Serial	6F5000000HA459103
Registration	XO22KK
Plant Internal ID	XO22KK
Aquipa Plant ID	2348M49



Maintenance Upload Details	
Maintenance Description:	4 new tyres Submitted By Scott Girard - 07/10/2025 03:22 pm
Upload Files:	

Upload Maintenance Form - 2348M49

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	30/09/2025
Date submitted:	07/10/2025

Plant Details

Owner	S & L Girard Grader Hire
Make	Kenworth
Model	T409 SAR
Type	Prime Mover
VIN / Serial	6F5000000HA459103
Registration	XO22KK
Plant Internal ID	XO22KK
Aquipa Plant ID	2348M49



Maintenance Upload Details	
Maintenance Description:	serviced truck at 9124502 kms Submitted By Scott Girard - 07/10/2025 03:20 pm
Upload Files:	

Upload Maintenance Form - 2348M49

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	30/09/2025
Date submitted:	30/09/2025

Plant Details

Owner	S & L Girard Grader Hire
Make	Kenworth
Model	T409 SAR
Type	Prime Mover
VIN / Serial	6F5000000HA459103
Registration	XO22KK
Plant Internal ID	XO22KK
Aquipa Plant ID	2348M49



Maintenance Upload Details	
Maintenance Description:	912450km serviced at 932,450kms next service Submitted By Scott Peters - 30/09/2025 03:19 pm
Upload Files:	Basic Service Checklist.docx

Upload Maintenance Form - 2348M49

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	20/09/2025
Date submitted:	30/09/2025

Plant Details

Owner	S & L Girard Grader Hire
Make	Kenworth
Model	T409 SAR
Type	Prime Mover
VIN / Serial	6F5000000HA459103
Registration	XO22KK
Plant Internal ID	XO22KK
Aquipa Plant ID	2348M49



Maintenance Upload Details	
Maintenance Description:	New Eclip put back on wipers Submitted By Scott Girard - 30/09/2025 10:08 am
Upload Files:	

Upload Maintenance Form - 2348M49

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	18/09/2025
Date submitted:	30/09/2025

Plant Details

Owner	S & L Girard Grader Hire
Make	Kenworth
Model	T409 SAR
Type	Prime Mover
VIN / Serial	6F5000000HA459103
Registration	XO22KK
Plant Internal ID	XO22KK
Aquipa Plant ID	2348M49



Maintenance Upload Details	
Maintenance Description:	Repairs to LHF Blinker Submitted By Scott Girard - 30/09/2025 10:08 am
Upload Files:	

Upload Maintenance Form - 2348M49

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	17/09/2025
Date submitted:	30/09/2025

Plant Details

Owner	S & L Girard Grader Hire
Make	Kenworth
Model	T409 SAR
Type	Prime Mover
VIN / Serial	6F5000000HA459103
Registration	XO22KK
Plant Internal ID	XO22KK
Aquipa Plant ID	2348M49



Maintenance Upload Details	
Maintenance Description:	Repairs to RHF Blinker Submitted By Scott Girard - 30/09/2025 10:07 am
Upload Files:	

Upload Maintenance Form - 2348M49

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	16/09/2025
Date submitted:	30/09/2025

Plant Details

Owner	S & L Girard Grader Hire
Make	Kenworth
Model	T409 SAR
Type	Prime Mover
VIN / Serial	6F5000000HA459103
Registration	XO22KK
Plant Internal ID	XO22KK
Aquipa Plant ID	2348M49



Maintenance Upload Details	
Maintenance Description:	new nut and bolt on mud guard lhf Submitted By Scott Girard - 30/09/2025 10:06 am
Upload Files:	

Upload Maintenance Form - 2348M49

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	26/09/2025
Date submitted:	30/09/2025

Plant Details

Owner	S & L Girard Grader Hire
Make	Kenworth
Model	T409 SAR
Type	Prime Mover
VIN / Serial	6F5000000HA459103
Registration	XO22KK
Plant Internal ID	XO22KK
Aquipa Plant ID	2348M49



Maintenance Upload Details	
Maintenance Description:	New comp 2 x new hoses 1 x receiver dryer working very good Submitted By Scott Girard - 30/09/2025 10:06 am
Upload Files:	

Upload Maintenance Form - 2348M49

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	23/09/2025
Date submitted:	30/09/2025

Plant Details

Owner	S & L Girard Grader Hire
Make	Kenworth
Model	T409 SAR
Type	Prime Mover
VIN / Serial	6F5000000HA459103
Registration	XO22KK
Plant Internal ID	XO22KK
Aquipa Plant ID	2348M49



Maintenance Upload Details	
Maintenance Description:	fixed air con replaced broken break booster Submitted By Scott Girard - 30/09/2025 10:04 am
Upload Files:	

Upload Maintenance Form - 2348M49

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	01/07/2025
Date submitted:	01/07/2025

Plant Details

Owner	S & L Girard Grader Hire
Make	Kenworth
Model	T409 SAR
Type	Prime Mover
VIN / Serial	6F5000000HA459103
Registration	XO22KK
Plant Internal ID	XO22KK
Aquipa Plant ID	2348M49



Maintenance Upload Details	
Maintenance Description:	Checked batteries. Battery test said they were faulty Replaced all 4 Submitted By Scott Peters - 01/07/2025 03:29 pm
Upload Files:	

Upload Maintenance Form - 2348M49

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	25/06/2025
Date submitted:	25/06/2025

Plant Details

Owner	S & L Girard Grader Hire
Make	Kenworth
Model	T409 SAR
Type	Prime Mover
VIN / Serial	6F5000000HA459103
Registration	XO22KK
Plant Internal ID	XO22KK
Aquipa Plant ID	2348M49



Maintenance Upload Details	
Maintenance Description:	Serviced at 891,000kms Next service is at 910,000kms Submitted By Scott Peters - 25/06/2025 03:53 pm
Upload Files:	Basic Service Checklist.docx

Upload Maintenance Form - 2348M49

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	13/06/2025
Date submitted:	13/06/2025

Plant Details

Owner	S & L Girard Grader Hire
Make	Kenworth
Model	T409 SAR
Type	Prime Mover
VIN / Serial	6F5000000HA459103
Registration	XO22KK
Plant Internal ID	XO22KK
Aquipa Plant ID	2348M49



Maintenance Upload Details	
Maintenance Description:	Replaced heater core. As old one was leaking Submitted By Scott Peters - 13/06/2025 09:24 pm
Upload Files:	

Upload Maintenance Form - 2348M49

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	05/06/2025
Date submitted:	05/06/2025

Plant Details

Owner	S & L Girard Grader Hire
Make	Kenworth
Model	T409 SAR
Type	Prime Mover
VIN / Serial	6F5000000HA459103
Registration	XO22KK
Plant Internal ID	XO22KK
Aquipa Plant ID	2348M49



Maintenance Upload Details	
Maintenance Description:	Replaced themostat and gasket Replaced coolant Submitted By Scott Peters - 05/06/2025 09:56 am
Upload Files:	

Upload Maintenance Form - 2348M49

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	19/05/2025
Date submitted:	19/05/2025

Plant Details

Owner	S & L Girard Grader Hire
Make	Kenworth
Model	T409 SAR
Type	Prime Mover
VIN / Serial	6F5000000HA459103
Registration	XO22KK
Plant Internal ID	XO22KK
Aquipa Plant ID	2348M49



Maintenance Upload Details	
Maintenance Description:	Replaced air dyer filter Submitted By Scott Peters - 19/05/2025 09:21 am
Upload Files:	

Upload Maintenance Form - 2348M49

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	31/03/2025
Date submitted:	09/04/2025

Plant Details

Owner	S & L Girard Grader Hire
Make	Kenworth
Model	T409 SAR
Type	Prime Mover
VIN / Serial	6F5000000HA459103
Registration	XO22KK
Plant Internal ID	XO22KK
Aquipa Plant ID	2348M49



Maintenance Upload Details	
Maintenance Description:	replaced tyres Dunlop 9.5R17 SP341 ×2 Submitted By Scott Girard - 09/04/2025 02:35 pm
Upload Files:	

Upload Maintenance Form - 2348M49

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	03/02/2025
Date submitted:	11/02/2025

Plant Details

Owner	S & L Girard Grader Hire
Make	Kenworth
Model	T409 SAR
Type	Prime Mover
VIN / Serial	6F5000000HA459103
Registration	XO22KK
Plant Internal ID	XO22KK
Aquipa Plant ID	2348M49



Details	
Maintenance Description:	Carry out basic service at 871000 kms - Next due 891000 kms. Submitted By Scott Girard - 11/02/2025 01:27 pm
Upload Files:	Basic Service Checklist.docx

Upload Maintenance Form - 2348M49

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	22/01/2025
Date submitted:	22/01/2025

Plant Details

Owner	S & L Girard Grader Hire
Make	Kenworth
Model	T409 SAR
Type	Prime Mover
VIN / Serial	6F5000000HA459103
Registration	XO22KK
Plant Internal ID	XO22KK
Aquipa Plant ID	2348M49



Details	
Maintenance Description:	Serviced at 871,000kms NS at 891,000kms Submitted By Scott Peters - 22/01/2025 03:06 pm
Upload Files:	Basic Service Checklist.docx

Upload Maintenance Form - 2348M49

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	06/11/2024
Date submitted:	06/11/2024

Plant Details

Owner	S & L Girard Grader Hire
Make	Kenworth
Model	T409 SAR
Type	Prime Mover
VIN / Serial	6F5000000HA459103
Registration	XO22KK
Plant Internal ID	XO22KK
Aquipa Plant ID	2348M49



Details	
Maintenance Description:	Travelled to truck. Drain coolant and removed a/c compressor Removed thermostat housing and removed thermostat to keep truck running cooler until new one arrives Submitted By Scott Peters - 06/11/2024 09:12 pm
Upload Files:	

Upload Maintenance Form - 2348M49

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	15/10/2024
Date submitted:	21/10/2024

Plant Details

Owner	S & L Girard Grader Hire
Make	Kenworth
Model	T409 SAR
Type	Prime Mover
VIN / Serial	6F5000000HA459103
Registration	XO22KK
Plant Internal ID	XO22KK
Aquipa Plant ID	2348M49



Details	
Maintenance Description:	Inspect Kenworth for A/C blowing hot air Connect gauges and found system to be low on refrigerant and leaking from high side test port Tighten Schrader valve Charge system with 600g of R134a refrigerant Check for any other leaks in system, all ok Check operation, all ok System now cycling at 5°C Also inspected sleeper A/C system for blowing hot air Found system to be low on refrigerant Charge system with 400g of refrigerant Test operation, all ok Submitted By Scott Girard - 21/10/2024 01:00 pm
Upload Files:	Invoice INV-0116.pdf Submitted By Scott Girard - 21/10/2024 01:00 pm

Upload Maintenance Form - 2348M49

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	27/05/2024
Date submitted:	27/05/2024

Plant Details

Owner	S & L Girard Grader Hire
Make	Kenworth
Model	T409 SAR
Type	Prime Mover
VIN / Serial	6F5000000HA459103
Registration	XO22KK
Plant Internal ID	XO22KK
Aquipa Plant ID	2348M49



Details	
Maintenance Description:	Serviced at 831,293kms Next at 851,000kms Terry Submitted By Scott Peters - 27/05/2024 11:29 am
Upload Files:	Basic Service Checklist.docx

Basic Maintenance Form - 2348M49

Performed by:	Scott Girard (accounts@girardgraderhire.com.au) at S & L Girard Grader Hire
Date performed:	06/03/2024
Date submitted:	13/03/2024

Plant Details

Owner	S & L Girard Grader Hire
Make	Kenworth
Model	T409 SAR
Type	Prime Mover
VIN / Serial	6F5000000HA459103
Registration	XO22KK
Plant Internal ID	XO22KK
Aquipa Plant ID	2348M49



Usage Log

Details	
Maintenance Performed Date:	06/03/2024 Submitted By Scott Girard - 13/03/2024 12:59 pm
Maintenance Description:	KENWORTH, REGO XO22KK. REPAIR, REGAS & TEST A/C SYSTEM. 3.5 125.00 43.75 437.50 Compressor 12V Direct Mount OEX - SB7H15 Sanden Style REC/DRIER (KENWORTH) FITTING NO 8 STR FEMALE STEEL NO8 90 FEMALE ORING FITTING W/PORT SIZE 8 AIR COND HOSE 1.2 14" CABLE TIE NO. 6 O' RING NO. 8 O' RING O'RING NO: 10 UNIVERSAL AIR CONDITIONING GAS 134A SYNTHETIC OIL R134A-R12 DYE 7.5ML Submitted By Scott Girard - 13/03/2024 01:01 pm
Upload Files:	Inv_76030_from_David_Ford_Auto_ElectricalAir_Conditioning_Pty_Limited.pdf Submitted By Scott Girard - 13/03/2024 01:12 pm

Basic Maintenance Form - 2348M49

Performed by:	Scott Peters (scottpeters2013@outlook.com) at S & L Girard Grader Hire
Date performed:	01/02/2024
Date submitted:	01/02/2024

Plant Details

Owner	S & L Girard Grader Hire
Make	Kenworth
Model	T409 SAR
Type	Prime Mover
VIN / Serial	6F5000000HA459103
Registration	XO22KK
Plant Internal ID	XO22KK
Aquipa Plant ID	2348M49



Usage Log	
Odometer Reading (km)	817784 Submitted By Scott Peters - 01/02/2024 12:27 pm

Details	
Maintenance Performed Date:	01/02/2024 Submitted By Scott Peters - 01/02/2024 12:27 pm
Maintenance Description:	Replaced both cab air bags Submitted By Scott Peters - 01/02/2024 12:28 pm
Upload Files:	