

Veh#	Date	W/O#	Description	Notes	Odometer
143	09/29/2026	1372708	Decommission of Bus for AUCTION	carried out bus decommission.	668330
143	09/03/2026	1367494		Completed ATS 16.08.2026	667546
143	09/01/2026	1366295	Service	CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST complate fire safety inspection as per checklist	667142
143	08/31/2026	1365930	PTI Tablet Entered -AC belt pulley loose bolt	tightened bolt	667142
143	08/29/2026	1365848	Service	VEHICLE SAFETY INSPECTION complete	667142
143	08/29/2026	1365848		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS complete	667142
143	08/21/2026	1327129	Service	Bus comingout of service 16/09/2026. Fault will not be rectified.	666671
143	08/13/2026	1361617	PTI Tablet Entered -Body - OTHERleft wiper loose	replaced bn/s wiper arm with second hand unit from 60. took some time to get arm off pivot due to being siezed on	666300
143	08/13/2026	1361617	Consumables		666300
143	08/06/2026	1359737	Drv entered - Elec and Light Exterior Lights2 Back lefthan	double up defect	665803
143	08/06/2026	1359738	PTI Tablet Entered -Elec and Light - Exterior Lights nearsid	fitted second hand light assemblys checked working well	665803
143	08/06/2026	1359737	Consumables		665803
143	08/06/2026	1359738	Consumables		665803
143	07/27/2026	1357143	PTI Tablet Entered -Body - OTHER Flat battery	jump sartrted bus checked charge rate all ok	664952
143	07/27/2026	1357143	Consumables		664952
143	07/14/2026	1354187	Mechanic entered - Wheels and Tyres Wheel Nut Retension p7 p	Completed wheel nut retension position 7&8	664105
143	07/14/2026	1354187	Assisted wheel nut retension		664105
143	07/14/2026	1354187	Consumables		664105
143	07/13/2026	1353915	PTI Tablet Entered -Wheels and Tyres - Flat or Leaking rear	removed tyres p7 and p8 found p8 off tyre off the rim and p7 tyre wall damaged grabbed 2 new recaps cleaned and buffed mating surfaces and cleaned surface on hub oiled wheel nuts fitted wheels on tensioned to spec. with Guy and booked a retension current odo 664446 kms	664105
143	07/13/2026	1353915	TYRE 275/70R22.5 RECAP		664105
143	07/13/2026	1353915	Consumables		664105
143	07/01/2026	1346105	(HISTORIC DEFECT) SWAY BAR WORN		664105
143	07/01/2026	1346105	Consumables		664105
143	06/27/2026	1327129	Mechanic entered - Warning Lights Brakes Linings Warning on	replaced broken wire on nsr middle axel	664105
143	06/27/2026	1327129		Removed the rear wheels as part of the removal of paint from steel rims campaign and found the O/S/R sensor is missing none is fitted. We have sensors on back order so can not fit new one yet till parts come.	664105
143	06/27/2026	1327129		Found while doing ref W/O: 1327128 Paint removal off rims & hubs. Wires for the middle axle sensors were both damaged removed & replaced both sensors with Nathan warning lights still on tho will need to check rears as well.	664105
143	06/27/2026	1327129		Removed pos 9/10 wheels and installed a new brake lining sensor as old one was missing. Fit back wheels tensioned all wheel nuts with George to 650nm. Road tested bus but still brake warning light on have fixed x3 sensors now all others inspected looked fine. Needs further diagnostics.	664105
143	06/27/2026	1327129			664105
143	06/27/2026	1327129		Removed all sensors from underneath and fitted new. Warning light still on dash. Removed all new sensors and plugged old ones. Further investigation required.	664105
143	06/26/2026	1327129	SENSOR WEAR KIT BLOCK TYPE AXLE SET SCANIA 1794440		664105
143	06/11/2026	1346970	PTI Tablet Entered -Wheels and Tyres - Flat or Leaking off s	Checked OSR tyre flat. Pressure only a little down. Checked and adjusted all tyre presssures as they were down by approx 10-15 PSI	663169
143	06/11/2026	1346970	Consumables		663169
143	06/10/2026	1346603	Mechanic entered - Fluid Leaks Rear of bus oil leak	Inspected for oil leak from rear of bus. Some minor oil weep/sweat but no leaks found.	663169
143	06/05/2026	1346022		VEHICLE SAFETY INSPECTION completed	663169
143	06/05/2026	1346022		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS completed	663169
143	06/05/2026	1346103	OSF UPPER TORQUE ROD PLAY	checked over suspection no wear in torque rod	663169
143	06/05/2026	1346104	OIL PRESSURE NOT DISPLAYING ON DASH	checked all ok	663169
143	06/05/2026	1346104	Consumables		663169
143	05/26/2026	1343340	PTI Tablet Entered -Body - Body Damage scuff on front bump		662385
143	05/26/2026	1343340	PTI Tablet Entered -Body - Body Damage nearside rear		662385
143	05/26/2026	1343340	PTI Tablet Entered -Body - Body Damage rear offside corner		662385
143	05/26/2026	1343340	Consumables		662385
143	05/25/2026	1343091	MIRROR R/H 380MM SHORT UES1411D		662385
143	05/25/2026	1343091	PTI Tablet Entered -Body - Mirrors Exterior driver side	replaced drivers side mirror	662385
143	05/25/2026	1343099	PTI Tablet Entered -Body - Body Damage Nearside lower rear	Needs to be entered as accident	662385
143	05/25/2026	1343163	PTI Tablet Entered -unusually dusty inner passenger windows	steam cleaned both front and rear a/c filters and used compressed air to dry both	662385
143	05/25/2026	1343091	Consumables		662385
143	05/25/2026	1343099	Consumables		662385
143	05/25/2026	1343163	Consumables		662385
143	05/21/2026	1342458	Mechanic entered - Gearbox Driveline OTHER trans slipping wh	bring bus into workshop. check trans level. topped up with approx 5lts. test drove. drove ok at time. will consult with driver after tomorrow mornings run.	662210
143	05/13/2026	1340567	Consumables		661700
143	05/13/2026	1340567	Mechanic entered - Wheels and Tyres Wheel Nut Retension p9 p	retensioned position 9/10 to 650nm.	661700
143	05/11/2026	1339849	Consumables		661467
143	05/11/2026	1339849	PTI Tablet Entered -Wheels and Tyres - Flat or Leaking O/S/	Assisting removed p9 found slice on sidewall replaced with new tensioned to spec. and booked a retension with Chris	661467
143	05/11/2026	1339849	PTI Tablet Entered -Wheels and Tyres - Flat or Leaking O/S/	assisted	661467
143	05/11/2026	1339849	PTI Tablet Entered -Wheels and Tyres - Flat or Leaking O/S/	checked and found a slice on p9 replaced tyre with new recep torqued to spec. with Chris and booked a retension 661655 kms	661467
143	05/11/2026	1339849	PTI Tablet Entered -Wheels and Tyres - Flat or Leaking O/S/	Assisting	661467
143	05/11/2026	1339849	PTI Tablet Entered -low air pressure driver side rear	removed p9 found slice on sidewall replaced with new tensioned to spec. and booked a retension with Chris	661467
143	05/11/2026	1339849	PTI Tablet Entered -low air pressure driver side rear	Assisting assisted	661467
143	05/11/2026	1339849	TYRE 275/70R22.5 RECAP		661467
143	05/08/2026	1339391	Consumables		661467
143	05/08/2026	1339391	PTI Tablet Entered -low tyre pressure Rear near side	bus parked on un even ground. pressures all ok	661467
143	05/04/2026	1338180	PTI Tablet Entered -Wheels and Tyres - Flat or Leaking O/S/R	checked tyre pressures of pos 9/10 all ok. bus on un even ground	661130
143	05/04/2026	1338180	Consumables		661130
143	05/04/2026	1338173	PTI Tablet Entered -Fluid Leaks - Rear of bus minor oil spil	checked for oil spill. could not find one.	661130
143	05/01/2026	1332168	GASKET INJ PUMP GEAR COVER L94 K94 1403694	supervisor ordered transfered from dept	661130
143	04/28/2026	1337045	Mechanic entered - Wheels and Tyres Wheel Nut Retension O/S/	Retensioned P9+P10 wheel nuts to 650nm. 660.614 klm with Nikki	660820
143	04/28/2026	1337045	Mechanic entered - Wheels and Tyres Wheel Nut Retension O/S/	assist George	660820
143	04/28/2026	1337045	Consumables		660820
143	04/21/2026	1335482	Consumables		660392
143	04/21/2026	1335482	PTI Tablet Entered -Body - Body Damage panel loose rear lef	SECURED PANEL . BUS WILL NEED TO BE REPAIRED AT ECTB	660392
143	04/15/2026	1334065		TRANSMISSION CHECK AS PER CHECK LIST completed as per check list	660300
143	04/10/2026	1331336	Consumables		660300
143	04/10/2026	1333040	Consumables		660300
143	04/10/2026	1331336	(Historic defect) Rust in door on trailer step - CONFIRMED -	to be repaired at the bodyshop	660300
143	04/10/2026	1333040	PTI Tablet Entered -don't start	STARTED BUS 5 TIMES IN A ROW . COULD NOT FAULT	660300
143	04/09/2026	1332717	Consumables		660300
143	04/09/2026	1332717	(Historic defect) Replace Camp pulley bearing front unit	CHECKED CONDITION AND OPERATION OF AC PULLY BEARING . COULD NOT FAULT . NO MOVEMENT OR NOISE FROM BEARING UNIT .	660300
143	04/08/2026	1332168	GASKET SUMP DSC9 SCANIA L94 S51450 1412666 1382398		660300
143	04/08/2026	1332168	FRONT CRANK SEAL LEAKING - CONFIRMED - LDM - 17-3-26FRONT CR	Drained engine oil. Removed engine spinner housing. Removed sump. Removed old sump gasket and cleaned edges. Washed sump. Fitted new sump gasket and refitted sump. Refitted spinner housing. Added 34L of engine oil. Ran bus checked for leaks all ok.	660300
143	04/07/2026	1332168	FRONT CRANK SEAL LEAKING - CONFIRMED - LDM - 17-3-26	double entry	660300
143	04/07/2026	1332168	(Historic defect) Engine leak from crankcase ventilation ga	ORDERED GASKET WITH BRAD	660300
143	04/07/2026	1332215	Air System OTHER2nd Air tank taking a long time to build	tested air system for time build up all ok. tested for leakdown. could not replicate driver complaint of air dropping when doors openeing or closing	660300
143	04/01/2026	1329494	POWER STEERING RESERVOIR SCANI	Creditor #:PP-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:PP406392 Receiving #:433579 Date :2026-04-02	660171
143	03/31/2026	1331335	(Historic defect) disable fold down seat locker - CONFIRMED	. removed seat strut and looked for new strut could not find new strut reinstalled old strut i waited for supervisor who was in meeting and he found strut but bus was needed and driver took busreplace the next day	660002
143	03/31/2026	1331335	STRUT GAS STAY 200NM 128mm LNG		660002
143	03/31/2026	1331228	FILTER OIL SCANIA VARIOUS MODELS		660002
143	03/31/2026	1331228	FILTER ZF ECOMAT TRANS (E39HD119)(1193281-1)		660002
143	03/31/2026	1331228		CARRY OUT B SERVICE AS PER CHECK LIST completed service	660002
143	03/31/2026	1331228	OIL SAMPLE TEST KIT		660002
143	03/31/2026	1331228	OIL ENGINE ALL FLEET PLUS E900 15W-40		660002
143	03/31/2026	1331228	OIL ATF STEERING DEX-3 VALVOLINE		660002

143	03/31/2026	1331228	PAPER SPINNER FILTER OIL INSERT SCANIA VARIOUS MODELS		660002
143	03/31/2026	1331228	FILTER FUEL SCANIA VARIOUS MODELS H17WK04		660002
143	03/31/2026	1331228	O-RING LARGE UPPER SPINNER FILTER SCANIA		660002
143	03/31/2026	1331228	O-RING LARGE UPPER SPINNER FILTER SCANIA		660002
143	03/31/2026	1331228	Consumables		660002
143	03/31/2026	1331228	Consumables		660002
143	03/31/2026	1331228	Consumables		660002
143	03/27/2026	1329491		replaced torn seat base	659833
143	03/27/2026	1329491	SEAT CUSH SINGLE CEN CVR CI		659833
143	03/25/2026	1329494	PTI Tablet Entered -power steering oil low and leaking	replace p/steering reservoir at the back of the vehicle top up fluid test found no leak	659048
143	03/24/2026	1329758	Mechanic entered - Wheels and Tyres Wheel Nut Retension POS	retentioned position 9/10 to 650Nm with 40210	659048
143	03/24/2026	1329758	Consumables		659048
143	03/24/2026	1329579	Mechanic entered - Elec and Light Next Stop Button No Bell f	checked the system this is the school bus not required this function.	659048
143	03/23/2026	1329494	PTI Tablet Entered -power steering oil leaks	duplicate	659048
143	03/23/2026	1329494	(Historic defect) Power steer resivion leak	duplicate	659048
143	03/23/2026	1329493	Mechanic entered - Body Passenger Seat Torn End Cap missing	replaced end cap job complete	659048
143	03/23/2026	1329491	Mechanic entered - Body Passenger Seat Torn x1		659048
143	03/22/2026	1327149		FIRE EXTINGUISHER TEST & TAG completed by ATS 15.02.26	659048
143	03/19/2026	1328360	Mechanic entered - Elec and Light Interior Lights x3 Saloon	checked the system repaired the connections changed the fluoro lights.	659398
143	03/18/2026	1328222	Mechanic entered - Elec and Light Exterior Lights Rear light	Removed all the rear lenses for all lights and cleaned out dust & dirt inside. Fit back all lenses.	659398
143	03/18/2026	1328213	Mechanic entered - Body Rear_Door Operation Faulty Middle d	CHECKED DOOR FOR SECURITY . CHECKED OPERATION . ALL OK	659398
143	03/17/2026	1327897	Mechanic entered - Wheels and Tyres Wheel Nut Retension ALL	CARRIED OUT RETORQUE AS REQUIRED	659048
143	03/17/2026	1327897	Mechanic entered - Wheels and Tyres Wheel Nut Retension ALL	Assisting	659048
143	03/17/2026	1327897	Consumables		659048
143	03/17/2026	1327907	Mechanic entered - Fluid Leaks Rear of bus Sump gasket leak	OIL LEAK IS COMING FROM FRONT CRANK SEAL . SEAL WILL BE REPLACED ON A DIFFERENT WORK ORDER	659048
143	03/17/2026	1327895	Mechanic entered - Body Rear_Door Operation Faulty Rear doo	CHECKED OPERATION OF ALL SENSITIVE EDGES ON ALL 3 DOORS WITH HARLEY . COULD NOT FAULT . ALL WORKING	659048
143	03/16/2026	1327529	Mechanic entered - Wheels and Tyres Worn O/S/R tyre pos 10 w	Removed & replaced tyre pos 10 sanded paint off rims new & old. Tensioned all wheel nuts with George to 650nm.	659048
143	03/16/2026	1327529	TYRE 275/70R22.5 RECAP		659048
143	03/16/2026	1327637	PTI Tablet Entered -Wheels and Tyres - Flat or Leaking	Ref W/O: 1327529 - Tyre pos 10 replaced job doubled up.	659048
143	03/16/2026	1327529	Consumables		659048
143	03/16/2026	1327637	Consumables		659048
143	03/16/2026	1327435	Mechanic entered - Engine Other Steam clean engine bay	Gave the engine bay a good clean not pit at Rosebud so used creeper to wash what I can underneath	659048
143	03/16/2026	1327397	BUZZER REVERSING 24V 102DB NR72602		659048
143	03/16/2026	1327398	LAMP LED NUMBER PLATE & EXIT LIGHT 250120 27771		659048
143	03/16/2026	1327397	Mechanic entered - Elec and Light Reverse Buzzer N/W	replaced faulty reverse buzzer. tested all ok	659048
143	03/16/2026	1327398	Mechanic entered - Elec and Light Exterior Lights x1 Number	replace corroded number plate light with new led. tested all ok	659048
143	03/16/2026	1327128		Backed the rear of this articulated bus on the pit and removed all rear wheels and sanded off all paint on rims & hubs fit back wheels & tensioned all wheel nuts to 650nm with George. Flipped the bus around and removed front wheels sanded off all paint from hubs & rims fit back wheels & tensioned all wheel nuts with George.	659048
143	03/13/2026	1325740		Removed middle axle wheels as part of paint removal campaign ref W/O: 1327128 inspected middle brakes pads & rotors good thickness.	659048
143	03/13/2026	1327186	PTI Tablet Entered -Wheels and Tyres - Flat or Leaking tyre	checked all pressure found number 8 tyre at 40 psi pumped up to correct psi	659048
143	03/13/2026	1327186	Consumables		659048
143	03/13/2026	1327128	PERFORM CAMPAIGN 01/26 ALL WHEELS NEED TO BE REMOVED ALL RI	Removed middle axle wheels and sanded off & cleaned rims / hubs free of paint. Tensioned all wheel nuts with Darren to 650nm. Carry over for the next wheels.	659048
143	03/11/2026	1325740		Reversed the back of the bus on the pit and completed the back end of this bus for the safety due to the design of the middle axle the wheels will need to be removed to inspect the brakes this will be last check to do.	658645
143	03/11/2026	1326589	Mechanic entered - Engine Noisy or Rattling Alternator brake	Removed the broken bracket which had snapped in two cleaned up the parts & Darren welded the bracket back together. Fit back alternator bracket alternators now properly secured.	658645
143	03/11/2026	1326345	Drv entered - Elec and Light HornHorn is faulty and doesn't	checked the system adjust the horn and checked the steering wheel connections all good now	658645
143	03/11/2026	1326328		CARRY OUT CCTV - A SERVICE AS PER CHECK LIST complete CCTV A service as per checklist	658645
143	03/06/2026	1325740		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Tensioned all wheel nuts with Darren to 650nm.	658645
143	03/06/2026	1325740		VEHICLE SAFETY INSPECTION Started Safety Inspection and followed thru checklist not yet completed only checked inside the bus / outside and underneath front & middle axles. Need to reverse the rear of this Articulated bus on the pit to finish the Safety.	658645
143	03/06/2026	1325501	Mechanic entered - Elec and Light Exterior Lights number pla	repair number plate light wiring	658645
143	02/09/2026	1319257	Mechanic entered - Elec and Light Flat Batteries	jump start bus due to flat battery's. check charge rate. charging at 27.1V.	657100
143	02/09/2026	1319257	Consumables		657100
143	02/02/2026	1317818	Drv entered - Air System Air_Leak Front	check bus for air leaks. found worn air line in chassis near r/f air bag. replaced air line tested all ok	656842
143	01/29/2026	1317036	PTI Tablet Entered -Elec and Light - Exterior Lights N/S/R u	replaced globe and checked ok	656579
143	01/28/2026	1316886	Mechanic entered - Fluid Leaks Rear of bus wash engine oil l	fitted 2 clamps after returned to depo from break down mechanic and coolant was topped up by break down mechanic started and rechecked ok	656579
143	01/28/2026	1316800	PTI Tablet Entered -Elec and Light - Exterior LightsO/S rear	checked the system repaired the light connections changed the globe	656579
143	01/22/2026	1315774		CARRY OUT A/C - B SERVICE AS PER CHECK LIST - completed by coldrive	656489
143	01/22/2026	1315774	DIRECT PURCHASE - MECHANICAL G	Creditor #:PP-COLO04 COLD DRIVE PTY LTD P/O #:PP403270 Receiving #:428886 Date :2026-01-30 a/c B service and repairs	656579
143	01/22/2026	1315774		CARRY OUT A/C - A SERVICE AS PER CHECK LIST - Assisting	656489
143	12/11/2025	1308718		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	655749
143	12/11/2025	1308718		VEHICLE SAFETY INSPECTION completed as per check list	655749
143	12/08/2025	1308041	PTI Tablet Entered -Elec and Light - Exterior Lights N/S/R u	checked operation of light no faults found	655749
143	12/08/2025	1308041	Consumables		655749
143	11/19/2025	1303844	Drv entered - Elec and Light HornHorn not working	bring bus to workshop. horn not working. check for power. no power checked fuses found blown fuse. replaced fuse did not work due to short in horn circuit. trace circuit found horn to be the problem. no horn in stock drove to seaford to get horn returned fitted horn. tested all ok	654421
143	11/19/2025	1303844	HORN 24V	Creditor #:PP-MUL001 MULTISPARES LTD P/O #:PP399398 Receiving #:424421 Date :2025-11-20	654695
143	11/19/2025	1303844	Consumables		654695
143	11/14/2025	1303059	A/C Heating (None) evaporator fans replacement	Assisting complete	654421
143	11/14/2025	1303059	A/C Heating (None) evaporator fans replacement	2 evaporating fan motor been replaced by Dave Cold drive	654421
143	11/14/2025	1301244	DIRECT PURCHASE - AIR CONDITIO	Creditor #:PP-COLO04 COLD DRIVE PTY LTD P/O #:PP399120 Receiving #:424298 Date :2025-11-19 143 a/c fan replacement	654421
143	11/14/2025	1303059		CARRY OUT A/C - A SERVICE AS PER CHECK LIST A service been completed by Dave	654421
143	11/06/2025	1301244	Drv entered - A/C Heating Warning Light OnError 2 still co	evaporator motor need replaced	653908
143	11/06/2025	1301244	Drv entered - A/C Heating Warning Light OnError 2 code is	check and found drive side evaporator motor not working (need replaced)	653908
143	11/06/2025	1301244	Drv entered - A/C Heating Warning Light OnError 2 code is	Assisting	653908
143	11/03/2025	1300556	Drv entered - Elec and Light Indicators Not Workingside ind	found globe about to go off replaced and rechecked ok	653565
143	11/03/2025	1300556	Consumables		653565
143	10/31/2025	1300345	PTI Tablet Entered -Elec and Light - Exterior Lights rear nu	remove assembly straiten. fit new globes and clean lens. re fit and test all ok	653565
143	10/31/2025	1300345	Consumables		653565
143	10/26/2025	1297984	Apply print film	Completed 19.10.25 by GlassProtech	652708
143	10/21/2025	1297984	Anti-graffiti film replacement	Creditor #:PP-GLA010 GLASSPROTECH MELBOURNE P/O #:PP397460 Receiving #:422047 Date :2025-10-22	653007
143	10/21/2025	1297872	Drv entered - Body Passenger Seat TornBack of one of the re	re fit passenger seat back	652708
143	09/18/2025	1290931	DIRECT PURCHASE - BUS INSPECTI	Creditor #:PP-ROASAF ROAD SAFETY INSPECTIONS P/O #:PP395448 Receiving #:420033 Date :2025-09-18 143 RSI complete	651846
143	09/18/2025	1291194	Mechanic entered - Wheels and Tyres Wheel Nut Retension all	retensioned all wheels on rear axle to spec.	651581
143	09/18/2025	1291194	Consumables		651581
143	09/17/2025	1290931		VEHICLE SAFETY INSPECTION	651581
143	09/17/2025	1290931		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	651581
143	09/17/2025	1290931		ANNUAL SAFETY INSPECTION SERIAL #RSI 073659__ WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25	651581
143	09/17/2025	1290931		Assisting	651581
143	09/17/2025	1290894	REFLECTOR AMBER HELLA 94 X 44MM		651581
143	09/17/2025	1290983	Mechanic entered - Elec and Light Exterior Lights n/s headli	replaced headlight and checked ok	651581
143	09/17/2025	1290894	Mechanic entered - Elec and Light Exterior Lights n/s middle	fitted ok	651581
143	09/17/2025	1290982	Mechanic entered - Body Other n/s first window emergency exci	fitted new sticker emergency exit stone glass	651581
143	09/17/2025	1290982	Consumables		651581
143	09/16/2025	1290689	Brakes (None) replace rear brake pad	replaced rear brake pads adjusted tensioned wheel nuts and booked a retension	651581
143	09/16/2025	1290689	BRAKE PAD SET FRT/RR SCANIA K310UB & K320 2271805		651581
143	09/16/2025	1290751		CARRY OUT COMPLETE VEHICLE UNDER CARRIAGE WASH completed undercarriage wash	651581

143	09/02/2025	1287640		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST complete fire safety inspection as per checklist	650686
143	08/31/2025	1287154		CARRY OUT FIRE EXTINGUISHER TEST & TAG replacement extinguisher completed from spare stock	650686
143	08/31/2025	1287154		Assisting	650686
143	08/28/2025	1286410	Mechanic entered - Elec and Light Interior Lights emergency	repair emergency exit lights as required	650686
143	08/28/2025	1286410	Consumables		650686
143	08/28/2025	1286410	Mechanic entered - Body Other drivers side blind faulty	replace drivers side blind with second hand blind from bus 63	650686
143	08/22/2025	1284587	Drv entered - A/C Heating Warning Light OnRear air-conditi	double up defect	650171
143	08/22/2025	1284588	Drv entered - A/C Heating Warning Light Onerror code on re	double up defect	650171
143	08/21/2025	1284304		VEHICLE SAFETY INSPECTION complete	650171
143	08/21/2025	1284304		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	650171
143	08/21/2025	1284305		PRE ANNUAL SAFETY INSPECTION CHECK complete	650171
143	08/21/2025	1284305		CARRY OUT CCTV - B SERVICE AS PER CHECK LIST complete	650171
143	08/21/2025	1284353	Drv entered - A/C Heating Warning Light OnError 2 still sh	double up defect	650171
143	08/21/2025	1284353	Drv entered - A/C Heating Warning Light OnError 2 still sh	repair completed by Jimmy From Colddrive. o/s rear unit condensor fan fault	650171
143	08/07/2025	1284353	Repair heating	Creditor #:PP-COL004 COLD DRIVE PTY LTD P/O #:PP393348 Receiving #:418233 Date :2025-08-26 BUS 143	650427
143	08/05/2025	1280677	Drv entered - Driver Tablet Not Charging	checked the system the tablet was 21% charged and coontinue charged.	649219
143	08/05/2025	1280677	Consumables		649219
143	08/03/2025	1280162	Drv entered - Driver Tablet Not Charging		648761
143	08/03/2025	1280162	Consumables	remove tablet from bus boost charge to 100% and will monitor on monday	648761
143	07/31/2025	1279597	Drv entered - Air System Air_Leak Interiorairleaking from p	replaced park brake valve defect on w/o1267144	648761
143	06/13/2025	1267114	Drv entered - Air System Air_Leak FrontAir leak coming fro	replace hand brake valve starting to leak	647109
143	06/10/2025	1269334	Elec and Light Exterior Lights n/s/r side marker broken	checked the system change the side marker light	646771
143	06/10/2025	1269334	LAMP LED SIDE RED/AMBER PERE1 52-98002 85760BL		646771
143	06/10/2025	1269334	Consumables		646771
143	06/07/2025	1269203	Wont start	master switch left on < jumper pack wouldnt start it got the workshop van and started it left running ti charge batteries	646771
143	06/07/2025	1269203	Consumables		646771
143	05/30/2025	1267114	VALVE PARK BRAKE SCANIA SR3 4		646261
143	05/29/2025	1267145		Creditor #:PP-MUL001 MULTISPARES LTD P/O #:PP388349 Receiving #:411854 Date :2025-05-30	645923
143	05/29/2025	1267145		VEHICLE SAFETY INSPECTION completed	645923
143	05/29/2025	1267145		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS completed	645923
143	05/29/2025	1267113	Mechanic entered - Fluid Leaks Rear of bus coolant leak nea	Put bendy bus on pit found trans cooler hose clamp loose tightened and checked hoses topped up coolant	645923
143	05/27/2025	1266768	Drv entered - Elec and Light Exterior LightsTop drivers si	replace o/s/r top tail light globe	645923
143	05/27/2025	1266768	Drv entered - Elec and Light Exterior LightsTop drivers si	replace n/s/f top parker light globe	645923
143	05/27/2025	1266768	Consumables		645923
143	04/20/2025	1259458	Apply print film	Audit 1160 Job stage 1 completed 15.04.25	644049
143	04/15/2025	1259458	Apply print film - AUDIT 1160	Creditor #:PP-GLA010 GLASSPROTECH MELBOURNE P/O #:PP385819 Receiving #:409248 Date :2025-04-23	644049
143	03/28/2025	1248534	BELT A/C TWIN COMP SCANIA L94UAB 8PK2020		643580
143	03/28/2025	1248534	BELT V COGGED TRI-POWER 17x1145mm		643580
143	03/28/2025	1248534	BELT V COGGED TRI-POWER 17x1675mm		643580
143	03/11/2025	1249418	DIPSTICK ENGINE OIL 753MM SCAN	Creditor #:PP-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:PP381886 Receiving #:406266 Date :2025-03-11	642556
143	03/11/2025	1251270		CARRY OUT CCTV - A SERVICE AS PER CHECK LIST complete CCTV A service as per checklist	642081
143	03/08/2025	1249695		Completed by ATS 16.02.25	642081
143	03/05/2025	1250182		VEHICLE SAFETY INSPECTION Carried out safety inspection + tensioned wheelnuts to spec.	642081
143	03/05/2025	1250182		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Carried out safety inspection + tensioned wheelnuts to spec.	642081
143	03/03/2025	1249418	needs dipstick	fit new dipstick p/n 1515996	642081
143	02/27/2025	1248534	Fault#:39535 - Ops Entered - Fault - Breakdown Oil Leak -	fit new belt P/N 8pk2592 Bx63Bx420641201 fit new bolt on lower a/c compressor support was missing and loosed	642081
143	02/27/2025	1248534	BELT ALT W/PUMP CRANK SCANIA L94UAB 1803334 1389044		642081
143	02/11/2025	1244072	Drv entered - Engine Low PowerEngine warning light came on	check found bus go om limp modepressurise turn table hyd piston test found ok	641060
143	02/11/2025	1244097	Drv entered - Brakes Warning Light OnOrange warming light	check all brake pad all withing spec need to work on wear sensor fault	641060
143	01/29/2025	1241333	PTI Tablet Entered -Elec and Light - Exterior Lights. N/S/R	checked the system repaire the connection change the globe	640460
143	01/29/2025	1241333	Consumables		640460
143	01/24/2025	1239616	FILTER ZF ECOMAT GEARBOX 4139-298-038 3098081	mech booked old a/m# should be gen#	640049
143	01/24/2025	1239616	FILTER ZF ECOMAT TRANS (E39HD119)(1193281-1)	correct # used booked	640049
143	01/24/2025	1239616	Consumables		640049
143	01/24/2025	1239616	Consumables		640049
143	01/20/2025	1208004		Cleaned around suspected leak going to monitor for leaking.	640049
143	01/20/2025	1208004	Engine front main seal leaking	defect under mntoring	640049
143	01/20/2025	1239616	PAPER SPINNER FILTER OIL INSERT SCANIA VARIOUS MODELS		640049
143	01/20/2025	1239616	FILTER FUEL SCANIA VARIOUS MODELS H17WK04		640049
143	01/20/2025	1239616	FILTER ZF ECOMAT GEARBOX 4139-298-038 3098081		640049
143	01/20/2025	1239616		CARRY OUT B SERVICE AS PER CHECK LIST Carried out B service.	640049
143	01/20/2025	1239616			640049
143	01/20/2025	1239616	OIL ENGINE ALL FLEET PLUS E900 15W-40		640049
143	01/20/2025	1239616	OIL ATF STEERING DEX-3 VALVOLINE		640049
143	01/20/2025	1239616	OIL SAMPLE TEST KIT		640049
143	01/20/2025	1239616	FILTER OIL SCANIA VARIOUS MODELS		640049
143	01/20/2025	1239616	O-RING LOWER SPINNER FILTER SCANIA L94 K124		640049
143	01/20/2025	1239616	O-RING LARGE UPPER SPINNER FILTER SCANIA		640049
143	12/10/2024	1232520		VEHICLE SAFETY INSPECTION Carried out safety inspetion as per checklist.	640049
143	12/10/2024	1232520		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Tensioned wheelnuts to spec	640049
143	12/10/2024	1232581	Mechanic entered - Suspension Noisy Middle axle swaybar bush	Fit new bushes to mid axle.	640049
143	12/10/2024	1232581	BUSH SWAY BAR MID AXLE D-BUSH SCANIA ARTIC K360 489648		640049
143	12/10/2024	1232622	Mechanic entered - Body Passenger Seat Torn Multiple seat ba		640049
143	12/10/2024	1232622	Consumables	Tightened loose seat bases.	640049
143	12/01/2024	1230165	DIRECT PURCHASE - AIR CONDITIO	Creditor #:PP-COL004 COLD DRIVE PTY LTD P/O #:PP377169 Receiving #:399768 Date :2024-12-05 143 a/c A service	640049
143	11/28/2024	1230165		CARRY OUT A/C - A SERVICE AS PER CHECK LIST a/c service been completed by Jimmy cold drive	639556
143	11/28/2024	1230165		Assisting	639556
143	11/22/2024	1228924	Breakdown Not Starting	check found battery faulty	639292
143	11/22/2024	1228924		Checked operation of rear hatch switch all ok. Checked all starte motor connections were secure checked starter relay + fuses. Tested batteries both failed at 41% 51%. Fit new set of batteries + tested for fault could not fault during time of test.	639292
143	11/22/2024	1228924	BATTERY 1350CCA POS ON RHS EMFN150R		639292
143	11/19/2024	1228089	Drv entered - Body Windows Front *** need to go to East coas	Retrieved the bus and repaired the front driver's window re-sealed window frame from out side repaired damaged floorings removed section of the floor cleaned thoroughly and cut vinyl to patch up bonded floorings and filled the gaps job completed. 18/11/2024	638858
143	11/19/2024	1228090	Drv entered - Body Body Damage *** need to go to East coast	Retrieved the bus and repaired the front driver's window re-sealed window frame from out side repaired damaged floorings removed section of the floor cleaned thoroughly and cut vinyl to patch up bonded floorings and filled the gaps job completed. 18/11/2024	638858
143	11/19/2024	1228089	Consumables		638858
143	11/19/2024	1228090	Consumables		638858
143	11/08/2024	1226049	Drv entered - Air System Air_Leak Interiorair hose to drive	repaired air line.	638288
143	10/30/2024	1224183	Mechanic entered - Wheels and Tyres Wheel Nut Retension posi	Retensioned wheelnuts.	637804
143	10/30/2024	1224183	Consumables		637804
143	10/29/2024	1223871	Drv entered - Wheels and Tyres Flat or Leakingtyre blew out	replaced position 5 tyre and tentioned to 650Nm	637804
143	10/29/2024	1223871	TYRE 275/70R22.5 NEW		637804
143	10/29/2024	1223871	Consumables		637804
143	10/14/2024	1210131	Consumables		637057
143	10/14/2024	1210131	MIRROR R/H 380MM SHORT UES1411D	advised mech used & not booked	637057
143	10/14/2024	1220786		CARRY OUT FIRE EXTINGUISHER TEST & TAG check found ok	637057
143	10/04/2024	1218736	PERFORM CAMPAIGN 11/24 CHECK & ENSURE ALL BUS DRIVE AXLE WHE	everything already fitted	636553
143	09/17/2024	1214762	DIRECT PURCHASE - BUS INSPCTI	Creditor #:PP-ROASAF ROAD SAFETY INSPECTIONS P/O #:PP372500 Receiving #:394846 Date :2024-09-19 143 RSI	636432

143	09/16/2024	1214762	VEHICLE SAFETY INSPECTION	636106
143	09/16/2024	1214762	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	636106
143	09/16/2024	1214762	ANNUAL SAFETY INSPECTION SERIAL # RSI 061742 WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25	636106
143	09/16/2024	1214762	PRE ANNUAL SAFETY INSPECTION CHECK carried pre safety inspection as per chec list	636106
143	09/16/2024	1214762	CARRY OUT CCTV - B SERVICE AS PER CHECK LIST carried out cctv B service	636106
143	09/13/2024	1214388	CARRY OUT COMPLETE VEHICLE UNDER CARRIAGE WASH wash completed	635770
143	09/12/2024	1214140	VEHICLE SAFETY INSPECTION Carried out safety insption.	635770
143	09/12/2024	1214140	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Tensioned all wheelnuts to spec.	635770
143	09/11/2024	1213931	CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST complate fire safety inspection as per checklist	635770
143	09/04/2024	1212376	replaced dash guage cluster (not speedo) test drove all ok at time of test.	635035
143	08/29/2024	1210733	incorrect unit entered	635035
143	08/29/2024	1210735	incorrect unit entered	635035
143	08/27/2024	1210131	Consumables	634351
143	08/27/2024	1210131	Tightened and adjusted both mirrors.	634351
143	08/23/2024	1209334	Consumables	634351
143	08/23/2024	1209501	Consumables	634351
143	08/23/2024	1209334	Workshop Tablet Entered -left mirror swing around all the gi	634351
143	08/23/2024	1209501	PTI Tablet Entered -Body - Mirrors Exterior left left-hand	634351
143	08/23/2024	1209501	Workshop Tablet Entered -Body - Mirrors Exterior left side	634351
143	08/22/2024	1209062	Consumables	634351
143	08/22/2024	1209065	Consumables	634351
143	08/22/2024	1209062	Workshop Tablet Entered -Body - Mirrors Exterior	634351
143	08/22/2024	1209065	Workshop Tablet Entered -left mirror very loose	634351
143	08/21/2024	1208868	could not fault defect	634351
143	08/21/2024	1208868	could not fault defect	634351
143	08/21/2024	1208868	PRE ANNUAL SAFETY INSPECTION CHECK Carried out pre annual as per checklist.	634351
143	08/21/2024	1208868	CARRY OUT CCTV - B SERVICE AS PER CHECK LIST	634351
143	08/21/2024	1208968	Consumables	634351
143	08/21/2024	1208968	Strapped up curtain away from ground.	634351
143	08/19/2024	1208004	Creditor #:PP-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:PP370679 Receiving #:392660 Date :2024-08-20	634351
143	08/10/2024	1195831	job completed	633670
143	08/09/2024	1206590	Consumables	633670
143	08/09/2024	1206590	Workshop Tablet Entered -Body - Mirrors Exterior left mirror	633670
143	08/08/2024	1206023	Consumables	633670
143	08/08/2024	1206023	Mechanic entered - Wheels and Tyres Wheel Nut Retension 5/6	633670
143	08/08/2024	1206255	Drv entered - Engine Low PowerIntermittent power loss	633670
143	08/07/2024	1205775	Mechanic entered - Wheels and Tyres Wheel Nut Retension 3/4	633670
143	08/07/2024	1205775	Consumables	633670
143	08/06/2024	1195831	Fit near side centre axle air bags + checked for leaks. Fit off side bags.	633670
143	08/02/2024	1205017	Consumables	633670
143	08/02/2024	1205017	Workshop Tablet Entered -Body - Mirrors Exterior	633670
143	08/01/2024	1204638	Mechanic entered - Wheels and Tyres Wheel Nut Retension posi	633451
143	08/01/2024	1204638	Consumables	633451
143	07/31/2024	1204385	Mechanic entered - Brakes Other centre axle brakes starting	633451
143	07/31/2024	1204385	BRAKE PAD SET FRT/RR SCANIA K310UB & K320 2271805	633451
143	07/29/2024	1203865	Mechanic entered - Wipers and Washers Wipers Loose	633119
143	07/18/2024	1201621	Workshop Tablet Entered -Body - Rear_Door Operation Faulty	632504
143	07/18/2024	1201622	Workshop Tablet Entered -Body - Rear_Door Operation Faulty	632504
143	07/18/2024	1201621	Consumables	632504
143	07/18/2024	1201622	Consumables	632504
143	07/17/2024	1201530	Body Windows Front chip	632504
143	07/17/2024	1201530	DIRECT PURCHASE - GLASS	632749
143	07/17/2024	1201530	Consumables	632749
143	07/13/2024	1196155	Driver Tablet Entered -Engine \Low PowerKEEPS DROPPING out	632504
143	07/10/2024	1196155	assisting	632504
143	07/05/2024	1198471	cleaned potentiometer plugs. lubed linkages tested was all ok at time of test.	632504
143	07/02/2024	1195831	correct sticker fitted	632504
143	07/02/2024	1195831	AIRBAG DRIVE/TAG AXLE (1X 0812	632504
143	07/01/2024	1195831	AIRBAG DRIVE/TAG AXLE (1X 0812	632504
143	06/27/2024	1196922	Drv entered - Body Front_Door Operation Faulty	632178
143	06/25/2024	1196455	Mechanic entered - Wheels and Tyres Wheel Nut Retension posi	632178
143	06/25/2024	1196455	Consumables	632178
143	06/24/2024	1196156	Mechanic entered - Wheels and Tyres Other position 1 rim ben	631883
143	06/24/2024	1196156	TYRE 275/70R22.5 NEW	631883
143	06/24/2024	1196156	Consumables	631883
143	06/24/2024	1196154	Mechanic entered - Suspension Other front axle air bags crac	631883
143	06/24/2024	1196154	AIRBAG FRONT SCANIA K310UB E5 40Y2248 40Y2223	631883
143	06/19/2024	1195294	VEHICLE SAFETY INSPECTION carried out safety inspection as per check lis	631801
143	06/19/2024	1195294	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS tentioned wheel nuts to 650Nm	631801
143	06/19/2024	1195357	replaced leaking 4 way protection valve tested all ok	631801
143	06/19/2024	1195357	VALVE CIRCUIT PROTECTION 4WAY SCANIA 1431049 1381883	631801
143	06/12/2024	1193942	Drv entered - Elec and Light Exterior Lights	631448
143	06/12/2024	1193942	Consumables	631448
143	06/04/2024	1192472	TRANSMISSION CHECK AS PER CHECK LIST carried out trans check as per check list	631037
143	05/24/2024	1190348	fit new flasher can test found good	630420
143	05/24/2024	1190348	RELAY FLASHER SCANIA L94 UAB1401789 4DN-007-431-021	630420
143	05/24/2024	1190348	Consumables	630420
143	05/17/2024	1189002	Driver Tablet Entered -Elec and Light - Exterior LightsRear	630074
143	05/17/2024	1189002	Consumables	630074
143	05/17/2024	1189001	Driver Tablet Entered -Air System - Warning Light Onwhen ra	630074
143	05/08/2024	1187047	test drove bus raised / lowered all ok. no warning lights present at time of test.	629346
143	05/08/2024	1187047	check indecator and replaced faulty flasher unit indecatores ok.	629346
143	05/08/2024	1187047	RELAY FLASHER SCANIA L94 UAB 40V2402	629346
143	05/08/2024	1187048	PTI Tablet Entered -Elec and Light - Indicators Not Working	629346
143	05/08/2024	1187047	Consumables	629346
143	05/08/2024	1187103	Driver Tablet Entered -Air System - Air_Leak Front	629346
143	04/24/2024	1184387	Mechanic entered - Wheels and Tyres Wheel Nut Retension retn	628332
143	04/24/2024	1184387	Consumables	628332
143	04/23/2024	1184166	Driver Tablet Entered -Wheels and Tyres - Flat or Leakingt	628148
143	04/23/2024	1184166	TYRE 275/70R22.5 RECAP	628148
143	04/23/2024	1184166	Consumables	628148
143	04/23/2024	1184058	For swap smart track from bus 143 to bus 1628	628148
143	04/23/2024	1184058	Consumables	628148
143	04/22/2024	1183879	PTI Tablet Entered -Fluid Leaks - Rear of busfuel cap missi	628148
143	04/15/2024	1182192	Checked fuel cap Coolant cap P/S oil cap and Engine oil filler point cap Every thing their.	627760
143	03/27/2024	1178979	CARRY OUT CCTV - A SERVICE AS PER CHECK LIST Complete CCTV A Service as per check list.	627727
143	03/27/2024	1178979	VEHICLE SAFETY INSPECTION Carried out safety inspection as per check list tension all wheel nuts with Jimmy	627727
143	03/27/2024	1178979	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	627727

143	03/27/2024	1178979		completed safety inspection as per check list and tensioned all wheel nuts with indika and fitted missing seat end cap	627727
143	03/27/2024	1178979	PULLEY IDLER (SMOOTH STL) SCAN	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G361901 Receiving #:382582 Date :2024-03-27	627727
143	03/27/2024	1178979	TENSIONER BELT SCANIA SR4 L94 K230 1859654 1503113 2197002		627727
143	03/27/2024	1178979	CAP CENTRA SEAT END MCCONNELL		627727
143	03/27/2024	1178979	BELT ALT W/PUMP CRANK SCANIA L	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G361901 Receiving #:382582 Date :2024-03-27	627727
143	03/27/2024	1179070	Mechanic entered - Engine Other alternator serpentine belt d	removed and replaced belt. PARTS BOOKED TO SAFETY	627727
143	03/27/2024	1179071	Mechanic entered - Engine Other alternator idler and tension	removed and replaced with new assisted by indika	627727
143	03/27/2024	1179069	Consumables		627727
143	03/27/2024	1179069	Mechanic entered - Elec and Light Other o/s/f saloon light o	no power coming to lights due to wires being broke reconnected wiring and repaired broken bracket tested all good	627727
143	03/19/2024	1168507	Driver Tablet Entered -Jack knife light comes on while drivi	Run sd2 check for fault codes. found brake system and atcuated unit not connecting need to check wire harnes c/o bus serviceble	626765
143	03/19/2024	1168507		check wire harnes middel of bus. removed articulate flore hatch clean unit. c/o	626620
143	03/19/2024	1168507		greased turning table and fixed all removal covers PTI done and moped.	626620
143	03/19/2024	1168507	Driver Tablet Entered -Engine - Warning Lightlow power	road tested can't see jak knife light check fault codes all ok.	626620
143	03/19/2024	1168507	Drv entered - Engine Low Power		626620
143	03/19/2024	1168507	Driver Tablet Entered -Brakes - Foot_Brakes Pullingretarde	check retarder solonide secure wire conector road tested retader ok.	626620
143	03/07/2024	1168507		repressure turn table hydraulic system road tested check jack nife warning not appere c/o	626620
143	02/29/2024	1173509	PERFORM CAMPAIGN 01/24 REMOVAL OF OLD NO SMOKING DECALS	completed	626620
143	02/28/2024	1173226		COMPLETED BY ATS	626620
143	01/31/2024	1166475	Drv entered - Engine Low Power	Road tested bus seems to be slow but this bus is underpowered from factory driver runs with both A/C running on full and all the lights on. L94UA are not quick but the bus had no problem getting to 80km and staying there. Checked boost pipes intercooler air filter and transmission oil all fine.	625419
143	01/31/2024	1166475	Drv entered - Engine Warning Light	Same Job made twice.	625419
143	01/29/2024	1165892	Mechanic entered - Elec and Light AM-FM Radio not working	checked and fixed the connection of readio	625287
143	01/29/2024	1165892	Consumables		625287
143	01/29/2024	1165893	Mechanic entered - Body Other o/s front roof hatch panel out	fixed and secure the panel frame secure the panel back to bus	625287
143	01/29/2024	1165893	Consumables		625287
143	01/16/2024	1156134			625287
143	01/16/2024	1156134	NITROGEN DRY E SIZE	Replaced sight glass orings fit compressor back and pressure test found inner oring right back was weeping replaced and tested again tested ok vac and charge system run up tested ok	625287
143	01/16/2024	1156134	Mechanic entered - A/C Heating Air Conditioning Both compres	Weeping oil through all sight glass orings parts orderedjob not completed carry over	625287
143	01/15/2024	1156134		Reclaim refrigerant remove compressors ready for sight glass oring replacement job not completed carry over	625287
143	01/15/2024	1156134	OR-TM31-SP SIGHT GLASS O RING	Creditor #:GB-22C001 22 CELSIUS P/O #:G355686 Receiving #:377370 Date :2024-01-16	625287
143	01/06/2024	1161954	Mechanic entered - Body Other o/s middle seat vinyl flooring		625287
143	01/06/2024	1161954		removed and made new vinyl peice and applied	625287
143	01/06/2024	1161954	Consumables		625287
143	01/05/2024	1161692	PERFORM CAMPAIGN 10/23 POSITIONING OF 2024 PTV FARES	Done by Refeulers	625287
143	01/02/2024	1160626		VEHICLE SAFETY INSPECTION carried out safty inspection as per check list and tensined all wheel nuts with indi. carried out fitting missing screw into ac vent replace one e exit light secure all screws behind driver panel and steam cleaned dusty engine bay.	625287
143	01/02/2024	1160626		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	625287
143	12/08/2023	1156979	Mechanic entered - Wipers and Washers Wipers Loose	checked and find one wiper arm on left hand side came off. re-paired and put circlip to hold the arm and checked it ok. Complete.	624541
143	12/08/2023	1156978	Consumables		624541
143	12/08/2023	1156978	Mechanic entered - Elec and Light Exterior Lights	checked and find driver side globe not working. checked and find blown globe. re-placed and checked it ok. Complete.	624541
143	12/08/2023	1156978	GLOBE 24V 75/70W H4		624236
143	12/05/2023	1154487		Finish off B service Rear unit	624143
143	12/04/2023	1155837	Mechanic entered - A/C Heating Noisy Brush mount plate has c	Remove front left bank motor disassemble motor and resure brush mount plate assemble motor fit back into position and test ok	623525
143	12/04/2023	1154487		Service as per list frount unit only Not completed carry over	623525
143	11/27/2023	1154549	Drv entered - Wipers and Washers Wipers Not Working	checked for wiper function and find all works ok plus wiper washer also works fine. Complete.	623525
143	11/27/2023	1154548	Drv entered - Elec and Light Exterior Lights	checked for all lights all works ok and chekced for brake and reverse light with LOchi and find works ok. Complete.	623525
143	11/27/2023	1154548	Consumables		623525
143	11/27/2023	1154487		CARRY OUT A/C - B SERVICE AS PER CHECK LIST	623525
143	11/27/2023	1154487	FILTER DRYER 5/8 3K171124 A/C DML305		623525
143	11/27/2023	1154487	OIL COMPRESSOR AIR CONDITIONING		623525
143	11/27/2023	1154487		CARRY OUT A/C - A SERVICE AS PER CHECK LIST Stsrtd service not completed carry over	623525
143	11/21/2023	1152803	DIRECT PURCHASE - VANDALISM	Creditor #:MT-GLA010 GLASSPROTECH MELBOURNE P/O #:M354567 Receiving #:374183 Date :2023-11-23 Vandalism GRAFFITI AUDIT 986 FILM REPLACEMENT	623319
143	11/21/2023	1153468	*** PHOTOS TAKEN BY GERALD *** - TPAF - R/2023/55958/MR - A	No Damage Instructed to close off accident.	622940
143	11/17/2023	1152803	Vandalism GRAFFITI AUDIT 986 FILM REPLACEMENT		622845
143	10/23/2023	1147918	GASKET ROCKER CVR DC903 B01 SCANIA L94UAB 1425921		620945
143	10/23/2023	1147918		SERVICE MOISTURE EJECTOR N/A	620945
143	10/23/2023	1147918		Assisted.	620945
143	10/23/2023	1147918		Assisted.	620945
143	10/23/2023	1147918		CARRY OUT TUNE-UP SERVICE AS PER CHECK LIST completed as per check list	620945
143	10/20/2023	1145089	TYRE 295/80R22.5 RECAP	WRONG TYRES BOOKED OUT BY DE SILVA	620945
143	10/20/2023	1145089	TYRE 275/70R22.5 RECAP		620945
143	10/20/2023	1145089	Consumables		620945
143	10/20/2023	1147526	Consumables		620945
143	10/20/2023	1147526	Consumables		620945
143	10/20/2023	1147526	Consumables		620945
143	10/20/2023	1147526	Consumables		620945
143	10/20/2023	1147526	OIL ENGINE MOBIL DELVAC MODERN 15W-40 MIN		620945
143	10/20/2023	1147526	OIL MOBILUBE HD PLUS 80W-90 LU6 BORATE		620945
143	10/20/2023	1147526	OIL AUTOMATIC MOBIL ATF MULTIPURPOSE(TEXAMATIC)		620945
143	10/20/2023	1147526	FILTER FUEL SCANIA L94 (1372444)		620945
143	10/20/2023	1147526		CARRY OUT C SERVICE AS PER CHECK LIST	620945
143	10/20/2023	1147526	FILTER OIL SCANIA K93 L94 1117285 2059778		620945
143	10/20/2023	1147526	OIL SAMPLE TEST KIT		620945
143	10/20/2023	1147526	FILTER ZF ECOMAT GEARBOX 4139-298-038 1193281		620945
143	10/20/2023	1147526	FILTER FUEL/WATER SEPARATOR SCANIA L94UB 1393640		620945
143	10/20/2023	1147526	FILTER P/STRG MERC SCANIA VOLVO (0153468)(349619)		620945
143	10/20/2023	1147526	O-RING SPINNER FILTER SCANIA L94		620945
143	10/20/2023	1147526	PAPER SPINNER FILTER OIL INSERT SCANIA L94		620945
143	10/20/2023	1147526	O-RING SPINNER FILTER SCANIA K230		620945
143	10/20/2023	1147526	FILTER AIR DRYER SCANIA VOLVO 1393551 20546795 20424148		620945
143	10/20/2023	1147526	Consumables		620945
143	10/20/2023	1147526	Consumables		620945
143	10/20/2023	1147526	Consumables		620945
143	10/20/2023	1147526	Consumables		620945
143	10/20/2023	1147526	Service	CARRY OUT B SERVICE AS PER CHECK LIST completed.	620945
143	10/19/2023	1147526	FILTER AIR OUTER SCANIA SR 3 &	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G352896 Receiving #:371911 Date :2023-10-20	620945
143	10/19/2023	1147526	FILTER HYD COOLING FAN SCANIA	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G352896 Receiving #:371911 Date :2023-10-20	620945
143	10/11/2023	1145635		re-tensioned nuts on wheels 7 and 8 with feda.	620052
143	10/10/2023	1145303		VEHICLE SAFETY INSPECTION	619916
143	10/10/2023	1145303		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	619916
143	10/10/2023	1145303		ANNUAL SAFETY INSPECTION SERIAL # RSI 052420 - PASS - 10.10.23 WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25	619916
143	10/10/2023	1145303		Assisting completed rsi.	619916
143	10/10/2023	1145303	CARRYOUT ANNUAL INSPECTION	Creditor #:GB-ROA001 ROAD SAFETY INSPECTIONS P/O #:G352260 Receiving #:372858 Date :2023-11-02 BUS 143 - RWC - 10.10.2023	621750
143	10/10/2023	1145421	Consumables		619916
143	10/10/2023	1145421	Body R/h reaqr passanger seat loose		619916
143	10/09/2023	1145089	TYRE 295/80R22.5 RECAP	Fixed	619916

143	10/09/2023	1145089	WHEEL NUT SCANIA L94UAB 1749034 2285273		619916
143	10/09/2023	1145089	Mechanic entered - Wheels and Tyres Flat or Leaking pos 8	Changed N/S drive axle 2 tyres tensioned wheel nut with Jimi	619916
143	10/09/2023	1145085	Consumables		619916
143	10/09/2023	1145085	Carry out final inspection for RSI	completed	619916
143	09/26/2023	1142446	DECAL PLEASE HOLD ON BLACK ON YELLOW		619314
143	09/26/2023	1142446		applied decal.	619314
143	09/25/2023	1141818		checked ok	619314
143	09/25/2023	1142435	Mechanic entered - Body Other steam clean bus	Assist to sathees to clean the bus	619314
143	09/25/2023	1142441	Mechanic entered - Body Other missing yellow floor strip o/s	Assisted.	619314
143	09/25/2023	1142441		fitted new 5 places	619314
143	09/25/2023	1142442	Mechanic entered - Body Other rear n/s exterior do not overt	Fitted new decal.	619314
143	09/25/2023	1142462	Mechanic entered - Body Drivers Seat Controls Knob missing	fitted one from screap bus	619314
143	09/25/2023	1142445	Mechanic entered - Body Drivers Seat Controls driver seat co		619314
143	09/25/2023	1142446	Mechanic entered - Body Other please hold on decal behind dr		619314
143	09/25/2023	1142447	Mechanic entered - Body Other please keep clear decal on mid		619314
143	09/25/2023	1142461	Mechanic entered - Body Drivers Seat Cover need to change		619314
143	09/25/2023	1142442	DECAL DO NOT OVERTAKE 100MM X 300MM		619314
143	09/25/2023	1142441	EDGE STEP INSERT YELLOW 40MM P/M 2B10378SER		619314
143	09/25/2023	1142443	STRUT GAS STAY LIFT UP SEAT		619314
143	09/25/2023	1142445			619314
143	09/25/2023	1142440	Mechanic entered - Body Other both priority decal peeling	W/O 1142462 and this is the same Job completed	619314
143	09/25/2023	1142444	Mechanic entered - Body Other top up before you travel decal	Fitted new Decal.	619314
143	09/25/2023	1142435		Fitted new decal.	619314
143	09/25/2023	1142443	Mechanic entered - Body Other pirority seats gas struts both	Steam cleaned Engine bay And Gear box. Fixed Rusted Chasis.	619314
143	09/25/2023	1142448	Mechanic entered - Air System Air_Leak Doors front door exte	Fitted new Gas struts.	619314
143	09/25/2023	1142448	BUTTON CLIPPARD DOOR VALVE 11916-2	replaced Front air switch & knob	619314
143	09/25/2023	1142448	VALVE CLIPPARD DOOR OPEN/CLOSE (11916-2) BUTTON		619314
143	09/21/2023	1141940	Consumables		619314
143	09/21/2023	1141940	Mechanic entered - Elec and Light Interior Lights middle doo	replaced blown globes in emergancy exit lights and tested tested ok	619314
143	09/21/2023	1141818	Mechanic entered - Body Other front interior mirror loose	put packers behind sml. cab mirror and tightened.	619314
143	09/20/2023	1141730		VEHICLE SAFETY INSPECTION completed	619314
143	09/20/2023	1141730		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS done with Jimi	619314
143	09/20/2023	1141730		completed same time as per work order 1141694	619314
143	09/20/2023	1141694		CARRY OUT CCTV - B SERVICE AS PER CHECK LIST completed	619314
143	09/20/2023	1141694		completed Pre RSI and cctv b service as per check list with sisil and tensioned all wheel nuts with sisil	619314
143	09/20/2023	1141694		PRE ANNUAL SAFETY INSPECTION CHECK completed	619314
143	09/20/2023	1141713	Service	CARRY OUT FIRE EXTINGUISHER TEST & TAG Completed 18/8/2023 by ATS	619314
143	09/20/2023	1141713	Service	Assisting	619314
143	09/12/2023	1140134	OIL ENGINE MOBIL DELVAC MODERN 15W-40 MIN		618890
143	09/12/2023	1140134	OIL SAMPLE TEST KIT		618890
143	09/12/2023	1140134	OIL AUTOMATIC MOBIL ATF MULTIPURPOSE(TEXAMATIC)		618890
143	09/12/2023	1140134		CARRY OUT B SERVICE AS PER CHECK LIST complete	618890
143	09/12/2023	1140134	FILTER OIL SCANIA K93 L94 1117285 2059778		618890
143	09/12/2023	1140134	Consumables		618890
143	09/12/2023	1140134	Consumables		618890
143	09/12/2023	1140134	Consumables		618890
143	09/12/2023	1140134	COVER EMERGENCY EXIT BUTTON 16906		618890
143	09/12/2023	1140134	O-RING SPINNER FILTER SCANIA L94		618890
143	09/12/2023	1140134	O-RING LARGE SPINNER FILTER SCANIA L94 & K230		618890
143	09/12/2023	1140134	PAPER SPINNER FILTER OIL INSERT SCANIA L94		618890
143	09/12/2023	1140134	FILTER FUEL SCANIA L94 (1372444)		618890
143	09/12/2023	1140134	FILTER ZF ECOMAT GEARBOX 4139-298-038 1193281		618890
143	08/31/2023	1137680	Drv entered - Warning Lights Engine	no engine light .	617963
143	08/31/2023	1137653		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST Complete fire safety safety as per check list. fire some lose wire in fuse box tight it up and checked it ok.find bellow for arctic is having hole in it did a temporary fit and complete the safety as per check list. Complete.	617963
143	08/31/2023	1137653		complete fire safety inspection as per check list	617963
143	08/31/2023	1137653		assist with sealing up hol in arctic.	617963
143	08/21/2023	1134871	Drv entered - Breakdown	Attened to B/Down check batteries jump start check chargine rate all ok bus serviceble	617144
143	08/17/2023	1134065	PERFORM CAMPAIGN 05/23 POSITIONING OF NO SMOKING NO VAPING	Done by Refuelers	616924
143	07/27/2023	1129457	GLOBE 24V 75/70W H4		615110
143	07/27/2023	1129457	Drv entered - Elec and Light Exterior Lights	inspect bus and found blown L/H lowbeam globe removed headlight surround and headlight replaced headlight globe and refit headlight. test lights tested ok	615110
143	07/27/2023	1129457	Consumables		615110
143	07/25/2023	1128904	Drv entered - Wipers and Washers Washers Not Working		614913
143	07/25/2023	1128904	WIPER BLADE 28 INCH ARTIC N72		614913
143	07/25/2023	1128904	WASHER JET SUIT CWA1326 220111		614913
143	07/25/2023	1128904		check and found that washer jets was blocked and wiper was not good so replaced both wiper blades and washer jets.	614913
143	07/25/2023	1128871	Drv entered - Dash Dash_Lights Not Working		614913
143	07/25/2023	1128871	Drv entered - Dash Dash_Lights Not Working	removed cluster and replaced all blown dash light globes tested lights test ok	614913
143	07/25/2023	1128903	Drv entered - Elec and Light Exterior Lights	checked and found r/h top brake and r/h rear bottom park lights not working. found and replaced 2 blown globes tested ok	614913
143	07/25/2023	1128871	Consumables		614913
143	07/25/2023	1128903	Consumables		614913
143	07/24/2023	1128603	PERFORM CAMPAIGN 02/23 POSITIONING OF 2023 PTV FARES	Completed	614818
143	07/12/2023	1125897		re-tensioned nuts on wheels 5; 6; 9 and 10 with zubair.	614012
143	07/06/2023	1124468	Mechanic entered - Elec and Light Flat Batteries	jump started.	613827
143	07/06/2023	1124468	Consumables		613827
143	06/26/2023	1122550		VEHICLE SAFETY INSPECTION Completed safety service.	613827
143	06/26/2023	1122550		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	613827
143	06/26/2023	1122550		Assisted.	613827
143	06/26/2023	1122563	TYRE 275/70R22.5 RECAP		613827
143	06/26/2023	1122563		assisted and tensioned the wheel nuts With haysun	613827
143	06/26/2023	1122563	Mechanic entered - Wheels and Tyres Worn pos 6 and 910 tyre	r/r pos 910 with recap and fitted runout tyre on pos 6 and tensioned the wheel nuts with sujeong	613827
143	06/26/2023	1122563	Consumables		613827
143	06/26/2023	1122573	Mechanic entered - Elec and Light Other Few light out.	Replaced globe for N/S/F top parkerN/S/R top brakeRear interior e/exit N/S/R end saloonand 2 passenger stop buttons buttons from 585.	613827
143	06/26/2023	1122573	Consumables		613827
143	06/23/2023	1122168	Drv entered - Elec and Light Indicators Not Working	Replaced O/S/F upper indicator globe	613827
143	06/07/2023	1119202	Engine Steam clean engine and check for oil leak	Steam clean - road test no leak found	612470
143	06/07/2023	1119202	Engine Steam clean engine and check for oil leak	Assisting	612470
143	06/06/2023	1118981	Drv entered - Elec and Light Reverse Buzzer	checked reverse buzzer working ok. Complete.	612325
143	06/06/2023	1118981	Interior ceiling light fallen off	checked and find rear saloon lense fallen. put back. Complete.	612325
143	06/06/2023	1118981	Drv entered - Elec and Light Horn	checked horn working ok. Complete.	612325
143	06/06/2023	1118981	Consumables		612325
143	05/29/2023	1117396	Mechanic entered - Body Other drivers door storing panel bro	replaced door hinges. checked all ok	611679
143	05/29/2023	1117396	HINGE 80DEG DRIVERS DOOR COMPARTMENT PLASTIC		611679
143	05/04/2023	1112400	Mechanic entered - Elec and Light Exterior Lights	Marker light cover missing Replaced with new cover. Working as normal.	609912

143	05/04/2023	1112400	LAMP SIDE MARKER RED/AMBER(HL2029)		609912
143	05/04/2023	1112400	Consumables		609912
143	05/04/2023	1112402	Mechanic entered - Body Drivers Seat Belt	Found drivers seat belt buckle wiring the be frayed Replaced with new buckle. Working per usual.	609912
143	05/04/2023	1112402	BUCKLE SEAT BELT TWIN WIRE GREY SOB2123GY 340446		609912
143	05/03/2023	1112158	Night gear button has fallen off/missing	fitted neutral button.	609774
143	05/03/2023	1112155	Elec and LightDriver reported an interior light cover miss	carried out fitting back plastic saloon cover and fitting spare n switch from upstairs.	609774
143	05/03/2023	1112155	Consumables		609774
143	05/03/2023	1112158	Consumables		609774
143	04/14/2023	1095391	NITROGEN DRY E SIZE	NO STOCK SHOWING	609228
143	04/03/2023	1107034		VEHICLE SAFETY INSPECTION Complete	608622
143	04/03/2023	1107034		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	608622
143	04/03/2023	1107010		CARRY OUT CCTV - A SERVICE AS PER CHECK LIST Complete as per Check list. Complete.	608622
143	03/16/2023	1103342		CARRY OUT FIRE EXTINGUISHER TEST & TAG Completed by ATS	607442
143	03/06/2023	1101208	Consumables		606582
143	03/06/2023	1101208	Drv entered - Elec and Light Exterior Lights	checked and find out drive side center indicator not working. find out globe blown re-placed with new one and checked it working ok. Complete.	606582
143	03/03/2023	1100770	Consumables		606582
143	03/03/2023	1100770	Elec and Light Exterior Lights n/s tail light not working	replaced n/s lower brake light globe all ok	606582
143	02/21/2023	1098300	A/C Heating Not Cooling No Power to Rear A/C Unit	Locate and repair short in rear loom for rear A/C unit tested ok	605689
143	02/08/2023	1095391	NITROGEN DRY E SIZE		604822
143	02/08/2023	1095391	Drv entered - A/C Heating Not Cooling	Tested both units dead traced fault back to no Alternator signal found broken wire in pillar repaired wire and run units up rear unit had a broken clutch wire replaced connector tested ok front unit controller was disconnected reconnect run unit up rear unit has no refrigerant pressure tested with a trace gas unable to dete	604822
143	02/07/2023	1095152	Consumables		604616
143	02/07/2023	1095152	Drv entered - Dash Guages Not Working	checked the circuit clean the connections adjut the instruments working now	604616
143	01/09/2023	1089957	Mechanic entered - Elec and Light Exterior Lights park light	checking the electrical wirering diagram checking the connections change few globes repaire the cable working now.	604191
143	01/09/2023	1090008	Mechanic entered - Elec and Light Other dash light jack knif	fixed under the other job number 1089957	604191
143	01/09/2023	1089957	Mechanic entered - Elec and Light Exterior Lights park light	checked the fuses and relays if faulty then find out the fuse holder for park lights is not getting power and then checked wiring diagram and checked relay then noticed when pressing relay the lights are coming on then checked the wire all the way behind the relay and fuse pannel and find out a short fixed it up and checke	604191
143	01/09/2023	1089957	Consumables		604191
143	01/09/2023	1090008	Consumables		604191
143	01/06/2023	1089584		VEHICLE SAFETY INSPECTION completed	604191
143	01/06/2023	1089584		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS done with Ben	604191
143	01/06/2023	1089584		Assisted Sisil. Completed checklist as per work order. Tensioned all wheelnuts to OEM specs	604191
143	01/06/2023	1089584		Incorect entry	604191
143	01/04/2023	1089116	Mechanic entered - Body Drivers Seat Belt		604191
143	11/21/2022	1081955	COMPUTER SLRT/RM-RP (2 DEG O/S)		602268
143	11/21/2022	1081955		CARRY OUT A/C - A SERVICE AS PER CHECK LIST Replaced rear unit ccc Service as per list	602268
143	11/21/2022	1081955		assisted	602268
143	11/18/2022	1081401	Consumables		602268
143	11/18/2022	1081401	Master-switch is not working	checkedthe connection install new cable beatwin master swich and solenoid.	602268
143	11/17/2022	1081401	Master-switch is not working	assisted	602268
143	11/17/2022	1081401	RELAY VOLVO H/LIGHT DIODE PROTECTED 21244697		602268
143	11/17/2022	1081401	Master-switch is not working	checked bus wiring and tried to find wiring diagram but not able then for every possible wirings and did continuity test but did not find any thing then run new wiring from fuse box to master switch and started working. C/O.	602268
143	11/17/2022	1081401	'Jackknife' warning light comes on every time bus turns	long road test warning light jack knife not there	602268
143	11/17/2022	1081401	Master-switch is not working	checked bus wiring and tried to find wiring diagram but not able then for every possible wirings and did continuity test but did not find any thing then run new wiring from fuse box to master switch and started working. C/O.	602268
143	11/16/2022	1081401	Master-switch is not working	replaced masterm switch	602268
143	11/16/2022	1081401	'Jackknife' warning light comes on every time bus turns	trying to get the fault code c/o	602268
143	11/16/2022	1081401	SWITCH MASTER SWITCH SCANIA		602268
143	11/16/2022	1081401	'Jackknife' warning light comes on every time bus turns	road tested no fault coming on dash need investigation c/o	602268
143	11/15/2022	1081095	Mechanic entered - Elec and Light Flat Batteries needs jump	jump started 143.	602119
143	11/15/2022	1081095	Consumables		602119
143	11/14/2022	1080872	Mechanic entered - Elec and Light AM-FM Radio am-fm radio n/	repalced the radio from scrap bus and fixed it	601987
143	11/14/2022	1080872	Consumables		601987
143	10/28/2022	1078139		TRANSMISSION CHECK AS PER CHECK LIST Complete as per shit	600907
143	10/28/2022	1078139		TRANSMISSION CHECK AS PER CHECK LIST Completed	600907
143	10/28/2022	1078151	Glasspro-Vandalism- Replace anti Grafiti film	Checked has been dane	600907
143	10/28/2022	1078149	Mechanic entered - Body Wheel Chair Ramp Wheel chair ramp f	Clean up and secured OK	600907
143	10/13/2022	1074478	Annual saftey inspection	Creditor #:GB-ROA001 ROAD SAFETY INSPECTIONS P/O #:G330493 Receiving #:347379 Date :2022-10-14	599852
143	10/12/2022	1075007		Tensioned wheel nuts position 3 and 4 with Kuma.	599798
143	10/12/2022	1075007		Assisted Rene.	599798
143	10/11/2022	1074478		VEHICLE SAFETY INSPECTION	599798
143	10/11/2022	1074478		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	599798
143	10/11/2022	1074478		ANNUAL SAFETY INSPECTION SERIAL #RSI 044191. WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25	599798
143	10/11/2022	1074478		Assisting carried out rsi and fitted e exit globe	599798
143	10/11/2022	1074478	Service	ASSISTED	599798
143	10/10/2022	1073708	ELBOW FITTING TWIN 16MM RR AIR	Creditor #:GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G330385 Receiving #:347004 Date :2022-10-10	599678
143	10/10/2022	1073708	Mechanic entered - Suspension Other Drive axle rear of rear	Removed and replace air bag.	599678
143	10/10/2022	1072659	Mechanic entered - Elec and Light Other Engine light stay on	Roadtest check for fault no light showing on dash.	599678
143	10/10/2022	1072659	Consumables		599678
143	10/10/2022	1074327	Mechanic entered - Body Other Battery panel gas strut need r	Removed and replace gas strut.	599678
143	10/10/2022	1074327	STRUT GAS STAY 500Nm 330mm LONG		599678
143	10/10/2022	1074331	Carry out final inspection for RSI	Carry out completed check list.	599678
143	10/07/2022	1073708	AIRBAG REAR 16MM SCANIA K280UB K310 6714 NP02 40Y2222		599678
143	10/07/2022	1073708	Mechanic entered - Suspension Other Drive axle rear of rear	Removed air bag Check air bag fitting found out new air bag hole bigger than the old one. New air bag need to provide new fitting to use and to fit air bag. Parts order reported to Kuma advise to refit old air bag parts on order. Carry/over.	599678
143	10/07/2022	1072656	Mechanic entered - Fluid Leaks Rear of bus Engine oil leak n	Checked found out leak from top of engine fitting removed and secured refit test no leak.	599678
143	10/07/2022	1073906	PERFORM CAMPAIGN 10/22 WEAR A FACE MASK WHILE TRAVELLING D	completed.	599678
143	10/06/2022	1072328	Mechanic entered - Suspension Other Drive axle v rod worn.	assist Dulkith and Gerrald to remove rear Vbar Rod.	599678
143	10/06/2022	1072328	Mechanic entered - Suspension Other Drive axle v rod worn.	removed rear Vbar rod	599678
143	10/06/2022	1072328	Mechanic entered - Suspension Other Drive axle v rod worn.	Cleaned thread and fitted new V-rod assembly tensioned all bolts according to specs. Secured wirings and hoses.	599678
143	10/06/2022	1073708	Mechanic entered - Suspension Other Drive axle rear of rear	Check for parts no parts available need to order. Carry/over.	599678
143	10/06/2022	1072328	M22 X 1.5 X 70 BLACK HEX HEAD	Creditor #:GB-ECO001 ECONOMY BOLT COMPANY PTY LTD P/O #:G330269 Receiving #:346832 Date :2022-10-06	599678
143	10/06/2022	1072657	Mechanic entered - Body Other Under carriage and engine need	Steam cleaned. Cleaned work area.	599678
143	10/05/2022	1072584	Mechanic entered - Elec and Light Interior Lights Saloon lig	put new holder and fit the light and checked working ok. Complete.	599678
143	10/05/2022	1072584	Consumables		599678
143	10/05/2022	1073339	SEAT CUSH SINGLE CEN CVR CI		599678
143	10/05/2022	1073339	Mechanic entered - Body Passenger Seat Torn Passenger seat c	Removed and replace three passenger seat cushion.	599678
143	10/04/2022	1072328	Mechanic entered - Suspension Other Drive axle v rod worn.	tap V bar thred start pulling V rod C/O.	599678
143	10/04/2022	1072584	62076 FLURO LIGHT END FITTING	Creditor #:GB-VOL001 VOLGREN AUSTRALIA PTY LTD P/O #:G330017 Receiving #:346679 Date :2022-10-04	599678
143	10/04/2022	1072659	Mechanic entered - Elec and Light Other Engine light stay on	C/O	599678
143	10/04/2022	1072657	Mechanic entered - Body Other Under carriage and engine need	C/O	599678
143	10/04/2022	1072658	STONEGUARD BLACK AEROSOL 500ML		599678
143	10/04/2022	1072658	Mechanic entered - Body Other Under carriage chassi rusted n	Cleaned and paint rusted area.	599678
143	10/04/2022	1072655	Mechanic entered - Body Other Drivers control panel off side	Secured fitted new vinyl to damged area and fitted new screws to panel.	599678
143	10/03/2022	1071904	TYRE 275/70R22.5 NEW		599678
143	10/03/2022	1071904	Consumables		599678
143	10/03/2022	1072328	Mechanic entered - Suspension Other Drive axle v rod worn.		599678
143	10/03/2022	1072656	Mechanic entered - Fluid Leaks Rear of bus Engine oil leak n	C/O	599678

143	10/03/2022	1072584	Mechanic entered - Elec and Light Interior Lights Saloon lig	599678
143	10/03/2022	1072584	Mechanic entered - Elec and Light Interior Lights Saloon lig	599678
143	10/03/2022	1072583	Mechanic entered - Elec and Light Exterior Lights Off side r	599678
143	10/03/2022	1072585	Mechanic entered - Elec and Light Interior Lights Dash board	599678
143	10/03/2022	1072654	Mechanic entered - Elec and Light Other Drivers shifting gea	599678
143	10/03/2022	1072659	Mechanic entered - Elec and Light Other Engine light stay on	599678
143	10/03/2022	1072583	Mechanic entered - Elec and Light Exterior Lights Off side r	599678
143	10/03/2022	1072585	Mechanic entered - Elec and Light Interior Lights Dash board	599678
143	10/03/2022	1072583	Consumables	599678
143	10/03/2022	1072585	Consumables	599678
143	10/03/2022	1072654	Consumables	599678
143	10/03/2022	1072657	Mechanic entered - Body Other Under carriage and engine need	599678
143	10/03/2022	1072655	Mechanic entered - Body Other Drivers control panel off side	599678
143	10/03/2022	1072658	Mechanic entered - Body Other Under carriage chassi rusted n	599678
143	09/30/2022	1072328	Mechanic entered - Suspension Other Drive axle v rod worn.	599678
143	09/30/2022	1072328	Mechanic entered - Suspension Other Drive axle v rod worn.	599678
143	09/30/2022	1072329	BUSH SWAY BAR MID AXLE SCANIA	599678
143	09/30/2022	1072329	Mechanic entered - Suspension Other Middle d rubber worn.	599678
143	09/30/2022	1072329	Mechanic entered - Suspension Other Middle d rubber worn.	599678
143	09/30/2022	1072328	ASSEMBLY V STAY ASSEMBLY SCANI	599678
143	09/30/2022	1072331	Mechanic entered - Suspension Other Off side front sway bar	599678
143	09/30/2022	1072331	LINK FRT SWAY BAR SCANIA L94 1	599678
143	09/30/2022	1072331	Mechanic entered - Suspension Other Off side front sway bar	599678
143	09/30/2022	1072330	Mechanic entered - Body Other Drivers lumbar control switch	599678
143	09/30/2022	1072330	SWITCH AIR LUMBAR COMPLETE LH+RH	599678
143	09/30/2022	1072330	Mechanic entered - Body Other Drivers lumbar control switch	599678
143	09/30/2022	1072330	Consumables	599678
143	09/28/2022	1071886		599678
143	09/28/2022	1071886		599678
143	09/28/2022	1071904	Mechanic entered - Wheels and Tyres Worn Position 4 tyre wor	599678
143	09/28/2022	1071904	Consumables	599678
143	09/28/2022	1070277	Mechanic entered - A/C Heating Noisy Failed hub armature	599678
143	09/28/2022	1070277	AIR CON REFRIDGERANT	599678
143	09/27/2022	1070277	PULLEY IDLER (SMOOTH PLASTIC) SCANIA 1514086 1428940	599678
143	09/27/2022	1070277	TENSIONER BELT SCANIA SR4(1859654)(1503113)	599678
143	09/27/2022	1070277	Part - 1378280 Spacer	599678
143	09/27/2022	1070277	Part - 814825 Bolt	599678
143	09/27/2022	1070277	Mechanic entered - A/C Heating Noisy Failed hub armature	599678
143	09/26/2022	1070277	BELT A/C TWIN COMP SCANIA L94UAB	599678
143	09/26/2022	1070277	BELT MICRO V SERPENTINE BELT 8 RIB 2595mm LONG	599678
143	09/26/2022	1070277	Mechanic entered - A/C Heating Noisy Failed hub armature	599678
143	09/19/2022	1070277	HUB ARMATURE & PULLEY TM31	599678
143	09/17/2022	1069542	Apply print film	599159
143	09/16/2022	1070202		599409
143	09/16/2022	1070202		599409
143	09/16/2022	1070202		599409
143	09/16/2022	1069542	Apply print film -L1 L2 L3 L4	599409
143	09/16/2022	1070277	Mechanic entered - A/C Heating Noisy Failed hub armature	599678
143	09/16/2022	1070203	O-RING SPINNER FILTER SCANIA K230	599409
143	09/16/2022	1070203	FILTER FUEL SCANIA L94(1372444)	599409
143	09/16/2022	1070203	FILTER OIL SCANIA K93 L94(1117285)(2059778)	599409
143	09/16/2022	1070203	O-RING LARGE SPINNER FILTER SCANIA L94 & K230	599409
143	09/16/2022	1070203	O-RING SPINNER FILTER SCANIA K230	599409
143	09/16/2022	1070203	PAPER INSERT OIL SPINNER FILTER SCANIA K SERIES	599409
143	09/16/2022	1070203	OIL ENGINE MOBIL DELVAC MODERN 15W-40 (MIN)	599409
143	09/16/2022	1070203	OIL AUTOMATIC MOBIL ATF MULTIPURPOSE(TEXAMATIC)	599409
143	09/16/2022	1070203	PAPER INSERT OIL SPINNER FILTER SCANIA K SERIES	599409
143	09/16/2022	1070203	PAPER SPINNER FILTER OIL INSERT SCANIA L94	599409
143	09/16/2022	1070203	O-RING SPINNER FILTER SCANIA L94	599409
143	09/16/2022	1070203	FILTER ZF ECOMAT GEARBOX 4139-298-038 1193281	599409
143	09/16/2022	1070203		599409
143	09/16/2022	1070203		599409
143	09/16/2022	1070203	Consumables	599409
143	09/16/2022	1070203	Consumables	599409
143	09/16/2022	1070203	Consumables	599409
143	09/16/2022	1070203	Consumables	599409
143	09/02/2022	1067418		598416
143	09/01/2022	1067196	Drv entered - Elec and Light Indicators Not Working	598416
143	09/01/2022	1067099	Mechanic entered - Elec and Light Indicators Not Working	598416
143	09/01/2022	1067196	Consumables	598416
143	09/01/2022	1067099	Consumables	598416
143	08/24/2022	1065381		597799
143	08/24/2022	1065381		597799
143	07/21/2022	1029317	Air System Air_Leak Interior AIR LEAK AT REAR DOOR	595394
143	07/21/2022	1029317	VALVE CLIPPARD DOOR OPEN/CLOSE (11916-2) BUTTON	595394
143	07/21/2022	1029317	Air System Air_Leak Interior AIR LEAK AT REAR DOOR	595394
143	07/21/2022	1029317	Air System Air_Leak Interior AIR LEAK AT REAR DOOR	595394
143	06/23/2022	1053419		594428
143	06/23/2022	1053419		594428
143	06/23/2022	1053419	SEAT SINGLE BACK REST	594428
143	06/23/2022	1053419		594428
143	06/03/2022	1049929	PERFORM CAMPAIGN 03/22 QR CODE & SELECTED COVID19 DECAL REM	592839
143	06/01/2022	1049539	Drv entered - A/C Heating Demister Not Heating	592504
143	06/01/2022	1049543	Drv entered - A/C Heating Demister Not Heating	592504
143	06/01/2022	1049540	Drv entered - A/C Heating Demister Not Heating	592504
143	06/01/2022	1049540	Service	592504
143	06/01/2022	1049541	A/C Heating Demister Not Heating - DRIVER CAN'T SEE ROAD P	592504
143	06/01/2022	1049542	Drv entered - A/C Heating Demister Not Heating	592504
143	06/01/2022	1049604	Mechanic entered - Elec and Light Other Temperature guage no	592504
143	06/01/2022	1049604	Mechanic entered - Elec and Light Other Temperature guage no	592504
143	06/01/2022	1049604	Consumables	592504
143	05/19/2022	1047284		592001
143	05/19/2022	1046468	Mechanic entered - Suspension Noisy	592001
re-placed one saloon light and checked working ok. need to change theother and it is having broken holder. don't have holder in stock and ordered one coming tomorrow and can change it.C/O.				
light worn out re-placed with new one and checked it working ok. Complete.				
Removed shifting gear switch control assembly and removed plus replace reverse and drive gear switch control cover. Parts taken from old parts stock.				
C/O				
change the side marking lighth the used but good condition one.				
C/O				
Removing v rod with Roshan to continue carry/over.				
Assisted Rene.				
Creditor #:-GB-MUL001 MULTISPARES LTD P/O #:-G329819 Receiving #:-346552 Date :2022-09-30				
Assisted Roshan replace d rubber bushes and tensioned all bolts 70 nm.				
replaced Drubber.				
Creditor #:-GB-MUL001 MULTISPARES LTD P/O #:-G329819 Receiving #:-346552 Date :2022-09-30				
Removed and replace link rod.				
Creditor #:-GB-MUL001 MULTISPARES LTD P/O #:-G329819 Receiving #:-346552 Date :2022-09-30				
Removed and replace link rod.				
Removed and replace test works ok.				
assisted.				
PRE ANNUAL SAFETY INSPECTION CHECK Completed check list.				
CARRY OUT CCTV - B SERVICE AS PER CHECK LIST Completed check list.				
Removed and replace tyre position 3 and 4 fitted run out tyre and return position 3 to rack. Tensioned all wheel nuts with Abraham.				
Pressure test vac and charge system tested ok				
Creditor #:-GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:-G329602 Receiving #:-346245 Date :2022-09-27				
Creditor #:-GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:-G329602 Receiving #:-346245 Date :2022-09-27				
Remove both compressor and compressor mount attempt to remove broken bolts from chassis received mount kit started to fit all back together job not completed carry over				
Remove and replaced failed hub armature fitted belts found compressor mount plate had movement plate had the wrong size mount bolts and spacers were missing parts ordered job not completed carry over				
Creditor #:-GB-22C001 22 CELSIUS P/O #:-G329280 Receiving #:-345946 Date :2022-09-20				
Completed 12/9/22				
VEHICLE SAFETY INSPECTION carried out as per check list tayla continue need wheel nuts and oil check				
TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS				
Completed as per checklist. Tension wheels with Matty				
Creditor #:-MT-GLA010 GLASSPROTECH MELBOURNE P/O #:-M329021 Receiving #:-345875 Date :2022-09-19				
Failed hub armature parts ordered				
NOT BOOKED OUT BY ZUBAIR				
CARRY OUT B SERVICE AS PER CHECK LIST carried out as per check list.				
B service completed as per checklist				
CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST Exterior roof bellows torn from n/s to o/s allowing water ingress. Inspection complete.				
Repair completed by moorabbin under work order 1067099				
Replaced flasher unit with 1192 flasher unit checked operation of indicators. ok.				
CARRY OUT FIRE EXTINGUISHER TEST & TAG				
Completed by ATS				
replaced Leaked switch 16/02/2022				
Date changed from 16/2/22 to 1/7/22 to post wo				
VEHICLE SAFETY INSPECTION				
TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS				
Assisted and Re-tensioned wheel nuts with Zubair.				
Has been completed				
Duplicate job. Delete.				
Heater tap at driver's left knee not in the 'ON' position. Demister working correctly. Complete.				
Duplicate job. Delete.				
Duplicate job. Delete.				
Drove bus and noticed temp guage not going past 40 deg even though the temp from the demister fan was reaching 42deg. Removed dash and swapped temperature guage with second hand unit guage now reaching 80 deg. Complete.				
wnt on route test with Neil amnd assist him to open up and re-place the guage the with a second hand from the stocks. Complete.				
Retensioned wheel nut pos 1 with sathees				
Fixed 18/09/2022				

143	05/19/2022	1047305	REMOVE OLD 2020 DECAL AND FIT NEW 2022 DECAL POSITION AS S	DONE	592001
143	05/18/2022	1046468	Mechanic entered - Suspension Noisy	replaced N/F top torque rod and rosd tested ok. also tensioned wheel nut with Alan	592001
143	05/18/2022	1046468	LINK FRT SWAY BAR SCANIA L94 1	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G321536RET Receiving #:337417 Date :2022-05-18 ORDERED BY DE SILVA THEN NOT REQUIRED	592001
143	05/18/2022	1046468	NUT M18 RR LWR TORQUE ROAD SCANIA L94UAB		592001
143	05/17/2022	1046468	Mechanic entered - Suspension Noisy	Road tested and found faulty torque rod on N/S next to shock absorber.waiting for parts. c/o	592001
143	05/17/2022	1046468	Mechanic entered - Suspension Noisy	removed front sway bar & chockabsobber road test still noisy. found N/F torque rod bush worn orser part	592001
143	05/17/2022	1046468	NUT M16 SCANIA TORQUE ROD	Creditor #:GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G321572 Receiving #:337371 Date :2022-05-18	592001
143	05/17/2022	1046468	TORQUE ROD FRT UPPER SCANIA K2	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G321570 Receiving #:337335 Date :2022-05-17	592001
143	05/17/2022	1046468	BOLT SCANIA TORQUE ROD M16 X 1	Creditor #:GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G321572 Receiving #:337374 Date :2022-05-18	592001
143	05/17/2022	1046468	BOLT SCANIA TORQUE ROD M16 X 5	Creditor #:GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G321572 Receiving #:337374 Date :2022-05-18	592001
143	05/17/2022	1046606	Consumables		592001
143	05/17/2022	1046607	Consumables		592001
143	05/17/2022	1046606	Drv entered - Dash Guages Not Working	Notes under WO no. 1046607	592001
143	05/17/2022	1046607	Drv entered - Dash Guages Not Working	Checked all dash gauges for function. All working fine. All dash ights and switch lights working fine. Need more information in defect so I know what I am looking for.	592001
143	05/16/2022	1046468	LINK FRT SWAY BAR SCANIA L94 1766014 0463245 20486 01		592001
143	05/16/2022	1045366	Mechanic entered - Suspension Other Middle Axle both side to	checked it's servisable	592001
143	05/16/2022	1046468	Mechanic entered - Suspension Noisy	replaced O/F worn link repaired broken mudgard still noisy c/o	592001
143	05/16/2022	1046468	LINK FRT SWAY BAR SCANIA L94 1	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G321536 Receiving #:337309 Date :2022-05-17	592001
143	05/16/2022	1046468	BUSH FRONT SWAY BAR SCANIA K23	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G321536 Receiving #:337309 Date :2022-05-17	592001
143	05/16/2022	1045367	Mechanic entered - Engine Other Main seal oil leak.	replaced the seal tensioned hub nut 300nm+60 fitted belt road tested ok	592001
143	05/13/2022	1045367	Service	went to 43 Ambly cresnt Dandenong to look for steel ring.	592001
143	05/13/2022	1045366	38 X 50 X 10 OIL SEAL	Creditor #:GB-EAS100 EASTERN BEARING COMPANY P/O #:G321423 Receiving #:337251 Date :2022-05-16	592001
143	05/13/2022	1045366	SPEEDI SLEEVE	Creditor #:GB-EAS100 EASTERN BEARING COMPANY P/O #:G321423 Receiving #:337251 Date :2022-05-16	592001
143	05/12/2022	1045366	Mechanic entered - Suspension Other Middle Axle both side to		592001
143	05/12/2022	1045367	Mechanic entered - Engine Other Main seal oil leak.	Removed Main seal. ordered Hub for seal running waiting for parts. c/o	592001
143	05/12/2022	1045367	Mechanic entered - Engine Other Main seal oil leak.	removed the main seal hub worn order part c/o	592001
143	05/11/2022	1045367	SEAL FRT CRANK DC903 B01 SCANI	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G321135 Receiving #:336941 Date :2022-05-11	592001
143	05/10/2022	1045366	Mechanic entered - Suspension Other Middle Axle both side to		592001
143	05/10/2022	1045367	Mechanic entered - Engine Other Main seal oil leak.	started removing the front seal	592001
143	05/10/2022	1045367	Mechanic entered - Engine Other Main seal oil leak.	Assited sisil. carry over.	592001
143	05/10/2022	1045227	FUEL LINE CONNECTORS	Creditor #:GB-ENZ001 ENZED DANDENONG P/O #:G321153 Receiving #:336843 Date :2022-05-10	592001
143	05/10/2022	1045227	Drv entered - Breakdown	Found leak from pipe fitting replaced the fitting	592001
143	05/10/2022	1045227	Drv entered - Breakdown	Assisting Assisted sisil. Went to enzed to buy parts.	592001
143	05/09/2022	1045042	Drv entered - A/C Heating Demister Not Heating	Commision tested unit run up to operating temperatures tested demisters at 42 c tested ok	592001
143	05/09/2022	1045043	Drv entered - A/C Heating Demister Not Heating	Commision tested unit run engine temperature up to operating temperatyre demisters tested at 42c tested ok	592001
143	05/03/2022	1043776	Mechanic entered - Elec and Light Exterior Lights o/s head I	removed and replaced head light globe and bolt for head light cover all working now .	591214
143	05/01/2022	1037721	Consumables		591214
143	05/01/2022	1037721	Drv entered - Elec and Light AM-FM Radio		591214
143	04/11/2022	1037721	Drv entered - Elec and Light AM-FM Radio		590725
143	04/11/2022	1037721	Drv entered - Elec and Light AM-FM Radio	cheanged the switch for driver volume control for the radio ckced it and find out radio not working try to figure out then find out one of the switch for radio has gone switched that on and checked the radio working fine and checked the volume switch working fine. Complete	590725
143	04/11/2022	1037721	Consumables		590725
143	04/11/2022	1040148	LOCK CCTV BOX 16mm BATON		590725
143	04/11/2022	1040148		CARRY OUT CCTV - A SERVICE AS PER CHECK LIST changed the lock for the CCTV device cover and did the inspection of cctv working fine. Complete.	590725
143	03/31/2022	1038229		VEHICLE SAFETY INSPECTION completed	590112
143	03/31/2022	1038229		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Done with Sathees	590112
143	03/31/2022	1038229		completed amd tentioned wheel nuts with Sisil	590112
143	03/31/2022	1037721	Consumables		590112
143	03/31/2022	1038277	Consumables		590112
143	03/31/2022	1038277	Mechanic entered - Elec and Light Other interior and exterio	faulty rear left hand park light changed the globe in it and checked it working fine interior front saloon light not working changed the light still not working checked for it again find out faulty invertor re-placed it with old one from the scrap buses checked it working fine. Complete. broken cover on the re-placed it with one	590112
143	03/31/2022	1037721	62076 VOLUME CONTROL SWITCH	Creditor #:GB-VOL001 VOLGREN AUSTRALIA PTY LTD P/O #:G318664 Receiving #:334455 Date :2022-04-01	590112
143	03/21/2022	1036178	Drv entered - Brakes Park_Brake Leaking Air	check park brake system replaced faulty check value. road tested bus ok.	589191
143	03/21/2022	1036178	CHECK VALVE SCANIA L113CRL 2	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G318138 Receiving #:333563 Date :2022-03-21	589191
143	03/02/2022	1032779	Ops Entered - Fault - Elec and Light Flat Batteries - Route	Check batteries. Charging fine. Complete.	588117
143	03/02/2022	1032779	Consumables		588117
143	02/23/2022	1030913		CARRY OUT FIRE EXTINGUISHER TEST & TAG	587533
143	02/23/2022	1030913		Completed by ATS	587533
143	02/21/2022	1030129	Air System Air_Leak Interior AIR LEAK AT REAR DOOR		586991
143	02/21/2022	1030129	Air System Air_Leak Interior AIR LEAK AT REAR DOOR	Assisting	586991
143	02/18/2022	1029828	Suspension REPLACE N/S SHOCK ABSORBER REAR	checked with Nevan 16/02/2022 ok	586991
143	02/18/2022	1029829	Suspension REAR SWAY BAR SHIFTED REPLACE D- MOUNTS	16/02/2022 checked with nevan ok	586991
143	02/18/2022	1029830	Suspension FRONT UPPER CONTROL ARMS CRACKING	checked with nevan 16/02/2022. ok	586991
143	02/18/2022	1029831	Suspension FRONT SWAY BAR LINKPINS SPLIT / CRACKING BOOTS	checked with nevan 16/02/2022. ok	586991
143	02/18/2022	1029832	Suspension REPLACE ALL REAR AIR BAGS	checked with nevan 16/02/2022. ok	586991
143	02/18/2022	1029833	Suspension FRONT LOWER CONTROL ARMS CRACKING	checked with nevan 16/02/2022. ok	586991
143	02/18/2022	1029834	Suspension REAR UPPER TORQUE RODS CRACKING	checked with Nevan on 16/02/2022. ok	586991
143	02/18/2022	1029835	Engine WASH POWER STEERING RESERVOIR AREA AND ENGINE	cleaned Tayla	586991
143	02/18/2022	1029827	Body (None) REAR 5 SEATER LOCKING LATCHS LOOSE	checked ok	586991
143	02/16/2022	1029287	Mechanic entered - Wheels and Tyres Flat or Leaking POS 3	changed flat pos 3 tyre (used runout) tensioned wheel nut with Nevan	586746
143	02/16/2022	1029287	Mechanic entered - Wheels and Tyres Flat or Leaking POS 3	changed flat pos 3 tyre (used runout) tensioned wheel nut with Nevan	586746
143	02/16/2022	1029287	Consumables		586746
143	02/16/2022	1029290	Suspension REPLACE BOTH FRONT AIR BAGS	checked with nevan ok	586746
143	02/16/2022	1029290	Suspension REPLACE BOTH FRONT AIR BAGS	checked with nevan ok	586746
143	02/16/2022	1029276	BELT MICRO V SERPENTINE BELT 8 RIB 2595mm LONG		586746
143	02/16/2022	1029276	Engine Belts_Loose Noisy Missing REPLACE ENGINE BELT TENSI	Replace alternator belt	586746
143	02/16/2022	1029256	Elec and Light Exterior Lights O/S INDICATOR NOT WORKING	checked ok	586746
143	02/16/2022	1029256	Elec and Light Exterior Lights O/S INDICATOR NOT WORKING	Assisting	586746
143	02/16/2022	1029391	Warning Lights (None) Jack-knife light on dash	Road tested can not see any light	586746
143	02/16/2022	1029391	Warning Lights (None) Jack-knife light on dash	Road tested can not see any light	586746
143	02/16/2022	1029391	Consumables		586746
143	02/16/2022	1029256	Consumables		586746
143	02/16/2022	1029292	Body (None) NO HAZARD TAPE		586746
143	02/16/2022	1029292	Body (None) NO HAZARD TAPE	Fitted new hazzard tape	586746
143	02/16/2022	1029291	Body Passenger Seat DISABLED SEAT CUSHIONS FADED		586746
143	02/16/2022	1029291	Body Passenger Seat DISABLED SEAT CUSHIONS FADED	Fitted 4 new fold down seat bases	586746
143	02/16/2022	1029291	SEAT BASE DOUBLE SEAT BASE RETRIMMED		586746
143	02/16/2022	1029265	Body (None) N/S RAMP REQUEST BELLSTEP NOT WORKING	Found stop bell wires broken underneath body. cut and stripped wires. Fitted joiners. Checked bell. Bell works	586746
143	02/16/2022	1029265	BELL PUSH FOR WHEEL CHAIR PASS (40792)		586746
143	02/16/2022	1029265	Body (None) N/S RAMP REQUEST BELLSTEP NOT WORKING	Found stop bell wires broken underneath body. cut and stripped wires. Fitted joiners. Checked bell. Bell works	586746
143	02/14/2022	1028740	Elec and Light Exterior Lights Top left rear tail light no	Checked function of all lights including indicators and brake lights. All working fine.	586651
143	02/14/2022	1028740	Consumables		586651
143	01/28/2022	1025316	Elec and Light Exterior Lights - drivers side indicator -	Replaced o/s front indicator globe insert. Replaced n/s rear stop/tail light globe. replaced n/s top front park light.	585377
143	01/28/2022	1025316	LAMP INDICATOR L94 (0478341 SC)		585377
143	01/28/2022	1025316	Elec and Light Exterior Lights - drivers side indicator -	replace rear break light replace front indicator lighta and replace front top front park light. complete	585377

143	01/28/2022	1025316	Elec and Light	Exterior Lights - drivers side indicator -	Replace 2x park-light globes. O/S from indicator light had a corroded plug and socket socket was replaced but there is no plug available currently. Managed to get light using conductive grease on connection.	585377
143	01/28/2022	1025316	Consumables			585377
143	01/05/2022	1020997		VEHICLE SAFETY INSPECTION Carried out vehicle safety inspection as per checklist. ok.		585377
143	01/05/2022	1020997		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Tensioned all wheel nuts to OEM specifications. ok.		585377
143	01/05/2022	1020997				585377
143	12/23/2021	1017048	FOAM TAPE 4MM X 22MM	P/M	Creditor # :GB-EAS002 EASTCOAST TRUCK & BUS SERVICE P/O # :G313321 Receiving # :328598 Date :2021-12-23	585377
143	12/22/2021	1017048	FOAM TAPE 4MM X 22MM	P/M		585377
143	12/10/2021	1017048	PERFORM CAMPAIGN 20/20 PRE SUMMER PREVENTATIVE MAINTENANCE C			584595
143	12/10/2021	1017048	CLAW CATCH & ANGLE			584595
143	12/10/2021	1017048	HOSE G/BOX COOLING 160 DEG 1 7		Creditor # :GB-MUL001 MULTISPARES LTD P/O # :G312631 Receiving # :327778 Date :2021-12-10	584830
143	12/10/2021	1017048	HOSE G/BOX COOLING SCANIA L94		Creditor # :GB-MUL001 MULTISPARES LTD P/O # :G312631 Receiving # :327794 Date :2021-12-10 6617	584830
143	12/10/2021	1017048	PERFORM CAMPAIGN 20/20 PRE SUMMER PREVENTATIVE MAINTENANCE C		Replace G.box cooling hoses	584595
143	12/09/2021	1017055	Drv entered - Elec and Light - Indicators Not Working		Checked all indicators - working correctly. Auditor not working in dash will need repairing or replacing if nessacary.	584595
143	12/09/2021	1017055	Drv entered - Elec and Light - Indicators Not Working		All exterior indicator lights working. No noise from indicator buzzer in dash. Will need further inspection.	584595
143	12/09/2021	1017055	Consumables			584595
143	12/09/2021	1017048	FOAM TAPE 4MM X 22MM	P/M	removed intercooler and cleaned replaced all foam tape and re fitted intercooler	584595
143	12/09/2021	1017048	PERFORM CAMPAIGN 20/20 PRE SUMMER PREVENTATIVE MAINTENANCE C		Check lights and changed o/s/f indicator light	584595
143	12/08/2021	1016674	Mechanic entered - Elec and Light Exterior Lights			584595
143	12/08/2021	1016674	Consumables			584595
143	12/01/2021	1015187	Elec and Light	Flat Batteries LOAD TEST BATTERIES	TESTED BATTERIES ALL OK	584247
143	12/01/2021	1015188	Elec and Light Front	Indicators Not Working	CHECKED INDICATORS ALL WORKING	584247
143	12/01/2021	1015187	Consumables			584247
143	12/01/2021	1015188	Consumables			584247
143	11/29/2021	1014618	Mechanic entered - Elec and Light Flat Batteries		Attempted to jump start bus this morning as master switch had been left on by the cleaners over the weekend couldn't jump start so put batteries on charge through the day started bus in afternoon in time for school run tested batteries charging at 27.1V all ok. Will need to be booked back for a load test on a later date	584130
143	11/29/2021	1014618	Consumables			584130
143	11/23/2021	1012722			CARRY OUT A/C - B SERVICE AS PER CHECK LIST Service rear unit as per list replaced right bank evaporator fan brushes	583560
143	11/23/2021	1012722	BRUSHES MOTOR EVAPORATOR CONDENSOR			583560
143	11/19/2021	1012722	OIL COMPRESSOR OIL AIR CONDITIONING			583365
143	11/19/2021	1012722	BRUSH EMP AIR CON			583365
143	11/19/2021	1012722	AIR CON REFRIDGERANT			583365
143	11/19/2021	1012722			CARRY OUT A/C - A SERVICE AS PER CHECK LIST Service front unit Front unit only Service as per list replaced condenser fan brushes replaced oil not drier none in stock locate and repair refrigerant leak top up refrigerant job not completed carry over	583365
143	10/18/2021	1006185	Fluid Leaks - Coolant leak requires attention		Rectify coolant leaks found defective hose clamp. Replaced clamp drive tested and checked	581364
143	10/14/2021	1004925	DIRECT PURCHASE - BUS INSPECTI		Creditor # :GB-ROA001 ROAD SAFETY INSPECTIONS P/O # :G308694 Receiving # :323751 Date :2021-10-15	581364
143	10/12/2021	1004925			VEHICLE SAFETY INSPECTION	581044
143	10/12/2021	1004925			TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	581044
143	10/12/2021	1004925			ANNUAL SAFETY INSPECTION - RWC 038926 - PASSED - 12/10/2021 - WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25	581044
143	10/12/2021	1004925			Assisting	581044
143	10/11/2021	1004763	Carry out final inspection for RSI		Carried out final inspection on 143 steam cleaned whole busn for rsi replaced turbo wastegate hose as well.	580834
143	10/11/2021	1004763	Carry out final inspection for RSI		carried out final inspection and steam cleaned bus	580834
143	10/11/2021	1004763	Consumables			580509
143	10/06/2021	1002684	Mechanic entered - Suspension Other O/S/R lower torque rod b		Same job from yesterday carried over. Completed	580509
143	10/05/2021	1002684	Mechanic entered - Suspension Other O/S/R lower torque rod b		Picked up new body side torque rod bolts from scania replaced the torque rod bolts with Ben.	580509
143	10/05/2021	1002684	BOLT RR LWR TORQUE ROD SCANIA		Creditor # :GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O # :G308220 Receiving # :322973 Date :2021-10-05	580509
143	10/04/2021	1002686	Mechanic entered - Suspension - Noisy O/S/R Sway bar link ru		Job completed by Zubs	580509
143	10/04/2021	1002684	Mechanic entered - Suspension Other O/S/R lower torque rod b		Replaced diff side torque rod bolts with Ben the body side ones were not correct the ones supplied are too short spoke to lee to order right lenght ones.	580509
143	10/04/2021	1002684	Mechanic entered - Suspension Other O/S/R lower torque rod b		replaced o/s diff side bolts awaiting longer blts for the other side	580509
143	10/04/2021	1002685	Mechanic entered - Engine - O/S/R Engine mount torn rep		Lifted up body and supported with jack stands removed mount bolts and nuts lifted engine with soft block of wood and jack removed torn engine mounts cleaned all parts and fit studs to the new mounts fit the new engine mounts and tensioned all nut bolts to 47nm with Ben. Started engine mounts work well.	580509
143	10/04/2021	1002685	Mechanic entered - Engine Other O/S/R Engine mount torn rep		removed old engine mounts pulled out studs and fitted to new engine mount with lock tight and installed new mounts and tensioned nuts and bolts to 47NM	580509
143	10/01/2021	1002684	Mechanic entered - Suspension - O/S/R lower torque rod b		Fit the new torque rod back with the old bolts so it can go on its school run Monday when it returns we will have the new bolts and will replace bolts.	580251
143	10/01/2021	1002684	NUT M18 RR LWR TORQUE ROAD SCANIA L94UAB			580251
143	10/01/2021	1002684	Mechanic entered - Suspension Other O/S/R lower torque rod b		carried out removing old torque rod and fitting new one with old bolts new bolts on order waiting on parts	580251
143	10/01/2021	1002686	Mechanic entered - Suspension Noisy O/S/R Sway bar link rust		carried out removing and replacing new sway bar link and nut and new split pin.	580251
143	10/01/2021	1002684	BOLT RR LWR TORQUE ROD SCANIA		Creditor # :GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O # :G308106 Receiving # :322879 Date :2021-10-04	580509
143	10/01/2021	1002684	SPACER RR LWR TORQUE ROD BOLT		Creditor # :GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O # :G308106 Receiving # :322879 Date :2021-10-04	580509
143	10/01/2021	1002684	NUT M18 RR LWR TORQUE ROAD SCA		Creditor # :GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O # :G308106 Receiving # :322879 Date :2021-10-04	580509
143	10/01/2021	1002714	Mechanic entered - Elec and Light Interior Lights x2 saloon		assissted rowdy all working now	580251
143	10/01/2021	1002714	Mechanic entered - Elec and Light Interior Lights x2 saloon		I replaced the new inverter that was installed with the old one because the outputs for the lights are on the opposite side to the power inputs. Fuse for step lights was blown so replaced that as well. All interior saloon and step lights working properly now.	580251
143	10/01/2021	1002891	Mechanic entered - Dash - Dash Lights Not Working x7 switch		Replaced all switch globes all lights now working	580251
143	10/01/2021	1002714	Consumables			580251
143	10/01/2021	1002891	Consumables			580251
143	10/01/2021	1002907	Mechanic entered - Body - N button gear selector missing		Removed gear selector fromm dash removed whasts left of the N button in the selector found a second hand button and fitted to the selector for 143 fit back to dash buttons all working.	580251
143	10/01/2021	1002908	Mechanic entered - Body - x1 Grab handle bracket missing		Can't get the brackets anymore that old the grab handle in place removed grab handle.	580251
143	10/01/2021	1002909	Mechanic entered - Body - Front bumper exit sticker worn		Replaced front exit bumper sticker.	580251
143	10/01/2021	1002907	Consumables			580251
143	10/01/2021	1002908	Consumables			580251
143	10/01/2021	1002909	Consumables			580251
143	09/30/2021	1002611			VEHICLE SAFETY INSPECTION Carried out Safety and pre RSI together as per checklist with Zubs reported / repaired any found defects.	580251
143	09/30/2021	1002611			TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Tensioned all wheel nuts with Ben	580251
143	09/30/2021	1002610			PRE ANNUAL SAFETY INSPECTION CHECK Carried out Pre rsi and Safety inspection at same time reported / repaired any found defects.	580251
143	09/30/2021	1002610			CARRY OUT CCTV - B SERVICE AS PER CHECK LIST Zubs completed CCTV	580251
143	09/30/2021	1002610			carried out rsi inspection scramble as per check list and carried out fitting new saloon light lens .	580251
143	09/30/2021	1002686	LINK RR SWAY BAR D AXLE SCANIA		Creditor # :GB-MUL001 MULTISPARES LTD P/O # :G308012 Receiving # :322805 Date :2021-09-30	580251
143	09/30/2021	1002684	TORQUE ROD RR LWR D/AXLE SCANI		Creditor # :GB-MUL001 MULTISPARES LTD P/O # :G308012 Receiving # :322805 Date :2021-09-30	580251
143	09/30/2021	1002644	FILTER ZF ECOMAT GEARBOX 1193281 E39HD119			580251
143	09/30/2021	1002644	Mechanic entered - Gearbox Driveline Other Replace gearbox o		Just as a pre causion becuase at one point there was coolant in the oil drained oil and replaced filter for the transmission. Topped up fresh 15L and checked after running good.	580251
143	09/30/2021	1002644	OIL AUTOMATIC MOBIL ATF MULTIPURPOSE(TEXAMATIC)			580251
143	09/30/2021	1002685	MOUNT ENGINE FRT SCANIA 147586			580251
143	09/30/2021	1002714	Consumables		Creditor # :GB-MUL001 MULTISPARES LTD P/O # :G308012 Receiving # :322805 Date :2021-09-30	580251
143	09/30/2021	1002714	INVERTER 15-58W 24V T8 (49V2706)			580251
143	09/16/2021	1000053				580251
143	09/10/2021	998829	Drv entered - Fluid Leaks Rear of bus		cleaned transmission where leak was road tested bus engine temp was at runningtemp found no leakage anywhere	579980
143	09/07/2021	997876	*CHANGE PLUG NEXT GEAR BOX SERVICE *- Mechanic entered - Gea		checked for fluid leaksfound milky oil in trans filler cleaned filler topped up coolant and trans oil road tested ok.	579759
143	09/07/2021	996987	Mechanic entered - Fluid Leaks - Rear of bus Spinner filter		Accidently put coolant into gearbox drained out oil / coolant from box and strained through fresh oil topped up another 15 litres of new texamatic took for another road test driving fine and checked oil when returned looks a lot cleaner on the dipstick.	579759
143	09/07/2021	996987	Mechanic entered - Fluid Leaks - Rear of bus Spinner filter		Removed spinner filter removed spinner housing from the sump had to remove A/C belts to get it out cleaned the top of the engine fit new gasket and the spinner housing back fit A/C belts back took bus to wash bay and cleaned more took for road test no more weeping from spinner gasket.	579759
143	09/07/2021	996987	Mechanic entered - Fluid Leaks - Rear of bus Spinner filter		Same notes as below.	579759
143	09/07/2021	996988	Mechanic entered - Fluid Leaks - Rear of bus Diff input seal		Cleaned the back of the diff fit the new seal in by hand as far as it goes heat up the yoke in the hot wash fit the yoke back to the diff and tensioned the lock nuts to 1000nm punched the locking tabs in. Fit tailshaft back and tensioned all bolts to 105nm. Took bus for road test Then back to the pit checked for leaks no more i	579759
143	09/07/2021	996989	Mechanic entered - Fluid Leaks Rear of bus Transmission outp		With other jobs complete took bus for the road test returned to depot no more leaking from output shaft seal. Tensioned tailshaft bolts to 105nm.	579759
143	09/07/2021	997875	Fluid Leaks (None) Coolant Leaking		Checked over engine bay and bus can not find any coolant leaks.	579759
143	09/06/2021	996988	Mechanic entered - Fluid Leaks - Rear of bus Diff input seal		Removed the diff nut and yoke with scania tool removed the old seal	579759
143	09/06/2021	996989	Mechanic entered - Fluid Leaks - Rear of bus Transmission ou		Lifted up bus on hoist removed tailshaft removed yoke with scania puller removed old seal cleaned the back of the transmission of oil fitted the new seal with the correct zf tools fit the yoke back and tensioned the two bolts for it to 85nm.	579759
143	09/06/2021	996989	Mechanic entered - Fluid Leaks - Rear of bus Transmission ou		removed and fitted new transmission output shaft seal	579759
143	09/06/2021	996907	Consumables			579759
143	09/06/2021	996907	Consumables			579759
143	09/06/2021	996907	Consumables			579759

143	09/06/2021	996907	Consumables		579759
143	09/06/2021	996907		Continued the Transmission service part of the B service removed the rounded out drain plug and changed the oil.	579759
143	09/03/2021	996987	GASKET SPINNER HSG MTG SCANIA	Creditor #:GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G306296 Receiving #:320876 Date :2021-09-06	579759
143	09/03/2021	996987	GASKET SPINNER HSG - ADAPTOR S	Creditor #:GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G306296 Receiving #:320876 Date :2021-09-06	579759
143	09/03/2021	996989	SEAL GEARBOX OUTPUT SHAFT ZF 4HP500 5HP500 49D8505		579759
143	09/03/2021	996989	LOCK TAB OUTPUT FLANGE ZF 4HP500 5HP500 49D8525		579759
143	09/03/2021	996988	SEAL DIFF PINION SCANIA R660 1	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G306268 Receiving #:320792 Date :2021-09-03	579759
143	09/03/2021	996988	NUT DIFF PINION SCANIA R660 15	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G306268 Receiving #:320792 Date :2021-09-03	579759
143	09/03/2021	996952	PERFORM CAMPAIGN 17/21 QR CODE DECAL FITMENT TO ALL BUSES	completed.	579759
143	09/03/2021	996952	PERFORM CAMPAIGN 17/21 QR CODE DECAL FITMENT TO ALL BUSES	completed.	579759
143	09/03/2021	996907	FILTER ZF ECOMAT GEARBOX 1193281 E39HD119		579759
143	09/03/2021	996907	FILTER FUEL FILTER SCANIA SR4 (1372444)		579759
143	09/03/2021	996907	FILTER OIL SCANIA S4 & K		579759
143	09/03/2021	996907	O-RING LARGE SPINNER FILTER SCANIA 40A7703		579759
143	09/03/2021	996907	OIL AUTO TRANSMISSION MOBIL MULTIPURPOSE ATF		579759
143	09/03/2021	996907	OIL ENGINE MOBIL DELVAC MODERN 15W-40		579759
143	09/03/2021	996907	SPINNER FILTER OIL INSERT PAPER SCANIA L94		579759
143	09/03/2021	996907	DRAIN PLUG M22 X 1.5 ECOMAT ZF	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G306268 Receiving #:320794 Date :2021-09-03	579759
143	09/03/2021	996907		CARRY OUT B SERVICE AS PER CHECK LIST Carried out B service this bus has transmission leaks will complete the service once new seal is fitted.	579759
143	09/03/2021	996907		carried out b service with Matt leaks from transmission will complete service once seal is replaced	579759
143	09/03/2021	996907	O-RING SPINNER FILTER SCANIA(4	Creditor #:GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G306296 Receiving #:320785 Date :2021-09-03	579759
143	09/02/2021	996557		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST Fire safety inspection complete. Battery terminal was sitting high off the battery post so re-secured it.	579759
143	09/02/2021	996557		Inspection complete.	579759
143	09/02/2021	996557		fixed.	579759
143	09/02/2021	996557			579759
143	09/01/2021	988285	BRAKE CALIPER SCANIA L94UAB LH	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G303712 Receiving #:322597 Date :2021-09-29	580251
143	09/01/2021	988285	BRAKE CALIPER SCANIA L94UAB RH	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G303712 Receiving #:322597 Date :2021-09-29	580251
143	08/26/2021	994836		Assist	579414
143	08/26/2021	994836		re-tensioned nuts on wheels 3; 4; 5; 6; 7; 8; 9 and 10 with indika.	579414
143	08/26/2021	994758	Mechanic entered - Wheels and Tyres Wheel Nut Retension all	Retorque middle axle wheel nuts - Job completed	579414
143	08/26/2021	994758	Consumables		579414
143	08/25/2021	994642	HARNESSE BRAKE PAD WEAR SENSOR	Creditor #:GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G305584 Receiving #:320016 Date :2021-08-25	579414
143	08/25/2021	994642	Drv entered - Brakes Warning Light On	Put the bus on the pit wheel wear sensor light on checked all brake sensor to chassis plugs and cleaned with contact clean light still on tested front and drive axle wear sensors with test one still light on lifted up tag axle and removed all wheels found N/S/T wear sensor wires were broken and found O/S/T wear sensor chas	579414
143	08/25/2021	994642	WEAR SENSOR KIT BLOCK TYPE-AXLE SET SCANIA 1794440		579414
143	08/20/2021	992808	Bus at moorabbin and repairing by moorabbin mechanic under	from w/o #989769 job completed by moorabbin go to w/o 989769 for the parts and 990884 for the repair	579209
143	08/19/2021	993214	Mechanic entered - Wheels and Tyres Worn os inner tyre flat	replace second hand runnerout tyre 275 / 80 / 22.5R rethread	579209
143	08/19/2021	993214	Consumables		579209
143	08/19/2021	992974	Mechanic entered - Elec and Light Other brake pads wear lig	repair os brake wear pad cencer [burnt down wire] put all the wheels and road test ok wheel nut retention done middle axle	579209
143	08/19/2021	992974	Consumables		579209
143	08/18/2021	992974	Mechanic entered - Elec and Light Other brake pads wear lig	repair broken sencer wire ns middle axle solderring and insulated	579209
143	08/18/2021	989769	Bus at moorabbin and repairing by moorabbin mechanic under	go to w/o #992808 as this one closed by accident	579209
143	08/18/2021	990884	Mechanic entered - Brakes Other overhaul middle axle brakes	suply and fit ns brake caliper fit all the brake pads adjust brake ok repair air leak etc	579209
143	08/17/2021	989769	CALIPER BRAKE LH TAG AXLE SCAN	Creditor #:GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G304093 Receiving #:319379 Date :2021-08-17	579209
143	08/17/2021	989769	LOCK WASHER TAG AXLE HUB SCANIA L94UAB		579209
143	08/12/2021	990884	Mechanic entered - Brakes Other overhaul middle axle brakes	fit x2 hubs and disc retention according to manufacture meserment os middle axle new caliper with old cridle refit it	579209
143	08/11/2021	990884	Mechanic entered - Brakes Other overhaul middle axle brakes	change the n/s brake booster change one air line and fittings fitted and secure the abs sensor tighten the n/s hub nuts as per the specs	579209
143	08/11/2021	990884	Mechanic entered - Brakes Other overhaul middle axle brakes	remove and refit new brake cham ber os rear middle axle re position brae cham ber too	579209
143	08/11/2021	990884	NEW AIR HOSE	Creditor #:MT-ENZSER ENZED MOORABBIN P/O #:M304685 Receiving #:319058 Date :2021-08-12 AIR HOSE 1M	579209
143	08/10/2021	990884	Mechanic entered - Brakes Other overhaul middle axle brakes	remove brake disc os fit new disc grease hub and fitted	579209
143	08/10/2021	990884	Mechanic entered - Brakes Other overhaul middle axle brakes	regrease the both n/s bearings fitted the hub seal on n/s fitted the hub and tighten the inner nut	579209
143	08/09/2021	990884	Mechanic entered - Brakes Other overhaul middle axle brakes	remove the hub seals clean the hubs clean the bearings clean the stub axles	579209
143	08/09/2021	989242	Bus at moorabbin and repairing by moorabbin mechanic under	Repairs to be completed at Moorabbin workshop.	579209
143	08/09/2021	989769	SENSOR ABS RH FRT / TAG AXLE S	Creditor #:GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G304361 Receiving #:318793 Date :2021-08-10	579209
143	08/04/2021	989769	BRAKE PAD SET SCANIA MERC BENZ 0500LE		579209
143	08/04/2021	989769	BRAKE BOOSTER RR TYPE 24/30 16MM PORTS SCANIA		579209
143	08/04/2021	989769	WEAR SENSOR KIT BLOCK TYPE-AXLE SET SCANIA 1794440		579209
143	08/04/2021	989769	SEAL HUB TAG AXLE SCANIA L94UAB		579209
143	08/04/2021	989769	LOCK WASHER TAG AXLE HUB SCANIA L94UAB		579209
143	08/03/2021	989769	CABLE ABS SENSOR TAG AXLE RH S	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G303995 Receiving #:318457 Date :2021-08-04	579209
143	08/03/2021	989769	CALIPER BRAKE RH TAG AXLE SCAN	Creditor #:GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G304093 Receiving #:318456 Date :2021-08-04	579209
143	08/03/2021	989769	GASKET HUB COVER TAG AXLE SCAN	Creditor #:GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G304093 Receiving #:318456 Date :2021-08-04	579209
143	08/03/2021	989769	BRAKE DISC TAG AXLE SCANIA L94	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G303995 Receiving #:318457 Date :2021-08-04	579209
143	08/03/2021	991930	Completed by ATS	CARRY OUT FIRE EXTINGUISHER TEST & TAG	579209
143	08/02/2021	989242	Brakes - Smoke coming out from middle of bus from tyres.	removed wheels and found o/s brake calliper seized abs sensor damage and hub seal leaking refit wheel to secure next door. Take to other workshop and secure bus remove middle axle tyres and arrange parts required.	579209
143	07/29/2021	988285	Drv entered - Brakes - Foot Brakes Noisy	fitted new brake pads new boosters. fitted the wheels tensioned the wheel nuts with Nick. road tested and check brake temp and ok . brake tested ok	579112
143	07/29/2021	988285	SET DISC PAD SET SCANIA / MERCEDES 0500		579112
143	07/29/2021	988285	WEAR SENSOR KIT BLOCK TYPE-AXLE SET SCANIA 1794440		579112
143	07/29/2021	988285	Drv entered - Brakes - Foot Brakes Noisy	assisted Drive/brake tested.	579112
143	07/28/2021	988285	SEAL RR HUB INNER SCANIA K230U	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G303805 Receiving #:318044 Date :2021-07-29	579112
143	07/28/2021	988285	Drv entered - Brakes - Foot Brakes Noisy	removed booster brake pads caliper stub axle and disc/roter. Night shift to continue removed caliper brakes booster and hub	579112
143	07/28/2021	988285	Drv entered - Brakes - Foot Brakes Noisy	removed calipers hub boosters.	579112
143	07/28/2021	988285	Drv entered - Brakes Foot_Brakes Noisy	Assisted	579112
143	07/28/2021	988285	Drv entered - Brakes Foot_Brakes Noisy	removed and replaced both drive axel brake rotors and calipers. clean and inspect wheel bearing regrease and refitted the wheel hub. tensioned hub nuts rotors bolts and calipers bolts to spec. (C/O fit brake pads and boosters) Replaced all hub seals.	579112
143	07/28/2021	988285	BRAKE BOOSTER RR TYPE 24/30 16MM PORTS		579112
143	07/28/2021	988285	BRAKE DISC FRT SCANIA K230UB FR & RR K310 1858351 1402272		579112
143	07/28/2021	988285	SEAL RR HUB OUTER SCANIA K230U	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G303805 Receiving #:318044 Date :2021-07-29	579112
143	07/28/2021	988285	SEAL REAR AXLE CAP SCANIA 1765	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G303805 Receiving #:318044 Date :2021-07-29	579112
143	07/27/2021	988285	Drv entered - Brakes - Foot Brakes Noisy	remove drive axle wheels c/o need replace both rotors n/s caliper & check n/s booster.	578866
143	07/12/2021	984941	AIRBAG DRIVE & TAG AXLE	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G302598 Receiving #:316653 Date :2021-07-12	577840
143	07/12/2021	984941	Suspension - Air bag on trayler L/H front leaks	Replaced	577795
143	07/10/2021	984803		VEHICLE SAFETY INSPECTION	577795
143	07/10/2021	984803		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	577795
143	07/10/2021	984823	Elec and Light interior U/S	Replace tubes	577795
143	07/10/2021	984825	Elec and Light Emergency light out	Replace globes	577795
143	07/10/2021	984826	Mechanic entered - Elec and Light Exterior Lights front top	Replace globe	577795
143	07/10/2021	984823	Consumables		577795
143	07/10/2021	984825	Consumables		577795
143	07/10/2021	984826	Consumables		577795
143	07/08/2021	984186	Drv entered - A/C Heating - Demister Not Heating	Remove and replaced failed boost pump modify bracket to fit new bracket run up tested ok	577795
143	07/07/2021	984273		Tensioned wheel nuts pos 9 and 10.	577795
143	07/07/2021	984273		Assisted	577795
143	07/07/2021	984186	Drv entered - A/C Heating - Demister Not Heating	Started to look at demister fault job not completed carry over	577795
143	07/07/2021	984186	PUMP BOOST PUMP COACH 90 LTR		577795

143	07/06/2021	983987	Mechanic entered - Wheels and Tyres Flat or Leaking Pos 9.	Fitted 2nd hand tyres from store pos 9 and 10. Tensioned wheel nuts with Haysun.	577752
143	07/06/2021	983987	Consumables		577752
143	06/18/2021	980230	Steering - Steering wheel need replace		577057
143	06/18/2021	980230	Steering wheel need replace	replaced & road tested	577057
143	06/17/2021	980230	STEERING WHEEL SCANIA	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G301032 Receiving #:314979 Date :2021-06-17	576763
143	06/16/2021	980248	Mechanic entered - Wheels and Tyres - Wheel Nut Retension p		576763
143	06/16/2021	980248	Mechanic entered - Wheels and Tyres - Wheel Nut Retension po		576763
143	06/16/2021	980248	Consumables	tensioned pos 12 wheel s with Zube	576763
143	06/15/2021	978131	Ops Entered - Exhaust		576763
143	06/15/2021	978354	Body concertina need repair.	Fault was wheel wobble under break . driver entered DVR wrong. Cardinia checked repair front break under work order 978375	576763
143	06/15/2021	978354	Consumables	repaired consentina finish	576763
143	06/11/2021	978354	Body concertina need repair.	repaired and modified consentina [needs to finish]	576763
143	06/10/2021	978354	Body concertina need repair.	checked consentina Traveled to Rosebud to remove the parts from bus 13	576763
143	06/07/2021	978375	Drv entered - Steering - Shakes/ Wobbles	roadtested ok	576763
143	06/07/2021	978375	Drv entered - Steering - Shakes/ Wobbles	tensioned both front hub nuts and rotor bolts and wheel nuts	576763
143	06/04/2021	978375	Drv entered - Steering - Shakes/ Wobbles	Fitted new brake rotor and pads to RH front	576763
143	06/04/2021	978375	Drv entered - Steering - Shakes/ Wobbles	removed N/S front rotor and replaced and started reinstalling	576763
143	06/04/2021	978375	1889543 brake disc	Creditor #:CT-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:CT300388 Receiving #:314341 Date :2021-06-07	576763
143	06/04/2021	978375	2325213 disc pad set	Creditor #:CT-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:CT300388 Receiving #:314341 Date :2021-06-07	576763
143	06/04/2021	978375	1794440 wear sensor	Creditor #:CT-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:CT300388 Receiving #:314341 Date :2021-06-07	576763
143	06/04/2021	978376	Drv entered - Breakdown	Bus not break down and driver entered accidentally	576763
143	06/04/2021	978376	Consumables		576600
143	05/31/2021	975800	Drv entered - Steering - Shakes/ Wobbles		576600
143	05/31/2021	975800	Drv entered - Brakes - Foot Brakes Pulling		576255
143	05/27/2021	976927			575895
143	05/26/2021	975800	TYRE 275/70R22.5 NEW		575895
143	05/26/2021	975800	Drv entered - Steering Shakes/ Wobbles	Assisted Nick	575895
143	05/26/2021	975800	Drv entered - Steering - Shakes/ Wobbles	Fitted new front tyres. Tensioned wheel nuts with Haysun. (old tyre back to rack) Drive tested still minor steering wobbles under braking. (informed supervisor).	575895
143	05/26/2021	975800	Drv entered - Brakes - Foot Brakes Pulling	Inspect and adjust front brakes. Brake tested drive tested and checked found minor shacking under braking.	575549
143	05/21/2021	975800	Drv entered - Steering Shakes/ Wobbles		573501
143	05/21/2021	975800	Drv entered - Brakes Foot _Brakes Pulling	visial checked brake pads ok almost new checked brake discs and they are in good condition..checked both front tyres almost brand new.. checked steering components ok checked front suspension and kingpin ok.. road test and found nothing wrong went road test with driver again found when drive over km per hour an	572384
143	04/30/2021	962577	PERFORM CAMPAIGN 09/21 POSITIO	Creditor #:GB-EAS002 EASTCOAST TRUCK & BUS SERVICE P/O #:G298089 Receiving #:311606 Date :2021-05-03	572384
143	04/22/2021	969840	Drv entered - Elec and Light - Horn	Replace horn and check operation. Complete.	572384
143	04/22/2021	969840	HORN 24V 112MM		572384
143	04/22/2021	969840	Consumables		572384
143	04/22/2021	969895		retension pos 7-8 wheel nuts with Hasan.	572384
143	04/22/2021	969895		Assisting	571913
143	04/16/2021	968372	Mechanic entered - Engine - Belt tensioner pulley noise	Remove belt check all pooleys no fault found	571913
143	04/16/2021	968372	Mechanic entered - Air System - Air Leak Interior airleak in	Replace broome brake valve	571913
143	04/14/2021	968142		Assisting	571913
143	04/14/2021	968142		Retension pos 7-8	571913
143	04/13/2021	968372	VALVE EMERGENCY RELEASE SCAN	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G296724 Receiving #:310376 Date :2021-04-15	571913
143	04/12/2021	967542		VEHICLE SAFETY INSPECTION Completed VSI.	571913
143	04/12/2021	967542		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Tensioned all wheel nuts w/ Haysun.	571913
143	04/12/2021	967542		assisted	571913
143	04/12/2021	967543	Mechanic entered - Wheels and Tyres - Tyres pos. 7 and 8	Fitted run out tyres pos. 7 and 8 cleaned tyre rim and tensioned wheel nuts w/ Haysun.	571913
143	04/12/2021	967543	Consumables		571913
143	04/12/2021	967541	Mechanic entered - Engine - Belt tensioner pulley noise		571913
143	04/12/2021	967541	TENSIONER SR4 FLATBACK BELT 1859654 knx 1503113	removed and replaced belt tensioner pulley	571398
143	04/12/2021	967344			571398
143	03/30/2021	964395	Mechanic entered - Elec and Light - Flat Batteries	CARRY OUT CCTV - A SERVICE AS PER CHECK LIST complete.	571230
143	03/30/2021	964395	Consumables	carried out load testing both batteries good.	571230
143	03/29/2021	964395	Mechanic entered - Elec and Light - Flat Batteries		571230
143	03/26/2021	964233		carried out jump starting bus at 6:31 and put sticker not to turn bus off until 10:31	571230
143	03/26/2021	964233		Tensioned wheel nuts w/ Rene pos. 1 and 2.	571230
143	03/26/2021	964233		Assisted Abraham.	571230
143	03/26/2021	963846	BusMinder No Power intermittent fault on the 2amp side po	Removed UDB socket found that the negative lead had been badly crimped resulting with wire falling out of terminal. Re-crimped both positive and negative terminals and re-installed USB socket. Complete.	571230
143	03/26/2021	963846	Consumables		571230
143	03/26/2021	964132	PERFORM CAMPAIGN 10/21 FITMENT OF AUTHORISED OPERATOR DECAL	Complete	571103
143	03/25/2021	963509	Brakes - O/S front calipar faulty.	R/R f/o/s brake caliper. Fitted new front brake pads and adjust the brake. Drive tested/brake tested and checked all ok.	571103
143	03/25/2021	963509	SET DISC PAD SET SCANIA / MERCEDES 0500		571103
143	03/25/2021	963509	Brakes - O/S front calipar faulty.	Assisted.	571103
143	03/24/2021	963226	Place new poster over the top attach hangers to hand rails	Completed by refuellers as per email	570796
143	03/23/2021	962844		Tensioned wheel nuts pos 1 and 2.	570796
143	03/23/2021	962844		Assisted.	571230
143	03/23/2021	963509	BRAKE CALIPER SCANIA L94 LHR	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G295603 Receiving #:309053 Date :2021-03-26	570796
143	03/23/2021	962577	PERFORM CAMPAIGN 09/21 POSITIONING OF 2021 PTV FARES & COVI	Done by Miguel	570639
143	03/22/2021	962354		TRANSMISSION CHECK AS PER CHECK LIST	570639
143	03/22/2021	962475	Drv entered - Steering - Shakes/ Wobbles	Checked front wheels found wrong tyre thread pattern. R/R fronts tyres and tensioned wheel nuts. Drive tested ok. (old tyre back to rack)	570639
143	03/22/2021	962475	TYRE 275/70R22.5 NEW		570639
143	03/22/2021	962475	Drv entered - Steering - Shakes/ Wobbles	Assisted.	570639
143	03/22/2021	962474	Drv entered - Brakes - Park Brake Leaking Air	Checked found no leaks.	570341
143	03/18/2021	961446	Elec and Light - Park brake not working	wrong DVR ns tail light nw replaced globe bus ok.	570341
143	03/18/2021	961446	Consumables		568416
143	03/18/2021	961449	Body - Front door not opening.	checked and fixed front passanger door ramp	567584
143	02/28/2021	957672		CARRY OUT FIRE EXTINGUISHER TEST & TAG	567376
143	02/28/2021	957672		completed by ATS	566348
143	02/18/2021	955194	Consumables		565661
143	02/18/2021	955194	Ops Entered - Fault - Elec and Light Flat Batteries - Route	jump started. (master sw. left on).	565661
143	02/16/2021	954581	Leave old poster in and fit you must wear a maskover the	Fitted by Refuellers	565661
143	02/03/2021	951073	Keep ol poster in holder and place Travel off Peak and Sav	Done by Refuellers	565661
143	01/20/2021	945894	Consumables		565661
143	01/20/2021	945894	Mechanic entered - Elec and Light Interior Lights Drivers li	R/r drivers light globe.Test works ok.	565661
143	01/20/2021	945894	GLOBE STEP LIGHT 24V 20W DOWNLIGHT (DICHROIC)		565661
143	01/18/2021	947419	Please fit A3 poster over COVID-19 poster and hangers to be		565661
143	01/11/2021	945870		Fitted completed.	565661
143	01/11/2021	945870		VEHICLE SAFETY INSPECTION Completed check list.	565661
143	01/11/2021	945870		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Done with Tayla.	565661
143	01/11/2021	945873	Mechanic entered - A/C Heating Other A/c bracket bolt loose.		565661
143	01/11/2021	945876	Consumables	Retightened bolts secured.	565661
143	01/11/2021	945895	Consumables		565661
143	01/11/2021	945876	Mechanic entered - Elec and Light Exterior Lights Park light	R/r globe.	565661
143	01/11/2021	945895	Mechanic entered - Elec and Light Interior Lights Emergency	Fitted lens Took lens from scrap bus.	565661
143	01/11/2021	945894	Mechanic entered - Elec and Light Interior Lights Drivers li	Remove LED globe for order no stock Reported to Kumar parts order to Lee. Carry over.	565661

143	01/11/2021	945892	Removed N/S/F window COVID-19 & MYKI decals and reposi	Decals have been repositioned	565661
143	11/26/2020	936981	PERFORM CAMPAIGN 27/20 UPDATED INTERNAL BUS NUMBER DECALS	completed.	564168
143	11/17/2020	933835	PERFORM CAMPAIGN 26/20 REAR EXIT DECAL MAKE YOUR MARK & SER	completed.	563205
143	11/16/2020	933299	Remove old poster and fit you must wear a face mask when t	Replaced by Refuellers	562787
143	11/13/2020	932660		Finish off A service rear unit	562787
143	11/12/2020	932660	COMPUTER SLRT/RM-RP (2 DEG O/S)		562787
143	11/12/2020	932660			562787
143	11/04/2020	930670	Fit new Myki Decals & refit COVID-19 decals new position fo	completed.	562161
143	10/29/2020	929316	Warning Lights - Engine - STOP Warning Light on Dash Engine		561921
143	10/29/2020	929316	Warning Lights - Engine - STOP Warning Light on Dash Engine		561921
143	10/29/2020	929316	HOSE COOLING SCANIA L94UAB		561921
143	10/28/2020	929316	Warning Lights Engine STOP Warning Light on Dash Engine		561921
143	10/28/2020	929316	Warning Lights Engine STOP Warning Light on Dash Engine		561921
143	10/28/2020	929316	Warning Lights Engine STOP Warning Light on Dash Engine		561921
143	10/16/2020	926985	Ops Entered - Warning Lights - Engine - Route: - Take a A	couldnt start bus so jump started and bleed fuel system found turntable jack light on not engine light inform Dulkie and deleted fault code..	560880
143	10/15/2020	925819	DIRECT PURCHASE - BUS INSPECTI	Creditor #:GB-ROA001 ROAD SAFETY INSPECTIONS P/O #:G285460 Receiving #:298941 Date :2020-10-30	561921
143	10/13/2020	925819		VEHICLE SAFETY INSPECTION	560591
143	10/13/2020	925819		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	560591
143	10/13/2020	925819		Assisting	560591
143	10/13/2020	925819		ANNUAL SAFETY INSPECTION - RWC 023319 - PASSED - 13/10/2020 - WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLESAFETY INSPECTION LINE TIME ON THE W/O TO 0.25	560591
143	10/12/2020	925655	Body Water Leaks Windows carry out final check for RSI	Final inspection completed. changed some stickers O/R clearance light rubber secure wire under constanttinotested the brake	560591
143	10/12/2020	925655	Body Water Leaks Windows carry out final check for RSI	Final inspection completed. changed some stickers O/R clearance light rubber secure wire under constanttinotested the brake	560591
143	10/12/2020	925655	DECAL PLEASE KEEP CLEAR DOOR OPENS INWARDS		560591
143	10/12/2020	925655	Body Water Leaks Windows carry out final check for RSI		560591
143	10/12/2020	925655	Body Water Leaks Windows carry out final check for RSI	Final inspection completed. changed some stickers O/R clearance light rubber secure wire under constanttinotested the brake	560591
143	10/12/2020	925655	Consumables	Assisted Sisil	560591
143	10/08/2020	924946			560224
143	10/08/2020	925123	PERFORM CAMPAIGN 20/20 VEHICLE TOLLWAY ETAG FITMENT	CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST completed	560224
143	10/01/2020	923339	Mechanic entered - Body Other Inspection.	assist indika plus check tyres pressures etc.	560224
143	10/01/2020	923339	Mechanic entered - Body Other Inspection.	Checked Engine Bay and top up E/oil Checked Under chassis.pumped up tyre tyer pressure.	560224
143	10/01/2020	923339	Consumables		560224
143	09/30/2020	923110	Mechanic entered - A/C Heating Not Cooling Pretrip inspectio	Carry out pretrip inspection	560224
143	09/24/2020	921542	Mechanic entered - Body - Rear door inner decal torn.		560224
143	09/24/2020	921542	Mechanic entered - Body Other rear door inner decal torn.	new decal fitted.	560224
143	09/23/2020	921544	Mechanic entered - Engine - ALT drive belt damaged.	fitted new drive belt.	560224
143	09/23/2020	921546	Mechanic entered - Engine - Engine rear start box damaged.	repair with new panel.	560224
143	09/23/2020	921544	BELT MICRO V SERPENTINE BELT 8 RIB 2595mm LONG		560224
143	09/23/2020	921535	Mechanic entered - Elec and Light - LHF lower indicator lens		560224
143	09/23/2020	921535	LAMP INDICATOR L94 (0478341 SC)	fitted new light unit.	560224
143	09/23/2020	921535	Consumables		560224
143	09/23/2020	921534	Mechanic entered - Body - RHS outer emergency decal torn.	fit new decal.	560224
143	09/23/2020	921536	Mechanic entered - Body - LHS inside emergency exit decal to	fit new decal.	560224
143	09/23/2020	921543	Mechanic entered - Body - Reposition L/H/R passenger bell pu	remove and refit bell push button.	560224
143	09/23/2020	921545	Mechanic entered - Body - Refit mid door emergency door butt	refit cover.	560224
143	09/23/2020	921542	DECAL PLEASE KEEP CLEAR DOOR OPENS INWARDS		560224
143	09/23/2020	921534	DECAL EMERGENCY EXIT ROCK RED / SILVER 600 x 80MM		560224
143	09/23/2020	921536	DECAL EMERGENCY EXIT (HAMMER)		560224
143	09/23/2020	921547	EDGE SENSITIVE EDGE DOOR SWITCH		560224
143	09/23/2020	921547	Mechanic entered - Body - Mid door sensitive edge not workin	fitted new bircher switch adjusted edge.	560224
143	09/23/2020	921548	Mechanic entered - Body - Secure L/H/R seat base.	secure seat base.	560224
143	09/23/2020	921549	Mechanic entered - Body - Mid door inner decal torn	fit new decal. fit new decal.	560224
143	09/22/2020	921461		PRE ANNUAL SAFETY INSPECTION CHECK completed.	560224
143	09/22/2020	921461		CARRY OUT CCTV - B SERVICE AS PER CHECK LIST	560224
143	09/22/2020	921461		PRE ANNUAL SAFETY INSPECTION CHECK assited alan with pre annual.	560224
143	09/22/2020	921461		CARRY OUT CCTV - B SERVICE AS PER CHECK LIST	560224
143	09/22/2020	921537	Mechanic entered - Body Other refit folding seat strut.	refit strut.	560224
143	09/22/2020	921539	Mechanic entered - Body Other rear L/H/S emergency sticker t	replaced emergency sticker.	560224
143	09/22/2020	921539	DECAL EMERGENCY EXIT (HAMMER)		560224
143	09/22/2020	921462	FILTER FUEL FILTER SCANIA SR4 (1372444)		560224
143	09/22/2020	921462	OIL AUTOMATIC TRANSMISSION OIL TEXAMATIC OR DEXRON (LU2)		560224
143	09/22/2020	921462	OIL ENGINE DELO 400 MGX SAE 15W-40 (MIN)		560224
143	09/22/2020	921462	FILTER ZF ECOMAT GEARBOX 1193281 E39HD119		560224
143	09/22/2020	921462		CARRY OUT B SERVICE AS PER CHECK LIST completed changed oil filter and gearbox oil and filter.	560224
143	09/22/2020	921462		CARRY OUT B SERVICE AS PER CHECK LIST completed.	560224
143	09/22/2020	921462	KIT O-RING OIL SPINNER FILTER SCANIA ABOVE ENG #6203050		560224
143	09/22/2020	921462	Oil Filter SCANIA S4 & K		560224
143	09/22/2020	921462	Consumables		560224
143	09/22/2020	921462	Consumables		560224
143	09/22/2020	921462	Consumables		560224
143	09/09/2020	918946	Fluid Leaks - Rear of bus	replaced 2 heater hoses steam cleaned checked for leaks after Ryan road test no more leak	559540
143	09/09/2020	918946	JOINER NYLON 16mm		559540
143	09/09/2020	918946	Fluid Leaks - Rear of bus		559540
143	09/07/2020	918498	Ops Entered - Fault - Fluid Leaks Rear of bus - Route: - A	Replaced 2 heater hosesdrain coolant and top uproad test to check coolant leak No Leak found and steam washed under engine	559288
143	09/02/2020	917620	Mechanic entered - Engine Belts Loose Noisy Missing A/C Belt	checked for coolant leaks. could not find any.	558889
143	09/02/2020	917620	BELT V-BELT COGGED TRI-POWER 17x1145mm	Replaced 2x BX42 belts.	558889
143	08/26/2020	916264		VEHICLE SAFETY INSPECTION Completed safety replaced A/C beltALT Beltadjusted idler postTop up 3L E/oil and &7L Coolant.	558723
143	08/26/2020	916264		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	558723
143	08/26/2020	916264	BELT A/C TWIN COMP SCANIA L94UAB		558723
143	08/26/2020	916264	BELT MICRO V SERPENTINE BELT 8 RIB 2595mm LONG		558723
143	08/26/2020	916360	Mechanic entered - Elec and Light Other Stop bell not workin	checked found broken wire under chasis.Repaired and re secured checked and ok.	558723
143	08/26/2020	916360	Consumables		558889
143	08/26/2020	916360	VALVE CLIPPARD DOOR OPEN/CLOSE (11916-2) BUTTON		558723
143	08/26/2020	916360	FITTING MALE ELBOW 6mm		558723
143	08/26/2020	916360	SILENCER DOOR VALVE SILENCER		558723
143	08/26/2020	916360	Mechanic entered - Air System Other Air leaking from around	found faulty valve block leaking at middle door so removed and replaced.	558723
143	08/25/2020	915183	DIRECT PURCHASE ACCIDENT #5084	Creditor #:GB-EAS002 EASTCOAST TRUCK & BUS SERVICE P/O #:G282310 Receiving #:294554 Date :2020-08-26	558723
143	08/24/2020	915682	Ops Entered - Fluid Leaks - Rear of bus - Route: - Arrive	carried out replacing coolant hose from trans cooler. and refilled and topped up coolant no leaks.	558254
143	08/24/2020	915682	HOSE G/BOX COOLING SCANIA L9	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G282269 Receiving #:294375 Date :2020-08-24	558254
143	08/20/2020	897285	LAMP SIDE MARKER (RED+AMBER)	Part used was a non stock item	558254
143	08/20/2020	897285	Consumables		558254
143	08/20/2020	915183	Accident #50840 - Front bumper damage - UDAF	Replaced front bumper middle by east coast	558254
143	08/20/2020	915183	*PHOTOS TAKEN* - Accident #50840 - Front bumper damage - UDAF	Sent bus to ECTB for repairs	558254
143	08/06/2020	912763	Completed by ATS	CARRY OUT FIRE EXTINGUISHER TEST & TAG	557689

143	08/02/2020	910487	Remove old A3 Poster and fit with You can no longer top up	Completed by Refuellers	557162
143	06/15/2020	900996	Drv entered - Steering Shakes/ Wobbles	road tested checked wheelsok checked brakes and discsok checked steering ball jointsoktie rod and drag link new.	555093
143	06/15/2020	900945	Mechanic entered - Elec and Light Other reverse buzzer not w	fit new reverse buzzer.	555093
143	06/15/2020	900945	BUZZER REVERSING 24V 102DB NR72602		555093
143	06/15/2020	900994	Ops Entered - Fault - Elec and Light Exterior Lights - Rout	fit new stop/ tail light globes . checked ok.	555093
143	06/15/2020	900945	Consumables		555093
143	06/15/2020	900994	Consumables		555093
143	06/15/2020	900995	Drv entered - Brakes Foot_Brakes Noisy	adjusted brakes road tested ok.	555093
143	06/12/2020	900529	Fit A3 Poster in poster frame and fit decals as requested i	Completed	554708
143	06/10/2020	899866	Engine Low Power	road tested It's normal	554708
143	06/10/2020	899866	Ops Entered - Fault - Elec and Light Flat Batteries - Route	not flat battery Started normally	554708
143	06/10/2020	899866	Consumables		554708
143	06/01/2020	897823		CARRY OUT CCTV - A SERVICE AS PER CHECK LIST completed the service.	554057
143	05/28/2020	896655		VEHICLE SAFETY INSPECTION	554057
143	05/28/2020	896655		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	554057
143	05/28/2020	896655			554057
143	05/28/2020	897285	Mechanic entered - Elec and Light Exterior Lights Rear n/s c	R/R clearance light.	554057
143	05/28/2020	897285	LAMP SIDE MARKER (RED+AMBER)		554057
143	05/28/2020	897285	Consumables		554057
143	05/28/2020	897287	Mechanic entered - Body Other Safety triangle broken.	Took 3 safety triangle from stock and fitted on bus.	554057
143	05/28/2020	896393	Breakdown	afternoon shift	554057
143	05/28/2020	896393	Breakdown	Continuing job only. Drive tested and checked ok.	554057
143	05/26/2020	896393	SOLENOID FUEL SHUT OFF SCANI	Creditor #:'GB-MUL001 MULTISPARES LTD P/O #:'G276160 Receiving #:'287664 Date :2020-05-26	554057
143	05/25/2020	896393	Breakdown	Attended b/down and assisted	554057
143	05/25/2020	896393	Breakdown	attened to braekdown faulty fuel system call tow truck check fuel valuepower need to check fuel value bus can start	554057
143	05/25/2020	896393	DIRECT PURCHASE - TOWING	Creditor #:'GB-EAG001 EAGLE TOWING & SALVAGE P/O #:'G276097 Receiving #:'287717 Date :2020-05-27 FROM / TO DANDENONG	554057
143	05/21/2020	895277	Check and repair brake light stay on and not moving when st	Repaire air leak on air water seperator and replace brake light relay - road tested OK	553709
143	05/21/2020	895277	FITTING STRAIGHT JOINER 12MM MDQ62DOT12		553709
143	05/21/2020	895277	RELAY VOLVO H/LIGHT DIODE PROTECTED		553709
143	05/20/2020	895277	Check and repair brake light stay on and not moving when st	Replace foot valve C/O job	553709
143	05/19/2020	895277	VALVE FOOTBRAKE C/W RET SWI	Creditor #:'GB-MUL001 MULTISPARES LTD P/O #:'G275713 Receiving #:'287132 Date :2020-05-20	553709
143	05/14/2020	894494	Elec and Light replace batteries	fitted new batteries n150	553709
143	05/14/2020	894494	BATTERY 1030CCA POS ON RHS		553709
143	05/14/2020	894494	Consumables		553709
143	04/29/2020	891161	Air System Air_Leak Rear; possibly governor release value	fitted new air drier govenor valve.	553010
143	04/29/2020	891161	AIR DRYER VALVE BLOCK SCANIA	Creditor #:'GB-MUL001 MULTISPARES LTD P/O #:'G274259 Receiving #:'285551 Date :2020-04-29	553010
143	04/27/2020	890800		Tensioned wheel nuts tyre pos 1 and 2 with Nick.	552590
143	04/27/2020	890800		Assisted	552590
143	04/24/2020	890336	Air leak reported and brake pulling right	Assisting	552590
143	04/24/2020	890336	Air leak reported and brake pulling right	Removed and fitted new front left caliper. Tightened all bolts to specs and tensioned wheel nuts with Abraham. Road tested and brake tested by Kuma.	552590
143	04/24/2020	890336	SAFETY VALVE 14.3 BAR SCANIA 40G0303		552590
143	04/24/2020	890336	BRAKE CALIPER OSR DRIVE AXLE &	Creditor #:'GB-MUL001 MULTISPARES LTD P/O #:'G273978 Receiving #:'285275 Date :2020-04-27	552590
143	04/16/2020	884977	REPLACE ANTI GRAFITTI FILM	Creditor #:'GB-GLA010 GLASSPROTECH MELBOURNE P/O #:'G272182 Receiving #:'284597 Date :2020-04-17 REPLACE MODESTY	552227
143	04/16/2020	888733	Ops Entered - Fault - Brakes Foot_Brakes Pulling - Route:	checked all steering components ok did brake test ok.. road test and found steering pull to the right checked again ok readjust brakes and found r/h brakes before l/h road test and check ok..	552227
143	04/14/2020	887917	A4 notification to be printed off in colour laminated and	Completed by Refuellers	552227
143	03/31/2020	885355	GLOBE 24V 75/70W H4		552227
143	03/31/2020	885355	Mechanic entered - Elec and Light Exterior Lights R/H side h	Fitted new headlight bulb o/s	552227
143	03/31/2020	885355	Consumables		552227
143	03/31/2020	885355	Consumables		552227
143	03/30/2020	885108		retension pos 1-2 wheel nuts with sadid.	552227
143	03/30/2020	884977	Vandalism - Replace anti graffiti film - MODESTY	Replaced by Glassprotech	552227
143	03/26/2020	884371		Tensioned wheel nuts w/ Kuma position 1 and 2	552227
143	03/26/2020	882829	SET DISC PAD SET SCANIA / MERCEDES 0500	done	552227
143	03/25/2020	882829	Brakes when applying brakes wheels started shaking		552227
143	03/25/2020	882829	SENSOR WEAR SENSOR KIT BLOCK TYPE-AXLE SET L94UB (1794440)		552227
143	03/25/2020	882829	SET DISC PAD SET SCANIA / MERCEDES 0500		552227
143	03/25/2020	882829	Brakes when applying brakes wheels started shaking	fit new front discs and brake pads. road tested ok.	552227
143	03/25/2020	882829	DISC PAD SET SCANIA 1856108	Creditor #:'GB-MUL001 MULTISPARES LTD P/O #:'G271865 Receiving #:'282939 Date :2020-03-26	552227
143	03/25/2020	883780	Tape off front Seats of All Route and Rail Buses with spec	Done	552227
143	03/24/2020	882829	Brakes when applying brakes wheels started shaking	Carry out wheel alignment by Big wheel	552227
143	03/24/2020	882829	Brakes when applying brakes wheels started shaking	road test fitted new wheels steering okdiscs faulty. remove wheels and secure bus.	552227
143	03/24/2020	882829	BRAKE DISC FRT SCANIA K230UB	Creditor #:'GB-MUL001 MULTISPARES LTD P/O #:'G271718 Receiving #:'282733 Date :2020-03-24	552227
143	03/24/2020	882829	CARRY OUT WHEEL ALIGNMENT	Creditor #:'GB-BIG010 BIG WHEELS TRUCK ALIGNMENT P/O #:'G271729 Receiving #:'282677 Date :2020-03-24	552227
143	03/24/2020	882829	TYRE 275/70R22.5 NEW	Creditor #:'GB-TYR002 TYRES4U P/O #:'G271716 Receiving #:'282722 Date :2020-03-24 GITI	552227
143	03/23/2020	881499	Mechanic entered - Steering Shakes/ Wobbles Steering Shakes/	Replaced Front D bushes.	552227
143	03/23/2020	882430	Remove old poster and fit Reduce Your Risk of Coronavirus	Completed by Refuellers	552227
143	03/20/2020	881499	BUSH FRT SWAY BAR SCANIA K23	Creditor #:'GB-MUL001 MULTISPARES LTD P/O #:'G271506 Receiving #:'282556 Date :2020-03-23	552227
143	03/20/2020	881499	Mechanic entered - Steering Shakes/ Wobbles Steering Shakes/	Removed Cliper & checked Rotor 44mm for warping 0.04mm.	552227
143	03/19/2020	881499	Mechanic entered - Steering Shakes/ Wobbles Steering Shakes/	Replaced front Tyres Still the same.	552227
143	03/19/2020	881499	TYRE 275/70R22.5 NEW		552227
143	03/06/2020	878995	Service	Retention wheel nuts pos 78 and 910 with Darcy	551527
143	03/04/2020	878541	SENSOR WEAR SENSOR KIT BLOCK TYPE-AXLE SET L94UB (1794440)		551098
143	03/04/2020	878541	Brakes R/H traylor brake were sensor broken	Replaced	551098
143	03/02/2020	878103		Retensioned all rear wheel nuts with Kuma.	550932
143	03/02/2020	878103		Retensioned all rear wheel nuts with Sadid.	550932
143	03/01/2020	877623	REPAIR SINGLE SEAT BASE	Creditor #:'GB-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:'G270001 Receiving #:'281314 Date :2020-03-04	551098
143	02/28/2020	877623		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	550391
143	02/28/2020	877623		VEHICLE SAFETY INSPECTION completed as per check list and tension wheel nuts with Darcy	550391
143	02/28/2020	877664	Mechanic entered - Elec and Light Exterior Lights OSR top br	Tayla and Elias repaired park light	550391
143	02/28/2020	877664	Consumables		550932
143	02/28/2020	877623	Mechanic entered - Body Passenger Seat Torn	Darcy replaced seat	550391
143	02/28/2020	877645	Mechanic entered - Brakes Other rear axle pads low	replaced rearf pads. Checked over by Howard	550391
143	02/28/2020	877645	SET DISC PAD SET SCANIA / MERCEDES 0500		550391
143	02/28/2020	877665	Mechanic entered - Brakes Other rear brakes low	replaced brakes with Zubs and Tayla	550391
143	02/19/2020	875266	A/C Heating - Not Cooling		549976
143	02/19/2020	875266	A/C Heating - Not Cooling	Run bus up found set point on front unit was set to 27c readjusted too 22 tested ok	549976
143	02/13/2020	876677	Completed by ATS	CARRY OUT FIRE EXTINGUISHER TEST & TAG	549595
143	01/31/2020	870764	Fault#:37296 - Ops Entered - Fault - Breakdown Overheating/C	checked hoses topup coolant wash engine checked all ok	548578
143	01/14/2020	867187	Mechanic entered - Elec and Light Flat Batteries	Jumpstartcheck battery and top up water	548244
143	01/14/2020	867187	Consumables		548244
143	01/09/2020	866063	PERFORM CAMPAIGN 01/20 POSITIONING OF 2020 PTV FARES & PRIOR	completed.	548244
143	12/13/2019	860649	Engine- Hard at starting	replaced hand primer pump assy	548018
143	12/13/2019	860649	Body Rear_Door Operation Faulty - not closing jack knife	fixed mid door and check articulation control unit road tested bus ok	548018

143	12/09/2019	860649	PUMP ASSY HAND PUMP SCANIA L94UAB	Creditor #::GB-MUL001 MULTISPARES LTD P/O #:G264350 Receiving #:274529 Date :2019-12-09	548018
143	12/09/2019	860649	RELAY FLASHER SCANIA L94 UAB		548018
143	12/09/2019	860649	Consumables		548018
143	12/09/2019	860095	REPLACE N/S REAR WINDOW	Creditor #::GB-ALP003 ALPHA BUS GLASS PTY LTD P/O #:G264260 Receiving #:274532 Date :2019-12-10	548018
143	12/06/2019	860095	Body - Windows Rear cracked		548018
143	12/06/2019	860095	Body - Windows Rear cracked		548018
143	12/05/2019	859061	DIRECT PURCHASE - BUS INSPECTI	Creditor #::GB-ROA001 ROAD SAFETY INSPECTIONS P/O #:G264015 Receiving #:275692 Date :2019-12-23 ANNUAL INSPECTION	548018
143	12/05/2019	828441	BOOST PUMP CO90 38MM PORTS		548018
143	12/05/2019	859144	Elec and Light- Hi beam warning light on dash n/w		548018
143	12/05/2019	859144	Consumables	replaced dash globe	548018
143	12/05/2019	859144	DECAL EMERGENCY EXIT HAMMER 190MM X 120MM		548018
143	12/05/2019	859144	Body- Replace rear emer exit decal		548018
143	12/05/2019	859144	Body- CENTRE DOOR SENSITIVE EDGE NEED TO ADJUST	replaced sticker adjusted door sensetive edge	548018
143	12/04/2019	859061			547830
143	12/04/2019	859061			547830
143	12/04/2019	859061		VEHICLE SAFETY INSPECTION TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS ANNUAL SAFETY INSPECTION - RWC 017514 - PASSED - 04/12/19WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLESAFETY INSPECTION LINE TIME ON THE W/O TO 0.25	547830
143	12/04/2019	859061			547830
143	12/04/2019	859061			547830
143	12/03/2019	858766	A3 Poster Frame Adhesive Decal Campaign please remove old	Completed by ECTB	547642
143	11/26/2019	849314	CCTV 6 month service	Completed by Johnny @ Bwere	547088
143	11/26/2019	849314	CCTV 6MONTHLY SERVICE	Creditor #::GB-BWE001 BWERE ELECTRICS PTY LTD P/O #:G263421 Receiving #:273812 Date :2019-11-29	547642
143	11/25/2019	854386	REBUILD FLOOR HATCH	Creditor #::GB-EAS002 EASTCOAST TRUCK & BUS SERVICE P/O #:G263227 Receiving #:273277 Date :2019-11-26	547088
143	11/20/2019	855782	completed with Pre RSI	VEHICLE SAFETY INSPECTION	546737
143	11/20/2019	855782		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	546737
143	11/19/2019	854386	Mechanic entered - Body Other 3 flow hatch need to repair	Repaired by ECTB	546479
143	11/19/2019	855099		Finish off B service too rear unit	546479
143	11/18/2019	854386	FLOOR HATCH SCREWS 13405 + 30628	CARRY OUT A/C - B SERVICE AS PER CHECK LIST Front unit Service as per list adjusted belts and tidy up wiring above compressor	546479
143	11/18/2019	854386	FLOOR HATCH SCREWS 13405 + 30628		546479
143	11/18/2019	854386	FLOOR HATCH SCREWS 13405 + 30628		546479
143	11/18/2019	855099	FILTER DRYER AIR COND 5/8 (3K171124)	CARRY OUT A/C - A SERVICE AS PER CHECK LIST Job not completed carry over	546479
143	11/18/2019	855099	OIL COMPRESSOR OIL AIR CONDITIONING		546479
143	11/18/2019	855099			546479
143	11/18/2019	855099	LAMP INDICATOR [ORANGE]	replaced cover and globe	546479
143	11/18/2019	855099			546479
143	11/15/2019	854810	COVER BUS STOPPING SIGN		546479
143	11/15/2019	854810	Mechanic entered - Elec and Light Next Stop Button bus stop	fitted NEW ONE	546479
143	11/15/2019	854810	Consumables		546479
143	11/15/2019	854834	CAP END CAP CENTRA SEAT END CAP		546479
143	11/15/2019	854834	Mechanic entered - Body Other Pas; seat side cap missing	replaced 12	546479
143	11/15/2019	854390	PLASTIC TRIANGLE HANDSTRAP GREY		546479
143	11/15/2019	854390	Mechanic entered - Body Other Few rail handdle damage and wo		546479
143	11/15/2019	854383	DECAL NO SMOKING 130x130mm	replaced 7 sticker cleaned repaired	546479
143	11/15/2019	854383	Mechanic entered - Body Other Few stickers need to change		546479
143	11/15/2019	854379	Mechanic entered - Body Other steam clean the bus		546479
143	11/15/2019	854384	Mechanic entered - Body Other Pax poll loose back of the bus	Creditor #::GB-MUL001 MULTISPARES LTD P/O #:G262407 Receiving #:272346 Date :2019-11-14	546479
143	11/14/2019	854381	LINK RR SWAY BAR D AXLE SCAN		546479
143	11/14/2019	854381	Mechanic entered - Suspension Other N/R drive axle sway bar		546479
143	11/14/2019	854382	TIE ROD ASSY SCANIA L94/K230/	Creditor #::GB-MUL001 MULTISPARES LTD P/O #:G262407 Receiving #:272346 Date :2019-11-14	546479
143	11/14/2019	854382	Mechanic entered - Steering Excessive Play O/F tio rod ball	replaced tio rod	546479
143	11/14/2019	854389	Mechanic entered - Elec and Light Interior Lights one out	replaced inverter and tube	546479
143	11/14/2019	854388	Mechanic entered - Elec and Light Indicators Not Working O/F	replaced THE DAMAGE LIGHT	546479
143	11/14/2019	854388	LAMP INDICATOR L94 (0478341 SC)	repaired	546479
143	11/14/2019	854380	Mechanic entered - Elec and Light Indicators Not Working O/R		546479
143	11/14/2019	854378	LENS TO SUIT 2029 (RED & AMBER)		546479
143	11/14/2019	854378	Mechanic entered - Elec and Light Exterior Lights N/R cleara	replaced	546479
143	11/14/2019	854380	Consumables		546479
143	11/14/2019	854388	Consumables		546479
143	11/14/2019	854389	Consumables	replaced broken bolt and bottom bush FITTED BACK NEW	546479
143	11/14/2019	854378	Consumables		546479
143	11/14/2019	854387	Mechanic entered - Body Front_Door Operation Faulty need to		546479
143	11/14/2019	854385	Mechanic entered - Body Other yellow strip missing	CARRY OUT CCTV - B SERVICE AS PER CHECK LIST completed PRE ANNUAL SAFETY INSPECTION CHECK CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST did the fire saftety check. CARRY OUT CCTV - A SERVICE AS PER CHECK LIST	546479
143	11/13/2019	854309	INVERTER 24V 15-36W (KIRG)		546479
143	11/13/2019	854309			546479
143	11/13/2019	854309		remove broken light assemblies replace new paker light assembly repair body as much i can replace amber light lense new x 2 gloubes	545097
143	11/13/2019	854399			545097
143	11/06/2019	852703	Bwere doing ATM		545286
143	10/24/2019	850252	Consumables	Creditor #::MT-ALP003 ALPHA BUS GLASS PTY LTD P/O #:M260644 Receiving #:271029 Date :2019-10-25	545494
143	10/24/2019	850252	LIGHT REAR STOP (2322)		545097
143	10/24/2019	850252	Mechanic entered - Accident Other when driver reversing bus		545097
143	10/24/2019	850252	LENS AMBER TO SUIT 2149	Replaced by Alpha Glass Commission tested found set point was at 27c set at 22c tested ok Creditor #::GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G252060-1 Receiving #:267663 Date :2019-09-18	545286
143	10/22/2019	849227	Consumables		545494
143	10/22/2019	849227	REPLACE N/S WINDOW		545097
143	10/21/2019	849227	N/S window cracked.	Done Assisted by Nick. Assisted. re-tensioned nuts on wheels 9 and 10 with matthew 's'. Remove position 10 and return position 9 to rack. Fitted two new tyre 27570R22.5R. Tenasion wheel nuts with Sadid.	543947
143	10/01/2019	845236	A/C Heating (None) - CLIMATE CONTROL A/C NOT WORKING		543557
143	09/01/2019	826123	INSTALL REAR MAIN SEAL		542346
143	08/30/2019	839353		Remove and replace d rubber bushes. Steam clean engine and under carriage. Complete.	542346
143	08/30/2019	839353			542346
143	08/30/2019	839173			542346
143	08/29/2019	838971	Mechanic entered - Wheels and Tyres Worn Tyre position 10 wo	Check wiring ok Roadtest check at dash if light coming on No light coming on dash all good. Remove n/s dis able seat found out bolt for the base broken Fitted new bolt and re fit seat.	542323
143	08/29/2019	838971	TYRE 275/70R22.5 RECAP		542323
143	08/29/2019	838971	Consumables		542346
143	08/29/2019	837931	Mechanic entered - Suspension Other Mid axle sway bar d-rubb	Brake test pass and done good roadtest check brake operation ok. After roadtest check mid axle brake temperature ok 50 both side. Creditor #::GB-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:G256342 Receiving #:265898 Date :2019-08-28	542323
143	08/29/2019	838957	Mechanic entered - Engine Other Need to steam clean engine a		542323
143	08/29/2019	837928	Consumables		542346
143	08/29/2019	837928	Mechanic entered - Dash Other Jack knife light coming on das	Clean stub axle both side and Re fit hub assembly fitted new bearing Re fit hub nut and tension bearing free play and tension hub nut both o/s and n/s middle axle. Re fit caliper and tension all caliper bolts according to specification. Re fit brake booster both side and fitted new brake pads both side and replace sensor wirir	542323
143	08/29/2019	837929	Mechanic entered - Body Passenger Seat Torn Passenger xseat		542323
143	08/29/2019	837929	Consumables		542346
143	08/29/2019	838680	Mechanic entered - Brakes Other N/s and o/s bearing need rep	Drain coolant and remove thermostat assembly. Clean thermostat housing and fitted new thermostat. Re fit radiator cover being remove to get access to remove thermostat. Top up coolant and start engine re check for leak all ok. Clean hub assembly both side o/s and n/s axle Remove rotor fitted new rotor both side Remove bearing cone and fitted new cone. Repack grease all bearing and fitted new hub seal both side. Clean up job to continue carry over.	542323
143	08/28/2019	837583	REPAIR SINGLE SEAT BASE		542323
143	08/28/2019	837926	Mechanic entered - Brakes Other N/s mid axle noisy need to r		542323
143	08/28/2019	838680	Mechanic entered - Brakes Other N/s and o/s bearing need rep		542323
143	08/28/2019	838680	SENSOR WEAR SENSOR KIT BLOCK TYPE-AXLE SET L94UB (1794440)		542080
143	08/27/2019	837930	Mechanic entered - Engine Other Radiator thermostat leaking		542080
143	08/27/2019	837926	Mechanic entered - Brakes Other N/s mid axle noisy need to r		

143	08/27/2019	837926	BEARING INNER TAG AXLE SCANIA	Creditor #:GB-STA101 STATEWIDE BEARINGS P/O #:G256530 Receiving #:265752 Date :2019-08-27	542323
143	08/27/2019	837926	BRAKE DISC TAG AXLE SCANIA L	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G256538 Receiving #:265751 Date :2019-08-27	542323
143	08/27/2019	837926	SET DISC PAD SET SCANIA / MERCEDES 0500		542080
143	08/27/2019	837926	BEARING OUTER TAG AXLE SCANIA	Creditor #:GB-STA101 STATEWIDE BEARINGS P/O #:G256530 Receiving #:265752 Date :2019-08-27	542323
143	08/27/2019	837926	CONE INNER BEARING TAG AXLE	Creditor #:GB-STA101 STATEWIDE BEARINGS P/O #:G256530 Receiving #:265752 Date :2019-08-27	542323
143	08/27/2019	837926	SEAL HUB TAG AXLE SCANIA L94	Creditor #:GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G256535 Receiving #:265753 Date :2019-08-27	542323
143	08/27/2019	838160		CARRY OUT FIRE EXTINGUISHER TEST & TAG checked and replaced.	542080
143	08/26/2019	837672	A/C Heating replace clutch coil	Locate and repair electrical fault too rear unit Replaced front unit clutch bearing tested ok	542080
143	08/26/2019	837672	BEARING A/C		542080
143	08/26/2019	837930	GASKET THERMOSTAT SCANIA L94	Creditor #:GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G256444 Receiving #:265680 Date :2019-08-27	542323
143	08/26/2019	837930	THERMOSTAT 75/79 DEG - DOUBLE	Creditor #:GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G256444 Receiving #:265680 Date :2019-08-27	542323
143	08/26/2019	837926	Mechanic entered - Brakes Other N/s mid axle noisy need to r	Rectify noise remove brake pad check still have noise remove caliper still have noise remove hub assembly found out bearing inner faulty out of casing. Remove brake booster pads caliper and hub assembly o/s and clean all parts. Need to order inner and outer bearing both side n/s and o/s mid axle. Need to order rotor w	542080
143	08/26/2019	837927	Mechanic entered - Brakes Other N/s mid axle brake booster a	Replace last 24/8/2019 job done.	542080
143	08/26/2019	837882	BRAKE BOOSTER SCANIA L94UAB (35CLE0100)		542080
143	08/26/2019	837882	Mechanic entered - Brakes Other N/s mid axle brake booster a	N/s brake booster already replace last 24/8/2019. Remove fitted new brake booster o/s.	542080
143	08/24/2019	837583			542080
143	08/24/2019	837583		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Done with Sadid.	542080
143	08/24/2019	837583		VEHICLE SAFETY INSPECTION Completed check list with Sadid.	542080
143	08/24/2019	837593	Consumables		542323
143	08/24/2019	837592	Consumables		542323
143	08/24/2019	837593	Mechanic entered - Elec and Light Other N/s top park light n	Remove and fitted new globe test works ok.	542080
143	08/24/2019	837592	Mechanic entered - Elec and Light Other N/s tail light lower	Rectify fault remove globe found faulty and terminal full of rust clean replace globe. Test works ok.	542080
143	08/22/2019	828379	Consumables		542080
143	08/22/2019	828379	GLOBE DASH 24V 1.2W GREY		542080
143	08/20/2019	836324	FILTER AIR FILTER (395773) AF25066		541758
143	08/20/2019	836324	Fault#:36835 - Ops Entered - Fault - Breakdown Not Starting	Look for the defect checked fuel line cut off solanidecutoff relayfound no fuel in secondary filter replaced borth fuel filters long road tested .bus runing normaly	541758
143	08/20/2019	836324	PULLEY IDLER (SMOOTH STL) SCANIA L94UAB 1779801		541758
143	08/20/2019	836324	RELAY VOLVO H/LIGHT DIODE PROTECTED		541758
143	08/19/2019	836324	PICK UP FROM NEW ST BRIGHTON	Creditor #:GB-EAG001 EAGLE TOWING & SALVAGE P/O #:G255891 Receiving #:265761 Date :2019-08-28 BRING TO DANDENONG DEPOT	542323
143	08/19/2019	836324	FILTER FUEL FILTER SCANIA SR4 (1372444)		541758
143	08/19/2019	836324	FILTER FUEL FILTER SCANIA SR4 (1393640)		541758
143	08/07/2019	821395	PERFORM CAMPAIGN 10/19 ROUTE BUS DESTINATION FILE UPDATE	programmed the desto	540786
143	08/06/2019	833683		TRANSMISSION CHECK AS PER CHECK LIST Transmission Check Completed 05/08/19	540786
143	08/05/2019	833358	Consumables		540786
143	08/05/2019	833358	Consumables		540786
143	08/05/2019	833358	Consumables		540786
143	08/05/2019	833358	Consumables		540786
143	08/05/2019	833358	FILTER ZF TRANS ECOMAT (1193281-1)(4139 298 038 01)		540544
143	08/05/2019	833358	Oil Filter SCANIA S4 & K		540544
143	08/05/2019	833358	OIL ENGINE DELO 400 MGX SAE 15W-40		540544
143	08/05/2019	833358		Completed B service and tensioned all wheel nuts w/ Ryan	540544
143	08/05/2019	833358		CARRY OUT B SERVICE AS PER CHECK LIST B Service Completed	540544
143	08/05/2019	833358	FILTER FUEL FILTER SCANIA SR4 (1372444)		540544
143	08/05/2019	833358	KIT O-RING OIL SPINNER FILTER SCANIA ABOVE ENG #6203050		540544
143	07/19/2019	829931	Fluid Leaks COOLANT LEAKING - MUST BE FIXED	Fixed coolant leak.	539236
143	07/15/2019	828441	Ops Entered - Fault - A/C Heating Demister Not Heating - Ro	diagnose and replaced thermostats	539092
143	07/15/2019	828441	THERMOSTAT 85 DEG - DOUBLE SC	Creditor #:GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G252887 Receiving #:261833 Date :2019-07-15	539092
143	07/15/2019	828441	GASKET THERMOSTAT SCANIA L94	Creditor #:GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G252887 Receiving #:261833 Date :2019-07-15	539092
143	07/12/2019	828441	Ops Entered - Fault - A/C Heating Demister Not Heating - Ro	Tested found boost pup for accessories has failed new one ordered engine thermostat need to be looked at job not completed carry over	539092
143	07/12/2019	828441	BOOST PUMP C090 38MM PORTS	Creditor #:GB-COA001 COACHAIR PTY LTD P/O #:G252762 Receiving #:261845 Date :2019-07-15	539092
143	07/12/2019	828379	Consumables		539092
143	07/12/2019	828379	GLOBE DASH 24V 1.2W GREY		539092
143	07/12/2019	828379	Consumables		539092
143	07/12/2019	828379	Ops Entered - Fault - Elec and Light - Next Stop Light on Da	changed blown globe.	539092
143	07/08/2019	826123	Mechanic entered - Engine Other bell houseing oil leak	Fitted new water pump and coolant heather tank. Filled up engine oil and coolant. Steam cleaned the engine drive tested and checked oil and coolant level. Checked leaks ok.	538916
143	07/05/2019	826123	12MM X 1.5MM X 1M NYLON TUBING	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G252230 Receiving #:261134 Date :2019-07-08	538916
143	07/04/2019	826123	Mechanic entered - Engine Other bell houseing oil leak	Replaced gasket and refitted engine oil sump. Refitted flywhee and transmission and tension all the bolt to spec. C/O	538916
143	07/03/2019	826123	HOSE ELBOW EXP TANK SCANIA L	Creditor #:GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G251774 Receiving #:260930 Date :2019-07-03	538916
143	07/03/2019	826123	GASKET OIL COOLER SCANIA L94	Creditor #:GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G251774 Receiving #:260930 Date :2019-07-03	538916
143	07/03/2019	826123	GASKET OIL COOLER SCANIA L94	Creditor #:GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G251774 Receiving #:260930 Date :2019-07-03	538916
143	07/03/2019	826123	GASKET OIL COOLER SCANIA L94	Creditor #:GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G251774 Receiving #:260930 Date :2019-07-03	538916
143	07/03/2019	826123	SEAL RING OIL COOLER SCANIA	Creditor #:GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G251774 Receiving #:260930 Date :2019-07-03	538916
143	07/03/2019	826123	GASKET SUMP SCANIA L94 5514	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G251775 Receiving #:260917 Date :2019-07-03	538916
143	07/03/2019	826123	Mechanic entered - Engine Other bell houseing oil leak	Removed engine oil sump. R/R bell housing gasket. C/O	538916
143	07/03/2019	826123	PUMP WATER PUMP SCANIA S4	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G251775 Receiving #:260918 Date :2019-07-03	538916
143	07/02/2019	826123	SEAL REAR MAIN DS9 SCANIA (40	Creditor #:GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G251774 Receiving #:260820 Date :2019-07-02	538916
143	07/02/2019	826123	GASKET SPINNER HSG MTG SCANI	Creditor #:GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G251774 Receiving #:260820 Date :2019-07-02	538916
143	07/02/2019	826123	GASKET SPINNER HSG - ADAPTOR	Creditor #:GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G251774 Receiving #:260820 Date :2019-07-02	538916
143	07/02/2019	826123	GASKET FLYWHEEL HSG SCANIA L	Creditor #:GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G251774 Receiving #:260820 Date :2019-07-02	538916
143	07/02/2019	826123	EXPANSION END FILL SCANIA S	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G251775 Receiving #:260919 Date :2019-07-03	538916
143	07/01/2019	826123	Mechanic entered - Engine Other bell houseing oil leak	Removed transmission and flywheel. C/O	538833
143	06/21/2019	821395	PERFORM CAMPAIGN 10/19 ROUTE BUS DESTINATION FILE UPDATE		538833
143	06/15/2019	823113	Consumables		538134
143	06/15/2019	823113	COOLANT LIGHT COMING ON DASH	No compline again	538134
143	06/12/2019	822453	Mechanic entered - Vandalism Other seat torn	removed and replaced seat base	537645
143	06/12/2019	822452	Consumables		537996
143	06/12/2019	822452	Mechanic entered - Elec and Light Warning Light On Dash Jack	removed flooring and check pressure found low.Pumped pressure back up.Road tested and ok put the floor back together.	537645
143	06/06/2019	821395	PERFORM CAMPAIGN 10/19 ROUTE BUS DESTINATION FILE UPDATE	***Unit/Card not working***	537438
143	06/05/2019	821394	Engine - Temp gauge not working.	Found temp gauge stuck slaped dash and went down went on road test and not goin up.Low water light intermitently coming on.	537438
143	06/05/2019	821394	Consumables		537438
143	06/05/2019	821394	Dash Guages Not Working 2 SEATS RIPPED OFF JACKKNIFE WA	checked found 1 seat rip no jack knife light coming on went on road test and reffer other work job for gauge not working.	537438
143	06/05/2019	821394	TOP LHS REAR TAIL INDICATOR NOT WORKING	check indicators and ok	537438
143	06/04/2019	821164	Consumables		537438
143	06/04/2019	821164	Mechanic entered - Elec and Light Other rear ns park light o	remove and change both gloubes	537212
143	06/01/2019	800179	DIRECT PURCHASE - AIR CONDITIONING		538134
143	06/01/2019	757358	CCTV 6 MONTHLY SERVICE	Creditor #:GB-BWE001 BWERE ELECTRICS PTY LTD P/O #:G250277 Receiving #:258955 Date :2019-06-14 SERVICE AS REQUIRED	538134
143	06/01/2019	757358	VIDEO LOSS	Creditor #:GB-BWE001 BWERE ELECTRICS PTY LTD P/O #:G250243 Receiving #:258907 Date :2019-06-13 REPAIR AS REQUIRED	537996
143	05/30/2019	820258		done with Akabar	537036
143	05/30/2019	820256		done with Akabar	537036
143	05/30/2019	820179	BOLT M12 X 130 IDLER BASE	Creditor #:GB-ECO001 ECONOMY BOLT COMPANY PTY LTD P/O #:G249362 Receiving #:257890 Date :2019-05-30	537036
143	05/30/2019	820179	BEARING IDLER POST PULLEY (CURRUM TYPE) 633313		537036
143	05/30/2019	820179	AC CLUTCH DAMAGED	Tested clutch function tested ok Replaced idler post bearing and center pin replaced idler post bush tested Main compressor clutch noisey when hot will need to be replaced	537036
143	05/30/2019	820179	Engine Belts_Loose Noisy Missing - loud noise when on high		537036

143	05/28/2019	819417	79G262440 DIAPHRAGM TYPE 24 DE	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G249025RET Receiving #:257641 Date :2019-05-28	536753
143	05/27/2019	819376		completed	536753
143	05/27/2019	819376		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS completed with sisil	536753
143	05/27/2019	819376		VEHICLE SAFETY INSPECTION completed with sisil	536753
143	05/27/2019	819389	Consumables		536753
143	05/27/2019	819389	Consumables		536753
143	05/27/2019	819389	Consumables		536753
143	05/27/2019	819389	Mechanic entered - Wheels and Tyres Flat or Leaking pos 9	Zube changed pos 9 tyre and tensioned wheel nut sisil. (used half worn from stor)	536753
143	05/27/2019	800179	DIRECT PURCHASE - AIR CONDITIONING		536753
143	05/27/2019	800179	DIRECT PURCHASE - AIR CONDITIONING		536753
143	05/27/2019	819417	DIAPHRAGM TYPE 24 SHALLOW	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G249025 Receiving #:257639 Date :2019-05-28	536753
143	05/27/2019	819417	79G262440 DIAPHRAGM TYPE 24 DE	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G249025 Receiving #:257639 Date :2019-05-28 INCORRECT PART	536753
143	05/27/2019	819417	Mechanic entered - Air System Air_Leak Doors	replaced the brake booster tensioned wheel nut with Zube N/F	536753
143	05/17/2019	817643	CARRY OUT 6 MONTH SERVICE AND	Creditor #:GB-BWE001 BWERE ELECTRICS PTY LTD P/O #:G248368 Receiving #:257476 Date :2019-05-27	536753
143	05/17/2019	817643	CCTV 6 month service	Completed 6 month service and reapar	535948
143	05/10/2019	815798	FILTER PNEUMATIC REGULATOR DOOR RAM (AW20-02H-C)		535540
143	05/10/2019	815798	GAUGE MIST SEPARATOR		535540
143	05/09/2019	815784	WIPER LINKAGE ASSY	Creditor #:GB-VOL001 VOLGREN AUSTRALIA PTY LTD P/O #:G247656 Receiving #:256144 Date :2019-05-10	535540
143	05/09/2019	815784	Wipers and Washers - DRIVER SIDE WIPER NOT WORKING	fit new wiper linkage.	535533
143	05/09/2019	815784	Wipers and Washers - DRIVER SIDE WIPER NOT WORKING	already fixed by allan.	535533
143	05/09/2019	815798	Mechanic entered - Air System Air_Leak Doors	fit new front door air control valve.	535533
143	05/08/2019	815161	Mechanic entered - A/C Heating Not Cooling	Tested found the frount unit was set at 27c adjusted to 22c rear unit was set at 25c adjusted to 22c tested ok	535305
143	05/06/2019	814454	Consumables		535305
143	05/06/2019	814454	Consumables		535305
143	05/06/2019	814454	Consumables		535305
143	05/06/2019	814454	Drv entered - Elec and Light Exterior Lights		535305
143	05/02/2019	813706	Fluid Leaks. coolant leak.	all lights checked - all working o.k.	534770
143	04/09/2019	809224	Accident#:48689 - Ops Entered - Accident - Malicious damage	Coolant tank had been filled up too much drained some and washed engine.	534135
143	04/08/2019	809010		REF TO W/O #804606	533896
143	04/08/2019	808666	Consumables	re tensioned 7 and 8 tyre with sadid	534135
143	04/08/2019	808666	TYRE 275/70R22.5 RECAP		533896
143	04/05/2019	808666	Mechanic entered - Wheels and Tyres Worn	replaced pos 6/7 tyre tension wheel nuts with kuma.	533896
143	03/21/2019	805153	Consumables		532756
143	03/21/2019	805153	Fit decals to rear window.	Fit new give way long vehicle and emergency exit decals as rear window was replaced.	532543
143	03/20/2019	804606	DECAL LONG VEHICLE		532543
143	03/20/2019	804606	DECAL GIVE WAY 240x225mm		532543
143	03/20/2019	804606	Accident #48689 BUS BEING VANDALISED AND BACK GLASS WINDOW	replaced by Alpha	532543
143	03/19/2019	804606	REPLACE REAR BACK GLASS	Creditor #:GB-ALP003 ALPHA BUS GLASS PTY LTD P/O #:G243726 Receiving #:251866 Date :2019-03-20	532543
143	03/12/2019	800179	DIRECT PURCHASE - AIR CONDITIONING	Apologies incorrect entry again.	531688
143	03/12/2019	800179	DIRECT PURCHASE - AIR CONDITIONING	Incorrect entry.	531688
143	03/04/2019	801607	Consumables		531095
143	03/04/2019	801607	GASKET LENS GASKET HELLA		531095
143	03/04/2019	801607	24V 21/5W D/ CONTACT GLOBE		531095
143	03/04/2019	801607	GLOBE 24V 5W FESTOON (17136)		531095
143	03/04/2019	801607	Drv entered - Elec and Light Exterior Lights	changed blown festoon (nsf) clearance light. changed blown globe and replaced missing gasket (nsr) bottom stop / tail light.	531095
143	03/01/2019	800179	Consumables		531095
143	03/01/2019	800179	AIR CONDITIONING REPAIR	Creditor #:IB-COL004 COLD DRIVE PTY LTD P/O #:V242741REV Receiving #:251239 Date :2019-03-12 Welding repair (incorrect entry - should of been for Lilydale 720 WO 801179)	531688
143	03/01/2019	800179	AIR CONDITIONING REPAIR	Creditor #:IB-COL004 COLD DRIVE PTY LTD P/O #:V242741 Receiving #:251037 Date :2019-03-07 Welding Repair	531513
143	02/27/2019	800739	Retight		530741
143	02/27/2019	800739	Wipers and Washers - RHS washer jet n/w	repaired	530741
143	02/27/2019	800739	Wipers and Washers - Replace both wiper blades	Fixed	530741
143	02/27/2019	800739	Steering - Bus pulls to right when braking	Adjust front brakes	530741
143	02/27/2019	800739	Engine - Oil around rear main seal	Steam clean road tested OK	530741
143	02/27/2019	800739	Consumables		530741
143	02/27/2019	800691	Consumables		530741
143	02/27/2019	800691	Elec and Light - Rear stop bus globe out	REPLACED	530741
143	02/27/2019	800739	Elec and Light - Rear door emer light u/s	Replace globe	530741
143	02/27/2019	800739	Elec and Light - Switch on dash globes blown	Fixed	530741
143	02/27/2019	800739	Elec and Light - Salloon cover u/s	Replaced	530741
143	02/27/2019	800739	Elec and Light - LH emer light n/w	Replace globe	530741
143	02/27/2019	800739	Elec and Light - Middle door emer light n/w	Replace globe	530741
143	02/27/2019	800739	Consumables		530741
143	02/27/2019	800739	Body - Handle on seat damaged	painted	530741
143	02/27/2019	800739	PASSENGER A/C VENT		530741
143	02/27/2019	800739	Body - Base seats torn	Repaired	530741
143	02/27/2019	800739	Body - A/C vent missing	Fitted	530741
143	02/25/2019	800135		completed safety with craig and tenioned all wheel nuts and repaired saloon lights	530535
143	02/25/2019	800135		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS tensioned all wheel nuts with agaba	530535
143	02/25/2019	800135		VEHICLE SAFETY INSPECTION completed safey check<> R/R 8x saloon globes and made a repair list	530535
143	02/25/2019	800179	Mechanic entered - Wheels and Tyres Vibration Pos: 12	Help Craig with tyres and tensions	530535
143	02/25/2019	800179	TYRE 275/70R22.5 NEW		530535
143	02/25/2019	800179	Mechanic entered - Wheels and Tyres Vibration Pos: 12	R/R Pos 1 and 2 tries and tensioned all wheel nuts with Agaba	530535
143	02/25/2019	800179	Consumables		530535
143	02/12/2019	796756	Consumables		529674
143	02/12/2019	796756	Elec and Light Horn not working	fixed loose electrical connection.	529568
143	02/09/2019	796756	Elec and Light Horn not working	bus not at dandenong.	529568
143	02/07/2019	795902	Please remove old 2018 fare decals and fit new 2019 fare dec	completed.	528941
143	02/06/2019	795902	Please remove old 2018 fare decals and fit new 2019 fare dec	bus not here.	528941
143	02/01/2019	798851	Completed by ATS	CARRY OUT FIRE EXTINGUISHER TEST & TAG	528941
143	12/01/2018	782300	DIRECT PURCHASE - BUS INSPECTI	Creditor #:GB-ROA001 ROAD SAFETY INSPECTIONS P/O #:G235481 Receiving #:245434 Date :2018-12-21	527411
143	11/29/2018	782569	Steering - Steering cover loose	repaired.	526136
143	11/28/2018	782300		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	526136
143	11/28/2018	782300		VEHICLE SAFETY INSPECTION	526136
143	11/28/2018	782300		Assisting	526136
143	11/28/2018	782300		ANNUAL SAFETY INSPECTION - RWC 015924 - PASSED - 28/11/18WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLESAFETY INSPECTION LINE TIME ON THE W/O TO 0.25	526136
143	11/28/2018	780602	Suspension - Replace mid axle sway bar link rod	completed	526136
143	11/27/2018	782174	Engine - NO KEY STARTING	job completed under my defect on 26/11/18	525837
143	11/27/2018	781821	Mechanic entered - Body Passenger Seat Torn the seat handle	replaced	525837
143	11/27/2018	781821	Mechanic entered - Body Passenger Seat Torn the seat handle	assisted	525837
143	11/26/2018	781784		done repair water separater wires and replaced int tube	525837
143	11/26/2018	781784		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS completed	525837
143	11/26/2018	781784		VEHICLE SAFETY INSPECTION completed	525837
143	11/26/2018	781870	Consumables		525837

143	11/26/2018	781870	SWITCH STARTER LOCK TO SUIT SCANIA L94UAB		525837
143	11/26/2018	781870	Mechanic entered - Elec and Light Other Ignition switch neee	dis assmbled steering collum pannels and removed wiper stakl and ignition switch.replaced ignition switch and bput back everything together.Checked and ok.	525837
143	11/26/2018	781821	Mechanic entered - Body Passenger Seat Torn the seat handle	replaced seat	525837
143	11/26/2018	781821	PASS SEAT HANDGRIP CENTRA MK 2		525837
143	11/22/2018	780602	WIPER WASHER NON-RETURN VALVE WP10		525469
143	11/22/2018	780602	Suspension - Front end drops check suspension solenoid	fitted new O/S front air bag. raised bus left over night. re checked . all good	525469
143	11/21/2018	780602	Wipers and Washers - Windscreen washer n/w	blew out both washer jets . now all good	525469
143	11/21/2018	780602	LINK SWAY BAR L94 CENTRE AXLE	Creditor #:-GB-CBM001 CBM COMPANY P/O #:G234937 Receiving #:243161 Date :2018-11-27	525837
143	11/21/2018	780602	LINK SWAY BAR O/S TAG AXLE	Creditor #:-GB-MUL001 MULTISPARES LTD P/O #:G234867 Receiving #:242860 Date :2018-11-22	525469
143	11/21/2018	780602	Suspension - Front end drops check suspension solenoid	replaced front air bag check if bus has dropped over night	525469
143	11/21/2018	780602	Engine - Remove flow hatche & s/clean for RSI	cleaned under carriage and top of engine.	525469
143	11/21/2018	780602	Body - Secure low skirt panels	secured 6 panels replaced missing bolts	525469
143	11/21/2018	780602	Body - Secure hand rail grabs	tightened all interior grab handles	525469
143	11/21/2018	780602	Air System - Repair air leak next to air dryer	cut airline and placed air joiner	525469
143	11/20/2018	780479		PRE ANNUAL SAFETY INSPECTION CHECK	525469
143	11/20/2018	780479	GLOBE 24V SW FESTOON (17136)		525469
143	11/20/2018	780479	SINGLE SEAT BASE		525469
143	11/20/2018	780479	STRUT GAS STAY LIFT UP SEAT		525469
143	11/20/2018	780602	AIRBAG FRONT SCANIA L94 SERI	Creditor #:-GB-MUL001 MULTISPARES LTD P/O #:G234867 Receiving #:242869 Date :2018-11-22	525469
143	11/20/2018	780602	BUSH SWAYBAR D-SHAPE SCANIA L9	Creditor #:-GB-MUL001 MULTISPARES LTD P/O #:G234867 Receiving #:242869 Date :2018-11-22	525469
143	11/20/2018	780578	Consumables		525469
143	11/20/2018	780578	Elec and Light - Replace NSR park light	replaced	525469
143	11/20/2018	780578	Drv entered - Elec and Light Interior Lights	replaced	525469
143	11/20/2018	780578	Elec and Light - Replace saloon light	replaced	525469
143	11/20/2018	780578	MUDFLAP 605MM X 330MM		525469
143	11/20/2018	780578	Body - replace seat cushions	replaced	525469
143	11/20/2018	780578	Body - Replace OS front mudflap	replaced	525469
143	11/20/2018	780669		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST did the fire saftey.	525469
143	11/13/2018	779237	Consumables		525099
143	11/13/2018	779237	SWITCH HAZARD 4 SERIES 1327015		524541
143	11/13/2018	779237	Elec and Light - HAZARD LIGHTS NOT WORKING	Replaced hazard switch	524541
143	11/13/2018	778045		Service rear unit as per list	524541
143	11/13/2018	778045		CARRY OUT A/C - A SERVICE AS PER CHECK LIST	524541
143	11/07/2018	778045		CARRY OUT A/C - A SERVICE AS PER CHECK LIST Service front unit only not completed carry over	524541
143	10/26/2018	775895	Consumables		523565
143	10/26/2018	775895	Mechanic entered - Wheels and Tyres Other no 2 wheel missing	already been replaced.	523239
143	10/26/2018	775968	Mechanic entered - Body Other constantino rubber come out.	fitted back rubber	523239
143	10/26/2018	775968	Mechanic entered - Body Other constantino rubber come out.	fitted back the rubber to constantino.	523239
143	10/18/2018	774058	RUB BUFFER		522075
143	10/17/2018	774058	Engine - OSRR shocker mounts u/s	fit new shocker mounts.	522075
143	10/15/2018	774058	WASHER RR SHOCKER L94UAB	Creditor #:-GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G231750 Receiving #:239807 Date :2018-10-17	522075
143	10/15/2018	774058	WASHER RR SHOCKER L94UAB	Creditor #:-GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G231750 Receiving #:239807 Date :2018-10-17	522075
143	10/15/2018	774058	WASHER RR SHOCKER L94UAB	Creditor #:-GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G231750 Receiving #:239807 Date :2018-10-17	522075
143	10/15/2018	774058	BUSHING RR SHOCKER L94UAB	Creditor #:-GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G231750 Receiving #:239807 Date :2018-10-17	522075
143	10/04/2018	770127	Consumables		520887
143	10/04/2018	770127	Consumables		520887
143	10/04/2018	770127	Consumables		520887
143	10/04/2018	770127	Consumables		520887
143	10/04/2018	770127	FILTER WATER FILTER SCANIA SR3/SR4 (0342988)		520887
143	10/03/2018	770333	SEAL L94UB ROCKER COVER	Creditor #:-GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G230888 Receiving #:238785 Date :2018-10-03	520887
143	10/03/2018	770333	BOLT L94UB ROCKER COVER	Creditor #:-GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G230888 Receiving #:238785 Date :2018-10-03	520887
143	10/03/2018	770127		CARRY OUT C SERVICE AS PER CHECK LIST	520739
143	10/03/2018	770127	FILTER AIR DRYER SCANIA SERIES 4 (1393551) (20546795)		520739
143	10/03/2018	770127	FILTER FUEL FILTER SCANIA SR4 (1393640)		520739
143	10/03/2018	770127	FILTER AIR FILTER (395773) AF25066		520739
143	10/03/2018	770127	FILTER P/STEER SCANIA VOLVO MERCEDES (349619-7) (2192404)		520739
143	10/03/2018	770127	FILTER ZF TRANS ECOMAT (1193281-1)(4139 298 038 01)		520739
143	10/03/2018	770127	OIL AUTOMATIC TRANSMISSION OIL TEXAMATIC OR DEXRON (LU2)		520739
143	10/03/2018	770127	FILTER FUEL FILTER SCANIA SR4 (1372444)		520739
143	10/03/2018	770127	FILTER WATER FILTER SCANIA S	Creditor #:-GB-MUL001 MULTISPARES LTD P/O #:G231031 Receiving #:238796 Date :2018-10-03	520887
143	10/03/2018	770127	OIL FILTER HYDRAULIC FAN	Creditor #:-GB-MUL001 MULTISPARES LTD P/O #:G231031 Receiving #:238796 Date :2018-10-03	520887
143	10/03/2018	770127	KIT O-RING OIL SPINNER FILTER SCANIA ABOVE ENG #6203050		520739
143	10/03/2018	770127	Oil Filter SC S4 & K		520739
143	10/03/2018	770127	OIL ENGINE OIL MINERAL 15W-40 DELO 400 LE (LU18)(3361808)		520739
143	10/03/2018	770127	Consumables		520887
143	10/03/2018	770127	Consumables		520887
143	10/03/2018	770127	Consumables		520887
143	10/03/2018	770127	Consumables		520887
143	10/03/2018	770127	Consumables		520887
143	10/03/2018	770127		CARRY OUT B SERVICE AS PER CHECK LIST replaced oil and feul filters. drained and refilled oil	520739
143	10/02/2018	770333		SERVICE MOISTURE EJECTOR	520739
143	10/02/2018	770333		CARRY OUT TUNE-UP SERVICE AS PER CHECK LIST remove air cleaner and CAC pipes . adjusted valves . replaced rocker cover gaskets. refit all components and check for leaks	520739
143	10/02/2018	770333			520739
143	10/02/2018	770333	ROCKER COVER GASKET L94UAB (40A8509)		520739
143	10/01/2018	769813	REMOVE AND REPLACE A3 POSTER TO ALL ROUTE VEHICLES	Replaced by Refuellers	520739
143	09/21/2018	768245	painted vandalism	Creditor #:-GB-EAS002 EASTCOAST TRUCK & BUS SERVICE P/O #:G230203 Receiving #:238471 Date :2018-10-01 repairs completed by eastcoast	520887
143	09/21/2018	768245	Vandalism - rear walls side walls seats a/c ducts		520107
143	09/20/2018	766366	Mechanic entered - Engine Other Radiator thermostat by pass	R/R hosetopped up coolantsteam cleaned engine and road tested - ok.	519817
143	09/20/2018	768081	PERFORM CAMPAIGN 26/18 CHASSIS WASH & UNDER CARRIAGE CHECK	Completed.	519817
143	09/15/2018	766366	HOSE COOLING (40N0557)	Creditor #:-GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G229516 Receiving #:237473 Date :2018-09-18	519560
143	09/13/2018	766052	Completed by ATS	CARRY OUT FIRE EXTINGUISHER TEST & TAG	519181
143	09/12/2018	765891		Assisting	519181
143	09/12/2018	765891		Tensioned pos 9 and 10 with Nick.	519181
143	09/12/2018	765877	Fluid Leaks Rear of bus. Coolant leak.	Temporary fixed leaking hose.Ordered new hose for replacement.	519181
143	09/08/2018	764973	Drv entered - Fluid Leaks Rear of bus	repaire coolant leak on top of coolant tank filler	518600
143	09/01/2018	743109	DIRECT PURCHASE - VANDALISM	Creditor #:-GB-EAS002 EASTCOAST TRUCK & BUS SERVICE P/O #:G221481Receiving #:236207 Date :2018-09-03	518147
143	08/30/2018	762992	Breakdown#:35461 - Ops Entered - Breakdown - Breakdown Elect	jump start	517855
143	08/29/2018	762768	Breakdown#:35461 - Ops Entered - Breakdown - Breakdown Elect	bus B/down jump start bus ok.	517397
143	08/28/2018	762561			517397
143	08/28/2018	762561		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	517397
143	08/28/2018	762561		VEHICLE SAFETY INSPECTION	517397
143	08/28/2018	762563	Consumables		517522
143	08/28/2018	762563	Mechanic entered - Wheels and Tyres Worn Rear tyre pos. 9 wo	Remove and replace pos. 9 & 10 tyre. pos. 10 return to track Assisted by Rene and tension all wheel nuts.	517397
143	08/28/2018	762563	TYRE 275/70R22.5 RECAP		517397
143	08/28/2018	762563	Mechanic entered - Wheels and Tyres Worn Rear tyre pos. 9 wo	Assisted Craig and tension wheel nuts.	517397

143	08/25/2018	761784	Consumables			517522
143	08/25/2018	761784	BOTH OUTER REAR TYRES HAVE SCREWS IN THEM.	check and removed screws on tyre pos 7&10 check leak pressure bus ok		517397
143	08/16/2018	756089	PERFORM CAMPAIGN 17/18 INTERNAL BUS NUMBERS	Done by refuelers		516280
143	08/09/2018	756089	DECAL YOU ARE TRAVELLING ON B	Creditor #::GB-TRA013 TRANSCAL P/O #::G225940 Receiving #:234532 Date :2018-08-15		516280
143	08/06/2018	757358	CCTV CCTV not recording video loss reported.	As above		515092
143	08/06/2018	757358	CCTV CCTV not recording video loss	Repair completed by Bwere jonny		515092
143	08/01/2018	757358	CABLE EXTENSION DIN JACK 7M	Creditor #::GB-TH0005 THOREB AUSTRALIA PTY LTD P/O #::G224475 Receiving #:233953 Date :2018-08-07		515325
143	07/26/2018	755124	REMOVE OLD POSTER AND REPLACE WITH BUS TIMES ARE CHANGING	Replaced by refuellers		514045
143	07/25/2018	754755	Drv entered - A/C Heating Demister Not Heating	Commission tested unable to fault		514045
143	07/25/2018	754755	Drv entered - A/C Heating Not Heating	Commission tested unable to fault		514045
143	07/25/2018	754900	PERFORM CAMPAIGN 11/18 VENTURA BUS MINDER INSTALLATION	checked bus and allready has a bus minder fitted.		514045
143	07/17/2018	752710	Consumables			513282
143	07/17/2018	752710	Ops Entered - Fault - Elec and Light Flat Batteries - Route	bus started o.k.		513181
143	07/13/2018	752309	Consumables			513181
143	07/13/2018	752309	GLOBE 24V 3W FESTOON			512960
143	07/13/2018	752309	Mechanic entered - Elec and Light Exterior Lights n/s cleara	R/R globe.		512960
143	07/09/2018	751381	PERFORM CAMPAIGN 16/18 2019 REGISTRATION LABEL REPLACEMENT	Replaced		512662
143	06/28/2018	742053	SCANIA DIP STICK L94UAB (40A8200)			512235
143	06/25/2018	747779	Consumables			512115
143	06/25/2018	747779	Elec and Light Warning Light On Dash - JACK KNIFE LIGHT CO	repressurised turntable working ok.		512060
143	06/15/2018	745829	Wipers and Washers Washers Not Working	Repaired wiper arm & replaced washer tube.		511053
143	06/14/2018	745346		TRANSMISSION CHECK AS PER CHECK LIST Transmission Service Completed		511053
143	06/13/2018	745081	BELT MICRO V SERPENTINE BELT 8 RIB 2595mm LONG			510828
143	06/13/2018	745081	Drv entered - Engine Belts_Loose Noisy Missing	remove broken bolt from alt bracketfit new drive belt adjust idler pulley. road tested ok.		510828
143	06/12/2018	744825	DECAL DISABLED WHITE ON BLUE S/SIDED 150MM X 150MM			510828
143	06/12/2018	744825	PERFORM CAMPAIGN 13/18 VENTURA ROUTE BUS DECAL UPDATE	completed.		510828
143	06/08/2018	744392	BELT MICRO V SERPENTINE BELT 8 RIB 2595mm LONG			510828
143	06/08/2018	744392	Drv entered - Engine Belts_Loose Noisy Missing	fit new idler pulley. fit new alt drive belt.		510828
143	06/07/2018	744392	IDLER PULLEY SCANIA NO GROOVES	Creditor #::GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #::G221824 Receiving #:229327 Date :2018-06-08		510828
143	06/07/2018	741295	BELT MICRO V SERPENTINE BELT 8 RIB 2595mm LONG			510570
143	06/07/2018	741295	BELT MICRO V SERPENTINE BELT 8 RIB 2595mm LONG			510570
143	06/07/2018	740621	BELT MICRO V SERPENTINE BELT 8 RIB 2595mm LONG			510570
143	06/07/2018	740621	BELT MICRO V SERPENTINE BELT 8 RIB 2595mm LONG			510570
143	06/06/2018	743866		helped with wheel nuts		510570
143	06/06/2018	743866		retensioned wheel nuts both fronts		510570
143	06/05/2018	742053	Consumables			510570
143	06/05/2018	742053	Mechanic entered - Wheels and Tyres Vibration front wheel wo			509929
143	06/05/2018	742053	Mechanic entered - Wheels and Tyres Vibration front wheel wo	Tension hub nuts to spec with Shalen. Fitted new brake pads and adjust the brakes. Tension all front wheel nuts with Invika. Brake test and road test. Checked brake temps ok.		509929
143	06/05/2018	742824	Breakdown Belts Pulleys & Idler BearingsMissing a belt	Line up alternator and fitted new belt. Drive tested. OK		509929
143	06/05/2018	742053	Mechanic entered - Engine Other oil presure sender not worki	R/R engine temp gauge.		509929
143	06/05/2018	742053	Mechanic entered - Engine Other engine temp gauge not workin	R/R engine temp gauge.		509929
143	06/05/2018	742053	DIAPHRAGM TYPE 24 SHALLOW			509929
143	06/05/2018	742053	Mechanic entered - Brakes Foot_Brakes Leaking Air right fron	R/R front o/s brake booster diaphragm. Checked air leak. ok		509929
143	06/05/2018	742053	Mechanic entered - Brakes Foot_Brakes Leaking Air right fron			509929
143	06/04/2018	742053	SENSOR WEAR SENSOR KIT BLOCK TYPE-AXEL SET L94UB (1794440)			509929
143	06/04/2018	742053	SET DISC PAD SET SCANIA / MERCEDES 0500			509929
143	06/04/2018	742824	Breakdown Belts Pulleys & Idler BearingsMissing a belt			509929
143	06/04/2018	742824	BELT MICRO V SERPENTINE BELT 8 RIB 2595mm LONG			509929
143	06/04/2018	742824	PULLEY IDLER SCANIA (1514087)			509929
143	06/04/2018	742053	TEMP SENDER UNIT	Creditor #::GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #::G221408 Receiving #:228956 Date :2018-06-04		510447
143	06/02/2018	743109	Mechanic entered - Vandalism Vandalism/ Graffiti Interior t	Vandalism removed and painted as required by ECB		510447
143	06/01/2018	742053	SENDER OIL PRESS. L94	Creditor #::GB-MUL001 MULTISPARES LTD P/O #::G221332 Receiving #:228861 Date :2018-06-01		510447
143	06/01/2018	742053	ROTOR FRONT DISC BRAKE SCANI	Creditor #::GB-MUL001 MULTISPARES LTD P/O #::G221332 Receiving #:228861 Date :2018-06-01		510447
143	05/31/2018	741295	BELT MICRO V SERPENTINE BELT 8 RIB 2595mm LONG			509929
143	05/31/2018	740621	Consumables			510447
143	05/31/2018	740621	BELT MICRO V SERPENTINE BELT 8 RIB 2595mm LONG			509929
143	05/30/2018	741295	BELT MICRO V SERPENTINE BELT 8 RIB 2595mm LONG			509929
143	05/30/2018	740621	BELT MICRO V SERPENTINE BELT 8 RIB 2595mm LONG			509929
143	05/29/2018	742053	Mechanic entered - Wheels and Tyres Vibration front wheel wo	road test bus found that the bus was pulling to the right and had badwobbling when braking. checked over wheels and all good. check over discand pads and would say that the disc are warped (need a set of front Brakesand pads)		509929
143	05/29/2018	742053	Consumables			510246
143	05/29/2018	742053	Mechanic entered - Engine Other oil presure sender not worki	road test bus to check oil pressure wont go over 7 bar even on idle. need to order new oil pressure sender		509929
143	05/29/2018	742053	Mechanic entered - Engine Other engine temp gauge not workin	road test bus to get temp up. but temp gauge wouldnt move. need to order a new temp sensor		509929
143	05/29/2018	742069	GLOBE 24V 5W FESTOON (17136)			509929
143	05/29/2018	742069	GLOBE 24V 2W (HLH242)			509929
143	05/29/2018	742069	Mechanic entered - Elec and Light Exterior Lights Rear LH si	R/R Clearance Light globe and Number Plate Light Globe		509929
143	05/29/2018	742068	GLOBE 24V 10W SINGLE CONTACT			509929
143	05/29/2018	742068	LENS CLEAR TO SUIT 1406			509929
143	05/29/2018	742068	Mechanic entered - Elec and Light Interior Lights Lhtop park	R/R top Lh Parker Lense and Globe		509929
143	05/29/2018	742053	GLOBE 24V 3W FESTOON			509929
143	05/29/2018	742053	Mechanic entered - Elec and Light Interior Lights emergency	R/R Rear Emergency exit Light Globe R/R Drivers side front emergency exit light globe		509929
143	05/29/2018	742069	Consumables			510246
143	05/29/2018	742068	Consumables			510246
143	05/29/2018	742053	Consumables			510246
143	05/29/2018	742053	Mechanic entered - Brakes Foot_Brakes Leaking Air right fron	Rh front booster has small leak around clamp. need to rebook back to replace booster (order a bladder)		509929
143	05/28/2018	741644		complete safety inspection		509929
143	05/28/2018	741644		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Tentioned all wheel nuts.		509929
143	05/28/2018	741644		VEHICLE SAFETY INSPECTION Carried out safety with dean and tentioned all wheel nuts.		509929
143	05/25/2018	741295	Drv entered -***ALTERNATORS NOT ALIGNED-SS** Engine Belts_L	aligned a;lt and repaired wiring to coolant sensor working ok. belt not throwing.		509929
143	05/25/2018	741295	BELT MICRO V SERPENTINE BELT 8 RIB 2595mm LONG			509929
143	05/24/2018	738458	AIR CON REFRIDGERANT			508630
143	05/24/2018	738458	Drv entered - A/C Heating Not Cooling	Run the unit up complete charge and tested ok		508630
143	05/23/2018	738458	Drv entered - A/C Heating Not Cooling	Remove make up and replaced both discharge hoses pressure and vac tested charge unit run up tested ok		508630
143	05/23/2018	740621	ALTERNATOR 140AMP	Creditor #::GB-MUL001 MULTISPARES LTD P/O #::G220580 Receiving #:228020 Date :2018-05-23		509604
143	05/23/2018	740621	Mechanic entered - Elec and Light Other alternator loose.	replaced alternator. removed broken bolt from mount point and replaced replaced alt belt and tightened all up working ok.		508630
143	05/23/2018	740621	BELT MICRO V SERPENTINE BELT 8 RIB 2595mm LONG			508630
143	05/18/2018	739893	PERFORM CAMPAIGN 15/18 A3 POSTER CHANGE - MYKI AUTO TOP UP	Completed		509038
143	05/14/2018	738458	A/C HOSE FITTINGS	Creditor #::GB-DAN013 DANDENONG RADIATORS PTY LTD P/O #::G219907 Receiving #:227434 Date :2018-05-15		508822
143	05/14/2018	738458	Drv entered - A/C Heating Not Cooling	Tested found rear unit has constant fault traced back to failed discharge hose parts ordered		508630
143	04/30/2018	735572		CARRY OUT FIRE EXTINGUISHER TEST & TAG		506917
143	04/30/2018	735572		COMPLETED ON 15/02/18		506917
143	04/21/2018	734302	Ops Entered - Fault - Warning Lights - jackknife light keeps	checked turn table senseor clear fault code bus ok.		506177
143	04/03/2018	719052	AIR CON REFRIDGERANT			504540
143	03/26/2018	729358	Drv entered - Fluid Leaks Rear of bus	washed road tested bus tightend clamps nere radiator and ok.		504013

143	03/22/2018	728365	HOSE TRANSMISSION COOLING	Creditor #:GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G216349 Receiving #:223608 Date :2018-03-22	503460
143	03/21/2018	728365	Drv entered - Fluid Leaks Middle of bus	Fitted hose supplied found out wrong part. Assisted Lee inordering correctpart. Fitted hosetopped up coolant. Fitted covers and seats.Asked Eliasto road test.Re checked bus after road test and topped up coolant.	503460
143	03/21/2018	728365	Drv entered - Fluid Leaks Middle of bus	Road tested bus for Shalen.	503460
143	03/20/2018	728039	Consumables		503460
143	03/20/2018	728039	Elec and Light - Done by Craig. R/R rear licence plate ligh	R/r light- ok.	503460
143	03/20/2018	728039	LAMP NUMBER PLATE		503460
143	03/20/2018	728004	Consumables		503460
143	03/20/2018	728004	Consumables		503460
143	03/20/2018	728004	Consumables		503460
143	03/20/2018	728004	Consumables		503460
143	03/20/2018	728004	Consumables		503460
143	03/20/2018	728004	FILTER TRANSMISSION ZF (4139-298-038) (4139 298 038 01)		503460
143	03/20/2018	728004	OIL AUTOMATIC TRANSMISSION OIL TEXAMATIC OR DEXRON (LU2)		503460
143	03/20/2018	728004	KIT O-RING OIL SPINNER FILTER SCANIA ABOVE ENG #6203050		503460
143	03/20/2018	728004	FILTER OIL SCANIA SR4 [EARLY] K320 (LF3730) (H200W20)		503460
143	03/20/2018	728004	OIL ENGINE OIL MINERAL 15W/40 DELO 400 (LU18) (3361808)		503460
143	03/20/2018	728004		CARRY OUT B SERVICE AS PER CHECK LIST	503460
143	03/20/2018	728004	FILTER FUEL FILTER ETHANOL SCANIA SR4 (H17WK04)		503460
143	03/20/2018	728004	Consumables		503460
143	03/20/2018	728004	Consumables		503460
143	03/20/2018	728004	Consumables		503460
143	03/20/2018	728004	Consumables		503460
143	03/20/2018	728004		CARRY OUT A SERVICE AS PER CHECK LIST	503460
143	03/19/2018	727676	Breakdown#:34654 - Ops Entered - Breakdown - Breakdown Overh	Attended break down at Haileysbury College Keyborouhg. Check for fault found no coolant at the header tank topped-up coolant check for leak no leak. Driver continue His job. back to depot.	503254
143	03/09/2018	719052	A/C Heating - ALIGN COMPRESSOR	Remove and replaced failed compressor change over hub assembly trouble removing from old compressor	502244
143	03/08/2018	725722	Consumables		502244
143	03/08/2018	725722	GLOBE 24V 75/70W H4		502244
143	03/08/2018	725722	Drv entered - Elec and Light Exterior Lights	removed and fitted new o/s head light globe.	502244
143	03/02/2018	721581	BELT MICRO V SERPENTINE BELT 8 RIB 2595mm LONG		501536
143	03/02/2018	713896	BELT ALT W/PUMP CRANK SCANIA ARTIC (8PK2595)		501536
143	03/02/2018	713896	BELT MICRO V SERPENTINE BELT 8 RIB 2595mm LONG		501536
143	03/01/2018	721823	PERFORM CAMPAIGN 26/17 BUSES REQUIRING FRONT DBI ENGAGEMENT	completed by Johnny 18/01/18	501099
143	02/28/2018	723512		Assist Nick.	501099
143	02/28/2018	723512		Tension whell nuts pos 1 & 2 with Elias.	501099
143	02/28/2018	723050	Consumables		501350
143	02/28/2018	723050	TYRE 275/70R22.5 NEW		501099
143	02/27/2018	723043		completed.	501099
143	02/27/2018	723043		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS done with Alan	501099
143	02/27/2018	723043		VEHICLE SAFETY INSPECTION completed	501099
143	02/27/2018	723050	Mechanic entered - Wheels and Tyres Worn pos1	Changed pos 12 tyres and tensioned wheel nut with Sisil	501099
143	02/27/2018	723050	Mechanic entered - Wheels and Tyres Worn pos1	Alan changed pos 12 tyres and tensioned wheel nut with Me	501099
143	02/27/2018	722882	Please remove any old poster and fit new ones multi choice	Fitted by Refuellers	501099
143	02/27/2018	722787	PERFORM CAMPAIGN 06/18 REPLACEMENT OF NO ACCESS / PARK BRAK	Replaced decal	501099
143	02/23/2018	721581	Mechanic entered - Engine Belts_Loose Noisy Missing	ref to w/o 721893	500823
143	02/23/2018	721894	Consumables		501099
143	02/23/2018	721893	Consumables		501099
143	02/23/2018	721894	Dash Guages Not WorkingTemptrature guage is not working	checked ok.	500823
143	02/23/2018	721893	Elec and LightAlternator mount broken	removed broken bolt. refit alternator fit belts. started working ok. parked on fuel bay for pti and fuel.	500823
143	02/22/2018	719052	DKS32 AIR COMPRESSOR	Creditor #:GB-22C001 22 CELSIUS P/O #:G213621 Receiving #:221762 Date :2018-02-26	501099
143	02/22/2018	721581	BELT MICRO V SERPENTINE BELT 8 RIB 2595mm LONG		500823
143	02/22/2018	721581	BELT V-BELT COGGED TRI-POWER 17x1145mm		500823
143	02/22/2018	721581	BELT V-BELT COGGED TRI-POWER 17x1675mm		500823
143	02/22/2018	721893	Elec and LightAlternator mount broken	Pulled apart housings from both alternators and fitted good housing to the alternator.Re -assembled.	500823
143	02/22/2018	721893	Elec and LightAlternator mount broken	removed alternator. had to drain coolant from bus which necessitated draining the waste coolant dump and a coolant drum. carry over.	500823
143	02/22/2018	721823	PERFORM CAMPAIGN 26/17 BUSES REQUIRING FRONT DBI ENGAGEMENT	COMPLETED DBI BY BEN	500823
143	02/21/2018	721549	Breakdown#:34525 - Ops Entered - Breakdown - Breakdown Elec	out 8.20 in 10 40 am brighton fault belt missing fitted temparay belts driven to dopot	500823
143	02/21/2018	721581	Mechanic entered - Engine Belts_Loose Noisy Missing	try to remove broken aulternater front bracket bolt found aulternater rear bracket broken.	500823
143	02/15/2018	720240		Assisting	500114
143	02/15/2018	720240		Tensioned all tag axles.	500114
143	02/15/2018	720056	Consumables		500398
143	02/15/2018	720056	Drv entered - Elec and Light Two Way Radio	Check with driver and two way working O/K	500114
143	02/14/2018	719885	Drv entered - Brakes Warning Light On	removed rear wheels checked pads and sensors and ok.Checked fuse box found 1 abs fuse missing put in and lights went away.Put back wheels on bus and Tensioned wheel nuts.	500114
143	02/12/2018	719052	A/C Heating - ALIGN COMPRESSOR	Realign compressors and fitted belts run up found that the right bank compressor is noisey disconnected the clutch wire and ordered in newn compressor DKS32 no completed	500114
143	02/09/2018	713896	BELT MICRO V SERPENTINE BELT 8 RIB 2595mm LONG		500069
143	02/09/2018	713896	BELT A/C BELT SCANIA L94 1389052		500069
143	02/09/2018	713896	Engine exhaust smokes	Fitted new alternator and a/c belts. Refitted air cleaner and floor hatch. Steam cleaned the engine drive tested and checked the performance of the engine Ok. Checked all oil level and oil leaks after road test all ok.	500069
143	02/08/2018	713896	Engine exhaust smokes	Refitted engine accessories. Filled steering oil and fan oil. C/F	500069
143	02/07/2018	713896	Engine exhaust smokes	Cleaned parts and refitted injection pump and injectors. Set up pump timing with Shallen. Torque all the bolts and nuts to spec. C/F	500069
143	02/05/2018	713896	SERVICE / REPAIR INJECTORS	Creditor #:GB-AGD001 AG DIESEL PUMPS & INJECTORS P/L P/O #:G212376 Receiving #:220265 Date :2018-02-06	500069
143	02/05/2018	713896	REPAIR INIECTOR PUMP	Creditor #:GB-AGD001 AG DIESEL PUMPS & INJECTORS P/L P/O #:G212376 Receiving #:220265 Date :2018-02-06	500069
143	02/05/2018	717238	Perform Campaign 27/17 Positioning of 2018 PTV Fares Decals	already been done.	500069
143	01/25/2018	713896	Engine exhaust smokes	Cleaned diesel pump and injectors. C/O	500069
143	01/24/2018	713896	Engine exhaust smokes	Removed diesel pump and accessories. C/O	500069
143	01/22/2018	713896	Engine exhaust smokes	Refitted injector # 1 and start the engine. (requires to removed diesel pump waiting bay in workshop) C/O	500069
143	01/16/2018	713896	Engine exhaust smokes	Rectify engine faults found injector # 1 faulty. Removed injector # 1 to send away for repair. C/O	500069
143	01/15/2018	713638	DIRECT PURCHASE - TOWING	Creditor #:GB-EAG001 EAGLE TOWING & SALVAGE P/O #:G212086 Receiving #:219146 Date :2018-01-23 1789 PRINCES HWY OAKLEIGH TO DANDENONG	500069
143	01/15/2018	713638	Breakdown Belts Pulleys & Idler BearingsEngine No power	Fitted n/s/r axle and parked bus on the steam bay pit.C/O.	499998
143	01/15/2018	713638	Breakdown Belts Pulleys & Idler BearingsEngine No power	Attended break down at Princess highway Chadston Check for fault driver complain smoke come from the back check for fault found A/c compressor pulley rubbing to another pulley. cut belt start engine driver move bus run 30km/hr. only and bus blowing heavy smoke(white smoke). Bus suddenly stall need to re start ag	499998
143	01/12/2018	713163	Consumables		499998
143	01/12/2018	713163	Consumables		499998
143	01/12/2018	713163	Warning Lights (None) jack knife light on dash	checked fault codes. no faults. roadtested to determine if fault would surface. no instance after extensive test. parked bus ok.	499864
143	01/05/2018	711824	Consumables		499400
143	01/05/2018	711824	Consumables		499400
143	01/05/2018	711824	DIRECT PURCHASE - VANDALISM	Creditor #:GB-A1W001 A-1 Windscreens P/O #:G210820 Receiving #:217888 Date :2018-01-05 REPLACE SIDE WINDOW AS REQ	499400
143	01/05/2018	711824	Body - LH #5 window damaged	Replaced by A1	499400
143	01/05/2018	711824	Body - LH #5 window damaged	Replaced by A1	499400
143	01/03/2018	711081	Consumables		499400
143	01/03/2018	711081	Consumables		499400
143	01/03/2018	711081	Body Drivers Seat Beltneeds to checked	replaced faulty driver's seat belt mechanism and adjusted buckle.	499126
143	01/03/2018	711081	BELT SEAT BELT R/H A60RH		499126
143	12/29/2017	710515	BELT CRANK-TWIN A/C COMP SC- ARTIC 8PK2000		498961
143	12/29/2017	710515	A/C Heating - A/C belt faulty	Replace A/C belt	498961
143	12/28/2017	710301	GLOBE 24V SW FESTOON (17136)		498961
143	12/28/2017	710301	Elec and Light - Side clearance light out	changed blown festoon and fixed broken wire - connection plug (os) mid clearance light.	498961

143	12/28/2017	710301	Consumables				499062
143	12/08/2017	706974	Breakdown#:34188 - Ops Entered - Breakdown - Breakdown Road	Checked bus all good. Escorted bus to workshop. Saw bus blowing bit of smokeasked Nick to check turbo and road test.			497246
143	12/08/2017	706977	Engine Low Power	Inspect turbo shaft. Drive tested bus running fine.			497246
143	12/04/2017	704560	DIRECT PURCHASE - BUS INSPECTI	Creditor #:'GB-ROA001 ROAD SAFETY INSPECTIONS P/O #:G208323 Receiving #:216711 Date :2017-12-15 Anual RSI			498019
143	12/02/2017	705580		re-tensioned nuts on wheels 5 and 6 with dulkith.			496158
143	12/01/2017	705303	Wheels and Tyres Flat or Leakingmiddle outer side on the	changed tyre 6 (flat). nuts tensioned with dulkith.			496158
143	12/01/2017	705303	Consumables				496413
143	11/29/2017	704560		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS			496158
143	11/29/2017	704560		VEHICLE SAFETY INSPECTION			496158
143	11/29/2017	704560		ANNUAL SAFETY INSPECTION SERIAL #			496158
143	11/27/2017	703447	REPAIR / SERVICE INJECTOR No 1	Creditor #:'GB-AGD001 AG DIESEL PUMPS & INJECTORS P/L P/O #:G207930 Receiving #:215103 Date :2017-11-27			496158
143	11/27/2017	703447	Warning Lights Engine / no power 20 to 30 km/h	Cleaned injector housing remove dirt inside and fitted new injector sensor wiring. refit all accesories refit turbo hose refit air filter housing. refit filter and air compressor pipe. start and test works ok steam clean engine radiator roadtested to freeway to check the power bus runing good power ok bu bus can be use.			495647
143	11/22/2017	695332	DIRECT PURCHASE - VANDALISM	Creditor #:'GB-GLA010 GLASSPROTECH MELBOURNE P/O #:'G205181 Receiving #:214785 Date :2017-11-22 REPLACE ANTI GRAFFITI FILM PRINTED DOT FILM			495950
143	11/22/2017	703447	Warning Lights Engine / no power 20 to 30 km/h	checked found No 1 injector faulty Rane c/o			495647
143	11/22/2017	703447	Warning Lights Engine / no power 20 to 30 km/h	Remove accesories and remove number one injector.			495647
143	11/22/2017	702400	Consumables				496147
143	11/22/2017	702400	LENS STOP LAMP LENS SUIT 2322				495647
143	11/22/2017	702132	LENS STOP LAMP LENS SUIT 2322				495647
143	11/22/2017	702132	LENS AMBER TO SUIT 2149				495647
143	11/22/2017	702132	LENS RED TO SUIT 2319				495647
143	11/22/2017	702132	LENS TO SUIT 2143 LAMP				495647
143	11/17/2017	702132	Engine - Steam clean all bus for RSI	done.			495647
143	11/17/2017	702400	LENS AMBER TO SUIT 2149				495647
143	11/17/2017	702400	Mechanic entered - Elec and Light Exterior Lights replace re	replaced all rear lenses.			495647
143	11/17/2017	702132	Body - Secure all lower skirt panels	done.			495647
143	11/16/2017	702132	Body repair n/s/rear top corner grip mold.	repaired.			495647
143	11/16/2017	702132	Body repair n/s concertina metal clamp	done			495647
143	11/15/2017	701870	AIRBAG DRIVE & TAG AXLE				495647
143	11/15/2017	701870	Mechanic entered - Suspension Leaning	replaced.			495647
143	11/15/2017	701440	Steering replace drag link.	replaced.			495647
143	11/15/2017	701440	Brakes replace park brake valve.	replaced.			495647
143	11/14/2017	701359	completed	PRE ANNUAL SAFETY INSPECTION CHECK			495647
143	11/14/2017	701440	DRAGLINK	Creditor #:'GB-MUL001 MULTISPARES LTD P/O #:'G207154 Receiving #:214193 Date :2017-11-14			495647
143	11/14/2017	701440	Steering replace both front torque rid bushes.	replaced.			495647
143	11/14/2017	701440	BUSH TORQUE ROD BUSH SCANIA/MERCEDES (1517403) (2520801)				495647
143	11/14/2017	701440	VALVE PARK BRAKE SCANIA L94	Creditor #:'GB-MUL001 MULTISPARES LTD P/O #:'G207154 Receiving #:214193 Date :2017-11-14			495647
143	11/13/2017	700750	AIR CON REFRIDGERANT				495647
143	11/13/2017	700750	BRUSH EMP AIR CON				495647
143	11/13/2017	700750	COMPRESSOR OIL AIR CON				495647
143	11/13/2017	700750	OIL COMPRESSOR OIL AIR CONDITIONING				495647
143	11/13/2017	700750	FILTER DRYER AIR COND 5/8 (3K171124)				495647
143	11/11/2017	700972	Mechanic entered - A/C Heating Not Cooling Condensor fan bru	Remove and pull down both condensor motors clean the stator and comutator remove failed rivet from brush holders and replace fitted and tested ok			495647
143	11/10/2017	700750	Mechanic entered - A/C Heating Noisy Evap fan motor has brok	Remove failed evap fan motor replaced with rebilt leeson motor align and fit into position both evap fan motor brackets are streched and will need to be replaced			495647
143	11/10/2017	700749		CARRY OUT A/C - B SERVICE AS PER CHECK LIST			495647
143	11/10/2017	700749		CARRY OUT A/C - A SERVICE AS PER CHECK LIST			495647
143	11/06/2017	699888	CCTV Warning Light On	As above			495275
143	11/06/2017	699888	Mechanic entered - CCTV Warning Light On	checked cctv system. found faulty ir receiver/warning light panel. replaced with stock working ok.			495275
143	11/06/2017	699879		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST completed firesafety inspection on artic bus. checked turntable and secured necessary wiring.			495275
143	11/06/2017	699878	Please remove the 2 x Do Not Enter decals at the exterior	removal complete			495275
143	11/02/2017	699344	Consumables				494984
143	11/02/2017	699344	Drv entered - Elec and Light Interior Lights	changed blown fluro tubes and fixed loose electrical connection in (1) tube end holder - saloon lights.			494725
143	10/24/2017	696752	PERFORM 19/17 DOOR BRAKE INTERLOCK FITMENT AUDIT	did the audit			493498
143	10/19/2017	695524	Engine Low Power when ac is on	checked when road tested bus for speedo and driving ok.			492977
143	10/19/2017	695524	Consumables				493225
143	10/19/2017	695524	Consumables				493225
143	10/19/2017	695524	Dash Speedo Not Working 60 % of the time	swapped sender went on road test and still not good.Removed dash checked plugs behind speedo traced and found loose wire crimp.Re crimped and put dash back together.went on road test and all working now.			492977
143	10/19/2017	695626	Consumables				493225
143	10/19/2017	695626	Consumables				493225
143	10/19/2017	695626	Consumables				493225
143	10/19/2017	695626	Consumables				493225
143	10/19/2017	695626	Consumables				493225
143	10/19/2017	695626	Consumables				493225
143	10/19/2017	695626	Consumables				493225
143	10/19/2017	695626	Consumables				493225
143	10/19/2017	695626	Consumables				493225
143	10/19/2017	695626	Consumables				493225
143	10/19/2017	695626	Consumables				493225
143	10/18/2017	695332	Vandalism - Replace anti graffiti film	CARRY OUT A SERVICE AS PER CHECK LIST completed.			492977
143	10/18/2017	695524	Dash Speedo Not Working 60 % of the time	CARRY OUT A SERVICE AS PER CHECK LIST completed.			492977
143	10/17/2017	694868	Remove old poster and fit new A3 Posters and hangers	Replaced by Glassprotech			492716
143	10/03/2017	691337		road tested the bus speedo droppin out intermintantly.Checked plug and loom going to it and sprayed with contacty cleaner went on road test again same issue.Want to swap sender over tommoro.			491300
143	10/03/2017	691337		REPLACED BY REFUELLERS			491300
143	10/03/2017	691337		Assisting			491300
143	10/02/2017	690946	Consumables	Tensioned pos 10 tyre.			491300
143	10/02/2017	690946	Consumables				491300
143	10/02/2017	690946	TYRE 275/70R22.5 RECAP				491300
143	10/02/2017	690946	Mechanic entered - Wheels and Tyres Damaged Pos 10 tyre dama	Replaced tyre pos 10 and re-tensioned with Sisil			491300
143	09/28/2017	690414	Suspension - Middle axle sway bar bush worn	fit new sway bar D bushes			491075
143	09/28/2017	690414	Body - NSR rear mudflap	Fit new mudflap			491075
143	09/27/2017	690156					490520
143	09/27/2017	690156		Done with Alex.			490520
143	09/27/2017	689335		CARRY OUT FIRE EXTINGUISHER TEST & TAG			490520
143	09/27/2017	689335		Replaced by ATS on 24/09/17			490520
143	09/26/2017	689503		VEHICLE SAFETY INSPECTION Safety Inspection Completed			490646
143	09/26/2017	689503		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS			490646
143	09/26/2017	689503		VEHICLE SAFETY INSPECTION Safety Inspection Completed			490646
143	09/26/2017	689779	Consumables				490920
143	09/26/2017	689779	Elec and Light - 3 emer exit globes out	replaced			490646
143	09/26/2017	689779	Body - Side mirror arm bent	Straightened			490646
143	09/26/2017	689606	SET DISC PAD SET SCANIA / MERCEDES 0500				490646
143	09/26/2017	689606	Mechanic entered - Brakes Other Middle axle brake pads worn	Replaced brake pads with Alan and tensioned all wheel nuts			490646
143	09/26/2017	689820	Remove old A3 Posters with Seniors Festival please leave	Replaced by Fleet Support			490646
143	09/25/2017	688745	Consumables				490520
143	09/25/2017	688745	Drv entered - Dash Speedo Not Working	checked speedo and odometer on road test speed is correct according to gps and odometer is correct. complete			490520
143	09/25/2017	688745	PERFORM CAMPAIGN 09/17 REAR DOOR WARNING SIGNS	fit do not enter sign to middle door and rear door. complete			490520

143	09/25/2017	688745	DO NOT ENTER REAR DOOR DECAL 125MM REED/WHITE		490520
143	09/20/2017	687593	BUSH SWAY BAR BUSH D-SHAPE MID AXLE SCANIA L94		489268
143	09/19/2017	687593	Suspension - Mid axle sway bar bushes worn	R/R mid axle sway bar bushes.	489268
143	09/19/2017	687262	Consumables		490058
143	09/19/2017	687262	GLOBE 24V 1.2W WEDGE LED DASH (SWFLED) 17040 E-596WLED		489268
143	09/19/2017	687262	GLOBE & HOLDER INSTRUMENT PANEL GREY (NR47774)		489268
143	09/19/2017	687262	LIGHT SOCKET		489268
143	09/18/2017	687262	Drv entered - Dash Dash_Lights Not Working	replaced speedo and switch dash globes.	489268
143	09/15/2017	686657	Consumables		489684
143	09/15/2017	686657	Drv entered - Elec and Light Exterior Lights	Replaced N/S headlight globe	489268
143	09/13/2017	686302	MOTOR WIPER MOTOR	Creditor #-GB-KIR001 KIRG IMPORTERS PTY LTD P/O #-G202738 Receiving #-209767 Date :2017-09-13	489268
143	09/13/2017	686302	Wipers and Washers Wipers Not Working	connected linkage to motor tested working ok. parked bus.	489268
143	09/13/2017	686302	Wipers and Washers Wipers Not Working	took off old wiper motor fitted new one. passed over to matt	489268
143	09/13/2017	686303	Consumables		489268
143	09/13/2017	686303	FUSE BLADE 10 AMP (NR52810)		489268
143	09/13/2017	686303	HOLDER FUSE HOLDER NARVA INLINE (54406BL)		489268
143	09/13/2017	686303	Fit bus minder	fit bus minder. had to replace usb socket due to supplied socket being faulty. complete working ok.	489268
143	09/13/2017	686303	BROOM HANDLE (8232715)		489268
143	09/13/2017	686303	BROOM HEAD (07890234)		489268
143	09/12/2017	686029	Consumables		489268
143	09/12/2017	686029	Drv entered - Elec and Light Indicators Not Working	fitted new globe all working now	489032
143	09/04/2017	683578	COMPUTER SLRT/RM-RP		488433
143	09/04/2017	683578	PANEL RELAY PANEL 24 Volt		488433
143	09/04/2017	683578	DASH PANEL ROUTE BUS		488433
143	08/31/2017	683578	Ops Entered - Fault - A/C Heating Not Heating - Route: 812d	Tested found the the CCC ESP and dash controller needed to be replaced rewired the boost pumps and tested found that the bus is unable to maintain tempreture	488179
143	08/30/2017	683536	Mechanic entered - Vandalism Vandalism/ Graffiti Interior	Cleaned	488179
143	08/22/2017	681557	Ops Entered - Fault - Air System Air_Leak Rear - Route: -	check and fixed lavalng value rod bus ok.	487121
143	08/02/2017	677634	Consumables		485930
143	08/02/2017	677634	HEADLAMP HI-LOW RECTANGULAR MK3 B10M (72086) (1043)		485780
143	08/02/2017	677634	GLOBE 24V 75/70W H4		485780
143	08/02/2017	677634	Drv entered - Elec and Light Exterior Lights	changed blown globes (ns) low beam headlight and (nsf) bottom park light. replaced damaged headlight insert.	485780
143	08/02/2017	677634	GLOBE 24V 2W		485780
143	07/26/2017	676239	Consumables		485301
143	07/26/2017	676239	LAMP INDICATOR [ORANGE]		485185
143	07/26/2017	676239	LENS TO SUIT 2029 (RED & AMBER)		485185
143	07/26/2017	676239	Mechanic entered - Elec and Light Exterior Lights o/s/f corn	fitted two lens all ok	485185
143	07/19/2017	674893	Accident damage - O/S/R bumper - Acc # DAN 45350. THIRD PAR	completed on W/O 674887	484422
143	07/19/2017	674887	Accident damage - Rear - Acc # DAN 45350. *THIRD PARTY AT F	Touched up O/S/R bumper corner.	484422
143	07/12/2017	673361	Consumables		484171
143	07/12/2017	673361	LENS NARVA AMBER/RED		484171
143	07/12/2017	673361	osr side clearance light lens missing(reported by Geoff)	fitted lens ok	484171
143	07/10/2017	672717		Ref to w/o # 671856	483602
143	07/05/2017	671856	Wheels and Tyres - carry out full retorque as required on a	carried out full retorque on all axles LDM AND HIRAN	482835
143	07/05/2017	672156	Consumables		483602
143	07/05/2017	672159	Consumables		483602
143	07/05/2017	672156	Mechanic entered - Elec and Light Other n/s/r marker light n	replaced n/s/r marker light globe ok	482835
143	07/05/2017	672159	Elec and Light - n/s/r marker light	double entry	482835
143	07/02/2017	671353	PERFORM CAMPAIGN 05/17 BUS DESTINATION PROGRAM UPDATE	carried out campaign as required	482835
143	06/30/2017	670929	TYRE 275/70R22.5 RECAP		482835
143	06/30/2017	670929	Consumables		483085
143	06/30/2017	671105	GLOBE 24V 10W SINGLE CONTACT		482835
143	06/30/2017	671105	COVER BUS STOPPING SIGN		482835
143	06/30/2017	671105	Consumables		483085
143	06/29/2017	670811		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	482835
143	06/29/2017	670811		VEHICLE SAFETY INSPECTION completed.	482835
143	06/29/2017	670811		VEHICLE SAFETY INSPECTION completed.	482835
143	06/29/2017	670929	Wheels and Tyres - Tyre 8 worn	Replaced tyres position 8 and 9 and tensioned all wheel nuts with Alan	482835
143	06/29/2017	671105	Elec and Light - Rear emer door light n/w	Replaced	482835
143	06/29/2017	671105	Elec and Light - Bus stop light n/w & cover broken	replaced	482835
143	06/29/2017	671105	Body - Rear yellow step strip missing	Replaced	482835
143	06/29/2017	670810	Consumables		482920
143	06/29/2017	670810	Consumables		482920
143	06/29/2017	670810	Consumables		482920
143	06/29/2017	670810	Consumables		482920
143	06/29/2017	670810	Consumables	CARRY OUT B SERVICE AS PER CHECK LIST completed	482835
143	06/29/2017	670810	KIT O-RING OIL SPINNER FILTER SCANIA ABOVE ENG #6203050		482835
143	06/29/2017	670810	FILTER OIL SCANIA SR4 [EARLY] K320 (LF3730) (H200W20)		482835
143	06/29/2017	670810	FILTER TRANSMISSION ZF (4139-298-038) (4139 298 038 01)		482835
143	06/29/2017	670810	FILTER FUEL FILTER ETHANOL SCANIA SR4 (H17WK04)		482835
143	06/29/2017	670810	Consumables		482920
143	06/29/2017	670810	Consumables		482920
143	06/29/2017	670810	Consumables		482920
143	06/29/2017	670810	Consumables		482920
143	06/29/2017	670810	Consumables		482920
143	06/29/2017	670810	Consumables	CARRY OUT A SERVICE AS PER CHECK LIST	482835
143	06/29/2017	670810	Consumables		482920
143	06/21/2017	668969	Remove old Green 2016/17 registration Label and/ or Blue EF	Replacedl	482219
143	06/19/2017	668104	Consumables		482185
143	06/19/2017	668104	GLOBE 24V 21/5W STOP AND TAIL LAMP (17925)		481955
143	06/19/2017	668104	Mechanic entered - Elec and Light Exterior Lights	Replaced O/S/R brakr light globe	481955
143	06/16/2017	667696	SWITCH 3 POSITION SWITCH CENTRE OFF SPRING LOADED		481835
143	06/15/2017	667696	Body front door switch u/s.	replaced.	481755
143	06/09/2017	666709	PERFORM CAMPAIGN 17/16 DASH SWITCH LABELLING	fitted labeling	481435
143	06/02/2017	665148	Consumables		481066
143	06/02/2017	665148	Elec and Light (None) / jackknife	checked edc. cleaned up connections at computer. roadtested could not fault. pti fuelled and parked bus. complete.	481006
143	06/02/2017	665148	HOLDER FUSE HOLDER NARVA INLINE (54406BL)		481006
143	06/02/2017	665407	Mechanic entered - Body Other passenger pole loose	found pole loose and missing screws. replaced screws and secured pole into position. complete.	481006
143	06/01/2017	665148	Elec and Light (None) / jackknife	checked bus. clearted codes related to fault. roadtested fault for edc came back began checking edc. carry over.	481006
143	05/30/2017	664292		TRANSMISSION CHECK AS PER CHECK LIST	480820
143	05/30/2017	664292		completed	480820
143	05/23/2017	662913	Consumables		480468
143	05/23/2017	662913	Fit A3 Poster/Hangers	Fitted	480343
143	04/21/2017	657416	Body - check Ventura decals	Now at Moorabbin	477712

143	04/12/2017	656159	MIRROR RIGHT HAND BRAZILIAN			477273
143	04/12/2017	656159	Body - R/H mirror broken	R/R mirror.		477273
143	04/10/2017	655730		Assisting		477057
143	04/10/2017	655730		Tensioned pos 9 and 10 tyres.		477057
143	04/10/2017	655348	Consumables			477141
143	04/10/2017	655348	TYRE 275/70R22.5 RECAP			477057
143	04/07/2017	655346		Assisting		477057
143	04/07/2017	655346		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		477057
143	04/07/2017	655346		VEHICLE SAFETY INSPECTION		477057
143	04/07/2017	655348	Wheels and Tyres Worn pos 9 tyre	Assisting		477057
143	04/07/2017	655348	Wheels and Tyres Worn pos 9 tyre	R/R pos 9 tyre and tensioned wheel nuts		477057
143	04/07/2017	655370	Body - Handbrake panel missing screw	Fitted new scerw		477057
143	04/01/2017	639780	Consumables			476598
143	04/01/2017	639780	ELECTRICAL REPAIR	Creditor #:GB-BWE001 BWERE ELECTRICS P/O #:G185788 Receiving #:197919 Date :2017-04-07 SUPPLY & FIT ROLLAWAY		477057
143	03/07/2017	649561	Vandalism Vandalism/ Graffiti Interior Graffiti on floor	Bus was graffiti refurbished inside.		474600
143	03/07/2017	649560	Vandalism Vandalism/ Graffiti Interior Etching in Window	Bus was graffiti refurbished inside		474600
143	02/25/2017	647712	Mechanic entered - Body Other INT mirror loose	Tighten mirror		473663
143	02/24/2017	647458	BELT CRANK-TWIN A/C COMP SC- ARTIC 8PK2000			473663
143	02/24/2017	647458	Engine Belts_Loose Noisy Missing	replaced broken inner A/C belt road tested ok		473663
143	02/24/2017	647458	Consumables			473740
143	02/24/2017	647458	GLOBE 24V 75/70W H4			473663
143	02/24/2017	647458	Mechanic entered - Elec and Light Exterior Lights O/F head l	replaced globe		473663
143	02/24/2017	647458	Mechanic entered - Elec and Light Exterior Lights O/F top pa	replaced globe		473663
143	02/24/2017	647458	GLOBE 24V 10W SINGLE CONTACT			473663
143	02/20/2017	646133	Please remove any old poster and fit either Good News for T	Fitted by Fleet Support		473177
143	02/17/2017	645548	PERFORM CAMPAIGN 01/17 SMARTRAK DRIVER CONTROL CONSOLE AUDIT	DCC FITTED - YES TIME DISPLAYED - YES		473177
143	02/15/2017	644847	Consumables			473080
143	02/15/2017	644847	Consumables			473080
143	02/15/2017	644847	Consumables			473080
143	02/15/2017	644847	Consumables			473080
143	02/15/2017	644847		CARRY OUT A SERVICE AS PER CHECK LIST A service completed with wheel nut retensions and steam washed bus		472908
143	02/15/2017	644847		A Service Completed and steam wash engine		472908
143	02/07/2017	643313	Ops Entered - Fault - Engine Low Power - Route: 811d - Cntr	check and road test bus ok.		472548
143	01/19/2017	639794	Consumables			471329
143	01/19/2017	639794	tyre number 7 flat	tyre #7 checked - low pressure (80psi). tyre 8 also 80psi. inflated both to specs. **no wheels nor nuts removed**.		471321
143	01/19/2017	639780	Consumables			471329
143	01/19/2017	639843	Consumables			471329
143	01/19/2017	639803	Consumables			471329
143	01/19/2017	639843	Elec and Light Jackknight light on	Ass Neven with recharging hydraulic system in t/table		471321
143	01/19/2017	639843	Elec and Light Jackknight light on	fill oil in concertino hydraulic system		471321
143	01/19/2017	639803	BELT CRANK-TWIN A/C COMP SC- ARTIC 8PK2000			471321
143	01/19/2017	639803	Elec and Light - Broken belt	Replace belt and idle pooley bearing		471321
143	01/19/2017	639803	BEARING ALTERNATOR+SPIGOT BEARING G7			471321
143	01/19/2017	639780	PERFORM CAMPAIGN 08/16 BUS ROLLAWAY PREVENTION DEVICE (RPD)	COMPLETED BY BRADMAN		471321
143	01/09/2017	637589		VEHICLE SAFETY INSPECTION		470110
143	01/09/2017	637589	REFILL WIPER REFILL TO SUIT TX800 / TX900			470110
143	01/09/2017	637589		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		470110
143	01/09/2017	637589		VEHICLE SAFETY INSPECTION		470110
143	01/05/2017	637157	Fit New 2107 Large and Small Fares Small Concessionand AO	Replaced		470110
143	12/08/2016	631150	DIRECT PURCHASE - BUS INSPECTI	Creditor #:GB-ROA001 Road Safety Inspections P/O #:G182796 Receiving #:189363 Date :2016-12-08		468092
143	12/02/2016	631150		ANNUAL SAFETY INSPECTION - RWCO08061 - PASSED - 02/12/16		467517
143	12/02/2016	631341	VALVE FOOTBRAKE WITH RETARDE	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G182850 Receiving #:189076 Date :2016-12-02		467668
143	12/02/2016	631341	Brakes Foot valve leaking	Replaced		467517
143	12/01/2016	622567	Supply and apply PTV decal for	Creditor #:GB-LAB010 LABEL CONCEPTS P/O #:G179947 Receiving #:190082 Date :2016-12-20		468813
143	11/22/2016	629269	one belt brokin	checked belts ok checked one belt in questin with ranjith and ok.		466666
143	11/17/2016	628514		Tensioned pos 3 & 4 wheel nuts		466327
143	11/17/2016	628514		Assisting		466327
143	11/16/2016	627982	Body - RH 1st seat cushion torn	fit new cushion.		466208
143	11/15/2016	627760	BUSH SWAY BAR FRONT SCANIA SR4 & K230 0469081 1919010			466208
143	11/15/2016	627760	BUSH SWAY BAR BUSH D-SHAPE MID AXLE SCANIA L94			466208
143	11/15/2016	627760	Suspension - Front axle sway bar bushes worn	fit new bushes.		466208
143	11/15/2016	627760	Suspension - Middle axle sway bar D bush worn	fit new bushes.		466208
143	11/15/2016	627760	A/C Heating - Fit new short a/c belts	fit new a/c belts.		466208
143	11/15/2016	627760	BELT V-BELT COGGED TRI-POWER 17x1145mm			466208
143	11/15/2016	627760	Engine - Secure tail pipe	fit new bolts and secure.		466208
143	11/15/2016	627760	Consumables			466208
143	11/15/2016	627760	WEAR SENSOR SCANIA DISC BRAKE 40G8401			466208
143	11/15/2016	627760	Elec and Light - Brake wear light on dash (electrical)	traced fault to mid axle left brake wear sensorfitted new sensor wire.		466208
143	11/15/2016	627760	SEAT BASE DOUBLE SEAT BASE RETRIMMED			466208
143	11/15/2016	627760	Body - Fit new invalid sticker	fit new stickers.		466208
143	11/15/2016	627760	Body - Fit No Standing on Turntable sticker	fitted		466208
143	11/15/2016	627760	Body - Secure pass hand rail at roof (RHS)	fit new screws and secure hand rail.		466208
143	11/14/2016	627658		PRE ANNUAL SAFETY INSPECTION CHECK		466208
143	11/11/2016	627518	Consumables			466067
143	11/11/2016	627518	Elec and Light - Found loose wiring in t/table	REPAIRED		466000
143	11/11/2016	627518	Elec and Light - Found loose wiring underneath	REPAIRED		466000
143	11/11/2016	627327		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST did the fire saftey		466000
143	11/02/2016	625304	A/C Heating Noisy: particularly the drivers fan	Repaired by Daniel @ 22c		465223
143	11/02/2016	625203	AIR CONDITIONING SERVICE	Creditor #:GB-22C001 22 CELSIUS P/O #:G180519 Receiving #:188731 Date :2016-11-30 A SERVICE		467400
143	11/02/2016	625203	Daniel @22c Replaced drier filters repaired open circuit fo	CARRY OUT A/C - A SERVICE AS PER CHECK LIST		465223
143	10/31/2016	625004	Consumables			465339
143	10/31/2016	625004	Elec and Light Exterior Lights	checked all lights. all good. checked camera. adjusted time. checkedfootage and it was recording.		465223
143	10/31/2016	625004	CCTV Warning Light On. Video loss throughout footage and	checked all lights. all good. checked camera. adjusted time. checkedfootage and it was recording.		465223
143	10/28/2016	624601	Accident damage - O/S/F - Acc # 44313. *INTERNAL*.			465190
143	10/28/2016	624601	INDICATOR LIGHT FRONT ARTIC			465190
143	10/26/2016	623492	DIFFUSER INTERIOR LIGHT (price per metre)			464991
143	10/26/2016	623492	Vandalism - Graffiti Inside of Bus			464991
143	10/26/2016	623492	BODY SHOP SUPPLIES			464991
143	10/26/2016	623492	CLEANER GRAFFITI REMOVER AMERASE PER LITRE			464991
143	10/26/2016	623492	HARDENER DELFLEET GRAFFITI RESISTANT PER 500ML			464991
143	10/26/2016	623492	PAINT ANTI GRAFFITI PAINT SATIN BLACK			464991
143	10/26/2016	623492	PAINT ANTI GRAFFITI PAINT DARK GREY			464991
143	10/26/2016	623492	PAINT ANTI GRAFFITI PAINT LIGHT GREY			464991

143	10/26/2016	624208	Fit A3 poster to holder either Explore Melbourne or PTV Ap	Fitted by Fleet Support	465034
143	10/25/2016	623492	Vandalism - Graffiti inside of Bus		464991
143	10/25/2016	623492	Vandalism - Graffiti inside of Bus		464991
143	10/25/2016	622567	PAINT SUPPLIES		464991
143	10/25/2016	622567	BODY SHOP SUPPLIES		464991
143	10/24/2016	623492	STRUT GAS STAY 600Nm 540mm LONG		464991
143	10/24/2016	623492	Vandalism Vandalism/ Graffiti Interior	refit o/s/r panel replace gas strut	464991
143	10/24/2016	623492	Vandalism - Graffiti inside of Bus		464991
143	10/24/2016	623492	Vandalism Vandalism/ Graffiti Interior		464991
143	10/24/2016	623442	Vandalism - Graffiti inside of Bus	ref to w/o 623492	464991
143	10/24/2016	623442	Vandalism - Graffiti inside of Bus	ref to w/o 623492	464991
143	10/24/2016	623442	Drv entered - Vandalism Vandalism/ Graffiti Interior		464991
143	10/24/2016	623442	Vandalism Vandalism/ Graffiti Interior		464991
143	10/24/2016	623442	Vandalism Vandalism/ Graffiti Interior		464991
143	10/24/2016	623442	Drv entered - Vandalism Vandalism/ Graffiti Interior		464991
143	10/24/2016	622567	UNREPORTED damage O/S/R		464991
143	10/21/2016	623297	Vandalism Vandalism/ Graffiti Interior	rebooked	464991
143	10/21/2016	623297	Vandalism Vandalism/ Graffiti Interior	rebooked	464991
143	10/21/2016	623200	Consumables		464991
143	10/21/2016	623200	FLOURO TUBE CLIP LAQ37/ VOLGREN		464991
143	10/21/2016	623200	FLOURO TUBE END LA140 VOLGREN		464991
143	10/21/2016	623200	Elec and Light Interior Lights o/s/r saloon light holder	replaced broken fluro tube ends and blown fluro tube - saloon light.	464991
143	10/21/2016	622567	UNREPORTED - OSR panel damage		464991
143	10/20/2016	622567	SHEET FLAT ALUMINIUM 3x1200x2400mm		464790
143	10/20/2016	622567	UNREPORTED - OSR panel damage		464790
143	10/20/2016	622567	UNREPORTED - OSR panel damage		464790
143	10/14/2016	621967	CCTV Some cameras CCTV not recording	found camera was not recording. fitting with new second hand one ajusted and working correctly	464426
143	10/14/2016	621985	SWITCH AIR LUMBAR SWITCH COMPLETE LH+RH		464426
143	10/14/2016	621985	Body Drivers Seat lower lumber support n/w and o/s passeng	replaced old damaged parts with new job completed	464426
143	10/12/2016	621363	Consumables		464357
143	10/12/2016	621363	GLOBE 24V 3W FESTOON		464198
143	10/12/2016	621363	HEADLAMP HI-LOW RECTANGULAR MK3 B10M (72086)		464198
143	10/11/2016	621330			464198
143	10/11/2016	621330		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	464198
143	10/11/2016	621330		VEHICLE SAFETY INSPECTION	464198
143	10/11/2016	621363	Elec and Light - O/S emergency exit light n/w and o/s/f hea	R/R globes and replaced headlight .	464198
143	10/11/2016	621361	Body - N/S grab postmodesty panel missing screw need to s	replaced screws	464198
143	09/27/2016	618556	Consumables		463211
143	09/27/2016	618556	DECAL CUSTOMER ENQUIRY		463211
143	09/26/2016	618556	A3 Poster Change please remove old poster and fit Vitorian	Completed by Fleet Support	463211
143	09/26/2016	618556	Body - Replace 1300 decal	Completed by Fleet Support	463211
143	09/26/2016	618337	Consumables		463211
143	09/26/2016	618337	Consumables		463211
143	09/26/2016	618337	Consumables		463211
143	09/26/2016	618337	Consumables		463211
143	09/26/2016	618337	Consumables		463211
143	09/26/2016	618337	FILTER OIL SCANIA SR4 [EARLY] K320 (LF3730) (H200W20)		463211
143	09/26/2016	618337	FILTER FUEL FILTER SCANIA SR4 (H17WK04)		463211
143	09/26/2016	618337	O-RING KIT OIL SPINNER FILTER SCANIA ABOVE ENG #6203050		463211
143	09/26/2016	618337			463211
143	09/26/2016	618337	FILTER TRANSMISSION ZF (4139-298-038) (4139 298 038 01)		463211
143	09/26/2016	618337		CARRY OUT B SERVICE AS PER CHECK LIST	463211
143	09/26/2016	618337	Consumables		463211
143	09/26/2016	618337	Consumables		463211
143	09/26/2016	618337	Consumables		463211
143	09/26/2016	618337	Consumables		463211
143	09/26/2016	618337	Consumables		463211
143	09/26/2016	618337	Consumables		463211
143	09/10/2016	612637	Consumables		462270
143	09/10/2016	612637	REPAIR SOTH PORT CONTROLER AS	Creditor #:GB-LON001 LONSDALE ST AUTO ELECTRICS P/O #:G1676001 Receiving #:183291 Date :2016-09-15	462551
143	09/10/2016	615645	Consumables		462270
143	09/10/2016	615645	Body - Remove till tray	removed & cleaned	462270
143	09/01/2016	613587	Consumables		461640
143	09/01/2016	612637	Repair south port desto controller as require	repaired by lonsdale	461125
143	09/01/2016	613587	Elec and Light - JACK KNIFE WARNING LIGHT ON	checked bus ok.	461125
143	09/01/2016	612637	Repair south port desto controller as require	fitted new desto controller and its working fine now	461125
143	08/16/2016	610032		re-tensioned nuts on wheels 3 and 4.	459940
143	08/15/2016	609782	Consumables		460092
143	08/15/2016	609782	Mechanic entered - Wheels and Tyres Flat or Leaking	removed tyres 3 and 4. removed leaking valve ext. inflated both to specs. re-fitted wheels. nuts tensioned.	459940
143	08/01/2016	607508	Consumables		458686
143	08/01/2016	607508	Please remove old poster and fit Route 709 A3 POSTER	n/a	458518
143	07/25/2016	605919	Campaign 10/16 WIFI CCTV UPGRADE -Round 2this campiang	completed by lonsdale on 8/06/16	457766
143	07/14/2016	603903		re-tensioned nuts on wheels 3; 4; 5 and 6.	456842
143	07/13/2016	603550		VEHICLE SAFETY INSPECTION Vehicle inspection completed	456842
143	07/13/2016	603550		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	456842
143	07/13/2016	603550		VEHICLE SAFETY INSPECTION Vehicle inspection completed	456842
143	07/13/2016	603680	Consumables		456919
143	07/13/2016	603680	Wheels and Tyres - Replace tyres 56	Replaced tyres position 5 and 6 with Alex	456842
143	07/13/2016	603680	Wheels and Tyres - Replace tyres 56	Replaced tyres position 5 and 6	456842
143	07/13/2016	603680	TYRE 275/70R22.5 RECAP		456842
143	07/12/2016	603423	Consumables		456919
143	07/12/2016	603423	GLOBE 24V 3W FESTOON		456842
143	07/12/2016	603423	emergency exit back and front door	changed blown festoons - exit lights.	456842
143	07/12/2016	603423	DECAL PLEASE KEEP CLEAR DOOR OPENS INWARDS		456842
143	07/12/2016	603423	emergency exit back and front door		456842
143	07/12/2016	603396	CCTV (None) Adjust camera position (rotate angle by 180 d	put new decal on first exit door.	456842
143	07/12/2016	603396	CCTV (None) Mirror Effect on Driver's Camera	fliped image 180 degs	456842
143	07/12/2016	603396	CCTV Warning Light On Video Loss Alarm on Hard Drive Unit	changed settings and now drivers camera does NOT show the mirroe effect	456842
143	07/12/2016	603620	PLEASE REMOVE ANY OLD POSTERS & FIT NEW A3 POSTER	could not see a warning light on unit and on thoreb display. all cameras on and recording	456842
143	06/14/2016	597377	Please remove any old poster and fit new A3 poster and add	Fleet Support	456919
143	06/09/2016	596724	PERFORM CAMPAIGN 04/16 DRIVERS WALLETS AND MAP POCKET INSTA	done by fleet support	454820
143	06/08/2016	596327	Fit new CCTV upgrade	Fitted	454458
143	06/08/2016	597345	-Replace Drivers Camera with a 2.1mm Thoreb unit-Place a	Creditor #:GB-LON001 LONSDALE ST AUTO ELECTRICS P/O #:G169833 Receiving #:176619 Date :2016-06-23	455769
143	06/08/2016	596327	CCTV - Fit new CCTV upgrade	Done by Lonsdale	454820
				Fitted by Lonsdale	454458

143	05/21/2016	593010	Consumables		453227
143	05/21/2016	593010	Consumables		453227
143	05/21/2016	593010	Consumables		453227
143	05/21/2016	593010	Consumables		453227
143	05/21/2016	593010		CARRY OUT A SERVICE AS PER CHECK LIST	453152
143	05/21/2016	593010		CARRY OUT A SERVICE AS PER CHECK LIST completed with shalen	453152
143	05/05/2016	589672	VALVE FOUR WAY SCANIA	Creditor #;GB-MUL001 MULTISPARES LTD P/O #:G167525 Receiving #:173280 Date :2016-05-05	452006
143	05/05/2016	589672	Ops Entered - Fault - Air System Air_Leak Front - Route: 81	Removed rear 4 way valve and check air pipe from compressor for block. Cleaned air pipes and refit 4 way valve ok. Washed the engine drive tested and check the operation of the brake. Working normal in heavy traffic. Recheck for air leak engine oil leaks and collant leaks.OK. Check engine oil and coolant levelAll OK.	451912
143	05/04/2016	589672	BOLT COMPRESSOR GEAR	Creditor #;GB-MUL001 MULTISPARES LTD P/O #:G167431 Receiving #:173205 Date :2016-05-04	451912
143	05/04/2016	589672	Ops Entered - Fault - Air System Air_Leak Front - Route: 81	Fitted new air compressor and fill coolant in the system. Build up air and check the operation of the brake. Found the air gauge # 1 on dash is playing up. Removed and replaced 4 way protection (middle). Check the operation of the brake found air gauge # 2 on dash is playing up. C/F	451912
143	05/04/2016	589672	O RING COMPRESSOR MOUNT SCANIA L94		451912
143	05/03/2016	589672	O RING 11MM ID	Creditor #;GB-MUL001 MULTISPARES LTD P/O #:G167348 Receiving #:173188 Date :2016-05-04	451912
143	05/03/2016	589672	AIR COMPRESSOR SCANIA L94	Creditor #;GB-MUL001 MULTISPARES LTD P/O #:G167348 Receiving #:173188 Date :2016-05-04	451912
143	05/03/2016	589672	Ops Entered - Fault - Air System Air_Leak Front - Route: 81	Rectify air system fault. Check 4 way protection air valves for faults. ok. Measured air pressure in the 4 way protection valves all ok. Check air pressure coming from the air compressor found insufficient air. Drained coolant and removed air compressor. (waiting for parts) C/F	451912
143	05/02/2016	589337	FITTING STRAIGHT JOINER 6MM 11060600		451912
143	05/02/2016	589337	Ops Entered - Fault - Body Drivers Seat Controls - Route: 8	complete seat been replaced with reconditioned one.	451912
143	05/02/2016	589337	Body - Lumber support switches in drivers seat leaking air	complete seat been replaced with reconditioned one.	451912
143	05/02/2016	589337	Body - Driver seat needs complete overhaul	removed old seat and fitted returned reconditioned seat.	451912
143	04/14/2016	586245	Consumables		450823
143	04/14/2016	586245	SINGLE CONTACT GLOBE 24V 5W 17181		450668
143	04/14/2016	586245	24V DRIVERS FAN (USE FASCO ONLY)		450668
143	04/13/2016	586245			450668
143	04/13/2016	586245		TRANSMISSION CHECK AS PER CHECK LIST	450668
143	04/13/2016	586246			450668
143	04/13/2016	586246		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS done with phil	450668
143	04/13/2016	586246		VEHICLE SAFETY INSPECTION Completed with phil	450668
143	04/13/2016	586402	Consumables		450748
143	04/13/2016	586402	Elec and Light - REPLACE PARK LIGHT GLOBE	REPLACED	450668
143	04/13/2016	586245	Mechanic entered - Elec and Light Other Drivers fan not work	Remove and replace drivers fan reposition fan test works ok.	450668
143	04/05/2016	584449		re-tensioned nuts on wheels 7; 8; 9 and 10.	449938
143	04/04/2016	584108	Consumables		449938
143	04/04/2016	584108	TYRE RECAP 275/70R22.5		449938
143	04/01/2016	584108	Wheels and Tyres. tyer number 9 damage	Remove pos. 9&10 tyre tyre worn and one tyre sidewall damage. fitted two new recap tyre and tensioned wheel nuts.	449938
143	04/01/2016	584132	Mechanic entered - A/C Heating Belt Loose or_Missing	A/c belt worn replace fitted new belts and adjusted belt.	449938
143	04/01/2016	584132	BELT		449938
143	04/01/2016	584108	Ops Entered - Fault - Air System Leak - Route: 811d - Dande	Check for air leak check brake system operation no leak suspension no leak and door air system no leak.	449938
143	03/24/2016	583036	Consumables		449685
143	03/24/2016	583036	Drv entered - Elec and Light Interior Lights	replaced frond interior drivers salloon light and 2 carrige n/s salloon light.	449612
143	03/24/2016	583036	Drv entered - Elec and Light Interior Lights	assisted Elias	449612
143	03/12/2016	579808	Check and repair bus no power	fitted leek off line and air filter rpad tested.	448956
143	03/11/2016	579808	Check and repair bus no power	fit leek off line injector wire start the bus c/o	448956
143	03/10/2016	579808	REPAIR INJECTORS	Creditor #;GB-AGD001 AG DIESEL PUMPS & INJECTORS P/L P/O #:G163946 Receiving #:170810 Date :2016-03-30	449685
143	03/10/2016	579808	Check and repair bus no power	stert fit injectors	448956
143	03/08/2016	579808	Check and repair bus no power	removed injectors send for repair. adjust valve clearance. c/o	448956
143	03/07/2016	579808	Air System Air Not Building_Up	checked and found no4 injector u/s start remove injectors. c/o	448956
143	03/04/2016	579808	Air System Air Not Building_Up	out 3.45pm 1n 4.45 pm fault air won't bild up+ no pover bild up air switch a/c off driven to depot.	448956
143	02/25/2016	578105	Ops Entered - Breakdown - Breakdown Road Defect Affects Serv	check all bus serviceble.	448276
143	02/02/2016	573689	Consumables		446650
143	02/02/2016	573689	Elec and Light Exterior Lights / Headlights switch is bro	Replaced head light knob	446650
143	02/02/2016	573689	KNOB HEAD LIGHT SWITCH (037262	Creditor #;GB-MUL001 MULTISPARES LTD P/O #:G161347 Receiving #:167086 Date :2016-02-02	446650
143	01/19/2016	571728	The Campaign requires all Bus destinations systems to be in	10 X 106 N/A N/A	445466
143	01/18/2016	570902	CCTV - one videao camera n/w	Checked CCTV OK	445466
143	01/18/2016	570813	DECAL PTV METRO MYKI DECAL LARGE 450x330mm		445466
143	01/18/2016	570813	Campaign 23_15 A3 Poster Change		445466
143	01/16/2016	570527	Engine Low Power	Jack knif was on erased the code road tested ok	445466
143	01/13/2016	569488	PUMP WIPER-WASHER 24 VOLT 80826		445466
143	01/13/2016	569532	Consumables		445466
143	01/13/2016	569532	GLOBE FESTOON 24V-18W		445466
143	01/13/2016	569600	PERFORM CAMPAIGN 22/15 POSITIONING OF 2016 PTV FARES DECALS	Done	445466
143	01/12/2016	569484		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	445466
143	01/12/2016	569484		VEHICLE SAFETY INSPECTION	445466
143	01/12/2016	569484		done.	445466
143	01/12/2016	569488	Mechanic entered - Wipers and Washers Washers Not Working	Check operate washer found washer motor faulty change fitted new test works ok.	445466
143	01/12/2016	569531	Consumables		445466
143	01/12/2016	569532	Elec and Light - Replace emergency exit light	Replaced	445466
143	01/12/2016	569531	Ops Entered - Fault - Elec and Light Electric Mirrors Fault	Tightened mirror on drivers side	445466
143	01/12/2016	569532	CCTV - Last recording 15/10/15	Found camera was in off position turned on OK	445466
143	01/05/2016	568329	Consumables		445348
143	01/05/2016	568329	Elec and Light - Bus wont start	Jump started	445222
143	01/04/2016	568073		re-tensioned nuts on wheels 1 and 2.	445222
143	12/31/2015	567844	Consumables		445222
143	12/31/2015	567844	Mechanic entered - Wheels and Tyres Flat or Leaking	removed tyre 2 - valve stem loose. tightened lock nut. inflated tyre to specs. checked for leaks at stem. o.k. re-fitted wheel. all steer nuts tensioned with alex.	445222
143	12/07/2015	562319	DIRECT PURCHASE - BUS INSPECTI	Creditor #;GB-ROA001 Road Safety Inspections P/O #:G158847 Receiving #:164976 Date :2015-12-10	444401
143	12/05/2015	562319	BUTTON PUSH DRIVE		444039
143	12/04/2015	563068	TIE ROD ASSY K230	Creditor #;GB-MUL001 MULTISPARES LTD P/O #:G159032 Receiving #:164633 Date :2015-12-04	444039
143	12/04/2015	562319	Consumables		444039
143	12/04/2015	562319	Mechanic entered - Elec and Light Indicators Not Working HAZ	checked circuit. determined broken wire. ran new wire from control unit to hazard switch. working ok.	444039
143	12/03/2015	562319		ANNUAL SAFETY INSPECTION - RWC 046242 - PASSED - 04/12/15	443729
143	12/03/2015	563068	Steering Replace tie- rod	pick up tie rod from multispars adjust and fitted.	443729
143	12/03/2015	563068	Engine - Crank shaft seal front leaking oil and vibration da	steernk clean .	443729
143	12/03/2015	563068	Consumables		444039
143	12/03/2015	563068	FLASHER RELAY SUIT SCANIA K124IB 40V2402		443729
143	12/03/2015	563068	Elec and Light Exterior Lights / HAZARD NOT WORKING SOMETI	checked hazard switch and ok found the blinkengerber(flasher) not good so replaced with multispares one. now ok	443729
143	12/03/2015	563068	Body / LOOSE SCREWS ON LOWER SKIRT PANEL NXT TO FUEL HOLE	secured	443729
143	12/01/2015	562395	Consumables		443845
143	12/01/2015	562395	Ops Entered - Fault - Elec and Light Indicators Not Working	Completed	443729
143	11/26/2015	561479	DECAL MAKE YOUR MARK		443357
143	11/26/2015	561479	Camapign 20/15 Audit & Update of Safety Decals.Requires a		443357
143	11/25/2015	561169	INDICATOR STALK SCANIA SERIES	Creditor #;GB-MUL001 MULTISPARES LTD P/O #:G158547 Receiving #:164090 Date :2015-11-25	443236
143	11/25/2015	561169	Elec and Light Indicator not canceling	removed and replaced broken stalk	443236
143	11/25/2015	561169	Consumables		443357
143	11/24/2015	560632	O-RING KIT OIL SPINNER FILTER SCANIA ABOVE ENG #6203050		442950
143	11/24/2015	560632	FILTER OIL SCANIA SR4 EARLY K320 (LF3730)(2059778)(H200W20)		442950

143	11/24/2015	560632	FILTER TRANSMISSION ZF 4139-298-038/4139 298 038 01		442950
143	11/24/2015	560632	FILTER FUEL SCANIA SR4(H17WK04)		442950
143	11/24/2015	560632	Consumables		443236
143	11/24/2015	560632	Consumables		443236
143	11/24/2015	560632	Consumables		443236
143	11/24/2015	560632	Consumables		443236
143	11/23/2015	560632			442950
143	11/23/2015	560632		CARRY OUT B SERVICE AS PER CHECK LIST	442950
143	11/23/2015	560632		CARRY OUT A SERVICE AS PER CHECK LIST	442950
143	11/23/2015	560632	Consumables		443111
143	11/23/2015	560632	Consumables		443111
143	11/23/2015	560632	Consumables		443111
143	11/23/2015	560632	Consumables		443111
143	11/19/2015	559561	N/S engine mount crack	replaced	442750
143	11/19/2015	559889	Mechanic entered - Elec and Light Other repair insulation an	re insulated and repaired wiring in the turntable road tested to make sure all ok after and all good.	442750
143	11/19/2015	559889	Consumables		442875
143	11/19/2015	559827	Remove Old Poster and Fit new All Night Public Transport Po	Completed	442750
143	11/19/2015	559888		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST did the fire inspection	442750
143	11/18/2015	559495		PRE ANNUAL SAFETY INSPECTION CHECK completed	442750
143	11/18/2015	559561	TYRE RECAP 275/70R22.5	POS 7&8	442750
143	11/18/2015	559561	Pos 8 tyre need replace	changed pos 78 tyres and tensioned wheel nut with Rane	442750
143	11/18/2015	559561	Consumables		442750
143	11/18/2015	559561	MOUNT ENGINE SCANIA	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G158280 Receiving #:163935 Date :2015-11-18	442750
143	11/18/2015	559561	N/S engine mount crack	replaced	442750
143	11/18/2015	559561	AMBER LENS SUIT 2149		442750
143	11/18/2015	559561	STOP LAMP LENS		442750
143	11/18/2015	559561	driver light need fix	repaired	442750
143	11/18/2015	559561	N/S rear light lences crack need replace	replaced	442750
143	11/18/2015	559561	Consumables		442750
143	11/18/2015	559561	Steam clean all bus for RSI	completed	442750
143	11/09/2015	556558	A/C Heating Not Cooling	Checked Ok need check within two week	441850
143	11/09/2015	556558	Ops Entered - Fault - Elec and Light Interior Lights - Rout	check ok all interir light working.	441850
143	11/09/2015	556558	Consumables		442088
143	11/04/2015	556558	A/C Heating Not Cooling	Pressure tested system removed constantina and check hoses unable to detect leak released nitrogen and put a trace gas into system looked for leak using a electronic leak detector unable to find any leaks put a dye into system and charged with r134A sent out on road will look at on monday	441765
143	11/04/2015	556921		CARRY OUT A/C - B SERVICE AS PER CHECK LIST	441765
143	11/04/2015	556921		CARRY OUT A/C - A SERVICE AS PER CHECK LIST	441765
143	11/02/2015	556558	A/C Heating Not Cooling	Tested system found that the discharge service valave and cap are loose pressure tested system found unit has a leak unable to detect at this time will look at another day	441680
143	11/02/2015	556558	Drv entered - AC Heating Not Cooling		441680
143	10/29/2015	556161	Consumables		441680
143	10/29/2015	556161	Elec and Light - Bus wont start	Jump started	441523
143	10/23/2015	555068	Consumables		441302
143	10/23/2015	555068	Elec and Light Exterior Lights / Hazard lights not worki	checked. working ok.	441177
143	10/15/2015	553570			440693
143	10/15/2015	553570		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	440693
143	10/15/2015	553570		VEHICLE SAFETY INSPECTION	440693
143	10/15/2015	553612	Engine - Hydraulic fan oil leaking	Found fault hose fittings loose undo nut and retightened fittings topped up oil	440693
143	10/15/2015	553612	Consumables		440763
143	10/15/2015	553612	Complete task as instructed in Fleet Campaign 09/15	Completed	440693
143	10/15/2015	553612	Body - Screws loose lower skirt panel on fuel hole	Secured	440693
143	10/09/2015	552434		re-tensioned nuts on wheels 1; 2; 3 and 4.	440190
143	10/09/2015	552480	Consumables		440231
143	10/09/2015	552480	DOWN LIGHT LED		440190
143	10/09/2015	552480	Mechanic entered - Elec and Light Interior Lights	modified and repaired a/c duct at front door to accept led door light. fit working ok.	440190
143	10/07/2015	551202	Ops Entered - Fault - Steering Shakes/ Wobbles - Route: -	Fitted brake padstyrestensioned wheels.adjusted brakes.Road tested .Re-check front hubs - ok.	439950
143	10/07/2015	551202	INDICATOR LOOSE WHEEL NUT 33MM		439950
143	10/06/2015	551202	Ops Entered - Fault - Steering Shakes/ Wobbles - Route: -	R/R front brake rotorsfitted caliperstensioned hubs.To be cont'd.	439950
143	10/06/2015	551202	Ops Entered - Fault - Steering Shakes/ Wobbles - Route: -	road test and check front brake brake disc and pads low need to check both.	439950
143	10/06/2015	551202	BRAKE DISC 126.100-00	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G156577 Receiving #:161903 Date :2015-10-06	440065
143	10/06/2015	551202	DISC PAD SET SCANIA MB0500		439950
143	09/28/2015	549556	Replace A3 poster with Victorian Seniors Festival Poster	Replaced by refuellers	439876
143	09/28/2015	549528	Campaign 11/15. Fit 2 x Supplied Decals to Internal Saloo	Fitted	439876
143	09/24/2015	548662	Fluid Leaks Middle of bus Coolant Leak over turntable	suprevised Pascal to take down turntable and find cut hose so cut section out placed new hose and joiners and secured and put table back together	439741
143	09/24/2015	548662	Fluid Leaks Middle of bus Coolant Leak over turntable	suprevised Pascal to take down turntable and find cut hose so cut section out placed new hose and joiners and secured and put table back together	439741
143	09/24/2015	548662	Consumables		439834
143	09/24/2015	548662	Elec and Light Warning Light On Dash Red Battery Light On	Revoved coolant pipes to get to alternators.Removed some wires from the bus the removed alternators and put new ones on with old pullys.Re did everything and cleaned the bus.road tested checked and all ok now.	439741
143	09/24/2015	548662	Elec and Light Warning Light On Dash Red Battery Light On	Revoved coolant pipes to get to alternators.Removed some wires from the bus the removed alternators and put new ones on with old pullys.Re did everything and cleaned the bus.road tested checked and all ok now.	439741
143	09/23/2015	548662	Elec and Light Warning Light On Dash	ordered 2 alternators from lee	439741
143	09/23/2015	548662	ALTERNATOR 140AMP	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G156174 Receiving #:161463 Date :2015-09-23	439741
143	09/22/2015	548346	Consumables		439741
143	09/22/2015	548346	Ops Entered - Fault - Warning Lights Batteries - Route: 811	checked alternators and charge rate and wires found inner one not good bus had to go out so could not change alternators so just removed and replaced the regulators found inner one not good but replaced both.Road tested and all ok.	439583
143	09/22/2015	548346	Ops Entered - Fault - Warning Lights Batteries - Route: 811	checked alternators and charge rate and wires found inner one not good bus had to go out so could not change alternators so just removed and replaced the regulators found inner one not good but replaced both.Road tested and all ok.	439583
143	09/03/2015	545078	COAT HOOK DRIVERS WAS0004		438223
143	09/03/2015	545078	as per Campaign 08/15Fit Hi Vis Vest DecalFit Coat Hook	Fitted decal and hook	438223
143	08/27/2015	543793		re-tensioned nuts on wheels 3 and 4.	437628
143	08/27/2015	543621	TYRE RECAP 275/70R22.5		437628
143	08/26/2015	543621	Wheels and Tyres Flat pos4	Replaced	437476
143	08/21/2015	542682	Consumables		437351
143	08/21/2015	542682	GLOBE FESTOON 24V 5W		437158
143	08/21/2015	542682	Mechanic entered - Elec and Light Exterior Lights	changed blown globe/festoon (nsf) bottom park and (ns) mid clearance lights.	437158
143	08/20/2015	542752	A3 Poster Change on Route buses for Legacy Week 30/08/15-05	Replaced	437231
143	08/14/2015	541123		re-tensioned nuts on wheels 3 and 4.	436763
143	08/14/2015	541126	Consumables		436795
143	08/14/2015	541126	Mechanic entered - Elec and Light Interior Lights change blu	removed blue fluro lights and replaced them with white fluro lights. also had to replace two fluro ends. checked and worked fine.	436763
143	08/14/2015	541126	FLOURO TUBE CLIP LA037/ VOLGREN		436763
143	08/14/2015	541126	FLOURO TUBE END LA140 VOLGREN		436763
143	08/13/2015	540750	EXTENSION FLEXIBLE TYRE VALVE 180mm LONG		436478
143	08/13/2015	540769	Consumables		436763
143	08/13/2015	540769	GLOBE 24V 75/70W H4		436478
143	08/13/2015	540769	Ops Entered - Fault - Elec and Light Exterior Lights - Rout	removed panel and replaced globe put back panel.	436478
143	08/12/2015	540750	Wheels and Tyres Flat or Leaking pos 4	Replaced leaking tyre valve for pos 4 tyre pumped up tyre tensioned wheel nuts	436478
143	07/29/2015	537917	Complete Campaign 6/15 A3 Marketing Poster Change	Replaced	435179
143	07/21/2015	536601		re-tensioned nuts on wheels 3; 4; 5 and 6 with dulkith.	434514
143	07/21/2015	536808	Suspension - V bar bush worn	Assisted Kumar.	434514

143	07/21/2015	536808	Suspension - V bar bush worn	Completed	434514
143	07/20/2015	536463	EXTENSION FLEXIBLE TYRE VALVE 180mm LONG		434514
143	07/20/2015	536463	CLAMP SUIT TYRE VALE EXTENSION T18 & T19		434514
143	07/20/2015	536463	TYRE RECAP 275/70R22.5		434514
143	07/20/2015	536808	V STAY ASSEMBLY L94	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G153816 Receiving #:158872 Date :2015-07-21	434809
143	07/20/2015	536463	BRAKE PADS M/B O500LE (49G7501)		434514
143	07/18/2015	536314		change park light globe nsf top.	434514
143	07/18/2015	536314		change a/c belt.	434514
143	07/18/2015	536314		change one interior light holder clip and globe.	434514
143	07/18/2015	536314		change passanger door open value front under bumper.	434514
143	07/18/2015	536314		did safty inspection.	434514
143	07/18/2015	536314		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	434514
143	07/18/2015	536314		VEHICLE SAFETY INSPECTION	434514
143	07/18/2015	536463	Wheels and Tyres - Rear o/s tyre pressure low	Inflated OK	434514
143	07/18/2015	536463	Wheels and Tyres - NS tyre 4 flat	Replaced 34 returned 3 to rack	434514
143	07/18/2015	536314	BELT		434514
143	07/18/2015	536314	VALVE CLIPPARD DOOR OPEN/CLOSE (11916-2) BUTTON		434514
143	07/18/2015	536486	Engine Low Power	checked ok	434514
143	07/18/2015	536314	Consumables		434514
143	07/18/2015	536314	GLOBE S/CONTACT 24V-10W		434514
143	07/18/2015	536314	FLOURO TUBE CLIP LA037/ VOLGREN		434514
143	07/18/2015	536314	FLOURO TUBE END LA140 VOLGREN		434514
143	07/18/2015	536463	Brakes - NS middle axle brake booster leaking	checked found brake booster clamp loose retightened clamp checked OK	434514
143	07/18/2015	536463	Brakes - Middle axle brake pads worn	Replaced brake pads and adjusted sensors	434514
143	07/18/2015	536314	WEAR SENSOR SCANIA DISC BRAKE 40G8401		434514
143	07/07/2015	534575	NO 0 WHITE 25MM		434007
143	07/07/2015	534575	NO 1 WHITE 25MM		434007
143	07/07/2015	534575	DECAL MAX SAFE CARRY WHITE ON CLEAR		434007
143	07/07/2015	534575	EMERGENCY PROCEDURE DECAL		434007
143	07/07/2015	534575	DECAL VIDEO AND AUDIO SURVEILLANCE		434007
143	07/07/2015	534575	Audit Route buses for correct Decals and positions. Replace		434007
143	07/07/2015	534575	NO 6 WHITE 25MM		434007
143	06/19/2015	531918	Ops Entered - Fault - Wipers and Washers Wipers Loose -	tightened loose wiper arms - both sides. replaced rusted circlips (ns) wiper arms.	433037
143	06/18/2015	531649	Body Yellow strip missing	Fitted	432988
143	06/18/2015	531648	BodyReplace passanger seat cushin	Replaced	432988
143	06/18/2015	531631	Consumables		433037
143	06/18/2015	531631	Consumables		433037
143	06/18/2015	531631	Consumables		433037
143	06/18/2015	531631	Consumables		433037
143	06/18/2015	531631		A SERVICE AS PER CHECK LIST	432988
143	06/18/2015	531631	FESTOON GLOBE 24V/3W		432988
143	06/18/2015	531631		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	432988
143	06/18/2015	531631		A SERVICE AS PER CHECK LIST	432988
143	06/05/2015	529854	CCTV CAMERA 2.5MM		431898
143	06/05/2015	529854	Drivers CCTV Camera is broken	replaced broken camera adjusted tim to correct time	431898
143	05/19/2015	526708		re-tensioned nuts on wheels 1 and 2.	430364
143	05/18/2015	526554	Wheels and Tyres Vibration		430364
143	05/18/2015	526554	Wheels and Tyres Vibration		430364
143	05/18/2015	526554	TYRE NEW 275/70R22.5	removed front 2 tyres fitted new ones and washed and cleaned.	430364
143	05/04/2015	524565	Consumables		429332
143	05/04/2015	524565	Elec and Light - Park lights n/w	Found broken wire in t/table repaired OK	429332
143	05/01/2015	524092	Consumables		429297
143	05/01/2015	524092	Elec and Light - Parklight out at rear		429297
143	05/01/2015	524092	Mechanic entered - Elec and Light Exterior Lights last 2 cl		429297
143	05/01/2015	524092	GLOBE FESTOON 24V 5W		429297
143	05/01/2015	524092	Mechanic entered - Elec and Light Exterior Lights	changed blown festoon - (osf) clearance light.	429297
143	05/01/2015	522385	BRAKE BOOSTER L94UAB 35CLE0100 49G2538WABCO		429297
143	04/23/2015	522675		re-tensioned nuts on wheels 3; 4; 5; 6; 7; 8; 9 and 10.	428561
143	04/21/2015	522377		complete	428515
143	04/21/2015	522377		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	428515
143	04/21/2015	522377			428515
143	04/21/2015	522535	Consumables		428561
143	04/21/2015	522535	Elec and Light - Check indicators	Checked and found indicator fault	428561
143	04/21/2015	522385	Brakes O/S drive axle brake booster leaking air.	R/R booster and tensioned w/nuts.	428515
143	04/20/2015	520029	PTV REBRAND - Method 2. {ARTIC VEHICLE}	Rebrand and wheels	428515
143	04/20/2015	520029	PTV REBRAND - Method 2. {ARTIC VEHICLE}	Rebrand	428515
143	04/20/2015	520029	GLOBE FESTOON 24V 5W		428515
143	04/20/2015	520029	LAMP INDICATOR {ORANGE}		428515
143	04/20/2015	520029	LAMP (RED+AMBER)		428515
143	04/20/2015	522022	Direct Purchase - BODYWORK	Creditor #:GB-A1W001 A-1 Windscreens P/O #:G150492 Receiving #:154033 Date :2015-04-20 Replace O/S/F windscreen	428515
143	04/20/2015	522022	Body - Replace O/S/F windscreen	Organised windscreen replacement	428515
143	04/20/2015	522022	Consumables		428515
143	04/20/2015	520029	Consumables		428515
143	04/17/2015	520029	AMBER REFLECTOR		428515
143	04/17/2015	520029	NUMBER PLATE LAMP		428515
143	04/16/2015	521117	Elec and Light - Hazard button broken	change hazard light switch.	428515
143	04/16/2015	521117	Consumables		428515
143	04/16/2015	520029	PTV REBRAND - Method 2. {ARTIC VEHICLE}	Rebrand	428515
143	04/16/2015	520029	PTV REBRAND - Method 2. {ARTIC VEHICLE}	Rebrand	428515
143	04/16/2015	520029	Body shop consumables and Spray Booth		428515
143	04/16/2015	520029	Paint materials		428515
143	04/15/2015	520029	PTV REBRAND - Method 2. {ARTIC VEHICLE}	Rebranding	428515
143	04/15/2015	520029	PTV REBRAND - Method 2. {ARTIC VEHICLE}	Repair front bumper and and front face sanded and masked up painted primer and 2pac white paint	428515
143	04/15/2015	520029	PTV REBRAND - Method 2. {ARTIC VEHICLE}	prep work to rear of trailer	428515
143	04/15/2015	520029	40V3103 HAZARD SWITCH	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G150331 Receiving #:153829 Date :2015-04-15	428515
143	04/14/2015	521117	Elec and Light - Hazard button broken	fixed switch temperaly and order partes.	428515
143	04/14/2015	520029	PTV REBRAND - Method 2. {ARTIC VEHICLE}	rebranding	428515
143	04/13/2015	520029	PTV REBRAND - Method 2. {ARTIC VEHICLE}	Remove decls etc rebranding	428515
143	04/02/2015	519595	Consumables		428338
143	04/02/2015	519595	Update destination Files and Check display	desto id flip dot and south port n/a	428338
143	04/02/2015	519594	COMPLETE VEHICLE DETAILS AUDIT CHECK LIST	did the audit	428338
143	04/02/2015	519594	Consumables		428338
143	03/30/2015	518997	Replace See Something Say Something Poster	fitted	428338

143	03/24/2015	517558	Consumables			427719
143	03/24/2015	517558	Mechanic entered - Elec & Light Park Lights	report from driver that stop and park lights (os) and (osr) top and bottom n/w. checked fuses. found tripped fuse. reset fuse. checked - all working o.k.		427551
143	03/13/2015	516008	Consumables			426943
143	03/13/2015	516008	Mechanic entered - Elec & Light Park Lights	reset tripped fuse - (os) and (osr) park lights n / w.		426892
143	03/03/2015	514241	Steering - Top up p/steering fluid	Checked OK		425910
143	03/03/2015	514244	Gearbox (None) power steering fluid low	checked OK		425910
143	02/27/2015	513642	Consumables			425791
143	02/27/2015	513642	Elec & Light (None) off side clearance light all not worki	check short clear fault change fuse bus ok.		425516
143	02/20/2015	512367	Consumables			425089
143	02/20/2015	512363	Consumables			425089
143	02/20/2015	512367	Ops Entered - Fault - Elec & Light Stop lights - Route: -	checked system. checked fuse box. found tripped fuse. reset fuse. checked tail and brake lights. all working o.k.		424879
143	02/20/2015	512363	Elec & Light - RH top park light out	checked system and fuse box. found tripped fuse. reset fuse. checked lights. all o.k.		424879
143	02/06/2015	510218	Mechanic entered - Engine Won't Start	washed engine bay to check for cooland and hydraulic leak.found coolant leaking from pipe removed pipe and put new one has to cahase a t peice for an hour.filled with coolant.removed and replaced starter.road tested check for any leaks all good.		423852
143	02/06/2015	510218	10MM I/B BRASS T PIECE	Creditor #:GB-BUR001 BURSON AUTO PARTS P/O #:G148181 Receiving #:150507 Date :2015-02-06		423852
143	02/06/2015	510218	STARTER MOTOR SCANIA K93+L94	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G148165 Receiving #:150480 Date :2015-02-06		423852
143	02/02/2015	509333	Mechanic entered - Steering Other	added power steering fluid - low.		423554
143	01/30/2015	509057	Mechanic entered - Eng Cool Radiator Cap	replaced broken header tank cap.		423387
143	01/23/2015	508140		safety inspection completed		423069
143	01/23/2015	508140		Perform Safety Inspection as per checklist Safety Inspection Completed		423069
143	01/23/2015	508141	Consumables			423079
143	01/23/2015	508141	Consumables			423079
143	01/23/2015	508141	Consumables			423079
143	01/23/2015	508141		d service completed		423069
143	01/23/2015	508141	FILTER FUEL SCANIA SR4(H17WK04)			423069
143	01/23/2015	508141	OIL TEXAMATIC TRANSMISSION 1888 (LU2)			423069
143	01/23/2015	508141	OIL ENGINE DELO 400LE 15W40 (LU18)			423069
143	01/23/2015	508141	FILTER OIL SCANIA SR4 EARLY K320 (LF3730)(2059778)(H200W20)			423069
143	01/23/2015	508141		Tension ALL Wheel Nuts to OEM Specs		423069
143	01/23/2015	508141		D Service Completed		423069
143	01/23/2015	508141	FILTER TRANSMISSION ZF (4139-298-038)(4139 298 038 01)			423069
143	01/23/2015	508141	FILTER AIR OUTER SCANIA SR3 SR4 (AF25066)(0395773)			423069
143	01/23/2015	508141	O-RING KIT OIL SPINNER FILTER SCANIA			423069
143	01/23/2015	508141	Consumables			423079
143	01/23/2015	508141	Consumables			423079
143	01/23/2015	508141	Consumables			423079
143	01/23/2015	508141		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		423069
143	01/23/2015	508141		A SERVICE AS PER CHECK LIST		423069
143	01/12/2015	504202	DIRECT PURCHASE - BUS INSPECTI	Creditor #:GT-ROA002 ROAD SAFETY INSPECTION P/O #:G146945 Receiving #:149486 Date :2015-01-15		423069
143	01/12/2015	506200	Consumables			422993
143	01/12/2015	506200	FESTOON GLOBE 24V/3W			422533
143	01/09/2015	504202	Annual Licence	RWC 486524 - PASSED 09/01/15		422533
143	01/09/2015	506200	Elec & Light - Replace globe	Replaced		422533
143	12/18/2014	502805	Consumables			0
143	12/18/2014	502805	GLOBE FESTOON 24V 5W			422009
143	12/18/2014	502805	Mechanic entered - Elec & Light Park Lights	replaced smashed clearance light (os) mid.		422009
143	12/18/2014	502805	LAMP (RED+AMBER)			422009
143	12/12/2014	499802	HEADER TANK FILLER CAP 1403954	Creditor #:CT-EAS004 EASTCOAST TRUCK & BUS SERVICE P/O #:G146061 Receiving #:148486 Date :2014-12-12		421648
143	12/10/2014	501129	A3 Poster Change	Fitted		421243
143	12/02/2014	499545		Adjust tappetsreplace turbo inter-cooler seal		420723
143	12/02/2014	499802	Mechanic entered - Engine Other	assist to phil adjust valve.+replaced turbo pipe'o'ring.		420763
143	12/02/2014	499556	Consumables			0
143	12/02/2014	499556	FLURO TUBE 36W			420763
143	12/02/2014	499556	INTERIOR LIGHT DEFUSER			420763
143	12/02/2014	499803	Consumables			0
143	12/02/2014	499803	Mechanic entered - Body & Acc Other secure coolening fan cov	remove repair fitted.		420763
143	12/01/2014	499545	FILTER AIR DRYER SCANIA K124EB (T350W)			420723
143	12/01/2014	499545	FILTER K124EB HYD COOLING FAN E90HD149			420723
143	12/01/2014	499545		Replace power steering filter Complete		420723
143	12/01/2014	499545		Replace final drive oil		420723
143	12/01/2014	499545		Replace fuel filters Complete		420723
143	12/01/2014	499545		Inspect bus as per inspection sheet complete		420723
143	12/01/2014	499545		no filter		420723
143	12/01/2014	499545	RPM BORATE EP LUBE 220 80/90 (LU6)			420723
143	12/01/2014	499545	FILTER OIL GEARBOX DIFF K124 H24W05 1768402/2002705			420723
143	12/01/2014	499545	FILTER FUEL K124 / LU94A (1411894 / H17WK05)			420723
143	12/01/2014	499545	POWER STEERING FILTER VOLVO			420723
143	12/01/2014	499545		Changed air dryer filter		420723
143	12/01/2014	499545				420723
143	12/01/2014	499545		Rekit quick release valve NO valve		420723
143	12/01/2014	499545		Clean inter-cooler and radiator		420723
143	12/01/2014	499545		Clean a/c filters		420723
143	12/01/2014	499545		PRE ANNUAL BUS SAFETY INSPECTION CHECK		420723
143	12/01/2014	499545		check for RSI.		420723
143	12/01/2014	499556	Engine - Steam clean bus			420763
143	12/01/2014	499556	Mechanic entered - Engine Leaking retight sump bolts.	retight + steem clean.		420763
143	12/01/2014	499556	Repair wiring	Repair wiring Complete		420763
143	12/01/2014	499556	Elec & Light Interior lights n/w	Replace fluoro tubes and cover		420763
143	12/01/2014	499559	Eng Cool Leaking hydraulic hose	Tighten hoses and steam clean		420723
143	12/01/2014	499547	Mechanic entered - Diff & Hubs Other replace diff oil.	replaced.		420723
143	12/01/2014	499556	Consumables			0
143	12/01/2014	499545	Consumables			0
143	12/01/2014	499559	Consumables			0
143	12/01/2014	499545	Mechanic entered - Body & Acc Grab Rails			420723
143	12/01/2014	499559	Body & Acc Secure panel	Complete		420723
143	12/01/2014	499556	Mechanic entered - Body & Acc Other repair front door ramp.	fixed.		420763
143	10/29/2014	493571	Consumables			0
143	10/29/2014	493571	Complete AM/FM radio saloon speaker modification	did speaker campaing		418198
143	10/29/2014	493423	Mechanic entered - Eng Cool Coolant Low	added coolant.		418198
143	10/29/2014	493537	BATTERY			418198
143	10/29/2014	493537	Ops Entered - Breakdown - Breakdown Road Defect Unaffected S	batteries checked n tested checked batteries and found to be faulty so removed and replaced them.		418198
143	10/29/2014	493791	Attend break down at Brighton Terminus. Batteries flat	Attended site. Jumped batteries.returned to depot.OK		418494
143	10/28/2014	492146		Perform Safety Inspection as per checklist		418198
143	10/28/2014	493104	WHEEL NUT SQUIRREL			418198

143	10/28/2014	493390	Engine	Won't Stop	flat battery jump started	418198
143	10/28/2014	492146	Consumables			0
143	10/28/2014	492146	Mechanic entered - Elec & Light Battery Flat	jump started.		418198
143	10/28/2014	492146	Consumables			0
143	10/28/2014	492146	Consumables			0
143	10/28/2014	492146	Consumables			0
143	10/28/2014	492146		A Service & Bus Safety Inspection		418198
143	10/28/2014	492146		Tension ALL Wheel Nuts to OEM Specs		418198
143	10/28/2014	492146		A Service & Bus Safety Inspection		418198
143	10/27/2014	493104	Consumables			0
143	10/27/2014	493288	Consumables			0
143	10/27/2014	493288	Remove Legacy Poster and replace with See Something Say So	Removed and replaced by refuellers		418389
143	10/27/2014	493104	Mechanic entered - Body & Acc Exterior	Pop rivetted rear coolant cap cover assisted tension wheel nuts X 6 and replaced safety squirrels parked the bus.		418198
143	10/16/2014	491433	Accident damage - O/S/M - Acc # DAN 39802. *THIRD PARTY AT	Delivered and picked up vehicle from Knox		418198
143	10/13/2014	489478	COMPRESSOR OIL AIR CON			417528
143	10/13/2014	489478	COMPRESSOR OIL AIR CON			417528
143	10/13/2014	489478	FILTER DRIER 5/8 3K171124			417528
143	10/10/2014	490469	Consumables			0
143	10/10/2014	490469	Mechanic entered - Elec & Light Battery Flat	jump started.		417798
143	10/09/2014	490326	Consumables			0
143	10/09/2014	490326	Elec & Light Battery Flat	Jump start bus		417528
143	10/06/2014	489478	Training with Jack	UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensor pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation		417528
143	10/06/2014	489478		CONDENSOR AREA: Clean condensor coils; check boltsclamps for tension		417528
143	10/06/2014	489478		INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condensor fan grills		417528
143	10/06/2014	489478		EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check boltsclamps & fittings; clean condensate drains; clean drip tray		417528
143	10/06/2014	489478		REFRIGERATION FILTER DRYER: Replace filter dryer; check pump operation;		417528
143	10/06/2014	489478		COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose		417528
143	10/06/2014	489478		DRIVE PULLEY'S: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear		417528
143	10/06/2014	489478		DRIVE PULLEY'S: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;		417528
143	10/06/2014	489478		COMPRESSOR DRIVE BELTS: Inspect belt wear; Retension belts;		417528
143	10/06/2014	489478		FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)		417528
143	10/06/2014	489478		Clean R/A & F/A filters; inspect and report on condition; Replace filter media		417528
143	09/30/2014	488437	Security CCTV System Faulty - Camera 1 not working.	CHECKED CCTV AND PLAYBACK ALL OK.		417138
143	09/29/2014	488237	Mechanic entered - Elec & Light Battery Flat	jump started.		416939
143	09/11/2014	485245		RETENSIONED		415735
143	09/09/2014	484216	DECAL AUTHORISED OFFICER			415570
143	09/09/2014	484884	Ops Entered - Accident - Vehicle ran into Bus - Route: 811d	Attend bus accident check situation bus driveable only O/S panel damage. Follow the bus thru workshop.		415570
143	09/08/2014	484493	Mechanic entered - Elec & Light Park Lights	replaced indicator and parker globes n len on o/s		415454
143	09/08/2014	484493	LAMP INDICATOR [ORANGE]			415454
143	09/08/2014	484493	LENS TO SUIT 2029 (RED+AMBER)			415454
143	09/05/2014	484167	Mechanic entered - Elec & Light Battery Flat	Jumpstart		415267
143	09/05/2014	484216	Remove old decal and fit new Authorised Officers Decal DO N	Replaced		415267
143	09/03/2014	483650	Brakes check wear sensor warning coming on dash	check wear sensor wiresfit new wear sensor to l/h/r hub.		415267
143	09/03/2014	483650	WEAR SENSOR SCANIA DISC BRAKE 40G8401			415267
143	08/29/2014	426067	SEAT ADJUSTER KNOB ISRI	Creditor #;IB-EAS003 EASTCOAST TRUCK & BUS SERVICE P/O #:V142458 Receiving #:144765 Date :2014-08-29		415267
143	08/20/2014	480981	VALVE EXTENSION-130mm Metal type			415267
143	08/20/2014	480981	Mechanic entered - Brakes Brake Linings Worn	checking out wear sensors osr nsf osf		415267
143	08/20/2014	480981	Mechanic entered - Brakes Brake Linings Worn	check brake wear senser light change 2 nd axel wear senser still light on need to check other wheel.		415267
143	08/19/2014	480918	Remove old A3 poster & replace with Legacy or Penalty Fares	Replaced		415267
143	08/12/2014	479474	Mechanic entered - Elec & Light Battery Flat	Jumpsart		414964
143	08/06/2014	478450	Mechanic entered - Elec & Light Park Lights	Replace park/brake light globe		414472
143	08/06/2014	478450	GLOBE STOP/TAIL O/SET 24V 21W			414472
143	08/05/2014	478330	Mechanic entered - Engine Won't Start	engine hatch switch out of adjustment readjust bus ok.		414472
143	08/04/2014	477943	Mechanic entered - Elec & Light Battery Flat	Jumpstart		414320
143	07/29/2014	476990	Mechanic entered - Elec & Light Battery Flat	Jumpstart		413935
143	07/28/2014	476652	Elec & Light - Brake light top & bottom LH n/w	completed		413935
143	07/26/2014	476652	Mechanic entered - Elec & Light Stop lights	change ns topbottum brake light globe.		413935
143	07/26/2014	476652	GLOBE STOP/TAIL O/SET 24V 21W			413935
143	07/26/2014	476652	GLOBE 24V 21W SINGLE CONTACT			413935
143	07/23/2014	476156	Service			413655
143	07/23/2014	476156	Service	Completed		413655
143	07/23/2014	476157	Service			413655
143	07/23/2014	476157	Service	Completed		413655
143	07/23/2014	476158	Service			413655
143	07/23/2014	476158	Service	Completed		413655
143	07/23/2014	475954	Clamp Suit Tyre Valve			413655
143	07/23/2014	475954	TYRE VALVE EXTENSION 180mm LONG			413655
143	07/23/2014	475941	EMERGENCY EXIT BUTTON PULL COVER			413655
143	07/23/2014	475943	WEAR SENSOR SCANIA DISC BRAKE 40G8401			413655
143	07/23/2014	475943	DISC PAD SET SCANIA MB0500			413655
143	07/22/2014	475926		Perform Safety Inspection as per checklist		413647
143	07/22/2014	475942	Whls & Tyres - Tyre 7 needs replacing	R/R o/s/r drive axle tyres and matched on the n/s/r.did valve extensions on drive axle		413647
143	07/22/2014	475943	Whls & Tyres re- tensione tag axle	Removed o/s/r tag axle wheel washed inner tyre and fitted to outside.		413655
143	07/22/2014	475954	Fit Tyre Valve Extensions To All Inner Rear Axle Wheels	Done on workorder 475942 / 475943		413647
143	07/22/2014	475954	Fit Tyre Valve Extensions To All Inner Rear Axle Wheels	Done on workorder 475942 / 475943		413647
143	07/22/2014	475941	Vandalism - Remove graffiti	Removed		413655
143	07/22/2014	475941	Elec & Light - Replace fluoro globe	Replaced		413655
143	07/22/2014	475941	Elec & Light - replace door switch pull cover	Replaced		413655
143	07/22/2014	475943	Brakes drive axle brake pads u/s.	Removed & replaced rear rear brake pads & adjusted checked all tyre pressures		413655
143	07/22/2014	475941	Brakes drive axle brake pads u/s.	R/R drive axle brake pads and road tested to check handbrakes - ok.		413655
143	07/22/2014	475926		A Service & Bus Safety Inspection		413647
143	07/22/2014	475926		Tension ALL Wheel Nuts to OEM Specs - Helped Rene tension wheel nuts.		413647
143	07/22/2014	475926				413647
143	07/16/2014	474742	Mechanic entered - Elec & Light Battery Flat	Jumpstart		413199
143	07/15/2014	474381	GLOBE FESTOON 24V-3W (17104)			413050
143	07/14/2014	474381	Elec & Light - Replace globe	Replaced		413050
143	07/10/2014	473350	GLOBE FESTOON 24V-3W (17104)			412666
143	07/09/2014	473350	Mechanic entered - Steering Other	added power steering fluid - low.		412583
143	07/09/2014	473326	Eng Cool - Coolant sight glass missing	No need Slight glass		412583
143	07/08/2014	473148	Body & Acc - Repair seat	Repaired & replaced		412540
143	06/30/2014	471402	33MM LOOSE WHEEL NUT INDICATOR			411693
143	06/30/2014	471276	SCANIA - WORN - POS 910 - 275	Creditor #;GB-TYR002 TYRES4U P/O #:G140604 Receiving #:142499 Date :2014-06-30 REPLACE WITH RECAP - 27570R225B		411767
143	06/28/2014	471402		re-tension nuts on wheels 9 and 10 to specs. after recent tyre change. o.k.		411693

143	06/27/2014	471237	Whls & Tyres - Tyre 10 needs replacing	Replaced O/S rear tyres	411693
143	06/27/2014	471237	Fit Wheel Nut Pointers to all wheel nuts on the front axle	fitted tension pointers	411693
143	06/27/2014	471276	Whls & Tyres - Replace tyres 910 - worn	Replaced	411693
143	06/27/2014	471237	Security CCTV Check System NO hard drive for camera	replaced harddrive and adjusted time ands date.	411693
143	06/24/2014	470327	Mechanic entered - Elec & Light Interior Lights	replace 1 interior light globe	411256
143	06/13/2014	468483	Ops Entered - Fault - Elec & Light W'rnng Light - Route:	Checked all OK	409976
143	06/10/2014	467850	STARTER MOTOR SCANIA K93+L94		409728
143	06/10/2014	467850	Ops Entered - Breakdown - Breakdown Change Over Request - R	complete ref to w/o 467848	409728
143	06/10/2014	467848	Ops Entered - Breakdown - Breakdown Change Over Request - R	went to bus. tried to start. bus had full battery power. replaced starter motor on location. bus working ok.	409728
143	06/05/2014	467256	BROOM HEAD (09803211)		409434
143	06/05/2014	467256	BROOM HANDLE (8232715)		409434
143	06/04/2014	467256	Body & Acc - Replace broom		409434
143	05/30/2014	466113	THROUGH BODY CONNECTOR WIPER WASHER		408791
143	05/30/2014	466150	BELT		408791
143	05/30/2014	466150	GLOBE FESTOON 24V-3W (17104)		408791
143	05/29/2014	465939		Perform Safety Inspection as per checklist	408675
143	05/29/2014	466113	Wipers & Washers - Replace NS wiper spray	Replaced	408791
143	05/29/2014	466150	Air Cond - AC belt worn	Removed and fitted 2 belts and repositioned centre bolt of idler pulley rubbing on belt	408791
143	05/29/2014	466150	Passenger Doors - Rear door brush loose	Secured tightened nuts	408791
143	05/29/2014	466150	Body & Acc - Middle door noisy	Fitted new screws on overhead panel	408791
143	05/29/2014	466113	Brakes - Remove NS middle wheel to check brake pads	Removed checked refitted & tensioned w/nuts	408791
143	05/29/2014	465939		Tension ALL Wheel Nuts to OEM Specs	408675
143	05/29/2014	465939		A Service & Bus Safety Inspection	408675
143	05/23/2014	464656	RELAY WATER LEVEL B10M		408051
143	05/23/2014	464656	Elec & Light fire light stay on dash	checking out wirring checked out wirring found broken wire repaired checked out low coolant light and replaced relay road tested ok	408051
143	05/22/2014	464547	NARVA 24V REVERSING BUZZER		408051
143	05/22/2014	464547	Mechanic entered - Elec & Light Other reverse buzzer not wor	Fit new reverse buzzer	408051
143	05/12/2014	462477	Fit Myki decals as requiredFit Recruitment decal as requi	Replaced	407014
143	05/12/2014	462477	Remove A3 Marketing Poster CATCHING A BUSFit A3 Marketing	Removed	407014
143	05/12/2014	462477	Remove Fair Evasion A3 Poster & Replace with MYKI AUTO TOP	Replaced	407014
143	05/08/2014	461743	Passenger Doors Faulty Controls back door not opening and	adjust rear pasanger door sensetive edge	406474
143	05/07/2014	461593	Elec & Light Rectify red light coming on dash	Road tested and located fault in loose contact - repaired - ok.	406353
143	05/07/2014	461307	GLOBE STOP AND TAIL 24V 21/5W		406353
143	05/06/2014	461307	Elec & Light Battery Flat		406259
143	05/01/2014	460440	INDICATOR LIGHT FRONT ARTIC		405740
143	05/01/2014	460440	Elec & Light cracked left front indicator	removed and replaced broken indicator lens.	405740
143	04/28/2014	459637	Adjust Valve Clearances	completed	405237
143	04/28/2014	459637	BRAKE BOOSTER MID AXLE L94UAB		405237
143	04/28/2014	459637	Brakes - Rear NS rear rear brake booster leaking air	fit new brake booster.	405237
143	04/16/2014	458172	GLOBE 24V 75/70W H4		404715
143	04/16/2014	458172	Mechanic entered - Elec & Light Headlights	change nsf head light globe	404715
143	04/13/2014	457378	Elec & Light - Fluro tube holder (WOP)		404347
143	04/10/2014	457378	Elec & Light - Fluro tube holder (WOP)		404347
143	04/10/2014	457378	FLOURO TUBE CLIP LA037/ VOLGREN	replacedm holder globe and light defuser. checked ok.	404347
143	04/10/2014	457378	FLOURO TUBE END LA140 VOLGREN		404347
143	04/10/2014	457378	INTERIOR LIGHT DEFUSER		404347
143	04/10/2014	457378	Elec & Light - Emer exit light (middle door) n/w	checked ok.	404347
143	04/10/2014	457378	Elec & Light Middle emergency exit light n/wto be rectifi		404347
143	04/04/2014	456070	GLOBE FESTOON 24V-3W (17104)		403771
143	04/03/2014	456024		Perform Safety Inspection as per checklist	403490
143	04/03/2014	456245	Whls & Tyres - While driving pulling to left	DONE	403771
143	04/03/2014	456245	Whls & Tyres - While driving pulling to left	Replaced front tyres	403771
143	04/03/2014	456246	Suspension - Rear airbag not moving on switch	SHALEN - checked OK	403771
143	04/03/2014	456072	Engine emmision control	R/R exhaust mount	403490
143	04/03/2014	455790	Perform Campaign 1_14 School Bus Light Globe Check Check	No school light this bus	403490
143	04/03/2014	456263	Elec & Light - Replace 2 emer exit light globes	Replaced	403771
143	04/03/2014	456070	Eng Cool Leaking	R/R coolant hoses to the header tank.	403490
143	04/03/2014	456024	FILTER FUEL K124 / LU94A (1411894 / H17WK05)		403490
143	04/03/2014	456024		Tension ALL Wheel Nuts to OEM Specs	403490
143	04/03/2014	456024		D Service & Bus Safety Inspection	403490
143	04/03/2014	456024	TEXAMATIC 1888		403490
143	04/03/2014	456024	ENGINE OIL DELO 400LE 15W40		403490
143	04/03/2014	456024	O RING FILTER KIT K93		403490
143	04/03/2014	456024	FILTER TRANSMISSION ZF 4139-298-038E39HD119		403490
143	04/03/2014	456024	FILTER OIL K124 / L94UAB (H200W20)2059778		403490
143	04/03/2014	456024	AIR FILTER SCANIA CLEANED		403490
143	04/03/2014	456024		Tension ALL Wheel Nuts to OEM Specs	403490
143	04/03/2014	456024		A Service & Bus Safety Inspection	403490
143	03/19/2014	452665	WORN - POS 9 - 275/70 R22.5 -	Creditor #:GB-BEA001 BEAUREPAIRES P/O #:G136497 Receiving #:138212 Date :2014-03-19 REPLACE WITH RECAP	401708
143	03/18/2014	452665	Whls & Tyres - Replace tyre pos 9 - worn	Replaced	401531
143	03/17/2014	452601		Perform Safety Inspection as per checklist	401378
143	03/17/2014	452792	Whls & Tyres - Replace tyre pos 9	Replaced	401531
143	03/17/2014	452792	Whls & Tyres - Replace tyre pos 9	Replaced	401531
143	03/17/2014	452792	Elec & Light - Interior lights n/w	Replaced 3 interior tube	401531
143	03/17/2014	452792	Elec & Light - Interior lights n/w	Replaced 3 interior tube	401531
143	03/17/2014	452601		Tension ALL Wheel Nuts to OEM Specs	401378
143	03/17/2014	452601		A Service & Bus Safety Inspection	401378
143	03/14/2014	452488	Ops Entered - Fault - Elec & Light Dash Light - Route: 849	Removed & replaced FNS ind lens	401378
143	03/06/2014	451040	Suspension jack knife lighton	Reset fault code road tested failt code not back	400503
143	03/03/2014	447991	Elec & Light - Check electrics in t/table	Assisted Elias with t/table wiring found 4 broken wires repaired completed	398780
143	03/03/2014	447991	Elec & Light - Check electrics in t/table	ELIAS - Repaired artic table wiring reassembled	398780
143	02/17/2014	447991	Elec & Light - Check electrics in t/table	Checked wiring repaired fault & securely positioned wiring harness working OK	398780
143	02/11/2014	446532	NITROGEN DRY D SIZE		397952
143	02/11/2014	446532	AIR CON REFRIDGERANT		397952
143	02/10/2014	446532	AIR CONDITIONING REPAIR	Creditor #:GB-22C001 22 CELSIUS P/O #:G135004 Receiving #:136662 Date :2014-02-12 REPAIR	398135
143	02/10/2014	446532	Air Cond Rear air con unit not working	22 celsius inspect unit for not cooling assist electrician with short in system pressure test unit and locate leak at NS Hp service valve cap remove and replace evacuate and regas run & checked OK	397784
143	02/10/2014	446532	Air Cond Rear air con unit not working	repared wirring loom and looked for short inac loom	397784
143	02/08/2014	446532	Air Cond Rear air con unit not working	Checked over fund unloader fuse keep blowing check wires but did not find any short wire C/O for monday	397784
143	02/06/2014	446144	Drv entered - Air Cond Cooling Fault Light	Has been done	397485
143	02/06/2014	446143	Drv entered - Air Cond Cooling Fault Light	Has been done	397485
143	02/06/2014	446146	Eng Coolant low	repair coolant low level sender wires.	397485
143	02/06/2014	446153	Mechanic entered - Body & Acc Mirrors Exterior r/h mirror cr	replaced	397485
143	02/04/2014	444167	Body & Acc - Replace rear number plate very hard to read	completed replaced rear number plate	397363

143	02/03/2014	444909	ANNUAL INSPECTION	Creditor #:GB-ROA001 Road Safety Inspections P/O #:G134447 Receiving #:136449 Date :2014-02-06	397784
143	02/03/2014	445389	WORN - POS 8 - 275/70 R22.5 -	Creditor #:GB-BEA001 BEAUREPAIRES P/O #:G134588 Receiving #:136240 Date :2014-02-03 REPLACE WITH RECAP	397363
143	02/03/2014	445389	WORN - POS 7 - 275/70 R22.5 -	Creditor #:GB-BEA001 BEAUREPAIRES P/O #:G134588 Receiving #:136240 Date :2014-02-03 REPLACE WITH NEW	397363
143	02/03/2014	444167	Body & Acc - Replace rear number plate very hard to read	rEPLACED	395994
143	02/02/2014	444909	Annual Licence	RWC 676514 - Passed	396511
143	01/31/2014	445389	Whls & Tyres - Replace tyre pos 78 - worn	Replaced	397014
143	01/29/2014	445156	Mechanic entered - Breakdown Road Defect Unaffected Service	jump start flat batteries.	396511
143	01/22/2014	444172	SINGLE CONTACT GLOBE 24V 5W		396102
143	01/22/2014	444172	GLOBE STOP AND TAIL 24V 21/5W		396102
143	01/22/2014	444167	GAS STAY 330MM X 500NM		396102
143	01/22/2014	444167	NUT HAND RAIL CLAMP (280010)		396102
143	01/22/2014	444167	AIR LUMBAR SWITCH COMPLETE L/H+R/H		396102
143	01/22/2014	444167	SEAT BELT BUCKLE TWIN WIRE GREY		396102
143	01/22/2014	444167	BLACK PD NOZZLE AIR VENT DASH		396102
143	01/21/2014	444167	Vandalism - Clean graffiti - floor seats & side walls	cleaned as best as possible	395994
143	01/21/2014	444172	Elec & Light - LHS rear clearance light - no rear lights wo	replace globes to rear park lights. repair side clearance lamp connection to lamp	395994
143	01/21/2014	444167	Body & Acc - Secure drivers blind	completed	395994
143	01/21/2014	444167	Body & Acc - Secure dash panels	completed	395994
143	01/21/2014	444167	Body & Acc - Repair and paint till stand	repaired and painted	395994
143	01/21/2014	444167	Body & Acc - Secure drivers compartment door pin	completed	395994
143	01/21/2014	444167	Body & Acc - Replace demister duct	completed	395994
143	01/21/2014	444167	Body & Acc - Drivers seat - replace covers	completed	395994
143	01/21/2014	444167	Body & Acc - secure adjust front doors	completed	395994
143	01/21/2014	444167	Body & Acc - Secure hand rails - NS & OS rear	completed	395994
143	01/21/2014	444167	Body & Acc - Secure seat frames - OS endcap seat 5	completed	395994
143	01/21/2014	444167	Body & Acc - Replace interior decals - No Smoking	completed	395994
143	01/21/2014	444167	Body & Acc - Secure back seat	completed	395994
143	01/21/2014	444167	Body & Acc - Replace gas stays on lift up panels - OS 1	completed	395994
143	01/21/2014	444167	Body & Acc - Paint wheels	completed	395994
143	01/21/2014	444167	Body & Acc - Secure all lower skirt panels	completed	395994
143	01/21/2014	444009	WHEEL ARCH BRUSH RUBBER 2.5MTR		395994
143	01/21/2014	444009	WHEEL ARCH BRUSH 2.5MTR		395994
143	01/21/2014	444009	CENTRA SEAT END CAPS		395994
143	01/21/2014	444134	Air System - Air valve leaking on the air tank in front of	remove and replace circuit protection vavle	395994
143	01/20/2014	444009	Annaul Body Inspection	Inspected	395994
143	01/20/2014	444009	Body & Acc - replace w/arch rubber and brush	Replaced with new	395994
143	01/20/2014	443989	HINGE DRIVER COMPARTMENT		395994
143	01/17/2014	443758	CRANK TO PULLEY SCANIA 21/32X67		395994
143	01/17/2014	443989	Body & Acc - Replace compartment door hinge	ADAM DUSCOMBE - Replaced	395994
143	01/17/2014	444134	CIRCUIT PROTECTION VALVE	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G134096 Receiving #:135702 Date :2014-01-21	396102
143	01/16/2014	443356		Remove intercooler wash intercooler and raditor	395994
143	01/16/2014	443356		Clean a/c filters	395994
143	01/16/2014	443356		Replace coolant filter in engine cooling system	395994
143	01/16/2014	443356		Replace air dryer canister	395994
143	01/16/2014	443356		Replace hydraulic fan filter and top up oil	395994
143	01/16/2014	443356		Rekit quick release valve	395994
143	01/16/2014	443356		Replace power steering filter	395994
143	01/16/2014	443356		Adjust valve clearances	395994
143	01/16/2014	443356		Replace final drive oil	395994
143	01/16/2014	443356		Replace fuel filters	395994
143	01/16/2014	443356		Inspect bus as per inspection sheet	395994
143	01/16/2014	443758	Air Cond - A/C drive belts	ADAM DUSCOMBE - Replaced	395994
143	01/16/2014	443758	Body & Acc - Replace broken hinge on drivers door	ADAM DUSCOMBE - Replaced	395994
143	01/15/2014	443355	ADAM DUSCOMBE	Perform Safety Inspection as per checklist	395994
143	01/15/2014	443356	RPM BORATE EP LUBE 220		395994
143	01/15/2014	443356	POWER STEERING FILTER VOLVO		395994
143	01/15/2014	443356	FILTER OIL GEARBOX DIFF K124		395994
143	01/15/2014	443356	FILTER AIR DRYER SCANIA K124EB (T350W)		395994
143	01/15/2014	443356	FILTER K124EB HYD COOLING FAN		395994
143	01/15/2014	443356	FILTER FUEL K124 / LU94A (1411894 / H17WK05)		395994
143	01/15/2014	443356	FUEL FILTER ELEMENT SCANIA L94UAB/volvo (R90T / H7090WK10)		395994
143	01/15/2014	438731	Elec & Light Fire allarm light commes on	put bus back together and roaded ok	395994
143	01/15/2014	443355	ADAM DUSCOMBE	A Service & Bus Safety Inspection	395994
143	01/15/2014	443355	ADAM DUSCOMBE	Tension ALL Wheel Nuts to OEM Specs	395994
143	01/14/2014	438731	Elec & Light Fire allarm light commes on	checked out wiring found broken wires in turntable repaired them and start putting back together	395994
143	01/09/2014	438731	Elec & Light Fire allarm light commes on	fOLLOWING WIRING IN T/TABLE LOOKS LIKE WIRING BREAK IS NOT IN T/TABLE UNABLE TO REPLICATE FAULT c/o	395994
143	01/06/2014	438731	Elec & Light Fire allarm light commes on	Checking turntable wiring c/o	395994
143	01/06/2014	438731	Mechanic entered - Body & Acc Other	checked ok	395994
143	01/06/2014	438731	GAS STAY 330MM X 500NM	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G133622 Receiving #:135541 Date :2014-01-15	395994
143	01/03/2014	438731	Elec & Light Fire allarm light commes on	Drove bus to replicate fault once fault reappeared I tested circuit fault contained before the turntable up to the front determined fault to be in turntable currently checking t/table	395994
143	12/31/2013	438731	Elec & Light Fire allarm light commes on	tested continuity between fire alarm sensors and electrical panel. fault not showing up. will need to get the bus into a turning position before checking again.	395994
143	12/24/2013	440849	Remove A3 Hold On Poster and Fit A3 Catching a bus poster	removed	395994
143	12/20/2013	439566	Remove BTS Equipment Fuses	Removed	395994
143	12/13/2013	439566	Remove BTS Equipment Fuses	n/a	395994
143	12/10/2013	438731	Elec & Light Fire allarm light commes on	Moved bus and checked rear	395994
143	12/10/2013	438731	Elec & Light Fire allarm light commes on	Checked out fire alarm	395994
143	12/09/2013	438173	SINGLE CONTACT GLOBE 24V 5W		395994
143	12/07/2013	438173	Drv entered - Elec & Light Stop lights	Replace globe	395994
143	11/30/2013	436697	Brakes ABS light and jack knife light on dash	Road rested checked fault code no any fault in systerm top up fuel and parked	395279
143	11/29/2013	436697	Brakes ABS light and jack knife light on dash	Remved wheel and check sensors and resistance all O/K but found middle axle bearing olay too much adjust wheel bearing fit new lock tab and toque both hubnuts to 800NM	395279
143	11/29/2013	436697	L94UAB SCANIA HUB LOCK WASHER		395279
143	11/27/2013	436697	WEAR SENSOR SCANIA DISC BRAKE		395279
143	11/26/2013	436697	Brakes ABS light and jack knife light on dash	Checked over removed wheel and replaced damage werw sensor wire clean ABS road tested but Intermediately fire light and ABS light coming onC/O job	395279
143	11/25/2013	436437	Fit New Myki Decal as Per PTV fitting instructions	Fitted new Myki decal to N/S/F exterior window.	395279
143	11/25/2013	436327	Perform Campaign as per Instructions Ensure that appropri	Completed	395279
143	11/25/2013	436248	Ops Entered - Breakdown - Breakdown Road Defect Unaffected	???	395279
143	11/21/2013	435742	Ops Entered - Fault - Brakes ABS On - Route: 800 - Dandeno	refit n/s mid axle abs sencer road tested.	394944
143	11/21/2013	435742	Ops Entered - Breakdown - Breakdown Mech Defect Affects Ser	refit n/s mid axle abs sencer road tested.	394944
143	11/20/2013	435742	Mechanic entered - Brakes ABS On	refit n/s mid axle abs sencer road tested.	394944
143	11/15/2013	435160	GLOBE FESTOON 24V-3W		394649
143	11/15/2013	435165	Mechanic entered - Eng Cool Coolant Low	top up coolant	394649
143	11/14/2013	435160	Elec & Light - Replace globe	Replaced	394649
143	11/08/2013	434041	STARTER SOLENOID SUIT JF		394649

143	11/08/2013	434041	BUSH KIT SUIT JF			
143	11/08/2013	434041	STARTER DRIVE SUIT JF			
143	11/08/2013	434041	0001368301 STARTER MOTOR SCANIA K93+L94	coMPLETED rebuild		
143	11/01/2013	424868	IMAGE RELATED REPAIRS TO BUSES	Creditor # :GB-TRA013 TRANSCAL P/O #:G128890 Receiving #:133463 Date :2013-11-19		394944
143	10/29/2013	432505	Ops Entered - Accident - Ran into back of Other Vehicle -	repaired at Knox		394470
143	10/25/2013	427529	AIR CON REFRIDGERANT			394393
143	10/25/2013	427529	24 VOLT RELAY PANEL			394393
143	10/25/2013	427529	DASH PANEL ROUTE BUS			394393
143	10/25/2013	427529	FILTER DRIER 5/8			394393
143	10/23/2013	431551	Mechanic entered - Brakes ABS On	fit new abs wheel sensor to middle n/s wheel and road tested ok		393048
143	10/22/2013	431269	LH ABS SENSOR TAG AXLE	Creditor # :GB-EAS002 EASTCOAST TRUCK & BUS SERVICE P/O #:G130975 Receiving #:132444 Date :2013-10-22		393936
143	10/22/2013	431269	Suspension plays up and down	checked out found air leaking at a nother joiner		393048
143	10/22/2013	431551	Mechanic entered - Brakes ABS On	removed abs sensor and ordered new part		393048
143	10/21/2013	431269	AIRBAG REAR SCANIA K124EB	Creditor # :GB-MUL001 MULTISPARES LTD P/O #:G130935 Receiving #:132337 Date :2013-10-21		393936
143	10/21/2013	431269	VALVE SOLENOID ELC			393048
143	10/21/2013	431269	AIRBAG REAR SCANIA K124EB			393048
143	10/21/2013	431269	Suspension plays up and down	replaced two air bags and valve body		393048
143	10/19/2013	431191	Remove A3 Poster 15/8Fit Poster (HOLD ON) as per Campaign	Completed by operations		393048
143	10/14/2013	427529	FUSE BLADE 7.5			393048
143	10/14/2013	427529	5 PIN CHANGE-OVER RELAY WITH DIODE			393048
143	10/11/2013	429774	Drv entered - Air Cond Air Conditioner	REPAIRED AT SERVICE		393936
143	10/11/2013	427529		UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensor pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation		393048
143	10/11/2013	427529	FRONT: Replace d dash control	CONDENSOR AREA: Clean condensor coils; check boltsclamps for tension		393048
143	10/11/2013	427529		INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condensor fan grills		393048
143	10/11/2013	427529		EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check boltsclamps & fittings; clean condensate drains; clean drip tray		393048
143	10/11/2013	427529		REFRIGERATION FILTER DRYER: Replace filter dryer; check pump operation;		393048
143	10/11/2013	427529	REAR: Found wiring to right bank missing tested replace wiri	COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose		393048
143	10/11/2013	427529		DRIVE PULLEY'S: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear		393048
143	10/11/2013	427529		Clean R/A & F/A filters; inspect and report on condition; Replace filter media		393048
143	10/11/2013	427529		DRIVE PULLEY'S: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;		393048
143	10/11/2013	427529	REAR: Found compressor out of alignment realign and test OK	COMPRESSOR DRIVE BELTS: Inspect belt wear; Retension belts;		393048
143	10/11/2013	427529		FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)		393048
143	10/07/2013	428879	EMERGENCY PROCEDURE DECAL			393464
143	10/07/2013	428879	CCTV SURVEILLANCE DECAL			393464
143	10/07/2013	428879	BY LAW PICKUP/SET DOWN DECAL			393464
143	10/07/2013	428879	CUSTOMER ENQUIRY DECAL			393464
143	10/07/2013	428879	PLEASE ASSIST DRIVER DECAL			393464
143	10/07/2013	428879	PASSENGERS REQUIRED BY LAW DECAL			393464
143	10/07/2013	428879	DRIVERS NO DEFECT CHECKLIST DECAL			393464
143	10/07/2013	428879	WARNING MAXIMUM HEIGHT DECAL			393464
143	10/07/2013	428879	LICENSED TO CARRY DECAL			393464
143	10/07/2013	428879	NO SMOKING DECAL			393464
143	10/02/2013	427129	Brakes - Check ABS sensor	cleanup wheel and sensor and road tested ok		393048
143	10/01/2013	428879	Perform sticker audit on vehicles ensuring that correct sti			393048
143	09/27/2013	427520		Perform Safety Inspection as per checklist done		393048
143	09/27/2013	427520		done		393048
143	09/27/2013	427520		Tension ALL Wheel Nuts to OEM Specs done		393048
143	09/27/2013	427520		A Service & Bus Safety Inspection done		393048
143	09/25/2013	427129	Brakes - Check ABS sensor	Checked and found which wheel waiting on room in w/shop c/o		393048
143	09/19/2013	422796	spension - Replace middle sway bar bush	Replace sway bar bush		393048
143	09/19/2013	425046	Mechanic entered - Gearbox No Gears	finished off wiring put back together		393048
143	09/19/2013	426067	Ops Entered - Fault - Air System Slow To Build - Route: -	Check air build up O/K		393048
143	09/18/2013	422796	Suspension - Replace middle sway bar bush	puting bus back together		393048
143	09/17/2013	422796	Suspension - Replace middle sway bar bush	checked out for short found in turn table repair wires		393048
143	09/16/2013	425046	Mechanic entered - Gearbox No Gears	Removed constantina and checked short wires c/o		393048
143	09/14/2013	424868	Carry out campaign as per Fleet re-branding Procedure.	Completed		393048
143	09/13/2013	425046	Mechanic entered - Gearbox No Gears	Re check fault code after fitted retarder padal it's o/k but no 15 fuse blowing need to carry over job chech short wire		393048
143	09/12/2013	425046	Mechanic entered - Gearbox No Gears	Check gears not selecting replace foot valve retader plate and fit axle shaft		393048
143	09/07/2013	423380	Remove A3 Marketing Poster 30/9Fit Marketing Poster 15/8	Completed		393048
143	09/01/2013	422873	TOW BUS TO DEPOT	Creditor # :GB-EAG001 EAGLE TOWING & SALVAGE P/O #:G128910 Receiving #:130389 Date :2013-09-03		393154
143	08/30/2013	422796	Suspension - Replace middle sway bar bush			393048
143	08/30/2013	422847	Lost gears at Church st Brighton.	Go to Church st Brighton check and found 10amp fuse for gearbox out reset and drive fuse out again. Secure bus and arrange for tow truck. Return to depot.		393048
143	08/30/2013	422873	Breakdown - No gear - Brighton terminal - 10.00am ret - 11.	NO-15 FUSE KEEPS BLOWING get bus towed back to depot		393048
143	08/29/2013	422677		Safety Inspection Completed		393048
143	08/29/2013	422677		Perform Safety Inspection as per checklist did safty inspection.		393048
143	08/29/2013	422796	BUSH SWAYBAR D-SHAPE SCANIA L9	Creditor # :GB-MUL001 MULTISPARES LTD P/O #:G128864 Receiving #:130185 Date :2013-08-30		393154
143	08/28/2013	422566	grenda stickers to remove	removed and polished		393048
143	08/28/2013	422501	Ops Entered - Breakdown - Breakdown 1-Mech Defect Affects S	DID NOT GET CALL OUT ???		393048
143	08/27/2013	422157	RELAY 24V/20AMP			393048
143	08/26/2013	422157	Elec & Light - interior lights inop	strip and check dash wiring and switch fit new relay and fuse and check light tubes.. relay and fuse were the problem.		392861
143	08/21/2013	419831	Gearbox.. gears not engaging vehicle not starting. (have to	checked ok		391947
143	08/21/2013	419812	Mechanic entered - Engine Won't Start	finish off bus and road tested ok		391947
143	08/20/2013	419812	Mechanic entered - Engine Won't Start	checking out wiring and start to put back together road tested		391947
143	08/15/2013	419812	Mechanic entered - Engine Won't Start	checking out gearbox loom for ashort in it		391947
143	08/14/2013	419831	Gearbox.. gears not engaging vehicle not starting. (have to	checking out short in gearbox loom		391947
143	08/12/2013	419831	Gearbox.. gears not engaging vehicle not starting. (have t	AO PJL SKD (SKD had half an hour on this job AO/PJL had one hour each) short out starter to start remove front number plate remove towing eye. hook up forklift. gears not engaging.. vehicle had to be towed into the workshop by using the forklift.		391947
143	08/12/2013	419812	Mechanic entered - Engine Won't Start	started from starter motor		391947
143	08/12/2013	419886	Bus will not start at Mentone stn	Check for non start. Reset fuse and check ok. Return to depot		391947
143	08/09/2013	419355	GLOBE S/CONTACT 24V-10W			391947
143	08/09/2013	419355	Elec & Light - Replace rear globes	Replaced		391947
143	08/01/2013	418255	Elec & Light - Refit OSR parker globe	Refitted		391094
143	07/31/2013	418051	Elec & Light - Replace OSR parker globe	Replaced		390893
143	07/29/2013	417330	GLOBE FESTOON 24V-3W			390319
143	07/26/2013	417330	Elec & Light - Replace emer exit globe	Replaced		390319
143	07/26/2013	416837	RELAY 50 AMP	Creditor # :GB-MUL001 MULTISPARES LTD P/O #:G127493 Receiving #:128690 Date :2013-07-26		390100
143	07/25/2013	416837	Mechanic entered - Elec & Light Park Lights	park lights u/s traced using diagram and found supply relay 58 faulty. ordered new part and robbed the relay from bus 60.		390100
143	07/24/2013	416837	Mechanic entered - Elec & Light Park Lights	Park lights u/s checked switch now following wiring suspect broken wire c/o		390100
143	07/23/2013	416636	Elec & Light - Check park lights	Checked electrics & took to GBS		390100
143	07/19/2013	415938	Wheel Alignment - Bus runs towards LHS	R/tested fitted new front wheels/tyres r/tested OK		389898
143	07/18/2013	415890	T'rntable - check turntable	Repressured t/table and cleared codes		389898
143	07/18/2013	415745	Suspension - Front axle sway bar D bush - worn	Replaced		389898
143	07/18/2013	415890	Brakes - Check ABS sensors	Checked sensors still u/s		389898
143	07/17/2013	415745	BUSH SWAY BAR FRONT K230	Creditor # :GB-MUL001 MULTISPARES LTD P/O #:G127172 Receiving #:128346 Date :2013-07-18 143		389898

143	07/14/2013	415205	Elec & Light - Lights are n/w	Changed fuse	389459
143	07/08/2013	413915	GLOBE STOP AND TAIL 24V 21/5W		388988
143	07/08/2013	413915	GLOBE FESTOON 24V-3W		388988
143	07/08/2013	413915	DOWN LIGHT LED		388988
143	07/05/2013	413915	Elec & Light - Replace globes	Replaced	388988
143	07/05/2013	413702		A Service & Bus Safety Inspection	388971
143	07/05/2013	413702		Tension ALL Wheel Nuts to OEM Specs	388971
143	07/05/2013	413702		A Service & Bus Safety Inspection	388971
143	06/26/2013	412335	Body & Acc - Front seat off	refitted	387999
143	06/13/2013	410046	GASKET LIGHT 2139+2143+2043		386002
143	06/13/2013	410046	GLOBE STOP AND TAIL 24V 21/5W		386002
143	06/12/2013	410046	Elec & Light - Replace park light globe	Replaced	386002
143	06/04/2013	408548	GLOBE 24V 21W SINGLE CONTACT		385217
143	06/03/2013		0 Imported Service History	Imported Service History	383640
143	06/03/2013	406484	Perform Campaign 01_13 CCTV and GPS AUDIT inspect vehicles	Repaired CCTV wiring and fixed loom in t/table had to go for parts	383640
143	06/03/2013	408769	Elec & Light - Replace LH top brake light globe	Replaced	385217
143	06/03/2013	408548		Tension ALL Wheel Nuts to OEM Specs	383640
143	06/03/2013	408548	O RING FILTER KIT K93		383640
143	06/03/2013	408548	FILTER AIR SCANIA USE AF25066		383640
143	06/03/2013	408548			383640
143	06/03/2013	408548	TEXAMATIC 1888	D Service & Bus Safety Inspection	383640
143	06/03/2013	408548	ENGINE OIL DELO 400LE 15W40		383640
143	06/03/2013	408548	FILTER TRANSMISSION ZF 4139-298-038E39HD119		383640
143	06/03/2013	408548	FILTER OIL K124 / L94UAB (H200W02)		383640
143	06/03/2013	408548		Tension ALL Wheel Nuts to OEM Specs	383640
143	06/03/2013	408548		A Service & Bus Safety Inspection	383640
143	05/31/2013	406484	Perform Campaign 01_13 CCTV and GPS AUDIT inspect vehicles	Checked out and started repairing CCTV pull t/table apart checking wiring	383640
143	05/23/2013	406621	FLAT - POS 3 - 275/70 R22.5 74	Creditor #:GB-BEA001 BEAUREPARES P/O #:K124648 Receiving #:125744 Date :2013-05-28 REPAIR OR REPLACE WITH RECAP	384596
143	05/22/2013	406621	Whls & Tyres - Replace tyre pos 3 - flat	Replaced	383769
143	05/22/2013	406368	FUSE BLADE 10AMP		383769
143	05/22/2013	406368	INDICATOR LIGHT FRONT ARTIC		383769
143	05/21/2013	406681	Whls & Tyres - Replace pos 3 tyre	Replaced flat tyre	383769
143	05/21/2013	406368	Elec & Light R/H/F indicator lens broken and R/H parking li	replaced lens for indicator and fit fuse for parklights. working ok.	383640
143	05/20/2013	406484	Perform Campaign 01_13 CCTV and GPS AUDIT inspect vehicles	Fixede one camera need to check wires for the other one c/o	383640
143	05/20/2013	402289	GLOBE FESTOON 24V 5W		383640
143	05/20/2013	402289	GLOBE FESTOON 24V 5W		383640
143	05/20/2013	402289	INDICATOR SWITCH SCANIA L94UAB	Creditor #:MUL001 MULTISPARES LTD P/O #:G123555 Receiving #:124464 Date :2013-04-30	383640
143	05/20/2013	402289	Mechanic entered - Elec & Light Indicators	moved bus to the front of line 2. continued checking wiring but will need a pit to proceed	383640
143	05/20/2013	402289	Mechanic entered - Elec & Light Indicators	got bus onto pit eliminated a section of wire directly behind the turntable underneath the bus. secured cabling back up. parked bus will get bus onto hoist on monday to continue tracing fault.	383640
143	05/20/2013	402289	Mechanic entered - Elec & Light Indicators	Began setting up hoists c/o	383640
143	05/20/2013	402289	Mechanic entered - Elec & Light Indicators	Put bus on hoist cont tracing wiring	383640
143	05/20/2013	402289	Mechanic entered - Elec & Light Indicators	Continued tracing wiring fault c/o	383640
143	05/20/2013	402289	Mechanic entered - Elec & Light Indicators	Continued following suspect wire	383640
143	05/20/2013	402289	Mechanic entered - Elec & Light Indicators	continued following wiring to find short. also repaired a unrelated previously broken wire underneath turntable.	383640
143	05/20/2013	402289	Mechanic entered - Elec & Light Indicators	Wires hanging inside and short to body	383640
143	05/20/2013	402289	Mechanic entered - Elec & Light Indicators	Wiring fault with Ranjith we found a side light was not reconnected after body work had been done	383640
143	05/20/2013	402289	Mechanic entered - Elec & Light Indicators	Working on securing all wiring hooking up side lights and securing panels	383640
143	05/20/2013	402289	Mechanic entered - Elec & Light Indicators	continued following fault couldn't get onto pit. replaced indicator stalk after i took the original to fit to bus 102.	383640
143	05/20/2013	402289	Mechanic entered - Elec & Light Indicators	connected circuit tester and began tracing signal through bus. traced fault to behind turntable leading to the back of the bus. will need to use pit in order to proceed.	383640
143	05/20/2013	402289	Mechanic entered - Elec & Light Indicators	Cont tracing indicator short removed NSR indicators	383640
143	05/20/2013	402289	Mechanic entered - Elec & Light Indicators	followed wires into turntable and behind. found plug after turntable for indicators. once disconnected the front indicators work ok. fault is in trailer section of bus.	383640
143	05/20/2013	402289	Mechanic entered - Elec & Light Indicators	replaced all n/s indicator globes. began following wires to locate broken wire(this is what i have determined to be the fault given the behaviour of flasher unit)	383640
143	05/20/2013	402289	Mechanic entered - Elec & Light Indicators	removed indicators n/s indicators looking for a blown globe or short. checked wiring from stalk to flasher. will carry out more tests tomorrow.	383640
143	05/20/2013	402289	Mechanic entered - Elec & Light Indicators	Assisted Matt	383640
143	05/20/2013	402289	LAMP INDICATOR [ORANGE]		383640
143	05/20/2013	402289	LAMP (RED+AMBER)		383640
143	05/20/2013	402289	GLOBE FESTOON 24V5W		383640
143	05/20/2013	402289	BATTERY 800CCA		383640
143	05/20/2013	402289	BATTERY 800CCA		383640
143	05/20/2013	402289	Mechanic entered - Elec & Light Indicators	secured all cables in place. fit new batteries. parked bus. complete.	383640
143	05/16/2013	391480	Supply and install decals	Creditor #:GB-ATT001 ATTITUDE SIGNS P/O #:G119828 Receiving #:125075 Date :2013-05-16	383640
143	04/29/2013	392254	BUSH SWAY BAR	Creditor #:MUL001 MULTISPARES LTD P/O #:G120035 Receiving #:124275 Date :2013-04-29	383640
143	04/29/2013	391626	STEERING WHEEL	Creditor #:MUL001 MULTISPARES LTD P/O #:G119906 Receiving #:124274 Date :2013-04-29	383640
143	04/19/2013	401795	STARTER DRIVE SUIT JF		383640
143	04/19/2013	401795	STARTER SOLENOID SUIT JF		383640
143	04/19/2013	401795	JF24V 4KW BRUSH SET		383640
143	04/19/2013	401795	BUSH KIT SUIT JF		383640
143	04/19/2013	400374	Suspension Front radius rod bushe worn	Front both upper torque rod bushes changed.	382581
143	04/19/2013	400374	Suspension Front radius rod bushe worn	Assisted Subu	382581
143	04/19/2013	401899	Elec & Light IndicatorsLeft hand indicators keep ceasing	fit new indicator stalk. tested indicators but could not fault.	383640
143	04/19/2013	401899	INDICATOR SWITCH SCANIA L94UAB	Creditor #:MUL001 MULTISPARES LTD P/O #:G123144 Receiving #:123912 Date :2013-04-19	383640
143	04/18/2013	401795		Rebuild comp	
143	04/16/2013	401250	15AMP BLADE FUSE		383578
143	04/16/2013	401125	GLOBE+HOLDER INSTRUMENT (GREY)		383578
143	04/16/2013	401587	Elec & Light - Indicators n/w	Checked could not find problem then started working	383578
143	04/15/2013	401243	Indicators u/s at southland	Leave for break down at 9.00 Verify r/h inicator works hazards and l/h indicator are u/s check fuse ok remove indicator storck and test operation verify electical connector is ok disconnect hazard switch and test operation u/s reinstall and inspect flasher relay module suspect stuck contacts in module no parts available. Ret	383489
143	04/15/2013	401250	Elec & Light Indicators U/S	Remove refit check bulbs indicator stalk fuses remove flasher unit strip clean & refit	383489
143	04/15/2013	401250	Elec & Light Indicators U/S	checked indicators working ok. possible intermittant fault.	383489
143	04/12/2013	401125	Elec & Light - Replace globes	Replaced	383323
143	04/09/2013	400374	BUSH TORQUE ROD SCANIA/MERC	Creditor #:MUL001 MULTISPARES LTD P/O #:G122618 Receiving #:123351 Date :2013-04-09 143	382581
143	04/09/2013	400421	LAMP (RED+AMBER)		382581
143	04/09/2013	400421	GLOBE FESTOON 24V10W		382581
143	04/08/2013	400192	Throttle CAN NOT CONTROL	Checked no fault found	382417
143	04/08/2013	400421	Elec & Light - Replace clearance light	Replaced	382581
143	04/04/2013	399294	GLOBE S/CONTACT 24V-10W		382080
143	04/04/2013	399294	FANBELT		382080
143	04/04/2013	399294	BELT ALT W/PUMP CRANK SCANIA ARTIC		382080
143	04/04/2013	399678	Elec & Light - Alt mount bolts missing and pulleys rubbing	Removed 2 broken bolts from alt mounting and fitted new	382080
143	04/04/2013	399294	DISC PAD SET SCANIA MB0500		382080
143	04/03/2013	399678	Elec & Light - Alt mount bolts missing and pulleys rubbing	Checked out found alt bolt broken removed bits of belt from main pulley	382080
143	04/02/2013	399294	Elec & Light - Replace stop signal globe	Replaced	382080
143	04/02/2013	399294	Brakes - ABS On	Replaced middle axle LHS brake pad	382080
143	04/02/2013	399294	Brakes - ABS On	Replaced middle axle LHS brake pad	382080

143	04/02/2013	399295	A Service & Bus Safety Inspection	381978
143	04/02/2013	399295	Tension ALL Wheel Nuts to OEM Specs	381978
143	04/02/2013	399295	A Service & Bus Safety Inspection	381978
143	03/28/2013	398822	MIRROR METAGAL R/H	381748
143	03/27/2013	398822	Go to Balcombe rd & replace broken o/s mirror.	381543
143	03/22/2013	398334	GLOBE STOP AND TAIL 24V 21/SW	380888
143	03/21/2013	398334	Elec & Light Park light out	380888
143	03/20/2013	397848	D HANDLE LENLOCK CHROME PLATED	380478
143	03/19/2013	397851	Air Cond clean filters	380478
143	03/19/2013	397849	Elec & Light N/S/r clearance ligt broken	380478
143	03/19/2013	397848	Body & Acc engine Door handle missing	380478
143	03/12/2013	396808	Engine no power	379738
143	03/07/2013	395812	LOW TREAD - POS 78 - 275/70 R	379184
143	03/07/2013	396240	Elec & Light - Replace fluoro cover	379377
143	03/06/2013	395812	Whls & Tyres - Replace tyre pos 78 - low tread	378993
143	03/05/2013	394587	ROAD SAFETY INSPECTIONS	378993
143	03/05/2013	395964	Whls & Tyres - Replace tyres 78	378993
143	03/03/2013	394587	Annual Licence	378024
143	02/28/2013	394946	GASKET LIGHT 2139+2143+2043	378228
143	02/28/2013	394946	LENS TO SUIT 2029 (RED+AMBER)	378228
143	02/28/2013	394946	FUSE BLADE 10AMP	378228
143	02/28/2013	394946	GLOBE STOP AND TAIL 24V 21/SW	378228
143	02/28/2013	394946	GLOBE S/CONTACT 24V-10W	378228
143	02/28/2013	394946	CLEARANCE LIGHT IS NOT WORKING FUSE KEEPS BLOWING	378228
143	02/28/2013	394946	CLEARANCE LIGHT IS NOT WORKING FUSE KEEPS BLOWING	378228
143	02/27/2013	394946	Elec & Light No parking lights on rear	378228
143	02/27/2013	394946	Elec & Light - OS parkers n/w - (changed fuse & globes but	378228
143	02/26/2013	394575	GLOBE S/CONTACT 24V-10W	378024
143	02/26/2013	394575	GLOBE FESTOON 24V-3W	378024
143	02/25/2013	394684	Elec & Light - No clearance lights	378024
143	02/22/2013	394575	Elec & Light - RHS side marker n/w	377792
143	02/22/2013	394575	Elec & Light - RHS side marker n/w	377792
143	02/20/2013	393613	FLAT - POS 3 - 275/70 R22.5 74	377379
143	02/19/2013	393708	BUSH KIT SUIT JF	376969
143	02/19/2013	393708	STARTER SOLENOID SUIT JF	376969
143	02/19/2013	393708	STARTER DRIVE SUIT JF	376969
143	02/19/2013	393708	JF24V 4KW BRUSH SET	376969
143	02/19/2013	393034	FLAT - POS 4 - 275/70 R22.5 74	376969
143	02/19/2013	393613	Whls & Tyres - Replace tyre pos 3 - flat	376969
143	02/18/2013	393708		
143	02/18/2013	393650	Whls & Tyres - Replace tyre 3	376969
143	02/15/2013	392437	WIPER BLADE ARTIC 28inch	376868
143	02/15/2013	392437	Wipers & Washers - Replace wiper blades	376379
143	02/15/2013	392254	Suspension - Replace sway bar bush rubbers middle axle	376379
143	02/14/2013	393034	Whls & Tyres - Replace tyre pos 4 - flat	376661
143	02/13/2013	393278	Whls & Tyres - Replace tyre 4	376661
143	02/13/2013	393278	Elec & Light - No park lights	376661
143	02/12/2013	393159	Elec & Light - Bus wont start	376470
143	02/11/2013	389944	SIDEWALL DAMAGE	376379
143	02/08/2013	391856		376379
143	02/08/2013	391856	c/o	376379
143	02/08/2013	392437	Wipers & Washers - Replace wiper blades	376379
143	02/08/2013	392437	Engine - Steamclean bus	376379
143	02/08/2013	392262	Body & Acc - Concertina damaged underneath	376379
143	02/08/2013	391398	AMBER REFLECTOR	376379
143	02/07/2013	391856	c/o	376379
143	02/07/2013	392262	Vandalism - Clean graffiti - in rear of bus	376379
143	02/07/2013	391626	HORN PAD SCANIA	376379
143	02/07/2013	391626	Steering - Steering wheel top cover (horn assy) is not locki	376379
143	02/07/2013	392262	Body & Acc - Wheel chair ramp - operation and clean	376379
143	02/07/2013	392262	Body & Acc - Secure & paint exterior mirrors and arms	376379
143	02/07/2013	392262	Body & Acc - Polish exterior panels/headers & touch up paint	376379
143	02/07/2013	392262	Body & Acc - Clean air condition filter secure vents	376379
143	02/07/2013	392262	Body & Acc - Replace interior decals	376379
143	02/07/2013	391480	Body & Acc - NS pax holding rail in middle curtain area bend	376379
143	02/07/2013	391626	Air System - Air leaking at air dryer area	376379
143	02/07/2013	391398	Accident Damaged # 36455 R/R. o/s. fibreglass edge trim o/s	376379
143	02/07/2013	391480	Accident Damaged # 35664 R/R. n/s/r. trailer clearance light	376379
143	02/06/2013	392262	Vandalism - Clean graffiti - in rear of bus	376379
143	02/06/2013	391626	Suspension - Front LHS airbag leaking	376379
143	02/06/2013	391626	Suspension - Front LHS airbag leaking	376379
143	02/06/2013	391626	BALL JOINT ZF L94	376379
143	02/06/2013	391626	Steering - Link rod ball joint rubber boot torn	376379
143	02/06/2013	391626	Steering - Steering wheel cover loose	376379
143	02/06/2013	391626	Steering - Link rod ball joint rubber boot torn	376379
143	02/06/2013	391626	Steering - Steering wheel top cover (horn assy) is not locki	376379
143	02/06/2013	391626	Engine - Engine oil leaking at surrounding engine	376379
143	02/06/2013	392262	Body & Acc - Replace emergency exit decals with safety hamme	376379
143	02/06/2013	392262	Body & Acc - Paint front modesty panel - rear door	376379
143	02/06/2013	392262	Body & Acc - Secure black interior mirror	376379
143	02/06/2013	392262	Body & Acc - Paint rear b/bar	376379
143	02/06/2013	392262	Body & Acc - Replace Licensed to carry (No) seat (No) adult	376379
143	02/06/2013	392262	Body & Acc - Secure NS 26 - hand rails	376379
143	02/06/2013	391480	Body & Acc - Replace rear middle door seals	376379
143	02/06/2013	391398	Accident Damaged # 36455 R/R. o/s. fibreglass edge trim o/s	376379
143	02/05/2013	391856		376379
143	02/05/2013	391856		376379
143	02/05/2013	391856		376379
143	02/05/2013	391856		376379
143	02/05/2013	391856		376379
143	02/05/2013	391856		376379
143	02/05/2013	391856		376379
143	02/05/2013	391856		376379
143	02/05/2013	391856	POWER STEERING FILTER VOLVO	376379

143	02/05/2013	391856	FUEL FILTER ELEMENT SCANIA L94UAB (R90T / H7090WK10)		376379
143	02/05/2013	391856	FILTER FUEL K124 / LU94A (1411894 / H17WK05)		376379
143	02/05/2013	391856	FILTER K124EB HYD COOLING FAN		376379
143	02/05/2013	391856	FILTER AIR DRYER SCANIA K124EB (T350W)		376379
143	02/05/2013	391856	FILTER OIL GEARBOX DIFF K124		376379
143	02/05/2013	391856	RPM BORATE EP LUBE 220		376379
143	02/05/2013	391856		Replace coolant filter in engine cooling system	376379
143	02/05/2013	391856		Clean a/c filters	376379
143	02/05/2013	391626	Steering - Steering wheel cover loose	ordered	376379
143	02/05/2013	392034	Eng Cool - Coolant leak	Fitted hose clamp & added coolant	376379
143	02/05/2013	391480	Body & Acc - Replace rear middle door seals	replaced one	376379
143	02/05/2013	391480	WHEEL ARCH BRUSH PLASTIC		376379
143	02/05/2013	391480	'GIVE WAY' DECAL 240MM X 225MM		376379
143	02/05/2013	391398	Accident Damaged # 36455 R/R. o/s. fibreglass edge trim o/s	repairing accident damaged	376379
143	02/05/2013	391480	Accident Damaged # 35664 R/R. n/s/r. trailer clearance light	Painted all panels & refitted w/arch brush hinge rubber trailer door rubber	376379
143	02/04/2013	391480	2MM X 1200MM X 2400MM FLAT ALUMINIUM		376379
143	02/04/2013	391771	Body & Acc - Secure all lower skirt panel	Secured	376379
143	02/04/2013	391771	Body & Acc - Replace give way decal - OSR corner window	Replaced	376379
143	02/04/2013	391771	Body & Acc - Paint wheels	Painted	376379
143	02/04/2013	391771	Body & Acc - Replace end caps on OS 512	Replaced	376379
143	02/04/2013	391771	Body & Acc - Paint till stand	Painted	376379
143	02/04/2013	391771	Body & Acc - Replace emergency exit decal - NSOS front	Replaced	376379
143	02/04/2013	391480	Body & Acc - NS pax holding rail in middle curtain area bend		376379
143	02/04/2013	391480	3MM X 1200MM X 2400MM FLAT ALUMINIUM		376379
143	02/04/2013	391480	Accident Damaged # 35664 R/R. n/s/r. trailer clearance light		376379
143	02/04/2013	391480	Accident Damaged # 35664 R/R. n/s/r. trailer clearance light	remove all panels prep and painted o/s/r trailer panel and n/s panels	376379
143	02/02/2013	391657	Complete Campaign 16/12 as required	began repairs	376379
143	02/01/2013	391398	Annau Body Inspection	Painted wheels	376379
143	02/01/2013	391398	Accident Damaged # 36455 R/R. o/s. fibreglass edge trim o/s	completed	376379
143	01/30/2013	385800	AIR CONDITIONING REPAIR	started accident repairs	376379
143	01/24/2013	390316	Consumable - ELECTRICAL	Creditor # :CEL001 22 CELSIUS P/O # :G119489 Receiving # :120207 Date :2013-01-30	376379
143	01/23/2013	390316	Elec & Light - All lights are n/w		376147
143	01/23/2013	390141	Air System Air pape behind front/r wheel leaks	Changed fuse and put hand rail back again	376147
143	01/22/2013	389944	Whls & Tyres - side wall damage	Fit new joyner and secured	375941
143	01/22/2013	390063	Body & Acc - Secure pax hand rail	Scrapped	375614
143	12/27/2012	386610	Eng Cool - Clean radiator	secured	375941
143	12/27/2012	386610	Eng Cool - Clean radiator	Cleaned	375614
143	12/27/2012	386619	Body & Acc - Replace passenger seat	Cleaned	375614
143	12/27/2012	386449		Replaced	375614
143	12/27/2012	386449		A Service & Bus Safety Inspection	375614
143	12/27/2012	386449		Tension ALL Wheel Nuts to OEM Specs	375614
143	12/21/2012	385800	Air Cond - Twin a/c compressors loose in bracket (bolts sna		375614
143	12/21/2012	385800	Air Cond - Twin a/c compressors loose in bracket (bolts sna	rECLAIM REFRIGERANT - repaired by 22C - 22/01/2013	375614
143	12/20/2012	385632	STARTER MOTOR SCANIA K93+L94	Replaced both rear unit compressors & regassed by 22c	375614
143	12/19/2012	385800	Air Cond - Twin a/c compressors loose in bracket (bolts sna		375614
143	12/19/2012	385614	Eng Cool - REPLACE WATER LEVEL SWITCH	A/C compressor mounting bracket broken tied up parts ordered	375614
143	12/19/2012	385614	SENDER LOW WATER LEVEL SCANIA	Coolant level sender changed.	375614
143	12/18/2012	385521	Wont start Brighton Town Hall.		375614
143	12/18/2012	385632	Breakdown - Brighton Town Hall - OUT 4.00 pm BACK 7.30 pm -	Drive To Brighton City Hall.Check problem.Unable to restart-faultystarter.Come back to depot.(15.10 - 16.40)	375614
143	12/13/2012	385000	Wipers & Washers - Check wipers	Van 619. Replaced starter motor	375614
143	12/12/2012	384942	Body & Acc - Secure interior panel	OS wiper water pipe came out refitted	375195
143	12/11/2012	384734	Eng Cool - Check coolant light on	Secured	374988
143	12/11/2012	384689	Body & Acc - Secure interior panel	Checked found low level sensor bad connection find connection and top up coolant	374837
143	12/05/2012	383296	FLAT - POS 3 - 275/70 R22.5 74	Secured	374837
143	12/05/2012	383916	Elec & Light - fit back horn cover	Creditor # :BEA001 BEAUREPAIRES P/O # :K117310 Receiving # :118015 Date :2012-12-05 REPAIR OR REPLACE WITH RECAP	373864
143	12/04/2012	383587	PUMP WIPER-WASHER 24 VOLT	Fitted	374055
143	12/03/2012	383587	Wipers & Washers - Replace wiper motor and clean pipes		373641
143	12/03/2012	383296	Whls & Tyres - REPLACE TYRE POS 3 - FLAT	Replaced & cleaned	373641
143	12/03/2012	383048	LOW TREAD - POS 910 - 275/70	REPLACED	373446
143	11/30/2012	383404	Whls & Tyres - Replace flat No 3 tyre	Creditor # :BEA001 BEAUREPAIRES P/O # :K117253 Receiving # :117889 Date :2012-12-03 REPLACE WITH RECAP	373641
143	11/30/2012	383404	Whls & Tyres - Replace flat No 3 tyre	Replaced & torqued w/nuts	373446
143	11/30/2012	383048	Whls & Tyres - Replace tyres 910 - low tread	Replaced	373446
143	11/29/2012	383183	Whls & Tyres - Replace tyres 910	Replaced	373253
143	11/29/2012	383183	Whls & Tyres - Replace tyres 910	Replaced & torqued w/nuts	373253
143	11/29/2012	381499	SIDE FLASHER LAMP AMBER	Assisted Ryan to change & torque	373045
143	11/26/2012	382708	Wipers & Washers - Driver side wiper washer n/w - maybe pip		372600
143	11/25/2012	382395	GLOBE STOP AND TAIL 24V 21/5W	Checked for washer n/w dont have wiper motor	372378
143	11/25/2012	382395	O/S stop/tail light u/s.		372378
143	11/20/2012	382018	Air Cond Belt Replacement	Change globe.	371520
143	11/20/2012	382018	Air Cond Belt Replacement	Replaced	371520
143	11/20/2012	381499	Elec & Light Alternator belt mising	Replaced	371520
143	11/20/2012	381499	BELT ALT W/PUMP CRANK SCANIA ARTIC	Remove alternator mounting braket two broken bolts - fit new bolts and replace A/C belts	371520
143	11/20/2012	381499	PUMP WIPER-WASHER 24 VOLT		371520
143	11/20/2012	381499	Elec & Light Alternator belt mising		371520
143	11/20/2012	381499			371520
143	11/20/2012	381499		FITTED NEW ONES	371520
143	11/20/2012	381499	M12 X 35 8.8 SETSCREW	Creditor # :ECO001 ECONOMY BOLT CO. P/L P/O # :G116775 Receiving # :117286 Date :2012-11-20	371520
143	11/20/2012	381499	IDLER PULLEY	Creditor # :SCA001 SCANIA AUSTRALIA PTY LTD P/O # :G116785 Receiving # :117295 Date :2012-11-20	371520
143	11/20/2012	382018	Body & Acc - Alternator belts needed no dip stick R/H wip	Replaced	371520
143	11/19/2012	381499	Elec & Light Alternator belt mising	go to keysborough fit alt belt and ordered dip stickit got taken out by the belt	371327
143	11/19/2012	381499	BELT ALT W/PUMP CRANK SCANIA ARTIC		371327
143	11/19/2012	381499	SCANIA DIP STICK L94UAB		371327
143	11/13/2012	380922	Air Cond - Clean a/c filters	Cleaned	370666
143	11/13/2012	380782	GLOBE+HOLDER INSTRUMENT (GREY)		370666
143	11/12/2012	380782	Elec & Light - Replace RHS rear tubelight	Replaced	370666
143	11/12/2012	380782	Elec & Light - Replace speedo globe	Replaced	370666
143	11/12/2012	380782	Eng Cool - Clean radiator	Cleaned	370666
143	11/12/2012	380609		A Service & Bus Safety Inspection	370468
143	11/12/2012	380609		A Service & Bus Safety Inspection	370468
143	11/12/2012	380609		Tension ALL Wheel Nuts to OEM Specs	370468
143	11/11/2012	380693	Body & Acc - Secure panel	Secured with new cap screws	370468
143	11/05/2012	379613	PUMP WIPER-WASHER 24 VOLT		369431
143	11/05/2012	378765	FLAT - POS 2 - 275/70 R22.5 -	Creditor # :BEA001 BEAUREPAIRES P/O # :K115851 Receiving # :116708 Date :2012-11-05 REPAIR OR REPLACE WITH NEW	369665

143	11/05/2012	378765	WORN - POS 4 - 275/70 R22.5 74	Creditor #:BEA001 BEAUREPAIRES P/O #:K115851 Receiving #:116708 Date :2012-11-05 SUPPLIED BY GRENDA	369665
143	10/31/2012	379613	Wipers & Washers - wiper n/w	tried to fix wiper maybe pipe cut in middle replaced wiper motor	369012
143	10/31/2012	379131	BELT		368795
143	10/31/2012	379131	BELT ALT W/PUMP CRANK SCANIA ARTIC		368795
143	10/31/2012	379131	CRANK TO PULLEY SCANIA 21/32X67		368795
143	10/30/2012	378765	Whls & Tyres - replace tyre pos 24 - flat	Replaced	368391
143	10/30/2012	379131	Elec & Light - Flat batteries	Found alt & a/c belts missing replaced r/tested OK	368795
143	10/29/2012	378517	WEAR SENSOR SCANIA DISC BRAKE		368391
143	10/29/2012	378517	DISC PAD SET SCANIA MB0500		368391
143	10/28/2012	378747	Breakdown - Boxhill Station - OUT 5.30 pm BACK 7.30 pm - Wo	Van 619. Jump started and returned	368391
143	10/27/2012	378741	Whls & Tyres - Replace tyre pos 4	Replaced	368182
143	10/26/2012	378690	Whls & Tyres - Replace tyre 2	Replaced flat tyre noticed disc pads were worn took bus to GBS and assisted Alan to replace	368399
143	10/26/2012	374203	Side wall damage - Scrap	Creditor #.:BEA001 BEAUREPAIRES P/O #:G114443 Receiving #:116263 Date :2012-10-26	368399
143	10/26/2012	374203	Side wall damage - Scrap	Creditor #.:BEA001 BEAUREPAIRES P/O #:G114443 Receiving #:116274 Date :2012-10-26	368399
143	10/26/2012	378517	Mechanic entered - Brakes Brake Linings Worn	Fit new front brake pads r/tested Ok	367765
143	10/23/2012	377896	GLOBE FESTOON 24V5W		367145
143	10/22/2012	377896	Air Cond - Clean a/c filters	Cleaned	367145
143	10/22/2012	377607	Drv entered - Passenger Doors Require Adjusted	Adjusted	367019
143	10/22/2012	377607	Engine - replace dipstick	Replaced	367019
143	10/22/2012	377607	SCANIA ALT BELT ROLLER(METAL) K1241B+L94UAB		367019
143	10/22/2012	377607	BELT ALT W/PUMP CRANK SCANIA ARTIC		367019
143	10/22/2012	377607	SCANIA DIP STICK L94UAB	Creditor #.:SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G115478 Receiving #:116046 Date :2012-10-22	367019
143	10/22/2012	377607	BELT ALT W/PUMP CRANK SCANIA ARTIC		367019
143	10/22/2012	377607	FAN BELT A/CON ARTIC 21/32X45		367019
143	10/22/2012	377607	CRANK TO PULLEY SCANIA 21/32X67		367019
143	10/22/2012	377607	Engine - Very sluggish no power (Checked on 29/05/1225/06/	Checked OK	367019
143	10/22/2012	377607	Engine - S/clean chassis and engine (Checked on 25/06/121	Checked OK	367019
143	10/22/2012	377607	Engine - belt idler seized	New engine idler fitted new belt fitted and adjusted tensioner s/cleaned engine checked OK	367019
143	10/22/2012	377607	Elec & Light - Drivers cabin down light n/w	Checked OK	367019
143	10/22/2012	377896	Elec & Light - Replace clearance light	Replaced	367145
143	10/22/2012	377607	Air System - Air leak from front door emergency switch (ns	Checked OK	367019
143	10/19/2012	377607	Engine - belt idler seized	Bring bus back to w/shop	367019
143	10/19/2012	377699	Breakdown - Heatherton Rd - OUT 3.00 pm BACK 4.30 pm - lost	Van 619. Replaced main belt returned (need to replace belts & pulleys)	367019
143	10/11/2012	376286	Mechanic entered - Elec & Light Other	J/STARTED BUS AND REPLACED DRIVER DOWNLIGHT GLOBE OK.	365869
143	10/11/2012	376286	HALOGEN GLOBE 24V20W		365869
143	10/07/2012	375603	Elec & Light - Bus wont start	Jump started	365475
143	10/04/2012	375410	Elec & Light - Replace emer exit light globe	Replaced	365254
143	10/03/2012	366960	DRIVERS SEAT BELT BUCKLE		365104
143	10/02/2012	373695	FILTER DRIER 5/8		365104
143	09/26/2012	374203	Whls & Tyres - Scrap tyre - sidewall damage	Scrapped	365104
143	09/24/2012	373695		Clean R/A & F/A filters; inspect and report on condition; Replace filter media	365104
143	09/24/2012	373695		FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)	365104
143	09/24/2012	373695		COMPRESSOR DRIVE BELTS: Inspect belt wear; Retension belts;	365104
143	09/24/2012	373695		DRIVE PULLEY'S: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;	365104
143	09/24/2012	373695		DRIVE PULLEY'S: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear	365104
143	09/24/2012	373695		COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose	365104
143	09/24/2012	373695		REFRIGERATION FILTER DRYER: Replace filter dryer; check pump operation;	365104
143	09/24/2012	373695		EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check boltsclamps & fittings; clean condensate drains; clean drip tray	365104
143	09/24/2012	373695		CONDENSOR AREA: Clean condensor coils; check boltsclamps for tension	365104
143	09/24/2012	373695		INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condensor fan grills	365104
143	09/24/2012	373695		UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensor pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation	365104
143	09/21/2012	373696	Ops Entered - Fault - Passenger Doors Slow - Route: - TIM	Fitted new emergency door open valve & new 3rd door operating switch	365104
143	09/20/2012	372441	UNEVEN - POS 1 - 275/70 R22.5	Creditor #.:BEA001 BEAUREPAIRES P/O #:K113873 Receiving #:114531 Date :2012-09-20 REPLACE WITH RECAP	364929
143	09/20/2012	373459	Elec & Light - Bus wont start	Jump started	364929
143	09/19/2012	373239	Steering - Add power steering fluid	Added	364880
143	09/19/2012	373122	FAN BELT A/CON ARTIC 21/32X45		364880
143	09/18/2012	373122	Air Cond - A/C belt is cracked	Changed	364880
143	09/18/2012	373142	Random Vehicle Audit	Inspected	364880
143	09/18/2012	373122	Elec & Light - NSR interior fluro n/w	Replaced	364880
143	09/18/2012	373143	Eng Cool - Clean radiator	Cleaned	364880
143	09/18/2012	373143	Brakes - Check brake condition	Removed tyre & checked brake condition	364880
143	09/18/2012	372985	O RING FILTER KIT K93		364865
143	09/18/2012	372985	FILTER AIR SCANIA USE AF25066		364865
143	09/18/2012	372985	ENGINE OIL DELO 400LE 15W40		364865
143	09/18/2012	372985	TEXAMATIC 1888		364865
143	09/18/2012	372985		D Service & Bus Safety Inspection	364865
143	09/18/2012	372985		Tension ALL Wheel Nuts to OEM Specs	364865
143	09/18/2012	372985	FILTER OIL K124 / L94UAB (H200W02)		364865
143	09/18/2012	372985	FILTER TRANSMISSION ZF 4139-298-038E39HD119		364865
143	09/18/2012	373012		A Service & Bus Safety Inspection	364865
143	09/18/2012	373012		Tension ALL Wheel Nuts to OEM Specs	364865
143	09/18/2012	372985		A Service & Bus Safety Inspection	364865
143	09/18/2012	372985		Tension ALL Wheel Nuts to OEM Specs	364865
143	09/14/2012	372441	Whls & Tyres - Replace tyre pos 1 - uneven	Replaced	364351
143	09/13/2012	372455	Whls & Tyres - Replace NSF tyre	replaced & arranged tyres in store	364351
143	08/21/2012	369365	Elec & Light - Replace emergency exit light globe	Replaced	361237
143	08/17/2012	368556	PUMP WIPER-WASHER 24 VOLT		360570
143	08/15/2012	368556	Wipers & Washers - Wiper washer n/w	Cleaned all pipes changed motor and moved started working now	360374
143	08/07/2012	367101	INDICATOR LIGHT FRONT ARTIC		359022
143	08/07/2012	367106	GLOBE S/CONTACT 24V-10W		359022
143	08/06/2012	367101	Elec & Light - Replace broken OS indicator	Replaced	359022
143	08/06/2012	367106	Elec & Light - Replace NSF top park light	Replaced	359022
143	08/05/2012	366960	Body & Acc - Replace drivers seat belt buckle	Replaced	358846
143	08/01/2012	366266	GLOBE FESTOON 24V-3W		357961
143	07/30/2012	366266	Drv entered - Wipers & Washers Washers Not Working	Pipes were out put back on	357961
143	07/30/2012	366266	Elec & Light - Replace emer exit globe	Replaced	357961
143	07/27/2012	365718	GLOBE FESTOON 24V-3W		357961
143	07/26/2012	365718	Elec & Light - Replace emergency exit light globe	replaced	357961
143	07/16/2012	363787	D HANDLE LENLOCK CHROME PLATED		357960
143	07/15/2012	363666	Body & Acc - Repair mirror	Replaced	357960
143	07/13/2012	363666	CONVEX MIRROR		357960
143	07/13/2012	363666	MOUNTING CONVEX MIRROR		357960
143	07/12/2012	363787	Body & Acc Enginr door catch missing	replaced	357960

143	07/06/2012	362871	Elec & Light - Refit horn pad	Refitted	357960
143	07/04/2012	361981	Whls & Tyres - REPLACE TYRE POS 4 - FLAT	REPLACED	357957
143	07/03/2012	361975	WHEEL NUT SQUIRREL		357957
143	07/02/2012	361975	Whls & Tyres - Replace tyre 4	Replaced tyre & w/nuts. tensioned w/nuts	357957
143	07/01/2012	343439	LEVEL SENSOR	Creditor #::MUL001 MULTISPARES LTD P/O #:G104751 Receiving #:105325 Date :2012-02-24	338153
143	07/01/2012	361819	Elec & Light - Bus wont start	Jump started	357957
143	06/29/2012	360796	Heat & Demist - Heater n/w	completed	357957
143	06/29/2012	361455	Body & Acc - Seat uncomfortable needs looking at	replaced foam cushion	357957
143	06/29/2012	361455	Body & Acc - Clear tape left overs distorting view	cleaned windscreen of tape	357957
143	06/29/2012	360796	Body & Acc - Door ramp lock out n/w	went to Volgren for part and fit to w/chair ramp working OK	357957
143	06/28/2012	361106	WORN - POS 78 - 275/70 R22.5	Creditor #::BEA001 BEAUREPAIRES P/O #:G110112 Receiving #:110617 Date :2012-06-28 REPLACE WITH RECAP	357957
143	06/28/2012	361106	WORN - POS 78 - 275/70 R22.5	Creditor #::BEA001 BEAUREPAIRES P/O #:G110112 Receiving #:110618 Date :2012-06-28 REPLACE WITH RECAP	357957
143	06/28/2012	360796	GLOBE DASH B7L		357957
143	06/28/2012	360796	GLOBE DASH B7L		357957
143	06/28/2012	360796	Elec & Light - High beam indicator light on dash n/w	Fitted new relay r/tested OK	357957
143	06/28/2012	360796	Elec & Light - Door switches n/w prop	Fixed broken bolt in front door middle door rubber on door edge fell down push back up door not slamming now	357957
143	06/28/2012	360796	RELAY 24V/20AMP	Fixed broken bolt in front door middle door rubber on door edge fell down push back up door not slamming now	357957
143	06/28/2012	360796	Body & Acc - Door ramp lock out n/w	Unable to fault switches	357957
143	06/27/2012	361106	Whls & Tyres - Replace tyre pos 78 - worn	Replaced	357957
143	06/27/2012	360796	Suspension - Bus goes up/down when stationary	Checked and replaced suspension level sensor NS middle axle	357957
143	06/27/2012	360796	Heat & Demist - Heater n/w	Rewired boost pump ordered relay Tues still have no relay	357957
143	06/27/2012	360796	Elec & Light - Door switches n/w prop	Checking out relay fuses and sender	357957
143	06/26/2012	360796	Heat & Demist - Heater n/w	Checked heater boost pump n/w relay n/w ordered parts	357957
143	06/26/2012	360796	Elec & Light - High beam indicator light on dash n/w	Replaced globe	357957
143	06/26/2012	360796	Elec & Light - Internal lights reflecting to strongly	Replaced	357957
143	06/26/2012	360796	Body & Acc - Replace struts on rear OS panel	Replaced	357957
143	06/26/2012	360944	FRONT DISC BRAKE ROTORS SCANIA(40F3319)		357957
143	06/26/2012	360944	Brakes - Rear axle rotor 37mm L & R	Replaced	357957
143	06/26/2012	360944	Brakes - Rear axle rotor 37mm L & R	Assist allan with brakes	357957
143	06/26/2012	360944	Brakes - Rear axle rotor 37mm L & R	Fitted new LHR tyres	357957
143	06/26/2012	361185	Ops Entered - Fault - Brakes - Route: - MEAL at New Grend	Remove NS drive axle hub assy changed hub seal kit brake disc adjust hub bearing and fixed hub axle to bus	357957
143	06/26/2012	360944	INNER SEAL REAR AXLE SCANIA L94UAB		357957
143	06/26/2012	360944	OUTER HUB SEAL REAR SCANIA L94UAB+L113CRB		357957
143	06/26/2012	360944	GASKET REAR AXLE SCANIA		357957
143	06/26/2012	360944	DISC PAD SET SCANIA MB0500		357957
143	06/25/2012	360796	Passenger Doors - Front door operation very rough	Checked out bus and checked for parts	357957
143	06/25/2012	360944	Brakes - Rear axle rotor 37mm L & R	Removed rear hubs & rotors c/o	357957
143	06/25/2012	360822		A Service & Bus Safety Inspection	357957
143	06/25/2012	360822		Tension ALL Wheel Nuts to OEM Specs	357957
143	06/22/2012	360521	GLOBE INST 24V 2W		357957
143	06/21/2012	360521	Elec & Light - NSR clearance & NS mid full of water	Drilled holes in bottom to drain water & replaced globes	357957
143	06/20/2012	360193	PUMP WIPER-WASHER 24 VOLT		357653
143	06/19/2012	360193	Wipers & Washers - Washer bottle missing	Changed washer motor and refitted pipe connections back from bottle	357653
143	06/19/2012	360193	Wipers & Washers - NS wiper jet missing	Changed washer motor and refitted pipe connections back from bottle	357653
143	06/19/2012	359972	GLOBE FESTOON 24V5W		357653
143	06/19/2012	359972	LAMP (RED+AMBER)		357653
143	06/18/2012	359972	Elec & Light - Replace broken NSR red/amber clearance light	Replaced	357653
143	06/14/2012	359516	Wipers & Washers - Blocked wiper n/w	Checked there is no water bottle	352208
143	06/07/2012	358735	Body & Acc - Secure mirror bracket	Secured	351447
143	05/29/2012	357047	Brakes - Check rear brakes	Removed tyres 910 to check brake & disc - low	350027
143	05/29/2012	356950		A Service & Bus Safety Inspection	349915
143	05/29/2012	356950		Tension ALL Wheel Nuts to OEM Specs	349915
143	05/29/2012	356950		A Service & Bus Safety Inspection	349915
143	05/25/2012	356720	Body & Acc - Windscreen leaking from top left side	Sealed top aerial and satellite unit	349730
143	05/15/2012	354964	LAMP (RED+AMBER)		348130
143	05/15/2012	354964	GLOBE FESTOON 24V5W		348130
143	05/11/2012	353685	BALD - Recap - 275R 22.5 - pos	Creditor #::BEA001 BEAUREPAIRES P/O #:K107806 Receiving #:108294 Date :2012-05-11 Replace	347931
143	05/09/2012	354964	Elec & Light Replace parking light	Replaced	347548
143	05/07/2012	353685	Whls & Tyres - Replace pos 9 and 10 tyre - bald	Replaced	346991
143	05/04/2012	353772	Whls & Tyres Replace tyres 9.10	Erplaced	346991
143	04/23/2012	351773	Elec & Light - Bus wont start	Jump started at KSB	345479
143	04/20/2012	348005	ROAD SAFETY INSPECTIONS	Creditor #::ROA001 Road Safety Inspections P/O #:G106085 Receiving #:107433 Date :2012-04-20	345218
143	04/20/2012	351306	GLOBE FESTOON 24V5W		344983
143	04/18/2012	351306	Elec & Light - Replace emer exit light globe	Replaced	344785
143	04/17/2012	350830	FILTER OIL K124 / L94UAB (H200W02)		344575
143	04/17/2012	350830	FILTER TRANSMISSION ZF 4139-298-038E39HD119		344575
143	04/17/2012	350830	O RING FILTER KIT K93		344575
143	04/17/2012	350830	FILTER AIR SCANIA USE AF25066		344575
143	04/17/2012	350830	ENGINE OIL DELO 400LE 15W40		344575
143	04/17/2012	350830	TEXAMATIC 1888		344575
143	04/17/2012	350830		D Service & Bus Safety Inspection	344575
143	04/17/2012	350830		Tension ALL Wheel Nuts to OEM Specs	344575
143	04/17/2012	350830		A Service & Bus Safety Inspection	344575
143	04/17/2012	350830		Tension ALL Wheel Nuts to OEM Specs	344575
143	04/01/2012	348005	Annual Licence	- RWC 233654 - Passed	341709
143	03/29/2012	348453	Wipers & Washers - Windscreen washers n/w	Diagnose washer fault hose kinked from cable ties motor not sucking heard enough replaced OK	342067
143	03/29/2012	348453	PUMP WIPER-WASHER 24 VOLT		342067
143	03/29/2012	348453	GLOBE STOP AND TAIL 24V 21/SW		342067
143	03/29/2012	348453	Air System - Front door switch on b/bar has air leak - order	Repaired	342067
143	03/27/2012	348342	Elec & Light - Refit horn cover properly	Refitted	341941
143	03/27/2012	348358	Elec & Light - horn n/w	Ref to w/o 348342	341941
143	03/23/2012	347666	Elec & Light - Bottom left tail light blown	Ref to w/o # 347437	340905
143	03/22/2012	347437	GLOBE STOP AND TAIL 24V 21/SW		340692
143	03/21/2012	347437	Elec & Light - Bottom rear left park light out	Replaced	340692
143	03/19/2012	347085	Elec & Light - Bus wont start	Jump started	340581
143	03/16/2012	346765	Whls & Tyres - Replace w/nut indicators	Torqued 910 w/nuts and replaced indicators	340581
143	03/14/2012	346131		Inspect bus as per inspection sheet	340579
143	03/14/2012	346131		Remove intercooler wash intercooler and raditor	340579
143	03/14/2012	346131		Clean a/c filters	340579
143	03/14/2012	346131		Replace coolant filter in engine cooling system	340579
143	03/14/2012	346131	RPM BORATE EP LUBE 220		340579
143	03/14/2012	346131	FILTER OIL GEARBOX DIFF K124		340579
143	03/14/2012	346131	FILTER K124EB HYD COOLING FAN		340579

143	03/14/2012	346131	FILTER FUEL K124 / LU94A (1411894 / H17WK05)		340579
143	03/14/2012	346131	FUEL FILTER ELEMENT SCANIA L94UAB (R90T / H7090WK10)		340579
143	03/14/2012	346131	POWER STEERING FILTER VOLVO		340579
143	03/14/2012	346131		Replace air dryer canister	340579
143	03/14/2012	346131		Replace hydraulic fan filter and top up oil	340579
143	03/14/2012	346131		Rekit quick release valve	340579
143	03/14/2012	346131		Replace power steering filter	340579
143	03/14/2012	346131		Inspect bus as per inspection sheet	340579
143	03/14/2012	346131		Replace fuel filters	340579
143	03/14/2012	346131		Replace final drive oil	340579
143	03/14/2012	346131		Adjust valve clearances	340579
143	03/14/2012	346131	FILTER AIR DRYER KIT(HALDEX)		340579
143	03/14/2012	346458	Elec & Light - Broken interior holder		340579
143	03/09/2012	343316	SP 275/70R22.5 SP138 DHR - FIT		339702
143	03/05/2012	344962	Air Cond - Clean a/c filter	Creditor #:BEA001 BEAUREPAIRES P/O #:G104718 Receiving #:105875 Date :2012-03-09 Replace with recap Cleaned	339695
143	02/28/2012	343694	GLOBE STOP AND TAIL 24V 21/SW		338231
143	02/28/2012	343908	Ops Entered - Fault - Brakes - Route: 811 - Centre Dandenoe	Ref to w/o # 343694	338231
143	02/27/2012	343439	BUTTON PUSH DRIVE		338153
143	02/27/2012	343694	Elec & Light - Replace NS rear stop light globe	Replaced	338231
143	02/27/2012	343906	Breakdown - Cnr Heatherton & Westall Rds - OUT 7.00 am BACK	Van 619. Checked and returned. (removed n/s front wheel remove brake pads cleaned disc fitted back r/tested)	338231
143	02/27/2012	343694	Mechanic entered - Brakes Smoking / Smell	Removed NS front wheel remove brake pads cleaned up brake disk fitted back & r/tested	338231
143	02/27/2012	343694	Brakes - Brakes pulling to right	Adjusted brakes	338231
143	02/24/2012	338341	STARTER MOTOR SCANIA K93+L94		338019
143	02/24/2012	343316	Whls & Tyres - Replace tyre pos 9 - bald	Replaced	338019
143	02/24/2012	343439	Suspension - Drive axle levelling valve & shock broken	Assisted Sisil to change shock absorber levelling valve & r/tested	338153
143	02/24/2012	343439	Suspension - Drive axle levelling valve & shock broken	Changed shock absorber levelling valve & r/tested & replaced Drive button	338153
143	02/24/2012	343439	Steering - Steering wheel play	Found line bolt loose fixed	338153
143	02/24/2012	343387	STARTER MOTOR SCANIA K93+L94		338019
143	02/23/2012	343400	Whls & Tyres - Replace tyre pos 9	Replaced tyre	338019
143	02/23/2012	343400	Whls & Tyres - Replace tyre pos 9	Replaced tyre. Removed OS middle axle tyres and checked brake pads	338019
143	02/23/2012	343387	Elec & Light - C/O starter motor	Changed over	338019
143	02/23/2012	343242	Tensioned w/nuts & cleaned radiator		338019
143	02/23/2012	343242		Tension ALL Wheel Nuts to OEM Specs	338019
143	02/23/2012	343242		A Service & Bus Safety Inspection	338019
143	02/21/2012	342852	Bus will not start at Brighton town hall	Check batteries ok trace to faulty starter. Tap starter and start bus. Return to depot	337592
143	02/20/2012	342752	Air Cond - Clean a/c filter	Cleaned	337592
143	02/20/2012	342752	Body & Acc - Refit w/arch brush	Refitted	337592
143	02/15/2012	342147	Body & Acc - Secure rear hatch grab handles	Secured	337238
143	02/14/2012	341715	GLOBE DASH B7L		337056
143	02/13/2012	341715	Elec & Light - Replace dash light globe	Replaced	337056
143	02/10/2012	341398	TORQUE ROD BUSH 75MM FRONT SUIT L94UAB SCANIA	Assisted Subu with bus	337030
143	02/10/2012	341398	Brakes - Brake problems - wobbling	Changed both front wheels tensioned w/nuts r/tested OK adjusted brakesr/tested still pulls found front torque rod bush worn removed and changedcleaned front wheels checked OK	337030
143	02/10/2012	341398	Brakes - Pulling to right side when brakes applied	Assisted Subu with bus	337030
143	02/09/2012	341228	Air Cond - Clean a/c filters	Cleaned	337030
143	02/07/2012	340938	Body & Acc - Refit w/arch brush at rear	Refitted	336807
143	02/06/2012	338341	STARTER SOLENOID SUIT JF		336312
143	02/06/2012	339310	ALUMINIUM NO 12 STRAIGHT FLARE		336312
143	02/06/2012	339310	AIR CON REFRIDGERANT		336312
143	02/02/2012	338341	S/motor rebuild ordered new solenoid	S/motor rebuild completed tested OK	
143	02/01/2012	338341	S/motor rebuild ordered new solenoid	S/motor rebuild c/o	
143	02/01/2012	340095	Air Cond - A/C rear n/w fault light on very hot	Ref to w/o 339310	336015
143	01/31/2012	339545	Whls & Tyres - Replace tyre pos 8 - tyre burst	Replaced	335663
143	01/31/2012	339545	Fitting	Creditor #:BEA001 BEAUREPAIRES P/O #:K103625 Receiving #:104576 Date :2012-02-07	336807
143	01/31/2012	339545	BALD	Creditor #:BEA001 BEAUREPAIRES P/O #:K103625 Receiving #:104576 Date :2012-02-07	336807
143	01/31/2012	339878	Elec & Light - Bus wont start	Jump started	335844
143	01/30/2012	339383	Wipers & Washers - Wipers n/w	checked ok	335606
143	01/30/2012	339310	Air Cond - Rear a/c fault 38.9	Locate and repair refrigerant leak replace suction hose on unit 2 tested OK	335606
143	01/30/2012	339310	Air Cond - Rear a/c n/w	Locate and repair refrigerant leak replace suction hose on unit 2 tested OK	335606
143	01/30/2012	339310	Air Cond - A/C faulty - back part hot air	Locate and repair refrigerant leak replace suction hose on unit 2 tested OK	335606
143	01/30/2012	339310	Air Cond - Faulty a/c blowing hot air 40	Locate and repair refrigerant leak replace suction hose on unit 2 tested OK	335606
143	01/30/2012	339310	Air Cond - Back a/c n/w 44.2c	Locate and repair refrigerant leak replace suction hose on unit 2 tested OK	335606
143	01/30/2012	339310	Air Cond - Rear a/c red fault high 20s	Locate and repair refrigerant leak replace suction hose on unit 2 tested OK	335606
143	01/25/2012	339536	Whls & Tyres - Needs No 8 tyre	Replaced pos 8 rear tyre cleaned rim & hub	335423
143	01/24/2012	338942	Air Cond - Clean a/c filter	Cleaned	335204
143	01/23/2012	338739	Elec & Light - Bus wont start	Turned flywheel and started bus	335020
143	01/20/2012	338178	BUSH KIT SUIT JF		334589
143	01/20/2012	338749	Elec & Light - Bus wont start	Knocked starter a couple of times then started	334805
143	01/19/2012	338178	Elec & Light - non starting	Changed starter motor	334589
143	01/19/2012	338178	GLOBE+HOLDER INSTRUMENT (GREY)		334589
143	01/19/2012	338178	Elec & Light - Stop signal on dash not coming on	Checked park brake lights OK	334589
143	01/19/2012	338178	Elec & Light - Stop signal on dash not coming on	Changed stop light dash globes	334589
143	01/19/2012	338178	Elec & Light - Stop signal on dash not coming on	Ass Brad with checking brakes OK	334589
143	01/19/2012	338178	STARTER MOTOR SCANIA K93+L94		334589
143	01/16/2012	337758	Elec & Light - Starter motor		334077
143	01/10/2012	336588	GLOBE INST 24V 2W	Checked OK ref to w/o 333844	333285
143	01/09/2012	333844	Starter motor rebuild waiting on parts	Finished & tested s/motor OK	
143	01/06/2012	336249	Done at Roadworthy inspection – Doc 135889	A Service & Bus Safety Inspection	332953
143	01/06/2012	336249		Tension ALL Wheel Nuts to OEM Specs	332953
143	01/05/2012	336588	Elec & Light - Replace No plate light globe	Replaced	332953
143	12/22/2011	331521	SCRAP	Creditor #:BEA001 BEAUREPAIRES P/O #:G101929 Receiving #:103016 Date :2011-12-22	331545
143	12/21/2011	334449	GLOBE STOP AND TAIL 24V 21/SW		331374
143	12/20/2011	334599	Air Cond - Clean a/c filter	Cleaned	331374
143	12/20/2011	334599	Body & Acc - Secure overhead passenger hand strap screws	Secured	331374
143	12/19/2011	334449	Elec & Light - Replace globes	Replaced	331140
143	12/15/2011	333844	BUSH KIT SUIT JF		
143	12/15/2011	333844	STARTER SOLENOID SUIT JF		
143	12/15/2011	333844	JF24V 4KW BRUSH SET		
143	12/14/2011	333844	Starter motor rebuild waiting on parts		
143	12/13/2011	331521	Pos 478 - bald and damage	Creditor #:BEA001 BEAUREPAIRES P/O #:G101144 Receiving #:102532 Date :2011-12-13 Replace - Cap	330224
143	12/13/2011	333366	Elec & Light - check non starting	Diagnosed faulty starter motor	330224
143	12/13/2011	333366	STARTER MOTOR SCANIA K93+L94		330224
143	12/13/2011	333366	Elec & Light - check non starting	Replaced starter motor	330224
143	12/13/2011	333366	Elec & Light - check non starting	Rebuild starter motor	330224

143	12/12/2011	333388	Elec & Light - Bus wont start	Jump started	330224
143	12/12/2011	333454	Elec & Light - Bus wont start	Jump started at KSB	330224
143	12/09/2011	333180	Elec & Light - Replace OS rear park light globe	Replaced	330068
143	12/09/2011	333184	Elec & Light - Bus wont start	Jump started	330068
143	12/07/2011	332855	Elec & Light - Bus wont start at KSB	Jump started and returned	329692
143	12/07/2011	332855	Elec & Light - Bus wont start at KSB	Jump started and returned	329692
143	12/07/2011	332863	Elec & Light - Bus wont start on fuel bay	Checked batteries and fuses knocked starter still wont start called GBS	329692
143	12/05/2011	332268	INTERIOR LIGHT DEFUSER		329093
143	12/02/2011	332011	GLOBE FESTOON 24V5W		328860
143	12/02/2011	332268	Elec & Light - Replace interior light globe	Replaced	329093
143	12/01/2011	332011	Elec & Light - Replace emer exit light globe	Replaced	328860
143	11/30/2011	331521	Whls & Tyres - Replace tyre pos 478 - bald damaged	Replaced	328403
143	11/29/2011	331523	Whls & Tyres - Replace tyre pos 347 & 8	Replaced	327129
143	11/29/2011	331523	Whls & Tyres - Replace tyre pos 347 & 8	Replaced	327129
143	11/29/2011	329900	Random Vehicle Audit	Inspected	327129
143	11/29/2011	329899		A Service & Bus Safety Inspection	327129
143	11/29/2011	329899		Tension ALL Wheel Nuts to OEM Specs	327129
143	11/29/2011	329899		A Service & Bus Safety Inspection	327129
143	11/28/2011	329910	BALD 275R NEW	Creditor # :BEA001 BEAUREPAIRES P/O #:G100671 Receiving #:101836 Date :2011-11-28	328173
143	11/28/2011	329836	FUEL BOWL	Creditor # :SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G100655 Receiving #:101798 Date :2011-11-28	328173
143	11/21/2011	330323	Elec & Light - Replace light & lens	Replaced cracked clearance light lens & RR indicator light	327308
143	11/21/2011	330400	Elec & Light - Bus wont start	Jump started	327308
143	11/21/2011	329899	LENS TO SUIT 2029 (RED+AMBER)		327216
143	11/21/2011	329899	GLOBE FESTOON 24V5W		327216
143	11/21/2011	329899	LAMP INDICATOR [ORANGE]		327216
143	11/18/2011	329910	Whls & Tyres - Replace tyre pos 1 - uneven wear	Replaced	327129
143	11/18/2011	329836	Ops Entered - Fault - Engine - Route: - TIM to read: Rout	Repaired fuel/water seperator bowl & bled air in fuel system	327129
143	11/18/2011	329836	Ops Entered - Fault - Engine - Route: - TIM to read: Rout	Checked and found air in fuel system	327129
143	11/18/2011	330160	Engine - Sight glass dirty	Removed water level sight glass coolant leak from glass ordered parts disconnected sight glass top up coolant & r/test	327216
143	11/18/2011	329836	Ops Entered - Fault - Engine - Route: - TIM to read: Rout	Find and fix coolant leak	327129
143	11/17/2011	329958	Breakdown - Police Rd & Springvale Rds - OUT 6.30 am BACK 7	C/O bus 29.. Bled due to air in fuel system	327216
143	11/16/2011	329454	GLOBE S/CONTACT 24V-10W		326894
143	11/15/2011	329670	Wipers & Washers - Check wipers	Cleaned blocked nozzles and tubes from motor	326894
143	11/15/2011	329670	Air Cond - Clean a/c filters	Cleaned	326894
143	11/14/2011	329161	GLOBE INDICATOR 24V-18W SINGLE CONTACT		326440
143	11/14/2011	329454	Elec & Light - Replace OS rear top park light globe	Replaced	326657
143	11/11/2011	318505	ACC PEDAL SESOR	Creditor # :SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G98881 Receiving #:101222 Date :2011-11-11	325948
143	11/11/2011	318505	486722 ACC PEDAL SENSOR		325948
143	11/10/2011	329161	Elec & Light - Replace OSF top indicator light globe	Replaced	325948
143	11/10/2011	329161	Elec & Light - OSR interior light cover broken	Replaced	325948
143	11/09/2011	328980	Elec & Light - Refit OSR interior light cover	Refitted	325548
143	11/08/2011	328247	PUMP WIPER-WASHER 24 VOLT		325334
143	11/07/2011	328247	Wipers & Washers - Replace wiper motor		325334
143	11/03/2011	327466	HEAD LIGHT GLOBE 24V 70/75W	Changed wiper motor and cleaned pipes and o/s pipe came out from nozzle put that back	324724
143	11/02/2011	327466	Elec & Light - Replace NS headlight globe	Replaced	324724
143	11/02/2011	326174	Ops Entered - Fault - Elec & Light - Route: - Take a Arti	Checked wire to fuel pump clean and fixed removed potentiometer from bus 102 fit to bus 143 bus ok fixed air cleaner assy and related parts covers cleaned inside bus r/tested fixed a/c compressor bolt	324585
143	11/02/2011	326174	Ops Entered - Fault - Elec & Light - Route: - Take a Arti	Ass Dulkith to fix EDC found wrong position control switch removed from bus 102 and fitted to 143 bus EDC system OK and order new	324585
143	10/28/2011	326174	Ops Entered - Fault - Elec & Light - Route: - Take a Arti	Fit throttle switch on still n/w properly	324585
143	10/27/2011	326174	Ops Entered - Fault - Elec & Light - Route: - Take a Arti	Checked out wiring found no breaks or shorts still fault codes 4142 take new throttle switch off tried on bus 102 fault came up on that bus too faulty part ordered replacement	324585
143	10/27/2011	326174	Ops Entered - Fault - Elec & Light - Route: - Take a Arti	Ass Greg with computer & find wiring problem	324585
143	10/26/2011	326174	Ops Entered - Fault - Elec & Light - Route: - Take a Arti	Check engine light codes on dash check wire connectors clean and fix same as clear fault code SD 2 need to check potentiometer	324585
143	10/26/2011	326174	Ops Entered - Fault - Elec & Light - Route: - Take a Arti	Ass Dulkith with fault codes	324585
143	10/26/2011	326174	Ops Entered - Fault - Elec & Light - Route: - Take a Arti	Diagnose potentiometer problem & elec prob	324585
143	10/25/2011	326174	Ops Entered - Fault - Elec & Light - Route: - Take a Arti	Checked engine light coming on & low coolant replaced coolant sensor r/tested check engine light comes on and bus loss power no acceration checked fault codes disconnected battery the reconnected r/tested still losing power	324585
143	10/25/2011	326174	Ops Entered - Fault - Elec & Light - Route: - Take a Arti	Ass Phil to change coolant sensor r/tested & disconnected the battery	324585
143	10/25/2011	326174	Ops Entered - Fault - Elec & Light - Route: - Take a Arti	Cleaned coolant level sender inactive codes on dash r/tested	324585
143	10/24/2011	326018	Eng Cool - Add coolant	Added	324585
143	10/24/2011	319019	decals bus	Creditor # :ATT001 ATTITUDE SIGNS P/O #:G97848 Receiving #:100407 Date :2011-10-24	324472
143	10/21/2011	325628	Whls & Tyres - Change OS front tyre	Changed	324472
143	10/21/2011	325628	Engine - MIL fault code	Cleaned wire connector middle of bus clear fault code r/tested bus OK	324472
143	10/20/2011	325073	Throttle sticking	Fit throttle switch	324472
143	10/20/2011	325460	SUS - Front sway bar bushes worn	Checked OK servicable	324472
143	10/20/2011	325460	SUS - Middle axle sway bar bushes (Checked on 31/03/11 14/	Checked OK servicable	324472
143	10/20/2011	325460	Valve Adjustment	Adjusted	324472
143	10/20/2011	325460	EN - S/clean bus	Cleaned	324472
143	10/20/2011	325628	Engine - MIL fault code	Checked fault code and r/tested need to check accelerator pedal wire connection	324472
143	10/20/2011	325460	Eng Cool - flush cooling system	Replaced coolant	324472
143	10/20/2011	325460	Eng Cool - Remove intercooler wash intercooler & radiator	Cleaned	324472
143	10/19/2011	325073	shaft + b/joint 0485973	Creditor # :SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G99283 Receiving #:100151 Date :2011-10-19 143	324472
143	10/17/2011	325073	Throttle sticking	Removed throttle switch found ball joint rusted up ordered new one	324472
143	10/17/2011	321029	SCANIA ALT BELT TENSIONER K1241B		324472
143	10/17/2011	321029	SCANIA ALT BELT ROLLER[METAL] K1241B+L94UAB		324472
143	10/17/2011	321029	Elec & Light - Service Exchange Alternators - Preventative	Reconnected all computers filled with coolant packed up	324472
143	10/17/2011	321096	Eng Cool - Began draining coolant. Found transmision oil in	Ass Matt with drain coolant	324472
143	10/14/2011	321029	Elec & Light - Service Exchange Alternators - Preventative	Fitted alts rebuilt one bus needs computers hooked up & coolant system filled	324472
143	10/13/2011	321029	BEARING ALT MAN 16-240+0500LE		324472
143	10/13/2011	321029	REAR ALTERNATOR BRG SCANIA+0500LE		324472
143	10/13/2011	321029	BRUSH KIT 55AMP ALT B10M MK3		324472
143	10/12/2011	321029	Elec & Light - Service Exchange Alternators - Preventative	Rebuild 1 alt checked OK start rebuilding 2nd washed parts waiting for bearings look for spacers for mounting	324472
143	09/30/2011	321096	Eng Cool - Began draining coolant. Found transmission oil in	Ass Tudor with bolt & nut for welding	324472
143	09/30/2011	321096	Eng Cool - Began draining coolant. Found transmission oil in	Ass Matt	324472
143	09/29/2011	321096	Eng Cool - Began draining coolant. Found transmission oil in	Cont with job to remove broken bolt from alt mount	324472
143	09/28/2011	321029	Elec & Light - Service Exchange Alternators - Preventative	Ass Matt	324472
143	09/28/2011	321029	Elec & Light - Service Exchange Alternators - Preventative	Began removing broken bolt from bus grinded mount down got advice from Tudor & Karl c/o tomorrow	324472
143	09/27/2011	321029	Elec & Light - Service Exchange Alternators - Preventative	Ass Bradman rebuilt alt ready to be fitted to bus	324472
143	09/27/2011	321029	Elec & Light - Service Exchange Alternators - Preventative	Cont with rebuild	324472
143	09/26/2011	321029	REAR ALTERNATOR BRG SCANIA+0500LE		324472
143	09/26/2011	321029	BEARING ALT MAN 16-240+0500LE		324472
143	09/26/2011	321029	Elec & Light - Service Exchange Alternators - Preventative	Removed & repaired alts x 2 from bus	324472
143	09/26/2011	321029	Elec & Light - Service Exchange Alternators - Preventative	Ass Bradman	324472
143	09/23/2011	321029	Elec & Light - Service Exchange Alternators - Preventative	Cont alternator removal	324472
143	09/22/2011	321029	Elec & Light - Service Exchange Alternators - Preventative	Help Bradman	324472
143	09/22/2011	321029	Elec & Light - Service Exchange Alternators - Preventative	Remove alternators	324472

143	09/22/2011	318505	486722	ACC PEDAL SENSOR	Creditor #::SCA001 SCANIA AUSTRALIA PTY LTD P/O #::G98120 Receiving #::99006 Date :2011-09-22	324472
143	09/21/2011	321096		Eng Cool - Began draining coolant. Found transmission oil in	Found tran.oil in cooling system	324472
143	09/20/2011	318505		Brakes - Check ABS fault	Check air pressure switch and all potentiometers	324472
143	09/20/2011	318505		Brakes - Check ABS fault	Check out bus wiring bus slow to move Ordered part C/O	324472
143	09/19/2011	319946		PLASTIC TOP DOOR ROLLER		324472
143	09/19/2011	318505		Brakes - Check ABS fault	Checked all wires from control unit to EDC	324472
143	09/19/2011	318505		Brakes - Check ABS fault	Check out bus wiring bus slow to move	324472
143	09/16/2011	320497		Passenger Doorsrear door rolle rwarn	Replaced roller	324472
143	09/16/2011	320496		Body & Acc Paint wheels	Painted	324472
143	09/16/2011	320498		Body & AccWandalism on middle concertino curtain	repaired vinal side wall	324472
143	09/15/2011	319946		BOD - Paint exterior mirrors and arms	Painted	324472
143	09/15/2011	320156		BOD - Paint wheels	Paint strip caps replace & painted wheels	324472
143	09/15/2011	319946		BOD - Rear step edges - replace/fit inserts	Replaced	324472
143	09/15/2011	319946		BOD - secure ticket machine stand	Checked ok	324472
143	09/15/2011	319946		BOD - Destination blind - secure screws	Checked OK	324472
143	09/15/2011	319946		BOD - Replace rollers top & adjust middle & rear doors	Adjusting	324472
143	09/14/2011	319946		BOD - Rear step edges - replace/fit inserts	Fitted inserts	324472
143	09/14/2011	319946		BOD - Replace destination decal - front header	Replaced	324472
143	09/14/2011	319946		BOD - Replace rollers top & adjust middle & rear doors	Checked OK	324472
143	09/14/2011	319946		BOD - Remove Grendas name address & weight	Removed	324472
143	09/14/2011	319946		BOD - Paint exterior mirrors and arms	Painted	324472
143	09/14/2011	319946		BOD - Hand rails - replace screws rear door	Replaced screws	324472
143	09/14/2011	319946		BOD - Destination blind - secure screws	Secured	324472
143	09/14/2011	319946		BOD - secure ticket machine stand	Secured	324472
143	09/14/2011	319019		SCREW HAND CLAMP(P/N 280010)		324472
143	09/14/2011	319019		NUT HAND RAIL CLAMP (280010)		324472
143	09/14/2011	319019		BOD - Repaint OS trailer No 2 panel & decals	Removed prep & prime only	324472
143	09/14/2011	319019		UNREPORTED Acc Dam - Repair/replace & paint trailer No 4 pa	Prep top & mask prime only	324472
143	09/14/2011	319019		UNREPORTED Acc Dam - Repair/replace & paint trailer No 4 pa	Painted	324472
143	09/14/2011	319019		UNREPORTED Acc Dam - Repair/replace & paint trailer No 4 pa	Assisted	324472
143	09/13/2011	319019		BOD - secure all lower skit panels	Fit 6 panel tek screws instructed by Karl secured	324472
143	09/13/2011	319019		BOD - Polish exterior panels/headers & touch up paint work	Polished & touched up	324472
143	09/13/2011	319019		AMBER REFLECTOR SIDE MOUNT		324472
143	09/13/2011	319019		Accident Damaged # 31504 R/R. o/s. lower body panel No5. Ma	Refit No 5 repaired w/arch	324472
143	09/13/2011	319019		UNREPORTED Acc Dam - Repair/replace & paint trailer No 4 pa	Refit No 4 Prep NS top rail trailer	324472
143	09/13/2011	319019		Replaced side reflectors NS 2 OS 1	Replaced	324472
143	09/12/2011	319019		VAN - Clean graffiti - floor seats & side walls	Replaced	324472
143	09/12/2011	318505		TURBO HOSE 1496295	Creditor #::SCA001 SCANIA AUSTRALIA PTY LTD P/O #::G97528 Receiving #::98616 Date :2011-09-12 143	324472
143	09/12/2011	319019		BOD - Replace wheel chair decal in front	Replaced	324472
143	09/12/2011	319019		HINGE DRIVERS COMPARTMENT		324472
143	09/12/2011	319019		BOD - Replace interior decals - priority seating	Replaced	324472
143	09/12/2011	319019		BOD - Polish exterior panels/headers & touch up paint work	Polishing	324472
143	09/12/2011	319019		BOD - Paint till stand	Painted	324472
143	09/12/2011	319019		BOD - Replace video surveillance decal in front	Replaced	324472
143	09/12/2011	319019		BOD - Replace drivers compartment door hinges	Replaced	324472
143	09/12/2011	319019		BOD - Clean air condition filter secure vents	Cleaned	324472
143	09/12/2011	319019		BOD - Replace wheel chair decal in front	Replaced	324472
143	09/12/2011	319019		UNREPORTED Acc Dam - Repair/replace & paint trailer No 4 pa	Fabricate NS trailer c/o	324472
143	09/12/2011	319019		Accident Damaged # 31504 R/R. o/s. lower body panel No5. Ma	Fabricate OS 5 c/o	324472
143	09/09/2011	319050		Air Cond - Clean a/c filters	Cleaned	324472
143	09/07/2011	318505		Engine - Check turbo	Fixed turbo inlet hose checked air flow sensor potentiometer all OK	324472
143	09/07/2011	318505		Brakes - Check ABS fault	Fix ABS fault with Dulkith	324472
143	09/07/2011	318505		Brakes - Check ABS fault	Assist Dulkith	324472
143	09/07/2011	318505		Brakes - Check ABS fault	Brake valve micro switch power line short when is removed brake signal to EDS relay bus is OK need to check wire line to brake foot valve to EDS	324472
143	09/06/2011	307096		scrap	Creditor #::BEA001 BEAUREPAIRES P/O #::G97433 Receiving #::98355 Date :2011-09-06	324392
143	09/06/2011	318505		Engine - Check turbo	Turbo hose removed turbo checked OK rubber hose cracked tried another hose from 13 unable to fit pipe	324472
143	09/06/2011	318505		Engine - Check turbo	Bus will not take off for 10 secs checked NO fault codes	324472
143	09/06/2011	318505		Engine - Check turbo	Checked fault code by laptop reset system	324472
143	09/05/2011	314255		GASKET WATER VALVE		324196
143	09/05/2011	314255		VALVE 4 WAY MODULATING		324196
143	09/05/2011	314255		COIL WATER VALVE		324196
143	09/05/2011	314255		90LTR BOOST PUMP COACH		324196
143	09/05/2011	314255		FILTER DRIER 5/8		324196
143	09/05/2011	314255		INTERFACE CONTROL CIRCUIT SUIT WATER VALVE		324196
143	08/26/2011	316540		GLOBE INST 24V 2W		322560
143	08/26/2011	316540		HEAD LIGHT GLOBE 24V 70/75W		322560
143	08/25/2011	316540		Elec & Light - Replace OF headlight globe	Replaced	322560
143	08/25/2011	316429		FILTER OIL K124 / L94UAB (H200W02)		322375
143	08/25/2011	316429		FILTER TRANSMISSION ZF 4139-298-038E39HD119		322375
143	08/25/2011	316429		O RING FILTER KIT K93		322375
143	08/25/2011	316429		AIR FILTER SCANIA CLEANED		322375
143	08/25/2011	316429		ENGINE OIL DELO 400LE 15W40		322375
143	08/25/2011	316429		TEXAMATIC 1888		322375
143	08/25/2011	316429			Tension ALL Wheel Nuts to OEM Specs	322375
143	08/25/2011	316429			D Service & Bus Safety Inspection	322375
143	08/25/2011	316429			A Service & Bus Safety Inspection	322375
143	08/25/2011	316429			Tension ALL Wheel Nuts to OEM Specs	322375
143	08/17/2011	314826		HALOGEN GLOBE 24V20W		321146
143	08/17/2011	314826		GLOBE FESTOON 24V-3W		321146
143	08/16/2011	314696		Air Cond - evap fans faulty	Removed and replaced faulty evap fan motor remove and replace boost pump rear unit	321139
143	08/16/2011	314826		Elec & Light - Replace interior down light & exit globes	Replaced	321146
143	08/15/2011	314255			Clean R/A & F/A filters; inspect and report on condition; Replace filter media	321131
143	08/15/2011	314255			FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)	321131
143	08/15/2011	314255			COMPRESSOR DRIVE BELTS: Inspect belt wear; Retension belts;	321131
143	08/15/2011	314255			DRIVE PULLEY'S: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;	321131
143	08/15/2011	314255			DRIVE PULLEY'S: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear	321131
143	08/15/2011	314255			COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose	321131
143	08/15/2011	314255			REFRIGERATION FILTER DRYER: Replace filter dryer; check pump operation;	321131
143	08/15/2011	314255			EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check boltsclamps & fittings; clean condensate drains; clean drip tray	321131
143	08/15/2011	314255			INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condensor fan grills	321131
143	08/15/2011	314255			CONDENSOR AREA: Clean condensor coils; check boltsclamps for tension	321131
143	08/15/2011	314255			UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensor pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation	321131
143	08/15/2011	314255		FRONT UNIT: Replaced boost pump & water valve wired in inter		321131

143	08/15/2011	314255	REAR UNIT: Remove evap fan motors replace bearing motors sti			321131
143	08/10/2011	312956	POS 5-6 275/70 CAP	Creditor #::BEA001 BEAUREPAIRES P/O #:G96249 Receiving #:97288 Date :2011-08-10		320499
143	08/09/2011	313495	PUMP WIPER-WASHER 24 VOLT			320499
143	08/09/2011	313426	Air Cond - Replace a/c belts	Replaced		320499
143	08/09/2011	313426	FAN BELT A/CON ARTIC 21/32X45			320499
143	08/09/2011	313426	CRANK TO PULLEY SCANIA 21/32X67			320499
143	08/09/2011	313426	Engine - 1 engine belt broken			320499
143	08/08/2011	313495	Wipers & Washers - wipers n/w	Checked replaced wiper motor		320499
143	08/07/2011	313314	Breakdown - Railway Pde - OUT 6.15 pm BACK 6.40 pm - All be	Used ute. removed belt from 102 and fixed to 143 bus OK		320400
143	08/05/2011	312956	replace worn tyre pos 5-6	replaced		319898
143	08/04/2011	312947	Whls & Tyres - Change tyres 56	Changed		319898
143	08/04/2011	312947	Whls & Tyres - Change tyres 56	Changed		319898
143	08/04/2011	312947	VAN - cannot remove graffiti at back of bus (Checked on 29/	Cleaned graffiti		319898
143	08/04/2011	312947	VAN - cannot remove graffiti at back of bus (Checked on 29/	Cleaned graffiti		319898
143	08/04/2011	312991	Air Cond - A/C belts need changing	Checked OK		319898
143	08/04/2011	312991	EN - Clean engine and check for oil leaks	Cleaned		319898
143	08/04/2011	312991	Comm Equip - 2way not hearing but everyone can hear 143	Checked OK		319898
143	08/04/2011	312961	BOD - replace front number plate	Ass Brad to change No plate		319898
143	08/04/2011	312961	BOD - replace front number plate	Change over No plate		319898
143	08/04/2011	312847		A Service & Bus Safety Inspection		319796
143	08/04/2011	312847		Tension ALL Wheel Nuts to OEM Specs		319796
143	08/04/2011	312847		A Service & Bus Safety Inspection		319796
143	07/29/2011	311919	PUMP WIPER-WASHER 24 VOLT			318934
143	07/29/2011	311922	GLOBE FESTOON 24V5W			318934
143	07/27/2011	311919	Wipers & Washers - n/w	Changed motor		318934
143	07/27/2011	311922	Elec & Light - Replace emergency exit light globe	replaced		318761
143	07/27/2011	311922	Body & Acc - refit rubber OS rear roof	refit		318761
143	07/22/2011	302948	Replace Grenda decals x 4	Creditor #::ATT001 ATTITUDE SIGNS P/O #:G93129 Receiving #:96490 Date :2011-07-22		317924
143	07/18/2011	310181	Elec & Light - Bus wont start	Jump started		317428
143	07/12/2011	309265	BROOM HEAD (09803211)			316525
143	07/12/2011	309265	BROOM HANDLE (8232715)			316525
143	07/11/2011	309265	Body & Acc - Replace broom	Replaced		316525
143	07/04/2011	307096	POS 7 275/70 CAP	Creditor #::BEA001 BEAUREPAIRES P/O #:G94426 Receiving #:95713 Date :2011-07-04		315260
143	06/30/2011	307548	GLOBE S/CONTACT 24V-10W			314900
143	06/29/2011	307330	Service			314702
143	06/29/2011	307330	MIRROR TOP BRAZILLIAN GLASS			314702
143	06/29/2011	307330	CONVEX MIRROR			314702
143	06/29/2011	307330	MOUNTING CONVEX MIRROR			314702
143	06/29/2011	307330	Service			314702
143	06/29/2011	307544	EN - Hydraulic tank leaking s/clean & check	Checked OK		314900
143	06/29/2011	307544	EN - Hydraulic tank leaking s/clean & check	Checked OK		314900
143	06/29/2011	307544	EN - Rocker cover gasket leaking	Checked OK		314900
143	06/29/2011	307544	EN - Rocker cover gasket leaking	S/cleaned		314900
143	06/29/2011	307548	Replace bus stop globe	Replaced		314900
143	06/29/2011	307386		A Service & Bus Safety Inspection		314702
143	06/29/2011	307386		A Service & Bus Safety Inspection		314702
143	06/29/2011	307386		Tension ALL Wheel Nuts to OEM Specs		314702
143	06/28/2011	307096	replace damaged tyre pos 7	replaced		314702
143	06/27/2011	306802	Replace tyre pos 7	Replaced		314702
143	06/27/2011	306949	CRANK TO PULLEY SCANIA 21/32X67			314608
143	06/27/2011	306802	BR - OSR brake pads 5mm	Changed middle axle and drive axle brake pads and r/tested		314702
143	06/27/2011	306802	BR - Middle axle brakes 5mm	Changed middle axle and drive axle brake pads and r/tested		314702
143	06/27/2011	306802	DISC PADS SCANIA L94+0500 MERC			314702
143	06/27/2011	306802	WEAR SENSOR SCANIA DISC BRAKE			314702
143	06/24/2011	306949	AC - A/C belt missing	Replaced		314608
143	06/24/2011	306589	GLOBE FESTOON 24V5W			314257
143	06/24/2011	306949	Check brake pads	removed tyres pad worn out & rotor need to fit wheel back		314608
143	06/24/2011	306949	Air leak near air dryer	Rectified leak		314608
143	06/22/2011	306589	Replace NS clearance light	Replaced		314179
143	06/08/2011	304296	BRAZILLIAN MIRROR RH			312084
143	06/07/2011	304296	Replace RH mirror	Replaced mirror head		312084
143	05/30/2011	302948	Replace Grenda decals x 4	Replaced		310676
143	05/27/2011	302628	EN - Thermostat temp gauge on dash never moved above 40	check ok		310462
143	05/25/2011	302447	Replace engine belt	Replaced		310292
143	05/24/2011	301962	GLOBE STOP AND TAIL 24V 21/SW			309925
143	05/23/2011	301962	Replace OSR stop/brake light out	Replaced		309925
143	05/23/2011	301952	EL - dash lights out	Checked OK		309925
143	05/23/2011	301952	EL - Front door tube light holder broken	Checked OK		309925
143	05/23/2011	301952	Check brake pads	Removed NSR wheel to check brake pads & re torqued		309925
143	05/23/2011	301952	Check brake pads	Removed NSR wheel to check brake pads & re torqued		309925
143	05/23/2011	301885		A Service & Bus Safety Inspection		309803
143	05/23/2011	301885		Tension ALL Wheel Nuts to OEM Specs		309803
143	05/23/2011	301885		A Service & Bus Safety Inspection		309803
143	05/10/2011	300046	Bus wont start at KSB	Took van 619 . Switch in rear engine switch over		307783
143	05/04/2011	297872	ROAD SAFETY INSPECTIONS	Creditor #::ROA001 Road Safety Inspections P/O #:G91529 Receiving #:92838 Date :2011-05-04		307116
143	05/01/2011	297872	Annual License -	RWC 583118		305590
143	04/28/2011	298117	POS 8-9 275/70 1CAP 1NEW	Creditor #::BEA001 BEAUREPAIRES P/O #:G91486 Receiving #:92559 Date :2011-04-28		306085
143	04/28/2011	298412	GLOBE STOP AND TAIL 24V 21/SW			305991
143	04/28/2011	298412	WIPER REFILL SUIT TX600+TX700			305991
143	04/21/2011	298413	Wiper blades U/S	Replaced		305991
143	04/21/2011	298413	Wiper blades U/S	Replaced		305991
143	04/21/2011	298117	replace worn tyre pos 8-9	replace worn tyre pos 8-9		305752
143	04/21/2011	298155	GLOBE DASH B7L			305752
143	04/21/2011	298412	Stop light U/S	Repaired		305991
143	04/21/2011	298412	Stop light U/S	Repaired		305991
143	04/20/2011	297961	DISC PADS SCANIA L94+0500 MERC			305752
143	04/19/2011	297960	WHL - RH mid inner tyre worn	replace both tyres		305752
143	04/19/2011	297960	WHL - RH & LH inner rear tyres worn	Replace both tyrea		305752
143	04/19/2011	298155	dash light U/S	Complited		305752
143	04/19/2011	297960	BR - NSR & OSR brake pads 5mm	Checked OK		305752
143	04/19/2011	297960	Br - NSF & OSF brake pads 5mm	Replace front brake pads		305752
143	04/19/2011	297961	Br - NSF & OSF brake pads 5mm	Replace front pads		305752
143	04/18/2011	297731	EL - Interior light LH side broken	FETAUI - Replaced fluro		305499

143	04/18/2011	297731	EL - Interior light LH side broken	Replaced fluoro	305499
143	04/18/2011	297731	FLOURO TUBE END LA140 VOLGREN		305499
143	04/18/2011	297731	FLOURO TUBE CLIP LA037/ VOLGREN		305499
143	04/18/2011	297731	INTERIOR LIGHT DEFUSER		305499
143	04/15/2011	297504	Add coolant	Added	305499
143	04/14/2011	297352		Replace fuel filters	305342
143	04/14/2011	297352		Replace final drive oil	305342
143	04/14/2011	297352	Made new w/o	Adjust valve clearances	305342
143	04/14/2011	297352		Replace power steering filter	305342
143	04/14/2011	297352		Rekit quick release valve	305342
143	04/14/2011	297352		Replace hydraulic fan filter and top up oil	305342
143	04/14/2011	297352		Replace air dryer canister	305342
143	04/14/2011	297352	FUEL FILTER ELEMENT SCANIA L94UAB (R90T / H7090WK10)		305342
143	04/14/2011	297352	FILTER FUEL K124 / LU94A (1411894 / H17WK05)		305342
143	04/14/2011	297352	made new w/o	Remove intercooler wash intercooler and raditor	305342
143	04/14/2011	297352	POWER STEERING FILTER VOLVO		305342
143	04/14/2011	297352	HYDRAULIC FILTER L94UAB		305342
143	04/14/2011	297352	FILTER AIR DRYER KIT(HALDEX)		305342
143	04/14/2011	297352	RPM BORATE EP LUBE 220		305342
143	04/14/2011	297352		Replace coolant filter in engine cooling system	305342
143	04/14/2011	297352		Clean a/c filters	305342
143	04/14/2011	297352		Inspect bus as per inspection sheet	305342
143	04/14/2011	297352		Inspect vehicle as per RSI Checklist	305342
143	04/07/2011	296506	ANN - Annual Body Inspection	Inspection	304486
143	04/06/2011	295337	POS 10 275/70 CAP	Creditor #::BEA001 BEAUREPAIRES P/O #:K90386 Receiving #::91656 Date :2011-04-06	304267
143	03/31/2011	295657	Remove graffiti	Removed	303577
143	03/31/2011	295656	Top up hydraulic oil	Topped up	303577
143	03/31/2011	295657	Replace NSR brake globe	Replaced	303577
143	03/31/2011	295657	Repair fuel leak	Repaired	303577
143	03/31/2011	295657	check brake pads	Removed middle tyres & check brake pdas	303577
143	03/31/2011	295105		D Service & Bus Safety Inspection	302962
143	03/31/2011	295105		Tension ALL Wheel Nuts to OEM Specs	302962
143	03/31/2011	295105		A Service & Bus Safety Inspection	302962
143	03/31/2011	295105		Tension ALL Wheel Nuts to OEM Specs	302962
143	03/30/2011	295337	replace worn tyre pos 10	replace worn tyre pos 10	303212
143	03/29/2011	295562	Replace tyre 10	Replaced	303212
143	03/28/2011	295105	FILTER TRANSMISSION ZF 4139-298-038E39HD119		302962
143	03/28/2011	295105	O RING FILTER KIT K93		302962
143	03/28/2011	295105	FILTER AIR SCANIA USE AF25066		302962
143	03/28/2011	295105	FILTER OIL K124 / L94UAB (H200W01)		302962
143	03/28/2011	295105	TEXAMATIC 1888		302962
143	03/28/2011	295105	ENGINE OIL DELO 400LE 15W40		302962
143	03/24/2011	294583	GLOBE S/CONTACT 24V-10W		302962
143	03/22/2011	294583	Replace OS front indicator globe		302962
143	03/16/2011	292355	Service	Replaced	300119
143	03/15/2011	292114	POS 7 275-70 CAP	Rebuild starter motor	301188
143	03/09/2011	291503	POS 1 275-70R NEW	Creditor #::BEA001 BEAUREPAIRES P/O #:K89241 Receiving #::90638 Date :2011-03-15	300557
143	03/09/2011	292809	GLOBE FESTOON 24V-3W	Creditor #::BEA001 BEAUREPAIRES P/O #:K89044 Receiving #::90427 Date :2011-03-09	300557
143	03/08/2011	292809	Replace emer exit light globe	Replaced	300557
143	03/07/2011	292355	BUSH KIT SUIT JF		300119
143	03/07/2011	292355	Service		300119
143	03/07/2011	292355	JF24V 4KW BRUSH SET	Started rebuild	300119
143	03/07/2011	292355	STARTER SOLENOID SUIT JF		300119
143	03/07/2011	292355	STARTER DRIVE SUIT JF		300119
143	03/04/2011	292114	REPAIR FLAT TYRE POS 7 CAP	Replaced	299924
143	03/03/2011	292324	Replace tyre 7	Replaced	299924
143	02/28/2011	291503	Replace tyre pos 1 - worn	Replaced	299067
143	02/25/2011	291422	BR - Brakes pull right when stopping	Checked brakes OK replaced f/left tyre	299067
143	02/24/2011	290803	EMERGENCY EXIT BUTTON PULL COVER		298658
143	02/24/2011	290803	BUSHING HORN BUTTON SCANIA(kit of 4)		298658
143	02/23/2011	290803	STARTER MOTOR SCANIA K93+L94		298658
143	02/23/2011	290803	EL - Starter motor not engaging at times	Replaced starter motor.	298658
143	02/23/2011	290803	EL - Horn pad adrift		298658
143	02/23/2011	290916		A Service & Bus Safety Inspection	298658
143	02/23/2011	290916	Service	A Service & Bus Safety Inspection	298658
143	02/23/2011	290916		Tension ALL Wheel Nuts to OEM Specs	298658
143	02/22/2011	290949	OS mirror lower part cracked	Replaced mirror	298658
143	02/18/2011	290522	Replace interior light globe	Replaced	298232
143	02/15/2011	289948	Add coolant	Added	297567
143	02/12/2011	289543	Front aircon n/w at all (needs a triple C computer)	Replace ccc with new run up and reprogram tested ok	297144
143	02/11/2011	289628	Clean graffiti	Cleaned	297144
143	02/08/2011	288947	Clean graffiti	Cleaned	296578
143	02/02/2011	288113	Clean graffiti	Cleaned	295877
143	01/31/2011	287660	BR - Brohms brake alarm going off when handbrake is kept on	ref to w/order # 287482	295403
143	01/27/2011	285907	POS 3 275/70 CAP	Creditor #::BEA001 BEAUREPAIRES P/O #:K87334 Receiving #::88808 Date :2011-01-27	295080
143	01/27/2011	286460	0478225 air dryer valve	Creditor #::SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G87531 Receiving #::88758 Date :2011-01-27	295080
143	01/27/2011	287482	After handbrake applied takes 20-30 secs to build up air ag	ref to w/order # 286460	295249
143	01/21/2011	286460	AIR - regeneration valve leaking on air dryer	found fault and ordered parts and fitted	294941
143	01/20/2011	286316	Check air system for air loss.	Strip valve next to air dryer found diaphram split. refit valve for trip back to grendas	294941
143	01/19/2011	286213	Air pressure dropping South & Bluff Rd's.	Take MT 506 out to South rd & c/o bus & bring bus back for checking.	294815
143	01/19/2011	286213	Check loss of air pressure.	Put bus on pit & check for air leak boosters & airbags ok. Found valve around air dryer continuously exhausting.	294815
143	01/18/2011	286160	Bus wont start	Jump started	294815
143	01/18/2011	286165	Refit rubber strip above windows LHS	Refitted	294815
143	01/17/2011	286016	Replace tyre pos 3	Replaced	294614
143	01/17/2011	285907	replace worn tyre pos 3	replace worn tyre pos 3	294614
143	01/10/2011	285041	Bus wont move	Drained air tanks compressor a bit slow building up	294091
143	01/07/2011	284889	Bus wont start	Jump started	294091
143	01/06/2011	284737	Rear door guide sleeve came off	Top mounting lock nut missing fitted back lock nut checked OK	293903
143	12/31/2010	281443	AC - AC drive belt stsrting to breakup	Replaced belt and 2 belt tension pulley replaced jockey pulley bearing	293098
143	12/31/2010	281443	SCANIA ALT BELT TENSIONER K1241B		293098
143	12/31/2010	281443	EL - Master switch n/w	Checked OK	293098
143	12/31/2010	281443	COOL - coolant leak at header tank	Replaced hose clamp top up coolant r/tested	293098
143	12/29/2010	281443	CRANK TO PULLEY SCANIA 21/32X67		291753

143	12/29/2010	281443	FAN BELT A/CON ARTIC 21/32X45		291753
143	12/29/2010	281443	BELT ALT W/PUMP CRANK SCANIA ARTIC		291753
143	12/29/2010	281443	BELT CRANK-TWIN A/C COMP SCANIA ARTIC		291753
143	12/23/2010	281443	AC - Air compressor drive belt splitting	same as	293098
143	12/20/2010	282848	Clean graffiti	Cleaned	292531
143	12/18/2010	282690	Engine cover lift handle broken	Checked OK	292335
143	12/16/2010	281443	EL - Battery switch on dash panel faulty	Replaced main solenoid	291753
143	12/15/2010	281443	GLOBE STOP AND TAIL 24V 21/5W		291753
143	12/15/2010	281443	1519485 relay master switch	Creditor #:BAN001 BANLAY PTY LTD P/O #:G86156 Receiving #:87299 Date :2010-12-15	291753
143	12/14/2010	281443	T/T Screen on turntable u/s	Recharged turntable oil pressure and lube sliding bars r/tested OK	291753
143	12/14/2010	281443	AC - Ac belt split	same as	291753
143	12/14/2010	281443	Doors not operating correctly	Adjusted checked OK	291753
143	12/14/2010	281443	EL - Battery switch on dash panel faulty	Checked master switch and ordered new	291753
143	12/14/2010	281443	EL - check wiring on Art. control unit pin 33 and pres swit	Put more oil in t/table to 7 bar put floor down OK	291753
143	12/14/2010	281443	Replace stop light globe	Replaced	291753
143	12/14/2010	281443	BOD - Screen on turntable u/s	same as	291753
143	12/13/2010	280457	POS 7-8 CAP	Creditor #::BEA001 BEAUREPAIRES P/O #::K85672 Receiving #:87149 Date :2010-12-13	291590
143	12/13/2010	281443	EL - check wiring on Art. control unit pin 33 and pres swit	Pull up floor	291590
143	12/10/2010	281079	GLOBE STOP AND TAIL 24V 21/5W		291590
143	12/10/2010	281079	SINGLE CONTACT GLOBE 24V 5W		291590
143	12/10/2010	281671	Check fault codes	Checked with laptop	291590
143	12/10/2010	281079	D HANDLE LENLOCK CHROME PLATED		291590
143	12/10/2010	281533	A/C compressor too close	Checked OK	291590
143	12/09/2010	281079	WHL - Tyres 78 - 3 & 4mm	Has been replaced	291590
143	12/09/2010	281079	SUS - No 2 airbag loses air all the time alarm sounds & hav	Clean up air suspension levelling valve sensors	291590
143	12/09/2010	281079	SCANIA UNLOADER VALVE HALDEX		291590
143	12/09/2010	281228	Random Vehicle Audit		291590
143	12/09/2010	281079	EL - RH bottom rear park light	Checked OK	291590
143	12/09/2010	281079	EL - Roof lights n/w	Replaced globe	291590
143	12/09/2010	281079	EL - Roof lights n/w	Checked OK	291590
143	12/09/2010	281079	EL - RH bottom rear park light	Checked OK	291590
143	12/09/2010	281148	GLOBE STOP AND TAIL 24V 21/5W		291671
143	12/09/2010	281079	BOD - Screws missing from dash panel	Fitted	291590
143	12/09/2010	281079	BOD - Needs screws or bolts in main dash console	Fitted	291590
143	12/09/2010	281079	BOD - Screws missing from dash panel	Checked OK	291590
143	12/09/2010	280954	D HANDLE LENLOCK CHROME PLATED		291590
143	12/09/2010	281079	AIR - Air dryer needs overhauling	Overhauled	291590
143	12/09/2010	281225		A Service & Bus Safety Inspection	291590
143	12/09/2010	281225		Tension ALL Wheel Nuts to OEM Specs	291590
143	12/09/2010	281225		A Service & Bus Safety Inspection	291590
143	12/08/2010	278940	POS 5 275/70 CAP	Creditor #::BEA001 BEAUREPAIRES P/O #:G85089 Receiving #:86961 Date :2010-12-08	291671
143	12/08/2010	281149	Clean a/c filter	Cleaned	291671
143	12/08/2010	281137	EN - Dip stick u/s need to change	Checked dipstick has been replaced	291671
143	12/08/2010	281148	Replace parker light globe	Replaced	291671
143	12/08/2010	281079	Check jack knife code	checked 18-12	291671
143	12/08/2010	281079	COMM - 2way radio n/w	Replaced new mic to 2way	291671
143	12/08/2010	281079	Repairs to height adjuster on seat	Replaced dial indicator	291671
143	12/08/2010	281079	Drivers seat weight adjusted	same as	291671
143	12/07/2010	280717	GLOBE STOP AND TAIL 24V 21/5W		290774
143	12/06/2010	280954	BOD - Seat cannot be adjusted - winder broken	Checked all seat operations tested OK	291465
143	12/06/2010	280954	Handbrake bus losing air when you put handbrake on	Checked for air leak found valve next to air dryer filter leaking needs to be overhauled	291465
143	12/02/2010	280442	R/L both tyres need changing	Changed & tensioned w/nuts	290774
143	12/02/2010	280457	replace tyre pos 78 - worn	Replaced	290774
143	12/02/2010	280717	Replace NS park/brake globe	Replaced	290774
143	12/02/2010	280442	Engine cover handle broken	Fitted	290774
143	12/01/2010	279594	1515996 DIP STICK ENG	Creditor #::SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G85165 Receiving #:86665 Date :2010-12-01	290676
143	11/29/2010	280171	Add coolant	Added	290274
143	11/25/2010	279397	Air coming out of handbrake dropping pressure	Checked OK but is taking time to build up	289883
143	11/24/2010	279319	AC compressor pulley rubbing together	Checked found bolt missing fitted and put back belts	289684
143	11/24/2010	279319	AC compressor pulley rubbing together	Assisted Sabu	289684
143	11/24/2010	279594	EN - needs a new engine oil dipstick	Replaced	290085
143	11/23/2010	278940	replace damaged tyre pos 5	replace damaged tyre pos 5	289285
143	11/23/2010	279212	AIR S - air leak from park brake	check air leak from park brake and steam clean front brake.	289684
143	11/22/2010	279009	WHL - LHR tyres not bald but low on tread	Replaced No 9 tyre	289520
143	11/22/2010	279009	WHL - LHR tyres not bald but low on tread	Replaced No 9 tyre	289520
143	11/20/2010	278883	Air pressure is lost when use hand brake	Checked & tested OK no air leak	289285
143	11/18/2010	278538	Fluro light holder broken	Removed fitted new & fitted tube	288858
143	11/17/2010	278458	Clean graffiti	Cleaned	288858
143	11/16/2010	278289	Clean graffiti	Cleaned	288654
143	11/12/2010	277975	Clean graffiti	Cleaned	287862
143	11/09/2010	277438	Air leak near air dryer	Rectified defect # 84928	287287
143	10/16/2010	274384	Bus needs a bin	Checked bin there	284106
143	10/14/2010	273907	GLOBE FESTOON 24V-3W		283688
143	10/14/2010	273907	EL - Emergency exit light u/s	Replaced globe	283688
143	10/13/2010	272087	Turntable light on / losing en	Creditor #::BAN001 BANLAY PTY LTD P/O #:G82839 Receiving #:84577 Date :2010-10-13	283471
143	10/09/2010	273353	Clean graffiti	Cleaned	282937
143	10/08/2010	273093	Back rear No plate light assy broken	Straightened holder fitted new lens working OK	285860
143	10/08/2010	273093	LENS TO SUIT 2557 LAMP		285860
143	10/07/2010	271767	POS 3-5-6 275/70 1 NEW 2 CAP	Creditor #::BEA001 BEAUREPAIRES P/O #:G82744 Receiving #:84389 Date :2010-10-07	285691
143	10/07/2010	272965	INDICATOR LIGHT FRONT ARTIC		282522
143	10/05/2010	272965	Replace NSF indicator	Replaced	282522
143	09/30/2010	272087	Turntable light on loosing engine power	Repaired by Banlay	281976
143	09/30/2010	272180	Replace front NS clearance light & emergency exit light glo	Replaced	281976
143	09/30/2010	272087	Jackknife light come on	Take bus to Banlay Jackknife light on code 18	281976
143	09/30/2010	272111	Replace interior light globe	Replaced	281976
143	09/28/2010	271767	replace worn tyre pos 3-5-6	replace worn tyre pos 3-5-6	281976
143	09/28/2010	271546	WHEEL NUT SQUIRREL		281976
143	09/28/2010	271692	WHEEL NUT SQUIRREL		281976
143	09/27/2010	271546	WHL - Drive axle in tyre both worn	Replaced	281976
143	09/27/2010	271546	OSR & NSR tyres bald	Replaced	281976
143	09/27/2010	271546	Replace squirrels	Replaced	281976
143	09/27/2010	271546	Replace wheel arch brush	Replaced	281976
143	09/27/2010	271546	Brake warning light coming on	Checked and found mid axle OS brake pad wear sensor wire broken replaced wire	281976

143	09/27/2010	271546	WEAR SENSOR SCANIA DISC BRAKE		281976
143	09/25/2010	271692	Replace squirrels	Replaced	281976
143	09/25/2010	271600	Clean graffiti	Cleaned	281976
143	09/25/2010	271546	Check brake pads	Removed tyres 56 & checked brake pads	281976
143	09/25/2010	271429		Tension ALL Wheel Nuts to OEM Specs	281744
143	09/25/2010	271429		D Service & Bus Safety Inspection	281744
143	09/25/2010	271429	TEXAMATIC 1888		281744
143	09/25/2010	271429	ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL		281744
143	09/25/2010	271429	FILTER AIR SCANIA USE AF25066		281744
143	09/25/2010	271429	O RING FILTER KIT K93		281744
143	09/25/2010	271429	FILTER TRANSMISSION ZF 4139-298-038E39HD119		281744
143	09/25/2010	271429	FILTER OIL K124 / L94UAB (H200W01)		281744
143	09/25/2010	271429		A Service & Bus Safety Inspection	281744
143	09/25/2010	271429		Tension ALL Wheel Nuts to OEM Specs	281744
143	09/25/2010	271429		A Service & Bus Safety Inspection	281744
143	09/24/2010	271407	Flat batterys Brighton Town Hall.	Go to Brighton Town Hall & jump start bus & return.	281744
143	09/24/2010	271380	BOD - Handle on engine hatch u/s	Fitted new handle	281744
143	09/24/2010	271380	D HANDLE LENLOCK CHROME PLATED		281744
143	09/22/2010	271048	LHS clearance light u/s	Went to Dandenong picked up parts came back and replaced side assembly	281319
143	09/18/2010	270705	Clean a/c filters	Cleaned	280880
143	09/18/2010	270705	Replace fluoro light	Replaced	280880
143	09/16/2010	270364	EL - RH fluoro light u/s	Both holders damaged removed fitted new holder clamped drilled & refitted	280225
143	09/10/2010	269645	Bus wont start	Jump started	279634
143	08/30/2010	267893	GLOBE FESTOON 24V5W		277494
143	08/28/2010	267893	RH clearance light u/s	Replaced	277494
143	08/28/2010	267893	Fluro tubes u/s	Fluro light holder broken fitted new drilled & fitted new clamp cut new shade to size	277494
143	08/26/2010	267580	VAN - Clean graffiti	Cleaned	277092
143	08/25/2010	266464	POS 4 275/70 CAP FLAT	Creditor #:BEA001 BEAUREPAIRES P/O #:G81083 Receiving #:82548 Date :2010-08-25	276886
143	08/19/2010	266464	fix flat tyre pos 4	fix flat tyre pos 4	275943
143	08/18/2010	263986	33MM LOOSE WHEEL NUT INDICATOR		275464
143	08/18/2010	263986	BROOM HEAD (09803211)		275464
143	08/18/2010	266344	LONG VEHICLE DECAL		275464
143	08/18/2010	266344	REAR MARKER DECAL		275464
143	08/18/2010	266344	DO NOT OVERTAKE TURNING DECAL		275464
143	08/18/2010	263986	BROOM HANDLE (8232715)		275464
143	08/18/2010	263986	BR - Handbrake releases by itself	replaced calipers	275464
143	08/18/2010	263986	BRK - LH 2nd axle disc worn	Changed ns mid axle brake caliper ABS sensor fixed hub assy torqued hub nut change brake pads changed NS 4 tyre r/tested cleaned work area & inside bus	275464
143	08/18/2010	263986	BRK - LH 2nd axle disc worn	Change caliper sensor change tyre & r/tested	275464
143	08/17/2010	266344	BODY - Replace marker plates decals	Replaced marker plates long vehicle do not overtake decals.	275464
143	08/17/2010	263986	DISC PADS SCANIA L94+0500 MERC		275464
143	08/17/2010	263986	WEAR SENSOR SCANIA DISC BRAKE		275464
143	08/17/2010	263986	HUB SEAL MIDDLE AXLE SCANIA L94UAB		275464
143	08/17/2010	263986	1892050 ROAD SPEED SENSOR	Creditor #:SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G80939 Receiving #:82251 Date :2010-08-17	275464
143	08/17/2010	263986	BRK - LH 2nd axle disc worn	Fixed OS mid axle hub assy new disc caliper brake pad and change NS hub bearing change disc & clean NS axle	275464
143	08/16/2010	263497	AIR CONDITIONER ELEC.MOTORS DO	Creditor #:AIR002 AIR INTERNATIONAL TRANSIT P/O #:G80104 Receiving #:82153 Date :2010-08-16	275464
143	08/16/2010	263986	CONSUMABLE DELIVERY CHARGE	Creditor #:CON001 CONSOLIDATED BEARING CO. P/O #:G80814 Receiving #:82127 Date :2010-08-16	275464
143	08/16/2010	263986	MID AXLE BRG OUTER 822049+8220	Creditor #:CON001 CONSOLIDATED BEARING CO. P/O #:G80814 Receiving #:82127 Date :2010-08-16	275464
143	08/16/2010	263986	MID AXLE BRG INNER 32021X	Creditor #:CON001 CONSOLIDATED BEARING CO. P/O #:G80814 Receiving #:82127 Date :2010-08-16	275464
143	08/13/2010	263986	K002962 LHS CALIPER MID AXLE	Creditor #:TRA004 TRADE BRAKE+CLUTCH CO. P/O #:G80795 Receiving #:82067 Date :2010-08-13	275464
143	08/12/2010	263986	BRK - LH 2nd axle disc worn	Removed NS mid axle hub bearing for sample	275464
143	08/12/2010	263986	SCANIA CALIPER PISTON BOOT KIT		275464
143	08/11/2010	263986	BRK - LH 2nd axle disc worn	Removed both side calipers and hub assy NS hub bearing damaged ordered parts	275464
143	08/09/2010	265162	Add coolant	Added	275464
143	08/09/2010	263497	AIR CON REFRIDGERANT		275464
143	08/05/2010	263986	BRK - LH 2nd axle disc worn	Remove caliper bolts	275464
143	08/04/2010	263986	BALL JOINT LOAD SENSOR 4HP500		275464
143	08/03/2010	264306	TT - When you make a turn there is a high pitch squeal from	Ref to w/order # 263589	275464
143	08/02/2010	263983	EL - TV screen for rear door n/w	checked ok	275464
143	07/30/2010	263916	DIP STICK MERCEDES 0500LE		275464
143	07/30/2010	263497	EL - Interior light out	Replaced	275464
143	07/29/2010	263916	EN - Needs a new dipstick	Replaced	275464
143	07/29/2010	263589	Jackknife & TC & ABS MIL coming on - DTC's : 12 & 46	Scania	275464
143	07/28/2010	263497	A/C - Rear a/c showing fault alarm	Traced fault back to failed schrader valve. replaced valve pressure & vac test system charge and run up unit all OK	275464
143	07/28/2010	263497	AC - Rear unit right evap fan n/s and compressor is out of	Parts have been ordered	275464
143	07/28/2010	263497	HTR - heater is n/w		275464
143	07/28/2010	263300	BRK - 2nd axle LS booster leak	Fault code 4/6 left 3rd axle sensor open/ short circuit tried to find intermittent problem with sensor removed rear wheel and checked for resistance & voltage in the sensor r/tested	275464
143	07/27/2010	263300	BRK - 2nd axle LS booster leak	Replaced booster. ABS & Jack knife light on (12 on the flash codes)	275464
143	07/26/2010	263299	BD - brakes locking on @ Mentone Stn. 11:45am - actioned to	actioned to MT	275464
143	07/26/2010	263263	Brakes Overheating At Mentone Station	Check bus at menton station leaking air from n/s rear brake booster .wind up p/brake & bring bus back to depot.put on hoist & disconnet air line & blocked air line .put it back .checked for leaks ok send bus back to dandenog depot ok	275464
143	07/26/2010	263300	BRK - 2nd axle LS booster leak	Removed brake booster - no parts so replaced old booster	275464
143	07/23/2010	262697	STARTER DRIVE SUIT JF		275034
143	07/23/2010	262697	BUSH KIT SUIT JF		275034
143	07/23/2010	262697	Service	Completed.	275034
143	07/23/2010	262697	STARTER SOLENOID SUIT JF		275034
143	07/23/2010	262975	WEAR SENSOR SCANIA DISC BRAKE		275034
143	07/22/2010	262975	BR - Brake pad wear indicator on	Checked for brake pad wheel light on removed middle axle and rear NS wheel to check found low pad indicator fitted wrong replaced with new	275034
143	07/21/2010	262697	Service	Assist Matt with repairs	275034
143	07/21/2010	262697	Service	Pulled down s/motor & cleaned up	275034
143	07/21/2010	262489	FLOURO TUBE CLIP LA037/ VOLGREN		275034
143	07/21/2010	262489	FLOURO TUBE END LA140 VOLGREN		275034
143	07/20/2010	262684	Bus wont start	Jump started	274865
143	07/19/2010	262425	Bus wont start	Jump started at KSB	274632
143	07/19/2010	262489	EL - Step down light n/w	Replaced globe	274865
143	07/06/2010	260562	GLOBE INST 24V 2W		272371
143	07/02/2010	260562	Replace No plate globe	Replaced	272264
143	06/29/2010	257880	ABS AND JACKKNIFE LIGHT STAY ON	Creditor #:SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G78410 Receiving #:80327 Date :2010-06-29	271561
143	06/29/2010	259345	HEAD LIGHT GLOBE 24V 70/75W		271561
143	06/26/2010	259755	EL - Indicators dont cancel out no beep	Checked OK	271200
143	06/23/2010	259442	EL - Red alarm came on for NO reason shut everything down	Ref to w/order # 257880	270492
143	06/23/2010	259441	BR - Brakes grab & pull bus to right when applied	Ref to w/order # 257880	270492
143	06/22/2010	259345	EL - Front left low beam out	Replaced globe	270270
143	06/16/2010	258316	BATTERY 800CCA		269180
143	06/15/2010	256337	ROAD SAFETY INSPECTIONS	Creditor #:ROA001 Road Safety Inspections P/O #:G77872 Receiving #:79854 Date :2010-06-15	269196

143	06/13/2010	258316	Bus wont start	Jump started r/tested & load tested batteries replaced	269180
143	06/13/2010	258316	Bus wont start	Jump started r/tested & load tested batteries replaced	269180
143	06/12/2010	258287	Breakdown - Springvale Station - OUT 11.15 am BACK 12.15 pm	Used van 619. Jump started	268979
143	06/11/2010	257880	EL - ABS and Jackknife MIL staying on - engine de-rating	Take bus to Scania	268777
143	06/11/2010	257880	EL - ABS and Jackknife MIL staying on - engine de-rating	Repaired by Scania	268777
143	06/10/2010	257880	EL - ABS and Jackknife MIL staying on - engine de-rating	Check for jack knife symbol coming on dash reset and r/test symbol still came on bus u/s	268777
143	06/09/2010	257854	VAN - Graffiti on floor	Scrubbed graffiti off	268777
143	06/09/2010	257856	Back rear door takes a long time to close & stiff	Lubed door	268777
143	06/08/2010	257543	Bus will not rev or move at chesterville rd	Found jackknife warning light on dash. shut down bus and restart ok. return to depot	268503
143	06/08/2010	256889	REAR V BAR+ REACTION ROD BUSH 85MM SCANIA L113+L94UAB		268472
143	06/08/2010	257589	BD - park brake not releasing @ Southland Shopping Centre -	done at MT	268503
143	06/07/2010	256889	SUS - Rear V bar bush damaged	R/tested checked V bar bolt	268472
143	06/07/2010	256889	SUS - Rear V bar bush damaged	R/tested checked V bar bolt	268472
143	06/07/2010	256889	ELE - alternator belt 2 idler pulley bearing and alternator	Replaced alt adjuster pully	268472
143	06/07/2010	256889	SCANIA ARTIC ALT PULLEY GROVED PLASTIC		268472
143	06/07/2010	256889	1530701 MID AXLE SPEED SENSOR	Creditor #:SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G78131 Receiving #:79609 Date :2010-06-07	268472
143	06/07/2010	256889	ELE - alternator belt 2 idler pulley bearing and alternator	Replaced alt adjuster pully	268472
143	06/07/2010	256889	AIR S - n/s mid axle 2 air bags leaking	Replaced abs sensor	268472
143	06/04/2010	256116		Adjust valve clearances	268189
143	06/04/2010	256116		Adjust valve clearances	268189
143	06/04/2010	256889	Replace a/c compressor bolts	Replaced	268472
143	06/03/2010	256116		Adjust valve clearances	268189
143	06/03/2010	256889	SUS - Rear V bar bush damaged	Changed Vbar 2 bushes fixed bar 2 bus	268472
143	06/03/2010	256889	SUS - Rear V bar bush damaged	Changed Vbar 2 bushes fixed bar 2 bus	268472
143	06/03/2010	256889	L94UAB SCANIA HUB LOCK WASHER		268472
143	06/02/2010	256848	VAN - need to clean graffiti	Cleaned graffiti	268472
143	06/02/2010	256889	SUS - rear v bar bushes damaged	Assisted Dulkith to remove V bar bush	268472
143	06/02/2010	256889	SUS - Rear V bar bush damaged	Removed V bar bush	268472
143	06/02/2010	256781	Bus wont start	Jump started	268472
143	06/02/2010	256889	AIR S - n/s mid axle 2 air bags leaking	Assisted with wheel bearing	268472
143	06/02/2010	256889	AIR S - n/s mid axle 2 air bags leaking	Adjusted mid axel wheel bearing and wheel speed sensor. OS speed sensor damaged	268472
143	06/01/2010	255931	ELE - change indicator lens	replaced	267812
143	06/01/2010	256710	Breakdown - Chadstone Shops - OUT 6.45 am BACK 8.00 am - Bu	C/O bus 585. ABS & Jack knife lights on cancelled & returned	268434
143	05/31/2010	256364	GLOBE FESTOON 24V-3W		268189
143	05/31/2010	256364	GLOBE S/CONTACT 24V-10W		268189
143	05/30/2010	256337	Annual Inspection - BC 126034	BC 126034 - Passed	268189
143	05/28/2010	256116		Inspect bus as per inspection sheet	268189
143	05/28/2010	256116		Clean a/c filters	268189
143	05/28/2010	256116		Replace air dryer canister	268189
143	05/28/2010	256116		Remove intercooler wash intercooler and raditor	268189
143	05/28/2010	256116		Clean a/c filters	268189
143	05/28/2010	256116		Replace coolant filter in engine cooling system	268189
143	05/28/2010	256116		Replace air dryer canister	268189
143	05/28/2010	256116		Replace hydraulic fan filter and top up oil	268189
143	05/28/2010	256116		Rekit quick release valve	268189
143	05/28/2010	256116		Replace power steering filter	268189
143	05/28/2010	256116		Replace final drive oil	268189
143	05/28/2010	256116		Replace fuel filters	268189
143	05/28/2010	256116		Inspect bus as per inspection sheet	268189
143	05/28/2010	256116	FILTER FUEL K124 / LU94A (1411894 / H17WK05)		268189
143	05/28/2010	256116	FUEL FILTER ELEMENT SCANIA L94UAB (R90T / H7090WK10)		268189
143	05/28/2010	256116	POWER STEER FILTER B10M		268189
143	05/28/2010	256116	FILTER OIL GEARBOX DIFF K124		268189
143	05/28/2010	256116	RPM BORATE EP LUBE 220		268189
143	05/28/2010	256116	FILTER AIR DRYER KIT(HALDEX)		268189
143	05/28/2010	256116	HYDRAULIC FILTER L94UAB		268189
143	05/28/2010	256116	REAR AIR BAG (MID AXLE) SCANIA L94UAB		268189
143	05/28/2010	256366	Replace NS mid axle front & rear airbags	Replaced	268189
143	05/28/2010	256364		Road tested	268189
143	05/28/2010	256364	Steamclean bus	Cleaned	268189
143	05/28/2010	256364	Steamclean bus	Cleaned	268189
143	05/28/2010	256364	Steamclean bus	Cleaned	268189
143	05/28/2010	256364	ELE - bus inside 4 emergency lights n/w	Replaced globes	268189
143	05/28/2010	256368	Bus stops revving has no pressure	Checked OK	268189
143	05/28/2010	256364	Middle Bus Stopping sign plastic cover is cracked	Put some super glue	268189
143	05/28/2010	256364	ELE - front and rear bus stop globe n/w	Replaced 2 globes	268189
143	05/27/2010	255933	LED CLEARANCE LIGHT (RED AMBER)		267812
143	05/27/2010	255933	GLOBE INDICATOR 24V-18W SINGLE CONTACT		267812
143	05/26/2010	255933	ELE - change indicator lens	changed	267812
143	05/26/2010	255933	ELE - change indicator globe	changed	267812
143	05/26/2010	255933	ELE - jump start bus	jump started	267812
143	05/26/2010	255933	ELE - change indicator lens	changed	267812
143	05/26/2010	255813	EL - Load test batteries & check charge rate	tested ok	267812
143	05/26/2010	255986	AIR S - air leakage	checked ok	267812
143	05/25/2010	255689	ELEC - jumpstart bus	jump started bus	267585
143	05/25/2010	255689	ELEC - jumpstart bus	jump started bus	267585
143	04/07/2010	249285	POS 1-2 275R	Creditor #:BEA001 BEAUREPAIRES P/O #:G76122 Receiving #:77738 Date :2010-04-07	267493
143	04/07/2010	249786	Accident Damaged # 21239 R/R. o/s. lower panel reflectoro/	Repaired by Volgren	267313
143	04/07/2010	249788	Accident damage #31118#. Trayler door damaged and trayler L	Repaired by Volgren	267313
143	04/07/2010	249937	Accident Damaged #21492 R/R. n/s.middle wheel arch clearanc	Repaired by Volgren	267493
143	04/01/2010	249505	Go to Brighton terminus to start bus	Start bus at Brighton terminus. Return to depot.	266924
143	04/01/2010	249495		A Service & Bus Safety Inspection	266924
143	04/01/2010	249522		A Service & Bus Safety Inspection	266924
143	04/01/2010	249522		Tension ALL Wheel Nuts to OEM Specs	266924
143	04/01/2010	249522		A Service & Bus Safety Inspection	266924
143	04/01/2010	249495		Tension ALL Wheel Nuts to OEM Specs	266924
143	03/31/2010	249247	Drv entered - Whls & Tyres Noisy	Changed tyres pos 12	266509
143	03/31/2010	249247	Drv entered - Whls & Tyres Noisy	Changed tyres pos 12	266509
143	03/31/2010	249285	Replace tyre pos 12 - needs balnce	Replaced	266509
143	03/31/2010	249356	WHL - front wheels need balancing	Fitted No 1 & 2 tyres & torqued w/nuts	266766
143	03/31/2010	249357	P/D - Front door does not open smoothly	Adjusted front doors	266766
143	03/30/2010	249247	Drv entered - Whls & Tyres Noisy	R/tested front tyres need balancing	266509
143	03/30/2010	249213	Bus wont start	Jump started	266509

143	03/30/2010	249213	Bus wont start	Jump started	266509
143	03/29/2010	249078	Bus wont start	Jump started	266328
143	03/29/2010	249078	Bus wont start	Jump started	266328
143	03/25/2010	248852	Clean a/c filter	Cleaned	265978
143	03/18/2010	248092	Clean a/c filter	Cleaned	265100
143	03/18/2010	247903	GLOBE FESTOON 24V-3W		264828
143	03/17/2010	247903	Replace emergency exit globe	Replaced	264828
143	03/05/2010	245281	POS 1 275/70 NEW	Creditor #:BEA001 BEAUREPAIRES P/O #:G75026 Receiving #:76848 Date :2010-03-05	263647
143	03/03/2010	246368	Clean a/c filter	Cleaned	263371
143	03/02/2010	246173	STARTER MOTOR SCANIA K93+L94		263131
143	03/02/2010	244889	BRUSH EMP AIR CON		263212
143	03/02/2010	244889	FILTER DRIER 5/8		263212
143	03/01/2010	361981	FLAT - Recap 275R 22.5 - Pos	Creditor #:BEA001 BEAUREPAIRES P/O #:K110491 Receiving #:111075 Date :2012-07-09 Repair	357960
143	03/01/2010	246173	Replace starter motor	Replaced	263131
143	03/01/2010	246088	Bus won't start at Brighton town hall	Go to Brighton town hall and trace starting fault found starter motor faulty hit slightly with hammer and try to start. All ok return to depot	263131
143	03/01/2010	263589	JACKNIFE LIGHT COMES ON	Creditor #:SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G80139 Receiving #:81791 Date :2010-08-09	275464
143	03/01/2010	263497	NITROGEN	Creditor #:ACT001 ACTROL P/O #:G80129 Receiving #:81654 Date :2010-08-04 143	275464
143	03/01/2010	360796	wheel chair ramp sensor 28118	Creditor #:VOL001 VOLGREN AUSTRALIA P/L P/O #:G110282 Receiving #:110817 Date :2012-07-03	357957
143	03/01/2010	263986	BRAKE ROTOR MIDDLE AXLE SCANIA	Creditor #:MUL001 MULTISPARES LTD P/O #:G80491 Receiving #:81861 Date :2010-08-10	275464
143	03/01/2010	263300	1802657 booster	Creditor #:MUL001 MULTISPARES LTD P/O #:G80016 Receiving #:81483 Date :2010-07-29 143	275464
143	02/27/2010	244889		Clean R/A & F/A filters; inspect and report on condition; Replace filter media	261804
143	02/27/2010	244889		FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)	261804
143	02/27/2010	244889		COMPRESSOR DRIVE BELTS: Inspect belt wear; Retension belts;	261804
143	02/27/2010	244889		DRIVE PULLEY'S: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;	261804
143	02/27/2010	244889		DRIVE PULLEY'S: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear	261804
143	02/27/2010	244889		COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose	261804
143	02/27/2010	244889		REFRIGERATION FILTER DRYER: Replace filter dryer; check pump operation;	261804
143	02/27/2010	244889		EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check boltsclamps & fittings; clean condensate drains; clean drip tray	261804
143	02/27/2010	244889		INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condensor fan grills	261804
143	02/27/2010	244889		CONDENSOR AREA: Clean condensor coils; check boltsclamps for tension	261804
143	02/27/2010	244889		UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensor pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation	261804
143	02/26/2010	245777	The seat belt broke	Replaced seat belt buckle	262965
143	02/24/2010	245651	Clean a/c filter	Cleaned	262635
143	02/22/2010	245281	replace worn tyre pos 1	Replaced	262201
143	02/19/2010	245276	Change tyre pos 12	Changed tyres	262150
143	02/19/2010	245276	Repair air/water seperator power line	Repaired	262150
143	02/19/2010	245041	FILTER OIL K124 / L94UAB (H200W01)		261989
143	02/19/2010	245041	FILTER TRANSMISSION ZF 4139-298-038E39HD119		261989
143	02/19/2010	245041	O RING FILTER KIT K93		261989
143	02/19/2010	245041	AIR FILTER SCANIA CLEANED		261989
143	02/19/2010	245041	ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL		261989
143	02/19/2010	245041	TEXAMATIC 1888		261989
143	02/19/2010	245041		D Service & Bus Safety Inspection	261989
143	02/19/2010	245041		Tension ALL Wheel Nuts to OEM Specs	261989
143	02/19/2010	245041		A Service & Bus Safety Inspection	261989
143	02/19/2010	245041		Tension ALL Wheel Nuts to OEM Specs	261989
143	02/16/2010	244673	Add coolant	Added	261643
143	02/12/2010	244345	Clean a/c filter	Cleaned	261219
143	02/11/2010	244093	33MM LOOSE WHEEL NUT INDICATOR		261172
143	02/11/2010	244093	Engine light remains on after bus is turned off	R/tested OK	261219
143	02/11/2010	244093	Check braking system for safety - (red brake warning symbol	Removed all 6 wheels and checked for brake warning light found O/S trailer brake pads sensor wires broken replaced	261219
143	02/11/2010	244093	Check braking system for safety - (red brake warning symbol	Found and replaced O/S tag brake wear indicator	261219
143	02/11/2010	244093	WEAR SENSOR SCANIA DISC BRAKE		261172
143	02/10/2010	244076	Add coolant	Added	261037
143	02/10/2010	244093	Check braking system for safety - (red brake warning symbol	Checked OK	261037
143	02/08/2010	243724	Bus wont start	Jump started	260711
143	02/08/2010	243724	Bus wont start	Jump started	260711
143	02/05/2010	241546	POS 2 275/70 FIT GBS SPECIAL	Creditor #:BEA001 BEAUREPAIRES P/O #:G74069 Receiving #:76001 Date :2010-02-05	260577
143	02/04/2010	243421	Bus wont start	Jump started	260335
143	02/03/2010	243195	Light on dash while driving	Checked OK	260137
143	02/03/2010	243162	emergency exit globe	changed globe	260137
143	02/03/2010	243162	GLOBE FESTOON 24V-3W		260137
143	02/01/2010	242873	Clean a/c filter	Cleaned	259828
143	01/31/2010	242846	Breakdown - Oakleigh Station - OUT 2.45 pm BACK 4.45 pm - W	Used van 619. By the time I got there it had already started	259660
143	01/28/2010	242576	Bus wont start	Jump started	259316
143	01/28/2010	231543	1757011 L/H MIDDLE AXLE CALIPE	Creditor #:SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G71339 Receiving #:75806 Date :2010-01-28	259316
143	01/22/2010	242019	Clean a/c filter	Cleaned	258834
143	01/21/2010	241905	replace no. plate lamp	replaced.	258672
143	01/21/2010	241905	NUMBER PLATE LAMP		258672
143	01/21/2010	241905	HALOGEN GLOBE 24V20W		258672
143	01/21/2010	241905	replace halogen globe	replaced.	258672
143	01/19/2010	241624	Replace no 2 tyre	Replaced	258323
143	01/19/2010	241624	Replace no 2 tyre	Replaced	258323
143	01/19/2010	241624	Replace no 2 tyre	Changed	258323
143	01/19/2010	241546	Replace tyre pos 2 - uneven wear	Replaced	258323
143	01/19/2010	241704	Bus wont start	Jump started	258323
143	01/19/2010	241647	Replace handle on rear hatch door	Replaced	258323
143	01/19/2010	241647	D HANDLE LENLOCK CHROME PLATED		258323
143	01/14/2010	241231	Clean a/c filter	Cleaned	257823
143	01/13/2010	239642	POS 4 275R CAP	Creditor #:BEA001 BEAUREPAIRES P/O #:G73549 Receiving #:75407 Date :2010-01-13	257668
143	01/08/2010	240577	check n/s indicator	checked ok.	257341
143	01/08/2010	240593	replace emergency exit globe	replaced	257192
143	01/08/2010	240577	check n/s indicator	checked ok.	257192
143	01/08/2010	240593	GLOBE FESTOON 24V-3W		257192
143	01/08/2010	240607	height adjuster not working	unable to locate fault.	257192
143	01/07/2010	240512	front tyres flatspot	checked ok	257099
143	01/07/2010	239936	DISC PADS SCANIA L94+0500 MERC	Creditor #:MUL001 MULTISPARES LTD P/O #:G73738 Receiving #:75181 Date :2010-01-07	257099
143	01/07/2010	239936	DISC BRAKE ROTORS SCANIA	Creditor #:MUL001 MULTISPARES LTD P/O #:G73738 Receiving #:75181 Date :2010-01-07	257099
143	01/07/2010	239936	WEAR SENSOR SCANIA DISC BRAKE		257099
143	01/07/2010	239936	removed o/s/f tyres and checked brake pads (worn out)	replace front rotors and pads	257192
143	01/07/2010	239936	removed o/s/f tyres and checked brake pads (worn out)	replaced brake pads and rotor clean and return all tools road test and park	257192
143	12/31/2009	239936	steam cleaned radiator	cleaned radiator	256553
143	12/31/2009	239936	removed o/s/f tyres and checked brake pads (worn out)	checked brake pads. c/o.	256553

143	12/31/2009	239587	Service	A Service & Bus Safety Inspection	256351
143	12/31/2009	239587	Service	A Service & Bus Safety Inspection	256553
143	12/31/2009	239587		Tension ALL Wheel Nuts to OEM Specs	256351
143	12/30/2009	239642	Replace tyre pos 4 - punctured	Replaced	256351
143	12/30/2009	239721	Change tyre 4	Changed	256553
143	12/30/2009	239721	Change tyre 4	Changed	256508
143	12/30/2009	239721	Change tyre 4	Changed	256508
143	12/30/2009	239647	Load test batteries	Loadtested and checked coolant OK	256508
143	12/30/2009	239721	Replace top brake light globe	Replaced	256508
143	12/30/2009	239721	GLOBE INDICATOR 24V-18W SINGLE CONTACT		256508
143	12/24/2009	239520	Bus wont start	Jump started	256238
143	12/24/2009	239435	Replace emergency exit globe	Replaced	256238
143	12/24/2009	239435	GLOBE FESTOON 24V-3W		256351
143	12/23/2009	239327	Bus wont start	Jump started	256001
143	12/23/2009	239327	Bus wont start	Jump started	256001
143	12/23/2009	239327	Bus wont start	Jump started	256001
143	12/22/2009	239222	Replace emergency light globe	Replaced	255832
143	12/22/2009	239222	GLOBE FESTOON 24V-3W		255832
143	12/15/2009	236732	POS 7 275/70 CAP	Creditor #:BEA001 BEAUREPAIRES P/O #:G72651 Receiving #:74738 Date :2009-12-15	255142
143	12/08/2009	237924	Replace emergency light globe	Replaced	254737
143	12/08/2009	237924	GLOBE FESTOON 24V-3W		254737
143	12/01/2009	237180	GLOBE FESTOON 24V-3W		253384
143	12/01/2009	237180	Replace emergency exit globe	Replaced	253384
143	11/27/2009	236745	Change tyre pos 7	Changed	253384
143	11/27/2009	236745	Change tyre pos 7	Changed	253384
143	11/27/2009	236732	replace worn tyre pos 7	Replaced	253384
143	11/27/2009	236871	Clean graffiti	Cleaned	253384
143	11/20/2009	236229	Replace flurosent	Replaced	252458
143	11/20/2009	236229	Replace flurosent	Replaced	252625
143	11/20/2009	236229	Replace flurosent	Replaced	252625
143	11/20/2009	236234	Replace emergency exit globe	Replaced	252458
143	11/20/2009	236234	GLOBE FESTOON 24V-3W		252625
143	11/18/2009	236093	Bus wont start	Jump started	252028
143	11/16/2009	235617	Bus wont start	Jump started	251852
143	11/13/2009	235326	PUMP WIPER-WASHER 24 VOLT		251852
143	11/13/2009	235326	No widscreen washer	Replaced washer bottle	251852
143	11/13/2009	235451	Random Vehicle Audit	Completed at service	251852
143	11/13/2009	235326	FAN BELT AIR/CON ARTIC VEE BELT B43		251852
143	11/13/2009	235326	CRANK TO PULLEY SCANIA 21/32X67		251852
143	11/13/2009	235326	Outer fan belt about to break	Replaced a/c belts	251852
143	11/13/2009	235339	Replace fluros	Replaced	251852
143	11/13/2009	235339	Replace fluros	Replaced	251852
143	11/13/2009	235422	Clean radiator	Cleaned	251852
143	11/13/2009	235326	Add coolant	Added	251852
143	11/13/2009	235422	Clean radiator	Cleaned	251852
143	11/13/2009	235422	Check brake pads	Removed tyres on middle axle & checked brake pads	251852
143	11/13/2009	235422	Check brake pads	Removed tyres on middle axle & checked brake pads	251852
143	11/13/2009	235327		Tension ALL Wheel Nuts to OEM Specs	251852
143	11/13/2009	235327		A Service & Bus Safety Inspection	251852
143	11/13/2009	235327		A Service & Bus Safety Inspection	251852
143	11/11/2009	235167	Bus wont start	Started bus	251273
143	11/10/2009	235044	A/C n/w - water leaking from a/c	checked out unable to find fault.	251104
143	11/06/2009	234564	Add coolant	Added	250685
143	11/05/2009	234518	Bus not starting at Brighton Terminus.	Go to Brighton Town Hall to jump start bus found bus not their. Call depot & was told driver started bus.Return back to depot.	250412
143	11/02/2009	233996	Service	Completed rebuild	249804
143	10/30/2009	233996	Service	Began starter rebuild needs to be tested	249804
143	10/30/2009	233996	BUSH KIT SUIT JF		249804
143	10/30/2009	233996	STARTER DRIVE SUIT JF		249804
143	10/30/2009	233996	STARTER SOLENOID SUIT JF		249804
143	10/27/2009	233804	RH drivers side headlight out		249208
143	10/27/2009	233804	HEAD LIGHT GLOBE 24V 70/75W		249375
143	10/26/2009	231543	1757010 R/H MIDDLE AXLE CALIPE	Creditor #:SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G71339 Receiving #:73166 Date :2009-10-26	249021
143	10/23/2009	233497	Add coolant	Added	248828
143	10/22/2009	231543	n/s middle axle inner brake pads worn unevenly	Fit caliper padswheels & r/tested OK	248828
143	10/22/2009	231543	n/s middle axle inner brake pads worn unevenly	Change brake caliper right middle	248828
143	10/22/2009	231543	WEAR SENSOR SCANIA DISC BRAKE		248602
143	10/21/2009	231543	Service	re build 2nd axle RS brake caliper and fit	248602
143	10/16/2009	231543	Service	strip 2nd axle RS brake caliper and attempt to rebuild from sapre parts - components too damaged to re-build.	248602
143	10/16/2009	232200	Accident Damaged # 30335 R/R. Front bumper-bar decalswinds	front bumper decal done	248602
143	10/15/2009	231543		assembly caliper and fit new brake pads - fit to bus 143 n/s middle axle.	248602
143	10/15/2009	231543	Service	assembled new brake caliper and fixed to the n/s middle axle/new brake pads/tyres.	248602
143	10/15/2009	231543	Service	removed tyres in o/s middle and checked brake caliper. One of the caliper piston stuck. c/o.	248602
143	10/15/2009	231543	WEAR SENSOR SCANIA DISC BRAKE		248602
143	10/15/2009	231543	DISC PADS SCANIA L94+0500 MERC		248602
143	10/15/2009	232504	Accident Damaged #21551 R/R. front bumper-bar decalsfront	removed entire bumper bar removed all decals removed number plate repaired all damaged areas using fibre fine filler sanded fibre filler applied body filler sanded body filler covered pin holes using body filler sanded body filler sanded entire bumper bar with 240 & 400 paper cleaned and made ready for grey primer and f	248602
143	10/15/2009	232504	Accident Damaged #21551 R/R. front bumper-bar decalsfront	Painted front bumper bar (yellow) of bus 143.	248602
143	10/15/2009	232200	Accident Damaged # 30335 R/R. Front bumper-bar decalswinds		248602
143	10/14/2009	232227	top up coolant	toped up coolant	248602
143	10/14/2009	232169	R H front (near coner) water leek on to driver over dash an	Re sealed N/S glass and O/S roof areal OK	248602
143	10/14/2009	231543	n/s middle axle inner brake pads worn unevenly	remove n/s middle wheel remove caliper - dismantle caliper order parts.	248602
143	10/14/2009	231543	n/s middle axle inner brake pads worn unevenly	removed brake caliper from axle stirp brake caliper (need new adjusting rod)	248602
143	10/14/2009	231543	SCANIA CALIPER PISTON BOOT KIT		248602
143	10/13/2009	231085	REPLACE REAR CAP 275R CAP POS	Creditor #:BEA001 BEAUREPAIRES P/O #:G71074 Receiving #:72793 Date :2009-10-13	248333
143	10/13/2009	231912	clean graffitti	cleaned graffitti	248333
143	10/13/2009	232005	Fair bit of graffitti in rear of bus	cleaned graffitti	248333
143	10/13/2009	231877	clean a/c filter	cleaned a/c filter	248333
143	10/09/2009	231543	oil leak around sump	Steam clean road test ok	248083
143	10/09/2009	231543	n/s middle axle inner brake pads worn unevenly	Checked brake caliper piston not working	248083
143	10/08/2009	231406	right hand bottom stop lamp not working	changed globe and lens as lens was broken as well	247739
143	10/07/2009	231406	LENS TO SUIT 2319 (RED)		247917
143	10/07/2009	231406	GLOBE STOP AND TAIL 24V 21/5W		247917
143	10/05/2009	231085	REPLACE TYRES POS 3-4-9-10 WORN		247306
143	10/02/2009	231176	Replace pos 34910 tyres	Replace tyres pos 34910	247070

143	10/02/2009	231175	Replace one seat	Replace seat	247070
143	10/02/2009	230962	Service	completed A service. changed n/s middle tyres. changed o/s rear tyres.	247070
143	10/02/2009	230962	Service	completed A service. changed n/s middle tyres. changed o/s rear tyres.	247306
143	09/30/2009	230729	Replace emergency exit globe	Replaced	246681
143	09/30/2009	230729	GLOBE FESTOON 24V-3W		246681
143	09/16/2009	229460	Bis wont start	Went to Endeavour hills got halfway ther and got called back driver started bus	245070
143	09/16/2009	229460	Bis wont start	Changed starter motor	245070
143	09/16/2009	229460	SCANIA STARTER MOTOR K93+L94		245170
143	09/14/2009	229093	Add coolant	Added	244708
143	09/11/2009	228903	Need to replace batteries	Replaced batteries & jump started	244471
143	09/11/2009	228903	Need to replace batteries	Jump started	244471
143	09/11/2009	228903	Need to replace batteries	Jump started	244471
143	09/11/2009	228903	BATTERY 800CCA		244471
143	09/09/2009	228378	ignition switch	Creditor #::SCA001 SCANIA AUSTRALIA PTY LTD P/O #::G70167 Receiving #:71936 Date :2009-09-09 143	244080
143	09/07/2009	228340	Replace engine door switch	Completed	243573
143	09/07/2009	228378	Bus wont start	Jump started	243573
143	09/07/2009	228378	Bus wont start	Jump started	243573
143	09/07/2009	228378	LIMIT SWITCH ENGINE STOP		243573
143	09/03/2009	228156	Not starting sometimes	Couldn't fault but ordered replacement inhibitor switch	243446
143	09/02/2009	228003	Bus not starting Brighton terminus.	Commenced going to Brighton got called when nearly there bus started.	243266
143	09/01/2009	227845	Bus wont start	Jump started	243008
143	09/01/2009	227928	Bus not starting Brighton terminus.	Drive to Brighton found bus not there & called in & returned to depot.	243008
143	08/28/2009	227537	Bus wont start	Jump started	242681
143	08/28/2009	227537	Bus wont start	Jump started	242681
143	08/26/2009	227248		D Service & Bus Safety Inspection	242345
143	08/26/2009	227248	FILTER OIL K124 / L94UAB (H200W01)		242345
143	08/26/2009	227248	FILTER TRANSMISSION ZF 4139-298-038E39HD119		242345
143	08/26/2009	227248	O RING FILTER KIT K93		242345
143	08/26/2009	227248	AIR FILTER SCANIA CLEANED		242345
143	08/26/2009	227248	ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL		242345
143	08/26/2009	227248	TEXAMATIC 1888		242345
143	08/26/2009	227248		Tension ALL Wheel Nuts to OEM Specs	242345
143	08/26/2009	227248	32MM LOOSE WHEEL NUT INDICATOR		242524
143	08/26/2009	227248		A Service & Bus Safety Inspection	242345
143	08/26/2009	227248		Tension ALL Wheel Nuts to OEM Specs	242345
143	08/20/2009	226788	Bus wont start	Jumpstarted	241403
143	08/10/2009	225860	Bus wont start	Jump started	240098
143	08/10/2009	225284	BRAKE BOOSTER MID AXLE	Creditor #::MUL001 MULTISPARES LTD P/O #::G69409 Receiving #:71073 Date :2009-08-10	240098
143	08/06/2009	225284	Replace o/s middle axle brake chamber.	Replace o/s middle axle brake booster & check for leaks ok.	239744
143	08/04/2009	222169	POS 7-8 275R REAR CAP	Creditor #::BEA001 BEAUREPAIRES P/O #::G68338 Receiving #:70858 Date :2009-08-04	239744
143	08/04/2009	225008	Replace trailer control relay valve.	Replace trailer control valve. Build-up air & found park & service brake system full of air (incorrect valve supplied). Fit old valve. Found original fault to be O/S middle axle spring brake back feeding.	239744
143	07/31/2009	224788	Replace brake relay valve.	Raise bus on lifters & trace air leak to trailer control valve. Parts on order.	239744
143	07/30/2009	224672	Breakdown - Cnr Charman Rd & Nepean Hwy - OUT 1.30 pm BACK	C/O bus 578. Attended by Moorabbin Transit. Middle axle park brake relay valve leaking.(MT will replace)	239744
143	07/30/2009	224671	Brakes air loss Charman Rd.	Go out to to bus trace air leak to trailer relay valve. Could not repair on road. Build-up air several times & drive back to depot.	239744
143	07/27/2009	224250	Replace clearance light O/s	Replaced	239222
143	07/27/2009	224250	GLOBE FESTOON 24V5W		239222
143	07/14/2009	223019	Acc damage on N/S rear wheel arch panel skirt panel	Temp repairs to bus on N/S rear wheel arch panel refitted wheelarch brush makeup new skirt panel & fit	237697
143	07/07/2009	222425	Rear door wont close	Replaced 3rd door edge switch adjusted door closer r/tested and checked power OK	236892
143	07/07/2009	222425	Rear door wont close	Repaired r/tested OK	236892
143	07/07/2009	222425	SENSITIVE EDGE DOOR SWITCH		237023
143	07/06/2009	222169	Replace tyre pos 78 - worn	Replaced	236783
143	07/06/2009	222174	Air bag bus going up/down at lights	Replaced airbag	236783
143	07/06/2009	222174	Air bag bus going up/down at lights	Replaced O/S middle rear airbag	236892
143	07/06/2009	222174	Air bag bus going up/down at lights	Replaced O/S middle rear airbag	236892
143	07/06/2009	222174	Tension hose clamps at rear	Tensioned	236783
143	07/06/2009	222174	Tension hose clamps at rear	Tensioned & r/tested	236892
143	07/06/2009	222174	Rear drive axle brakes pads low	Replaced brake pads	236881
143	07/06/2009	222174	DISC PADS SCANIA L94+0500 MERC		236881
143	07/06/2009	222174	REAR AIR BAG (MID AXLE) SCANIA L94UAB		236881
143	07/06/2009	222174	WEAR SENSOR SCANIA DISC BRAKE		236881
143	07/06/2009	222174	Rear drive axle brakes pads low	Replaced brake pads	236892
143	07/06/2009	222174	Rear drive axle brakes pads low	Replaced brake pads	236892
143	07/03/2009	222183	Change N/S/R tyres	Changed	236783
143	07/03/2009	222183	Change N/S/R tyres	Changed	236783
143	07/03/2009	222070		A Service & Bus Safety Inspection	236783
143	07/03/2009	222070		Tension ALL Wheel Nuts to OEM Specs	236783
143	07/03/2009	222070		A Service & Bus Safety Inspection	236783
143	06/29/2009	221617	GLOBE FESTOON 24V-3W		236098
143	06/29/2009	221617	Replace emergency light	Replaced	236098
143	06/26/2009	217140	SWAY BAR BUSH MID AXLE	Creditor #::MUL001 MULTISPARES LTD P/O #::G66823 Receiving #:69785 Date :2009-06-26 143	235948
143	06/19/2009	220795	Bus wont start	Jump started	235048
143	06/18/2009	220600	Replace fluorescent lights	Replaced	234979
143	06/18/2009	220600	Add coolant	Added	234979
143	06/18/2009	220600	Replace fluorescent lights	Replaced	235048
143	06/05/2009	219560	Add coolant	Added	233408
143	06/04/2009	219515	The very back door on artic when you open it then close it	Adjusted rear door sensitive edge	233256
143	06/04/2009	219515	LAMP INDICATOR [ORANGE]		233408
143	06/02/2009	218552	ROAD SAFETY INSPECTIONS	Creditor #::ROA001 Road Safety Inspections P/O #::G67252 Receiving #:69116 Date :2009-06-02	232840
143	05/31/2009	218552	Annual Inspection - BC 134528	Annual Inspection - BC 134528	232009
143	05/28/2009	217132	POS 6-9 275/70 REAR CAPS	Creditor #::BEA001 BEAUREPAIRES P/O #::G66797 Receiving #:68998 Date :2009-05-28	232303
143	05/28/2009	217132	POS 7 275/70 REAR CAP FLAT	Creditor #::BEA001 BEAUREPAIRES P/O #::G66797 Receiving #:68998 Date :2009-05-28	232303
143	05/28/2009	218745	Replace pos 1 tyre		232303
143	05/28/2009	218745	Replace pos 1 tyre	Replaced	232303
143	05/27/2009	218694	Replace N/S/F top indicator	Replaced	232303
143	05/27/2009	218694	Replace N/S/R top brake light	Replaced	232303
143	05/27/2009	218734	Measure front disc	Checked OK	232303
143	05/27/2009	218354	Ref to w/order # 218651	A Service & Bus Safety Inspection	231897
143	05/27/2009	218354		Tension ALL Wheel Nuts to OEM Specs	231897
143	05/27/2009	218651		A Service & Bus Safety Inspection	232303
143	05/27/2009	218651		Tension ALL Wheel Nuts to OEM Specs	232303
143	05/27/2009	218651		A Service & Bus Safety Inspection	232303
143	05/27/2009	218651	GLOBE S/CONTACT 24V-10W		232303
143	05/22/2009	218166	Replace grendas on both sides top of front wheel - N/s	Replaced	231758

143	05/22/2009	218166	Replace emergency exit push button under panel	Replaced	231758
143	05/21/2009	217140	Middle axle sway bar bushes worn	Assist with parts	230900
143	05/21/2009	217140	Middle axle sway bar bushes worn	Changed both sides sway bar bushes	231758
143	05/21/2009	217770	Secure all lower skit panels		231758
143	05/21/2009	217770	AMBER REFLECTOR SIDE MOUNT		231758
143	05/21/2009	217770	Accident Damaged No 18746 R/R. N/S. Lower panels No2 & No3	Painted white	231758
143	05/21/2009	217770	Accident damaged No19821 R/R. n/s/f. indicator assemblyn/	Painted white	231758
143	05/21/2009	217770	Paint O/S No 234 panels & replace decal repair No 4 pane		231758
143	05/20/2009	217140	489648 D BUSH	Creditor #::SCA001 SCANIA AUSTRALIA PTY LTD P/O #::G66861 Receiving #:68731 Date :2009-05-20	231758
143	05/20/2009	217770	Replace mud flaps - N/S/f	Replaced with new	231758
143	05/20/2009	217770	Paint wheels	Washed & painted	231758
143	05/20/2009	217770	Polish 235 panels & rear bumper bar	Polished all	231758
143	05/20/2009	217770	Paint wheels	Painted	231758
143	05/20/2009	217770	Accident damaged No19821 R/R. n/s/f. indicator assemblyn/	Repaired front b/bar sanded applied grey primer for repaired area	231758
143	05/20/2009	217770	Accident Damaged No 18746 R/R. N/S. Lower panels No2 & No3		231758
143	05/20/2009	217770	Replace & paint N/S trailer panels 14 & decals		231758
143	05/19/2009	217770	Paint till stand	Painted	231758
143	05/19/2009	217770	Polish 235 panels & rear bumper bar	Polished all	231758
143	05/19/2009	217770	Paint exterior mirrors and arms	Painted all mirrors and arms	231758
143	05/19/2009	217770	Clean graffiti - floor seats side walls	Cleaned graffiti	231758
143	05/19/2009	217770	Hand rails secure rivet - front N/s	Rivetted and secured all	231758
143	05/19/2009	217770	Polish exterior panels/headers & touch up paint work	Touched up	231758
143	05/19/2009	217770	Replace No Smoking decals	Replaced	231758
143	05/19/2009	217770	Clean graffiti - floor seats side walls	Cleaned graffiti	231758
143	05/19/2009	217770	Replace handle engine door - rear	Replaced	231758
143	05/19/2009	217770	Drivers foot rest - repair	Repaired	231758
143	05/19/2009	217770	Replace electrical door lock	Replaced	231758
143	05/19/2009	217770	O/S front access panel catch n/w	Replaced	231758
143	05/19/2009	217770	Replace interior decals	Replaced	231758
143	05/19/2009	217770	D HANDLE LENLOCK CHROME PLATED		231758
143	05/19/2009	217770	Adjust rear doors	Adjusted	231758
143	05/19/2009	217770	Drv entered - Accident		231758
143	05/19/2009	217770	Accident Damaged No 18746 R/R. N/S. Lower panels No2 & No3	Repaired lower panel No 2	231758
143	05/19/2009	217770	Accident damaged No19821 R/R. n/s/f. indicator assemblyn/	Replaced address decals	231758
143	05/19/2009	217770	Accident damaged No19821 R/R. n/s/f. indicator assemblyn/	Polished front b/.bar	231758
143	05/19/2009	217770	Accident damaged No19821 R/R. n/s/f. indicator assemblyn/		231758
143	05/15/2009	217140	Rear door sensitive adjuster n/w	Repaired	231416
143	05/15/2009	217140	Clean air condition filter secure vents	Cleaned	231416
143	05/13/2009	217140	Steamclean bus	Cleaned	231091
143	05/12/2009	217202	Replace tyre pos 4	Replaced	230900
143	05/11/2009	217132	Replace tyre pos 69 - bald	Replaced	230807
143	05/11/2009	217140	Replace tyre pos 56	Replaced	230807
143	05/11/2009	217064	O/S rear inner tyre worn pos 9	Replaced 910 tyres	230807
143	05/11/2009	217140	O/S middle axle both air bags leak	Replaced middle axle O/S/F O/S/R OK	230807
143	05/11/2009	217140	O/S middle axle both air bags leak	Drilled hole in floor so O/S drive wheels air bag could be replaced	230900
143	05/11/2009	217140	Middle axle sway bar bushes worn	Removed sway bar bush NO parts put back old bush	230807
143	05/11/2009	217140	O/S middle axle both air bags leak	Assist to remove air bag	230900
143	05/11/2009	217140	O/S middle axle both air bags leak	Assist Tudor with gaining access	230900
143	05/11/2009	217140	Middle axle sway bar bushes worn	Assist with parts	230900
143	05/11/2009	217140	REAR AIR BAG (MID AXLE) SCANIA L94UAB		230900
143	05/11/2009	217096	Remove timetable holder	Removed & cleaned	230807
143	05/07/2009	216551		Replace final drive oil	230156
143	05/07/2009	216793	Replace emergency light	Replaced	230449
143	05/07/2009	216793	GLOBE FESTOON 24V-3W		230449
143	05/06/2009	216551		Clean a/c filters	230156
143	05/06/2009	216551		Remove intercooler wash intercooler and raditor	230156
143	05/06/2009	216551		Adjust valve clearances	230156
143	05/06/2009	216551	DIAPHRAGM QUICK RELEASE VALVE B58		230449
143	05/06/2009	216551	O RING QUICK RELEASE VALVE+FRONT BRAKE	Clean a/c filters	230449
143	05/06/2009	216551		Remove intercooler wash intercooler and raditor	230156
143	05/06/2009	216551		Adjust valve clearances	230156
143	05/06/2009	216551		Rekit quick release valve	230156
143	05/06/2009	216667	Annual body inspection	Inspected	230392
143	05/05/2009	216551		Replace air dryer cansiter	230156
143	05/05/2009	216551	POWER STEER FILTER B10M		230156
143	05/05/2009	216551		Replace coolant filter in engine cooling system	230156
143	05/05/2009	216551		Inspect bus as per inspection sheet	230156
143	05/05/2009	216551		Inspect bus as per inspection sheet	230156
143	05/05/2009	216551		Replace fuel filters	230156
143	05/05/2009	216551		Replace power steering filter	230156
143	05/05/2009	216551		Replace hydraulic fan filter and top up oil	230156
143	05/05/2009	216551	FUEL FILTER ELEMENT SCANIA L94UAB (R90T / H7090WK10)		230156
143	05/05/2009	216551	FILTER FUEL K124 / LU94A (1411894 / H17WK05)		230156
143	05/05/2009	216551	HYDRAULIC FILTER L94UAB		230156
143	05/05/2009	216551	FILTER AIR DRYER KIT(HALDEX)		230156
143	05/05/2009	216551	RPM BORATE EP LUBE 220		230156
143	05/05/2009	216604	Check N/S brake	Fuelled & parked bus	230392
143	05/05/2009	216604	Check N/S brake	Removed middle axle N/S tyre and checked	230156
143	04/30/2009	216174	Bus wont start	Bleed fuel system	229901
143	04/30/2009	216174	Bus wont start	Jump started	229732
143	04/23/2009	215422	Middle axle stabiliser bar needs to be adjusted	Moved stabiliser bar to n/s & tighten bolts	228904
143	04/23/2009	215422	Middle axle stabiliser bar needs to be adjusted	Adjusted stabilizer bar	228744
143	04/22/2009	215252	Add coolant	Added	228555
143	04/18/2009	214929	PUMP WIPER-WASHER 24 VOLT		228114
143	04/18/2009	214929	Wiper washer n/w	Fit washer motor & fill water bottle	228114
143	04/16/2009	214663	GLOBE STOP AND TAIL 24V 21/5W		227956
143	04/16/2009	214663	Replace brake globe	Replaced	227956
143	04/09/2009	213953			227408
143	04/09/2009	213953			227533
143	04/09/2009	213953		Tension ALL Wheel Nuts to OEM Specs	227408
143	04/02/2009	213553	Bus not starting at Brighton terminal.	Go to Brighton & check no start restart bus & return.	226853
143	04/02/2009	213587	Breakdown - Brighton Terminal - OUT 3.00 pm BACK 4.00 pm -	Attended by Moorabbin Transit (Rear hatch playing up)	226853

143	03/31/2009	213206	Add coolant	Added	226452
143	03/21/2009	212270	Right rear saloon light cover broken	Replaced light cover	225415
143	03/19/2009	211997	HEAD LIGHT GLOBE 24V 70/75W		224958
143	03/19/2009	211997	Replace interior light	Replaced	224958
143	03/07/2009	210859	No horn	Loose connection - fixed	223381
143	03/07/2009	210859	Horn button doesn't work unless pointing straight ahead		223381
143	03/03/2009	209958	POS 1 275/70 NEW TYRE	Creditor #::BEA001 BEAUREPAIRES P/O #:G64658 Receiving #:66611 Date :2009-03-03	222709
143	02/27/2009	209958	REPLACE WORN TYRE POS 1	Replaced	222502
143	02/27/2009	209862	FILTER OIL K124 / L94UAB (H200W01)		222502
143	02/27/2009	209862	TEXAMATIC 1888		222502
143	02/27/2009	209862		D Service	222502
143	02/27/2009	209862		Tension ALL Wheel Nuts to OEM Specs	222502
143	02/27/2009	209862	AIR FILTER SCANIA INNER CLEANED		222502
143	02/27/2009	209862	FILTER TRANSMISSION ZF 4139-298-038E39HD119		222502
143	02/27/2009	209862	O RING FILTER KIT K93		222502
143	02/27/2009	209862	AIR FILTER SCANIA CLEANED		222502
143	02/27/2009	209862	ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL		222502
143	02/27/2009	209862			222502
143	02/27/2009	209862		Tension ALL Wheel Nuts to OEM Specs	222502
143	02/26/2009	210007	Replaced n/s/f. tyre	rep. pos. 1 tyre	222502
143	02/25/2009	209743	REPLACE INDICATOR LENS		222304
143	02/25/2009	209743	INDICATOR LIGHT FRONT ARTIC		222304
143	02/24/2009	209679	REFILL COOLANT	Fill coolant	222032
143	02/16/2009	208903	Replace emergency light	Replaced	220960
143	02/16/2009	208903	GLOBE FESTOON 24V-3W		220960
143	02/14/2009	208866	Needs A/C belts	Checked	220960
143	02/12/2009	208641	Bus wont start	Jump started	220543
143	02/12/2009	208641	Bus wont start	Jump started	220814
143	02/10/2009	208486	Hazard lights n/w	Checked working OK	220195
143	02/05/2009	207985	Replace emeregency light	Replaced	219594
143	02/05/2009	207985	GLOBE FESTOON 24V-3W		219594
143	02/04/2009	207834	Replace emergency light	Replaced	219362
143	02/04/2009	207834	GLOBE FESTOON 24V-3W		219362
143	01/19/2009	206533	Replace dash light globe	Replaced	217419
143	01/19/2009	206533	LED CLEARANCE LIGHT (RED AMBER)		217419
143	01/16/2009	206406	Replace A/C belts	Replaced	217260
143	01/16/2009	206406	Replace A/C belts	Replaced	217260
143	01/16/2009	206406	FAN BELT A/CON ARTIC 21/32X45		217419
143	01/16/2009	206406	CRANK TO PULLEY SCANIA 21/32X67		217419
143	01/14/2009	206134		Tension ALL Wheel Nuts to OEM Specs	216867
143	01/14/2009	206134			216867
143	01/14/2009	206134			216867
143	01/09/2009	205721	Add coolant	Added	216319
143	01/07/2009	205414		Clean R/A & F/A filters; inspect and report on condition; Replace filter media	216106
143	01/07/2009	205414		FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)	216106
143	01/07/2009	205414		COMPRESSOR DRIVE BELTS: Inspect belt wear; Retension belts;	216106
143	01/07/2009	205414		DRIVE PULLEY'S: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;	216106
143	01/07/2009	205414		DRIVE PULLEY'S: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear	216106
143	01/07/2009	205414		COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose	216106
143	01/07/2009	205414		REFRIGERATION FILTER DRYER: Replace filter dryer; check pump operation;	216106
143	01/07/2009	205414		EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check boltsclamps & fittings; clean condensate drains; clean drip tray	216106
143	01/07/2009	205414		INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condensor fan grills	216106
143	01/07/2009	205414		CONDENSOR AREA: Clean condensor coils; check boltsclamps for tension	216106
143	01/07/2009	205414		UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensor pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation	216106
143	01/07/2009	205414	Service as per list	UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensor pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation	216106
143	01/07/2009	205414	FILTER DRIER 5/8		216106
143	01/07/2009	205414	WATER VALVE SPARE PARTS KIT		216106
143	01/02/2009	205047	Engine no power - fault codes - 61833345	Repaired by Banlay	215571
143	01/02/2009	205047	Engine no power - fault codes - 61833345	Checked engine wont start bleed system start up cancel codes r/tested sent to Banlay	215571
143	12/31/2008	204951	Refill coolant	Refilled	215571
143	12/31/2008	204951	Refill coolant	Refilled	215571
143	12/24/2008	204544	Replace dash light	Replaced	215090
143	12/24/2008	204544	GLOBE+HOLDER INSTRUMENT (GREY)		215090
143	12/23/2008	200928	SOLENOID	Creditor #::PJL001 PJL DIESEL ELECTRIC P/O #:G61790 Receiving #:64688 Date :2008-12-23 143	214940
143	12/23/2008	200928	BUSHES	Creditor #::PJL001 PJL DIESEL ELECTRIC P/O #:G61790 Receiving #:64688 Date :2008-12-23 143	214940
143	12/23/2008	200928	DRIVE	Creditor #::PJL001 PJL DIESEL ELECTRIC P/O #:G61790 Receiving #:64688 Date :2008-12-23 143	214940
143	12/23/2008	200928	REGULATOR	Creditor #::PJL001 PJL DIESEL ELECTRIC P/O #:G61790 Receiving #:64688 Date :2008-12-23 GREG	214940
143	12/23/2008	200928	BRUSHES	Creditor #::PJL001 PJL DIESEL ELECTRIC P/O #:G61790 Receiving #:64688 Date :2008-12-23 143	214940
143	12/17/2008	203334	POS 7-8 275/70R REAR CAPS	Creditor #::BEA001 BEAUREPAIRES P/O #:G62571 Receiving #:64503 Date :2008-12-17	214155
143	12/17/2008	200928	Starter motor need rebuild	Completed starter rebuild	209571
143	12/15/2008	203819	Replace emergency exit globe	Replaced	213772
143	12/15/2008	203819	GLOBE FESTOON 24V-3W		213772
143	12/15/2008	203881	Flat batterys Brighton terminus.	drive to Brighton Town Hall & check no start jump start bus & return to depot.	213772
143	12/09/2008	203441	Wipers dont work	Fixed broken wiper arm	213110
143	12/09/2008	203334	Replace tyre pos 78 - bald	Replaced	213110
143	12/09/2008	200928	Replace emergency exit globe	Replaced	213110
143	12/09/2008	200928	GLOBE FESTOON 24V-3W		213110
143	12/09/2008	200928	Refill coolant	Refilled	213110
143	12/08/2008	203338	L/H thump tyre ?	Replaced pos 78 tyres and torqued w/nuts	212764
143	12/03/2008	202424	POS 3+4+8 275/70R REAR CAPS	Creditor #::BEA001 BEAUREPAIRES P/O #:G62267 Receiving #:64186 Date :2008-12-03	212678
143	11/28/2008	202526	Replace N/S/R tyres & O/S trailer tyres	Replaced	212010
143	11/28/2008	202424	REPLACE WORN TYRES POS 3+4+8+9	Replaced	212010
143	11/28/2008	202495	Replace light defuser	Replaced	212010
143	11/28/2008	202390		Tension ALL Wheel Nuts to OEM Specs	212010
143	11/28/2008	202390	RYAN & MEC		212134
143	11/28/2008	202390	GLOBE FESTOON 24V5W		212010
143	11/28/2008	202390			212010
143	11/25/2008	200928	DRIVE	Creditor #::PJL001 PJL DIESEL ELECTRIC P/O #:G61790 Receiving #:63886 Date :2008-11-25 143	211571
143	11/24/2008	201925	TOP UP COOLANT		211194
143	11/14/2008	201000	REPLACE EMERGENCY EXIT LIGHT GLOBE		210051
143	11/14/2008	201000	GLOBE FESTOON 24V-3W		210051
143	11/14/2008	201025	TOP UP COOLANT		210051
143	11/12/2008	200928	Starter motor need rebuild	Strip of and clean parts	209571

143	11/06/2008	200252	Bus wont start	Jump started	208852
143	10/31/2008	182351	Breakdown - Walker Street - OUT 7.45 pm BACK 8.15 pm - Just	Took van 619. Out of fuel. Got back to depot filled up took 236ltrs OK	208031
143	10/30/2008	182203	Not holding air pressure air leak near middle back door	Checked no air leak	208031
143	10/29/2008	181727	POS 5+8 275/70R REAR CAPS	Creditor #:BEA001 BEAUREPAIRES P/O #:G61240 Receiving #:63137 Date :2008-10-29	207785
143	10/27/2008	181727	Replace tyre pos 58 - worn	Replaced	207363
143	10/24/2008	181738	Replace O/S/R middle axle inner tyre	Replaced	207363
143	10/24/2008	181738	Replace N/S/R inner tyre	Replaced	207363
143	10/24/2008	181680	Ranndom vehicle audit	Completed	207363
143	10/24/2008	181738	Replace reverse buzzer	Replaced	207363
143	10/24/2008	181604			207363
143	10/24/2008	181604		Tension ALL Wheel Nuts to OEM Specs	207363
143	10/24/2008	181604			207456
143	10/24/2008	181604	NARVA 24V REVERSING BUZZER		207363
143	10/20/2008	181125	Refill coolant	Refilled	206531
143	10/17/2008	181068	Breakdown - Springvale - OUT 11.45 am BACK 1.15 pm - Altern	C/O bus 136. Replaced pulley on site	206323
143	10/17/2008	181068	SCANIA ALT BELT ROLLER(METAL) K1241B+L94UAB		206531
143	10/17/2008	181068	Breakdown - Springvale - OUT 11.45 am BACK 1.15 pm - Altern	C/O bus 136. Replaced pulley on site & refilled coolant	206531
143	10/09/2008	180216	Bus wont start (No electrics to start bus)	Found master switch replaced switch tested all OK	205268
143	10/02/2008	179600	HEAD LIGHT GLOBE 24V 70/75W		204248
143	10/02/2008	179600	Head lights U/S	Replaced head globe	204444
143	10/01/2008	179552	IND SWITCH SCANIA L113+K93		204080
143	10/01/2008	179552	Replace emergency exit globe	Replaced	204080
143	10/01/2008	179552	GLOBE FESTOON 24V-3W		204248
143	10/01/2008	179600	High beam wont go off	Tested bus for h/light fault not h/light stalk	204080
143	09/22/2008	178825	FILTER OIL K124 / L94UAB		202761
143	09/22/2008	178825	FILTER TRANSMISSION ZF 4139-298-038		202761
143	09/22/2008	178825	O RING FILTER KIT K93		202761
143	09/22/2008	178825	FILTER AIR SCANIA USE AF25066		202761
143	09/22/2008	178825	ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL		202761
143	09/22/2008	178825	TEXAMATIC 1888		202761
143	09/22/2008	178825		D Service	202761
143	09/22/2008	178825		Tension ALL Wheel Nuts to OEM Specs	202761
143	09/22/2008	178825			202761
143	09/22/2008	178825		Tension ALL Wheel Nuts to OEM Specs	202761
143	09/03/2008	177274	LIMIT SWITCH ENGINE STOP		200247
143	09/03/2008	177274	Rear kill switch n/w. This is very dangerous defeats the sa	Replaced switch working OK	200247
143	08/25/2008	176444	Replace fluroscnet tube	Replaced	198815
143	08/22/2008	176350	Fit fluro inside	Fitted	198628
143	08/21/2008	176143	Replace emergency exit globe	Replaced	198446
143	08/21/2008	176143	GLOBE FESTOON 24V-3W		198446
143	08/15/2008	175674	Flat batteries in mornings	Replaced battery	197688
143	08/15/2008	175674	Flat batteries in mornings	Jump started	197688
143	08/15/2008	175674	BATTERY 800CCA		197688
143	08/15/2008	175674	Flat batteries in mornings	Jump started	197855
143	08/13/2008	175544	Drv entered - Passenger Doors Require Adjusted	Checked OK	197362
143	08/13/2008	175544	Drv entered - Passenger Doors Require Adjusted	Checked OK	197456
143	08/13/2008	175474	Bus wont start	Jump started	197362
143	08/13/2008	175474	Bus wont start	Jump started	197362
143	08/13/2008	175488			197362
143	08/13/2008	175488		Tension ALL Wheel Nuts to OEM Specs	197362
143	08/13/2008	175488	D HANDLE LENLOCK CHROME PLATED		197362
143	08/13/2008	175488	15AMP BLADE FUSE		197362
143	08/13/2008	175488			197362
143	08/12/2008	175440	Front door not opening or closing properly catching on brus	Adjusted doors	197124
143	08/10/2008	175224	Bus wont start	Jump started	196726
143	08/05/2008	174868	Bus wont start	Jump started	196008
143	08/04/2008	174669	Replace emergency exit globe	Replaced	195753
143	08/04/2008	174669	GLOBE FESTOON 24V-3W		195753
143	08/01/2008	172247	VALVE BROKEN	Creditor #:BEA001 BEAUREPAIRES P/O #:G58149 Receiving #:60765 Date :2008-08-01 275 REAR CAP	195753
143	08/01/2008	174525	Bus wont start	Jump started	195594
143	08/01/2008	174525	Bus wont start	Jump started	195753
143	07/31/2008	174415	Bottom right stop tail light out	Replaced	195342
143	07/31/2008	174415	GLOBE STOP AND TAIL 24V 21/SW		195342
143	07/30/2008	174306	Replace emergency exit globe	Replaced	195157
143	07/30/2008	174306	GLOBE FESTOON 24V-3W		195157
143	07/30/2008	174324	Bus wont start	Jump started	195157
143	07/28/2008	174090	Bus wont start	Jump started	194721
143	07/28/2008	174090	Bus wont start	Jump started	194934
143	07/22/2008	173691	O RING AIR DRYER KIT HALDEX		194227
143	07/22/2008	173691	Breakdown - Wickham Rd Moorabbin - OUT 9.30 am BACK 10.45 a	Attended by Moorabbin Transit. replaced O ring on air dryer canister	194060
143	07/22/2008	173561	Bus losing air pressure Wickham Rd.	Drive to Wickham rd & c/o with MT 519. Check fault with air system. Remove air dryer cover & found cover O ring broken. Temp repair to O ring & bring bus back to MT depot. Fit new O ring supplied by GBS.	194060
143	07/21/2008	173547	30LTR RUBBISH BIN		194060
143	07/21/2008	173547	No rubbish bin	Replaced bin	193899
143	07/19/2008	173440	Bus needs new batteries	Loadtest batteries still in good condition	193899
143	07/18/2008	173372	Go to Brighton terminus & jump start bus.	Go out to Brighton & jump start bus ok.	193723
143	07/18/2008	173332	Bus wont start	Jumpstart	193723
143	07/16/2008	171302	1527631 REPAIR KIT	Creditor #:BAN001 BANLAY PTY LTD P/O #:G57778 Receiving #:60183 Date :2008-07-16 143	193308
143	07/16/2008	171302	1390430 CAP	Creditor #:BAN001 BANLAY PTY LTD P/O #:G57778 Receiving #:60183 Date :2008-07-16 143	193308
143	07/16/2008	173112	Bus wont start	Jump started	193489
143	07/16/2008	173112	Bus wont start	Jump started	193308
143	07/16/2008	173184	Check fault code on dash	Checked reset light on dash	193308
143	07/16/2008	173169	Fix strap on seat	Refit seat belt	193308
143	07/09/2008	172589			192430
143	07/09/2008	172589		Tension ALL Wheel Nuts to OEM Specs	192430
143	07/09/2008	172589			192430
143	07/04/2008	172328	Clean up bus for B.A.V conference.	Cleaned up interior & repainted wheels	191964
143	07/04/2008	171302	Service	repaired refitted all tyres & readjusted brakeslubed turntable.	191964
143	07/04/2008	171302	Service	road tested	191964
143	07/03/2008	172247	Rep. tyre pos. 3 valve broken	Rep. tyre	191964
143	07/03/2008	171302	411641 MIDDLE AXLE ROTOR	Creditor #:TRA004 TRADE BRAKE+CLUTCH CO. P/O #:G57823 Receiving #:50948 Date :2008-07-03	191964
143	07/03/2008	171302	Service	REFITTED L/H.MIDDLE CALIPER	191964
143	07/02/2008	171302	Service	replaced caliper kit on middle o/s. brakes.	191964
143	06/30/2008	171302	SENSORS	Creditor #:MUL001 MULTISPARES LTD P/O #:G57774 Receiving #:50767 Date :2008-06-30 143	191964

143	06/30/2008	171302	DISC PADS SCANIA L94+0500 MERC		191964
143	06/30/2008	171302	WEAR SENSOR SCANIA DISC BRAKE		191964
143	06/30/2008	171302	Warning light comes on for brakes low.	Fixed N/S middle hub rotor and caliper O/S middle hub and rotor fixed	191964
143	06/27/2008	171302	Warning light comes on for brakes low.	Cleaned brake parts hubs and bearings fixed L/S rotor - wrong parts	191964
143	06/26/2008	171302	WEAR SENSOR SCANIA DISC BRAKE		191964
143	06/26/2008	171302	DISC PADS SCANIA L94+0500 MERC		191964
143	06/26/2008	171302	Warning light comes on for brakes low.	Pulled out N/S middle caliper and rotor replaced both wheel brake pads	191964
143	06/25/2008	171302	Check / repair power steering leaking.	Fixed steering oil leak.	191964
143	06/25/2008	171302	Warning light comes on for brakes low.	Pulled out middle axle brake pads both sides pulled out rotor and caliper O/S middle	191964
143	06/24/2008	171302	Check / repair power steering leaking.	Checked steering system pull out steering pump fixed new and topped up bled air system checked for leaks	191964
143	06/24/2008	171302	WASHER POWER STEER PUMP B10M		191964
143	06/24/2008	171302	WASHER POWER STEER PUMP B10M		191964
143	06/24/2008	171302	O RING WATER PUMP VOLVO		191964
143	06/24/2008	171079	40A7603 POWER STEER PUMP	Creditor #:MUL001 MULTISPARES LTD P/O #:G57610 Receiving #:50660 Date :2008-06-24	191964
143	06/19/2008	171079	No power steering	No steering due to oil pumping out	191964
143	06/18/2008	170889	Drain power steering oil from reservoir	Drained and parked bus	191693
143	06/16/2008	170746	Check power steering leak	Checked found reservoir too full	191312
143	06/12/2008	169165	ROAD SAFETY INSPECTIONS	Creditor #::ROA001 Road Safety Inspections P/O #:G56489 Receiving #:50346 Date :2008-06-12	190879
143	06/12/2008	170447	Replaceside light globe		190879
143	06/12/2008	170447	Replaceside light globe	Replaced	190879
143	06/12/2008	170447	LENS TO SUIT 2030 LAMP		190879
143	06/03/2008	169763	Replace emergency light cover	Replaced	189675
143	06/03/2008	169763	EMERGENCY EXIT LIGHT		189915
143	06/02/2008	169721	Bus wont start	Jump started	189463
143	06/01/2008	169165	Road Safety Inspections BC 107470	Road Safety Inspections BC 107470	188923
143	05/28/2008	168197	1730876 BRAKE SENDER	Creditor #::BAN001 BANLAY PTY LTD P/O #:G56077 Receiving #:49780 Date :2008-05-28	188923
143	05/28/2008	169307	Check middle door sensitive edge	Checked OK	188923
143	05/28/2008	169307	INDICATOR LIGHT FRONT ARTIC		189020
143	05/28/2008	169307	Replace O/S/F indicator lens connector	Replaced	188923
143	05/26/2008	168936	Replace emergency exit globe		188550
143	05/26/2008	168936	Replace emergency exit globe	Replaced	188550
143	05/26/2008	168936	GLOBE FESTOON 24V-3W		188721
143	05/21/2008	168457	Replace mud flaps - N/S/F		187923
143	05/21/2008	168457	Paint wheels	Painted	187923
143	05/21/2008	168457	Replace wheel arch rubber and brush - N/S/F brush	Replaced	187923
143	05/21/2008	168457	Secure all lower skit panels	Secured	187923
143	05/21/2008	168457	Secure replace paint exterior mirrors and arms	Secured	187923
143	05/21/2008	168457	Seat end caps O/S 31315		187923
143	05/21/2008	168457	Clean graffiti - N/S 6 rear seat floor walls	Cleaned	187923
143	05/21/2008	168457	Rear step edges secure	Secured	187923
143	05/21/2008	168457	Replace interior decals O/S/R smoking	Replaced	187923
143	05/21/2008	168457	Secure clean adjust middle doors	Cleaned	187923
143	05/21/2008	168457	Clean air condition filter secure vents - front	Cleaned	187923
143	05/21/2008	168457	Secure clean adjust front doors	Cleaned	187923
143	05/21/2008	168457	Drivers foot rest - replace or repair		187923
143	05/21/2008	168457	Touch up paint work - O/S/F bar O/S/R	Touched up	187923
143	05/21/2008	168457	SCREW HAND CLAMP(P/N 280010)		187923
143	05/21/2008	168457	NUT HAND RAIL CLAMP (280010)		187923
143	05/21/2008	168457	AMBER REFLECTOR SIDE MOUNT		187923
143	05/21/2008	168457	CENTRA SEAT END CAPS		187923
143	05/21/2008	168457	Secure modesty panel - rear screws missing	Replaced	187923
143	05/21/2008	168457	Polish exterior panels/headers - N/S middle O/S/R corner		187923
143	05/21/2008	168457	Replace licensed to carry (No) seat (No) adult passengers		187923
143	05/21/2008	168457	Secure or replace side reflectors - O/S	Secured	187923
143	05/21/2008	168197	When press the foot brake air leak from relay valve fittings	Fixed	187632
143	05/21/2008	168197	CABLE HARNESS A/BAG+P/BRAKE SENDER		187923
143	05/21/2008	168457	N/S/R bar & 8-9		187923
143	05/20/2008	168197	When press the foot brake air leak from relay valve fittings	Checked still wrong parts	187632
143	05/16/2008	168197	Accumalator air line rubbing with engine mount	Completed	187632
143	05/16/2008	168197	Steamclean the bus	Steam cleaned	187632
143	05/16/2008	168197	Secure engine back door safety switch wire rubbing power st	Completed	187632
143	05/16/2008	168197	GLOBE INST 24V 2W		187632
143	05/16/2008	168219	Replace front head light globe	Replaced	187632
143	05/16/2008	168219	No broom for bus	Replaced	187632
143	05/16/2008	168219	BROOM HEAD (09803211)		187632
143	05/16/2008	168219	BROOM HANDLE (8232715)		187632
143	05/16/2008	168197	When press the foot brake air leak from relay valve fittings	Removed and ordered parts	187632
143	05/15/2008	168030	Secure heater hose near air filter		187632
143	05/15/2008	168030	Noplate light lens cracked	Repaired	187493
143	05/15/2008	168030	Middle exit light cover missing		187493
143	05/15/2008	168030	LENS TO SUIT 2029 (RED+AMBER)		187493
143	05/15/2008	168030	15LTR RUBBISH BINS		187493
143	05/15/2008	168030	LENS TO SUIT 2557 LAMP		187493
143	05/15/2008	168030	GLOBE STOP AND TAIL 24V 21/SW		187493
143	05/15/2008	168030	N/F parklight out		187493
143	05/15/2008	168030	N/R clearance light out	Replaced	187493
143	05/15/2008	168030	GLOBE FESTOON 24V5W		187493
143	05/15/2008	168030	Header tank clamp belt came off	Replaced	187632
143	05/15/2008	168030	Clean all rear lens	Cleaned	187493
143	05/15/2008	168030	Clean all clearance light lens	Cleaned	187493
143	05/15/2008	168030	Hand rails secure rivet N/S 1 screw roof 4 roof	Secured	187493
143	05/15/2008	168030	Secure N/S/F strip & touch up	Secured	187493
143	05/13/2008	167734		Adjust valve clearances	187122
143	05/13/2008	167734		Adjust valve clearances	187294
143	05/13/2008	167870	Bus wont start	Jump started	187209
143	05/13/2008	167875	Replace emergency exit globe		187209
143	05/13/2008	167875	Replace emergency exit globe	Replaced	187209
143	05/13/2008	167875	GLOBE FESTOON 24V-3W		187209
143	05/13/2008	167967	Breakdown - Noble Park - OUT 11.30 am BACK 12.00 noon - air	C/O bus 20. Returned and repaired air leak on air dryer	187209
143	05/12/2008	167734	FUEL FILTER ELEMENT SCANIA L94UAB		187122
143	05/12/2008	167734	FILTER FUEL K124 / LU94A		187122
143	05/12/2008	167734	HYDRAULIC FILTER L94UAB		187122
143	05/12/2008	167734	FILTER AIR DRYER KIT(HALDEX)		187122

143	05/12/2008	167734	RPM BORATE EP LUBE 220		187122
143	05/12/2008	167734		Replace coolant filter in engine cooling system	187122
143	05/12/2008	167734		Clean a/c filters	187122
143	05/12/2008	167734		Inspect bus as per inspection sheet	187122
143	05/12/2008	167734		Replace fuel filters	187122
143	05/12/2008	167734		Replace final drive oil	187122
143	05/12/2008	167734		Replace power steering filter	187122
143	05/12/2008	167734		Rekit quick release valve	187122
143	05/12/2008	167734		Replace hydraulic fan filter and top up oil	187122
143	05/12/2008	167734		Replace air dryer cansiter	187122
143	05/12/2008	167734	POWER STEER FILTER B10M		187122
143	05/12/2008	167746	Replace belts	Replaced	187122
143	05/12/2008	167746	FAN BELT A/CON ARTIC 21/32X45		187122
143	05/12/2008	167753			187122
143	05/12/2008	167753		Tension ALL Wheel Nuts to OEM Specs	187122
143	05/09/2008	167580	Annual body check list.		186986
143	04/28/2008	166494	Replace emergency exit globe	Replaced by Abdul	185301
143	04/28/2008	166494	GLOBE FESTOON 24V-3W		185447
143	04/22/2008	166089	Replace festoon globe	Replaced by Abdul	184817
143	04/22/2008	166062	Indicators dont work	Replaced the globe and cleaned the contact	184817
143	04/22/2008	166089	GLOBE FESTOON 24V5W		184974
143	04/22/2008	166062	GLOBE FESTOON 24V5W		184974
143	04/17/2008	165659	Steering box badly leak	Repaired	184226
143	04/17/2008	165659	Steering box leaking oil		184226
143	04/17/2008	165659	Steering box leaking		184226
143	04/17/2008	165659	WASHER OIL FEED LINE COMPRESSOR		184351
143	04/17/2008	165659	2way radio too noisy	Checked OK	184226
143	04/16/2008	164544	POS 7/8/9/10	Creditor #::BEA001 BEAUREPAIRES P/O #:G54420 Receiving #:48714 Date :2008-04-16 REAR CAPS	184076
143	04/15/2008	165500	Bus wont start	Jump started	183896
143	04/11/2008	165519	Front r/hand light	Replaced globe	183473
143	04/11/2008	165519	HEAD LIGHT GLOBE 24V 70/75W		183530
143	04/04/2008	164544	REP. TYRES POS. 78910 - BALD	rep. tyres pos.789 & 10	182616
143	04/03/2008	164620	REP. GLOBES	REP. GLOBES	182528
143	04/03/2008	164492	FILTER OIL K124 / L94UAB		182528
143	04/03/2008	164492	FILTER TRANSMISSION ZF 4139-298-038		182528
143	04/03/2008	164492	O RING FILTER KIT K93		182528
143	04/03/2008	164492	AIR FILTER SCANIA CLEANED		182528
143	04/03/2008	164492	ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL		182528
143	04/03/2008	164492	TEXAMATIC 1888		182528
143	04/03/2008	164492	Service	D Service	182528
143	04/03/2008	164492		Tension ALL Wheel Nuts to OEM Specs	182528
143	04/03/2008	164492	Service	REPLACED ALL REAR TYRES	182616
143	04/03/2008	164492	Service	REPLACED ALL REAR TYRES	182616
143	04/03/2008	164492	Service	D Service	182528
143	04/03/2008	164492	GLOBE FESTOON 24V-3W		182616
143	04/03/2008	164492	GLOBE FESTOON 24V5W		182616
143	04/03/2008	164492	Service		182528
143	04/03/2008	164492		Tension ALL Wheel Nuts to OEM Specs	182528
143	03/29/2008	164125	Bus wont start	Jump started	181682
143	03/20/2008	163701	Left front indicator not working	Checked OK	180615
143	03/11/2008	162258	FRONT AIR BAG SCANIA L94UAB		179031
143	03/11/2008	162258	Air leaks in front suspension.	Fit new air bag unit to O/S/F	179214
143	03/11/2008	162258	Air leaks in front suspension.	R/tested & topped up power steering oil & coolant	179214
143	03/04/2008	161080	POS 3+4	Creditor #::BEA001 BEAUREPAIRES P/O #:G53095 Receiving #:47625 Date :2008-03-04 CAPS	178206
143	03/03/2008	162258	Air leaks in front suspension.	Checked found n/s. air bag.(ride height) leaking air	177958
143	02/27/2008	162084	Indicator stork centralisers itself	Replaced indicator stork	177413
143	02/27/2008	162084	INDICATOR SWITCH SCANIA L94UAB		177577
143	02/13/2008	161080	REPLACED TYRES POS.3 & 4 WORN	rep. tyre pos.3 & 4 Worn	175483
143	02/13/2008	160844	Service	replaced hub seal	175483
143	02/13/2008	160844	Service	rep. r / tyres	175483
143	02/12/2008	160844	N/S mid axle hub seal leaking	Start to remove hub	175483
143	02/12/2008	160844	HUB SEAL TAG AXLE SCANIA L94UAB		175483
143	02/05/2008	160307	Service		175250
143	02/05/2008	160307		Tension ALL Wheel Nuts to OEM Specs	175250
143	02/05/2008	160307	Service		175250
143	02/04/2008	160141	GLOBE FESTOON 24V5W		175081
143	02/02/2008	160141	Turn blinker left side rear side	Replaced globe.	174933
143	02/01/2008	140580	ACC DAMAGE DRIVER SIDE	Creditor #::ATT001 ATTITUDE SIGNS P/O #:G44782 Receiving #:46831 Date :2008-02-01	174676
143	01/23/2008	159294	1368171 FUEL SOLENOID+O RING	Creditor #::BAN001 BANLAY PTY LTD P/O #:G52402 Receiving #:46539 Date :2008-01-23	173542
143	01/23/2008	159294	Bus wont start	R/tested bus for Daniel who replaced valve	173459
143	01/23/2008	159313	Indicators wont cancel	Repaired flashers	173542
143	01/23/2008	159313	Indicator sticking on will not click back	Removed steering wheel & repaired indicator cancellor	173542
143	01/23/2008	159407	Fit fuel solinoide	Removed & fitted fuel solinoide	173542
143	01/22/2008	159294	Bus wont start	Started bus bought to workshop need to replace fuel valve	173459
143	01/19/2008	159118	Replaced globe/s.	rep. globe	173232
143	01/14/2008	157548	BALD	Creditor #::BEA001 BEAUREPAIRES P/O #:G51825 Receiving #:46331 Date :2008-01-14 POS 8	172251
143	01/08/2008	156240	SIDE DAMAGE POS 1	Creditor #::BEA001 BEAUREPAIRES P/O #:G51477 Receiving #:46116 Date :2008-01-08	171410
143	01/04/2008	154771	Pos 7	Creditor #::BEA001 BEAUREPAIRES P/O #:G50943 Receiving #:46079 Date :2008-01-04 Bald	171061
143	01/04/2008	157832	Air leak from front of bus	Collect bus & fit joiner to air line near front panel & parked bus	171061
143	01/04/2008	157832	5/16inch AIR LINE JOINER		171061
143	01/03/2008	157793	Replace interior light globe	Replaced	170820
143	01/02/2008	157548	Replaced tyre pos. 8 - Bald.	Replaced tyre pos.8 Bald	170731
143	12/31/2007	157566	Replace wiper blades	replaced	170587
143	12/31/2007	157566	Replace N/S/R inner tyre	Replaced	170587
143	12/31/2007	157566	Replace N/S/R inner tyre	Replaced	170587
143	12/31/2007	157566	Replace dash globes	Replaced	170587
143	12/31/2007	157515	Service		170587
143	12/31/2007	157515		Tension ALL Wheel Nuts to OEM Specs	170587
143	12/31/2007	157515	HALOGEN GLOBE 24V20W		170731
143	12/31/2007	157515	WIPER BLADE ARTIC 28inch		170731
143	12/31/2007	157515	GLOBE+HOLDER INSTRUMENT (GREY)		170731
143	12/31/2007	157515	Service		170587
143	12/15/2007	156606	Coolant dose to low 24%	adjusted coolant	168999

143	12/14/2007	156454	Need new rear boot handles to open engine boot	replaced handles	168603
143	12/14/2007	156454	D HANDLE LENLOCK CHROME PLATED		168836
143	12/14/2007	156496	Service	REP. MOD. VALVE WIRE IN INTER FACE UNIT	168836
143	12/14/2007	156496		Clean R/A & F/A filters; inspect and report on condition; Replace filter media	168836
143	12/14/2007	156496		FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)	168836
143	12/14/2007	156496		COMPRESSOR DRIVE BELTS: Inspect belt wear; Retension belts;	168836
143	12/14/2007	156496		DRIVE PULLEY'S: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;	168836
143	12/14/2007	156496		DRIVE PULLEY'S: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear	168836
143	12/14/2007	156496		COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose	168836
143	12/14/2007	156496		REFRIGERATION FILTER DRYER: Replace filter dryer; check pump operation;	168836
143	12/14/2007	156496		EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check boltsclamps & fittings; clean condensate drains; clean drip tray	168836
143	12/14/2007	156496		INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condensor fan grills	168836
143	12/14/2007	156496		CONDENSOR AREA: Clean condensor coils; check boltsclamps for tension	168836
143	12/14/2007	156496		UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensor pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation	168836
143	12/14/2007	156496	WATER VALVE SPARE PARTS KIT		168999
143	12/14/2007	156496	FILTER DRIER 5/8		168999
143	12/12/2007	156240	Replaced tyre pos.1 - wire showing thru casing.	rep. tyre pos.1 - wire shows on side wall.	168519
143	12/11/2007	156250	N/S steer tyre u/s	Replace tyre	168260
143	12/03/2007	155516	Bus wont start	Had to bleed fuel system to start second time	167097
143	11/26/2007	155061	Bleed fuel system	Bled system	166107
143	11/23/2007	154771	Replaced tyre pos. -7 Bald	Rep. tyre pos. 7 Bald.	165776
143	11/23/2007	154823	Bus wont start	Jump started	165936
143	11/21/2007	154708	Replace N/S/R tyre	Replaced	165528
143	11/21/2007	154708	Replace A/C belt	Replaced	165528
143	11/21/2007	154708	CRANK TO PULLEY SCANIA 21/32X67		165776
143	11/21/2007	154661			165528
143	11/21/2007	154661		Tension ALL Wheel Nuts to OEM Specs	165528
143	11/21/2007	154661			165776
143	11/11/2007	153838	Interior light u/s	Replace globe	164314
143	10/30/2007	152799	Drv entered - Gearbox High Temperature	Checking out dash temp gauge there is a loose connector in plug r/tested	163103
143	10/29/2007	152799	Power steering box leaks.	Checked OK	162882
143	10/29/2007	152799	Drv entered - Gearbox High Temperature	Engine temp gauge u.s	162876
143	10/29/2007	152799	Drv entered - Gearbox High Temperature	Checking out dash loom unable to find fault	163103
143	10/29/2007	152799	Drv entered - Gearbox High Temperature	Tested dash engine temp gauge sticking faulty plug at back of dash	163103
143	10/29/2007	152326	1500455 L94UAB MUFFLER	Creditor #BAN001 BANLAY PTY LTD P/O #:G50213 Receiving #:44576 Date :2007-10-29	162882
143	10/26/2007	152326	Service	refitted muffler	162876
143	10/24/2007	152326	Replace tubro	Fitted exhaust pipe	162800
143	10/24/2007	152326	Replace tubro	Small r/test bus smoking still	162876
143	10/24/2007	152326	Replace tubro	Refitted muffler	162876
143	10/23/2007	152326	1766754 TURBO+GASKET KIT	Creditor #BAN001 BANLAY PTY LTD P/O #:G50057 Receiving #:44450 Date :2007-10-23	162800
143	10/23/2007	152326	Replace tubro	Cleaned out exhaust muffler & connection cleaned out intercooler & refitted	162800
143	10/23/2007	152326	Replace tubro	Assist Daniel with turbo	162800
143	10/22/2007	152326	Replace tubro	Replaced turbo disconnected intercooler	162800
143	10/22/2007	152326	Replace tubro	Assist Daniel	162800
143	10/08/2007	151204	GLOBE FESTOON 24V-3W		162594
143	10/08/2007	151251	Headlights not working	Checked relays & fuses replaced globe	162594
143	10/08/2007	151251	HEAD LIGHT GLOBE 24V 70/75W		162594
143	10/06/2007	151204	Emergency Exit light u/s	Replace globe	162594
143	10/02/2007	150855	Replace N/S/R side indicator	Replaced	162009
143	10/02/2007	150855	Replace clearance light	Replaced	162009
143	10/02/2007	150855	LENS TO SUIT 2029 (RED+AMBER)		162009
143	10/02/2007	150855	LENS TO SUIT 2029 (RED+AMBER)		162009
143	10/02/2007	150855	GLOBE FESTOON 24V5W		162009
143	09/28/2007	150546	GLOBE INDICATOR 24V-18W SINGLE CONTACT		161804
143	09/28/2007	150546	No indicatorsdamaged o/s/f. damaged.	REP. O/S/F. GLOBE & LIGHT.	161

143	07/27/2007	145466	CONVEX MIRROR		154201
143	07/27/2007	145466	MOUNTING CONVEX MIRROR		154201
143	07/27/2007	145463	Service		154201
143	07/27/2007	145463	MIRROR TOP BRAZILLIAN GLASS		154201
143	07/27/2007	145466	Service		154201
143	07/27/2007	145466	MIRROR TOP BRAZILLIAN GLASS		154201
143	07/25/2007	145225	Right side rear clearance	Replaced	153876
143	07/25/2007	145225	Left side bottom rear clearance light out	Replaced	153876
143	07/25/2007	145225	GLOBE FESTOON 24V5W		153876
143	07/25/2007	145225	Replace globe	Replaced exit light globe	153876
143	07/25/2007	145225	GLOBE FESTOON 24V-3W		154030
143	07/17/2007	144672	Replace lamp & globe	Replaced	152957
143	07/17/2007	144672	LAMP (RED+AMBER)		153087
143	07/17/2007	144672	GLOBE FESTOON 24V5W		153087
143	07/16/2007	144574	Front temp 17 and rear 20	Checked climate control is OK. Spoke to driver he said no problem with heater	152957
143	07/05/2007	143744	Rep. a/c. belts	Rep. a/c. belts	151390
143	07/05/2007	143744	FAN BELT AIR/CON ARTIC VEE BELT B43		151390
143	06/29/2007	143325		Tension ALL Wheel Nuts to OEM Specs	150772
143	06/29/2007	143325			150772
143	06/29/2007	143325			150772
143	06/18/2007	142413	L/H MIRROR ARM LONG (PM8844-1)		149436
143	06/18/2007	142413	BRAZILLIAN MIRROR L/H		149436
143	06/18/2007	142413	Front left mirror broken	Replace mirror and arm	149295
143	06/15/2007	142278	Wont start	Jump start	149137
143	06/06/2007	141632	GLOBE FESTOON 24V5W		148371
143	06/06/2007	141632	LAMP (RED+AMBER)		148371
143	06/06/2007	141632	R/H/R clearance lamp out	Checked OK	148371
143	06/06/2007	141632	R/H/R clearance lamp out	Fit O/S rear clearance lamp	148247
143	06/06/2007	140903	ROAD SAFETY INSPECTIONS	Creditor #:ROA001 Road Safety Inspections P/O #:G44524 Receiving #:41202 Date :2007-06-06	148247
143	06/03/2007	140903	Annual Inspection - BC 102687	Annual Inspection - BC 102687	147636
143	05/29/2007	140580	Oil leak around inspection covers	Checked OK	147636
143	05/29/2007	140580	Full steamclean	Cleaned	147636
143	05/29/2007	140580	Cross member under bell housing badly bent (Checked on 8/02	Straightened up	147636
143	05/29/2007	140580	Oil leak from engine inspection plate (Checked on 8/02/07	Cleaned checked OK	147636
143	05/29/2007	140580	Engine oil leak bell housing area (Checked on 20/12/06 8/0	Cleaned checked OK	147636
143	05/29/2007	140580	Oil leak at inspection covers	Cleaned & checked OK	147636
143	05/29/2007	140580	STOP LAMP LENS		147636
143	05/29/2007	140580	LENS TO SUIT 2029 (RED+AMBER)		147636
143	05/29/2007	140580	Replace broken N/R top parklight lens	Replaced	147636
143	05/29/2007	140580	Polish and repair N/S/R side panels and rear bumper bar	Repaired & polished	147636
143	05/29/2007	140580	Repair refit front n/s clip in strip	Fixed	147636
143	05/29/2007	140580	Polish exterior panels/headers & touch up paint work	Polished & touched up	147636
143	05/29/2007	140580	Paint rear bumper bar & repair n/s end	Repaired & painted	147636
143	05/29/2007	140580	Paint wheels	Painted	147636
143	05/29/2007	140580	Secure all lower skit panels	Secured	147636
143	05/29/2007	140580	Front bumper bar - polish & touch up	Polished & touched up	147636
143	05/29/2007	140580	Secure paint exterior mirrors & arms	Secured & painted	147636
143	05/29/2007	140580	Replace Exit Only on rear doors	Replaced	147636
143	05/29/2007	140580	Secure seat frames or capsules No 13 O/S (bucket to base)	Secured	147636
143	05/29/2007	140580	Secure clean and adjust front mid & rear doors	Clean & adjusted	147636
143	05/29/2007	140580	Polish O/S/R corner panels	Polished	147636
143	05/29/2007	140580	Secure clean and adjust front mid & rear doors	Paint front door	147636
143	05/29/2007	140580	Front bumper bar - polish & touch up	Polished & touched up	147636
143	05/29/2007	140580	Secure all lower skit panels	Secured	147636
143	05/29/2007	140580	Paint wheels	Painted	147636
143	05/29/2007	140580	Paint rear bumper bar & repair n/s end	Repaired & painted	147636
143	05/29/2007	140580	Polish exterior panels/headers & touch up paint work	Polished & touched up	147636
143	05/29/2007	140580	Polish O/S/R corner panels	Replaced the panel	147636
143	05/29/2007	140580	UNION STRAIGHT AIR LINE FITTING		147636
143	05/28/2007	140580	Replace V bar bush	Replaced	147636
143	05/28/2007	140580	V Bar bush worn (Checked on 8/02/07 29/03/07 servicable HK		147636
143	05/28/2007	140580	SCANIA L94UAB V STAY BUSK KIT		147636
143	05/28/2007	140580	BALLJOINT BOOT STEER DAMPER		147636
143	05/28/2007	140580	Replace ball joint boots for drive axle sway bar	Replaced 2 boots	147636
143	05/28/2007	140580	V Bar bush worn (Checked on 8/02/07 29/03/07 servicable HK	Assisted to remove & fit Vbar	147636
143	05/28/2007	140580	Replace oil seperator top elbow - cracked	Replaced	147200
143	05/28/2007	140580	Horn cover needs repair	Checked OK	147636
143	05/28/2007	140580	Replace interior light cover	Replaced	147636
143	05/28/2007	140580	Coolant leak from booster pump	Tighten the hose	147636
143	05/28/2007	140580	Dash Warning Light decal needs regluing	Reglued	147636
143	05/28/2007	140580	Repair air line	Repaired broken airline near oil seperator and secure 2 air lines	147636
143	05/28/2007	140580	Repair air leak near air driyer air valve	removed valve clean and re fitted but still leaking	147636
143	05/25/2007	140580	Cracks in N/S/O/R air bag	replaced air bags	147378
143	05/25/2007	140580	O/S rear air bags leak (drive axle)	replaced	147378
143	05/25/2007	140580	O/S rear air bags leak (drive axle)	replaced	147378
143	05/25/2007	140580	REAR AIR BAG (DRIVE AXLE) SCANIA L94UAB		147636
143	05/25/2007	140580	Steering box leak	checked o/k	147378
143	05/25/2007	140580	Oil leak around sump	repaired	147378
143	05/25/2007	140580	Indicator not cancelling	repaired	147378
143	05/25/2007	140580	N/S header tank hose needs replacing	replaced	147378
143	05/25/2007	140580	Replace gas stays on electrical panel	replaced	147378
143	05/25/2007	140580	Interior mirrors - loose centre	secured	147378
143	05/25/2007	140580	Clean air condition filter secure vents X2	cleaned	147378
143	05/25/2007	140580	SCREW TORX 8 X 20MM SIDE PANEL		147636
143	05/25/2007	140580	PLATE CLAMPING SIDE PANEL		147636
143	05/25/2007	140580	GAS STAY 500N		147636
143	05/24/2007	139761	POS 3	Creditor #:BEA001 BEAUREPAIRES P/O #:G43947 Receiving #:40860 Date :2007-05-24	147200
143	05/24/2007	140475	Wheel chair ramp - operation & clean	cleaned	147200
143	05/23/2007	140475	REFILL WIPER BLADE SUIT SWF 27		147026
143	05/23/2007	140475	Replace wiper blades	Replaced	147026
143	05/21/2007	140279	Accident Damaged n/s. mirror & arm	Fitted	146741
143	05/21/2007	140279	BRAZILLIAN MIRROR L/H		146741
143	05/21/2007	140279	R/H MIRROR ARM SHORT (PM8844-2)		146741

143	05/21/2007	140279	Accident Damaged n/s. mirror & arm	Fit new mirror head and arm	146741
143	05/15/2007	139761	ROCKER COVER GASKET L94UAB		146204
143	05/15/2007	139761		Clean a/c filters	146035
143	05/15/2007	139761		Adjust valve clearances	146035
143	05/14/2007	139761		Replace coolant filter in engine cooling system	146035
143	05/14/2007	139761		Inspect bus as per inspection sheet	146204
143	05/14/2007	139761	RPM BORATE EP LUBE 220		146035
143	05/14/2007	139761	FILTER AIR DRYER KIT(HALDEX)		146035
143	05/14/2007	139761	HYDRAULIC FILTER L94UAB		146035
143	05/14/2007	139761	FILTER FUEL K124 / LU94A		146035
143	05/14/2007	139761	FILTER ELEMENT SCANIA L94UAB		146035
143	05/14/2007	139761	POWER STEER FILTER B10M		146035
143	05/14/2007	139761		Replace air dryer cansiter	146035
143	05/14/2007	139761		Replace hydraulic fan filter and top up oil	146035
143	05/14/2007	139761		Rekit quick release valve	146035
143	05/14/2007	139761		Replace power steering filter	146035
143	05/14/2007	139761		Replace final drive oil	146035
143	05/14/2007	139761		Replace fuel filters	146035
143	05/14/2007	139761		Inspect bus as per inspection sheet	146035
143	05/14/2007	139785	Annual body check	Completed	146035
143	05/14/2007	139760		Tension ALL Wheel Nuts to OEM Specs	146035
143	05/14/2007	139760			146035
143	05/09/2007	139362	Replace O/S centre axle tyres	Checked OK	145349
143	05/08/2007	139361	Replace N/S/F tyre	Replaced	145349
143	05/08/2007	139361	FAN BELT A/CON ARTIC 21/32X45		145434
143	05/08/2007	139361	Replace A/C belts	Assisted	145434
143	05/08/2007	139361	Replace A/C belts	Replaced	145349
143	05/08/2007	139361	Pick bus up from CMV	Picked up	145349
143	05/08/2007	139361	Top right stop light out	Replaced	145349
143	05/08/2007	139361	Left side park light out	Replaced	145349
143	05/08/2007	139361	Front disc rotors to be replaced next reline	Checked measure OK	145349
143	05/07/2007	139324	MINI WEDGE GLOBE 24V-1.2W		145349
143	05/07/2007	139324	Fit dash globes	Fitted	145305
143	04/30/2007	139188	Breakdown - Moorrabin Stn.air leaks on n/s/f.(ATTENDED BY M	Attended by M/T. C/O. bus & retuned to M.T depotfound faulty suspension blockbus was returned to Grendas for replacement.	144306
143	04/30/2007	138617	5/16inch AIR LINE JOINER		144379
143	04/30/2007	138617	Air Leak N/S/F Wheel At Moorrabbin Station	Drive to Moorrabbin Stn & secure air leak & bring bus back to w/shop.Repair air leak.	144306
143	04/29/2007	138565	Replaced interior light tubes.	rep.int. light tube	144306
143	04/26/2007	138309	Engine stopped for no reason.	Bleed system and road tested bus engine running OK	143888
143	04/23/2007	138081	SUPPLY & FIT	Creditor #:ELI001 ELITE WINDSCREENS P/O #:G42943 Receiving #:40047 Date :2007-04-23	143652
143	04/21/2007	138081	Supply & refit o/s. side window.	side window repaced by Elite glass	143492
143	04/17/2007	136855	POS 8	Creditor #:BEA001 BEAUREPAIRES P/O #:G41623 Receiving #:39892 Date :2007-04-17	143000
143	04/12/2007	137421	DRIVERS BLIND ISUZU 987X1000MM		142581
143	04/12/2007	137421	Repairs to drivers blind.	Replaced sun blind	142581
143	04/04/2007	136855	TYRE POS 8 FLAT	Replace tyre pos 8	142131
143	04/04/2007	136434	POS 5+6+7+8+9	Creditor #:BEA001 BEAUREPAIRES P/O #:G41354 Receiving #:39625 Date :2007-04-04	142131
143	04/02/2007	136556	SCANIA ALT BELT ROLLER K1241B	Creditor #:BAN001 BANLAY PTY LTD P/O #:G41379 Receiving #:39547 Date :2007-04-02	141709
143	03/29/2007	136434	Replace tyres pos.56789 - Bald / worn.	Replaced	141514
143	03/29/2007	136556	Pully Idler Scania Artic (No Grove Plastic)		141593
143	03/29/2007	136556	SCANIA ALT BELT TENSIONER K1241B		141593
143	03/29/2007	136556	Replace idler pulleys as req	Replaced pulleys and adjuster went for parts	141514
143	03/29/2007	136556	Replace tensioner pulley	Replaced pulleys and adjuster went for parts	141514
143	03/28/2007	136448	Replace 3 trailer tyres	Replaced	141262
143	03/28/2007	136448	Replace 3 trailer tyres	Replaced	141262
143	03/28/2007	136392	FILTER OIL K124 / L94UAB		141262
143	03/28/2007	136392	FILTER TRANSMISSION ZF 4139-298-038		141262
143	03/28/2007	136392	O RING FILTER KIT K93		141262
143	03/28/2007	136392	FILTER AIR SCANIA USE AF25066		141262
143	03/28/2007	136392	ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL		141262
143	03/28/2007	136392	TEXAMATIC 1888		141262
143	03/28/2007	136392		D Service	141262
143	03/28/2007	136392		Tension ALL Wheel Nuts to OEM Specs	141262
143	03/28/2007	136392			141262
143	03/28/2007	136392		Tension ALL Wheel Nuts to OEM Specs	141262
143	03/27/2007	136201	MIRROR TOP BRAZILLIAN GLASS		141107
143	03/27/2007	136201	Service		141107
143	03/08/2007	134864	Right hand drivers mirror top part hair line crack	Checked mirror cracked- replaced	139044
143	03/08/2007	134864	BRAZILLIAN MIRROR RH		139044
143	02/13/2007	132869	Parker lens u/s	Replaced	135817
143	02/13/2007	132869	LENS TO SUIT 2029 (RED+AMBER)		135817
143	02/08/2007	132508	BOOST PUMP EXCHANGE		135231
143	02/08/2007	132508	Leak at boost pump (coolant)	Replaced pump	135231
143	02/08/2007	132508	Water leak from top of gearbox cooler pipe	Replaced clamp and tightened others	135231
143	02/08/2007	132508	GLOBE FESTOON 24V5W		135231
143	02/08/2007	132508	Drv entered - Elec & Light Reverse Lights	Checked OK	135231
143	02/08/2007	132508	Coolant leak above N/S of gearbox		135231
143	02/08/2007	132461			135049
143	02/08/2007	132461		Tension ALL Wheel Nuts to OEM Specs	135049
143	02/08/2007	132461			135478
143	01/22/2007	131342	Exit light not working	Replace globe	133106
143	01/22/2007	131342	GLOBE FESTOON 24V-3W		133260
143	12/20/2006	129183			130394
143	12/20/2006	129183			130394
143	12/20/2006	129183		Tension ALL Wheel Nuts to OEM Specs	130394
143	12/08/2006	113806	YELLOW ARROW DECAL O/S REAR	Creditor #:ATT001 ATTITUDE SIGNS P/O #:32279 Receiving #:36902 Date :2006-12-08	128932
143	11/23/2006	127094	Replace interior fluro	Replaced	126898
143	11/20/2006	126654	LENS TO SUIT 2030 LAMP		126393
143	11/20/2006	126654		DRIVE PULLEY'S: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear	126086
143	11/20/2006	126654		DRIVE PULLEY'S: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;	126086
143	11/20/2006	126654		COMPRESSOR DRIVE BELTS: Inspect belt wear; Retension belts;	126086
143	11/20/2006	126654		FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)	126086
143	11/20/2006	126654		Clean R/A & F/A filters; Inspect and report on condition; Replace filter media	126086
143	11/20/2006	126654	Service as per list	Repaired No 2 clutch on rear unit	126086
143	11/20/2006	126654	FILTER DRIER 5/8		126393

143	11/20/2006	126654	UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensor pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation	126086
143	11/20/2006	126654	CONDENSOR AREA: Clean condensor coils; check boltsclamps for tension	126086
143	11/20/2006	126654	INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condensor fan grills	126086
143	11/20/2006	126654	EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check boltsclamps & fittings; clean condensate drains; clean drip tray	126086
143	11/20/2006	126654	REFRIGERATION FILTER DRYER: Replace filter dryer; check pump operation;	126086
143	11/20/2006	126654	COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose	126086
143	11/15/2006	126306	Annual random audit	125842
143	11/15/2006	126373	NUT HAND RAIL CLAMP (280010)	125842
143	11/15/2006	126373	SCREW HAND CLAMP(P/N 280010)	125842
143	11/15/2006	126373	GLOBE S/CONTACT 24V-10W	125842
143	11/15/2006	126373	Replace stopping sign globe	125842
143	11/15/2006	126373	Replace 2 exit globes	125842
143	11/15/2006	126373	Change N/S clearance light & indicator light with 2 globes	125842
143	11/15/2006	126373	Replace No plate light & F/IO/S park light	125842
143	11/15/2006	126373	GLOBE FESTOON 24V5W	125842
143	11/15/2006	126373	LAMP INDICATOR [ORANGE]	125842
143	11/15/2006	126373	LAMP (RED+AMBER)	125842
143	11/15/2006	126373	GLOBE INST 24V 2W	125842
143	11/15/2006	126373	D HANDLE LENLOCK CHROME PLATED	125969
143	11/15/2006	126305		125842
143	11/15/2006	126305	Tension ALL Wheel Nuts to OEM Specs	125842
143	11/15/2006	126305		125842
143	11/09/2006	125894	Breakdown - Chandler Rd near Yaraman Railway Crossing - OUT	125099
143	10/20/2006	124379	DISC PADS SCANIA	122945
143	10/20/2006	124379	Last axle - brake pads low - check	122945
143	10/20/2006	124379	Middle axle - brake pads low - check	122945
143	10/03/2006	123011	First interior light behind driver o/s needs taking out to	120912
143	10/03/2006	123011	First interior light behind driver o/s needs taking out to	120795
143	10/03/2006	121926	Direct Purchase - BODYWORK	120795
143	10/03/2006	123011	Broom handle coming apart	120795
143	10/03/2006	122982	Tension ALL Wheel Nuts to OEM Specs	120795
143	10/03/2006	122982	D Service	120795
143	10/03/2006	122982	TEXAMATIC 1888	120795
143	10/03/2006	122982	ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL	120795
143	10/03/2006	122982	FILTER AIR SCANIA USE AF25066	120795
143	10/03/2006	122982	O RING FILTER KIT K93	120795
143	10/03/2006	122982	FILTER TRANSMISSION ZF 4139-298-038	120795
143	10/03/2006	122982	FILTER OIL K124 / L94UAB	120795
143	10/03/2006	122982	Tension ALL Wheel Nuts to OEM Specs	120795
143	10/03/2006	122982		120795
143	09/29/2006	122653	Drv entered - Vandalism Damaged Seat	120643
143	09/29/2006	122653	WATER PUMP SCANIA L94UAB	120643
143	09/28/2006	122653	Scrapping noise from turntable cover	120643
143	09/28/2006	122653	FRONT AIR BAG SCANIA L94UAB	120643
143	09/28/2006	122653	REAR AIR BAG (DRIVE AXLE) SCANIA L94UAB	120643
143	09/28/2006	122653	Air bag leaking front and rear	120643
143	09/28/2006	122653	Replace water pump	120643
143	09/20/2006	122173	Drv entered - Elec & Light Interior Lights	120291
143	09/20/2006	122173	GLOBE INDICATOR 24V21W SINGLE CONTACT	120291
143	09/20/2006	122173	LIGHT DIFFUSER 3M LENGHT	120117
143	09/20/2006	122173	Drv entered - Elec & Light Interior Lights	120117
143	09/20/2006	122173	Interior light cover broken	120117
143	09/18/2006	121926	Fit wear plate on turntable floor	119665
143	09/14/2006	121770	CRANK TO PULLEY SCANIA 21/32X67	119452
143	09/14/2006	121770	FAN BELT A/CON ARTIC 21/32X45	119452
143	09/14/2006	121770	BELT ALT W/PUMP CRANK SCANIA ARTIC	119452
143	09/14/2006	121770	SCANIA ALT BELT ROLLER(METAL) K1241B+L94UAB	119452
143	09/14/2006	121770	Breakdown - Mentone St. OUT 7.00 am BACK 11.00 am. Alternat	119452
143	09/07/2006	121000	REPAIR ELEC PROBLEM	118577
143	09/05/2006	121000	Bus wont start	118270
143	09/04/2006	121000	Bus wont start	118270
143	09/04/2006	121000	RELAY HIGH CAPACITY	118270
143	09/01/2006	120888	REP. LIGHT TUBE	118017
143	08/31/2006	120262	REPAIR S/MOTOR	117854
143	08/24/2006	120262	Service	117013
143	08/23/2006	119673	POS 4+7+8+10	116775
143	08/23/2006	120257	Replace interior light globe	116775
143	08/16/2006	119673	Replaced tyres pos. 10487. Bald	115784
143	08/16/2006	119707	Change tyre pos 4-3 7-8 9-10	115784
143	08/16/2006	119636	Replace drive axle tyres	115784
143	08/16/2006	119620		115784
143	08/16/2006	119620	Tension ALL Wheel Nuts to OEM Specs	115784
143	08/16/2006	119620		115784
143	08/16/2006	119620	Tension ALL Wheel Nuts to OEM Specs	115784
143	08/10/2006	119121	Air in fuel system	114528
143	08/10/2006	119121	O-RING VIPS FITTING	114696
143	07/28/2006	118242	INDICATOR LIGHT FRONT ARTIC	113135
143	07/28/2006	118242	Broken indicator cover n/s/f	113135
143	07/25/2006	117998	Lock on cabin door	112598
143	07/20/2006	117632	Breakdown at Dandy St. Bus wont go	112136
143	07/18/2006	117518	SCANIA STARTER MOTOR K93+L94	112821
143	07/18/2006	117518	Checked & found possible fault with starter motor	112821
143	07/11/2006	116914		110466
143	07/11/2006	116914		110466
143	07/11/2006	116914		110466
143	06/29/2006	115405	Turntable light on	109542
143	06/26/2006	115616	SPEEDO SENDER	108992
143	06/23/2006	115616	Service	108992
143	06/22/2006	115651	Replaced tyre pos. 1 unevean wear	108992
143	06/22/2006	115616	Replace speedo sender	108992
143	06/22/2006	115617	Breakdown - Dandy Nth.warning light came on for suspension	108992
143	06/20/2006	115405	Check turntable - light on	108869
143	06/19/2006	115354	Breakdown - Jack knife light on Dandy Sth. Greens Rd./ Hamm	108869

143	06/16/2006	114777	Service	o/haul starter motor	107938
143	06/16/2006	115237	Wont start	removed and fit starter motor	108698
143	06/15/2006	115177	Engine wont start - possible elect fault.		108544
143	06/15/2006	115177	Wont start	Rear switch was off	108544
143	06/08/2006	114777	STARTER DRIVE SUIT JF	Creditor #:PJL001 PJL DIESEL ELECTRIC P/O #:32560 Receiving #:32596 Date :2006-06-08	107938
143	06/08/2006	114777	Service	o/haul starter	107938
143	06/07/2006	114737	SCANIA STARTER MOTOR K93+L94		107781
143	06/07/2006	114737	Service	assist with reapears	107938
143	06/07/2006	114737	Replaced starter motor.	rep. starter motor	107781
143	06/06/2006	114395	ROAD SAFETY INSPECTIONS	Creditor #:ROA001 Road Safety Inspections P/O #:32448 Receiving #:32549 Date :2006-06-06	107781
143	06/04/2006	114395	Annual Inspection -	Annual Inspection -	107141
143	06/02/2006	107031	Service	r/r.thermo fan switch replaced switches & r/tested	107141
143	06/02/2006	107031	HYD T/STAT	Creditor #:BAN001 BANLAY PTY LTD P/O #:32388 Receiving #:32457 Date :2006-06-02	107141
143	06/02/2006	107031	SCREW HAND CLAMP(P/N 280010)		107141
143	06/01/2006	107031	Service	r/r.thermostats & refilled coolant checked & found fan in operation full timeordered parts	107141
143	05/30/2006	107031	GLOBE FESTOON 24V-3W		106866
143	05/30/2006	107031	gasket	Creditor #:BAN001 BANLAY PTY LTD P/O #:32260 Receiving #:32296 Date :2006-05-30	106866
143	05/30/2006	107031	temostat	Creditor #:BAN001 BANLAY PTY LTD P/O #:32260 Receiving #:32296 Date :2006-05-30	106866
143	05/29/2006	107031	Service	R/TESTED & ORDERED PARTS	106866
143	05/29/2006	113783	Service	polished & touched up	106866
143	05/29/2006	113806	Service	repainted side panel	106866
143	05/26/2006	113251	POS 9	Creditor #:BEA001 BEAUREPAIRES P/O #:32061 Receiving #:32226 Date :2006-05-26	106866
143	05/26/2006	113769	Cracked 'v' bar bush.	Checked ok serviceable	106692
143	05/26/2006	113769	Oil leaks at engine sump	Repair oil at rocker covers	106692
143	05/26/2006	113769	ROCKER COVER GASKET L94UAB		106866
143	05/26/2006	113769	Steam clean for inspection	Steam clean	106692
143	05/26/2006	113769	Oil leaks at engine sump	Redirect air sepearter exhaust pipe	106692
143	05/26/2006	113769	Coolant leaks at all 3 boost pumps - 2 n/s/r and 1 o/s/r	Reseal all pipes on n/s/r boost pumps	106692
143	05/26/2006	113769	Coolant leaks at hose between gear box and chassis	repaired o/k.	106692
143	05/26/2006	113769	Oil leaks at diff pinion seal	checked o/k.	106692
143	05/26/2006	113783	Polish exterior panels headers and touch up	polished & touched up	106692
143	05/26/2006	113783	REAR MARKER DECAL R/H		106866
143	05/26/2006	113783	REAR MARKER DECAL L/H		106866
143	05/26/2006	113783	Paint rear bumper bar	touched up	106692
143	05/26/2006	113783	Replace marker plates	replaced decals	106692
143	05/26/2006	113783	Polish front bumper bar	polished & toused up	106692
143	05/26/2006	113783	Secure paint exterior mirrors and arms	repainted	106692
143	05/25/2006	113769	BOOST PUMP EXCHANGE		106692
143	05/25/2006	113769	Coolant leaks from header tank hose	checked o/k.	106692
143	05/25/2006	113769	Raditor guard broken	checked o/k.	106692
143	05/25/2006	113783	Paint till stand		106692
143	05/25/2006	113783	Fit fleet number on dash - yellow		106692
143	05/25/2006	113783	Clean wheel chair ramp - check sensor for operation		106692
143	05/25/2006	113783	Clean a/c filter		106692
143	05/25/2006	113783	Clean and paint wheels	repainted wheels	106692
143	05/25/2006	113783	Secure all lower skit panels		106692
143	05/25/2006	113769	Remove rear wheels for brake pad inspections.	checked o/k.	106692
143	05/25/2006	113769	External air supply fitting need to be replaced & set at di	repositioned air line fittings	106692
143	05/25/2006	113806	Right rear panel lower got hit round about @ Mentone		106692
143	05/25/2006	113806	Accident damage - Repair and paint o/s panel no 3 replace	replaced o/s. lower panel	106692
143	05/25/2006	113806	2MM X 1200MM X 2400MM FLAT ALUMINIUM		106692
143	05/18/2006	113251	Replace pos 9 tyre - bald	REP. TYRE	105907
143	05/18/2006	113265	ON/OFF SWITCH 10AMP		105907
143	05/18/2006	113265	SCANIA DIP STICK L94UAB		105907
143	05/18/2006	113265	A SERVICE		105907
143	05/18/2006	113265		Tension ALL Wheel Nuts to OEM Specs	105907
143	05/18/2006	113265	A SERVICE		105907
143	05/17/2006	113049	Service	REP. ALTERNATOR BELTS & PULLEYS	105907
143	05/17/2006	113049	REFITTED ALL HOSES ETC	REFITTED HOSES ETC. -AFTER ADJ. TAPPETS	105907
143	05/17/2006	113303	REPLACED O/S/R TYRE.	rep. o/s/r tyre	105907
143	05/17/2006	113303	REPLACED O/S/R TYRE.	rep. o/s/r tyre	105907
143	05/17/2006	112503	PARK BRAKE	Creditor #:MUL001 MULTISPARES LTD P/O #:31832 Receiving #:32009 Date :2006-05-17	105907
143	05/16/2006	113049	FILTER AIR DRYER KIT(HALDEX)		105660
143	05/16/2006	113049	HYDRAULIC FILTER L94UAB		105660
143	05/16/2006	113049	FILTER FUEL K124 / LU94A		105660
143	05/16/2006	113049	FILTER FUEL SCANIA L94UAB		105660
143	05/16/2006	113049	POWER STEER FILTER B10M		105660
143	05/16/2006	113049		Replace air dryer cansiter	105660
143	05/16/2006	113049		Replace hydraulic fan filter and top up oil	105660
143	05/16/2006	113049		Rekit quick release valve	105660
143	05/16/2006	113049		Replace power steering filter	105660
143	05/16/2006	113049		Inspect bus as per inspection sheet	105660
143	05/16/2006	113049		Adjust valve clearances	105660
143	05/16/2006	113049	BELT ALT W/PUMP CRANK SCANIA ARTIC		105736
143	05/16/2006	113049	Pully Idler Scania Artic (No Grove Plastic)		105736
143	05/16/2006	113049	SCANIA ALT BELT TENSIONER K1241B		105736
143	05/16/2006	113049	LENS TO SUIT 2557 LAMP		105736
143	05/16/2006	113049	STOP LAMP LENS		105736
143	05/16/2006	113049	GLOBE S/CONTACT 24V-10W		105736
143	05/16/2006	113049		Clean a/c filters	105660
143	05/16/2006	113049		Replace coolant filter in engine cooling system	105660
143	05/16/2006	113049	RPM BORATE EP LUBE 220		105660
143	05/16/2006	113049		Replace fuel filters	105660
143	05/16/2006	113049		Adjust valve clearances	105660
143	05/16/2006	113049		Replace final drive oil	105660
143	05/10/2006	112503	GLOBE STOP AND TAIL 24V 21/5W		104742
143	05/10/2006	112503	Service	REP. HAND BRAKE VALVE	104742
143	05/09/2006	112559	Annual body check	check list completed	104742
143	05/09/2006	112503	Passenger seat nio o/s - loose and also needs end cap	SECURED SEATS	104567
143	05/09/2006	112503	Hand brake valve leaks when released	HAND BRAKE VALVE LEAKS OCCASIONALY	104567
143	05/09/2006	98174	Direct Purchase - BODYWORK	Creditor #:ATT001 ATTITUDE SIGNS P/O #:27230 Receiving #:31775 Date :2006-05-09	104742
143	05/05/2006	112379	GLOBE INDICATOR 24V21W SINGLE CONTACT		104384
143	05/05/2006	112379	Replaced globe	rep. globe	104384

143	04/20/2006	111369	Indicator u/s	Checked ok	102828
143	04/19/2006	111203	No broom in bus	Supply broom	102646
143	04/12/2006	110908	Front left side pass. buzzer not working	checked o/k.all works	102381
143	04/12/2006	111001	Breakdown no engine power took c/o. bus No 9. Heaterton Rd	c/o. bus returned to depot & CHECKED FAULT CODES has possible E.C.U DEFECT.	102381
143	04/05/2006	110471	Eng. oil filler cap cracked	rep. oil filler cap.	101539
143	04/05/2006	110495	Sticker - no exit - missing on rear door	fitted decal	101539
143	04/04/2006	110339	Rear top O/S. Park light out.	Replaced park light globe	101345
143	04/03/2006	110249	Bell not working	repaired o/k.	101163
143	04/03/2006	110223	PLASTIC OIL FILLER CAP	Creditor #:BAN001 BANLAY PTY LTD P/O #:31070 Receiving #:31137 Date :2006-04-03	101163
143	04/03/2006	110223	FLASHER RELAY SUIT SCANIA K124IB		101163
143	04/03/2006	110223		Tension ALL Wheel Nuts to OEM Specs	101163
143	04/03/2006	110223		D Service	101163
143	04/03/2006	110223	TEXAMATIC 1888		101163
143	04/03/2006	110223	ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL		101163
143	04/03/2006	110223	FILTER AIR SCANIA USE AF25066		101163
143	04/03/2006	110223	FILTER TRANSMISSION ZF 4139-298-038		101163
143	04/03/2006	110223	FILTER OIL K124 / L94UAB		101163
143	04/03/2006	110223	O RING FILTER KIT K93		101163
143	04/03/2006	110223		Tension ALL Wheel Nuts to OEM Specs	101163
143	04/03/2006	110223		D SERVICE	101163
143	03/29/2006	109963	Mein compressore belt cracked	replace A/C belt	95777
143	03/29/2006	109963	BELT ALT W/PUMP CRANK SCANIA ARTIC		95777
143	03/29/2006	109963	FAN BELT A/CON ARTIC 21/32X45		95777
143	03/29/2006	109963	CRANK TO PULLEY SCANIA 21/32X67		95777
143	03/29/2006	109963	Front indicator light broken	Replace indicator light	95777
143	03/29/2006	109963	Alternator belt cracked	Replace alternator belt	95777
143	03/29/2006	109963	INDICATOR LIGHT FRONT ARTIC		95777
143	03/17/2006	108264	FIT CAP	Creditor #:BEA001 BEAUREPAIRES P/O #:30399 Receiving #:30692 Date :2006-03-17 POS 3 + 4	95777
143	03/06/2006	108264	Replace tyres pos. 3 - 4	Replace tyres pos. 3 - 4	95447
143	03/03/2006	108021	GLOBE+HOLDER INSTRUMENT		95447
143	03/03/2006	108021	Service	repaired o/k.	95447
143	03/03/2006	108021	Service	all checks completed	95447
143	03/03/2006	108176	Replaced n/s/r middle tyres.	rep. tyres	95447
143	03/03/2006	108132	A/C not blowing cold air - Front temp. 33. - Rear temp.29.d	checked all system cooled from inside temp. of 43.5 to 22.5 degrees in about 40 minutes. *all o/k.	95447
143	03/02/2006	108041	D HANDLE LENLOCK CHROME PLATED		95447
143	03/02/2006	108041	Pre- trip body checks exterior & interior .	checked over as required.	95447
143	03/02/2006	108021	Pre - trip safety checks.	CHECKS AS REQUIRED	95447
143	03/02/2006	108043		A service	95447
143	03/02/2006	108043		Tension ALL Wheel Nuts to OEM Specs	95447
143	02/27/2006	107855	Front A/C unit U/S	Reclaim and recharge front unit	94897
143	02/23/2006	106972	Service		94869
143	02/23/2006	106972	Service	checked on charge found left bank not working traced fault to relay rep. relay & finished all pipe work & alternators run up front unit need attention.	94869
143	02/22/2006	106972	Service	replaced a/. align & modify compressorpressure test system .vac down system leave down leave o/night onvac. checked o/k.	94869
143	02/22/2006	106972	ZEXEL COMP (DKS-32-2B)	Creditor #:AIR002 AIR INTERNATIONAL TRANSIT P/O #:30065 Receiving #:30239 Date :2006-02-22	94869
143	02/20/2006	106972	Service	DROP OFF BUS AT VOLGREN FOR SEAT REPAIRS.	94869
143	02/17/2006	106972	AIR CON REFRIDGERANT		94869
143	02/17/2006	106972	Rear A/C fault light on	Replace both sunction hoses - Fitted both alternators - repaired fitting atcopper pipe - Removed belts to bus can be removedRemove clutch plite - prepare assembly	94869
143	02/16/2006	106972	Rear A/C fault light on	Replace both sunction hoses - Fitted both alternators - repaired fitting at copper pipe - Removed belts to bus can be removed	94533
143	02/15/2006	106972	Rear A/C fault light on	Removed n/s. compressorsuction hose attempted to remove r/h. bank suction hose.	94533
143	02/15/2006	107031	O/S/ head light sems to be on high beam	Checked temp. gauge still not working	94699
143	02/15/2006	107031	Engine temp. gauge stuck on 60	Adjust O/S headlight	94699
143	01/27/2006	105700	FAN BELT A/CON ARTIC 21/32X45		92509
143	01/27/2006	105700	Both main compressor belts cracked		92509
143	01/18/2006	105229	LENS TO SUIT 2029 (RED+AMBER)		91690
143	01/18/2006	105229	GLOBE FESTOON 24V5W		91690
143	01/18/2006	105229	O/S/R parker light lens broken	Replace O/S/R/ parker light lens and globe	91690
143	01/16/2006	105076	GLOBE FESTOON 24V-3W		91467
143	01/16/2006	105076	Exit light U/S	Replace two globes	91467
143	01/12/2006	104714	Split o/s trailer stabilizer bar ball joint boot cracked	Checked ok	90912
143	01/12/2006	104714	DISC PADS SCANIA		91113
143	01/12/2006	104714	N/S/F brake pads low	Replace front pads	90912
143	01/05/2006	104353		Tension ALL Wheel Nuts to OEM Specs	90273
143	01/05/2006	104353			90273
143	12/16/2005	101685	POS 6	Creditor #:BEA001 BEAUREPAIRES P/O #:28499 Receiving #:29081 Date :2005-12-16 FIT GBS TYRE	87536
143	12/13/2005	103157	Loosing air no safe to drive	repaired air line on o/s.	87207
143	12/13/2005	103157	5/16inch AIR LINE JOINER		87207
143	12/05/2005	102524	Raise & tilt switches diagrams worn off.	Fit labels	86272
143	12/05/2005	102598	Flat batteries	Replace batteries	86272
143	12/05/2005	102598	Flat batteries		86272
143	12/02/2005	102484	Replace interior light	Replace globe	86192
143	11/25/2005	101906	Replace safety hammers	replaced 3 x hammers	85481
143	11/25/2005	101828	DISC PADS SCANIA		85560
143	11/25/2005	101916	Accident damage no 9628 - Poilsh front door (Checked on 12/	polished & touched up	85481
143	11/25/2005	101916	Accident Damage o/s/f. corner.(Checked on 17/8/0512/10/05	repaired & repainted	85481
143	11/25/2005	101916	O/S. Front bumper bar damaged	polished & touched up	85481
143	11/24/2005	101845	Service	ASSIST WITH REPAIRS	85481
143	11/24/2005	101845	EXTINGUISHER FIRE 2.2K REFILL		85481
143	11/24/2005	101845	Service	REFITTING HAMMERS	85481
143	11/24/2005	101845	EMERGENCY HAMMERS		85481
143	11/24/2005	101845	Replace emergency hammers & fire extinguisher.	replaced hammer & emergency fire extinguisher	85481
143	11/24/2005	101828	Remove centre axle wheels & check disc pad thickness.	replaced mid axle disc pads & retorqued w/nuts	85481
143	11/23/2005	101685	MICHELIN RECAP 275-70R 22.5		85370
143	11/23/2005	101685	Replaced tyre pos. BALD.		85370
143	11/22/2005	101615	Service	A SERVICE	85196
143	11/22/2005	101615	AIR FILTER SCANIA CLEANED		85196
143	11/22/2005	101615		Tension ALL Wheel Nuts to OEM Specs	85196
143	11/22/2005	101615		A SERVICE	85196
143	11/15/2005	101167	Head lights staying oneven when switched off.	checked fouind relay sticks	84314
143	11/15/2005	101167	Service	reposition fuse of h/beam.	84314
143	11/11/2005	100948	A/C. Vents above driver not blowing cold air	Reset curcuit breaker and road test	83893
143	11/11/2005	100948	Right hand side rear clearance light above wheel out.	Replace o/s/r indiator lens and n/s/f	83893
143	11/11/2005	100948	GLOBE FESTOON 24V5W		83893
143	11/11/2005	100948	LENS TO SUIT 2030 LAMP		83893

143	11/11/2005	100948 LENS TO SUIT 2029 (RED+AMBER)				83893
143	11/03/2005	100375 Front unit - remove and replace shaft seal and top up refri	Replace shaft seal			83038
143	11/03/2005	100256	DRIVE PULLEY'S: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear			83038
143	11/03/2005	100256	DRIVE PULLEY'S: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;			83038
143	11/03/2005	100256	INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condensor fan grills			83038
143	11/03/2005	100256	EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check boltsclamps & fittings; clean condensate drains; clean drip tray			83038
143	11/03/2005	100256	REFRIGERATION FILTER DRYER: Replace filter dryer; check pump operation;			83038
143	11/03/2005	100256	COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose			83038
143	11/03/2005	100256	UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensor pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation			83038
143	11/03/2005	100256 SHAFT SEAL ASS BOCK FK40				83038
143	11/03/2005	100256	COMPRESSOR DRIVE BELTS: Inspect belt wear; Retension belts;			83038
143	11/03/2005	100256	FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)			83038
143	11/03/2005	100256	Clean R/A & F/A filters; Inspect and report on condition; Replace filter media			83038
143	11/03/2005	100256	CONDENSOR AREA: Clean condensor coils; check boltsclamps for tension			83038
143	11/03/2005	100256 FILTER DRIER 5/8				83038
143	11/03/2005	100256 DASH PANEL ROUTE BUS				83038
143	11/03/2005	100256 AIR CON REFRIDGERANT				83038
143	10/28/2005	100042 BELT ALT W/PUMP CRANK SCANIA ARTIC				82510
143	10/28/2005	100042 REPLACED ALTERNATOR BELTS.	REPLACED ALT. BELTS.			82510
143	10/26/2005	98877 POS 9	Creditor #:BEA001 BEAUREPAIRES P/O #:27630 Receiving #:27915 Date :2005-10-26			82344
143	10/17/2005	99098 GLOBE FESTOON 24V-3W				81094
143	10/15/2005	99098 Replaced exit globe.	rep. globe			81094
143	10/13/2005	98877 Replace tyres position - 9 - 10 - bald. Odometer - 80651.				80476
143	10/12/2005	98853 ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL				80476
143	10/12/2005	98853 AIR FILTER SCANIA CLEANED				80476
143	10/12/2005	98853 O RING FILTER KIT K93				80476
143	10/12/2005	98853 FILTER TRANSMISSION ZF 4139-298-038				80476
143	10/12/2005	98853	Tension ALL Wheel Nuts to OEM Specs			80476
143	10/12/2005	98853	D Service			80476
143	10/12/2005	98853 TEXAMATIC 1888				80476
143	10/12/2005	98853 FILTER OIL K124 / L94UAB				80476
143	10/12/2005	98853				80476
143	10/12/2005	98853	Tension ALL Wheel Nuts to OEM Specs			80476
143	10/10/2005	98727 Yellow line inside the bus rip off.	Re-fitted yellow strip.			80152
143	09/30/2005	98174 3MM X 1200MM X 2400MM FLAT ALUMINIUM				79380
143	09/30/2005	98174 Accident damage o/s/r. lower panels.	repaired & repainted all panels as required.			79380
143	09/29/2005	98174 Accident damage O/S/R. Lower panels No 10 & 11 . Replace no	manufacture no 11 lower panel			79380
143	09/21/2005	97467 O/S indicator u/s.	Replaced o/s indicator light globe.			78340
143	09/20/2005	97443 GLOBE FESTOON 24V5W				78340
143	09/20/2005	97443 Replace o/s clearance & indicator lamp.	Replaced o/s clearance & indicator lamp.			78340
143	09/20/2005	97443 LAMP INDICATOR [ORANGE]				78340
143	09/20/2005	97443 LAMP (RED+AMBER)				78340
143	09/20/2005	97386 2.5MM X 1200MM X 2400MM FLAT ALUMINIUM				78340
143	09/20/2005	97386 ACCIDENT DAMAGED O/S/R. LOWER PANELS. * Temporary repaired.	Temporary repaired o/s/r lower panel.			78340
143	08/23/2005	95615 replaced interior tube.				74971
143	08/17/2005	95178				74391
143	08/17/2005	95178 LENS TO SUIT 2029 (RED+AMBER)				74391
143	07/08/2005	92532				69438
143	07/05/2005	91495 WARRANTY	Creditor #:BAN001 BANLAY PTY LTD P/O #:25296 Receiving #:25531 Date :2005-07-05 RECALL FOR WARRANTY			69087
143	06/22/2005	91495 Campain Recall - TC041131- Tension centre axle bolts				67865
143	06/22/2005	91495 Campain Recall TC30932 - Rear wheel bearing procrection she				67865
143	06/22/2005	91495 Campgain Recall - RA030931 - Replace rear wheel bearings				67865
143	06/18/2005	91294 Repair water leak at sight glass.	Repaired water leak at sight glass.			67181
143	06/10/2005	90849 Fit turntable locking rubber	Fitted turn table rubber.			66443
143	06/07/2005	90066 ROAD SAFETY INSPECTION	Creditor #:ROA001 Road Safety Inspections P/O #:24844 Receiving #:24949 Date :2005-06-07			65730
143	06/05/2005	90066 Annual Inspection - BC 081273	Annual Inspection - BC 081273			64793
143	06/03/2005	89394 REPLACE DECALS	Creditor #:ATT001 ATTITUDE SIGNS P/O #:24748 Receiving #:24899 Date :2005-06-03			65287
143	06/02/2005	90236 EMERGENCY EXIT BUTTON PULL COVER				65207
143	06/02/2005	90236				65207
143	05/26/2005	89509 Touch up paint work.	Touchet up paint work.			64283
143	05/26/2005	89509 Secure all lower skit panels.	Secured all lower skit panels.			64283
143	05/26/2005	89509 Polish headers.	Polished headers.			64283
143	05/26/2005	89509 Replace air supply decal.	Replaced air sypply decal.			64283
143	05/26/2005	89509 Replace front door seals.	Replaced front door seals.			64283
143	05/26/2005	89509 Paint wheels.	Painted wheels.			64283
143	05/26/2005	89809 RUBBER BOOT FOR AIR LINE ON BUS				64283
143	05/26/2005	89809 Fit external air supply line.	Fitted external air supply line.			64283
143	05/26/2005	89509 AIR LINE COUPLING FOR AIR SYSTEM				64283
143	05/26/2005	89394 Accident damage / no number / n/s front top corner anddes	Repaired n/s/f top corner f/glass.			64283
143	05/26/2005	89394 N/S front body damage. Checked on 19/4/05 serviceable HKS	Repaired n/s front body.			64283
143	05/26/2005	89394 Accident damage / no number / n/s front top corner anddes	Repaired n/s/f top corner f/glass.			64283
143	05/25/2005	89394 O/S rea body damaged. Checked on19/4/05 serviceable HKS	Repaired o/s rear body.			64283
143	05/25/2005	89394 Repair & paint n/s panels - 7 - 9 - 10.	Repaired panels 7 - 9 - 10.			64283
143	05/25/2005	89394 Accident damage / no number / n/s front top corner anddes	Repaired n/s/f top corner f/glass.			64283
143	05/25/2005	89394 Accident damage / no number / n/s front top corner anddes	Repaired n/s/f top corner f/glass.			64283
143	05/25/2005	89643 SCRATCHES	Creditor #:KNI001 KNIGHTS WINDSCREEN REPAIRS P/O #:24712 Receiving #:24664 Date :2005-05-25			64283
143	05/25/2005	89643 Poilsh side windows				64283
143	05/24/2005	89509 Paint till stand.	Painted till stand.			64283
143	05/24/2005	89509 Paint wheels.	Painted wheels.			64283
143	05/24/2005	89509 Polish front bumper bar.	Polished front bumper bar.			64283
143	05/24/2005	89509 Clean A/C filter.	Cleaned A/C filter.			64283
143	05/24/2005	89509 Replace drivers seat decal.	Replaced drivers seat decal.			64283
143	05/24/2005	89509 Replace fleet number on dash - in Yellow.	Replaced fleet number on dash - in yellow.			64283
143	05/24/2005	89509 Secure front doordash hand rails & drivers guard.	Secured front doordash hand rails 7 drivers guard.			64283
143	05/24/2005	89394 Repair & paint n/s panels - 7 - 9 - 10.	Repaired panels 7 - 9 - 10.			64283
143	05/24/2005	89394 Repair & paint n/s panels - 7 - 9 - 10.	Repaired panels 7 - 9 - 10.			64283
143	05/23/2005	89421 "V " bar bush above diff cracked	Checked " V " bar bush o/k.			64283
143	05/23/2005	89421 Coolant leaks around boost pump.	Replaced boost pump.			64283
143	05/23/2005	89421 Coolant leaks around boost pump.	Replaced boost pump.			64283
143	05/23/2005	89421 Slight leak around bell housing.	Checked bell housing for oil leak o/k.			64283
143	05/23/2005	89421 Steam clean for inspection.				64283
143	05/23/2005	89421 Check thickness of middle axle brake peds.	replaced middle axle brake peds.			64283
143	05/23/2005	89421 Air leak around air dryer.	Repaired air leak at air dryer.			64283

143	05/23/2005	89421	Air leak around air dryer.	Repaired air leak at air dryer.	64283
143	05/23/2005	89394	Accident damage / no number / n/s front top corner anddes	Repaired n/s/f top corner f/glass.	64283
143	05/23/2005	89373	DESTO GLASS	Creditor #::ELI001 ELITE WINDSCREENS P/O #:24608 Receiving #:24561 Date :2005-05-23	64283
143	05/20/2005	89394	Accident damage / no number / n/s front top corner anddes	Repaired n/s/f top corner f/glass.	64283
143	05/20/2005	89373	Replace destination glass		64283
143	05/18/2005	89188		Replace hydraulic fan filter and top up oil	64013
143	05/18/2005	89188		Replace power steering filter	64013
143	05/18/2005	89188		Replace final drive oil	64013
143	05/18/2005	89188		Replace fuel filters	64013
143	05/18/2005	89188		Inspect bus as per inspection sheet	64013
143	05/18/2005	89188		Clean a/c filters	64013
143	05/18/2005	89188		Replace coolant filter in engine cooling system	64013
143	05/18/2005	89188	RPM BORATE EP LUBE 220		64013
143	05/18/2005	89188	FILTER OIL GEARBOX DIFF K124		64013
143	05/18/2005	89188	FILTER AIR DRYER KIT(HALDEX)		64013
143	05/18/2005	89188		Rekit quick release valve	64013
143	05/18/2005	89188	HYDRAULIC FILTER L94UAB		64013
143	05/18/2005	89188		Adjust valve clearances	64013
143	05/18/2005	89188	FILTER FUEL K124 / LU94A		64013
143	05/18/2005	89188	FILTER FUEL SCANIA L94UAB		64013
143	05/18/2005	89188	POWER STEER FILTER B10M		64013
143	05/18/2005	89188		Replace air dryer cansiter	64013
143	05/18/2005	89199	Annual body check	CHECKED LIST COMPLETED	64013
143	05/10/2005	88601	Rear door sticking.	Checked all doors o/k.	62963
143	04/26/2005	87669	GLOBE STOP AND TAIL 24V 21/5W		61186
143	04/26/2005	87669	GLOBE STOP AND TAIL 24V 21/5W	Replaced stop light globe.	61186
143	04/23/2005	87551	Replace dash light globe.	Replaced dash light globe.	61004
143	04/22/2005	87534	Front door has trouble opening.	Repaired & lubricated front door.	61004
143	04/20/2005	87307	1 st a/c. unit not working	Checked A/C - road tested working o/k.	60661
143	04/20/2005	87307	GLOBE FESTOON 24V-3W		60661
143	04/19/2005	87186	O RING FILTER KIT K93		60486
143	04/19/2005	87186	TEXAMATIC 1888		60486
143	04/19/2005	87186	ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL		60486
143	04/19/2005	87186	FILTER AIR SCANIA USE AF25066		60486
143	04/19/2005	87186	FILTER TRANSMISSION ZF 4139-298-038		60486
143	04/19/2005	87186		D Service	60486
143	04/19/2005	87186	FILTER OIL K124 / L94UAB		60486
143	04/19/2005	87186			60486
143	03/31/2005	85895	Paint wheels as required.	Painted trailer wheels	58377
143	03/31/2005	85901	FAN BELT A/CON ARTIC 21/32X45		58377
143	03/31/2005	85901	Belt tensioner pulley bush collapsed	Replaced pulley bushes	58377
143	03/23/2005	85247	SENSITIVE EDGE DOOR SWITCH		57813
143	03/19/2005	83806	POS 1	Creditor #::BEA001 BEAUREPAIRS P/O #:22826 Receiving #:23187 Date :2005-03-19 FIT GBS STOCK RETURN OLD CASE	57311
143	03/19/2005	83806	POS 7 & 9 & 10	Creditor #::BEA001 BEAUREPAIRS P/O #:22826 Receiving #:23187 Date :2005-03-19 FIT GBS STOCK RETURN OLD CASE	57311
143	03/18/2005	85247	Middle door sensitive edge u/s.	replaced rear door sensitive switch	57311
143	03/02/2005	84198	Horn not working.	Checked horn o/k.	55635
143	03/02/2005	84198	Fit n/s reflector.	Fitted n/s reflector.	55635
143	03/02/2005	84198	AMBER REFLECTOR SIDE MOUNT		55635
143	03/02/2005	84198	Graffiti on back seat.	No graffiti.	55635
143	03/02/2005	84198	D HANDLE LENLOCK CHROME PLATED		55635
143	03/01/2005	78882	MAKE WEDGE TO SKETCH		55483
143	02/24/2005	83806	Replaced tyres Pos. 1 flat spots 78910. BALD.	Creditor #::TQS001 TIME+QUALITY SERVICES P/O #:22828 Receiving #:22833 Date :2005-03-01	54974
143	02/24/2005	83806	MICHELIN TYRE 275-70R 22.5		54974
143	02/24/2005	83806	MICHELIN RECAP 275-70R 22.5		54974
143	02/23/2005	83738	Annual random audit	Checked	54794
143	02/23/2005	83737			54794
143	02/23/2005	83737	AIR FILTER SCANIA CLEANED		54794
143	01/31/2005	53638	AIR CONDITIONING REPAIR	Creditor #::REA002 READ RITE PTY LTD P/O #:13741 Receiving #:22187 Date :2005-01-31	52238
143	01/31/2005	67604	AIR CONDITIONING REPAIR	Creditor #::REA002 READ RITE PTY LTD P/O #:17647 Receiving #:22205 Date :2005-01-31	52238
143	01/31/2005	69938	AIR CONDITIONING REPAIR	Creditor #::REA002 READ RITE PTY LTD P/O #:18305 Receiving #:22193 Date :2005-01-31	52238
143	01/25/2005	81773	Service	ASSIST	51684
143	01/25/2005	81773	Service	REPAIR COOLANT LEAK NEAR BOOST PUMP.	51684
143	01/21/2005	81773	Took 8 liters of coolant	checked found heater tap leaking at boost pump.	51396
143	01/15/2005	81409	GLOBE STOP AND TAIL 24V 21/5W		50533
143	01/15/2005	81409	Near side brake light out	replaced globe	50533
143	01/10/2005	81045	Service		49961
143	01/10/2005	81045			49961
143	12/29/2004	78882	CONSUMABLE DELIVERY CHARGE		
143	12/21/2004	78882	CONSUMABLE DELIVERY CHARGE		
143	12/20/2004	78882	Remove power steering box for repairs - steering hard when		48095
143	12/17/2004	78882	Remove power steering box for repairs - steering hard when	Refitted steering box.	48095
143	12/17/2004	78882	CHECK AND REPORT	Creditor #::DAY001 DAYSWORTH INTERNALTIONAL P/L P/O #:21261 Receiving #:21407 Date :2004-12-17	
143	12/17/2004	78882	SCANIA ALT BELT TENSIONER K1241B		48095
143	12/01/2004	78882	Remove power steering box for repairs - steering hard when	Removed steering box.	48095
143	12/01/2004	77461	STEERING	Creditor #::BAN001 BANLAY PTY LTD P/O #:21027 Receiving #:21108 Date :2004-12-01	
143	11/30/2004	78882	Remove power steering box for repairs - steering hard when	Removed steering box.	48095
143	11/23/2004	77461	SWAY BAR LINK SUIT L94UAB SC	Creditor #::BAN001 BANLAY PTY LTD P/O #:21004 Receiving #:20868 Date :2004-11-23	
143	11/22/2004	77461	Steering heavy.	Checked front end & steering.	48095
143	11/18/2004	78110	A/C not working.	Checked & cleaned A/C filter.	47748
143	11/12/2004	77650	Inspection wiring harness in turntable for damage and repai	Inspected by Volgren	47348
143	11/10/2004	77461	Steering heavy.	Checked front end & steering.	46938
143	11/06/2004	77285	Clunks under front end.	Checked & cuted up front mud guards.	46568
143	11/01/2004		0 Imported Service History	Imported Service History	0
143	10/26/2004	76149	HUB SEAL SUIT MID AXLE SCANI	Creditor #::BAN001 BANLAY PTY LTD P/O #:20381 Receiving #:20263 Date :2004-10-26 BUS 143	
143	10/22/2004	76149	Oil leak at power steering box.	Repaired oil leak at power steering box.	45099
143	10/22/2004	76341	Steam clean - road test & check for coolant leak.	Steam cleaned - road tested & checked for coolant leak o/k.	45231
143	10/22/2004	76149	O/S middle axel hub seal is leaking	Replaced middle axle hub seal	45231
143	10/22/2004	76328	Replace driver's seat base with 200mm box	Replaced passengers seat i turntable.	45231
143	10/21/2004	76271	Repair coolant leak from booster pump.	Repaired coolant leak from booster pump.	45231
143	10/21/2004	76149	O/S middle axel hub seal is leaking	Removed middle axle hub & clean parts	45099
143	10/20/2004	76149	O/S middle axel hub seal is leaking	Removed middle axle hub	45099
143	10/19/2004	76101	Replace step light lens & number plate lens.	Replaced step light lens & number plate light lens.	45099
143	10/19/2004	75932	DOOR LATCH NO KEY		45099

143	10/19/2004	75932	LENS TO SUIT 2557 LAMP		45099
143	10/19/2004	75932	GLOBE S/CONTACT 24V-10W		45099
143	10/19/2004	75932	LENS TO SUIT 2319		45099
143	10/18/2004	75932			44937
143	10/13/2004	66684	ACCIDENT DAMAGE	Creditor #:ATT001 ATTITUDE SIGNS P/O #:17425 Receiving #:20018 Date :2004-10-13 SUPPLY AND FIT DECALS	
143	10/05/2004	75144	Warranty Recall - RC - 040161	Checked by Banlay - OK	43671
143	10/01/2004	75066	O/S bottom tail light out.	replaced globe	43671
143	10/01/2004	75066	A/C not working in the drivers compartment.	checked no fault	43671
143	10/01/2004	75066	Back seats have been slashed.	replaced seat	43671
143	09/06/2004	45981	AIR CONDITIONING REPAIR	Creditor #:REA002 READ RITE PTY LTD P/O #:11523 Receiving #:19200 Date :2004-09-06 WARRANTY	
143	09/02/2004	72988	O RING FILTER KIT K93		40350
143	09/02/2004	72988	TEXAMATIC DEXRON 111		40350
143	09/02/2004	72988	ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL		40350
143	09/02/2004	72988	FILTER AIR SCANIA USE AF25066		40350
143	09/02/2004	72988	FILTER OIL K124 / L94UAB		40350
143	09/02/2004	72988	FILTER TRANSMISSION ZF 4139-298-038		40350
143	09/02/2004	72988		D Service	40350
143	09/02/2004	72988			40350
143	08/31/2004	72110	POS 10	Creditor #:BEA001 BEAUREPAIRES P/O #:19091 Receiving #:19072 Date :2004-08-31	
143	08/30/2004	72703	Doors safety edge u/s.	Checked - adjusted rear door switch.	40089
143	08/30/2004	72703	Doors safety edge u/s.	Checked - adjusted rear door switch.	40089
143	08/27/2004	72599	SENDER LOW WATER LEVEL SCANIA		39844
143	08/27/2004	72599	Coolant light staying on.	Replaced coolant level sensor.	39844
143	08/27/2004	72633	Replace interior light globe.	Replaced interior light globe.	39844
143	08/27/2004	72620	Passengers buzzer not working.	Repaired passengers buzzer.	39844
143	08/27/2004	72599	Ticket mashine not working.	No fault found - ticket mashine works.	39844
143	08/20/2004	72110	Replace tyre position - 10 - wall crack. Odometer - 39203.		39086
143	08/19/2004	72100	Replace o/s rear tyre.	Replaced o/s rear tyre.	38925
143	08/12/2004	71612	Coolant low light comes on intermittent.	Check & clean contact.	37926
143	08/02/2004	70911	Loosing coolant.	Checked for coolant leak at engineg/boxA/C & inside turntable - can't find any leak.	36648
143	07/20/2004	70097	Warranty repairs to wiring in turntable area.		35377
143	07/16/2004	69938	A/C rear not working.		35208
143	07/16/2004	69925			35208
143	07/02/2004	69592	Replace tubro - warranty	Banlay replaced turbo under warranty	34355
143	06/10/2004	67718	Air leaks from regulator valve - under dash	Repaired air leak at regulator valve.	31973
143	06/09/2004	67074	Direct Purchase - MECHANICAL	Creditor #:ROA001 Road Safety Inspections P/O #:17512 Receiving #:17345 Date :2004-06-09 ANNUAL INSPECTION	
143	06/09/2004	67604	Coolant laeks on boost pump		31931
143	06/07/2004	66997	POS 7 & 8		
143	06/06/2004	67074	Annual Inspection - DN 082069	Creditor #:BEA001 BEAUREPAIRES P/O #:17496 Receiving #:17310 Date :2004-06-07 Annual Inspection - DN 082069	31454
143	06/01/2004	66997	Repair tyres position - 7 - 8 - bald. Odometer - 31511.		31288
143	06/01/2004	66965	Replace n/s/r inner tyre.	Replaced n/s/r inner tyre.	31288
143	06/01/2004	66965	Tie rod bar touching tyres on both turns.	Checked o/k.	31288
143	06/01/2004	66965	Oil leaking on A/C compressor conection at back.	Repaired oil leak on A/C compressor conection.	31288
143	06/01/2004	66965	Water leak from boost pump rear.	Replaced booster pump.	31288
143	06/01/2004	67012	A/C Belt Cracked	Replaced A/C belts.	31288
143	06/01/2004	67027	Steam clean all bus.	Steam cleaned all bus & road tested.	31454
143	06/01/2004	66965	Oil leak from bell housing.	Checked o/k.	31288
143	06/01/2004	66965	Oil leak around diff.	Checked o/k.	31288
143	05/27/2004	66685	Polish & touch up n/s top corners.	Polished & touch up n/s top corners.	31019
143	05/27/2004	66685	Secure n/s seat frames No - 5 - 6.	Secured n/s seat frames No - 5 - 6.	31019
143	05/27/2004	66685	Secure all hand rails & poles.	Secured all hand rails & poles.	31019
143	05/27/2004	66685	Clean A/C filters.	Cleaned A/C filters.	31019
143	05/27/2004	66685	Secure rear door hand rails.	Secured rear door hand rails.	31019
143	05/27/2004	66685	Fit drivers compartment door check strap.	Fitted drivers compartment door check strap.	31019
143	05/27/2004	66685	Lubricate front - middle - rear door top & lower door pivot	Lubricated frontmiddle & rear door top & lower door pivots.	31019
143	05/27/2004	66685	Polish n/s corner panels.	Polished n/s corner panels.	31019
143	05/27/2004	66685	Secure all lower panels - allen screews.	Secured all low panels.	31019
143	05/27/2004	66685	CHECK STRAP DRIVERS DOOR HINGE		31191
143	05/27/2004	66685	BRACKET FOR CHECK STRAP DOOR HINGE		31191
143	05/27/2004	66685	Paint wheels.	Painted wheels.	31019
143	05/27/2004	66685	Refit n/s/f corner clip in strip.	Reffited n/s/f corner clip in strip.	31019
143	05/27/2004	66685	Square up n/s/f skid foot.	Repaired n/s/f skid foot.	31019
143	05/27/2004	66685	Repair front door mounts - pivots.	Repaired front door mounts.	31019
143	05/27/2004	66685	Replace all window emergency exit decals.	Replaced all window emergency exit decals.	31019
143	05/27/2004	66685	Secure o/s seat frames No 5 - 6 - 7 - 8 - 10 - 11.	Secured o/s seat frames No 5 - 5 - 6 - 7 - 8 - 10 - 11.	31019
143	05/27/2004	66684	R/H/R panel scratched.	Polished r/h/r panel.	31019
143	05/27/2004	66684	O/S/R panel damaged. (Checked on 6/4/04 servicable HKS)	Repaired o/s/r panel.	31019
143	05/24/2004	66291	HYDRAULIC FILTER L94UAB		30730
143	05/24/2004	66291		Clean a/c filters	30730
143	05/24/2004	66291	FILTER FUEL K124 / LU94A		30730
143	05/24/2004	66291	FILTER FUEL SCANIA L94UAB		30730
143	05/24/2004	66291	POWER STEER FILTER B10M		30730
143	05/24/2004	66291		Replace air dryer cansiter	30730
143	05/24/2004	66291		Replace hydraulic fan filter and top up oil	30730
143	05/24/2004	66291		Replace final drive oil	30730
143	05/24/2004	66291		Replace fuel filters	30730
143	05/24/2004	66291		Inspect bus as per inspection sheet	30730
143	05/24/2004	66291		Replace coolant filter in engine cooling system	30730
143	05/24/2004	66291		Rekit quick release valve	30730
143	05/24/2004	66291		Replace power steering filter	30730
143	05/24/2004	66291		Adjust valve clearances	30730
143	05/24/2004	66291	RPM BORATE EP LUBE 220		30730
143	05/24/2004	66291	DRYER KIT {HALDEX}B10B+B12+L94UAB+B7R		30730
143	05/24/2004	66367	Passenger middle door senstive edge not working.	Adjusted middle door sensitive edge.	30863
143	05/24/2004	66367	Check electric & clean all lenses.	Checked electric - cleaned light lenses.	30863
143	05/24/2004	66305	Annual body check	Checked.	30730
143	05/20/2004	66164	Steering very heavy.	Checked king pinspower steering oil o/k. Couldn find fault.	30555
143	05/20/2004	66134			30555
143	05/11/2004	58208	WARRANTY	Creditor #:BAN001 BANLAY PTY LTD P/O #:15380 Receiving #:16694 Date :2004-05-11	
143	05/04/2004	64970	SENDER LOW WATER LEVEL SCANIA		28118
143	05/04/2004	64970	Low water light shows on.	Checked & replaced low water sender.	28118
143	05/03/2004	64907	MIRROR TOP BRAZILLIAN		27965
143	05/03/2004	64907	Need a convex mirror for left side.	replaced mirror head	27965

[illegible]