

Veh#	Date	W/O#	Description	Notes	Odometer
60	09/29/2026	1372709	Decommission of Bus for AUCTION	carried out bus decommission	647561
60	07/08/2026	1352874		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS tensioned wheel nuts with guy	646227
60	07/08/2026	1352874		VEHICLE SAFETY INSPECTION completed as per check list	646227
60	07/08/2026	1352874	Service	CARRY OUT CCTV - B SERVICE AS PER CHECK LIST completed as per check list	646227
60	07/08/2026	1352874		PRE ANNUAL SAFETY INSPECTION CHECK completed as per check list	646227
60	07/08/2026	1352980	Mechanic entered - Fluid Leaks Rear of bus minor coolant lea	tightened clamps and checked ok	645298
60	06/17/2026	1347842	Consumables		645298
60	06/17/2026	1347842	PTI Tablet Entered -oil stick difficult to get back in	No fault with distick or tube.	645298
60	06/16/2026	1347938	Consumables		645298
60	06/16/2026	1347938	PTI Tablet Entered -Wheels and Tyres - Worn drivers side rea	checked all tyres. all tyre sidewalls within specs	645298
60	06/15/2026	1347662	PTI Tablet Entered -Engine - OTHER minor - dip stick get stu	Inspected dipstick getting stuck. No damage to dipstick or tube. esign and angle of dipstick makes it difficult to insert but can not be altered.	645298
60	06/05/2026	1345945	Consumables		644854
60	06/05/2026	1345944	Consumables		644854
60	06/05/2026	1345945	PTI Tablet Entered -oil tube is detached from the entry po	remove tube. clean up tube end and refit into main bracket.	644854
60	06/05/2026	1345944	PTI Tablet Entered -the oil tube is detached from the entry	double up defect	644854
60	06/04/2026	1345134	Consumables		644854
60	06/04/2026	1345134	SEAT HANDGRIP BLACK CENTRA SINGLE		644854
60	06/04/2026	1345134	Service	2x chin guards replaced by Luke.	644854
60	06/03/2026	1345265	Consumables		644676
60	06/03/2026	1345265	PTI Tablet Entered -Wheels and Tyres - Worn off side middle	checked all tyres could not find any worn tyres	644676
60	06/02/2026	1344046	DIRECT PURCHASE - AIR CONDITIO	Creditor #-PP-COL004 COLD DRIVE PTY LTD P/O #-PP411356 Receiving #-438534 Date :2026-06-09 CARRY OUT A/C REPAIRS	645031
60	06/02/2026	1345134	Drv entered - Body Passenger Seat TornIsle seat just behind	requested new chin guards.	644676
60	05/28/2026	1344046	Drv entered - A/C Heating OTHERNo power to rear AC heating	Assisting Repairs carried out by colddrive. Wiring fault found and repaired	644237
60	05/27/2026	1343648	PTI Tablet Entered -Body - Body Damage -- cracks in front b	Reported on accident #60180	644237
60	05/27/2026	1343648	Consumables		644237
60	05/26/2026	1343593	Mechanic entered - Wheels and Tyres Wheel Nut Retension NSR	Assisting	644237
60	05/26/2026	1343593	Mechanic entered - Wheels and Tyres Wheel Nut Retension NSR	Retension n/s/r/t wheel nuts to OEM spec	644237
60	05/26/2026	1343593	Consumables		644237
60	05/25/2026	1342996	Consumables		643877
60	05/25/2026	1342996	PTI Tablet Entered -Wheels and Tyres - Flat or Leaking rear	NSRR outer tyre puncture. R&R tyre. Checked air pressure and torqued to spec	643877
60	05/25/2026	1342996	TYRE 275/70R22.5 RECAP		643877
60	05/21/2026	1335025	BATTERY 1500CCA POSITIVE ON LEFT H/S EMFN200L	re-open & fix 200R used	643877
60	05/21/2026	1335025	BATTERY 1500CCA POS ON RIGHT H/S EMFN200R		643877
60	05/21/2026	1342453	disable seat area staution pole rusty	remove both rusted poles. strip back to bare metal and re paint. refit poles	643877
60	05/21/2026	1342453	Consumables		643877
60	05/21/2026	1342436		CARRY OUT A/C - A SERVICE AS PER CHECK LIST - PO:1342427 - CARRIED OUT BY JIMMY FROM COLD DRIVE	643877
60	05/14/2026	1340782	Mechanic entered - Air System Air Not Building_Up	retrieve bus and back onto pit. check air in rear tanks and drain water. check air presure at test ports all ok. turn bus around check pressures at gfront tanks. drain air check pressures at all ports all ok. remove pressure senders and test found rear pressure sender to be faulty. get new one from knox and fit test all ok	643599
60	05/14/2026	1340782	SWITCH AIR PRESSURE 16 BAR SCANIA 4 SERIES 0478690		643599
60	05/13/2026	1340435	PTI Tablet Entered -Body - Body Damage front bumper damage	accident already in system	643422
60	05/13/2026	1340435	Consumables		643422
60	05/11/2026	1339854	PTI Tablet Entered -Fluid Leaks - Rear of bus minor fluid	wash engine down due to coolant all over front of motor. test drive bus to operating temp. found header tank cap to be faulty. replaced cap	643095
60	05/11/2026	1339854	CAP EXPANSION TANK 0.75BAR SCANIA K93 L94 L113 1403954		643095
60	05/11/2026	1339856	PTI Tablet Entered -Fluid Leaks - Rear of bus coolant leak	double up defect	643095
60	05/08/2026	1339454	PTI Tablet Entered -panel loose screws loosen rear wheel a	Tighten screws	643095
60	05/08/2026	1339454	Consumables		643095
60	05/01/2026	1337638	DIRECT PURCHASE - AIR CONDITIO	Creditor #-PP-COL004 COLD DRIVE PTY LTD P/O #-PP409499 Receiving #-436303 Date :2026-05-11 REPLACED AC COMPRESSOR X 1 AS REQUIRED	643239
60	05/01/2026	1336665	FIT NEW DIPSTICK	COMPLETE	642530
60	05/01/2026	1337831	AC BELT U/S	REPLACED AC BELT	642530
60	05/01/2026	1337831	BELT CRANK-TWIN A/C COMP SCANIA L94UAB(1389052)		642530
60	05/01/2026	1337763	Consumables		642530
60	05/01/2026	1337763	Body (None) you are travelling on sticker missing	fit new you are travelling on sticker	642530
60	04/30/2026	1337638	AC COMPRESSOR X1 U/S - WAITING ON QUOTE FROM SIMON - COLD D	Assisting	642530
60	04/30/2026	1337638	AC COMPRESSOR X1 U/S - WAITING ON QUOTE FROM SIMON - COLD D	a/c complessor been replace by cameron cold drive	642530
60	04/30/2026	1337517	ENGINE DIPSTICK TO SECURE	Secured dipstick with hose clamp. Checked engine oil level all ok.	642530
60	04/29/2026	1337320	Drv entered - A/C Heating Not HeatingRear AC heating unit	REFER TO DEFECT # 1158529	642530
60	04/29/2026	1337320	Mechanic entered - A/C Heating Not Cooling compressor clutc	REFER TO DEFECT # 1158529	642530
60	04/29/2026	1337201	Drv entered - Engine Low Powerlow power hard to take off an	check all fluid levels. test drive bus. bus would do 100kms on fwy. no warning lights present at time of test.	642530
60	04/29/2026	1335364		checked the system and all the step lights are working.	642530
60	04/29/2026	1335364	Consumables		642530
60	04/28/2026	1337043	Mechanic entered - Wheels and Tyres Wheel Nut Retension P5	Retensioned P5+P6 wheel nuts to 650nm. with George	642530
60	04/28/2026	1337043	Mechanic entered - Wheels and Tyres Wheel Nut Retension P5	Assist Nikki	642530
60	04/28/2026	1337043	Consumables		642530
60	04/27/2026	1336665	DIPSTICK ENGINE OIL 753MM SCAN	Creditor #-PP-SCA001 SCANIA AUSTRALIA PTY LTD P/O #-PP409186 Receiving #-435367 Date :2026-04-28	642530
60	04/27/2026	1336665	Mechanic entered - Engine Other Engine dipstick u/s (need t	ORDERED DIPSTICK 27-4-26	642423
60	04/27/2026	1336688	Consumables		642423
60	04/27/2026	1336688	SENSOR WEAR KIT BLOCK TYPE AXLE SET SCANIA 1794440		642423
60	04/27/2026	1336688	Warning Light On Dash brake pads lining	DOUBLE ENTRY	642423
60	04/27/2026	1336579	Consumables		642423
60	04/27/2026	1336579	Mechanic entered - Body Other PTI to be completed	Completed PTI check as per checklist. Topped up engine oil.	642423
60	04/27/2026	1336688	PTI Tablet Entered -Brakes - Brake lining warning light on	Removed P5 and P6 tyres. Removed and replaced O/S/R brake sensor wire. Checked dash warning light gone. Secured wire. Refitted tyres and tensioned O/S/R wheel nuts to 650nm.	642423
60	04/23/2026	1334342	Consumables		642176
60	04/23/2026	1334342	repair face on rear number plate . plate was not replaced	Repaired front and rear number plates.	642176
60	04/21/2026	1334214	Consumables		641957
60	04/21/2026	1335363	Consumables		641957
60	04/21/2026	1335363	Mechanic entered - Elec and Light Other battery cable rubbin	checked the system change the batteri cable isolations tighted up with zipties much better now	641957
60	04/21/2026	1334214	NS PAX BUTTON SWITCH MISSING	INSTALLED NEW SWITCH	641957
60	04/21/2026	1335364	Mechanic entered - Elec and Light Other all door step lights	checked the system change the globes but need more time to find the problem. when the bus are come back can to finalise the lights repair all good now.	641957
60	04/20/2026	1335025	Engine Will Not Start in Neutral battery flat	TRACED AND FOUND BATTERYS U/S X 2 . REPLACED BOTH BATTERYS . MODIFIED BATTERY BRACKET TO CREATE SPACE FOR BATTERY TERMINALS . ALL OK	641957
60	04/20/2026	1335025	BATTERY 1500CCA POSITIVE ON LEFT H/S EMFN200L		641957
60	04/16/2026	1334282	Mechanic entered - Fluid Leaks Rear of bus transmission cov	Removed and replaced transmission sensor cover o-ring with new. Washed bus.	641957
60	04/16/2026	1334282	Mechanic entered - Fluid Leaks Rear of bus transmission cov	picked up o ring from oakleigh depot .	641957
60	04/16/2026	1334282	O-RING ZF OUTPUT SENSOR COVER		641957
60	04/16/2026	1334214	SWITCH STOP YELLOW (62628)(50V	Creditor #-PP-VOLGRE VOLGREN AUSTRALIA PTY LTD P/O #-PP408405 Receiving #-434729 Date :2026-04-20	641957
60	04/16/2026	1334342	Mechanic entered - Body Other x2 you are travelling on stic	ORDERED WITH SUE	641957
60	04/16/2026	1334342	Mechanic entered - Body Other rear number plate faded	ORDERED WITH SUE	641957
60	04/15/2026	1334130	Consumables		641957
60	04/15/2026	1334145	Consumables		641957
60	04/15/2026	1334146	Consumables		641957
60	04/15/2026	1334147	Consumables		641957
60	04/15/2026	1334130	Mechanic entered - Elec and Light Interior Lights N/S/R + O/	Removed and replaced 3x globes with new. Checked all ok.	641957
60	04/15/2026	1334214	Mechanic entered - Elec and Light Next Stop Button n/s disab	ordered parts with kaitlyn	641957
60	04/15/2026	1334145	Mechanic entered - Elec and Light Other emergency exit light	Defect entered twice. Refer todefect # 1155647	641957
60	04/15/2026	1334146	Mechanic entered - Elec and Light Other interior saloon ligh	Removed and replaced 2x fluro tube. Adjusted tombstone and refitted defuser.	641957
60	04/15/2026	1334147	Mechanic entered - Elec and Light Interior Lights N/S/R +O/S	Replaced 3x emergency exit light globes with new.	641957

60	04/15/2026	1334142 Consumables		641957
60	04/15/2026	1334209 Consumables		641957
60	04/15/2026	1334084 Consumables		641957
60	04/15/2026	1334085 Consumables		641957
60	04/15/2026	1334113 Consumables		641957
60	04/15/2026	1334116 Consumables		641957
60	04/15/2026	1334131 Consumables		641957
60	04/15/2026	1334116 Mechanic entered - Body Other o/s/f disable seat not holding	Removed and replaced gas strut with new.	641957
60	04/15/2026	1334116 STRUT GAS STAY 200NM 128mm LNG		641957
60	04/15/2026	1334209 Mechanic entered - Body Other multiple seat bases worn	replaced passenger seat bases	641957
60	04/15/2026	1334209 helping fitting passenger seat		641957
60	04/15/2026	1334209 SEAT CUSH SINGLE CEN CVR CI		641957
60	04/15/2026	1334084 Mechanic entered - Body Other o/s/r staution pole loose at r	Repaired roof bracket internal threads. Secured all brackets with new bolts and spring washers.	641957
60	04/15/2026	1334085 Mechanic entered - Body Other turntable screws missing on fl	Fitted new turn table screws.	641957
60	04/15/2026	1334113 Mechanic entered - Body Other o/s x1 grab handle worn	Removed and replaced grab handle with new.	641957
60	04/15/2026	1334113 HANDLE GRAB GREY STRAP BRV001		641957
60	04/15/2026	1334131 Mechanic entered - Body Other no safety triangles in bus	Fitted 3x spare safety triangles.	641957
60	04/15/2026	1334142 Mechanic entered - Body Other multiple rear seats loose not	Removed 2x seat bases and tightened nuts under seat bases.	641957
60	04/14/2026	1333742	VEHICLE SAFETY INSPECTION completed vsi	641957
60	04/14/2026	1333742	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS completed	641957
60	04/14/2026	1333742	Assisting assisted completing safety	641957
60	04/14/2026	1333865 Consumables		641957
60	04/14/2026	1333867 Consumables		641957
60	04/14/2026	1333868 Consumables		641957
60	04/14/2026	1333869 Consumables		641957
60	04/14/2026	1333865 Mechanic entered - Body Other Fire extinguisher sticker miss	Fitted new decal.	641957
60	04/14/2026	1333867 Mechanic entered - Body Other No smoking decal missing	Fitted new decals.	641957
60	04/14/2026	1333868 Mechanic entered - Body Other Driver's sun blind not holding	Lubricated sun blind. Checked all ok.	641957
60	04/14/2026	1333869 Mechanic entered - Body Other Max capacity sticker on rear h	Fitted new decals.	641957
60	04/01/2026	1331517 Consumables		641780
60	04/01/2026	1331517 Drv entered - Body OTHERrear back bench seat latch has come	drill out rivits and refit latch. secure seat.	641780
60	03/31/2026	1321433 PULLEY IDLER PLASTIC GROOVED SCANIA L94 1514087	mech booked wrong #	641780
60	03/31/2026	1321433 PULLEY AC IDLER SCANIA K310UB 1910983	correct item used booked	641780
60	03/24/2026	1329478	No engine warning light on yesterday and today. Engine operating normal.	640561
60	03/23/2026	1317714 Mechanic entered - Engine Other water pump leaking	INSPECTED ENGINE WATER PUMP FOR COOLANT LEAKS . COULD NOT FAULT	640561
60	03/23/2026	1329283 Workshop Tablet Entered -Engine - Belts_Loose Noisy Missing	CHECKED CONDITION AND TENSION OF ALL ENGINE BELTS . COULD NOT FAULT .	640561
60	03/23/2026	1329478 Drv entered - Engine Low PowerSlower than normal in tak off	Road tested first can confirm bus is lacking take off power with about 2-3 second delay on accelerator before rolling struggled on the hill going up near mount martha. Inspected air filter still okay. Carry over.	640561
60	03/23/2026	1329285 (Historic defect) Foot valve leaking	FOOT BRAKE VALVE REPLACED ON WORK ORDER :1029364	640561
60	03/22/2026	1326546	FIRE EXTINGUISHER TEST & TAG completed by ATS 15.02.26	640561
60	03/17/2026	1327814 Mechanic entered - Wheels and Tyres Wheel Nut Retension p7p8	retensioned p7 p8 p9 p10 wheels to spec.	640561
60	03/17/2026	1327814 Consumables		640561
60	03/17/2026	1327886 Driver Tablet Not Charging		640561
60	03/17/2026	1318268	fix under an other job number.	640561
60	03/13/2026	1327042 PTI Tablet Entered -Body - OTHER interior over head panel ab	checked the system modified the bracket install a new charger leadd working now	640561
60	03/12/2026	1326798 Mechanic entered - Wheels and Tyres Wheel Nut Retension posi	secure a/c bulkhead above second door.	640561
60	03/12/2026	1326798 Consumables	retensioned to spec. with Guy at 640692 kms	640561
60	03/12/2026	1324983 Service		640561
60	03/10/2026	1326188 Mechanic entered - Wheels and Tyres Flat or Leaking position	removed wheels p7 p8 p9 p10 harley and guy cleaned wheels and hub i oiled wheel nuts and fitted wheels back on tensioned to spec. and booked a eretension	640265
60	03/10/2026	1326188 TYRE 275/70R22.5 RECAP	replaced position 3/4 due to slow leak and low traed. cleaned surfaces and tentioned to 650Nm	640265
60	03/10/2026	1326188 Consumables		640265
60	03/10/2026	1324983	removed position 3/4/5/6 and cleaned surfaces. re fitted wheels and tentioned to 650Nm assist	640265
60	03/10/2026	1324983 Service	help on removing wheel and clean surface	640265
60	03/06/2026	1325675 Mechanic entered - Wheels and Tyres Wheel Nut Retension both	complete front P12 wheel nuts retension to OEM spec with Harley	640265
60	03/06/2026	1325675 Consumables		640135
60	03/05/2026	1325136 Mechanic entered - Elec and Light Flat Batteries	jump start bus. charging at 27V. master was left on	640135
60	03/04/2026	1324983 PERFORM CAMPAIGN 01/26 ALL WHEELS NEED TO BE REMOVED ALL RI	Removed front wheel sanded backmallpaint on the rims and hub tension both front to OEM spec 650Nm wth Darren klm 640177	639823
60	03/03/2026	1324413 Driver Tablet Not Charging	checked the system install a new charger into the bus.	639823
60	03/03/2026	1324413 CHARGER USB 5V 3A DUAL CONVERTER MODULE BUS MINDER		639823
60	03/01/2026	1317714 Mechanic entered - Engine Other water pump leaking	order part	640561
60	03/01/2026	1317714 WATER PUMP SCANIA L94 UAB 15	Creditor #:PP-MUL001 MULTISPARES LTD P/O #:PP402528 Receiving #:431761 Date :2026-03-11 60	639823
60	03/01/2026	1318268 Drv entered - Air System Air Not Building_UpAir not buildin	check air build up time. is slow. check air system. found valve at rear of bus to be leaking. valve requires replacement. checked air system with soapy water could not find any other leaks. replaced leaking air valve in rear. tested all ok.	639212
60	02/19/2026	1321433 BELT ALT W/PUMP CRANK SCANIA L94UAB 1803334 1389044		639212
60	02/19/2026	1321433 BELT CRANK-TWIN A/C COMP SCANIA L94UAB(1389052)		639212
60	02/19/2026	1321433 BELT V COGGED TRI-POWER 17x1700mm		639212
60	02/19/2026	1321433 BELT V COGGED TRI-POWER 17x1220mm		639212
60	02/19/2026	1321433 COVER MOUNT BOLT AC BELT PULLE	Creditor #:PP-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:PP404981 Receiving #:430436 Date :2026-02-19	639389
60	02/18/2026	1321433 Breakdown Belts Pulleys & Idler Bearings	replace all pulleys and tensioner and all belts test found good	639212
60	02/18/2026	1321433 PULLEY IDLER SMOOTH PLASTIC SCANIA 1514086 1428940		639212
60	02/18/2026	1321433 PULLEY IDLER PLASTIC GROOVED SCANIA L94 1514087		639212
60	02/18/2026	1321433 TENSIONER BELT SCANIA SR4 L94 K230 1859654 1503113 2197002		639212
60	02/18/2026	1321433 PULLEY IDLER (SMOOTH STL) SCANIA L94UAB 1779801 1535068		639212
60	02/17/2026	1321433 DIRECT PURCHASE - TOWING	Creditor #:PP-EAG001 EAGLE TOWING & SALVAGE P/O #:PP404941 Receiving #:430745 Date :2026-02-25	639734
60	02/17/2026	1321059	CARRY OUT CCTV - A SERVICE AS PER CHECK LIST complate CCTV A service as per checklist	639212
60	02/13/2026	1320480 Body (None) cctv cabinet lock damage	replace cabinet lock test found good	639212
60	02/13/2026	1320480 LATCH PANEL QUAD		639212
60	02/13/2026	1320480 Consumables		638334
60	02/05/2026	1318580 Drv entered - Air System Air_Leak Doors	check and found external emergency door valve hose come off put it back in test found good	638334
60	02/04/2026	1318268 Drv entered - Air System Air Not Building_UpAir not buildin	check air build up time. is slow. check air system. found valve at rear of bus to be leaking. valve requires replacement. checked air system with soapy water could not find any other leaks.	638334
60	02/02/2026	1317714 Mechanic entered - Engine Other water pump leaking	order part	638245
60	01/21/2026	1315590	VEHICLE SAFETY INSPECTION complete	638245
60	01/21/2026	1315590	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	638245
60	01/14/2026	1314174 PTI Tablet Entered -Body - battery negative cable clamp no	checked the system repaire the battery terminal.	638245
60	01/07/2026	1312942 PTI Tablet Entered -Body -	double up defect	638014
60	12/01/2025	1305709 DIRECT PURCHASE - AIR CONDITIO	Creditor #:PP-COL004 COLD DRIVE PTY LTD P/O #:PP400145 Receiving #:425399 Date :2025-12-03 60 replace controller	637407
60	11/27/2025	1305709 Drv entered - A/C Heating Not CoolingFront ac unit not wor	Duplicate	637407
60	11/27/2025	1305709 Drv entered - A/C Heating Not CoolingFront ac unit not wor	Assisting Duplicate	636798
60	11/14/2025	1303058 A/C Heating (None) condenser fan replacement	Assisting comlete	636798
60	11/14/2025	1303058 A/C Heating (None) condenser fan replacement	2 condenser fan motor been replaced by Dave cold drive	636798
60	11/14/2025	1303058 A/C Heating (None) condenser fan replacement	Assisting complete	636973
60	11/14/2025	1301194 DIRECT PURCHASE - AIR CONDITIO	Creditor #:PP-COL004 COLD DRIVE PTY LTD P/O #:PP399120 Receiving #:424296 Date :2025-11-19 60 a/c fan replacement	635906
60	11/06/2025	1301194 Drv entered - A/C Heating Not HeatingPassenger's still com	check and found one condenser motor on both units are noisy need repalced recommended by Jimmy cold drive	635906
60	11/06/2025	1301194 Drv entered - A/C Heating Not HeatingPassenger's still com	Assisting	635906
60	11/06/2025	1301194 Mechanic entered - A/C Heating Noisy front a/c pod noisy fa	fan motor need replace by two	635906
60	11/03/2025	1297100	Secured knock on strip. Replaced body bolts and secured mirror assy to body.	635906
60	10/31/2025	1300281	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS complete	635906

60 10/31/2025	1300281	VEHICLE SAFETY INSPECTION complete	635906
60 10/31/2025	1300310 Mechanic entered - Elec and Light Interior Lights emergency	repair emergency exit lights as required	635906
60 10/31/2025	1300311 Mechanic entered - Dash Guages Not Working air guage not wor	remove dash cluster. fit second hand guage from bus 730. refit cluster and test all ok	635906
60 10/31/2025	1300310 Consumables		635906
60 10/31/2025	1300311 Consumables		635906
60 10/27/2025	1299141 O-RING LOWER SPINNER FILTER SCANIA L94 K124		635730
60 10/27/2025	1299141		635730
60 10/27/2025	1299141 OIL ATF STEERING DEX-3 VALVOLINE		635730
60 10/27/2025	1299141 FILTER ZF ECOMAT TRANS (E39HD119)(1193281-1)		635730
60 10/27/2025	1299141 FILTER FUEL SCANIA VARIOUS MODELS H17WK04		635730
60 10/27/2025	1299141 FILTER OIL SCANIA VARIOUS MODELS		635730
60 10/27/2025	1299141 PAPER SPINNER FILTER OIL INSERT SCANIA VARIOUS MODELS		635730
60 10/27/2025	1299141 O-RING LARGE UPPER SPINNER FILTER SCANIA		635730
60 10/27/2025	1299141 OIL ENGINE ALL FLEET PLUS E900 15W-40		635730
60 10/27/2025	1299141 Consumables		635730
60 10/27/2025	1299141 Consumables		635730
60 10/27/2025	1299141 Consumables		635730
60 10/21/2025	1297879 Mechanic entered - Body Other	re fit wheel nut indicators. check over bus for service	635125
60 10/20/2025	1297748 PTI Tablet Entered -Elec and Light - Exterior LightsO/S/F he	replaced headlight lens from another bus and fitted new globe on it	635125
60 10/20/2025	1297748 Consumables		635125
60 10/20/2025	1297749 Drv entered - Body Water Leaks Windowswater running down t	repair been completed by east coast	635125
60 10/17/2025	1297264 Panint wheels x 6 as requested by Portsea depot (17/010/2025	prep and mask up 6x wheels paint white	635125
60 10/17/2025	1297264 Consumables		635125
60 10/17/2025	1297076 Accident#59645 - Mirror (TPAF)	repair been completed by East coast on friday17/10/25	635125
60 10/17/2025	1297076 Accident#59645 - Mirror (TPAF)	Assisting complete bus to depot on Monday 20/10/25 at 10:45am	635125
60 10/16/2025	1297100 PAINT SPRAYCAN BLACK MATT 400ml		635125
60 10/16/2025	1297100		635125
60 09/11/2025	1289740 Drv entered - Elec and Light Exterior LightsHeadlights swit	Moved vehicles. Removed mirror and repainted. Collected new bolts.	633965
60 09/01/2025	1277624 VALVE FOOTBRAKE C/W RET SWITCH	check defect. found all mounting lugs on facia to be broken. removed entire dash facia from bus 63 remove all guages swap all guages from 60 to new facia re fit and install. check all functions all ok.	633965
60 08/31/2025	1283786	Creditor #-:PP-MUL001 MULTISPARES LTD P/O #-:PP391835 Receiving #-:419451 Date :2025-09-10 possible warranty ref original 26/2 PP391835	632589
60 08/21/2025	1284311 Drv entered - Body Mirrors ExteriorLeft side mirror moves	Completed by ATS 06.08.25	632901
60 08/14/2025	1281503 DIRECT PURCHASE - BUS INSPECTI	tightened mirror housing	632323
60 08/08/2025	1281503	Creditor #-:PP-ROASAF ROAD SAFETY INSPECTIONS P/O #-:PP392922 Receiving #-:417604 Date :2025-08-15 60 RSI complete	632156
60 08/08/2025	1281503	VEHICLE SAFETY INSPECTION	632156
60 08/08/2025	1281503	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	632156
60 08/08/2025	1281503	ANNUAL SAFETY INSPECTION SERIAL #RSI 069460_WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25	632156
60 08/08/2025	1281503	Assisting	632156
60 08/08/2025	1277624 Mechanic entered - Brakes Foot_Brakes Leaking Air	rebuilt middle and rear axle distribution QR valve. tested all ok replaced foot brake valve due to constant leak. possible warranty on parts	632156
60 08/07/2025	1281282 Drv entered - A/C Heating Not HeatingHeaters still not wor	a/c heating been fix by jimmy wirring issue	632156
60 08/07/2025	1281282 Drv entered - A/C Heating Not HeatingHeaters still not wor	Assisting complete	632156
60 08/07/2025	1281282 Drv entered - A/C Heating Not HeatingPassengers keep compl	a/c heating been fix by Jimmy wirring issue	632156
60 08/07/2025	1281282 Repair heating	Creditor #-:PP-COL004 COLD DRIVE PTY LTD P/O #-:PP393348 Receiving #-:417601 Date :2025-08-15	632323
60 08/07/2025	1281352	CARRY OUT COMPLETE VEHICLE UNDER CARRIAGE WASH complete under carriage wash	632156
60 08/01/2025	1279908 Mechanic entered - Wheels and Tyres Wheel Nut Retension posi	retentioned position 9/10 to 650Nm	631956
60 08/01/2025	1279908 Consumables		631956
60 08/01/2025	1279909 Drv entered - Warning Lights EngineEngine light orange colo	double up defect	631956
60 08/01/2025	1279922 Drv entered - Engine Low PowerVery low in power struggles t	hard reset system. checked codes. cleared codes checked engine over. test drove drove well plenty of power	631956
60 07/30/2025	1279431 Drv entered - Wheels and Tyres DamagedRear Tyre on driversi	replaced position 10 due to sidewall damage. tentioned to 650Nm	631418
60 07/30/2025	1279431 TYRE 275/70R22.5 RECAP		631418
60 07/30/2025	1279431 Consumables		631418
60 07/29/2025	1279150 Drv entered - Elec and Light Interior LightsRear interior l	refit light cover	631418
60 07/29/2025	1279150 Consumables		631418
60 07/15/2025	1276452	VEHICLE SAFETY INSPECTION complete	630967
60 07/15/2025	1276452	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS complete	630967
60 07/15/2025	1276451	PRE ANNUAL SAFETY INSPECTION CHECK complete	630967
60 07/01/2025	1273725	CARRY OUT CCTV - B SERVICE AS PER CHECK LIST complete	630967
60 06/23/2025	1272039 Drv entered - Engine Low PowerOrange engine light on again	CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST complate fire safety inspection as per checklist apply several zipties	630654
60 06/23/2025	1271972 Drv entered - Elec and Light Indicators Not Workinginderca	check on bus no warning light on test drive bus look fine	629930
60 06/23/2025	1271972 Consumables	swap indicator stork from bus 63 fit on 60 test found good	629930
60 06/05/2025	1267469 Drv entered - Air System Air_Leak RearAir dropping when par	drain air tanks replace air drier filter remove hot pipe at air drier to test air flow. replace four way protection valve sound good now	629412
60 06/05/2025	1267469 FILTER AIR DRYER SCANIA K1241B L941B L94UAB		629412
60 06/05/2025	1267469 VALVE CIRCUIT PROTECTION 4WAY SCANIA 1431049 1381883		629412
60 05/28/2025	1266995 Drv entered - Elec and Light Exterior LightsRear tail Light	emptied water from n/s front clearance light. replaced blown fuse tested all ok	629234
60 05/28/2025	1266995 Consumables		629234
60 05/22/2025	1265801	CARRY OUT A/C - B SERVICE AS PER CHECK LIST a/c B service been completed by Jimmy	628793
60 05/22/2025	1265801	Assisting complete	628793
60 05/22/2025	1265801 DIRECT PURCHASE - AIR CONDITIO	Creditor #-:PP-COL004 COLD DRIVE PTY LTD P/O #-:PP388018 Receiving #-:411850 Date :2025-05-30 60 a/c B service	629412
60 05/22/2025	1265801	CARRY OUT A/C - A SERVICE AS PER CHECK LIST a/c A service been completed by Jimmy	628793
60 05/01/2025	1261518 Mechanic entered - Wheels and Tyres Wheel Nut Retension posi	Retentioned wheelnus	627350
60 05/01/2025	1261518 Consumables		627350
60 05/01/2025	1261662 Drv entered - Elec and Light Exterior LightsA side light ha	Changed blown globe in rh side marker light	627350
60 05/01/2025	1261662 Consumables		627350
60 04/29/2025	1260945 Mechanic entered - Wheels and Tyres Flat or Leaking	replaced position 5 tyre due to blow out. tentioned to 650Nm	627169
60 04/29/2025	1260945 TYRE 275/70R22.5 RECAP		627169
60 04/21/2025	1259670	VEHICLE SAFETY INSPECTION complete	626670
60 04/21/2025	1259670	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS complete	626670
60 04/04/2025	1256913 Drv entered - Engine Low PowerBus has low power again. Oran	Checked for engine light test drove all ok.	626670
60 03/29/2025	1255671 Drv entered - Engine Low PowerBus running really low on po	found engine light on decoded engine light to find the vehiclle shut down procedure wasnt followed causing engine light and limp mode. reset ecu all good	626497
60 03/29/2025	1255658 Consumables		626497
60 03/29/2025	1255658 Drv entered - Body Body DamageLeft side mirror is lose and	tighten mirror	626497
60 03/24/2025	1254005 RELAY FLASHER SCANIA L94 UAB1401789 4DN-007-431-021	replaced flasher can all ok	625693
60 03/24/2025	1254340 Drv entered - Elec and Light Indicators Not WorkingRight si		625693
60 03/21/2025	1254005 Drv entered - Elec and Light Indicators Not WorkingRight s		625693
60 03/20/2025	1253514 Driver Tablet Entered -A/C Heating - Not Cooling	checked a/c operation all ok	625693
60 03/19/2025	1253345	TRANSMISSION CHECK AS PER CHECK LIST completed	625693
60 02/28/2025	1249143 Drv entered - Breakdown bus lost power . Orange engine war	complete	624603
60 02/19/2025	1246445 PTI Tablet Entered -Elec and Light - Exterior LightsO/S/F up	checked the system change the globe	624336
60 02/19/2025	1246445 Consumables		624336
60 02/14/2025	1240692 Mechanic entered - Air System Air_Leak Front Air leak on un	parts ordeerd job complete	623847
60 02/14/2025	1240692	Fit new brake foot valve.	623847
60 02/14/2025	1245122	CARRY OUT FIRE EXTINGUISHER TEST & TAG completed	623847
60 02/14/2025	1245122	Assisting	623847
60 02/01/2025	1240692 VALVE FOOTBRAKE C/W RET SWITCH	Creditor #-:PP-MUL001 MULTISPARES LTD P/O #-:PP379568 Receiving #-:405431 Date :2025-02-26 bus 60 cross from GEN 1778743	624603
60 01/30/2025	1240754	replaced both front upper torque rods	623056
60 01/29/2025	1241186 PTI Tablet Entered -Elec and Light - Exterior Lights N/S/F h	checked the system change the fuse	623056

60 01/29/2025	1241186 Consumables			623056
60 01/29/2025	1241258			623056
60 01/28/2025	1240754 TOP SUSPENSION ROD RH FRONT SC	CARRY OUT CCTV - A SERVICE AS PER CHECK LIST complate CCTV A service as per checklist		623056
60 01/24/2025	1240572	Creditor #:PP-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:PP380271 Receiving #:403441 Date :2025-01-29 60		623056
60 01/24/2025	1240572	VEHICLE SAFETY INSPECTION Carried out safety as per checklist		623056
60 01/24/2025	1240725 BUSH SWAY BAR MID AXLE D-BUSH SCANIA ARTIC K360 489648	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Tensioned wheelnuts to spec		623056
60 01/24/2025	1240725 Mechanic entered - Suspension Noisy movement in swaybar bush			623056
60 01/24/2025	1240754 Mechanic entered - Suspension Noisy LHF torque rod rubbers	Changed bushes		623056
60 01/24/2025	1240674 Mechanic entered - Elec and Light Exterior Lights RH side in	job completed		623056
60 01/24/2025	1240674 LAMP LED AMBER SIDE MARKER OEX	Fit new side indicator light.		623056
60 01/24/2025	1240674 Consumables			623056
60 01/01/2025	1224911 UNI-JOINT SCANIA P40 3059936			623056
60 11/28/2024	1230240 PTI Tablet Entered -Elec and Light - Exterior Lights N/S mid	Creditor #:PP-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:PP375443 Receiving #:403541 Date :2025-01-30		621970
60 11/28/2024	1230240 Consumables	Side markers all working.		621970
60 11/19/2024	1228039 Wipers and Washers hose split			621489
60 11/18/2024	1227877 PTI Tablet Entered -Body - Body. batteries not holding cha	replace split hose test found ok		621489
60 11/18/2024	1227877 BATTERY 1450CCA POS ON RHS EMFN200R	Fit new batteys x2		621489
60 11/18/2024	1227877 Consumables			621190
60 11/08/2024	1226020 PTI Tablet Entered -Elec and Light - Exterior Lights. N/S he			621028
60 11/01/2024	1224863	replaced globe tested all ok		621028
60 11/01/2024	1224863	VEHICLE SAFETY INSPECTION carried out safety inspection		621970
60 11/01/2024	1200697 Direct purchase - MECHANICAL	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS tentioned wheel nuts to 650Nm		621970
60 11/01/2024	1200697	Creditor #:PP-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:PP368607 Receiving #:399128 Date :2024-11-26 Elbow union p/n 321528		621970
60 11/01/2024	1200697 Direct purchase - MECHANICAL	Creditor #:PP-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:PP368607 Receiving #:399121 Date :2024-11-26 Elbow union p/n 812929		621970
60 11/01/2024	1200697 Direct Purchase - MECHANICAL	Creditor #:PP-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:PP368607 Receiving #:399122 Date :2024-11-26 Elbow union p/n 321528		621970
60 11/01/2024	1224911 Mechanic entered - Gearbox Driveline Vibration drive shaft	Creditor #:PP-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:PP368607 Receiving #:399122 Date :2024-11-26 Elbow union p/n 485990		621028
60 11/01/2024	1224894 Mechanic entered - Body Other n/s air con duct not secure	replaced both drive shaft uninversal kit p/n 3059936 and greased. test drove all ok		621028
60 11/01/2024	1224894 Consumables	secured duct back to roof.		620471
60 10/21/2024	1222118 Fault#:39368 - Ops Entered - Fault - Breakdown Gearbox Fault	driver fault all ok (broom brake was on)		620589
60 10/18/2024	1220376 Replace print film L3A L4 P2	Creditor #:PP-GLA010 GLASSPROTECH MELBOURNE P/O #:PP374083 Receiving #:397069 Date :2024-10-23		620170
60 10/14/2024	1208969 Consumables			620170
60 10/14/2024	1208969 SPRING LATCH SIDE PANEL OPTIMUS	advised mech used & not booked		619803
60 10/12/2024	1220376 Replace of damage print film	Replacement of damage film		619500
60 10/04/2024	1218730 PERFORM CAMPAIGN 11/24 CHECK & ENSURE ALL BUS DRIVE AXLE WHE	everything already fitted		619500
60 09/13/2024	1214406 Consumables			618897
60 09/13/2024	1214406 PTI Tablet Entered -Body - Body. excessive daily coolant	Repaired damaged heater hose above transmission.		618355
60 09/13/2024	1214406 PTI Tablet Entered -Body - Body. excessive daily coolant I	Repaired damaged heater hose above transmission.		618355
60 09/03/2024	1212021 Mechanic entered - Engine Noisy or Rattling	replaced noisy idler pulley. second hand pulley used		618203
60 08/21/2024	1208969 Consumables			618203
60 08/21/2024	1208969 PTI Tablet Entered -Body - O/S panel near middle wheels	Secured all loose side panels.		617871
60 08/14/2024	1207452 Consumables			617871
60 08/14/2024	1207452 PTI Tablet Entered -Elec and Light - Exterior Lights O/S/R q	find the faulty light change the unit.		617871
60 08/14/2024	1207452 LAMP LED SIDE RED/AMBER PEREI 52-98002			617871
60 08/13/2024	1206562 DIRECT PURCHASE - BUS INSPECTION	PP-ROASAF PP370185 RECVC392349		617871
60 08/12/2024	1206955 Consumables			617871
60 08/12/2024	1206955 Mechanic entered - Body Other n/s/f mudflap missing	Fit new mudflap.		617871
60 08/09/2024	1206562	VEHICLE SAFETY INSPECTION vsi completed		617871
60 08/09/2024	1206562	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS tension completed		617871
60 08/09/2024	1206562	ANNUAL SAFETY INSPECTION SERIAL # RSI 061536 WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25		617871
60 08/09/2024	1206678 Consumables			617871
60 08/09/2024	1206678 PTI Tablet Entered -Elec and Light - Exterior Lights O/S/R	check all side marker lamp found ok at this time		617871
60 08/09/2024	1206548 Consumables			617871
60 08/09/2024	1206390 Consumables			617871
60 08/09/2024	1206390 Mechanic entered - Body Other drivers blind not retracting e	repaired blind and emergency exit lights		617871
60 08/09/2024	1206548 Mechanic entered - Body Body Damage Missing mudflap.	Fit mudflap.		617871
60 08/09/2024	1206548 MUDFLAP 605MM X 330MM			617871
60 08/09/2024	1206575 Mechanic entered - Air System Air_Leak Doors Middle door saf	Changed safety edge door solenoid from 377 to 60 test found good		617750
60 08/05/2024	1205247 Consumables			617750
60 08/05/2024	1205247 PTI Tablet Entered -Elec and Light - Exterior Lights O/S mid	Checked lights all working.		617568
60 07/31/2024	1204322 Consumables			617568
60 07/31/2024	1204322 PTI Tablet Entered -Elec and Light - Exterior Lights. N/S/O	job completed		617568
60 07/31/2024	1204322 PTI Tablet Entered -Elec and Light - Exterior Lights. N/S/O/	repaired marker lights and change fuse with a 15amp		617327
60 07/24/2024	1200697 AIRBAG DRIVE/TAG AXLE SCANIA N	Creditor #:PP-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:PP368268 Receiving #:390868 Date :2024-07-25 on B/O ex Sweden eta 2W		617327
60 07/24/2024	1202953 Mechanic entered - Elec and Light Other power drain	checked the system mesure the batteryes find 50% and 57% capacity batteryes if the morning need to jumpstart the bus change the battery please		617043
60 07/24/2024	1202953 Consumables			617043
60 07/23/2024	1202661	is up to date.		617043
60 07/23/2024	1202661	CARRY OUT FIRE EXTINGUISHER TEST & TAG extinguisher is up to date		617043
60 07/20/2024	1202152 Mechanic entered - Wheels and Tyres Wheel Nut Retension posi	re tentioned positions 3/4/5/6 to 650Nm		617043
60 07/20/2024	1202152 Consumables			617043
60 07/19/2024	1200697 BRAKE PAD SET FRT/RR SCANIA K310UB & K320 2271805	fit 4 new airbag on center axle and set of brake pad		617043
60 07/16/2024	1200697 Mechanic entered - Suspension Other centre air bags cracked	Assisting job completed		617043
60 07/16/2024	1200697 Mechanic entered - Suspension Other centre air bags cracked	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS tentioned wheel nuts to 650Nm		617043
60 07/12/2024	1200233	VEHICLE SAFETY INSPECTION carried out safety inspection as per check list		617043
60 07/12/2024	1200233	PRE ANNUAL SAFETY INSPECTION CHECK carried out pre annual as per check list		617043
60 07/12/2024	1200253	CARRY OUT CCTV - B SERVICE AS PER CHECK LIST N/A		617043
60 07/05/2024	1198499 PERFORM CAMPAIGN 08/24 CHECK AND REPLACE WHERE REQUIRED ACCR	correct sticker fitted		617043
60 07/03/2024	1197986	CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST complate fire safety inspection as per checklist		616533
60 06/19/2024	1165564 TENSIONER BELT SCANIA SR4 L94 K230 1859654 1503113 2197002			615633
60 05/29/2024	1191312 Drv entered - Elec and Light Exterior Lights	change the interior lights		615633
60 05/29/2024	1191311 Drv entered - Dash Switches Not Working	change the demister fun		615633
60 05/29/2024	1191311 Consumables			615633
60 05/29/2024	1191312 Consumables			615633
60 05/29/2024	1189621 OIL ATF STEERING DEX-3 VALVOLINE			615633
60 05/29/2024	1189621 OIL AUTOMATIC MOBIL ATF MULTIPURPOSE(TEXTAMATIC)			615633
60 05/29/2024	1189621 Consumables			615633
60 05/29/2024	1189621 Consumables			615633
60 05/29/2024	1189621 Consumables			615513
60 05/23/2024	1190159	CARRY OUT A/C - A SERVICE AS PER CHECK LIST a/c A service been completed by Jimmy cold drive		615513
60 05/23/2024	1190159	Assisting Job Completed		615814
60 05/23/2024	1190159 DIRECT PURCHASE - AIR CONDITIO	Creditor #:PP-COLO04 COLD DRIVE PTY LTD P/O #:PP365788 Receiving #:387119 Date :2024-05-31 60 a/c A service		615212
60 05/21/2024	1189689 Mechanic entered - Engine Low Power Air filter blocked.	Replaced air filter. E218L		615212
60 05/21/2024	1189689 FILTER AIR OUTER SCANIA SR 3 & 4 0395773 AF25066			615212
60 05/21/2024	1189621 OIL ATF STEERING DEX-3 VALVOLINE			615212
60 05/21/2024	1189621 FILTER FUEL SCANIA L94 1372444			615212

60 05/21/2024	1189621	PAPER SPINNER FILTER OIL INSERT SCANIA VARIOUS MODELS		615212
60 05/21/2024	1189621	O-RING LARGE UPPER SPINNER FILTER SCANIA		615212
60 05/21/2024	1189621	O-RING LOWER SPINNER FILTER SCANIA L94 K124		615212
60 05/21/2024	1189621	OIL SAMPLE TEST KIT		615212
60 05/21/2024	1189621	FILTER ZF ECOMAT GEARBOX 4139-298-038 3098081		615212
60 05/21/2024	1189621	FILTER OIL SCANIA VARIOUS MODELS		615212
60 05/21/2024	1189621		CARRY OUT B SERVICE AS PER CHECK LIST Carried out B service as per checklis changed trans oil + filter (Mobil ATF).	615212
60 05/21/2024	1189621	OIL ENGINE ALL FLEET PLUS E900 15W-40		615212
60 05/17/2024	1189003	Drv entered - Dash Switches Not WorkingDemist not working	tested demister. working well on low and high. heat coming from vents after warmed up	615212
60 05/17/2024	1189003	Drv entered - Dash Switches Not WorkingDemist not working	repaired on w/o 1189003	615212
60 05/17/2024	1189003	Consumables		615212
60 05/14/2024	1188120	Drv entered - Dash Switches Not Working	Tested switches on dash all seemed ok during time of test.	614876
60 05/14/2024	1188120	Consumables		614876
60 05/07/2024	1186773	Drv entered - Body Body Damage	fit second hand broken a/c duct.	614727
60 05/07/2024	1186773	Consumables		614727
60 04/21/2024	1183690	Consumables		614093
60 04/21/2024	1183690	Mechanic entered - Wheels and Tyres Wheel Nut Retension Pos	complete n/s/r/r p7/8 retension to OEM spec 650Nm	614093
60 04/18/2024	1183160		VEHICLE SAFETY INSPECTION Carried out VSI as per checklist.	614093
60 04/18/2024	1183160		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Tensioned all wheelnuts to OEM spec 650nm.	614093
60 04/18/2024	1183223	Mechanic entered - Wheels and Tyres Worn Pos 7 tyre worn.	Fit new recap pair on pos 7&8.	614093
60 04/18/2024	1183223	TYRE 275/70R22.5 RECAP		614093
60 04/18/2024	1183223	Consumables		614093
60 03/05/2024	1174482	Mechanic entered - Body Passenger Seat Torn lower seat base	Replaced x2 second hand seat bases	612855
60 03/05/2024	1174482	Consumables		612855
60 02/13/2024	1169081	Mechanic entered - Fluid Leaks Other radiator cap requires	replace upper tank cap	611950
60 02/13/2024	1169081	CAP EXPANSION TANK 0.75BAR SCANIA K93 L94 L113 1403954		611950
60 02/13/2024	1169081		replaced radiator cap	611950
60 02/06/2024	1167542	Drv entered - Elec and Light dash indicator n/w Fault	Replaced indicator globe in dash tested ok	611708
60 02/06/2024	1167542	Consumables		611708
60 02/05/2024	1167179	PTI Tablet Entered -Elec and Light - Exterior Lights N/S/R u	Replaced globe from consumables	611526
60 02/05/2024	1167179	Consumables		611526
60 02/05/2024	1167200	PERFORM CAMPAIGN 01/24 REMOVAL OF OLD NO SMOKING DECALS	removal completed	611526
60 01/31/2024	1166340		CARRY OUT CCTV - A SERVICE AS PER CHECK LIST complate CCTV A service as per checklist clean the cavers	610950
60 01/25/2024	1165473		VEHICLE SAFETY INSPECTION carried out safety inspection as per check list	610950
60 01/25/2024	1165473		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS tentioned wheel nuts as per oem 650Nm	610950
60 01/25/2024	1165564	Engine Belts_Loose Noisy Missing	Replace alternator belt test found ok	610950
60 01/25/2024	1165564	BELT ALT W/PUMP CRANK SCANIA L94UAB 1803334 1389044		610950
60 01/25/2024	1165529	Mechanic entered - Elec and Light Interior Lights emergency	replace globes as required	610950
60 01/25/2024	1165528	Mechanic entered - Body Other light covers missing interior	fit missing light covers as required. second hand parts used from 733	610950
60 01/25/2024	1165526	Mechanic entered - Air System Air_Leak Interior front door a	replaced door air regulator. second hand part used from 472	610950
60 01/18/2024	1164262	Mechanic entered - Elec and Light Flat Batteries	Jump start bus live it running for 45 min test found ok (bus been sitting too long)	610950
60 01/04/2024	1161363	PERFORM CAMPAIGN 10/23 POSITIONING OF 2024 PTV FARES	Fit New Fare Decals	610950
60 12/20/2023	1159120		CARRY OUT FIRE EXTINGUISHER TEST & TAG checked tag all in date. Due Feb 24	610950
60 12/18/2023	1158557	PTI Tablet Entered -Elec and Light - Exterior Lights O/S/F	replaced headlight assembly. re wired indicator. second hand parts from 733 used.	610950
60 12/14/2023	1152460	HOSE RADIATOR LWR DC901 SCANIA L94 1872597 461737		610950
60 11/28/2023	1152507	PULLEY IDLER SMOOTH STL SCANIA L94UAB 40N0910		610408
60 11/27/2023	1154381	Drv entered - Fluid Leaks Rear of bus	checked fault. found coolant to be comming from radiator cap. tightened cap will continue to monitor.	610226
60 11/20/2023	1152507		replaced both tentioners. replaced idlers. replaced both drive belts.	610044
60 11/20/2023	1152507	BELT CRANK-TWIN A/C COMP SCANIA L94UAB(1389052)		610044
60 11/20/2023	1152507	BELT ALT W/PUMP CRANK SCANIA L94UAB 1803334 1389044		610044
60 11/20/2023	1152507	1803335 BELT	Creditor #:PP-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:PP354507 Receiving #:373951 Date :2023-11-21 (1534505 8PK2575)	610104
60 11/20/2023	1152507	COVER MOUNT BOLT AC BELT PULLE	Creditor #:PP-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:PP354507 Receiving #:373951 Date :2023-11-21 (1521031)	610104
60 11/17/2023	1152507	PULLEY IDLER SMOOTH PLASTIC SC	Creditor #:PP-MUL001 MULTISPARES LTD P/O #:PP354191 Receiving #:373903 Date :2023-11-20 60	610104
60 11/16/2023	1152460	Fault#:38968 - Ops Entered - Fault - Breakdown Belts Pulleys	replace bottom idler. replaced both drive belt tentioners. Second hand units fitted until we can recieve new items.	609806
60 11/16/2023	1152507	Mechanic entered - Engine Belts_Loose Noisy Missing require	job complete	609806
60 11/16/2023	1152507	BELT TENSIONER SCANIA SR4 1859	Creditor #:PP-MUL001 MULTISPARES LTD P/O #:PP354191 Receiving #:373727 Date :2023-11-17 60	609953
60 11/16/2023	1152507	PULLEY IDLER PLASTIC GROOVED S	Creditor #:PP-MUL001 MULTISPARES LTD P/O #:PP354191 Receiving #:373727 Date :2023-11-17 60	609953
60 11/03/2023	1150489		VEHICLE SAFETY INSPECTION performed safety inspection as per checklist	609378
60 11/03/2023	1150489		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS tensioned wheelnuts	609378
60 10/09/2023	1145028	Consumables		608119
60 10/09/2023	1145028	Elec and Light Exterior Lights o/s/r stop light n/w	replace o/s/r stop light globe from consumable test found good	608119
60 08/21/2023	1134679	PERFORM CAMPAIGN 05/23 POSITIONING OF NO SMOKING NO VAPING	school bus not required	606785
60 08/15/2023	1132669	DIRECT PURCHASE - BUS INSPECTI	Creditor #:PP-ROASAF ROAD SAFETY INSPECTIONS P/O #:PP348732 Receiving #:367155 Date :2023-08-16 60	606603
60 08/12/2023	1132865	Consumables		606420
60 08/12/2023	1132865	PTI Tablet Entered -Elec and Light - Exterior Lights O/S/R	replaced blown park globe	606420
60 08/11/2023	1132669		VEHICLE SAFETY INSPECTION	606420
60 08/11/2023	1132669		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	606420
60 08/11/2023	1132669		ANNUAL SAFETY INSPECTION SERIAL # RSI 055673 WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25	606420
60 07/23/2023	1128390	PERFORM CAMPAIGN 02/23 POSITIONING OF 2023 PTV FARES	fit new PTV fares stickers	605514
60 07/13/2023	1126371	Mechanic entered - Wheels and Tyres Wheel Nut Retension O/S	complete o/s/r p9 wheel nuts retension to OEM spec 650Nm	605213
60 07/13/2023	1126371	Consumables		605213
60 07/12/2023	1125878	Mechanic entered - Wheels and Tyres Worn Pos 9 tyre side wal	replaced broken tyre	605082
60 07/12/2023	1125878	TYRE 275/70R22.5 RECAP		605082
60 07/12/2023	1125878	Consumables		605082
60 07/11/2023	1125714		VEHICLE SAFETY INSPECTION Performed safety inspection as per checklist	605082
60 07/11/2023	1125714		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS tensioned wheelnuts	605082
60 07/11/2023	1125634		PRE ANNUAL SAFETY INSPECTION CHECK performed Pre annual as per checklist tensioned wheelnuts	605082
60 07/11/2023	1125634		CARRY OUT CCTV - B SERVICE AS PER CHECK LIST per forme CCTV B service as per checklist	605082
60 07/11/2023	1125717	PTI Tablet Entered -Wheels and Tyres - O/S/R P9 inner rear t	no fault found	605082
60 07/11/2023	1125717	Consumables		605082
60 07/05/2023	1124229		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST complate fire safety inspection as per checklist aply few cableties	605020
60 06/13/2023	1120126		CARRY OUT FIRE EXTINGUISHER TEST & TAG complete by ATS	604297
60 05/23/2023	1116315	Mechanic entered - Body Passenger Seat Torn o/s/r x 2	complete replacement rear seat x 2	603625
60 05/23/2023	1116315	Consumables		603625
60 05/19/2023	1116315	DIRECT PURCHASE - VANDALISM	Creditor #:PP-RP AUTO RP AUTO UPHOLSTERY PTY LTD P/O #:PP343659 Receiving #:361295 Date :2023-05-24 RE-TRIM DBL CUSHION 60	603625
60 05/18/2023	1115483	PTI Tablet Entered -Engine - belts or pullies Noisy or Rat	adjust belt tension test found ok required header cap	603321
60 05/18/2023	1115471	PTI Tablet Entered -Elec and Light - O/S/F Intermittent fa	removed o/s/f indicator connector change electrical wirring clips test found good	603321
60 05/18/2023	1115474	PTI Tablet Entered -Elec and Light - Exterior Lights O/S/F	job been completed on w/o 1115471	603321
60 05/18/2023	1115471	Consumables		603321
60 05/18/2023	1115474	Consumables		603321
60 05/18/2023	1115368		CARRY OUT A/C - B SERVICE AS PER CHECK LIST B service been completed by cold drive	603321
60 05/18/2023	1115368		Assisting A/C AB service been completed by cold drive	603321
60 05/18/2023	1115368	B Service	Creditor #:PP-COL004 COLD DRIVE PTY LTD P/O #:PP343757 Receiving #:361488 Date :2023-05-26 18/5/23	603747
60 05/18/2023	1115368		CARRY OUT A/C - A SERVICE AS PER CHECK LIST A service been completed by cold drive	603321
60 04/18/2023	1109374		VEHICLE SAFETY INSPECTION performed safety inspection as per checklist	602307

60 04/18/2023	1109374	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS tensioned wheelnuts	602307
60 04/05/2023	1107494	complate CCTV A service as per checklist	602187
60 03/29/2023	1104118 APPLY PRINT FILM L1 L2 L3 R3A	Creditor #:PP-GLA010 GLASSPROTECH MELBOURNE P/O #:PP339718 Receiving #:358267 Date :2023-04-06	602187
60 03/29/2023	1105851 Service	replaced rubbed through hydraulic oil line test driven no leaks found engine ccoling	601620
60 03/28/2023	1105851 emgine getting hot	removed intercooler and radiator fit second hand radiator and refit intercooler. filled engine with coolant and found hydraulic resevoir empty. refilled hydraulic resevoir. took for road test upon return to depot found engine covered with hydraulic oil inspected all hydraulic oil pipes lines and hoses no split found	601620
60 03/25/2023	1104118 Apply print film	Ventura Rosebud anti-graffiti film audit 846	601620
60 03/16/2023	1103324 Drv entered - Brakes Foot_Brakes Leaking Air	checked for air leaks tightened hose at air drier	601499
60 03/01/2023	1100154 Mechanic entered - Air System Air Not Building_Up	complete replacement air dryer	600668
60 03/01/2023	1100154 FILTER AIR DRYER SCANIA VOLVO(1393551)(20546795)(20424148)		600668
60 03/01/2023	1100313 Drv entered - Air dropping out then broms brake comes on.	test driven broms not coming on	600668
60 03/01/2023	1100313 Drv entered - Air dropping out then broms brake comes on.	test driven broms not coming on	600668
60 02/22/2023	1098517 Drv entered - Breakdown	hand railing loose tighten	600400
60 01/25/2023	1093009	VEHICLE SAFETY INSPECTION complete VSI as per check list	599299
60 01/25/2023	1093009	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS complete all wheel nuts tension to OEM spec	599299
60 12/15/2023	1086699 Fault#:38530 - Ops Entered - Fault - Breakdown Air System Fa	Checked vehicle for air leaks found front boosters leaking from hose connection found o/s front booster leaking from diaphragm replaced hose connections checked brakes for air leaks. ok.	599055
60 12/15/2022	1086699 DIAPHRAGM TYPE 24 DEEP DISH BRAKE BOOSTER BP24D		599055
60 12/15/2022	1086699	Found metal hanging underneath vehicle at middle curtain determined to be bracing for middle curtain removed metal strapping. ok.	599055
60 11/16/2022	1079940 Mechanic entered - Air System Air_Leak Rear o/s/r/t air bag	complete replacement rear tag axle air bags and level sensor x 4 test found ok	597554
60 11/15/2022	1079940 Mechanic entered - Air System Air_Leak Rear o/s/r/t air bag	complete replacement rear tag axle air bags x 4	597554
60 11/15/2022	1079940 FITTING ELBOW 16MM AIRBAG SCAN	Creditor #:PP-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:PP332499 Receiving #:349430 Date :2022-11-17 fittings airbags	597554
60 11/15/2022	1079940 ELBOW FITTING TWIN 16MM RR AIR	Creditor #:PP-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:PP332499 Receiving #:349430 Date :2022-11-17 airbag fittings	597554
60 11/14/2022	1079940 AIRBAG REAR 16MM SCANIA K280UB	Creditor #:PP-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:PP332097 Receiving #:349249 Date :2022-11-15	597554
60 11/09/2022	1079940 Mechanic entered - Air System Air_Leak Rear o/s/r/t air bag	parts ordered	597250
60 11/09/2022	1079940 SENSOR LEVEL FRT SCANIA L94UAB	Creditor #:PP-MUL001 MULTISPARES LTD P/O #:PP332100 Receiving #:348952 Date :2022-11-09	597250
60 11/09/2022	1079940 SENSOR LEVEL FRT SCANIA L94UAB	Creditor #:PP-MUL001 MULTISPARES LTD P/O #:PP332100 Receiving #:348972 Date :2022-11-09	597250
60 11/03/2022	1078934	VEHICLE SAFETY INSPECTION complete VSI as per check list	596999
60 11/03/2022	1078934	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS complete all wheel nuts tension to OEM spec	596999
60 11/02/2022	1078594	CARRY OUT FIRE EXTINGUISHER TEST & TAG	596999
60 10/19/2022	1070797 Repair engine low power	Creditor #:PP-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:PP330632 Receiving #:347822 Date :2022-10-21	596396
60 10/04/2022	1072982 PERFORM CAMPAIGN 10/22 WEAR A FACE MASK WHILE TRAVELLING D	complete removal face mask stickers	595959
60 09/20/2022	1070797 Drv entered - Engine Low Power	repaired by scania dandenong	595660
60 08/30/2022	1065786 APPLY PRINT FILM L2	Creditor #:PP-GLA010 GLASSPROTECH MELBOURNE P/O #:PP327789 Receiving #:344558 Date :2022-08-31 JOB STAGE 1	595660
60 08/27/2022	1065786 Apply print film	Stage-1 that was completed 1/8/22.	595660
60 08/24/2022	1065476 PERFORM CAMPAIGN 07/22 RETENSION ALL WHEEL NUTS TO OEM SPECI	tensioned wheelnuts	595660
60 08/15/2022	1062974 DIRECT PURCHASE - BUS INSPECTI	Creditor #:PP-ROASAF ROAD SAFETY INSPECTIONS P/O #:PP326947 Receiving #:343397 Date :2022-08-16 asi insp	595660
60 08/12/2022	1062998	TRANSMISSION CHECK AS PER CHECK LIST	595428
60 08/12/2022	1062974	VEHICLE SAFETY INSPECTION	595428
60 08/12/2022	1062974	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	595428
60 08/12/2022	1062985	VEHICLE SAFETY INSPECTION carried out on roadworthy	595428
60 08/12/2022	1062985	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	595428
60 08/12/2022	1062974	ANNUAL SAFETY INSPECTION SERIAL RSI #043868 WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25	595428
60 08/09/2022	1062154 ASI final check and wash	complete final ASI check	595428
60 08/09/2022	1062154 Consumables		595428
60 08/06/2022	1050504 alternator light on	parts ordered alternator replaced	595428
60 07/22/2022	1057683 Mechanic entered - Engine Other spiner filter defective	replaced spinner filter internal spinning bush housing spinner nut and housing cover bolt	595428
60 07/21/2022	1057683 FILTER OIL ROTARY SPINNER SCANIA		595428
60 07/21/2022	1057683 LOCK NUT		595428
60 07/21/2022	1057683 NUT OIL SPINNER HSG SCANIA K93CRB		595428
60 07/18/2022	1057750	PRE ANNUAL SAFETY INSPECTION CHECK	595428
60 07/18/2022	1057750	CARRY OUT CCTV - B SERVICE AS PER CHECK LIST	595428
60 07/18/2022	1057683 Mechanic entered - Engine Other spiner filter defectice part		595428
60 07/18/2022	1057689 Mechanic entered - Body Other Pre rsi defects	missing reflector on N/S replaced yellow grip surface replaced mid axle sway bar bushes	595428
60 07/18/2022	1057689 REFLECTOR AMBER HELLA 94x44mm		595428
60 07/18/2022	1057689 BUSH SWAY BAR MID AXLE SCANIA L94 489648 1919024		595428
60 07/18/2022	1057689 EDGE STEP INSERT YELLOW 40MM P/M 2B10378SER		595428
60 07/15/2022	1057461	CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST complate fire safety inspection	595428
60 07/15/2022	1057448	CARRY OUT B SERVICE AS PER CHECK LIST complete B service as per check list	595428
60 07/15/2022	1057448 FILTER ZF ECOMAT GEARBOX(4139-298-038)(1193281)		595428
60 07/15/2022	1057448 O-RING SPINNER FILTER SCANIA L94		595428
60 07/15/2022	1057448 O-RING LARGE SPINNER FILTER SCANIA L94 & K230		595428
60 07/15/2022	1057448 PAPER SPINNER FILTER OIL INSERT SCANIA L94		595428
60 07/15/2022	1057448 FILTER OIL D7C VOLVO B7RSA(466634)		595428
60 07/15/2022	1057448 FILTER FUEL CHASSIS SCANIA L94 UB(1393640)(PSD470/1)		595428
60 07/15/2022	1057448 Consumables		595428
60 07/15/2022	1057448 Consumables		595428
60 07/15/2022	1057448 Consumables		595428
60 07/15/2022	1057448 Consumables		595428
60 07/11/2022	1050503 Service	removed and replaced tie rod amd drag link complete assemblies michele assisted with fitment and adjusted sterring together	595428
60 07/11/2022	1056316 Drv entered - A/C Heating Warning Light On	ran up ac no fault lightspresent on control units	595428
60 06/24/2022	1050570 Drv entered - Engine Low Power	Returned on 23/06/22	595428
60 06/23/2022	1050570 DIRECT BRAKES	Creditor #:PP-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:PP323750 Receiving #:339851 Date :2022-06-24 Ocheck brakes for not holding air pressure	595428
60 06/23/2022	1050570 Direct Purchase - BODYWORK	Creditor #:PP-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:PP323750 Receiving #:339851 Date :2022-06-24 check turntable for jack knife loss of power	595428
60 06/09/2022	1050504 ALTERNATOR 24V 140A SCANIA (05	Creditor #:PP-MUL001 MULTISPARES LTD P/O #:PP322964 Receiving #:338948 Date :2022-06-09	595428
60 06/08/2022	1050503 DRAGLINK SCANIA SR4 1897667 2	Creditor #:PP-MUL001 MULTISPARES LTD P/O #:PP322964 Receiving #:338832 Date :2022-06-08	595428
60 06/08/2022	1050503 TIE ROD ASSY SCANIA L94/K230/N	Creditor #:PP-MUL001 MULTISPARES LTD P/O #:PP322964 Receiving #:338832 Date :2022-06-08	595428
60 06/07/2022	1050503 drag link sstarting to show wear	parts ordered	595428
60 06/07/2022	1050570 Drv entered - Engine Low Power	sent to scania	595428
60 06/06/2022	1025325 Service	ordered x2 alternators	595428
60 06/06/2022	1025325 Mechanic entered - Elec and Light Other warning light batter	Driver reported battery light on dash checked batteries ok charge rate 26v removed voltage regulators found both worn fit new ones ran engine now charging at 27v but battery light still on and no tachometer.	595428
60 06/06/2022	1025325 REGULATOR ALTERNATOR BOSCH 140AMP MERC 0500LE 1197311315		595428
60 06/03/2022	1050037	PRE ANNUAL SAFETY INSPECTION CHECK complete P/ASI as per check list	595428
60 06/03/2022	1050037	CARRY OUT CCTV - B SERVICE AS PER CHECK LIST	595428
60 06/03/2022	1049086 FRONT AIRBAGS LEAKING	completee replacement front airbags	595428
60 06/03/2022	1050032 PERFORM CAMPAIGN 03/22 QR CODE & SELECTED COVID19 DECAL REM	removed decals	595428
60 06/01/2022	1049086 Service	removed front ns airbag wrong parts received re fitted old and re ordered parts	595428
60 06/01/2022	1049086 AIRBAG FRT SCANIA L94UAB 14403	Creditor #:PP-MUL001 MULTISPARES LTD P/O #:PP322586 Receiving #:338460 Date :2022-06-02 ord multi VC version of gen 1475106 as NLA & crosses to 2809671 is incorrect	595428
60 05/30/2022	1049086 FRONT AIRBAGS LEAKING	parts orderd	595428
60 05/13/2022	1046172 Drv entered - Elec and Light Interior LightsOff side front	check on O/S/F head light lens found ok	594800
60 05/13/2022	1046172 Consumables		594800
60 05/12/2022	1045856	VEHICLE SAFETY INSPECTION complete VSI as per check list	594604
60 05/12/2022	1045856	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS complete all wheel nuts tension to OEM spec	594604
60 05/12/2022	1045894 Consumables		594604
60 05/12/2022	1045894 Drv entered - Elec and Light Exterior Lights	check on exterior light found ok at this timte	594604
60 05/06/2022	1044603	Assisting	593601
60 05/06/2022	1044603	CARRY OUT A/C - A SERVICE AS PER CHECK LIST	593601

60	05/05/2022	1044350	complete by csaba	CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST	593601
60	05/04/2022	1044036	Drv entered - Air System Air Not Building_Up	replaced air dryer cyclone seperator	593601
60	05/04/2022	1044036	AIR COMPRESSOR RR DRIVE SCANIA	Creditor #:PP-MUL001 MULTISPARES LTD P/O #:PP320853 Receiving #:336561 Date :2022-05-05	593943
60	05/04/2022	1044036	BOLT COMPRESSOR GEAR SCANIA	Creditor #:PP-MUL001 MULTISPARES LTD P/O #:PP320853 Receiving #:336561 Date :2022-05-05	593943
60	05/04/2022	1044036	SEAL O-RING COMPRESSOR MOUNT	Creditor #:PP-MUL001 MULTISPARES LTD P/O #:PP320853 Receiving #:336561 Date :2022-05-05	593943
60	05/04/2022	1044036	O-RING COMPRESSOR 11MM ID SCA	Creditor #:PP-MUL001 MULTISPARES LTD P/O #:PP320853 Receiving #:336561 Date :2022-05-05	593943
60	05/04/2022	1044036	GASKET INSPECTION PLATE	Creditor #:PP-MUL001 MULTISPARES LTD P/O #:PP320853 Receiving #:336561 Date :2022-05-05	593943
60	05/04/2022	1044036	O-RING SEAL INSPECTION PLATE (	Creditor #:PP-MUL001 MULTISPARES LTD P/O #:PP320853 Receiving #:336561 Date :2022-05-05	593943
60	05/04/2022	1044036	AIR DRYER ASSY SCANIA 174385	Creditor #:PP-MUL001 MULTISPARES LTD P/O #:PP320853 Receiving #:336561 Date :2022-05-05	593943
60	05/04/2022	1044036	CONDENSOR / OIL COLLECTOR AIR	Creditor #:PP-MUL001 MULTISPARES LTD P/O #:PP320853 Receiving #:336561 Date :2022-05-05	593943
60	05/04/2022	1044603	DIRECT PURCHASE - AIR CONDITIO	Creditor #:PP-COLO04 COLD DRIVE PTY LTD P/O #:PP320953 Receiving #:336816 Date :2022-05-10 ac a svc	594480
60	05/03/2022	1043774		CARRY OUT FIRE EXTINGUISHER TEST & TAG	593601
60	04/29/2022	1029364	DIRECT BRAKES	Creditor #:PP-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:PP320410 Receiving #:336265 Date :2022-05-02 repair air system	593601
60	03/02/2022	1013962	Mechanic entered - Body Other	replaced foot brake valve	593347
60	03/02/2022	1013962	Consumables		593347
60	02/22/2022	1030625	os rear booster leaking	replaced booster ok	593347
60	02/22/2022	1030625	BRAKE BOOSTER RR TYPE 24/30 16	Creditor #:PP-MUL001 MULTISPARES LTD P/O #:PP316542 Receiving #:331955 Date :2022-02-23	593347
60	02/16/2022	1029346		VEHICLE SAFETY INSPECTION	593347
60	02/16/2022	1029346		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	593347
60	02/16/2022	1029364	Mechanic entered - Brakes Foot_Brakes Leaking Air Foot brake	replaced foot brake valve with new valve already booked	593347
60	02/14/2022	1028584	REMOVE OLD 2020 DECAL AND FIT NEW 2022 DECAL POSITION AS S	school bus not required	592980
60	01/22/2022	1023024	Apply print film	cpmpleted 30/11/21	592668
60	01/18/2022	1023024	Apply print film L2 Modesty	Creditor #:PP-GLA010 GLASSPROTECH MELBOURNE P/O #:PP314316 Receiving #:329870 Date :2022-01-21	592668
60	01/07/2022	1021393		CARRY OUT CCTV - A SERVICE AS PER CHECK LIST Csaba performed CCTV A service as per checklist	592668
60	11/26/2021	1013962	VALVE FOOTBRAKE C/W RET SWITCH	Creditor #:PP-MUL001 MULTISPARES LTD P/O #:PP311616 Receiving #:326804 Date :2021-11-29	591828
60	11/25/2021	1013862		VEHICLE SAFETY INSPECTION	591457
60	11/25/2021	1013862		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	591457
60	11/25/2021	1013862			591457
60	11/25/2021	1013965	Mechanic entered - Wheels and Tyres Other O/S/Middle wheel m	put new o/s/middle squirell	591457
60	11/25/2021	1013965	WHEEL NUT SQUIRREL TUL-10STD-UK		591457
60	11/25/2021	1013965	Consumables		591457
60	11/25/2021	1013862	PERFORM CAMPAIGN 20/20 PRE SUMMER PREVENTATIVE MAINTENANCE		591457
60	10/26/2021	1007579	Mechanic entered - Elec and Light Exterior Lights O/S/F head	replaced O/S/F globe	590299
60	10/26/2021	1007579	GLOBE 24V 75/70W H4		590299
60	10/26/2021	1007579	Consumables		590299
60	10/25/2021	1007395	Mechanic entered - Fluid Leaks Rear of bus Rear fuel bleedin	Replace bleeding primer Oring and Copper washers	590299
60	10/11/2021	1004640		CARRY OUT FIRE EXTINGUISHER TEST & TAG	590299
60	09/20/2021	1000590	PERFORM CAMPAIGN 17/21 QR CODE DECAL FITMENT TO ALL BUSES		590299
60	09/02/2021	996508		VEHICLE SAFETY INSPECTION	590299
60	09/02/2021	996508		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	590299
60	07/12/2021	984996	Mechanic entered - Suspension Kneeel/ Raise	Checked suspension level height compared to 2 other scania l94 artics too high supported body and checked level rod rod was loose on level arm tightened and re-adjusted suspension height to match the other 2 rechecked after raising and lowering all good.	589175
60	07/12/2021	984997	Mechanic entered - Body Other Drivers seat calibration	turned weight adjuster to max removed back cover re-aligned max weight to correct position.	589175
60	07/12/2021	984997	Consumables		589175
60	06/10/2021	979337		VEHICLE SAFETY INSPECTION	588080
60	06/10/2021	979337		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	588080
60	06/10/2021	979337		ANNUAL SAFETY INSPECTION SERIAL #.....L453894..... WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25	588080
60	06/10/2021	979337	DIRECT PURCHASE - BUS INSPECTI	Creditor #:PP-FLE010 FLEETCHECK BUS PTY LTD P/O #:PP300798 Receiving #:314679 Date :2021-06-11 asi	588368
60	06/10/2021	979330	worn sway bar bushes front	replaced front and mid sway bar bushes	588080
60	06/09/2021	979330	BUSH SWAY BAR BUSH D-SHAPE	Creditor #:PP-MUL001 MULTISPARES LTD P/O #:PP300668 Receiving #:314676 Date :2021-06-11 60	588368
60	06/08/2021	978855	Service	re tenstioned all rear wheel nuts	588080
60	06/07/2021	978721	Mechanic entered - Wheels and Tyres Vibration	Found O/S kingpin loose greased and rechecked no more movement found o/s/f tyre flat spotting and n/s/f tyre wearing uneven replaced both front tyres tensioned wheel nuts to 650NM	588080
60	06/07/2021	978721	TYRE 275/70R22.5 NEW		588080
60	06/07/2021	978721	TYRE 275/70R22.5 NEW		588080
60	06/07/2021	978721	Consumables		588080
60	06/04/2021	978394	Service	re tenstioned pos 9 and 10	588080
60	06/03/2021	978081	Mechanic entered - Wheels and Tyres Wheel Nut Retension All	re tenstioned all 3rd axel wheel nuts	588080
60	06/03/2021	978081	Consumables		588080
60	06/03/2021	978128	remove and fit correct size tyres to pos 9 and 10 (remove	removed wrong tyres and fit correct tyres	588080
60	06/03/2021	978128	TYRE 275/70R22.5 RECAP		588080
60	06/02/2021	977950	Mechanic entered - Brakes Other Rear brakes low	replaced all rear brake pads and O/S/R tyres tenstioned wheel nuts and adjusted brakes	588080
60	06/02/2021	977950	SET DISC PAD SET SCANIA / MERCEDES 0500		588080
60	06/02/2021	977950	TYRE 295/80R22.5 RECAP		588080
60	06/01/2021	977640		PRE ANNUAL SAFETY INSPECTION CHECK	588080
60	06/01/2021	977640		CARRY OUT CCTV - B SERVICE AS PER CHECK LIST	588080
60	05/28/2021	976225	Direct Purchase - ELECTRICAL	Creditor #:PP-EAS002 EASTCOAST TRUCK & BUS SERVICE P/O #:PP299641 Receiving #:313750 Date :2021-05-31 fire safe	588080
60	05/25/2021	976225		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST	587742
60	05/25/2021	976225		Assisting completed by neil	587742
60	05/12/2021	973876		CARRY OUT A/C - B SERVICE AS PER CHECK LIST	587029
60	05/12/2021	973876	DIRECT PURCHASE - AIR CONDITIO	Creditor #:PP-COLO04 COLD DRIVE PTY LTD P/O #:PP299334 Receiving #:312986 Date :2021-05-20 ac b svc	587490
60	05/12/2021	973876		CARRY OUT A/C - A SERVICE AS PER CHECK LIST	587029
60	04/08/2021	966872		CARRY OUT FIRE EXTINGUISHER TEST & TAG	585794
60	04/07/2021	966428	PERFORM CAMPAIGN 10/21 FITMENT OF AUTHORISED OPERATOR DECAL		585794
60	04/01/2021	965714	Mechanic entered - Elec and Light Exterior Lights O/S/R uppe	globe had melted light plastic frame replaced globe and frame	585794
60	04/01/2021	965714	LIGHT CLEARANCE LIGHT AMBER (86510) HL2149		585794
60	03/26/2021	963631	PERFORM CAMPAIGN 09/21 POSITIONING OF 2021 PTV FARES & COVI	fitted	585451
60	03/22/2021	962264	Mechanic entered - Elec and Light Exterior Lights	Replaced blown O/S/R top park light globe checked light operation all good.	585019
60	03/22/2021	962265	Mechanic entered - Elec and Light Reverse Buzzer	Removed and replaced defective reverse buzzer tested in reverse buzzer is now working	585019
60	03/22/2021	962265	BUZZER REVERSING 24V 102DB NR72602		585019
60	03/22/2021	962264	Consumables		585019
60	03/22/2021	962265	Consumables		585019
60	03/19/2021	961833	top os brake light housing damaged	fitted new brake assembly os rear upper	585019
60	03/19/2021	961833	Consumables		585019
60	03/17/2021	961109	Drv entered - Elec and Light Indicators Not Working	replaced globe and repaired wiring	584848
60	03/17/2021	961109	Consumables		584848
60	03/12/2021	960089	re tenstion ns trailer wheel nuts	re tenstioned ns trailer wheel nuts	584666
60	03/11/2021	959906	Wheels and Tyres nsinner trailer	replaced ns rear tinner trailer tyre tenstioned wheel nuts	584666
60	03/11/2021	959906	TYRE 275/70R22.5 RECAP		584666
60	03/11/2021	959906	Consumables		584666
60	03/10/2021	959315		VEHICLE SAFETY INSPECTION	584444
60	03/10/2021	959315		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	584444
60	02/11/2021	953015	Mechanic entered - Air System Air_Leak Doors middle door ext	dumped air from bus and timed air pressure build up: build up time within acceptable limits . brought bus into workshop and inspected for air leaks. Found rear door emergency exit button leaking and one air tank drain valve. Replaced both built up air pressure leaks fixed. Replaced air dryer canister and adjusted regulato	583056
60	02/11/2021	953015	BUTTON CLIPPARD DOOR VALVE 11916-2		583056
60	02/11/2021	953015	VALVE CLIPPARD DOOR OPEN/CLOSE (11916-2) BUTTON		583056
60	02/11/2021	953015	FILTER AIR DRYER SCANIA SERIES 4 (1393551) (20546795)		583056
60	02/05/2021	950491	Engine Low Power engine light on	fit speedo back from testing/calibrating took for long road test to check if fault would re-occur no fault.	582412

60 02/04/2021	950491 Direct Purchase - ELECTRICAL	Creditor #:PP-LON002 LONSDALE ST AUTO ELECTRICS P/O #:PP292256 Receiving #:305574 Date :2021-02-09 Speedo head fault	582919
60 02/02/2021	950491 Engine Low Power engine light on	checked wiring at speed gauge no broken wires checked flash fault code (27) chased and inspected wire from gauge to ecu in trailer checked for continuity and short to ground all good removed speedo gauge from bus 13 to test and fault went away parked bus in corner and removed speedo to be sent away for repair.	582412
60 02/01/2021	942115 DIRECT PURCHASE - ELECTRICAL	Creditor #:PP-BWE001 BWERE ELECTRICS PTY LTD P/O #:PP290201 Receiving #:306364 Date :2021-02-18 cctv svc	583282
60 01/01/2021	934740 DIRECT PURCHASE - GLASS	Creditor #:PP-ALP003 ALPHA BUS GLASS PTY LTD P/O #:PP287971 Receiving #:303619 Date :2021-01-11 windscreen replaced	582210
60 12/18/2020	942115	CARRY OUT CCTV - A SERVICE AS PER CHECK LIST	582210
60 12/09/2020	940263	VEHICLE SAFETY INSPECTION	582210
60 12/09/2020	940263	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	582210
60 12/09/2020	940263	Assisting	581950
60 12/02/2020	938824 PERFORM CAMPAIGN 27/20 UPDATED INTERNAL BUS NUMBER DECALS		581779
60 11/30/2020	938007 Drv entered - Elec and Light Electric Mirrors Faulty	checked mirrors ok mirrors are the non electric type	581779
60 11/30/2020	938264 incorrect entry	INCORRECT ENTRY	581779
60 11/30/2020	938263 Drv entered - Body Windows FrontLeft hand mirror turning	REPAIRED MIRROR BRACKETS AT BODY	581779
60 11/26/2020	935930 repair wiring for fire alarm	Creditor #:PP-LON002 LONSDALE ST AUTO ELECTRICS P/O #:PP288198 Receiving #:300965 Date :2020-11-27 repair wiring fire alarm intermittent	581779
60 11/25/2020	936233 Overhaul AC system x 2	Creditor #:PP-COL004 COLD DRIVE PTY LTD P/O #:PP288615 Receiving #:301112 Date :2020-11-30 repair ac	581779
60 11/24/2020	936233 Drv entered - A/C Heating Not Cooling	replaced steering damper	581693
60 11/23/2020	935930 fire alarm fault in turntable	repaird by lonsdale	581609
60 11/20/2020	935163 Remove old poster and fit you must wear a face mask when t		581484
60 11/19/2020	934740 Accident - FRONT screen cracked by 1378	replaced windscreen	581484
60 11/18/2020	934085 PERFORM CAMPAIGN 26/20 REAR EXIT DECAL MAKE YOUR MARK & SER	removed exit decals and service sticker	581484
60 11/17/2020	933899 Fluid Leaks Rear of bus Fluid Leak Engine Bay	found fan motor leaking oil removed completey radiator intercooler fan assembly high pressure cleaned all cooleres like new re assemble fan assembly tightened loose oil line to fan motor re installed and tightened all hosses topped up fluids test driven vehichle all fixed	581484
60 11/17/2020	933899 Fluid Leaks Rear of bus Fluid Leak Engine Bay	Assisting	581484
60 11/12/2020	931932 SENSOR FIRE MONITOR ELC / SEN	Creditor #:PP-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:PP287275 Receiving #:300726 Date :2020-11-24	581693
60 11/12/2020	932739 BATTERY POS ON RHS (N200B)		581234
60 11/12/2020	932739 Mechanic entered - Elec and Light Flat Batteries	removed and fit new batteries had to grind part of the body back a few mm so the positive post woulnt touch the body.	581234
60 11/11/2020	932430 Drv entered - Elec and Light AM-FM Radio	removed head unit removed and refit fuse to reset unit radio now works fine	581149
60 11/11/2020	932430 fm radio		581149
60 11/10/2020	931932 Drv entered - Warning Lights Engine	diagnosed fire sensor wiring make new loom	580981
60 10/26/2020	928442 Mechanic entered - Elec and Light Exterior Lights		580191
60 10/26/2020	928442 LAMP LED NUMBER PLATE & EXIT LIGHT (250120) (2559)		580191
60 10/26/2020	928442 Consumables		580391
60 10/20/2020	927584 Drv entered - Elec and Light Warning Light On Dash	repaired passenger stop bell	579937
60 10/20/2020	927584 Consumables		580109
60 10/15/2020	926663 Suspension (None) front sway bar bushes worn	replaced front sway bar bushes	579772
60 10/15/2020	926663 BUSH SWAY BAR BUSH D-SHAPE MID AXLE SCANIA L94 489648		579772
60 10/15/2020	926663 BUSH RR SWAY BAR (50MM I/D) SCANIA K93CRB 228483		579772
60 10/15/2020	926663 SHOCK ABSORBER RR D/AXLE SCANIA K124IB 1478317		579772
60 10/15/2020	926644 Elec and Light Flat Batteries	replaced batteries	579772
60 10/15/2020	926644 BATTERY 1030CCA POS ON RHS		579772
60 10/15/2020	926644 Consumables		579854
60 10/14/2020	926121 Drv entered - Warning Lights Engine	jump started bus at padua mornington	579638
60 10/14/2020	926121 Drv entered - CCTV Warning Light On		579638
60 10/12/2020	925505 flat batteries		579423
60 10/12/2020	925505 Consumables	jumpstarted	579638
60 09/16/2020	920315 flat batteries		579237
60 09/10/2020	919240	jump started	579237
60 09/10/2020	919240	VEHICLE SAFETY INSPECTION	579237
60 09/09/2020	919048	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	579237
60 08/05/2020	911112 Remove old A3 Poster and fit with You can no longer top up	CARRY OUT FIRE EXTINGUISHER TEST & TAG	579237
60 06/25/2020	903195 Drv entered - Warning Lights Engine	fitted	579027
60 06/22/2020	901046 Direct Purchase - ELECTRICAL	diagnosed traced all wiring and repaired burnt wiring	578944
60 06/22/2020	901046 Consumables	Creditor #:PP-EAS002 EASTCOAST TRUCK & BUS SERVICE P/O #:PP277465 Receiving #:289793 Date :2020-06-24 bus minder fitment	578900
60 06/16/2020	901157 PERFORM CAMPAIGN 21/19 PUSH TO TALK / BUS MINDER SECURITY C		578285
60 06/15/2020	901046 BusMinder (None) install	swapped bus minder from 13	578285
60 06/13/2020	900757 Fit A3 Poster in poster frame and fit decals as requested i		578285
60 06/12/2020	900388 Air System (None) air leak at nsm brake air hose	repaired brake air hose	578285
60 06/11/2020	899993	VEHICLE SAFETY INSPECTION	578285
60 06/11/2020	899993 Service	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	578285
60 06/11/2020	899993	ANNUAL SAFETY INSPECTION SERIAL #k668710 WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25	578285
60 06/11/2020	899993 DIRECT PURCHASE - BUS INSPECTI	Creditor #:PP-FLE010 FLEETCHECK BUS PTY LTD P/O #:PP277256 Receiving #:289106 Date :2020-06-16 asi	578527
60 06/01/2020	897471 DIRECT PURCHASE - AIR CONDITIO	Creditor #:PP-COL004 COLD DRIVE PTY LTD P/O #:PP276534 Receiving #:288636 Date :2020-06-09 ac a svc	578285
60 05/29/2020	897388	CARRY OUT CCTV - A SERVICE AS PER CHECK LIST	578285
60 05/29/2020	897388 DIRECT PURCHASE - ELECTRICAL	Creditor #:PP-BWE001 BWERE ELECTRICS PTY LTD P/O #:PP276526 Receiving #:288310 Date :2020-06-03 cctv svc	578285
60 05/29/2020	897471	CARRY OUT A/C - A SERVICE AS PER CHECK LIST	578285
60 05/28/2020	897152	CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST	578285
60 05/28/2020	897152 Direct Purchase - ELECTRICAL	Creditor #:PP-LON002 LONSDALE ST AUTO ELECTRICS P/O #:PP276390 Receiving #:288003 Date :2020-05-29 fire safe	578285
60 05/27/2020	894993 sway bar bushes worn	replaced front axel and mid axel sway bar bushes	578285
60 05/26/2020	896569 Elec and Light Flat Batteries	jumpstarted	578285
60 05/15/2020	894993 BUSH FRT SWAY BAR SCANIA K23	Creditor #:PP-MUL001 MULTISPARES LTD P/O #:PP275573 Receiving #:286962 Date :2020-05-18 #60	578285
60 05/15/2020	894993 BUSH SWAY BAR BUSH D-SHAPE	Creditor #:PP-MUL001 MULTISPARES LTD P/O #:PP275573 Receiving #:286962 Date :2020-05-18 #60	578285
60 05/15/2020	894618 ns rear marker lamps	fitted second hand lamps x2	578285
60 05/15/2020	894618 check interior	checked all interior and exterior globes	578285
60 05/13/2020	894618 ASI bus wash and check	steam cleaned engine gearbox	578285
60 05/08/2020	893305	re tenstione all drive wheel nuts	578285
60 05/07/2020	892908	PRE ANNUAL SAFETY INSPECTION CHECK	578285
60 05/07/2020	892908	CARRY OUT CCTV - B SERVICE AS PER CHECK LIST	578285
60 05/07/2020	893029 cracked lense	replaced cracked lense	578285
60 05/07/2020	893029 LAMP SIDE MARKER (RED+AMBER)		578285
60 05/07/2020	893033 pad wear sensor light on dash	removed wheels on mid axel inspect all brakes and found a damaged ns pad wear sensor replaced sensor fitted wheels tenstioned wheel nuts	578285
60 04/29/2020	891152	SERVICE MOISTURE EJECTOR	578162
60 04/29/2020	891152	CARRY OUT TUNE-UP SERVICE AS PER CHECK LIST	578162
60 04/29/2020	891133 FILTER AIR FILTER (395773) AF25066		578162
60 04/29/2020	891133	CARRY OUT C SERVICE AS PER CHECK LIST	578162
60 04/29/2020	891133 FILTER FUEL FILTER SCANIA SR4 (1372444)		578162
60 04/29/2020	891133 FILTER STEERING FILTER (153468) (0153468)(349619)		578162
60 04/29/2020	891133 FILTER OIL STANDARD VOLVO B12 [EARLY] (46634-3)		578162
60 04/29/2020	891133 FILTER ZF TRANS ECOMAT (1193281-1)(4139 298 038 01)		578162
60 04/29/2020	891133 FILTER FUEL FILTER SCANIA SR4 (1393640)		578162
60 04/29/2020	891133 Consumables		578285
60 04/29/2020	891133 Consumables		578285
60 04/29/2020	891133 Consumables		578285
60 04/29/2020	891133 Consumables		578285
60 04/29/2020	891133 Service	CARRY OUT B SERVICE AS PER CHECK LIST	578162
60 04/29/2020	891133 Consumables		578285
60 04/29/2020	891133 Consumables		578285
60 04/29/2020	891133 Consumables		578285

60 04/29/2020	891133 Consumables		578285
60 04/01/2020	846129 Service	fitted new pads ns tag tenstioned wheel nuts 07/12/2019	578162
60 03/24/2020	882789	VEHICLE SAFETY INSPECTION	578162
60 03/24/2020	882789	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	578162
60 03/24/2020	882764 Tape off front Seats of All Route and Rail Buses with spec		578162
60 03/02/2020	877870 Service	re tenstioned all wehel nuts	576698
60 02/28/2020	877475 Drv entered - Gearbox Driveline Rough Gear Change	test driven and checked gearbox oil ok	576698
60 02/28/2020	877476 Drv entered - Elec and Light Warning Light On Dash	checked dash no faults found	576698
60 02/28/2020	877661 Brakes worn front	removed front wheels and replaced front brake pads and x1 wear sensor measured rotors @45mm mm removed mid axel checked brake pads 80 percent rotors liker new removed rear rear axel wheels measured rotors at 40.2mm pads at 70 percent fitted all wheelstenstioneddall wheels	576698
60 02/28/2020	877661 assisted		576698
60 02/24/2020	876133 Ops Entered - Fault - Flat battery at Padua - change over r	started at rear	576317
60 02/21/2020	875755 Ops Entered - Fault - Wipers and Washers Wipers Not Working	adjusted wipers	576317
60 02/15/2020	874439 Drv entered - A/C Heating Not Cooling		576055
60 02/14/2020	874211 Ops Entered - Fault - Elec and Light Flat Batteries - Rout		576055
60 02/13/2020	874211 DIRECT PURCHASE - AIR CONDITIO	repaired by cold drive	576317
60 02/13/2020	876567 Completed by ATS	Creditor #:PP-COL004 COLD DRIVE PTY LTD P/O #:PP268877 Receiving #:280029 Date :2020-02-20 repair air con lines in turntable area	576107
60 02/03/2020	871296 Ops Entered - Fault - A/C Heating Not Cooling - Route: opa	CARRY OUT FIRE EXTINGUISHER TEST & TAG	575381
60 02/03/2020	871296 Drv entered - A/C Heating Not Cooling		575381
60 01/30/2020	870371 Drv entered - Engine Low Power	repaired by cold drive	575107
60 01/18/2020	868177 PERFORM CAMPAIGN 01/20 POSITIONING OF 2020 PTV FARES & PRIO	test driven and drove normal	575107
60 01/01/2020	846126 ABS Pulse Sensor Kit - 40V6300	fitted	575107
60 01/01/2020	846126 49G8410 - Wear sensor kit pin	Creditor #:PP-MUL001 MULTISPARES LTD P/O #:PP263575 Receiving #:278313 Date :2020-01-30	575107
60 01/01/2020	846126 49G8411 - Wear sensor kit blo	Creditor #:PP-MUL001 MULTISPARES LTD P/O #:PP263575-1 Receiving #:278701 Date :2020-02-04	575464
60 12/31/2019	864433	Creditor #:PP-MUL001 MULTISPARES LTD P/O #:PP263575-1 Receiving #:278701 Date :2020-02-04	575464
60 12/31/2019	864433	VEHICLE SAFETY INSPECTION	575107
60 12/31/2019	864433 PERFORM CAMPAIGN 28/19 ROUTE BUS WHEELCHAIR TRIAL DECAL INS	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	575107
60 12/19/2019	819022 GLOBE & HOLDER INSTRUMENT PANEL GREY (NR47774)	fitted decals	575107
60 12/19/2019	819022 Consumables		575107
60 12/07/2019	860120 A3 Poster Frame Adhesive Decal Campaign please remove old		575107
60 12/04/2019	846129 seal # 1415136	xx	575107
60 12/02/2019	846124 Suspension O/S Tag axel sway bar link boot split.	Creditor #:PT-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:264079 Receiving #:274635 Date :2019-12-10	575107
60 12/02/2019	846129 Fluid Leaks Rear of bus Tag axel Hubseals leaking.	REPLACED SWAY BAR LINKS	575107
60 12/02/2019	846126 Air System Air_Leak RearMid airtank drain plug leaks	REMOVED OS TAG BRAKE ASSEMBLY FITTED NEW BRAKE BOOSTERNEWROTOR NEW CALIPER NEW PADS NEW ABS AND WEARSSENSORSTENSTIONED HUB NUT AND WHEEL NUTS	575107
60 12/01/2019	846129 Rationalised Caliper 40G8417KN	REPLACED DRAIN PLUG	575107
60 12/01/2019	846129 Disc Pad Set - Beral 40G7501BE	Creditor #:PP-MUL001 MULTISPARES LTD P/O #:PP263575 Receiving #:276207 Date :2020-01-02	575107
60 12/01/2019	846126 Brake Disc - 430MM 10 Stud	Creditor #:PP-MUL001 MULTISPARES LTD P/O #:PP263575 Receiving #:276207 Date :2020-01-02	575107
60 12/01/2019	846126 Brake Chamber T24/30IBV Disc B	Creditor #:PP-MUL001 MULTISPARES LTD P/O #:PP263575 Receiving #:276207 Date :2020-01-02	575107
60 12/01/2019	846126 Seal Hub inner - 40F1310	Creditor #:PP-MUL001 MULTISPARES LTD P/O #:PP263575 Receiving #:276211 Date :2020-01-02	575107
60 12/01/2019	846126 Seal Hub outer - 40F1311	Creditor #:PP-MUL001 MULTISPARES LTD P/O #:PP263575 Receiving #:276211 Date :2020-01-02	575107
60 12/01/2019	846126 Bearing set cone and Cup F25-H	Creditor #:PP-MUL001 MULTISPARES LTD P/O #:PP263575 Receiving #:276211 Date :2020-01-02	575107
60 12/01/2019	846126 Drain Tap - manual M22 49G7901	Creditor #:PP-MUL001 MULTISPARES LTD P/O #:PP263575 Receiving #:276213 Date :2020-01-02	575107
60 11/28/2019	846129 SENSOR ABS SENSOR SCANIA		575107
60 11/18/2019	855168 flat batteries replace batteries	test driven checked oil ok	574459
60 11/11/2019	853777 flat batteries	jumpstart vehicle	574100
60 10/26/2019	849863 PERFORM CAMPAIGN 21/19 PUSH TO TALK / BUS MINDER SECURITY C	xx	572801
60 10/25/2019	849863 push to talk	Creditor #:PP-EAS002 EASTCOAST TRUCK & BUS SERVICE P/O #:PP260914 Receiving #:271236 Date :2019-10-29	573320
60 10/17/2019	848608 smashed desto glass	removed desto glass from 474 decom and fit to 60	572303
60 10/10/2019	847208 Ops Entered - Fault - Elec and Light Flat Batteries - Rout	Jump started and checked charging.OK.	571596
60 10/09/2019	846124 40y3414zf Drop Link	Creditor #:PP-MUL001 MULTISPARES LTD P/O #:PP259465 Receiving #:269595 Date :2019-10-11	571848
60 10/09/2019	846124 LINK SWAY BAR O/S TAG AXLE	Creditor #:PP-MUL001 MULTISPARES LTD P/O #:PP259465 Receiving #:269595 Date :2019-10-11	571848
60 10/07/2019	846344 Ops Entered - Fault - Elec and Light Flat Batteries - Rout	Jump started	571221
60 10/01/2019	843819	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Completed	571221
60 10/01/2019	843819	VEHICLE SAFETY INSPECTION Completed	571221
60 09/17/2019	842794 Drv entered - Wipers and Washers Wipers Not_Clearing Screen	replaced wiper arm	570652
60 09/17/2019	842793 Drv entered - Engine Low Power	replaced wiper arm	570652
60 09/14/2019	842318	TRANSMISSION CHECK AS PER CHECK LIST	570652
60 09/09/2019	841159 Elec and Light Flat Batteries	jump started vehicle	570212
60 09/02/2019	839675	CARRY OUT FIRE EXTINGUISHER TEST & TAG	569493
60 08/13/2019	821512 PERFORM CAMPAIGN 10/19 ROUTE BUS DESTINATION FILE UPDATE	Bus at portsea and sendemail to andrew and Justing	567781
60 08/08/2019	834184 Ops Entered -Dip stick pipe has disconnected where the dip	re csecured dip stick	567273
60 07/11/2019	827318 DIRECT PURCHASE - VANDALISM	Creditor #:GB-EAS002 EASTCOAST TRUCK & BUS SERVICE P/O #:G252614 Receiving #:261520 Date :2019-07-11 CLEAN AS REQUIRED	565620
60 07/08/2019	827318 Vandalism Vandalism/ Graffiti Interior - graffiti on rear	COMPLETED BY ECTB	565326
60 07/08/2019	827318 Vandalism Vandalism/ Graffiti Interior - black graffiti r	COMPLETED BY ECTB	565326
60 07/08/2019	827318 Mechanic entered - Vandalism Other torn seat bases	COMPLETED BY ECTB	565326
60 07/05/2019	826847 Consumables		565326
60 07/05/2019	826847 Consumables		565326
60 07/05/2019	826847 Ops Entered - Fault - Elec and Light Exterior Lights - Rout	check wire harnes conectors road tested bus ok.	565178
60 07/01/2019	824908 CARRY OUT ANNUAL INSPECTION	Creditor #:GB-ROA001 ROAD SAFETY INSPECTIONS P/O #:G251169 Receiving #:260974 Date :2019-07-04	565178
60 06/27/2019	823822 REPAIR SINGLE SEAT BASE	Creditor #:GB-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:G250762 Receiving #:260323 Date :2019-06-27	564748
60 06/27/2019	823822 REPAIR DOUBLE SEAT BASE	Creditor #:GB-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:G250762 Receiving #:260323 Date :2019-06-27	564748
60 06/27/2019	825544 CLEAN GRAFFITI	Creditor #:GB-EAS002 EASTCOAST TRUCK & BUS SERVICE P/O #:G251508 Receiving #:260417 Date :2019-06-27	564748
60 06/27/2019	825544 Clean Graffiti	Done by EastCoast	564748
60 06/25/2019	824908 Service	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	564565
60 06/25/2019	824908 Service	VEHICLE SAFETY INSPECTION	564565
60 06/25/2019	824908 Service	ANNUAL SAFETY INSPECTION SERIAL # RSI 020267 completed 25/06/19 WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25	564565
60 06/25/2019	824908 Service	Assisting	564565
60 06/25/2019	824800 Final check for RSI	done.	564565
60 06/24/2019	824800 Final check for RSI		564464
60 06/19/2019	823822	completed	564150
60 06/19/2019	823822	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS tensioned wheel nuts to OEM specification	564150
60 06/19/2019	823822	VEHICLE SAFETY INSPECTION safety inspection complete. Assisting Sisil	564150
60 06/19/2019	823822 STRUT GAS STAY LIFT UP SEAT		564150
60 06/19/2019	823822 Mechanic entered - Body Other seat struts worn	replaced seat struts	564150
60 06/18/2019	823664	Re tensioOn pos 7 and 8 with rene	563870
60 06/14/2019	822848 new 'door open inward' sticker required for middle (2nd) do	Checked has been fitted	563626
60 06/14/2019	822198 REPAIR DISABLED SEAT BACK	Creditor #:GB-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:G250203 Receiving #:258996 Date :2019-06-14	563750
60 06/14/2019	822198 REPAIR SINGLE SEAT BASE	Creditor #:GB-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:G250203 Receiving #:258996 Date :2019-06-14	563750
60 06/13/2019	822403 Mechanic entered - Fluid Leaks Rear of bus hydroulic pump le	leaking hydrolick pump top T fitting replaced the T fitting	563626
60 06/13/2019	822380 Consumables		563750
60 06/13/2019	822380 Mechanic entered - Elec and Light Other speedo meter lock b		563626
60 06/13/2019	822198 Mechanic entered - Body Passenger Seat Torn a few passanger	fitted back repaired seats	563626
60 06/12/2019	822401 Mechanic entered - Engine Other steam clean the bus	completed	563626
60 06/12/2019	819022 GLOBE & HOLDER INSTRUMENT PANEL GREY (NR47774)		563626
60 06/12/2019	822380 Elec and Light speedo head lock damage	Repaired by Londsdale	563626
60 06/12/2019	822380 REPLACE SPEEDO HEAD LOCK	Creditor #:GB-LON001 LONSDALE ST AUTO ELECTRICS P/O #:G250147 Receiving #:258875 Date :2019-06-12	563626

60 06/12/2019	819022 Drv entered - Elec and Light Exterior Lights	Not the ex light it's dash globes replaced 7 globe	563626
60 06/12/2019	819022 GLOBE & HOLDER INSTRUMENT PANEL GREY (NR47774)		563626
60 06/12/2019	819022 GLOBE & HOLDER INSTRUMENT PANEL GREY (NR47774)		563626
60 06/12/2019	819022 Consumables		563626
60 06/12/2019	822403 T PIECE UNION ASSY HYD PUMP	Creditor #:-GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:-G250144 Receiving #:258822 Date :2019-06-12	563626
60 06/12/2019	822402 Mechanic entered - Body Other disability sticker needs to be	replaced borth	563626
60 06/11/2019	822099	PRE ANNUAL SAFETY INSPECTION CHECK completed	563626
60 06/11/2019	822146 Mechanic entered - Wipers and Washers Other o/s wiper blade	fitted spare wiper blade	563626
60 06/11/2019	822209 Consumables		563626
60 06/11/2019	822209 TYRE 275/70R22.5 RECAP		563626
60 06/11/2019	822209 Mechanic entered - Wheels and Tyres Worn pos 78	oliver replaced 2 tyres tensioned wheel nut with sisil	563626
60 06/11/2019	822152 Consumables		563626
60 06/11/2019	822144 Consumables		563626
60 06/11/2019	822144 GLOBE 24V 3W FESTOON		563626
60 06/11/2019	822144 Mechanic entered - Elec and Light Interior Lights some exit	2 exit lights were out fitted 2 new globes	563626
60 06/11/2019	822152 LIGHT CLEARANCE LIGHT AMBER (86510)		563626
60 06/11/2019	822152 Mechanic entered - Elec and Light Exterior Lights N/R indica	replaced	563626
60 06/11/2019	822124 Mechanic entered - Body Other staunchion poles were missing	fitted 6 new screws	563626
60 06/11/2019	822127 CAP END CAP CENTRA SEAT END CAP		563626
60 06/11/2019	822127 Mechanic entered - Body Other seatend plastick cap missing	replaced 2	563626
60 06/11/2019	822126 Mechanic entered - Body Other back row passenger seat came o	fitted back	563626
60 06/11/2019	822198 Mechanic entered - Body Passenger Seat Torn a few passanger	removed 5 seats sent for repair	563626
60 06/11/2019	822180 DECAL PLEASE KEEP CLEAR DOOR OPENS INWARDS		563626
60 06/11/2019	822180 Mechanic entered - Body Other 2 door sticker need to change	replaced	563626
60 06/07/2019	820561 Accident #49049 Damagre to the front and o/s front	Repair completed by east coast	563626
60 06/06/2019	821512 PERFORM CAMPAIGN 10/19 ROUTE BUS DESTINATION FILE UPDATE	***FAULTY UNIT/CARD*** will not upload tried another spare controller and same situation	563626
60 05/31/2019	820561 Accident #49049 Damagre to the front and o/s front	Bus sent to to east coast	563626
60 05/24/2019	819022 Mechanic entered - Engine Other Hydrolick pump leak	Steam cleaned and checked. assisting Howard	563100
60 05/24/2019	819022 Mechanic entered - Engine Other Replace hydraulic oil whole	Replace hydraulic oil assisting Howard	563100
60 05/24/2019	819022 Mechanic entered - Engine Other Replace hydraulic oil whole	replace hydraulic oil and clean system	563100
60 05/24/2019	819022 Mechanic entered - Engine Other Hydrolick pump leak	steam clean and checked oil leak	563100
60 05/24/2019	819038	CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST did the fire saftey	563100
60 05/21/2019	817743 AIR CON REFRIDGERANT		562663
60 05/21/2019	817743 BRUSHES MOTOR EVAPORATOR+CONDENSOR		562663
60 05/21/2019	817743	Replaced terminals over compressor for rear unit finish off service tested ok	562663
60 05/20/2019	817743 BRUSHES MOTOR EVAPORATOR+CONDENSOR		562663
60 05/20/2019	817743 FILTER DRYER AIR COND 5/8 FLARE		562663
60 05/20/2019	817743 OIL COMPRESSOR OIL AIR CONDITIONING		562663
60 05/20/2019	817743 FILTER DRYER AIR COND 5/8 (3K171124)		562663
60 05/20/2019	817743	CARRY OUT A/C - B SERVICE AS PER CHECK LIST	562663
60 05/20/2019	817743	CARRY OUT A/C - A SERVICE AS PER CHECK LIST Service as per list Service front unit as per list replaced safety switches terminals replaced evap fan brushes comb out damage to condenser coils Rear unit replaced evap fan and condenser brushes rear unit not completed carry over	562663
60 05/14/2019	816462 IDLER PULLEY SCANIA ARTIC (No Groove Plastic) (1428940)		562319
60 05/13/2019	816462 Mechanic entered - Body Other 2alternator Idler pully worn	replaced borth pully	562319
60 05/13/2019	816376 Consumables		562319
60 05/13/2019	816376 Consumables		562319
60 05/13/2019	816376 Consumables		562319
60 05/13/2019	816376 Consumables		562319
60 05/13/2019	816376 Consumables		562319
60 05/13/2019	816376 Consumables		562319
60 05/13/2019	816376 Consumables		562319
60 05/13/2019	816376 Consumables		562319
60 05/13/2019	816376 Consumables		562319
60 05/13/2019	816376 Consumables		562319
60 05/13/2019	816376 Consumables		562319
60 05/13/2019	816376 Consumables		562319
60 05/13/2019	816376 OIL AUTOMATIC TRANSMISSION OIL TEXAMATIC OR DEXRON (LU2)		562214
60 05/13/2019	816376 OIL ENGINE DELO 400 MGX SAE 15W-40		562214
60 05/13/2019	816376 FILTER ZF TRANS ECOMAT (1193281-1)(4139 298 038 01)		562214
60 05/13/2019	816376 Oil Filter SC S4 & K		562214
60 05/13/2019	816376 FILTER FUEL FILTER SCANIA SR4 (1372444)		562214
60 05/13/2019	816376 KIT O-RING OIL SPINNER FILTER SCANIA ABOVE ENG #6203050		562214
60 05/13/2019	816376	CARRY OUT B SERVICE AS PER CHECK LIST completed	562214
60 05/13/2019	816376 Consumables		562319
60 05/13/2019	816376 Consumables		562319
60 05/13/2019	816376 Consumables		562319
60 05/13/2019	816376 Consumables		562319
60 04/30/2019	813119 Please remove all old poster and fit MYKI has gone mobil	Completed by Refuellers	561320
60 04/18/2019	806032 V STAY COMPLETE L94	Creditor #:-GB-MUL001 MULTISPARES LTD P/O #:-G244235 Receiving #:254401 Date :2019-04-18	560648
60 04/10/2019	809439 SWITCH TOGGLE ON/OFF/MOM ON		559899
60 04/10/2019	809439 Fault#:36464 - Ops Entered - Fault - Breakdown Not Starting	check faultes replaced rear selactor switch bus ok.	559899
60 04/03/2019	806357 Consumables		559550
60 04/03/2019	806357 Direct Purchase - BODYWORK	Creditor #:-GB-VOL001 VOLGREN AUSTRALIA PTY LTD P/O #:-G244441 Receiving #:253191 Date :2019-04-03 DOOR HINGE	559460
60 03/27/2019	806357 Driver overhead locker's hinges are missing. Locker panel w	Replaced hinches	558750
60 03/27/2019	806356 Mechanic entered - Body Other above driver overhead locker h	Replaced hinches	558750
60 03/25/2019	806032 Suspension - V bar bush worn	Assisting	558641
60 03/25/2019	806032 Suspension - V bar bush worn	R/R V - Rod rear.Road tested and checked bus on the pit - ok.	558641
60 03/21/2019	805146 PUMP WASHER PUMP 24 VOLT		558420
60 03/21/2019	805146	Assisting	558420
60 03/21/2019	805146	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	558420
60 03/14/2019	803176 CLEAN VANDALISM	VEHICLE SAFETY INSPECTION	558420
60 03/12/2019	803176 Vandalism Vandalism/ Graffiti Interior - seats head rest	Creditor #:-GB-EAS002 EASTCOAST TRUCK & BUS SERVICE P/O #:-G243175 Receiving #:251480 Date :2019-03-14 CLEAN AND PAINT AS REQUIRED	557528
60 03/12/2019	803176 Vandalism Vandalism/ Graffiti InteriorRear left (nearsi	as above	557290
60 02/18/2019	798700 Consumables	Paint by east coast	557290
60 02/18/2019	798700 Mechanic entered - Elec and Light Exterior Lights head lig	checked all fuses and relays and ok.Check conector under bus and ok.Pulled out dash and tryed different switch and still no good.Pulled steering coloumn covers apart and found connector not in properly.Pushed back in put back together and checked lights and ok.	555444
60 02/06/2019	795891 Please remove old 2018 fare decals and fit new 2019 fare dec	completed.	554344
60 02/01/2019	795129	Assisting	553980
60 02/01/2019	795129	Tensioned middle axle tyres.	553980
60 02/01/2019	798926 Completed by ATS	CARRY OUT FIRE EXTINGUISHER TEST & TAG	554186
60 01/30/2019	792152 SENSOR WEAR SENSOR KIT BLOCK TYPE-AXEL SET L94UB (1794440)		553858
60 01/30/2019	792152 SET DISC PAD SET SCANIA / MERCEDES 0500		553858
60 01/30/2019	792152 BRAKE BOOSTER SCANIA L94UAB (35CLE0100)		553858
60 01/30/2019	792152 Ops Entered - Fault - Brakes Foot_Brakes Noisy - Route: 81	Lubricate n/s hub bearings and fitted new seal. Tension all hub nuts and rotors bolt to spec. Fitted new caliper and adjust tag axle brakes. Fitted new brake booster and checked air leaks. Refitted tyres and tension wheel nuts with Rene. Drive tested and checked brake temps ok. Brake tested all ok.	553858
60 01/29/2019	792152 REPAIR / RE SLEEVE TAG AXLE HU	Creditor #:-GB-HMG001 HM GEM ENGINES P/O #:-G239731 Receiving #:248052 Date :2019-01-30	553858
60 01/29/2019	792152 Ops Entered - Fault - Brakes Foot_Brakes Noisy - Route: 81	Lubricate new bearings and fitted new brake rotor caliper and pads. C/O	553858
60 01/25/2019	792152 Ops Entered - Fault - Brakes Foot_Brakes Noisy - Route: 812	Cleaned all the parts.Replace o/s tag axle bearings. C/O	553858

60 01/25/2019	792152 BEARING OUTER TAG AXLE SCANI	Creditor #:GB-STA101 STATEWIDE BEARINGS P/O #:G239708 Receiving #:247878 Date :2019-01-25	553858
60 01/25/2019	792152 CONE INNER BEARING TAG AXLE	Creditor #:GB-STA101 STATEWIDE BEARINGS P/O #:G239708 Receiving #:247878 Date :2019-01-25	553858
60 01/25/2019	792152 BEARING INNER TAG AXLE SCANI	Creditor #:GB-STA101 STATEWIDE BEARINGS P/O #:G239708 Receiving #:247878 Date :2019-01-25	553858
60 01/25/2019	792152 SEAL REARHUB MIDDLE AXLE SCANIA L94UAB ARTIC		553858
60 01/25/2019	792152 L94UAB SCANIA HUB LOCK WASHER		553858
60 01/25/2019	792152 GASKET HUB COVER L94UAB CENTRE AXLE		553858
60 01/24/2019	792152 BRAKE CALIPER LH TAG AXLE SC	Creditor #:GB-SMS001 SMS DIESEL SPARES PTY LTD P/O #:G239678 Receiving #:248098 Date :2019-01-30	553858
60 01/24/2019	792152 BRAKE CALIPER RH TAG AXLE SC	Creditor #:GB-SMS001 SMS DIESEL SPARES PTY LTD P/O #:G239678 Receiving #:248098 Date :2019-01-30	553858
60 01/24/2019	792152 Ops Entered - Fault - Brakes Foot_Brakes Noisy - Route: 812	Cleaned hub to send out for repair. C/O	553858
60 01/24/2019	792152 BRAKE ROTOR MIDDLE AXLE SCANIA	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G239605 Receiving #:247761 Date :2019-01-24	553858
60 01/23/2019	792152 Ops Entered - Fault - Brakes Foot_Brakes Noisy - Route: 81	Removed n/s & o/s tag axle brakes component and wheel hubs with Matt.	553858
60 01/18/2019	792152 Ops Entered - Fault - Brakes Foot_Brakes Noisy - Route: 81	atend to B/Down check n/s mid axel bearing releas brake booster drive slowly to depot	553858
60 01/11/2019	790790 Suspension O/side front traling arm bushes need repale	Rekit trailing arm.	553277
60 01/09/2019	790057 Consumables		553277
60 01/09/2019	790057 GLOBE 24V 75/70W H4		553010
60 01/09/2019	790057 Ops Entered - Fault - Elec and Light Exterior Lights - Rout	changed blown globe (ns) low beam headlight.	553010
60 01/08/2019	790790 BUSH TORQUE ROD SCANIA/MERC	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G238379 Receiving #:246674 Date :2019-01-14	553619
60 01/07/2019	789847 Vandalism - remove graffiti from side	removed by fleet support	552861
60 01/03/2019	789007 Consumables		552744
60 01/03/2019	789007 Driver mirror very loose. Needs to be tightend urgently	tightened loose (nsf) exterior mirror and arm. mirror re-adjusted.	552620
60 01/02/2019	788701 Mechanic entered - Accident - MIRROR front left mirro	reflited new arm and mirro on n/s supervious by rangie	552620
60 01/02/2019	788701 MIRROR LEFT HAND 380mm		552620
60 01/02/2019	788701 L/H MIRROR ARM LONG (PM8844-1)		552620
60 12/27/2018	788072	Assisting	551883
60 12/27/2018	788072	Tension tyre pos 5 & 6 with Nick	551883
60 12/27/2018	787972 Breakdown#:36013 - Ops Entered - Breakdown - Breakdown Runo	out 10.50am in 11.50am fault ran out of fuel topped up fuel bleed the system start upthe bus. fuel up jery cans and bus.	551883
60 12/24/2018	787750 Drv entered - Engine Low Power	Assisted Nick with Low power and road test.	551883
60 12/24/2018	787750 Drv entered - Engine Low Power	Drive tested found accelarator kickdown not working. Diagnose and delete the faults drive teted ok.	551883
60 12/24/2018	787750 Fluid Leaks check and repair oil leak near hydraulic pump ar	Checked ok.	551883
60 12/24/2018	787694 Consumables		551883
60 12/24/2018	787694 Elec and Light alternator tuching each other	Replaced missing nut too top bracket center off alternators left a 3mm gap between alternators	551883
60 12/23/2018	787605 NIPPLE TEST AIR TANK VOLVO B10BLE 30G4500WABCO		551883
60 12/23/2018	787605 GLOBE 24V 2W (HLH242)		551883
60 12/23/2018	787605 GLOBE 24V 21W CLEAR INDICATOR SINGLE CONTACT		551883
60 12/23/2018	787605 GLOBE 24V 5W FESTOON (17136)		551883
60 12/23/2018	787605 GLOBE 24V 10W SINGLE CONTACT		551883
60 12/23/2018	787605	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Replacepark lightglobe used step light and globe exit light globe and passenger stop signglobe Replaced tst nippleFixed cover above wheel chair seat	551883
60 12/23/2018	787605	VEHICLE SAFETY INSPECTION	551883
60 12/23/2018	787663 Remove middle axle and check brakes	Removed O/S middle axle wheel and checked brake pad all ok. tention wheel nuts with Kumara	551883
60 12/18/2018	786826 Consumables		551729
60 12/18/2018	786826 Ops Entered - Fault - Desto Signs - Route: - TIM to read:	Reset system slow but working.	551541
60 12/17/2018	786534 Driver console door faulty	refer other work order	551414
60 12/17/2018	786533 HINGE DRIVERS DOOR S/S 60mmX60mm (12205)(802505)		551414
60 12/17/2018	786533 Mechanic entered - Body Front_Door Operation Faulty	removed broken hinges and replaced with new ones.	551414
60 12/03/2018	783573 Consumables		549850
60 12/03/2018	783573 Drv entered - Elec and Light Exterior Lights	Could not fault	549740
60 11/29/2018	782857 Consumables		549595
60 11/29/2018	782857 Drv entered - Elec and Light Exterior Lights	checked could not fault.	549314
60 11/23/2018	781493 Mechanic entered - Vandalism Vandalism/ Graffiti Interior	dean cleaned graffiti	548924
60 11/21/2018	781014 Consumables		548800
60 11/21/2018	781014 Mechanic entered - Elec and Light Exterior Lights n/s lower	removed and replaced globe	548683
60 11/21/2018	780868 Accident#:47922 - Ops Entered - Accident - Bus is hit by 3r	Simon has checked and damage has been done and job has been taken offperformance monitor	548683
60 11/17/2018	780155 Check middle door not opnering intermitten	check and clean mid passanger door value doors ok.	548420
60 11/05/2018	777851	helped nick	547470
60 11/05/2018	777851	Tension pos 9 & 10 wheel nuts with Elias.	547470
60 11/03/2018	777553 Consumables		547590
60 11/03/2018	777553 TYRE 275/70R22.5 RECAP		547470
60 11/03/2018	777553 Mechanic entered - Wheels and Tyres Worn tyre 10 worn.	changed tyres 9 (rack) and 10 (worn). nuts tensioned with dulkith.	547470
60 10/31/2018	775429 RELAY HOIST 24V 30-40AMP 50V2715		547254
60 10/31/2018	775429 COMPUTER SLRT/RM-RP (2 DEG O/S)		547254
60 10/31/2018	775429 PANEL RELAY PANEL 24 Volt		547254
60 10/31/2018	775429 AIR CON REFRIDGERANT		547254
60 10/31/2018	775429 Drv entered - A/C Heating Not Cooling	Replaced ccc and esp replaced main relay found system had been spiked repair burnt wiring run unit up tested ok	547254
60 10/31/2018	776873 Consumables		547373
60 10/31/2018	776873 LAMP INDICATOR [ORANGE]		547254
60 10/31/2018	776873 Mechanic entered - Elec and Light Exterior Lights (os) mid i	replaced.	547254
60 10/31/2018	776875 Mechanic entered - Body Other (os) mid panel loose.	secured.	547254
60 10/30/2018	775429 Drv entered - A/C Heating Not Cooling	Remove and replaced failed rear compressor pressure tested and vac system job not completed carry over	547254
60 10/29/2018	775429 Drv entered - A/C Heating Not Cooling		546917
60 10/26/2018	775429 CLUTCH A/C COMP 8PV DKS32		547146
60 10/26/2018	775429 COMPRESSOR A/C DKS32 / TM31	Creditor #:GB-22C001 22 CELSIUS P/O #:G232700 Receiving #:240762 Date :2018-10-29	547146
60 10/26/2018	775752 Consumables	Creditor #:GB-22C001 22 CELSIUS P/O #:G232700 Receiving #:240762 Date :2018-10-29	547146
60 10/26/2018	775752 SWITCH STARTER LOCK TO SUIT SCANIA L94UAB		546917
60 10/25/2018	775751 Breakdown#:35709 - Ops Entered - Breakdown - Breakdown Low	Bring bus back to depot - ignition switch faulti	546508
60 10/25/2018	775752 Ops Entered - Fault - Engine Low Power - Route: 811d - Lwr	Assisting removed ignition barrel then removed and replaced switch. road tested switch on and off a few times and ok.	546508
60 10/25/2018	775752 Ops Entered - Fault - Engine Low Power - Route: 811d - Lwr	Bring bus back to depot - ignition switch faulty	546508
60 10/24/2018	775429 Drv entered - A/C Heating Not Cooling	Comission tested found that the ;left bank compressor has failed parts ordered Job not completed carry over	546508
60 10/11/2018	772833 Ops Entered - Fault - Engine Low Power - Route: 813 - Park	Road tested bus to fault via long road test operating park brakes and pulling over could not fault.Released bus to see if faults again.Need exact issue.	545470
60 10/01/2018	755902 KNOB BLOCK VALVE	Creditor #:GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G232571 Receiving #:240289 Date :2018-10-23	546508
60 10/01/2018	755902 INTERLOCK VALVE SCANIA L94UAB	Creditor #:GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G232571 Receiving #:240289 Date :2018-10-23	546508
60 10/01/2018	769860 REMOVE AND REPLACE A3 POSTER TO ALL ROUTE VEHICLES	Replaced by Refuellers	544704
60 09/22/2018	768414	VEHICLE SAFETY INSPECTION assist to safety inspection	544040
60 09/22/2018	768414	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	544040
60 09/22/2018	768414	VEHICLE SAFETY INSPECTION assist to safety inspection	544040
60 09/14/2018	766399 Consumables		543636
60 09/14/2018	766399 Elec and Light Check short circuit to RPD system.	finish putting new lamps insulated some wiring in turn table put back together road tested and ok.	543580
60 09/13/2018	766347 Breakdown#:35543 - Ops Entered - Breakdown - Breakdown Air	No one attended breakdown. Ben Were traced fault and C/O by Elias.	543580
60 09/13/2018	766399 Elec and Light Check short circuit to RPD system.	cut wire to heater element near airs system and cleaned and checked wires ner ac compressor as per instructions Bwere.pulled down turn table to check incase of rubed wires up there all appears ok but found few broken clamps I need to replace.	543580
60 09/13/2018	766105 Completed by ATS	CARRY OUT FIRE EXTINGUISHER TEST & TAG	543580
60 09/12/2018	761599 Consumables		543580
60 09/12/2018	761599 TYRE 275/70R22.5 NEW		543580
60 09/10/2018	763040 Breakdown#:35463 - Ops Entered - Breakdown - Breakdown Elect	Road tested bus.Couldn't fault of any alarm or issues with air building up.Checked middle axle brakes ok.	543580
60 09/01/2018	763040 Breakdown#:35463 - Ops Entered - Breakdown - Breakdown Elect	checked rpd system and opk.check alt signal and ok.clean wheel chair ramp and ok.Found bus taking long time to build air at idel and when press brakes 3 or 4 times buzzer for low air coming.check with Nick and confirmed.nm Air issue Mechanic to check air drier/compressor. 30/08/18	543580
60 08/29/2018	762722 Breakdown#:35459 - Ops Entered - Breakdown - Breakdown Air S	check bus found fuse 22 removed/fallen out Alternator control circuits.causing rpd to come on as recieves engine run throught alts.Put new fuse and road tested checked and ok.	543555
60 08/29/2018	762722 Breakdown#:35459 - Ops Entered - Breakdown - Breakdown Air S	bus B\Down door brake on door over ride switch off and bus sending to depot	543555

60 08/29/2018	762831 PERFORM CAMPAIGN 26/18 CHASSIS WASH & UNDER CARRIAGE CHECK	drove bus on under carrige washer.	543555
60 08/27/2018	761864 Consumables		543438
60 08/27/2018	761864 Mechanic entered - Wheels and Tyres Wheel Nut Retension pos	re-tensioned all steer wheel nuts with dulkith.	543130
60 08/27/2018	761039 HOLDER FUSE HOLDER NARVA INLINE (544068L)		543130
60 08/27/2018	761039 Drv entered - A/C Heating Demister Not Heating	Locate and repair short in boost pumpm circuit replaced fue holder and fuse tested ok	543130
60 08/24/2018	761599 Drv entered - Brakes Foot_Brakes Pulling	Assisting	543130
60 08/24/2018	761599 Drv entered - Brakes Foot_Brakes Pulling	changed front tyres tensioned wheel nut with Adid Adjusted front brake road tested ok	543130
60 08/22/2018	761039 Drv entered - A/C Heating Demister Not Heating	Started on bus bus had to leave not completed C/O	542885
60 08/16/2018	759803 Vandalism Graffiti in bus	Cleaned	542470
60 08/16/2018	759785 Consumables		542470
60 08/16/2018	759785 Consumables		542470
60 08/16/2018	759785 Consumables		542470
60 08/16/2018	759785 Consumables		542470
60 08/16/2018	759785 FILTER ZF TRANS ECOMAT (1193281-1)(4139 298 038 01)		542470
60 08/16/2018	759785 OIL AUTOMATIC TRANSMISSION OIL TEXAMATIC OR DEXRON (LU2)		542470
60 08/16/2018	759785 FILTER FUEL FILTER SCANIA SR4 (1372444)		542470
60 08/16/2018	759785 KIT O-RING OIL SPINNER FILTER SCANIA ABOVE ENG #6203050		542470
60 08/16/2018	759785	CARRY OUT B SERVICE AS PER CHECK LIST	542470
60 08/16/2018	759785 OIL ENGINE OIL MINERAL 15W-40 DELO 400 LE (LU18)(3361808)		542470
60 08/16/2018	759785 Oil Filter SC S4 & K		542470
60 08/09/2018	755902 VALVE RELAY SCANIA/VOLVO	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G226154RET1 Receiving #:234225 Date :2018-08-10	541897
60 08/09/2018	755902 VALVE RELAY D/AXLE SCANIA L	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G226154RET Receiving #:234217 Date :2018-08-10	541897
60 08/03/2018	755902 VALVE RELAY SCANIA/VOLVO	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G226154 Receiving #:234221 Date :2018-08-10	541897
60 08/03/2018	755902 VALVE RELAY D/AXLE SCANIA L	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G226154 Receiving #:234213 Date :2018-08-10	541897
60 08/03/2018	755902 VALVE MANUAL DRAIN VALVE		541150
60 08/03/2018	755902 Ops Entered - Fault - Air System Air Not Building_Up - Rout	check air system and replaced park brake check value assy air drain tank. road test bus ok	541150
60 08/02/2018	755902 VALVE FOUR WAY SCANIA	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G226120 Receiving #:233623 Date :2018-08-03	541150
60 08/01/2018	752170 Rear door camera not working properly	removed and replaced rear door camera.	541150
60 08/01/2018	755902 Ops Entered - Fault - Air System Air Not Building_Up - Rou	Fitted new B/valve still leaking. Isolated all park brake boostersstill leaking R/R park brake valve from bus 102still leaking. Reckon 4 way might needreplacing. While parking this bus there was no leak. Needs a road test.C/O.	541150
60 07/31/2018	755902 Valve Check	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G225798 Receiving #:233317 Date :2018-07-31	541150
60 07/31/2018	755902 Ops Entered - Fault - Air System Air Not Building_Up - Rou	Build up air and checked.Brooms brakes leaking as soon as you release park brakes.	541150
60 07/31/2018	756041 PERFORM CAMPAIGN 17/18 INTERNAL BUS NUMBERS	Checked by Refuellers and this job has been done	541150
60 07/30/2018	755902 Ops Entered - Fault - Air System Air Not Building_Up - Rou	Road tested bus to check for air leaksfound Brooms valve leaking intermittently.Looked for parts can't find any. Ordered part.	541150
60 07/27/2018	755383	TRANSMISSION CHECK AS PER CHECK LIST Transmission Check Completed	540709
60 07/26/2018	755141 REMOVE OLD POSTER AND REPLACE WITH BUS TIMES ARE CHANGING	Replaced by refuellers	540709
60 07/19/2018	752170 CAMERA RR 120DE	Creditor #:GB-LON001 LONSDALE ST AUTO ELECTRICS P/O #:G224447 Receiving #:232337 Date :2018-07-19	540111
60 07/17/2018	752667 Ops Entered - Fault - Engine Low Power - Route: 812d - Chel	check ok	539719
60 07/16/2018	752553 Ops Entered - Fault - A/C Heating Demister Not Heating - Ro	Commission tested found a/c both heated ok tested demisters found there was no supply coming from engine need pit to inspect pipes for any crushed sections	539719
60 07/16/2018	752624 Consumables		539875
60 07/16/2018	752624 GLOBE 24V 10W SINGLE CONTACT		539719
60 07/16/2018	752624 LIGHT REAR STOP (2322)		539719
60 07/16/2018	752624 Mechanic entered - Elec and Light Exterior Lights park light	found hosing cracked and replaced with new one and new globe.	539719
60 07/13/2018	752170 Rear door camera not working properly	found rear door drivers camera not working correctly (blurry). retrieved part numbers from component and have stores chasing new camera. awaiting parts	539639
60 07/11/2018	751576 BATTERY 800CCA (EMFN150)		539292
60 07/11/2018	751576 Breakdown#:35189 - Ops Entered - Breakdown - Breakdown Not S	changed batteries and roadttested bus with most electrical components operating. voltage dropped to 26.5v from 27.5v but no further. no cutouts occured.	539292
60 07/11/2018	751704 Consumables		539492
60 07/11/2018	751704 Mechanic entered - Elec and Light Other perform pti and fuel	complete and parked	539292
60 07/11/2018	751704 GLOBE 24V 21W CLEAR INDICATOR SINGLE CONTACT		539292
60 07/11/2018	751577 PERFORM CAMPAIGN 11/18 VENTURA BUS MINDER INSTALLATION	complete	539292
60 07/11/2018	751577 FUSE BLADE 10 AMP (NR52810)		539292
60 07/10/2018	751591 Drv entered - Steering Shakes/ Wobbles (Bus only release to	Road tested bus to check found very minor shakefront tyres all good. Ok to use. But got stuck with loosing battery power when A/c turned on.Not safe on the road.	539292
60 07/10/2018	740251 Mechanic entered - A/C Heating Not Heating	Job completed by PM shift	539292
60 07/10/2018	751576 Breakdown#:35189 - Ops Entered - Breakdown - Breakdown Not S	checked connection at rear of dash ok. checked connections in electical centre. all look ok. except found elc connector not attached correctly fit properly. roadtested bus to attempt to replicate fault. bus not faulting.	539292
60 07/10/2018	751577 PERFORM CAMPAIGN 11/18 VENTURA BUS MINDER INSTALLATION		539292
60 07/09/2018	751146 Breakdown#:35190 - Ops Entered - Breakdown - Breakdown Not S		539292
60 06/27/2018	744638	attend to brake down fix temperaly drive to depot	539292
60 06/27/2018	744638	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	537909
60 06/27/2018	744638	VEHICLE SAFETY INSPECTION	537909
60 06/27/2018	744638	ANNUAL SAFETY INSPECTION SERIAL - RWC 016910 - PASSED - 27/06/18WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLESAFETY INSPECTION LINE TIME ON THE W/O TO 0.25	537909
60 06/27/2018	748631 Steering wheel ply	Found movment in spline - replace top bolt and washer and tight up	537909
60 06/27/2018	748631 Steering line oil leak	retight oil pipe conections	537909
60 06/27/2018	748631 Engine oil leak	found leak on hidraulik pump - repaired -steam clean - road tested OK	537909
60 06/26/2018	744638 Service	VEHICLE SAFETY INSPECTION -drowe bus to Moorabin depot to doo RSI	537909
60 06/25/2018	747924 Engine - Steamclean bus for RSI	steamed bus last fri	537909
60 06/22/2018	744904 Check and repair engine smoke	ref to w/o # 747053	537909
60 06/22/2018	747340 PERFORM CAMPAIGN 16/18 2019 REGISTRATION LABEL REPLACEMENT	REPLACED	537909
60 06/21/2018	747053 Mechanic entered - Engine Other Rectify engine smoke.	Refitted intercooler and radiator accessories. Refitted side panel and rear passenger seat & floor hatch. Top up engine oil and fan oil. Drive tested and checked engine smoke normal. Brake tested as Ranjit instruction Ok.	537909
60 06/20/2018	744904 CLEAN INTERCOOLER	Creditor #:GB-DAN013 DANDENONG RADIATORS PTY LTD P/O #:G222308 Receiving #:230147 Date :2018-06-20	538265
60 06/18/2018	745369 CLEAN GRAFFITI AS REQUIRED	Creditor #:GB-EAS002 EASTCOAST TRUCK & BUS SERVICE P/O #:G222228 Receiving #:230056 Date :2018-06-20 CLEAN	538265
60 06/18/2018	744904 Check and repair engine smoke	Fitted new muffler refitted all exhaust pipe and radiator. Start the engine and checked smoke Ok. (Waiting for intercooler.) C/O	538265
60 06/15/2018	744904 GASKET EXHAUST MANIFOLD SCAN	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G222302 Receiving #:229791 Date :2018-06-15	538265
60 06/15/2018	744904 Check and repair engine smoke	Cleaned all the parts. Fitted new exhaust gasket and new turbo. Tension all the bolts to spec. C/O	537909
60 06/14/2018	744638 DIRECT PURCHASE - BUS INSPECTI	Creditor #:GB-ROA001 ROAD SAFETY INSPECTIONS P/O #:G221942 Receiving #:230349 Date :2018-06-25 RSI	538265
60 06/14/2018	745369 Vandalism - Clean graffiti as required	CLEANED BY ECTB 25/05/18	537909
60 06/14/2018	744904 Check and repair engine smoke	Removed intercooler radiator and engine accessories. Removed turbo and muffler. C/O	537909
60 06/14/2018	744904 V-CLAMP		537909
60 06/14/2018	744904 MUFFLER SCANIA (0357402)	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G222150 Receiving #:229609 Date :2018-06-14	538265
60 06/14/2018	744904 GASKET TURBO OIL RETURN SCAN	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G222049 Receiving #:229620 Date :2018-06-14	538265
60 06/14/2018	744904 GASKET - TURBO MOUNT SCANIA K9	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G222049 Receiving #:229620 Date :2018-06-14	538265
60 06/14/2018	744904 TURBOCHARGER SCANIA L94UAB 1	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G222049 Receiving #:229620 Date :2018-06-14	538265
60 06/12/2018	744904 Check and repair engine smoke	Rectify engine blowing smoke found turbo was full of oil. Requires newturbo.	537909
60 06/12/2018	744827 PERFORM CAMPAIGN 13/18 VENTURA ROUTE BUS DECAL UPDATE	completed.	537909
60 06/01/2018	740251 SWITCH HIGH PRESSURE SWITCH		537356
60 06/01/2018	742828 EMERGENCY EXIT BUTTON PULL COVER (16906)		537356
60 06/01/2018	742828 Mechanic entered - Body Rear_Door Operation Faulty Emergency	fitted new plastic cover.	537356
60 06/01/2018	742825 EDGE SENSITIVE EDGE DOOR SWITCH DW40		537356
60 06/01/2018	742825 Mechanic entered - Body Rear_Door Operation Faulty Middle do	checked door found not sensitive.Adjusted valve and still no good.Removed and replaced valve adjusted valve and cecked door and ok now.	537356
60 05/31/2018	742598	PRE ANNUAL SAFETY INSPECTION CHECK Cleaned and refitted fan pump and a/c bracket and accessories. Top up fan pump oil.	537356
60 05/31/2018	740251 Mechanic entered - A/C Heating Not Heating	Remove hydrolic pump gear housing remove compressor base drill out and helicoil all mount points	537356
60 05/31/2018	742585 Consumables		537620
60 05/31/2018	742585 REPLACED DAMAGE WINDOW	Creditor #:GB-ALP003 ALPHA BUS GLASS PTY LTD P/O #:G221286 Receiving #:228822 Date :2018-06-01	537620
60 05/31/2018	742585 Mechanic entered - Body Other N/s middle body window glass	Replaced window by Alpha	537356
60 05/31/2018	742585 Body Windows Side window next to rear doors cracked	as above	537356
60 05/30/2018	740251 Mechanic entered - A/C Heating Not Heating	Replaced ccc and boost pump remove both small compressors and mounting bracket drain hydrolic oil and remove pump not completed	537356
60 05/25/2018	741170 Consumables		537356
60 05/25/2018	741170 Body - Air-con vent hanging loose (opposite of the rear door	Replaced missing screw	536693

60 05/24/2018	740251 PUMP BOOST PUMP COACH 90 Ltr		536693
60 05/22/2018	740251 Consumables		536920
60 05/22/2018	740251 GLOBE 24V 21/SW STOP AND TAIL LAMP (17925)		536693
60 05/22/2018	740279	CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST fire safety complete	536693
60 05/22/2018	739844 COMPUTER SLRT/RM-RP (2 DEG O/S)		536693
60 05/22/2018	739844	Service to bothe units as per list	536693
60 05/21/2018	740251 PROBE ASSY DE/ICE A/C	Creditor #:GB-COA001 COACHAIR PTY LTD P/O #:G220402 Receiving #:228023 Date :2018-05-23	537055
60 05/21/2018	740251 COMPUTER SLRT/RM-RP	Creditor #:GB-COA001 COACHAIR PTY LTD P/O #:G220402 Receiving #:228023 Date :2018-05-23	537055
60 05/21/2018	740086 Mechanic entered - A/C Heating Not Heating	Locate and repair electrical fault to front unit replaced CCC tested ok	536693
60 05/21/2018	739844	CARRY OUT A/C - A SERVICE AS PER CHECK LIST Replaced ccc on the fromt unit Started service on front unit	536693
60 05/18/2018	739932 PERFORM CAMPAIGN 15/18 A3 POSTER CHANGE - MYKI AUTO TOP UP	Completed	536693
60 05/14/2018	738177	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Done with Shalen.	536273
60 05/14/2018	738177	VEHICLE SAFETY INSPECTION Complete	536273
60 05/14/2018	738562 Consumables		536280
60 05/14/2018	738562 Mechanic entered - Elec and Light Other O/s rear saloon high	Remove and replace flouro tube.	536273
60 05/11/2018	738182 Mechanic entered - Engine Other Fan drive noisy	Check hydraulic fan drive oil low in level no oil can see in dipstick add 3.50 ltrs. of hydraulic oil.	536273
60 05/11/2018	734240 Engine - Oil leak around bell housing	Refit steering oil pipes secured refit tail shaft secured all wirings topped-up coolant and steering oil. complete fit all accessories and steam clean engine and under of bus roadtested check heater temperature ok check gear shifting ok r re check for oil leak all ok no leak. coolant level ok and steering oil level ok .	536273
60 05/11/2018	734240 Engine - Oil leak around engine oil cooler		536273
60 05/11/2018	738178 Consumables		536273
60 05/11/2018	738178 Mechanic entered - Body Other N/s middle near rear door pane	Check found panel bolts loose at n/s body retightened all bolts.	536273
60 05/10/2018	734240 SUPPLY INSTALL REAR MAIN SEAL	Creditor #:GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G219549 Receiving #:227057 Date :2018-05-11	536273
60 05/10/2018	734240 Engine - Oil leak around bell housing	Fitted flywheel and tensioned all bolts according to specs. refit gear box assembly and refit all torque converter bolts and tensioned according to specs. Refit mount and trans. bracket refit all wirings and coolant pipe replace upper coolant hose pick-up from scania. refit coolant pipe and hoses. job to continue clean-up sor	536273
60 05/10/2018	734240 KIT O-RING OIL SPINNER FILTER SCANIA ABOVE ENG #6203050		536273
60 05/10/2018	734240 HOSE ELBOW TRANS OIL COOLER	Creditor #:GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G219726 Receiving #:227047 Date :2018-05-11	536273
60 05/09/2018	734240 REAR CRANK SEAL	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G218977RET Receiving #:227032 Date :2018-05-10	536273
60 05/09/2018	734240 HOSE SCANIA	Creditor #:GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G219581 Receiving #:226956 Date :2018-05-10	536273
60 05/09/2018	734240 GASKET FILTER HSG	Creditor #:GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G219581 Receiving #:226956 Date :2018-05-10	536273
60 05/09/2018	734240 Engine - Oil leak around bell housing	Fitted new water pump and gasket refit oil cooler and new gasket refit oil filter base and oil filter fitted new turbo hose fitted new oil sender fitted new gasket for oil spinner housing base fitted new oil filler hose and refit all oil pipes. Replace oil spinner kit and refit topped-up oil and refit water pump belt. Clean soroundir	536273
60 05/08/2018	724925 Direct Purchase - TYRES	Creditor #:GB-TYR002 TYRES4U P/O #:G219575 Receiving #:226887 Date :2018-05-09 TEN24 AFTER HOURS	536273
60 05/08/2018	734240 Engine - Oil leak around bell housing	Cleaned bell remove old gasket from block and bell housing fitted new gasket. torque all bolts according to specs. cleaned sump and remove old gasket fitted new gasket refit sump and tensioned according to specs. refit starter assembly and all wirings secured. clean soroundings.	536273
60 05/07/2018	734240 Engine - Oil leak around bell housing	Remove oil spinner oil dipstick assy. remove sump assy. remove starter and bell housing secured engine put jack stand to support engine. clean - up sorroundings and parts.	536273
60 05/02/2018	734240 GASKET	Creditor #:GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G219029 Receiving #:226504 Date :2018-05-02	536273
60 05/02/2018	734240 HOSE	Creditor #:GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G219029 Receiving #:226503 Date :2018-05-02	536273
60 05/02/2018	734240 SEAL SCANIA	Creditor #:GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G219029 Receiving #:226503 Date :2018-05-02	536273
60 05/02/2018	734240 SEAL RING SCANIA L94UAB	Creditor #:GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G219029 Receiving #:226503 Date :2018-05-02	536273
60 05/02/2018	734240 O-RING COL	Creditor #:GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G219029 Receiving #:226503 Date :2018-05-02	536273
60 05/02/2018	734240 SEALING RING	Creditor #:GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G219029 Receiving #:226503 Date :2018-05-02	536273
60 05/02/2018	734240 Engine - Oil leak around bell housing	Clean gear box assy. and parts.	536273
60 05/02/2018	734240 MAGNETIC PLUG (40A3400)		536273
60 05/02/2018	734240 SUMP GASKET SCANIA K230 D9 551450 (1412666)		536273
60 05/01/2018	734240 Engine - Oil leak around bell housing	Remove all coolant pipe remove wirings start tpo remove gear box to remove need to remove air line pipe remove steering oil pipe its on the way. remove gear box assembly.	536065
60 05/01/2018	734240 REAR CRANK SEAL	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G218977 Receiving #:226383 Date :2018-05-01	536273
60 05/01/2018	734240 SENDER OIL PRESS. L94		536065
60 05/01/2018	734240 FILTER OIL SCANIA SR4 [EARLY] K320 (LF3730) (H200W20)		536065
60 05/01/2018	734240 SEAL PRIMER PUMP SCANIA	Creditor #:GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G218973 Receiving #:226457 Date :2018-05-02	536273
60 05/01/2018	734240 GASKET	Creditor #:GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G218973 Receiving #:226457 Date :2018-05-02	536273
60 05/01/2018	734240 GASKET	Creditor #:GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G218973 Receiving #:226457 Date :2018-05-02	536273
60 05/01/2018	734240 GASKET	Creditor #:GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G218973 Receiving #:226457 Date :2018-05-02	536273
60 05/01/2018	734240 GASKET	Creditor #:GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G218973 Receiving #:226457 Date :2018-05-02	536273
60 05/01/2018	734240 PUMP WATER PUMP SCANIA S4	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G218977 Receiving #:226383 Date :2018-05-01	536273
60 04/30/2018	734240 Engine - Oil leak around engine oil cooler	Drain coolant remove water pump assembly remove oil pipe oil cooler and accessories. remove oil filter assembly. clean parts. parts need to change oil sender water pump assembly oil cooler gasket and oil filter base gasket banjo bolt washer.	536065
60 04/30/2018	734240 Engine - Oil leak around bell housing	Start to remove.	536065
60 04/30/2018	735627	CARRY OUT FIRE EXTINGUISHER TEST & TAG	536065
60 04/30/2018	735627	COMPLETED ON 15/02/18	536065
60 04/20/2018	734060 Vandalism Vandalism/ Graffiti InteriorGraffiti on rear	cleaned by refuellers	536065
60 04/20/2018	734240 Engine - Oil leak around engine oil cooler	Check for leak positive leaking around oil cooler need to change gasket and water pump leaking coolant as well and have play.	536065
60 04/20/2018	734240 Engine - Oil leak around bell housing	Check positive oil leak around bell housing need to remove gear box.	536065
60 04/17/2018	733254 PERFORM CAMPAIGN 26/17 BUSES REQUIRING FRONT DBI ENGAGEMENT	has already been completed (spoke to Ben)	535620
60 04/16/2018	732883 Consumables		535805
60 04/16/2018	732883 Consumables		535805
60 04/16/2018	732883 Ops Entered - Fault - Elec and Light Indicators Not Working	Dulkit fixed	535620
60 04/13/2018	732801	Re tensioned 78 tyres with craig	535620
60 04/12/2018	732511 Consumables		535620
60 04/12/2018	732511 Consumables		535620
60 04/12/2018	732511 TYRE 275/70R22.5 RECAP		535430
60 04/12/2018	732511 Mechanic entered - Wheels and Tyres Worn rear n/s outer no 7	removed and replaced pos 78 tyres.Tensioned wheel nuts with Nick	535430
60 03/19/2018	727607 Rectify Vandalism damage reported by refuelers	Completed	532927
60 03/14/2018	726795 Air System Air_Leak Front	Wrong bus eneterd.	532493
60 03/09/2018	726081 Consumables		532347
60 03/09/2018	726081 Consumables		532347
60 03/09/2018	726081 Consumables		532347
60 03/09/2018	726081 Consumables		532347
60 03/09/2018	726081	CARRY OUT A SERVICE AS PER CHECK LIST	532198
60 03/09/2018	726081	CARRY OUT A SERVICE AS PER CHECK LIST	532198
60 03/07/2018	725429	Tensioned pos 5 and 6 tyres.	531792
60 03/07/2018	725429	Assisting	531792
60 03/06/2018	725017 Breakdown - Flat tyre.	Attend breakdown in Chapel St Moorabbin found tyre had blown out. Bring slowly to Moorabbin depot and arrange after hours tyre assit to replace tyre.	531792
60 03/06/2018	724925 Breakdown#:34591 - Ops Entered - Breakdown - Breakdown Tyre	Arranged Satya. Organised Ten - 24 to repair tyre. Satya helped in changing the tyre.Called and asked me top bookback for re-tension.	531792
60 02/27/2018	722919 Please remove any old poster and fit new ones multi choice	Fitted by Refuellers	531194
60 02/27/2018	722815 PERFORM CAMPAIGN 06/18 REPLACEMENT OF NO ACCESS / PARK BRAK	Replaced decal	531194
60 02/26/2018	718168 Consumables		531194
60 02/26/2018	718168 Mechanic entered - Elec and Light Other Master fuse behind b	Removed and instaled new fuse holder box on bus.	530400
60 02/22/2018	718168 FUSE HOLDER	Creditor #:GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G214652 Receiving #:221789 Date :2018-02-27	531194
60 02/22/2018	718168 1904634 PROTECTOR & FUSES	Creditor #:GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G213349 Receiving #:221712 Date :2018-02-26 1 X 1794985 VSYD	531000
60 02/21/2018	721635 Consumables		530530
60 02/21/2018	721635 LAMP SIDE MARKER (RED+AMBER)		530400
60 02/21/2018	721635 Mechanic entered - Elec and Light Other smashed side clearan	removed and replaced lens	530400
60 02/21/2018	721002 Ops Entered - Fault - Air System Warning Light On - Route:		530400
60 02/20/2018	721002 Consumables		530530
60 02/20/2018	721002 Elec and Light Doors switches faulty	check and found brocken wire for door read switches fixed wire road test bus ok.	530400
60 02/20/2018	721002 SILENCER DOOR VALVE SILENCER		530400
60 02/19/2018	721002 BUTTON CLIPPARD DOOR VALVE 49Z4811		530400
60 02/19/2018	721002 VALVE CLIPPARD DOOR OPEN/CLOSE (11916-2) BUTTON		530400
60 02/19/2018	721002 Elec and Light Doors switches faulty	R/R door emergency exit switch. C/F	530400

60 02/14/2018	718168 1904634 PROTECTOR & FUSES	Creditor #:GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G213349 Receiving #:221710 Date :2018-02-26 1 X 1794985 VSYD	531000
60 02/13/2018	718667 EMERGENCY EXIT BUTTON PULL COVER (16906)		529922
60 02/13/2018	718667 Ops Entered - Fault - Air System Air_Leak Rear - Route: 811	fixed air system road test bus ok fixed door emergency button cover	529922
60 02/12/2018	718667 Ops Entered - Fault - Air System Air_Leak Rear - Route: 811	check air system and find problem c/o	529922
60 02/12/2018	718667 AIR DRYER VALVE		529922
60 02/09/2018	718616 Consumables		529922
60 02/09/2018	718616 Ops Entered - Fault - Elec and Light Indicators Not Working	check and fixed ideicator bus ok.	529922
60 02/09/2018	718667 AIR DRYER VALVE BLOCK (BLACK B	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G213479 Receiving #:220654 Date :2018-02-09	529922
60 02/09/2018	718667 Ops Entered - Fault - Air System Air_Leak Rear - Route: 811	checked air system find water seperater n/w unloder value full of water order parts	529922
60 02/09/2018	718667 KIT CYCLONE CONDENSER VALVE KIT		529922
60 02/08/2018	717139 REPAIR SPEED SWITCH ON DOOR	Creditor #:GB-SMC001 SMC PNEUMATICS (AUST) PTY LTD P/O #:G213202 Receiving #:220775 Date :2018-02-13	529922
60 02/07/2018	717139 RELAY SPEED SCANIA		529662
60 02/07/2018	717139 Ops Entered - Fault - Warning Lights Engine - Route: - Arr	Completed by SMC	529662
60 02/07/2018	718168 Mechanic entered - Elec and Light Other Master fuse behind b	Found master fuse touching bat cradle causing alt fuse to blow and cause rpd to come on.Fixed temorarily.Lee Chasing up new fuse.	529662
60 02/07/2018	718168 Elec and Light Rectify RPD having issues.	schecked rpd inputs.Found no engine run signal. checked plug to make sure wirse no come out.Checked fuses on bus side of things found alternatorcharge fuse blown.Put new one in and road tested ok.	529662
60 02/05/2018	717136 SCANIA ALT BELT TENSIONER K1241B (40N0903)		529662
60 02/02/2018	717116	VEHICLE SAFETY INSPECTION - Done by Mark Holt.	529662
60 02/02/2018	717116	VEHICLE SAFETY INSPECTION	529662
60 02/02/2018	717116 Service	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	529662
60 02/02/2018	717139 Ops Entered - Fault - Warning Lights Engine - Route: - Arr	Doors sticking shut.Checked rpd and ok.Checked switches and ok.Checked plc when pressing switches and lighting up.Checked valves and ok.Removed road speed sensor and doors still sticking shut also swapped with another bus and still same.Disconnected plc and operated doors from out side and openin and closing fin	529662
60 02/02/2018	716977 SCANIA ALT BELT TENSIONER K1241B (40N0903)		529662
60 02/02/2018	716977 Engine Belts_Loose Noisy Missing	atend to B/down fixe temperaly and drive to depot check alt belt replaced belt tensioner fixed coolant leak to top of drive beltes road test bus ok after road test passanger doors start playing need to check	529662
60 02/02/2018	717136 Mechanic entered - Engine Other Belt tensioner worn.	Remove and replace belt tensioner.	529662
60 02/01/2018	716761 Ops Entered - Fault - Passenger Doors - Route: 811d - Spri	Replace out side switch and test ok	529544
60 02/01/2018	716761 FITTING TEE FITTING 6mm x 1/8 (11080610)		529544
60 02/01/2018	716761 VALVE CLIPPARD DOOR OPEN/CLOSE (11916-2) BUTTON		529544
60 02/01/2018	716685 Perform Campaign 27/17 Positioning of 2018 PTV Fares Decals	Completed	529544
60 01/30/2018	715956 Fluid Leaks - Small coolant leak from hose next to coolant b	fit new coolant tanktop up coolant.	529326
60 01/30/2018	715956 TANK COOLANT TOP FILLER SCAN	Creditor #:GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G212435 Receiving #:219645 Date :2018-01-30	529326
60 01/30/2018	715956 Consumables		529377
60 01/30/2018	715956 Consumables		529377
60 01/30/2018	715956 Ops Entered - Fault - Body Front_Door Operation Faulty - Ro	clean and lube door hinges and rollers. checked ok. clean and lube door pivots and rollers.	529326
60 01/29/2018	715956 Fluid Leaks - Small coolant leak from hose next to coolant b	remove coolant tankwaiting parts.	529326
60 01/09/2018	712537 Air System Air_Leak-not sure of location in the bus-twice	Checked bus - all ok.	527897
60 01/05/2018	711944 Consumables		527707
60 01/05/2018	711944 Consumables		527707
60 01/05/2018	711944 Elec and Light - Indicator lever doesn't stay	Checked - ok.	527583
60 12/29/2017	710512 Wipers and Washers - Wipers are not working	Replace fuse	527055
60 12/28/2017	710302 Consumables		526971
60 12/28/2017	710302 GLOBE 24V 2W		526780
60 12/28/2017	710302 GLOBE 24V 5W FESTOON (17136)		526780
60 12/28/2017	710302 Elec and Light - RH side tail side park light out	changed blown festoon (osr) clearance light and blown globe (osf) bottom park light.	526780
60 12/27/2017	709645 Consumables		526823
60 12/27/2017	709645 Elec and Light - Rectify headlights n/w.	checked wiring. secured conection and wiring harness in place. roadtested bus. working ok. p.t.i'd fuelled and parked bus. complete	526780
60 12/21/2017	709645 Elec and Light - Rectify headlights n/w.	Checked wiring at bumper and elec panel found nothing.Removed dash and checked wiring there found loom going to ignition causing the issue will look and fix tommoro.	526677
60 12/20/2017	709357 Consumables		526677
60 12/20/2017	709357 LENS TO SUIT 2029 (RED & AMBER)		526637
60 12/20/2017	709357 Mechanic entered - Elec and Light Exterior Lights	fitted side clearance cover and also globe now workioing	526637
60 12/20/2017	707217 Accident#:46497 - Ops Entered - Accident - Bus is hit by 3r	Repaired by ECTB	526637
60 12/11/2017	707217 Accident#:46497 - Ops Entered - Accident - Bus is hit by 3r	Sent bus to ECTB	526637
60 12/01/2017	701913 CLEAN GRAFFITI INSIDE	Creditor #:GB-EAS002 EASTCOAST TRUCK & BUS SERVICE P/O #:G207272 Receiving #:216014 Date :2017-12-07	526487
60 12/01/2017	705555 Mechanic entered - Body Other 2nd Last fluro diffuser at rea	Fitted with second hand diffusers that I cut up.	525726
60 12/01/2017	705551 BELT SEAT BELT R/H A60RH		525726
60 12/01/2017	705551 Mechanic entered - Body Drivers Seat Belt Drivers seat belt	adjusted belt and put new belt stalk.	525726
60 12/01/2017	705550 Ops Entered - Fault - Passenger Doors - Route: 812d - Dande	checked and found door override on.Reset door override now ok.	525726
60 11/30/2017	705210 Drv entered - A/C Heating Not Cooling	checked ok	525726
60 11/30/2017	705158 Breakdown#:34145 - Ops Entered - Breakdown - Breakdown Road	road test drain air tanksfit new tank drain valveroad tested ok.	525726
60 11/30/2017	705158 VALVE MANUAL DRAIN VALVE		525726
60 11/28/2017	704523 Drv entered - Suspension Kneel/ Raise	check and fixed rear suspension	525683
60 11/24/2017	704126 Consumables		525683
60 11/24/2017	704126 Drv entered - Elec and Light Exterior Lights	found headlights not working checked fuses and head light relay and ok.removed plug and cleaned put back and working.	525490
60 11/23/2017	659471 VALVE FOUR WAY SCANIA	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G192990RET1 Receiving #:215023 Date :2017-11-24	525490
60 11/22/2017	703462 DIRECT PURCHASE - VANDALISM	Creditor #:GB-GLA010 GLASSPROTECH MELBOURNE P/O #:G205181 Receiving #:214785 Date :2017-11-22 REPLACE ANTI GRAFFITI FILM PRINTED DOT FILM	525203
60 11/22/2017	703462 Vandalism - Replace anti graffiti film - L1233a4 & R13	Replaced by Glassprotech 04/10/17	525203
60 11/21/2017	659471 VALVE FOUR WAY SCANIA	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G192990RET Receiving #:214646 Date :2017-11-21	525084
60 11/16/2017	701913 Clean graffiti inside	cleaned	524852
60 11/16/2017	702252 Ops Entered - Fault - Air System Air Not Building_Up - Rout	look for the defect replaced rear fourway valve road tested ok	524852
60 11/16/2017	701913 Mechanic entered - Air System Air_Leak Rear no 2 air gage go	look for the defect replaced rear new 4 way protection valve.	524852
60 11/16/2017	701913 VALVE MANUAL DRAIN VALVE		524852
60 11/16/2017	701913 VALVE FOUR WAY SCANIA		524852
60 11/14/2017	701575 Check and repair air won't build up intermitten	Road tested bus could not fault anything.	524754
60 11/13/2017	701283 Mechanic entered - Vandalism Vandalism/ Graffiti Interior		524754
60 11/08/2017	700048 Please remove the 2 x Do Not Enter decals at the exterior	Removed stickers	524453
60 11/06/2017	699949	Completed with Sisil	524453
60 11/06/2017	699949	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	524453
60 11/06/2017	699949	VEHICLE SAFETY INSPECTION	524453
60 11/02/2017	699051 Ops Entered - Fault - Air System Air_Leak Front - Route: 81	fit new broms brake pipe union.	524369
60 11/02/2017	699051 UNION ASSY	Creditor #:GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G206387 Receiving #:213468 Date :2017-11-02	524369
60 11/01/2017	699051 Ops Entered - Fault - Air System Air_Leak Front - Route: 8	Brom brakes won't release found hose came off temp fix hose took to M.T depot fixed grinding on on alternator bracket fitted missing bolts & sent bus to Dandy for hose repair	524252
60 11/01/2017	699040 Breakdown - Brake won't release.	Attend breakdown found broms brake pipe came off temp fix and bring bus back to Moorabbin depot to repair grinding noise from alternator bracket. Replace missing bolts and send back to Dandenong for repairs on air line.	524252
60 10/31/2017	698264 Air System Air Not Building_Up	check air leak and clean air dump value and check bus ok.	523995
60 10/30/2017	698200 Air System Air Not Building_Up	Checked could not fault.	523995
60 10/30/2017	698200 Ops Entered - Fault - Air System Air Not Building_Up - Rou	Checked could not fault.	523995
60 10/27/2017	697534 Consumables		523805
60 10/27/2017	697534 Consumables		523805
60 10/27/2017	697534 GLOBE 24V 10W SINGLE CONTACT		523601
60 10/27/2017	697534 GLOBE 24V 21W SINGLE CONTACT (HLR2421) (47241)		523601
60 10/27/2017	697534 INDICATOR LIGHT FRONT ARTIC	changed blown globe (osf) top marker light.	523601
60 10/27/2017	697534 Mechanic entered - Elec and Light Exterior Lights . front pa	changed blown globe; fixed loose electrical connection and replaced broken (nsf) corner indicator light.	523601
60 10/27/2017	697534 Drv entered - Elec and Light Exterior Lights		523601
60 10/25/2017	697064 Consumables		523601
60 10/25/2017	697064 Drv entered - Elec and Light Indicators Not Working	Checked could not fault.	523484
60 10/25/2017	697064 Consumables		523601
60 10/24/2017	696704 Check if fueltank cap is closing properly ? Due to fuelspi	Checked fuel cap - ok. If filled right up to the neck will leak from the breather.I will talk to the refuellers.	523377
60 10/23/2017	696428 Ops Entered - Fault - Body Drivers Seat Belt - Route: - Arr	Check found faulty replace driver seat belt.	523219

[illegible]

60 06/15/2017	667183 DIRECT PURCHASE - BUS INSPECTI	Creditor #:GB-ROA001 Road Safety Inspections P/O #:G195678 Receiving #:202946 Date :2017-06-20	514905
60 06/15/2017	667669 Suspension - NS torque rod bush clip front	assist to replace torque rod bush.	514903
60 06/15/2017	667669 Suspension - NS torque rod bush clip front	Put bus on hoist remove torque rod and fit new bush re- fit torque rod.lower bus	514903
60 06/15/2017	667669 BUSH TORQUE ROD BUSH SCANIA/MERCEDES (1517403) (2520801)		514903
60 06/15/2017	667670 Body - Concertina rod broken on bottom of bus.	repaired.	514903
60 06/15/2017	667670 BRAKE BOOSTER SCANIA L94UAB (35CLE0100)		514903
60 06/15/2017	667670 Brakes - O/S Mid axle booster	Remove wheel replace o/s middle booster re- tension wheel nuts with kuma	514903
60 06/15/2017	667666	CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST began fire safety carry over.	514903
60 06/14/2017	667183	ANNUAL SAFETY INSPECTION - RWC 013142 - PASSED - 14/06/17	514903
60 06/09/2017	666788	Assisting	514538
60 06/09/2017	666788	Tensioned tag axle tyres	514538
60 06/09/2017	666577 Consumables		514814
60 06/09/2017	666577 GLOBE 24V 5W CLEARANCE DOUBLE CONTACT		514538
60 06/09/2017	666577 GASKET LIGHT GASKET FOR USE WITH 2139 2143 & 2043		514538
60 06/09/2017	666577 LENS RED TO SUIT 2319		514538
60 06/09/2017	666577 LENS TO SUIT 2143 LAMP		514538
60 06/09/2017	666577 SINGLE SEAT BASE		514538
60 06/09/2017	666577 STRUT GAS STAY 500Nm 330mm LONG		514538
60 06/09/2017	666577 PASS SEAT HANDGRIP CENTRA MK 2		514538
60 06/08/2017	666577 SCANIA L94 REAR SWAY BAR LINK	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G195410 Receiving #:202401 Date :2017-06-09	514739
60 06/08/2017	666577 Suspension - O/S & N/S/R sway bar link worn.	done	514538
60 06/08/2017	666577 Gearbox Driveline - steam clean for RSI	done.	514538
60 06/08/2017	666577 Engine - Replace engine mounts.	done	514538
60 06/08/2017	666577 Fluid Leaks - Repair coolant leaks on header tank hose	done.	514538
60 06/08/2017	666577 Elec and Light - replace rear saloon light globes	done.	514538
60 06/08/2017	666577 Elec and Light - replace brake light rear lenses	done.	514538
60 06/08/2017	666577 Elec and Light - Replace rear indictaor lenses.	done	514538
60 06/08/2017	666577 Elec and Light - Replace licence plate globes	done.	514538
60 06/08/2017	666577 Body - secure mid door modesty panel post.	fixed.	514538
60 06/08/2017	666577 Body - Replace O/S/R 2nd seat grab handles.	fixed.	514538
60 06/08/2017	666577 Body - Secure lower skirt panels	done	514538
60 06/08/2017	666577 Body - replace electrical hatch gas struts.	done.	514538
60 06/08/2017	666577 Body - Secure mid door grab handle.	done.	514538
60 06/08/2017	666577 Body - secure rear seat base from o/s 4th5th and 6th.	done	514538
60 06/08/2017	666338 STRUT GAS STAY 600Nm 540mm LONG		514538
60 06/07/2017	666118 Suspension - Replace O/S/F top torque rod bush.	replaced.	514538
60 06/07/2017	666118 KIT BUSH KIT TORQUE ROD SCANIA (49Y3314) (25208 01)		514538
60 06/07/2017	666118 MOUNT ENGINE SCANIA	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G195347 Receiving #:202347 Date :2017-06-07	514739
60 06/07/2017	666338 Body - replace engine hatch gas struts.	replced.	514538
60 06/07/2017	666118 WEAR SENSOR SCANIA DISC BRAKE 49G8410		514538
60 06/07/2017	666118 SET DISC PAD SET SCANIA / MERCEDES 0500		514538
60 06/07/2017	666118 Brakes - Replace mid axle brake pads.	replaced.	514538
60 06/07/2017	666118 VALVE RELAY SCANIA/VOLVO	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G195347 Receiving #:202348 Date :2017-06-07	514739
60 06/07/2017	666337 Air System - Replace mid axle relay valve.	replaced.	514538
60 06/06/2017	666027	PRE ANNUAL SAFETY INSPECTION CHECK done.	514538
60 06/06/2017	664827 AIR CONDITIONING REPAIR	Creditor #:GB-22C001 22 CELSIUS P/O #:G196659 Receiving #:203540 Date :2017-06-28	515472
60 06/06/2017	664827 Ops Entered - Fault - Heat & Demist - Route: 813 - Dandeno	Repaired by 22c	514538
60 06/06/2017	666118 Brakes - Replace mid axle brake pads.	Start mid axle brake pad change c/o	514538
60 06/03/2017	664827 Ops Entered - Fault - Heat & Demist - Route: 813 - Dandeno	tested and found right bank rear unit has no refrigerant 22c warranty	514538
60 06/02/2017	645283 Consumables		514739
60 06/02/2017	645283 RELAY VOLVO H/LIGHT DIODE PROTECTED		514646
60 06/01/2017	645283 Body - Aluminium strip on conecrtino hanging down and broken	Has been rebooked	507781
60 05/31/2017	664827 SOLENOID VALVE MAGNET SVOM -18	Creditor #:GB-ACT002 ACTROL PARTS P/O #:G194934 Receiving #:201961 Date :2017-06-02	514739
60 05/31/2017	664827 Ops Entered - Fault - Heat & Demist - Route: 813 - Dandeno	Tested found constant fault light possible ecu lag	514538
60 05/26/2017	663372 Consumables		514246
60 05/26/2017	663372 GLOBE 24V 75/70W H4		514008
60 05/26/2017	663372 Mechanic entered - Elec and Light Exterior Lights N/S headli		514008
60 05/26/2017	663372 COMPRESSOR OIL AIR CON		514008
60 05/26/2017	663372 FILTER DRYER AIR COND 5/8 (3K171124)		514008
60 05/25/2017	663372 AIR CONDITIONING SERVICE	Creditor #:GB-22C001 22 CELSIUS P/O #:G194546 Receiving #:201774 Date :2017-05-31 B SERVICE	514538
60 05/25/2017	663372 Serviced by Daniel @ 22c	CARRY OUT A/C - B SERVICE AS PER CHECK LIST	514008
60 05/25/2017	663372	CARRY OUT A/C - A SERVICE AS PER CHECK LIST	514008
60 05/23/2017	662952 Consumables		514008
60 05/23/2017	662952 Fit A3 Poster/Hangers	Fitted	513869
60 05/05/2017	659471 VALVE FOUR WAY SCANIA	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G192990 Receiving #:199737 Date :2017-05-05	512262
60 05/04/2017	659471 Air System Air Not Building_Up	R/R middle and rear 4 way protection valve. Drive tested and check the build up of air. OK	512160
60 05/03/2017	659216	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	511992
60 05/03/2017	659216	VEHICLE SAFETY INSPECTION	511992
60 05/03/2017	659216		511992
60 05/03/2017	659214 Drv entered - Air System Warning Light On	Assisted	511992
60 05/03/2017	659214 Drv entered - Air System Warning Light On	Test drove cheked ok	511992
60 05/03/2017	659215 Consumables		512160
60 05/03/2017	659215 Consumables		512160
60 05/03/2017	659215 Consumables		512160
60 05/03/2017	659215 Consumables		512160
60 05/03/2017	659215		511992
60 05/03/2017	659215	CARRY OUT A SERVICE AS PER CHECK LIST	511992
60 04/28/2017	658455 Assisting.	Assisting	511663
60 04/28/2017	658455 Tensioned front tyres.		511663
60 04/28/2017	658359 Consumables		511764
60 04/28/2017	658359 Elec and Light Flat Batteries	found fault with engine hatch switch. rectified bus starting ok now. complete	511663
60 04/27/2017	658208 BLADE WIPER BLADE 28 INCH ARTIC		511548
60 04/27/2017	658208 Drv entered - Wipers and Washers Washers Not Working	replaced wiper washer pump.+ replaced n/s wiper blade.	511548
60 04/27/2017	658208 Drv entered - Wipers and Washers Washers Not Working	done.	511548
60 04/27/2017	658210 Consumables		511663
60 04/27/2017	658210 Wheels and Tyres Vibration front tyres	Assisting	511548
60 04/27/2017	658210 Wheels and Tyres Vibration front tyres	R/R wheel nuts and tensioned wheel nuts with Shalen.	511548
60 04/27/2017	658208 Steering - Steering wobbles under 60 ks	Found front tyres worn unevenly. replaced front tyres.	511548
60 04/27/2017	658208 Brakes - Pulling to right when putting on brakes	checked front caliper ok adjust brake. road tested.;	511548
60 04/19/2017	656889	TRANSMISSION CHECK AS PER CHECK LIST completed	510915
60 04/19/2017	656889	TRANSMISSION CHECK AS PER CHECK LIST completed	510915
60 04/19/2017	656898 Breakdown#:33331 - Ops Entered - Breakdown - Breakdown Road	REF TO W/O 656411	510915
60 04/14/2017	656411 Breakdown#:33332 - Ops Entered - Breakdown - Breakdown Road	assit with Ranjith	510770
60 04/14/2017	656411 Breakdown#:33332 - Ops Entered - Breakdown - Breakdown Road	Remove idler post and oil filler pipe from bus 13 and fitted to bus 60 also tested	510770
60 04/04/2017	647461 ASSEMBY A/C IDLER PIVOT ARM & BASE BRACKET - COACHAIR		509761

60 04/04/2017	654698 Body (None) / Interior roof panel has fallen to the floor	secured o/s roof panel	509761
60 04/01/2017	630906 Consumables		509761
60 04/01/2017	630906 SUPPLY & FIT ROLLAWAY	Creditor #:GB-BWE001 BWERE ELECTRICS P/O #:G184453 Receiving #:197817 Date :2017-04-06	510235
60 03/29/2017	653683	Assisting	509336
60 03/29/2017	653683	Tensioned pos 8 tyre	509336
60 03/28/2017	653311 Consumables		509336
60 03/28/2017	653311 Consumables		509336
60 03/28/2017	653311 TYRE 275/70R22.5 RECAP		507781
60 03/28/2017	653311 Wheels and Tyres - Tyre 8 on wear bar		507781
60 03/28/2017	653311 Mechanic entered - Wheels and Tyres Worn		507781
60 03/24/2017	647461 Drv entered - A/C Heating Not Cooling		507781
60 03/24/2017	652871 Consumables		509171
60 03/24/2017	652871 Consumables		509171
60 03/24/2017	652871 GLOBE 24V 21/SW STOP AND TAIL LAMP (17925)		507781
60 03/24/2017	652871 Mechanic entered - Elec and Light Exterior Lights	Replaced O/S/R brake/stop light globe	507781
60 03/20/2017	647461 NITROGEN DRY D SIZE		507781
60 03/20/2017	647461 AIR CON REFRIDGERANT		507781
60 03/20/2017	647461 SWITCH MP 100-150		507781
60 03/20/2017	647461 FILTER DRYER AIR COND 5/8 FLARE		507781
60 03/20/2017	647461 COMPUTER SLRT/RM-RP		507781
60 03/20/2017	647461 Consumables		508610
60 03/20/2017	647461 Consumables		508610
60 03/20/2017	647461 Mechanic entered - Elec and Light Exterior Lights	Replaced rear top park light globe	507781
60 03/17/2017	647461 FUSE BLADE 10 AMP (NRS2810)		507781
60 03/17/2017	647461 FUSE BLADE 7.5 (52807-1)		507781
60 03/07/2017	649557 Vandalism Vandalism/ Graffiti Interior Etchings on Windo	Bus 60 was graffiti refurbished inside.	507781
60 03/06/2017	647461 AIR CON REFRIDGERANT		507781
60 03/03/2017	647461 ASSEMBY A/C IDLER PIVOT ARM &	Creditor #:GB-COA001 COACHAIR PTY LTD P/O #:G188392 Receiving #:195877 Date :2017-03-14	508392
60 02/24/2017	647461 RELAY 5 PIN CHANGE OVER 24V 10/20 AMP 68052		507781
60 02/24/2017	647461 FUSE BLADE 7.5 (52807-1)		507781
60 02/24/2017	647461 Drv entered - A/C Heating Warning Light On	Rear unit run commission test found thaat the unit has a dead short taking out the CCC and th ESP had none in stock so repaired one to check unit got the unit up and running found that the No2 compressor was going into a vacuum possible fault at the liquide line solenoid u nable to get on the roof parts have been ordere	507781
60 02/24/2017	647461 A/C Heating Not Cooling	Frount unit Fitted gauged found unit had lost its charge pressure tested unit found that the unloader stem had worm replaced unloader and check again found that the liquide line covalve is weeping will need to be repaired	507781
60 02/23/2017	647005 Body Rear door rubber comes off	Fixed	507781
60 02/21/2017	646417 Please remove any old poster and fit either Good News for T	FITTED BY FLEET SUPPORT	508074
60 02/17/2017	645537 PERFORM CAMPAIGN 01/17 SMARTRAK DRIVER CONTROL CONSOLE AUDIT	DCC FITTED - YES TIME DISPLAYED - YES	507866
60 02/16/2017	645283 Body - Aluminium strip on conectrino hanging down and broken	found turntable floor rail broken. attempting to order replacement. carry over.	507781
60 02/14/2017	644562 Consumables		507706
60 02/14/2017	644562 Wheels and Tyres - TYRE 4 FLAT	check all tyres ok bus serviceble.	507546
60 02/14/2017	644562 Wheels and Tyres Flat or Leaking	check all tyres ok bus serviceble.	507546
60 02/07/2017	616377 Consumables		506944
60 02/07/2017	616377 Consumables		506944
60 02/07/2017	616377 KIT O-RING LARGE VOSS (A6739970145)		506702
60 02/03/2017	642559 Consumables		506702
60 02/03/2017	642559 Service	Checked ramp sent bus out it has been booked to have floor repaired in bodyshop	506660
60 02/02/2017	642468		506660
60 02/02/2017	642468	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	506660
60 02/02/2017	642468	VEHICLE SAFETY INSPECTION	506660
60 02/02/2017	642543 Drv entered - Ticket Equip	control room	506660
60 02/02/2017	642559 Service	Found w/chair ramp not closing properly due to rotted floor & loose bracket. gave to body shop to repair	506660
60 02/02/2017	642559 Breakdown - #33180 - Dandenong - Rear brakes holding	Found door brake holding turned off and returned bus to depot	506660
60 01/31/2017	642086 Drv entered - Ticket Equip	CONTROL ROOM	506405
60 01/30/2017	638689 Consumables		506405
60 01/30/2017	638689 FUSE BLADE 10 AMP		505416
60 01/30/2017	638689 GLOBE 24V 10W SINGLE CONTACT		505416
60 01/30/2017	638689 Elec and Light (None) jack knife light comes on bus goin	complete. roadtest and p.t.i ok.	505416
60 01/30/2017	638689 Elec and Light (None) jack knife light comes on bus goin	assisted with jack knife problem/	505416
60 01/24/2017	638689 Elec and Light (None) jack knife light comes on bus goin	helping out with diagnosing jack knife fault.	505416
60 01/24/2017	638689 Elec and Light (None) jack knife light comes on bus goin	continued tracing fault had pascal close up panels and check ancillary wiring. carry over.	505416
60 01/13/2017	638689 Elec and Light (None) jack knife light comes on bus goi	Started to pull down t/table bellows to get access to check wiring c/o tested continuity between front electrical centre and rear of turntable. found no signal in one wire to articulation control unit. pulled down wiring in turntable to find break. carry over.	505416
60 01/12/2017	625555 A/C Heating Not Heating		505416
60 01/06/2017	637291 A3 POSTER CHANGE X 4 ENDING JAN 2017 PLEASE SEE CAMPAIGN A	REPLACED	505416
60 01/04/2017	636857 Fit New 2107 Large and Small Fares Small Concessionand AO	REPLACED	505416
60 12/30/2016	630595 Consumables		506308
60 12/30/2016	630595 Body Drivers Seat Leaning and worn	Secured	505416
60 12/29/2016	630595 Body Drivers Seat Leaning and worn	removed old seat. transferred seat belt and buckle to new one. connected air line. **seat needs to be fastened to base**.	506308
60 12/28/2016	635531 Ops Entered - Fault - T'rntable - Route: 811d - Lwr Dandeno	roadtested bus. checked fault codes no turntable faults are logged in system. took bus around the yard at multiple full lock jackknife positions and could not replicate fault. p.t.i'd fuelled and parked bus.	505416
60 12/28/2016	635531 Consumables		506308
60 12/28/2016	635531 Body (None): turntable alarm is alway on when driving	checked roadtested bus and could not find fault with turntable	505416
60 12/14/2016	630595 SEAT SEAT ASSY ISRI A6008 AIR LUMBAR CHANGE OVER		505416
60 12/06/2016	630595 Gearbox Driveline Diff pinion seal leaking	replacde.	505416
60 12/06/2016	630595 Ops Entered - Fault - Warning Lights Engine - Route: 2229 -	check o/k.	505416
60 12/05/2016	630906 Mechanic entered - Engine Other	Remove idler pulleys and fit new ones	505416
60 12/05/2016	577634 Consumables		505416
60 12/05/2016	577634 MOTOR STARTER MOTOR SCANIA K93 & L94	PART CHARGED TO BUS DID NOT CURE FAULT PUT INSTORES & NEVER REMOVED FROM WORK ORDER ITEMFITTED TO BUS = 23 05/12/2016 LS	505416
60 12/02/2016	630595 IDLER PULLEY	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G182812 Receiving #:189029 Date :2016-12-02	505416
60 12/02/2016	630595 IDLER PULLEY SCANIA ARTIC (No Groove Plastic)		505416
60 12/01/2016	625555 FUSE BLADE 7.5 (52807-1)		505416
60 12/01/2016	630595 BELT ALT W/PUMP CRANK SCANIA ARTIC		505416
60 12/01/2016	630595 SCANIA ALT BELT TENSIONER K1241B (40N0903)		505416
60 12/01/2016	630595 Engine Steam clean engine and check for oil leak	Fit fuel lines.power steering linesclampsfit back alternatorsreplace alt belt bleed fuel system and power steering system	505416
60 12/01/2016	630906 Consumables		505416
60 12/01/2016	630906 PERFORM CAMPAIGN 08/16 BUS ROLLAWAY PREVENTION DEVICE (RPD)	Completed by Bwere electrical Bradman	505416
60 11/30/2016	630595 GASKET		505416
60 11/30/2016	630595 Engine Steam clean engine and check for oil leak	Remove fuel oil linesalternators and crankcase vent housingfit new gasket Fit back housing and fuel lines c/o	505416
60 11/30/2016	630595 PINION NUT SCANIA R660 DIFF	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G182608 Receiving #:188831 Date :2016-11-30	505416
60 11/30/2016	630595 SEAL COVER	Creditor #:GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G182617 Receiving #:188830 Date :2016-11-30	505416
60 11/30/2016	630595 SEAL DIFF PINION SCANIA L94+	Creditor #:GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G182617 Receiving #:188830 Date :2016-11-30	505416
60 11/28/2016	629020 PAINT ANTI GRAFFITI PAINT LIGHT GREY		505416
60 11/28/2016	629020 HARDENER DELFLEET GRAFFITI RESISTANT PER 500ML		505416
60 11/28/2016	629020 SUPPLIES BODY SHOP SUPPLIES		505416
60 11/28/2016	629020 CLEANER GRAFFITI REMOVER AMERASE PER LITRE		505416
60 11/28/2016	629020 PAINT ANTI GRAFFITI PAINT DARK GREY		505416
60 11/26/2016	629020 Vandalism Vandalism/ Graffiti Exterior	refit seats painted handgrips black PTI done	505416
60 11/25/2016	629020 Drv entered - Vandalism Vandalism/ Graffiti Interior	painted floor black two yellow entry squares refit light defuser n/s/r	505416
60 11/25/2016	629020 No Standing On Turntable Decal		505416

[illegible]

60 07/01/2016	601186 Ops Entered - Fault - Engine Low Power - Route: 804 - Chads	checked fuel system replaced air filter road test bus ok.	494961
60 07/01/2016	601529 Body - Remove till tray	Removed	496775
60 07/01/2016	601269 Body - Drivers seat lumbar support n/w and rear back rest wo	fixed driver seat lumba support air system.	494961
60 07/01/2016	601186	bus run ideling speed 15 min with lighta/c and others stop start again run 30 min changed both batterys.	494961
60 07/01/2016	601186 Brakes - Wheel rap brake n/w	adjusted wheel chair ramp senser check door brake all ok. removed till base.	494961
60 06/30/2016	600896	re-tensioned nuts on wheels 1; 2; 9 and 10.	494961
60 06/30/2016	601083 Breakdown#:32662 - Ops Entered - Breakdown - Breakdown Road	out 330 pm in 530 pm clayton fault wont start jump started.	494961
60 06/29/2016	599373 Consumables		496542
60 06/29/2016	599373 Elec and Light - Starting fault ref w/o # 589884 598331		494961
60 06/29/2016	598264	completed job. fit cable to turntable and rear of vehicle. parked on fuel bay for pti and fuelling.	494961
60 06/27/2016	599373 Elec and Light - Starting fault ref w/o # 589884 598331	CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST	494961
60 06/24/2016	599373 Elec and Light - Starting fault ref w/o # 589884 598331	continued running wiring through bus. carry over.	494961
60 06/23/2016	599373 30M ROLL BATTERY CABLE RED 16.	began running new cabling. carry over.	494961
60 06/22/2016	599373 Elec and Light - Starting fault ref w/o # 589884 598331	Creditor #:GB-LON001 LONSDALE ST AUTO ELECTRICS P/O #:G170773 Receiving #:177636 Date :2016-07-01	496542
60 06/21/2016	598331 ANTI GRAFFITI PAINT LIGHT GREY	ordered cabling and conduit to suit bus. removed cable from turntable and rear of bus. carry over.	494961
60 06/21/2016	598331 ANTI GRAFFITI PAINT DARK GREY		494961
60 06/21/2016	598331 GRAFFITI REMOVER AMERASE PER LITRE		494961
60 06/21/2016	598331 HARDENER DELFLEET GRAFFITI RESISTANT PER LITRE		494961
60 06/21/2016	599373 Elec and Light - Starting fault ref w/o # 589884 598331		494961
60 06/20/2016	598331 Vandalism - Graffiti inside of bus	Pulled down underneath t/table to gain access to battery cable began removing cable	494961
60 06/20/2016	598331 Vandalism Vandalism/ Graffiti Interior	painted	494961
60 06/20/2016	598331 Vandalism Vandalism/ Graffiti Interior	painted	494961
60 06/20/2016	598331 Consumables	painted	496396
60 06/20/2016	598331 Elec and Light - Starting fault ref w/o # 589884	put bus on hoists in workshop. placed stands for safety. began removing cable in turntable to be replaced carry over.	494961
60 06/18/2016	598331 Mechanic entered - Vandalism Vandalism/ Graffiti Interior	painted	494961
60 06/18/2016	598331 Mechanic entered - Vandalism Vandalism/ Graffiti Interior	painted graffiti with pascal	494961
60 06/17/2016	597691 DIRECT PURCHASE - BUS INSPECTI	Creditor #:GB-ROA001 Road Safety Inspections P/O #:G170226 Receiving #:176334 Date :2016-06-21	496396
60 06/16/2016	598331 Elec and Light - Starting fault ref w/o # 589884	Parked in w/shop began setting up hoists removed t/table floor for access to battery cable	494961
60 06/15/2016	597691	ANNUAL SAFETY INSPECTION - RWC 006953 - PASSED - 15/06/16	494961
60 06/15/2016	596451 Consumables		496396
60 06/15/2016	596451 GLOBE 24V 21W SINGLE CONTACT (HLR2421)		494961
60 06/15/2016	596451 HEADLAMP HI-LOW RECTANGULAR MK3 B10M 72086		494961
60 06/15/2016	596451 GLOBE 24V 75/70W H4		494961
60 06/15/2016	596451 GLOBE 24V 2W		494961
60 06/15/2016	596451 Mechanic entered - Elec and Light Exterior Lights	changed blown globes and replaced damaged (ns) low / high beam headlight.	494961
60 06/14/2016	597408 Please remove any old poster and fit new A3 poster and add	done by fleet support	494961
60 06/10/2016	596451 Suspension - Front axle sway bar links worn	fit new links.	494961
60 06/09/2016	596451 Consumables		496396
60 06/09/2016	596451 TYRE NEW 275/70R22.5		494961
60 06/09/2016	596451 Mechanic entered - Wheels and Tyres Vibration	fit new front tyres.road rested ok.	494961
60 06/09/2016	596451 Suspension - Front axle sway bar links worn	fit new fron swaybar links x2.road tested ok.	494961
60 06/09/2016	596451 Steering - Track rod ball joint worn (fitted end)	fit new track rod	494961
60 06/09/2016	596451 Gearbox Driveline - Diff pinion seal leaking	replaced seal	494961
60 06/09/2016	596451 SINGLE SEAT BASE	Creditor #:GB-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:G169771 Receiving #:175874 Date :2016-06-10	496396
60 06/09/2016	596451 Body - No 5 seat cushions torn L & R	fit repaired cushions X3	494961
60 06/08/2016	596451 Wheels and Tyres - RHR tyres worn (both)	fit new tyres to pos 9&10	494961
60 06/08/2016	596451 TYRE RECAP 275/70R22.5		494961
60 06/08/2016	596451 LINK SWAYBAR SCANIA K230 1766	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G169830 Receiving #:175742 Date :2016-06-08	496396
60 06/08/2016	596451 Suspension - LHF upper torque rod bushes worn	fitted new bushes.	494961
60 06/08/2016	596451 Suspension - LHR forward shock absorber leaking	new shocker fitted.	494961
60 06/08/2016	596451 Suspension - Front sway bar bushes worn		494961
60 06/08/2016	596451 BUSH TORQUE ROD SCANIA M/B 1517403 25208 01	fit new bushes.	494961
60 06/08/2016	596451 SHOCKER FRONT SCANIA K230		494961
60 06/08/2016	596451 BUSH SWAY BAR FRONT SCANIA SR4 & K230 0469081 1919010		494961
60 06/08/2016	596451 TIE ROD ASSY K230	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G169830 Receiving #:175742 Date :2016-06-08	496396
60 06/08/2016	596451 SEAL PINION DIFF SR4 SCANIA 15	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G169920 Receiving #:175768 Date :2016-06-09	496396
60 06/08/2016	596451 PINION NUT SCANIA R660 DIFF	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G169920 Receiving #:175768 Date :2016-06-09	496396
60 06/08/2016	596451 LENS TO SUIT 2029 (RED+AMBER)		494961
60 06/08/2016	596451 LAMP INDICATOR [ORANGE]		494961
60 06/08/2016	596451 INDICATOR LIGHT FRONT ARTIC		494961
60 06/08/2016	596451 Elec and Light - Bus stop light n/w (rear section)	new globes fitted	494961
60 06/08/2016	596451 STOP LAMP LENS		494961
60 06/08/2016	596451 Elec and Light - Top stop/tail light lens cracked (both)	replaced	494961
60 06/08/2016	596451 Elec and Light - Both rear sides marker lenses broken	replaced	494961
60 06/08/2016	596451 Elec and Light - RHF indicator lens cracked	new indicator unit fitted.	494961
60 06/08/2016	596451 NUT HAND RAIL CLAMP (280010)		494961
60 06/08/2016	596451 SCREW HAND CLAMP(P/N 280010)		494961
60 06/08/2016	596451 Body - Drivers door hinge broken	new hinge fitted.	494961
60 06/08/2016	596451 Body - Pax grab handles damaged x 3	new straps fitted.	494961
60 06/08/2016	596451 Body - Hand rail loose at front door	secured	494961
60 06/08/2016	596451 Body - RHS 4th seat mconnels cover broken	repaired	494961
60 06/08/2016	596451 Body - Hand pole at rear door screws missing		494961
60 06/08/2016	596451 Body - Rear window emer exit sign torn	new sign fitted.	494961
60 06/08/2016	596451 EMERGENCY EXIT (HAMMER)		494961
60 06/08/2016	596451 Body - Special needs stickers torn x 2	replaced	494961
60 06/08/2016	596451 Body - Demister vent cover broken	replaced	494961
60 06/08/2016	596451 PLASTIC TRIANGLE HANDSTRAP GREY		494961
60 06/08/2016	596451 CENTRA CUSHION CLIP RH		494961
60 06/08/2016	596451 CENTRA CUSHION CLIP LH		494961
60 06/08/2016	596451 SINGLE SEAT BASE		494961
60 06/08/2016	596451 HINGE DRIVERS COMPARTMENT 12205 49080		494961
60 06/08/2016	596451 BLACK PD NOZZLE AIR VENT DASH		494961
60 06/08/2016	596451 CENTRA SEAT END CAPS		494961
60 06/07/2016	595333		494961
60 06/07/2016	595333		494961
60 06/07/2016	594270 FUSE BLADE 10AMP		494961
60 06/02/2016	595333		494961
60 06/02/2016	595333	PRE ANNUAL SAFETY INSPECTION CHECK	494961
60 06/02/2016	595333		494961
60 06/02/2016	595333	PRE ANNUAL SAFETY INSPECTION CHECK	494961
60 06/01/2016	589884 REPAIR BUS NOT STARTING	Creditor #:GB-TRA100 TRAD AUTOTRONICS P/O #:G167435 Receiving #:175584 Date :2016-06-07	496396
60 05/27/2016	594270 MAP POCKETS COACH SEATS		494961
60 05/27/2016	594270 PERFORM CAMPAIGN 04/16 DRIVERS WALLETS AND MAP POCKET INSTA	Fited new one	494961
60 05/24/2016	593743 Breakdown Brighton town hall flat batteries.	Depart Moorabbin at 1600 Jump start and arrive back at 17.30 Arrive back	496396
60 05/24/2016	593490 Ops Entered - Breakdown - Breakdown Road Defect Affects Ser	Arranged breakdown and got feedback.	496396

60 05/24/2016	593490 Ops Entered - Breakdown - Breakdown Road Defect Affects Ser	Bridged starter motor but the startere motor was turning frreely for a while then got engaged.	496396
60 05/23/2016	589884 Ops Entered - Fault - T'rntable - Route: - Off service to	cleaned up wiring in front of turn table at junction. re checked signal boost from alternator. ok. closed up panels and turntable. parked on fuel bay.	494961
60 05/23/2016	593104	CARRY OUT A/C - A SERVICE AS PER CHECK LIST Evap fan brushes are @ 60% stock has not arrived will leave untill next service Rear unit evap brushes are at 65% no brushes in stock will replace next service	494961
60 05/19/2016	589884 Ops Entered - Fault - T'rntable - Route: - Off service to	continued tracinf fault. cleaned up junction box after turntable. carry over.	496214
60 05/18/2016	589884 Ops Entered - Fault - T'rntable - Route: - Off service to	repaired dash wiring. closedup engine electrical panel. moved buses and parked in red sqaures.	496214
60 05/17/2016	589884 Ops Entered - Fault - T'rntable - Route: - Off service to	assisted john with picoscope checking. carry over.	496214
60 05/16/2016	589884 Ops Entered - Fault - T'rntable - Route: - Off service to	started bus and brought to workshop then parked in line one.	496214
60 05/13/2016	589884 Ops Entered - Fault - T'rntable - Route: - Off service to		496214
60 05/13/2016	586493 FIT NEW CCTV		496214
60 05/12/2016	589884 Ops Entered - Fault - T'rntable - Route: - Off service to	Creditor #:GB-TH0005 THOREB AUSTRALIA PTY LTD P/O #:G168060 Receiving #:174255 Date :2016-05-19 UPGRADE C90	496214
60 05/11/2016	589884 Ops Entered - Fault - T'rntable - Route: - Off service to	assisted john with roadtesting bus and checking circuit with picoscope. found strange waveform pattern on start up. will need to follow up further.	496214
60 05/09/2016	590513 Consumables	had pascal assist with moving cables. cleaned up main battery cable to startermotor and battery solenoid. put panelling back together. got bus ready to go to scania.	496214
60 05/09/2016	590513 GLOBE & HOLDER INSTRUMENT PANEL GREY (NR47774)		496214
60 05/09/2016	590513 GLOBE FESTOON 24V 5W		496214
60 05/06/2016	590343		496214
60 05/06/2016	590343	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	496214
60 05/06/2016	590343	VEHICLE SAFETY INSPECTION	496214
60 05/06/2016	589884 Ops Entered - Fault - T'rntable - Route: - Off service to	Set up test wires r/tested bus to induce fault c/o	496214
60 05/06/2016	590513 Elec and Light - Park light n/w	Replaced	496214
60 05/06/2016	590513 Elec and Light - Dash globe n/w	Replaced	496214
60 05/06/2016	590337 As per Campaign 2/16 Review and Reset Camera Angles and ensu	set camera angle audio driver only	496214
60 05/04/2016	589884 Ops Entered - Fault - T'rntable - Route: - Off service to	assisted john with diagnosing starting fault in bus 60. could not replicate fault. followed circuit throughout vehicle. will wire up test equipment and subject bus to testing tomorrow. carry over.	496214
60 05/03/2016	589743 Breakdown - Won't start at Brighton terminus.	Attend breakdown at Brighton try starting at front and rear but no good could hear starter motor click brigde starter and engine starts. Return to depot.	496099
60 04/27/2016	588743 Breakdown - Won't start Brighton terminus.	Connect jumper try start from front but couldn't. Try starter but not starting. Reconnect jumper and start from the front return to depot.	495672
60 04/26/2016	588393 Breakdown#:32519 - Ops Entered - Breakdown - Breakdown Road	Aarranged Satya from Morrabbin to attend brakedown.	495557
60 04/26/2016	588393 Breakdown#:32519 - Ops Entered - Breakdown - Breakdown Road	Bridged starter motor and started the bus.	495557
60 04/18/2016	587041 Fit new air vent for O/Side rear near engine panal		495109
60 04/13/2016	585243 Consumables		494961
60 04/13/2016	585243 AIR INTAKE GRILLE	Creditor #:GB-VOL001 VOLGREN AUSTRALIA P/L P/O #:G165972 Receiving #:171586 Date :2016-04-13	494961
60 04/12/2016	585243 Elec and Light - Check for bus not starting	extensive testing cannot replicate the fault. organised to install some vents in engine hatch door to increase airflow. p.t.i'd fuelled and parked bus. ok.	494632
60 04/12/2016	585243 STOP TAIL LIGHT RED		494632
60 04/12/2016	585243 Mechanic entered - Elec and Light Exterior Lights bottom rea	changed wire over in bottom rear parklights. replaced n/s park/brake light assembly.	494632
60 04/11/2016	585243 Elec and Light - Check for bus not starting	found a/c to be powered by battery power rather than ignition this could effect battery power to cause starting fault. checked a/c wiring to ascertain fault with ignition circuit. no power still. roadtested bus with a/c disconnected to see if fault presents. cannot replicate fault. carry over.	494632
60 04/08/2016	585243 Elec and Light - Check for bus not starting	R/tested to get bus eng temp high attempting to replicate starter fault. Tested batteries starter gets signal but bus doesn't start looks to be voltage drop causing batteries to discharge & prevent starter operation fuelled bus	494549
60 04/08/2016	585551 Body - Straighten body panel	Straightened at radiator	494549
60 04/07/2016	585243 Elec and Light - Check for bus not starting	R/tested found starter clicking but not starting seems to besolenoid sticking c/o	494549
60 03/24/2016	583038 Consumables		494466
60 03/24/2016	583038 Elec and Light Two Way Radio: not working	checked 2 way called operations and it works.	494391
60 03/24/2016	583038 Elec and Light Two Way Radio: not working	assisted	494391
60 03/22/2016	582662 Ops Entered - Breakdown - Breakdown Road Defect Affects Ser	Starter motor fault b/down was cancelled	494232
60 03/21/2016	582139 Consumables		494232
60 03/21/2016	582139 GLOBE STOP AND TAIL 24V 21/5W (17925)		493981
60 03/19/2016	582139 Drv entered - Elec and Light Exterior Lights		493981
60 03/17/2016	581818 Consumables	Remove and replace globe rear n/s brake light.	493981
60 03/17/2016	581818 Elec and Light Flat Batteries	jump started.	493864
60 03/10/2016	580818 start motor not working	Already new statermotor fitted to the bus	493364
60 03/09/2016	580538 Consumables		493364
60 03/09/2016	580538 Ops Entered - Fault - Elec and Light Electric Mirrors Faulty	adjusted and tightened o/s mirror	493209
60 03/09/2016	580538 CCTV (None) youths have pulled the rear camera from the mo	removed loose camera and mounted bracketre secured camera checked and ok.	493209
60 03/08/2016	580712 Consumables		493209
60 03/08/2016	580712 Elec and Light - Bus wont start	Jump started	492310
60 02/23/2016	577634 Consumables		492310
60 02/23/2016	577634 STARTER MOTOR SCANIA K93+L94	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G162852 Receiving #:168460 Date :2016-02-23 60 wty	492310
60 02/23/2016	577634 Elec and Light start motor fault	removed battery terminals.removed starter motor and replaced with new one.sent old one back for warranty.	492310
60 02/23/2016	577634 Elec and Light start motor fault		492022
60 02/17/2016	576541 Consumables		491912
60 02/17/2016	576541 Mechanic entered - Elec and Light Flat Batteries	jump start.	491836
60 02/15/2016	576109 Consumables		491836
60 02/15/2016	576109 Consumables		491836
60 02/15/2016	576109 Consumables		491675
60 02/15/2016	576109 Consumables		491675
60 02/12/2016	575684 Consumables		491608
60 02/12/2016	575684 RADIO AM/FM 12-24VOLT (AV8141)	had to remove radio.re wired harnes for new radio.Could not secure radio so had to pull out and cut dash and make brakets for radio to mount properly.Found saloon speakers on n/s all working so had to disconnect them so drivers one was onlyone t work..Re secured antenna as was loose.	491608
60 02/12/2016	575684 Drv entered - Elec and Light AM-FM Radio	SOUTHPORT - S/PORT SCC2000 - 10 X 100 - N/A - N/A	491496
60 02/11/2016	575383 The Campaign requires all Bus destinations systems to be in	re-tensioned nuts on wheels 3; 4; 5 and 6 with shalen.	491126
60 02/06/2016	574471		491126
60 02/05/2016	574365 PUMP WIPER-WASHER 24 VOLT 80826		491077
60 02/04/2016	574148 Brakes - NS mid axle brake booster leak	Check remove brake booster aligned new brake booster position of fittings undo brake booster clamp to alligned. refit fittings fitted new brake booster found brake wear sensor worn. remove and replace sensor. refit wheels and torque all wheel nuts. roadtested check all ok air gauge all ok. brakes works ok.	491077
60 02/04/2016	574148 WEAR SENSOR SCANIA DISC BRAKE 40G8401		491077
60 02/04/2016	574148 BRAKE BOOSTER L94UAB 35CLE0100		490942
60 02/03/2016	573959	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	490942
60 02/03/2016	573959		490942
60 02/03/2016	573959	VEHICLE SAFETY INSPECTION	490942
60 02/03/2016	573959	REPLACED	491077
60 02/03/2016	574365 Wipers and Washers - REPLACE WASHER PUMP		490481
60 01/25/2016	572171 Consumables	jump started.	490231
60 01/25/2016	572171 Mechanic entered - Elec and Light Flat Batteries		490027
60 01/19/2016	570943 DECAL PTV METRO MYKI DECAL LARGE 450x330mm		489944
60 01/19/2016	570943 Campaign 23_15 A3 Poster Change		489788
60 01/05/2016	568330 Consumables	Jump started	489788
60 01/05/2016	568330 Elec and Light - Bus wont start		489621
60 01/04/2016	564156 Consumables	roadtested and checked a/c working correctly. p.t.i'd bus fuelled and parked.	489621
60 01/04/2016	564156 Ops Entered - Fault - Elec and Light Warning Light On Dash -		489621
60 01/04/2016	564156 FESTOON GLOBE 24V/3W		489621
60 01/04/2016	564156 Mechanic entered - Elec and Light Interior Lights 3 emergenc	replaced. working ok.	489621
60 12/30/2015	564156 Consumables		489621
60 12/30/2015	564156 Ops Entered - Fault - Elec and Light Warning Light On Dash -	roadtested bus. fault not reappearing. will roadtest in the morning once temperature drops. secured all panelling inside bus. need to close turntable. carry over.	489621
60 12/29/2015	564156 Ops Entered - Fault - Elec and Light Warning Light On Dash -	continued inspecting wiring in turntable. main harness ok. checked secondary harnesses. all look ok. secured wiring and drove around yard to park. need to roadtest tomorrow to determine whether fault is persisting.	489621
60 12/24/2015	564156 Ops Entered - Fault - Elec and Light Warning Light On Dash -	continued tracing wiring. removed large panel behind turntable for access.	489621
60 12/21/2015	564156 Ops Entered - Fault - Elec and Light Warning Light On Dash -	checking wiring in turntable. carry over.	489621
60 12/21/2015	566033 PERFORM CAMPAIGN 22/15 POSITIONING OF 2016 PTV FARES DECALS	Applied supplied decal	489621
60 12/15/2015	564156 Ops Entered - Fault - Elec and Light Warning Light On Dash -	re pressurised turntable in appropriate temperature. roadtested. fault still occuring will need to look into turntable wiring.	489621
60 12/14/2015	564156 Ops Entered - Fault - Elec and Light Warning Light On Dash -	pressurised turntable. roadtested fault appearing. will need to look into possible wiring fault carry over.	489621

60 12/09/2015	564156 Ops Entered - Fault - Elec and Light Warning Light On Dash	Jack knife light coming on removed t/table cover now looking for hydraulic pump to pressurise system c/o	489621
60 12/04/2015	563240 Consumables		489491
60 12/04/2015	563240 Mechanic entered - Elec and Light Other	jump started - battery flat.	489491
60 12/03/2015	562891 Consumables		489491
60 12/03/2015	562891 Mechanic entered - Elec and Light Other	jump started - battery flat.	489256
60 11/30/2015	561879 Consumables		489172
60 11/30/2015	561879 Elec and Light Interior Lights / HAZARD R/S REAR NOT WORKI	hazards and both L/H and R/H indicators all working o.k. saloon and all step lights also working.	488983
60 11/27/2015	559147 Supply and apply accident deca	Creditor #:GB-LAB010 LABEL CONCEPTS P/O #:G158287 Receiving #:164272 Date :2015-11-30	489093
60 11/26/2015	561519 DECAL MAKE YOUR MARK		488729
60 11/26/2015	561519 Camapign 20/15 Audit & Update of Safety Decals.Requires a		488729
60 11/23/2015	559079 Fluid Leaks leaking coolant from turntable area.	secured turntable wiring with rubber wear covers. secured turntable constatina. cleaned bus and roadtested ok.	488531
60 11/23/2015	559147 RADIATOR PUNCH PANEL	Creditor #:GB-VOL001 VOLGREN AUSTRALIA P/L P/O #:G158198 Receiving #:164032 Date :2015-11-23	488677
60 11/23/2015	559147 AMBER REFLECTOR		488531
60 11/20/2015	560137 Remove Old Poster and Fit new All Night Public Transport Po	completed	488531
60 11/20/2015	559147 PAINT SUPPLIES		488531
60 11/20/2015	559147 BODY SHOP SUPPLIES		488531
60 11/19/2015	559147 GLOBE FESTOON 24V 5W		488531
60 11/19/2015	559147 Decal Emergency Exit P/B under Panel		488531
60 11/19/2015	559147 Accident damage - N/S/M to R - Acc # DAN 42084. *THIRD PARTY	prep work painted white/orange reassemble	488531
60 11/19/2015	559147 SCREW TORX 8 X 15MM SIDE PANEL		488531
60 11/19/2015	559147 GAS STRUT 350NM X 565MM		488531
60 11/19/2015	559147 Accident damage - N/S/M to R - Acc # DAN 42084. *THIRD PARTY	Reassembled	488531
60 11/18/2015	559147 3MM X 1200MM X 2400MM FLAT ALUMINIUM		488531
60 11/18/2015	559147 Accident damage - N/S/M to R - Acc # DAN 42084. *THIRD PARTY	Assisted repairs	488531
60 11/18/2015	559147 Accident damage - N/S/M to R - Acc # DAN 42084. *THIRD PARTY	Continued repairs	488531
60 11/18/2015	559147 Accident damage - N/S/M to R - Acc # DAN 42084. *THIRD PARTY	dismantled ns lower panel and repaired sanded applied primer sanded and fitted to the bus assisted with wheel arch panels and sanded all panels and rear bumper corner masked up the bus to be painted c/o	488531
60 11/18/2015	559147 Accident damage - N/S/M to R - Acc # DAN 42084. *THIRD PARTY	finished off accident damage ready for painting	488531
60 11/18/2015	559147 WHEEL ARCH BRUSH PLASTIC		488531
60 11/18/2015	559147 LAMP INDICATOR [ORANGE]		488531
60 11/18/2015	559147 LENS TO SUIT 2029 (RED+AMBER)		488531
60 11/18/2015	559147 GLOBE FESTOON 24V 5W		488531
60 11/17/2015	559079 Fluid Leaks leaking coolant from turntable area.	ran new coolant hoses. secured with p-clamps. secured wiring. will need to test turntable under turning conditions before closing shroud. carry over.	488531
60 11/17/2015	559079 25 X 9MM X 2M AEROFLEX SHEATH	Creditor #:GB-VOL001 VOLGREN AUSTRALIA P/L P/O #:G158197 Receiving #:163884 Date :2015-11-18	488531
60 11/17/2015	559147 Accident damage - N/S/M to R - Acc # DAN 4	Continued repairs	488531
60 11/16/2015	559079 Fluid Leaks leaking coolant from turntable area.	removed coolant hoses ordered new protective sheathing for hoses. awaiting parts. carry over.	488531
60 11/16/2015	559147 Accident damage - N/S/M to R - Acc # DAN 4	Started repairs	488531
60 11/13/2015	559079 Fluid Leaks leaking coolant from turntable area.		488531
60 11/13/2015	558712 Consumables		488531
60 11/13/2015	558712 INTERIOR LIGHT DIFFUSER PER METRE		488531
60 11/13/2015	558712 Drv entered - Elec and Light Exterior Lights	replaced interior light and light defuser.	488531
60 11/06/2015	557415	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	488185
60 11/06/2015	557415	VEHICLE SAFETY INSPECTION	488185
60 10/28/2015	555925 Consumables		487690
60 10/28/2015	555925 Ops Entered - Fault - Elec and Light Exterior Lights - Rout	checked ok. parked bus.	487575
60 10/27/2015	556076 Consumables		487575
60 10/27/2015	556076 Complete task as instructed in Fleet Campaign 09/15	Checked OK	487575
60 10/26/2015	554605 Mechanic entered - Body Other	fixed 3rd passanger door middel rubber.	486929
60 10/26/2015	554605 Mechanic entered - Body Other	fixed 3rd passanger door middel rubber.	486929
60 10/26/2015	554605 Body - rear pax door rubber outer		486929
60 10/21/2015	552693 Consumables		487053
60 10/21/2015	552693 Elec and Light - Bus not starting	Fixed starting fault r/tested OK	486929
60 10/19/2015	552693 Elec and Light - Bus not starting	Continued tracing fault pulled down t/table & began checking wiring in there r/tested fault persists c/o	486929
60 10/15/2015	552693 Mechanic entered - Engine Other	pressure clean radiator.	486929
60 10/15/2015	552693 Elec and Light - Bus not starting	ordered new switch. traced power supply to starter interlock relay. parked bus near workshop carry over.	486929
60 10/15/2015	552693 Mechanic entered - Elec and Light Other	jump started - battery flat.	486929
60 10/15/2015	552693 SWITCH TOGGLE ON/OFF/MOM ON	Creditor #:GB-BUR001 BURSON AUTO PARTS P/O #:G156986 Receiving #:162374 Date :2015-10-15	486929
60 10/14/2015	552693 Elec and Light - Bus not starting	accessed diagrams and followed circuit. currently continuing to isolate.	486929
60 10/09/2015	552693 Elec and Light - Bus not starting	Currently starting to progress i need access to Scania wiring diagrams online c/o	486862
60 10/05/2015	551102 Ops Entered - Fault - Warning Lights Doors - Route: - Arri	secured door properly. working ok.	486365
60 10/01/2015	550783 Consumables		486365
60 10/01/2015	550783 Elec and Light Wont start	Jump started for Emergency rail	486365
60 09/28/2015	549580 Replace A3 poster with Victorian Seniors Festival Poster	Replaced by refuellers	486365
60 09/28/2015	549539 Campaign 11/15. Fit 2 x Supplied Decals to Internal Saloo	Fitted	486365
60 09/25/2015	547545 STARTER LOCK	Creditor #:GB-EAS002 EASTCOAST TRUCK & BUS SERVICE P/O #:G155994 Receiving #:161596 Date :2015-09-25	486365
60 09/21/2015	547545 Consumables		486365
60 09/21/2015	547545 STARTER MOTOR SCANIA K93+L94	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G156055 Receiving #:161356 Date :2015-09-21	486365
60 09/21/2015	547545 Mechanic entered - Air System Air_Leak Interior	Replaced new ignition barrell starter failed and assisted to replace	486365
60 09/21/2015	547545 Mechanic entered - Air System Air_Leak Interior	removed old ignition barrel placed new one put stuff back together. road tested ok.Checked when got back andstarter failed its self so removed from the bus went down to multispares and got the new starter put in tested andok.	486365
60 09/18/2015	547545 Mechanic entered - Air System Air_Leak Interior	checked and tested bus check wiring suspected fault barrel ordered.	486365
60 09/17/2015	547545 Mechanic entered - Air System Air_Leak Interior	Found bus would not start from the front check rear solinoid and no poer from switch wire checked the starter switch wire and no power toyed with fuses and starter relly now working further investigate tomorro	486365
60 09/17/2015	547545 Mechanic entered - Air System Air_Leak Interior	Found bus would not start from the front check rear solinoid and no poer from switch wire checked the starter switch wire and no power toyed with fuses and starter relly now working further investigate tomorro	486365
60 09/17/2015	547545 Mechanic entered - Air System Air_Leak Interior	Changed brake block valve assy	486365
60 09/15/2015	547122 Consumables		486365
60 09/15/2015	547122 Elec and Light - Bus wont start	wont start from front fixed solonide wire conector	486365
60 09/15/2015	547545 EMERGENCY RELEASE VALVE	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G155844 Receiving #:161241 Date :2015-09-17	486365
60 09/10/2015	546548 Consumables		486179
60 09/10/2015	545091 Consumables		486179
60 09/10/2015	546548 Elec and Light - Bus wont start	Checked bus rear switch not in start front position started OK	486179
60 09/10/2015	545091 5 PIN CHANGE-OVER RELAY WITH DIODE		486102
60 09/09/2015	545091 Mechanic entered - Elec and Light Other	bus not starting. replaced starter interlock relay working ok.	485985
60 09/07/2015	545551 Consumables		485985
60 09/07/2015	545551 Elec and Light - Bus wont start	Jump started	485901
60 09/07/2015	545605 VALVE CLIPPARD DOOR OPEN/CLOSE (11916-2) BUTTON		485901
60 09/07/2015	545605 Drv entered - Air System Air_Leak Front	checked and foundair leak from door switch replaced switch.	485721
60 09/03/2015	545090 as per Campaign 08/15Fit Hi Vis Vest DecalFit Coat Hook i		485721
60 09/03/2015	545091 as per Campaign 08/15Fit Hi Vis Vest DecalFit Coat Hook i		485721
60 09/03/2015	545091 Campaign 08/15	Fitted decal and hook	483962
60 08/12/2015	540532	did the wheel tension	484088
60 08/12/2015	540667 Consumables		483962
60 08/12/2015	540667 Mechanic entered - Elec and Light Interior Lights change blu	changed 5 blue fluro lights to white lights. working ok.	483962
60 08/11/2015	540287 CLAMP SUIT TYRE VALE EXTENSION T18 & T19		483962
60 08/11/2015	540287 EXTENSION FLEXIBLE TYRE VALVE 180mm LONG		483962
60 08/11/2015	540287 TYRE RECAP 275/70R22.5		483962
60 08/10/2015	540284		483838
60 08/10/2015	540284	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	483838

60 08/10/2015	540284	VEHICLE SAFETY INSPECTION	483838
60 08/10/2015	540287 Wheels and Tyres Worn pos 5 & 6 tyres		483838
60 08/10/2015	540287 Wheels and Tyres Worn pos 5 & 6 tyres	R/R pos 5& 6 tyres and tensioned w/nuts	483838
60 07/29/2015	537966 Complete Campaign 6/15 A3 Marketing Poster Change	Replaced	482843
60 07/24/2015	536983 CALIPER PLATE REPAIR KIT SC K		482497
60 07/24/2015	536983 Brakes Warning Light On (lining worn)		482497
60 07/22/2015	536983 Body Drivers Seat Controls Stuck on 70kgs and cannot be a	Checked all brakes and changed mid axle wear sensor assy and caliper wire plate r/tested bus OK	482497
60 07/14/2015	533062 Consumables	operation checked. o.k. weight dial loose on shaft and not representing adjustment.	481976
60 07/14/2015	533062 INTERIOR LIGHT DIFFUSER		481870
60 07/14/2015	533062 Saloon Light Covers have fallen off		481870
60 07/14/2015	533062 REAR VISION CAMERA C/W TWO CAM	replaced broken section of light diffuser. (os mid).	481870
60 07/09/2015	534895 Consumables	Creditor #:GB-LON001 LONSDALE ST AUTO ELECTRICS P/O #:G153391 Receiving #:158811 Date :2015-07-20 BUS 60	482267
60 07/09/2015	534895 Consumables		481820
60 07/09/2015	534895 Consumables		481820
60 07/09/2015	534895 Consumables		481820
60 07/09/2015	534895		481820
60 07/09/2015	534895	Tension ALL Wheel Nuts to OEM Specs	481820
60 07/09/2015	534895	D SERVICE AS PER CHECK LIST	481820
60 07/09/2015	534895 FILTER FUEL SCANIA SR4(H17WK04)		481820
60 07/09/2015	534895 OIL AUTO TRANSMISSION TEXAMATIC OR DEXRON (LU2)		481820
60 07/09/2015	534895 OIL ENGINE MINERAL 15W40 (LU18)		481820
60 07/09/2015	534895 FILTER AIR OUTER SCANIA SR3 SR4 (AF25066)(0395773)		481820
60 07/09/2015	534895 FILTER OIL SCANIA SR4 EARLY K320 (LF3730)(2059778)(H200W20)		481820
60 07/09/2015	534895 O-RING KIT OIL SPINNER FILTER SCANIA		481820
60 07/09/2015	534895 FILTER TRANSMISSION ZF (4139-298-038)(4139 298 038 01)		481820
60 07/09/2015	534895 Consumables		481820
60 07/09/2015	534895 Consumables		481820
60 07/09/2015	534895 Consumables		481820
60 07/09/2015	534895	A SERVICE AS PER CHECK LIST	481820
60 07/09/2015	534895	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	481820
60 07/07/2015	533062 CCTV (None) rear door camera not working	Repaired by Lonsdale	481820
60 06/26/2015	533062 CCTV (None) rear door camera not working	found camera display unit faulty checked and compared voltages seem ok.	481820
60 06/25/2015	532741 DECAL MAX SAFE CARRY WHITE ON CLEAR		481702
60 06/25/2015	532741 DECAL VIDEO AND AUDIO SURVEILLANCE		481702
60 06/25/2015	532741 Audit Route buses for correct Decals and positions. Replace		481702
60 06/25/2015	532741 25mm BLACK NO 0		481702
60 06/25/2015	532741 25mm BLACK NO 6		481702
60 06/25/2015	532741 NO 6 WHITE 25MM		481702
60 06/25/2015	532741 NO 0 WHITE 25MM		481702
60 06/25/2015	532741 NO 1 WHITE 25MM		481702
60 06/25/2015	532741 EMERGENCY PROCEDURE DECAL		481702
60 06/25/2015	532858 Consumables		481820
60 06/25/2015	532858 Consumables		481820
60 06/25/2015	532858 Consumables		481820
60 06/25/2015	532858 Consumables		481820
60 06/25/2015	532858		481702
60 06/25/2015	532858	Assisted Phil	481702
60 06/25/2015	532858	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	481702
60 06/25/2015	532858	A SERVICE AS PER CHECK LIST	481702
60 06/22/2015	531416 DIRECT PURCHASE - BUS INSPECTI	Creditor #:GB-ROA001 Road Safety Inspections P/O #:G152636 Receiving #:157760 Date :2015-06-29	481820
60 06/19/2015	532116 CCTV - Replace rear door camera	Replaced camera monitor with one from bus 136	481327
60 06/17/2015	531416	ANNUAL SAFETY INSPECTION - RWC 841632 - PASSED 17/06/15	481095
60 06/17/2015	531525 Consumables		481204
60 06/17/2015	531525 Mechanic entered - Elec and Light Other	jump started - battery flat.	481095
60 06/17/2015	531545	FIRE SAFETY INSPECTION AS PER CHECK LIST completed fire safety inspection ok.	481095
60 06/11/2015	530587	re-tensioned nuts on wheels 3; 4; 5 and 6.	480638
60 06/10/2015	530330 Brakes check brake holding	checked brake systemfit new mid axle l/h brake chamber.	480638
60 06/10/2015	530330 BRAKE BOOSTER L94UAB 35CLE0100		480638
60 06/09/2015	530342 Breakdown - Brakes overheating in Brighton	Attended by M.T. found NS rear brakes overheating wind off brake booster and follow bus up to Cheltenham Rd	480638
60 06/09/2015	530256 Attend breakdown Male st Brighton	Attend breakdown found n/s/r brakes overheating wind off brake chamber and follow bus up to Cheltenham rd.	480638
60 06/06/2015	529909	done with kuma	480638
60 06/06/2015	529909	done with kuma	480638
60 06/06/2015	529904 Consumables		480708
60 06/06/2015	529904 Ops Entered - Fault - Wheels and Tyres Flat or Leaking - Ro		480638
60 06/03/2015	529231 Consumables	checked can not fine anything wrong	480527
60 06/03/2015	529231 TYRE RECAP 275/70R22.5		480452
60 06/03/2015	529231 A/C Heating - A/C mount cracked	Fitted idler pulley and bracket and belttest drivesteam cleaned motor	480452
60 06/03/2015	529447 Audit Route buses for correct Decals and positions. Replace	Done	480452
60 06/03/2015	529231 Body - Tighten panel screws	Complete	480452
60 06/02/2015	529129	re-tensioned nuts on wheels 3; 4; 5; 6; 7; 8; 9 and 10.	480452
60 06/02/2015	529128	re-tensioned nuts on wheels 3; 4; 5; 6; 7; 8; 9 and 10.	480452
60 06/02/2015	529127	re-tensioned nuts on wheels 3; 4; 5; 6; 7; 8; 9 and 10.	480452
60 06/02/2015	529231 Mechanic entered - Wheels and Tyres Damaged	Replace n/s/r tyresdrive axle	480452
60 06/02/2015	529231 Wheels and Tyres - NSR hub seal leaking	Remove wheelscleaned disc and hub areaand replace wheel and re-torqed	480452
60 06/02/2015	529231 A/C Heating - A/C mount cracked	Remove beltsidler pulley and a/c compressors and a/c mount. Fit repaired mount and a/c compresor C/o	480452
60 06/02/2015	529231 Body - Tighten panel screws	Complete	480452
60 06/01/2015	528687 ROCKER COVER GASKET L94UAB	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G152118 Receiving #:156482 Date :2015-06-01	480452
60 06/01/2015	528687 ROCKER COVER GASKET L94UAB	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G152118 Receiving #:156473 Date :2015-06-01	480452
60 06/01/2015	528687	Replace air dryer canister	480358
60 06/01/2015	528687	Replace hydraulic fan filter and top up oil	480358
60 06/01/2015	528687	Replace power steering filter	480358
60 06/01/2015	528687	Adjust tappets	480358
60 06/01/2015	528687	Replace fuel filters	480358
60 06/01/2015	528687	Rekit quick release valve	480358
60 05/29/2015	528687 FILTER AIR DRYER SCANIA SR4 (20546795)(49G8709HALDEX)		480358
60 05/29/2015	528687 FILTER HYD COOLING FAN SCANIA SR3 (E90HD149)		480358
60 05/29/2015	528687 OIL MANUAL GEARBOX EP 80/90 (LU6)		480358
60 05/29/2015	528687 FILTER FUEL SCANIA SR4(H17WK04)		480358
60 05/29/2015	528687 FILTER FUEL SCANIA L94UAB (H7090WK30)		480358
60 05/29/2015	528687 FILTER P/STEER SCANIA VOLVO M/BENZ 0153468-1585618-0-153468		480358
60 05/29/2015	528687	Remove intercooler wash intercooler and raditor	480358
60 05/29/2015	528687	Clean a/c filters	480358
60 05/29/2015	528687	Replace final drive oil	480358
60 05/29/2015	528687	Inspect bus as per inspection sheet	480358
60 05/29/2015	528861 Wipers and Washers - Check wipers	Repaired washer hose	480414
60 05/29/2015	528861 TYRE RECAP 275/70R22.5		480414
60 05/29/2015	528861 Wheels and Tyres - Replace tyres 34	Replaced	480414

60 05/29/2015	528861 Engine - Steamclean engine	Cleaned	480414
60 05/29/2015	528861 WEAR SENSOR SCANIA DISC BRAKE 40G8401		480414
60 05/29/2015	528861 DISC PAD SET SCANIA MB0500		480414
60 05/29/2015	528861 Brakes - Replace os tag brake pad sensor	Replaced	480414
60 05/29/2015	528861 Brakes - Replace brake pads on tag axle	Replaced	480414
60 05/25/2015	527776 INTERFACE CONTROL CIRCUIT SUIT WATER VALVE		480414
60 05/25/2015	527776 5 PIN CHANGE-OVER RELAY WITH DIODE		480414
60 05/25/2015	527776 AIR CON REFRIDGERANT		480414
60 05/25/2015	527776 HIGH PRESSURE SWITCH		480414
60 05/25/2015	527776 tested oil will replace next service	Replace compressor oil	479966
60 05/25/2015	527776	B Service	479966
60 05/25/2015	527776 Tested drier will replace next service	Replace filter drier	479966
60 05/25/2015	527776	Clean R/A & F/A filters; Inspect and report on condition; Replace filter media	479966
60 05/25/2015	527776	FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)	479966
60 05/25/2015	527776	UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensor pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation	479966
60 05/25/2015	527776	CONDENSOR AREA: Clean condensor coils; check boltsclamps for tension	479966
60 05/25/2015	527776	INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condensor fan grills	479966
60 05/25/2015	527776	EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check boltsclamps & fittings; clean condensate drains; clean drip tray	479966
60 05/25/2015	527776	REFRIGERATION FILTER DRYER: Replace filter dryer; check pump operation; Locate and repair refrigerant leak right bank off rear unit	479966
60 05/25/2015	527776	COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose	479966
60 05/25/2015	527776	DRIVE PULLEY'S: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear	479966
60 05/25/2015	527776	DRIVE PULLEY'S: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;	479966
60 05/25/2015	527776	COMPRESSOR DRIVE BELTS: Inspect belt wear; Retension belts;	479966
60 05/22/2015	527386	re-tensioned nuts on wheels 7 and 8.	479741
60 05/21/2015	527297 Suspension Drive axle suspension wont go up.	Replaced suspension solenoid with Alan	479741
60 05/21/2015	527297 SOLENOID VALVE (REAR)		479741
60 05/21/2015	527297 Suspension Drive axle suspension wont go up.	fit new rear suspension control valve.check suspension computer system	479741
60 05/21/2015	527297 Engine Steam clean and check for engine oil leaks	steam washed engine and road test	479741
60 05/21/2015	527297 Engine Steam clean and check for engine oil leaks		479741
60 05/21/2015	526366 Fluid Leaks N/S/R drive axle hub seal leaking.	refitted hub and brakes.	479741
60 05/21/2015	526366 Fluid Leaks N/S/R drive axle hub seal leaking.	Refitted hub & brakes	479741
60 05/20/2015	526366 LOCK PLATE	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G151640 Receiving #:155770 Date :2015-05-20	479741
60 05/19/2015	526672 Consumables		479741
60 05/19/2015	526672 SINGLE CONTACT GLOBE 24V 5W 17181		479741
60 05/19/2015	526672 MUDFLAP 605MMX330MM	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G151563 Receiving #:155634 Date :2015-05-19	479741
60 05/19/2015	526672 Body Replace o/s middle axle mudflap	drilled new holes through mudflap then fitted mudflap onto bus body. all complete	479741
60 05/18/2015	526672 Elec and Light - Front park light out	parklight replaced	479741
60 05/18/2015	526672 Elec and Light - Front park light out	fitted new globe.	479741
60 05/18/2015	526672 Body Replace o/s middle axle mudflap	removed from bus gave mesurments to lee waiting on parts	479741
60 05/18/2015	526672 Body Replace Drivers Seat cushion.	fitted new cushion and cover.	479741
60 05/18/2015	526672 Body Repair rear door rubber	checked door rubber could not fault	479741
60 05/18/2015	526672 Body Replace o/s middle axle mudflap	assisted elias	479741
60 05/18/2015	526672 Body Repair rear door rubber	assisted elias	479741
60 05/18/2015	526672 Body Replace Drivers Seat cushion.	assisted elias.	479741
60 05/15/2015	526366 Fluid Leaks N/S/R drive axle hub seal leaking.	Started pulling out hubs.C/F.	479741
60 05/15/2015	526366 OUTER HUB SEAL REAR SCANIA L94UAB+L113CRB		479741
60 05/15/2015	526366 SEAL REAR HUB OUTER SR 3 & 4 SCANIA 1765061		479741
60 05/15/2015	526366 SEAL INNER REAR AXLE SCANIA	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G151501 Receiving #:155509 Date :2015-05-15	479741
60 05/13/2015	525959	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS with Shalen.	479741
60 05/13/2015	525959	VEHICLE SAFETY INSPECTION	479741
60 05/08/2015	525098 Consumables		479459
60 05/08/2015	525098 Ops Entered - Fault - Elec and Light Next Stop Button - Rou	checked bell next stop warning lights and pax buttons all working could not fault.	479174
60 04/29/2015	523672 Consumables		478583
60 04/29/2015	523672 GLOBE FESTOON 24V5W (17136)		478455
60 04/29/2015	523672 LAMP (RED+AMBER)		478455
60 04/29/2015	523672 Elec and Light - RH side clearance light broken at rear	replaced smashed (osr) clearance light.	478455
60 04/27/2015	521933 Accident damage - Front bumper - Acc # DAN 41009. *THIRD PAR	Prepared and painted bumper white	478316
60 04/27/2015	521933 Bodyshop consumables and Spray Booth		478316
60 04/27/2015	521933 Paint materials		478316
60 04/27/2015	522337 HIGH PRESSURE SWITCH		478316
60 04/27/2015	522337 Connector 3 Pin Coachair		478316
60 04/27/2015	522337 Terminal Solid State Relay Coachair		478316
60 04/27/2015	522337 RELAY SOLID STATE		478316
60 04/27/2015	522337 AIR CON REFRIDGERANT		478316
60 04/24/2015	522971 Ops Entered - Fault - CCTV System Noisy - Route: - Arrive	check cctv unit all ok cant hear any noisy. bus serviceble.	477967
60 04/21/2015	521933 Accident damage - Front bumper - Acc # DAN 41009. *THIRD PAR	repaired front bar ready for painting	477967
60 04/21/2015	522250 DIRECT PURCHASE ACCIDENT	Creditor #:GB-A1W001 A-1 Windscreens P/O #:G150520 Receiving #:154142 Date :2015-04-22 Supply and fit N/S/M side glass	477967
60 04/21/2015	522250 Accident damage - N/S/M glass - Acc # DAN 41019. *INTERNAL*	Arranged work to be completed	477967
60 04/21/2015	522337	C Service	477967
60 04/21/2015	522337	UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensor pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation	477967
60 04/21/2015	522337	CONDENSOR AREA: Clean condensor coils; check boltsclamps for tension	477967
60 04/21/2015	522337	INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condensor fan grills	477967
60 04/21/2015	522337	EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check boltsclamps & fittings; clean condensate drains; clean drip tray	477967
60 04/21/2015	522337	REFRIGERATION FILTER DRYER: Replace filter dryer; check pump operation;	477967
60 04/21/2015	522337	COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose	477967
60 04/21/2015	522337	DRIVE PULLEY'S: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear	477967
60 04/21/2015	522337	DRIVE PULLEY'S: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;	477967
60 04/21/2015	522337	FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)	477967
60 04/21/2015	522337	Clean R/A & F/A filters; Inspect and report on condition; Replace filter media	477967
60 04/21/2015	522337	COMPRESSOR DRIVE BELTS: Inspect belt wear; Retension belts;	477967
60 04/20/2015	521933 Accident damage - Front bumper - Acc # DAN 41009. *THIRD PA		477881
60 04/10/2015	518832 Suspension (None) / Jackknife	put turntable back together. roadtested after each step and could not get the bus to fault. parked on fuel bay to go back on the road.	476879
60 04/09/2015	518832 Suspension (None) / Jackknife	secured turntable cabling and roadtested bus. fault was not presenting. close turntable floor and will need to secure wiring in a/c duct.	476879
60 04/07/2015	518832 Suspension (None) / Jackknife	carried on with finding fault.	476879
60 04/02/2015	518832 Suspension (None) / Jackknife	removed panelling from rear of turntable. removed main loom from turntable and working on checking.	476879
60 04/01/2015	518832 Suspension (None) / Jackknife	continued checking fault. pulled down concentina to check roof wiring. removed sheathing. carry over.	476879
60 04/01/2015	519359 Replace See Something Say Something Poster	n/a	476879
60 03/31/2015	518832 Suspension (None) / Jackknife	continued tracing fault. repressurised system and connected appropriate measuring gauge. looks ok. began tracing back from turntable angle sensors.	476879
60 03/30/2015	518832 Suspension (None) / Jackknife	jackknife fault. removed turntable flooring. checked sensor wiring and will need to get a gauge to check turntable pressure.	476879
60 03/30/2015	514438 Paint materials		476879
60 03/30/2015	514438 Body shop consumables and Spray Booth		476879
60 03/24/2015	514228 T'rntable - Turntable fault	secured cabling. pressurised hydraulic system in turntable. roadtested to check for faults.	476431
60 03/20/2015	514228 T'rntable - Turntable fault	checked continuity in turntable wiring ok. continued tracing turntable fault.	476431
60 03/19/2015	514228 T'rntable - Turntable fault	continued tracing jackknife fault.	476431
60 03/13/2015	516035 Consumables		476431

60 03/13/2015	516035 Update destination Files and Check display - Southport	flipdot starcard system	476431
60 03/13/2015	514438 Body & Acc	finished off rebranding	476431
60 03/13/2015	514438 LONG VEHICLE DECAL		476431
60 03/13/2015	514438 AMBER REFLECTOR		476431
60 03/11/2015	514438 PTV REBRAND - Method 2. {ARTIC VEHICLE}	Unmasked the bus	476431
60 03/11/2015	514438 PTV REBRAND - Method 2. {ARTIC VEHICLE}	cont masking and prep work painted PTV orange	476431
60 03/10/2015	514438 PTV REBRAND - Method 2. {ARTIC VEHICLE}	Prep work maskup painted o/s trailer and front white cont masking ready for PTV orange	476431
60 03/10/2015	514438 PTV REBRAND - Method 2. {ARTIC VEHICLE}	Masked up for orange paint work c/o	476431
60 03/06/2015	514438 EMERGENCY EXIT DECAL 600MM X 80MM		476431
60 03/06/2015	514438 EXIT ONLY DECAL		476431
60 03/06/2015	514438 PLEASE KEEP CLEAR DECAL		476431
60 03/06/2015	514438 wheelchair access ramp load rated 300 KG		476431
60 03/06/2015	514438 'GIVE WAY' DECAL 240MM X 225MM		476431
60 03/06/2015	514438 Decal VENTURA yellow on blue 480mm		476431
60 03/06/2015	514438 Ventura Rear Header Decal for Routebus		476431
60 03/06/2015	514438 PTV REBRAND - Method 2. {ARTIC VEHICLE}	Polished near side all lower panels marked lines on main rails masked up roof and the sides c/o	476431
60 03/06/2015	514438 PTV REBRAND - Method 2. {ARTIC VEHICLE}	disassemble rear handles brackets cont prep work left work (1 hour stayed an extra hour)	476431
60 03/06/2015	514438 DO NOT OVERTAKE DECAL		476431
60 03/06/2015	514438 PTV REBRAND - Method 2. {ARTIC VEHICLE}	Rebrand	476431
60 03/05/2015	514438 PTV REBRAND - Method 2. {ARTIC VEHICLE}	Removal of decals of ns/os all lower panels and polished os 10 lower panels c/o	476431
60 03/05/2015	514438 PTV REBRAND - Method 2. {ARTIC VEHICLE}	Assisted with rebranding	476431
60 03/04/2015	514228 T'rntable - Turntable fault	pulled down turntable to assess wiring loom. checked under floor. carry over.	476431
60 03/02/2015	514228 T'rntable - Turntable fault	Checked codes r/tested deleted codes & r/tested problem returns with no fault code c/o	476431
60 02/27/2015	513699 Ops Entered - Accident - Bus Hit Stationery Vehicle - Rout	No damage	476357
60 02/26/2015	513603 Consumables		476357
60 02/26/2015	513603 Ops Entered - Fault - Elec & Light W'rning Light - Route:	Recharged system r/tested NO faults with t/table	476357
60 02/26/2015	513603 Body & Acc - Dash panel loose	Replaced screws in park brake panel	476357
60 02/26/2015	513603 Brakes Check brakes not holding	Road tested and checked brakes operation - ok.	476357
60 02/23/2015	512854 Brakes Holding On	Road tested and checked - ok.Checked bus on the pit too.Could not fault	475934
60 02/13/2015	511787	VEHICLE SAFETY INSPECTION - completed on 13/2/15	475644
60 02/13/2015	511446 completed	Perform Safety Inspection as per checklist	475443
60 02/13/2015	502902 Consumables		475527
60 02/13/2015	502902 Ops Entered - Fault - Elec & Light W'rning Light - Route: 2	completed job. roadtested ok.	475443
60 02/12/2015	502902 Ops Entered - Fault - Elec & Light W'rning Light - Route: 2	completed putting turntable hydraulics back in bus. fitted floors. bus needs a clean and roadtest. c/o	475443
60 02/10/2015	502902 Ops Entered - Fault - Elec & Light W'rning Light - Route: 2	continued with turntable. tightening bolts to spec and aligning turntable.	475443
60 02/09/2015	502902 Ops Entered - Fault - Elec & Light W'rning Light - Route: 2	fit new shafts and bushes. continued with securing turntable unit back into bus. c/o	475443
60 02/05/2015	502902 Ops Entered - Fault - Elec & Light W'rning Light - Route: 2	lifted turntable out and cleaned up area. ready to fit parts.	475443
60 02/03/2015	502902 BUSH ARTIC CONTROL L94	Creditor #:GB-EAS002 EASTCOAST TRUCK & BUS SERVICE P/O #:G147944 Receiving #:150203 Date :2015-02-03	475443
60 02/03/2015	502902 Tube	Creditor #:GB-EAS002 EASTCOAST TRUCK & BUS SERVICE P/O #:G147944 Receiving #:150203 Date :2015-02-03	475443
60 02/02/2015	502902 Ops Entered - Fault - Elec & Light W'rning Light - Route: 2	Creditor #:GB-EAS002 EASTCOAST TRUCK & BUS SERVICE P/O #:G147944 Receiving #:150203 Date :2015-02-03	475443
60 01/30/2015	502902 Consumables	checked out new parts	475443
60 01/30/2015	502902 Ops Entered - Fault - Elec & Light W'rning Light - Route: 2	Cont with preparing t/table c/o	475443
60 12/31/2014	502902 Consumables		0
60 12/31/2014	502902 BOLT	Creditor #:GB-EAS002 EASTCOAST TRUCK & BUS SERVICE P/O #:G146542 Receiving #:149055 Date :2014-12-31	475443
60 12/31/2014	502902 PLATE	Creditor #:GB-EAS002 EASTCOAST TRUCK & BUS SERVICE P/O #:G146542 Receiving #:149055 Date :2014-12-31	475443
60 12/31/2014	502902 ACCUMULATOR	Creditor #:GB-EAS002 EASTCOAST TRUCK & BUS SERVICE P/O #:G146542 Receiving #:149055 Date :2014-12-31	475443
60 12/29/2014	502902 Ops Entered - Fault - Elec & Light W'rning Light - Route: 2	removed shalts from turntable	475443
60 12/19/2014	502902 Consumables		0
60 12/19/2014	502902 COMPLETE VEHICLE DETAILS AUDIT CHECK LIST	completed vehicle audit check list	475443
60 12/18/2014	502902 Ops Entered - Fault - Elec & Light W'rning Light - Route: 2	continued preparing parts of job.	475443
60 12/17/2014	502902 Ops Entered - Fault - Elec & Light W'rning Light - Route:	Began removing t/table to replace accumalators found shaft and bush needing replacement	475443
60 12/12/2014	501775 A3 Poster Change	Replaced	475297
60 12/10/2014	501278 Consumables		0
60 12/10/2014	501278 Ops Entered - Fault - Elec & Light W'rning Light - Route: 8	road tested checked turntable	475082
60 12/05/2014	500490 Ops Entered - Fault - Engine Lacking Power - Route: - Arr	Test drove and checked - ok.Cleaned air filter.	474968
60 12/02/2014	499804 Passenger Doors Require Adjusted / Back Door is loose at	secured middle door mount (01-12-14)	474812
60 12/02/2014	499578 Consumables		0
60 12/02/2014	499578 Ops Entered - Fault - Elec & Light W'rning Light - Route:	check fault code check pressure senders clear fault code road test bus ok.	474812
60 11/26/2014	498800 Consumables		0
60 11/26/2014	498800 Elec & Light check bus -has been parked in line 16	checked warning ligts - road tested no fault found - give to operation	474581
60 11/20/2014	498028 Consumables		0
60 11/20/2014	498028	R/tested OK	474581
60 11/20/2014	498028 Drv entered -	PTId	474581
60 11/20/2014	498028 Elec & Light - Check batteries	Checked batteries OK	474581
60 11/19/2014	497514 Consumables		0
60 11/19/2014	497514 Ops Entered - Fault - Elec & Light W'rning Light - Route:	Battery fault jump started and checked charge rate leaving overnight to check the rate of batteries in the morning	474485
60 11/19/2014	497514 Ops Entered - Fault - Elec & Light W'rning Light - Route:	checked fault codes found none road tested ok	474485
60 11/17/2014	496669 AIR CON REFRIDGERANT		484281
60 11/17/2014	496669 5 PIN CHANGE-OVER RELAY WITH DIODE		484281
60 11/17/2014	496669 24 VOLT RELAY PANEL		484281
60 11/17/2014	497171 Consumables		0
60 11/17/2014	497171 Elec & Light - Bus wont start	Jump started	474485
60 11/14/2014	496669 Drv entered - Air Cond		474281
60 11/14/2014	496735 Consumables		0
60 11/14/2014	496709 Consumables		0
60 11/14/2014	496735 Ops Entered - Fault - Body & Acc Interior - Route: - Arriv	PTI & parked bus	474281
60 11/14/2014	496709 Body & Acc (None) / Rear door camera is not operating	checked ok and road tested checking out jackknife light coming on un able to fault bus	474281
60 10/31/2014	493801 HEADER TANK FILLER CAP 1403954		473642
60 10/31/2014	493801 Mechanic entered - Eng Cool Radiator Cap	replaced broken radiator cap	473642
60 10/31/2014	493801 Comm Equip Controls - Switches off when doors close	could not fault	473642
60 10/31/2014	493801 Security CCTV - n/w	put back together panels help it matt	473642
60 10/30/2014	493801 Security CCTV - n/w	ran a new power wire through turntable to camera.	473642
60 10/30/2014	493418 Security CCTV - n/w	rebooked	473642
60 10/29/2014	493418 WIPER LINK RH 464MM	Creditor #:GB-VOL001 VOLGREN AUSTRALIA P/L P/O #:G145060 Receiving #:146878 Date :2014-10-29	473642
60 10/29/2014	493418 Wipers & Washers (None) right hand side not working	removed the rest of linkage. measured. went to volgren to compare and collect new part. fit to bus. filled washer bottle. tested ok.	473642
60 10/29/2014	493418 Wipers & Washers (None) right hand side not working	remove damage os wipper link needto wellded or change link	473642
60 10/29/2014	493801 Comm Equip Controls - Switches off when doors close	Began tracing where the contact point could be	473642
60 10/29/2014	493801 Security CCTV - n/w	Camera behind turntable u/s looks to be faulty wiring in t/table began disassembling t/table	473642
60 10/29/2014	493418 Consumables		0
60 10/29/2014	493418 Remove Legacy Poster and replace with See Something Say So	N/A	473642
60 10/23/2014	492578 Consumables		0
60 10/23/2014	492578 Check jack knife light coming on dash	pressurised turntable. roadtested working ok.	473127
60 10/16/2014	491390 Consumables		0
60 10/16/2014	491390 Body & Acc - Cracked windscreen	checked. no cracks found.	472635

60 10/13/2014	490216 TYRE NEW 275/70R22.5	Creditor #-GB-TYR002 TYRES4U P/O #:G144423 Receiving #:146271 Date :2014-10-13	472226
60 10/10/2014	490385	RE-TENSIONED NUTS ON WHEELS 1 AND 2.	472193
60 10/09/2014	490216 Mechanic entered - Whls & Tyres Puncture	changed tyre 1 (to rack) and 2 (flat). nuts tensioned with julian.	472110
60 10/09/2014	490216 Consumables		0
60 10/09/2014	490216 Complete AM/FM radio saloon speaker modification	modified	472110
60 10/08/2014	490104 Consumables		0
60 10/08/2014	490104 Mechanic entered - Elec & Light Battery Flat	Jumpstart	472035
60 10/07/2014	488583 Consumables		0
60 10/07/2014	488583 Mechanic entered - Elec & Light Battery Flat	Jumpstart	471997
60 10/07/2014	488583 Repair accident damage as per	Creditor #-GB-EAS002 EASTCOAST TRUCK & BUS SERVICE P/O #:G144257 Receiving #:146138 Date :2014-10-07	472035
60 10/03/2014	489106 Consumables		0
60 10/03/2014	488583 Ops Entered - Fault - Elec & Light W'rning Light - Route: 8	road tested. no warning lights appeared.	471791
60 10/03/2014	489106 GLOBE 24V 21W SINGLE CONTACT		471791
60 10/03/2014	489106 LENS CLEAR SUIT 2043		471791
60 10/03/2014	489106 LAMP INTERIOR AND REVERSING		471791
60 10/02/2014	489117 Consumables		0
60 10/02/2014	489117 Elec & Light - Bus wont start	Jump started	471791
60 10/01/2014	488666	Perform Safety Inspection as per checklist Safety Inspection Completed	471685
60 10/01/2014	488666	Perform Safety Inspection as per checklist Safety Inspection Completed	471685
60 10/01/2014	489106 Elec & Light - REPLACE GLOBES	Replaced	471791
60 10/01/2014	488583 Accident damage - Front - Acc # DAN 39777 - *INTERNAL* *To	Picked up vehicle from Knox.	471685
60 10/01/2014	488666 Consumables		0
60 10/01/2014	488666 Consumables		0
60 10/01/2014	488666 Consumables		0
60 10/01/2014	488666	Tension ALL Wheel Nuts to OEM Specs Done	471685
60 10/01/2014	488666		471685
60 09/09/2014	484249 DECAL AUTHORISED OFFICER	Replaced	471685
60 09/05/2014	484249 Remove old decal and fit new Authorised Officers Decal DO N		471685
60 09/03/2014	483571 GLOBE 24V 75/70W H4		471408
60 09/03/2014	483571 Mechanic entered - Elec & Light Headlights	Replace headlight globe	471408
60 08/25/2014	482091 Whls & Tyres - Check tyre pressure 3	Inflated with Sisil	470666
60 08/25/2014	482091 Whls & Tyres - Check tyre pressure 3	Inflated with Phil	470666
60 08/19/2014	480769 Remove old A3 poster & replace with Legacy or Penalty Fares	Replaced	470248
60 08/18/2014	480525 Elec & Light - Reverse light out	Checked OK	470082
60 08/08/2014	479002 Mechanic entered - Elec & Light Battery Flat	jump started.	469452
60 07/29/2014	476605 Body shop consumables and Spray Booth		468683
60 07/29/2014	476605 Paint materials		468683
60 07/28/2014	476605 Accident damage - Bus reversed into bus in yard.	repaired n/s/f bar corner painted painted wheels also painted wheels on a differant bus (moorabbin)	468422
60 07/25/2014	476605 Accident damage - Bus reversed into bus in yard.		468422
60 07/25/2014	476605 Accident damage - Bus reversed into bus in yard.	replaced damaged light	468422
60 07/25/2014	476605 INDICATOR LIGHT FRONT ARTIC		468422
60 07/21/2014	474883 ANNUAL INSPECTION	Creditor #-GB-ROA001 Road Safety Inspections P/O #:G141377 Receiving #:143383 Date :2014-07-23	468049
60 07/20/2014	474883 Annual Licence	- RWC 915037 - PASSED	467526
60 07/17/2014	475009	Perform Safety Inspection as per checklist	467675
60 07/17/2014	475009	A Service & Bus Safety Inspection	467675
60 07/17/2014	475009	Tension ALL Wheel Nuts to OEM Specs	467675
60 07/15/2014	474573 Service	Tensioned pos 6 tyre with Shalen.	467341
60 07/15/2014	474573 Service	Tensioned pos 6 tyre with Sisil	467341
60 07/14/2014	474196 Mechanic entered - Whls & Tyres Puncture	changed tyre 6. valve extension and clamp fitted. wheel nuts tensioned to specs. with greg.	467258
60 07/14/2014	474196 Fit Tyre Valve Extensions To All Inner Rear Axle Wheels	fitted	467258
60 07/14/2014	474196 Clamp Suit Tyre Valve		467258
60 07/14/2014	474196 TYRE VALVE EXTENSION 180mm LONG		467258
60 07/03/2014	471948	Adjust valve clearances	466623
60 07/03/2014	471948	Rekit quick release valve	466623
60 07/03/2014	471948	Remove intercooler wash intercooler and raditor	466623
60 07/03/2014	471948	steam cleaned bus adjust tappets road tested. ok.	466623
60 07/03/2014	471948 Service		466623
60 07/03/2014	472248 33MM LOOSE WHEEL NUT INDICATOR	fitted new sway bar bushes	466623
60 07/03/2014	472326 Suspension - Mid axle sway bar bushes worn	fit new sway bar bushes.	466623
60 07/03/2014	472326 Suspension - Mid axle sway bar bushes worn		466623
60 07/03/2014	472326 BUSH SWAYBAR D-SHAPE SCANIA L94 MID AXLE		466623
60 07/03/2014	472326 Engine - Engine oil leak from front of engine	reseal cooler mount at water pump.	466623
60 07/03/2014	472248 BRAKE BOOSTER MID AXLE L94UAB		466623
60 07/02/2014	471948	Replace air dryer canister	466623
60 07/02/2014	471948	Clean a/c filters	466623
60 07/02/2014	471948	Replace air dryer canister	466623
60 07/02/2014	471948	Replace final drive oil	466623
60 07/02/2014	471948	Replace power steering filter	466623
60 07/02/2014	471948	Replace hydralic fan filter and top up oil	466623
60 07/02/2014	471948	Inspect bus as per inspection sheet	466623
60 07/02/2014	471948	Replace fuel filters	466623
60 07/02/2014	471948	Replace final drive oil	466623
60 07/02/2014	471948	Replace power steering filter	466623
60 07/02/2014	471948	Replace hydralic fan filter and top up oil	466623
60 07/02/2014	471948	Inspect bus as per inspection sheet	466623
60 07/02/2014	471948	Replace fuel filters	466623
60 07/02/2014	471948 FILTER K124EB HYD COOLING FAN		466623
60 07/02/2014	471948 FILTER FUEL K124 / LU94A (1411894 / H17WK05)	Clean a/c filters	466623
60 07/02/2014	471948		466623
60 07/02/2014	471948 RPM BORATE EP LUBE 220 (LU3)		466623
60 07/02/2014	471948 FILTER AIR DRYER SCANIA K124EB (T350W)	Replaced	466623
60 07/02/2014	471948 FUEL FILTER ELEMENT SCANIA L94UAB/volvo (R90T / H7090WK10)	Fitted new	466623
60 07/02/2014	471948 POWER STEERING FILTER VOLVO	Fitted new	466623
60 07/02/2014	472248 Fit Wheel Nut Pointers to all wheel nuts on the front axle	Creditor #-GB-ATT001 ATTITUDE SIGNS P/O #:G138745 Receiving #:141339 Date :2014-05-30 Supply and apply decals as required	463682
60 07/02/2014	472248 Brakes - Replace LH mid axle brake chamber		463207
60 07/02/2014	472248 Brakes - Replace LH mid axle brake chamber	changed blown globe (osf) bottom.	463207
60 05/30/2014	462423 DIRECT PURCHASE ACCIDENT		462906
60 05/28/2014	462313 GLOBE 24V 21W SINGLE CONTACT		462906
60 05/28/2014	462313 Mechanic entered - Elec & Light Indicators	Perform Safety Inspection as per checklist	462599
60 05/23/2014	464712 GLOBE FESTOON 24V-3W (17104)	??? defect for a/c has been put in	462599
60 05/23/2014	464711 PUMP FUEL LIFT PRIMER	Replaced emergency exit light globe	462599
60 05/22/2014	464649	Secured ABS line	462599
60 05/22/2014	464527 Drv entered - Other		
60 05/22/2014	464712 Elec & Light Interior light u/s		
60 05/22/2014	464711 Elec & Light ABS line u/s		

60 05/22/2014	464649	TEXAMATIC 1888 (LU2)		462599
60 05/22/2014	464649	ENGINE OIL DELO 400LE 15W40 (LU18)		462599
60 05/22/2014	464649	FILTER TRANSMISSION ZF 4139-298-038E39HD119		462599
60 05/22/2014	464649	FILTER OIL K124 / L94UAB (H200W20)2059778		462599
60 05/22/2014	464649	FILTER FUEL K124 / LU94A (1411894 / H17WK05)		462599
60 05/22/2014	464649	FILTER AIR SCANIA USE AF25066		462599
60 05/22/2014	464649	O RING FILTER KIT K93		462599
60 05/22/2014	464649	Tensioned 700 nm	Tension ALL Wheel Nuts to OEM Specs	462599
60 05/22/2014	464649		D Service & Bus Safety Inspection	462599
60 05/22/2014	464649		Tension ALL Wheel Nuts to OEM Specs	462599
60 05/22/2014	464649		A Service & Bus Safety Inspection	462599
60 05/19/2014	462313	Drv entered - Air Cond Cooling Fault Light	22 celsius. Travelled to site to complete repairs as previously stated manufactured new service valve fitting and suction hose fitted same and pressure tested same replaced drier evacuated unit and recharged with refrigerant ran and tested unit operation refitted rear seats and returned into service	463207
60 05/19/2014	462313	90LTR BOOST PUMP COACH		462444
60 05/19/2014	462313	AIR CON REFRIDGERANT		462444
60 05/19/2014	462313	COMPRESSOR OIL AIR CON		462444
60 05/19/2014	462313	NITROGEN DRY D SIZE		462444
60 05/16/2014	462313	co-cm1240-j & fittings	Creditor #:GB-22C001 22 CELSIUS P/O #:G138746 Receiving #:141276 Date :2014-05-29	463682
60 05/16/2014	462313	labour repairs	Creditor #:GB-22C001 22 CELSIUS P/O #:G138746 Receiving #:141276 Date :2014-05-29	463682
60 05/16/2014	462313	Drv entered - Air Cond Cooling Fault Light	22 celsius. Travelled to site to fit new compressor removed faulty comp and stripped clutch assembly fitted clutch assembly to new comp replaced 2x TX valves (faulty TX caused comp failure) removed leaking suction hose assembly found suction hose fittings to be rusted up and damaged beyond repair chased up new fitt	462079
60 05/14/2014	462423	Bodyshop consumables and Spray Booth		462079
60 05/14/2014	462423	Paint materials		462079
60 05/13/2014	462313	AIR CONDITIONING part	Creditor #:GB-22C001 22 CELSIUS P/O #:G138714 Receiving #:140607 Date :2014-05-14 2 MTR DASH 16 HOSE	462155
60 05/13/2014	462313	FUSE BLADE 10AMP		462079
60 05/13/2014	462153	SINGLE CONTACT GLOBE 24V 5W 17181		462079
60 05/13/2014	462423	AMBER REFLECTOR		462079
60 05/13/2014	462423	2MM X 1200MM X 2400MM FLAT ALUMINIUM		462079
60 05/12/2014	462313	Drv entered - Air Cond Cooling Fault Light	Repaired crack in suction pipe right bank replaced boost pump to front unit locate and repair elec fault at alternator for unit excite	462079
60 05/12/2014	462313	TX VALVE	Creditor #:GB-COA001 COACHAIR PTY LTD P/O #:G138710 Receiving #:140520 Date :2014-05-13	462155
60 05/12/2014	462153	Mechanic entered - Elec & Light Park Lights	replace top o/s park light	462079
60 05/12/2014	462222	Remove Fair Evasion A3 Poster & Replace with MYKI AUTO TOP U	fitted poster	462079
60 05/12/2014	462423	UNREPORTED damage - N/S/F - *To be repaired at DANDENONG*	REMOVED DAMAGED ns 3 PANEL AND MANUFACTURED NEW PANEL PREPPED & PAINTED	462079
60 05/12/2014	462423	UNREPORTED damage - N/S/F - *To be repaired at DANDENONG*	Manufactured NS panel 3 painted etch primer primer & top coat c/o	462079
60 05/12/2014	462153		EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check boltsclamps & fittings; clean condensate drains; clean drip tray	462079
60 05/12/2014	462153		DRIVE PULLEY'S: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear	462079
60 05/12/2014	462153		DRIVE PULLEY'S: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;	462079
60 05/12/2014	462153		COMPRESSOR DRIVE BELTS: Inspect belt wear; Retension belts;	462079
60 05/12/2014	462153		FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)	462079
60 05/12/2014	462153		Clean R/A & F/A filters; Inspect and report on condition; Replace filter media	462079
60 05/12/2014	462153		REFRIGERATION FILTER DRYER: Replace filter dryer; check pump operation;	462079
60 05/12/2014	462153		COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose	462079
60 05/12/2014	462153	Rear left compressor not pumping suction hose has gone hard	UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensor pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation	462079
60 05/12/2014	462153		CONDENSOR AREA: Clean condensor coils; check boltsclamps for tension	462079
60 05/12/2014	462153		INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condensor fan grills	462079
60 05/05/2014	461031	N150 MAINTENANCE FREE		461555
60 05/05/2014	461031	N150 MAINTENANCE FREE		461555
60 05/05/2014	461031	Elec & Light Battery Flat check battery	replaced batteries	461555
60 04/30/2014	460212	Mechanic entered - Elec & Light Battery Flat	Jumpstart	461119
60 04/30/2014	460306	Elec & Light Battery Flat	Jump started and checked charge rates - ok.saloon lights left on.	461119
60 04/29/2014	460146	Jump start at Brighton town hall.	Travel to Brighton terminal and jump start bus return to depot.	461119
60 04/17/2014	458497	Mechanic entered - Eng Cool Coolant Low	added coolant.	460540
60 04/14/2014	457653	GLOBE S/CONTACT 24V-10W		460362
60 04/14/2014	457653	GLOBE FESTOON 24V5W (17136)		460362
60 04/14/2014	457653	GLOBE FESTOON 24V-3W (17104)		460362
60 04/14/2014	457653	VALVE BRAKE L94 (40G0103)	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G137758 Receiving #:139520 Date :2014-04-14	460362
60 04/14/2014	457653	BRAKE RELAY VALVE SCANIA L94 U	Creditor #:GB-EAS002 EASTCOAST TRUCK & BUS SERVICE P/O #:G137764 Receiving #:139557 Date :2014-04-15	460362
60 04/11/2014	455685	Investigation/Inspection - looses power	change potension meater short road test bus ok need long road test	460362
60 04/11/2014	457653	Engine - Oil leak around oil cooler	Found minor leaksteam cleaned to monitor.	460362
60 04/11/2014	457653	Elec & Light - Exit lights n/w	Replaced globe	460362
60 04/11/2014	457653	Elec & Light - NS clearance light u/s	Replaced globe	460362
60 04/11/2014	457653	Elec & Light - Bus stop light rear out	Replaced x 2 globes onnn rear pax stop light	460362
60 04/11/2014	457653	Brakes - Foot brake valve leaking air	Replaced brake valve and road tested- ok.	460362
60 04/11/2014	457653	Air System - Middle axle air pressure valve leak	Replaced trailer relay valve	460362
60 04/10/2014	457272	WORN - POS 1 - 275/70 R22.5 -	Creditor #:GB-BEA001 BEAUREPAIRES P/O #:G137571 Receiving #:139581 Date :2014-04-15 REPLACE WITH RECAP	460362
60 04/10/2014	457272	Whls & Tyres - Replace tyre pos 1 - worn	Replaced	460362
60 04/10/2014	455685	GLOBE+HOLDER INSTRUMENT (GREY)		460362
60 04/09/2014	457205		Perform Safety Inspection as per checklist	460362
60 04/09/2014	457204		Perform Safety Inspection as per checklist	460362
60 04/09/2014	457204		Perform Safety Inspection as per checklist	460362
60 04/09/2014	457320	Whls & Tyres - Replace NS front tyre	Changed tyre & torqued w/nuts	460362
60 04/09/2014	457320	Whls & Tyres - Replace NS front tyre	Changed tyre & torqued w/nuts	460362
60 04/09/2014	457347	Elec & Light - Replace speedo globe	Replaced	460362
60 04/09/2014	457205		Tension ALL Wheel Nuts to OEM Specs	460362
60 04/09/2014	457205		A Service & Bus Safety Inspection	460362
60 04/03/2014	455764	Remove A3 Marketing Poster CATCHING A BUSFit A3 Marketing	completed	460362
60 04/02/2014	455685	Investigation/Inspection - looses power	checked and road tested unable to find faulty due to workshop computer not working	460362
60 03/31/2014	455032	Elec & Light - Jack knife light on	checked out fixed middle ns wheel bearing loose	460293
60 03/28/2014	455032	Elec & Light - Jack knife light on	Get bus into w/shop	460293
60 03/27/2014	454033	Elec & Light - Jack knife light coming on	Put t/table back together and adjusted pressureroadtest. fault would not come up. sent bus out.	460004
60 03/27/2014	454033	Elec & Light - Jack knife light coming on	adjusted pressure in turntable. took bus on a long roadtest. fault would not come up. sent bus out.	460004
60 03/25/2014	454033	Elec & Light - Jack knife light coming on	assisted elias with removing floor in turntable to access wiring and pressure valve.	460004
60 03/25/2014	454033	Elec & Light - Jack knife light coming on	Assisted Matt	460004
60 03/24/2014	452560	Air Conditioning Hose		460004
60 03/24/2014	452560	24 VOLT RELAY PANEL		460004
60 03/24/2014	452560	AIR CON REFRIDGERANT		460004
60 03/24/2014	454033	Elec & Light - Jack knife light coming on	Assisted Matt	460004
60 03/24/2014	454033	Elec & Light - Jack knife light coming on	I could not replicate fault secured wiring in t/table closed up & cleaned bus will need to r/test	460004
60 03/21/2014	453429	Elec & Light Jack knife on	Found engine preheat button been on - no fault codes on jack knife - road tested OK	460004
60 03/21/2014	453429	Elec & Light Jack knife on	Found engine preheat button been on - no fault codes on jack knife - roadtested OK - Assist Greg	460004
60 03/18/2014	452814	INDICATOR LIGHT FRONT ARTIC		459840
60 03/17/2014	452560	Ops Entered - Fault - Air Cond Air Conditioner - Route: -	Replaced failed discharge hose rear unit left bank repaced L/P switch located and repaired elec fault front unit. Training Jack	459792
60 03/17/2014	452814	Elec & Light - Replace damaged indicator lens	Replaced	459840
60 03/14/2014	452156	rear relay valve leaking	checked rear relay valve no any leak	459792
60 03/14/2014	452156	Ops Entered - Fault - Gearbox Vibrate - Route: - Take a A	Gear box not vibrate vibrate coming from front tyres	459792
60 03/14/2014	452156	Ops Entered - Fault - Engine Surging - Route: - Arrive Da	Road tested did not found any faulty	459792

60 03/14/2014	452156 Engine - S/clean engine & g/box	Completed steam clean engine and gear box	459792
60 03/14/2014	452156 Ops Entered - Fault - Elec & Light Horn - Route: - Arrive	Replaced horn	459792
60 03/14/2014	452156 FUSE BLADE 10AMP		459792
60 03/14/2014	452156 HORN 24VLT		459792
60 03/14/2014	452280 Perform Campaign 1_14 School Bus Light Globe Check Check	No school light in this bus	459792
60 03/14/2014	452156 Ops Entered - Fault - Comm Equip Faulty - Route: - Arrive	fixed	459792
60 03/14/2014	452156 Ops Entered - Fault - Comm Equip Faulty - Route: - Arrive	Checked over and found no power replaced fuse and checked it's O/K	459792
60 03/14/2014	452515 Fit Myki decals as requiredFit Recruitment decal as requi	Replaced	459792
60 03/14/2014	452156 Ops Entered - Fault - Air System Losing Air - Route: - Ta	Checked air bags and valves no any air leak	459792
60 03/13/2014	452156 Ops Entered - Fault - Air System Losing Air - Route: - Ar	Bring bus back from Dingley Village	459792
60 03/13/2014	452156 Ops Entered - Fault - Air System Losing Air - Route: - Ar		459792
60 03/13/2014	452156 Ops Entered - Fault - Air System Losing Air - Route: - Ar		459792
60 03/04/2014	449680 SCANIA K230 BELT	Bring bus back from Dingley Village	459417
60 03/04/2014	449680 A/CON BELT B10B 21/32X68		459417
60 03/03/2014	449680 AIR CONDITIONING REPAIR	Creditor #:GB-22C001 22 CELSIUS P/O #:G135723 Receiving #:137506 Date :2014-03-05 TM31 COMPRESSOR	459417
60 03/03/2014	449680 AIR CONDITIONING REPAIR	Creditor #:GB-22C001 22 CELSIUS P/O #:G135903 Receiving #:137504 Date :2014-03-05	459417
60 02/27/2014	449680 a/c copressor seized/artic light coming on at dash	Remove seized compressor and fit new one by gavin	459417
60 02/26/2014	449705 Brakes - Replace RHF brake sensor	Replaced	459417
60 02/21/2014	448505 A/CON BELT B10B 21/32X68		459417
60 02/20/2014	448717 Air Cond belt cracked	Replaced	459417
60 02/20/2014	448717 Air Cond belt cracked	Replaced	459417
60 02/19/2014	448505 Elec & Light W'rring Light / jackknife light on and loose	Investigating knife fault	459284
60 02/17/2014	447785 Engine stalling at times artic light on on dash	Assit with Alan to find broken wire and remove Wheel	458988
60 02/17/2014	447785 Engine stalling at times artic light on on dash	fault find brake wear light on dash.repair l/h/f wear sensor wire.	458988
60 02/17/2014	447785 WEAR SENSOR SCANIA DISC BRAKE		458988
60 02/11/2014	446429 BRAKE BOOSTER MID AXLE L94UAB		458644
60 02/11/2014	446429 Brakes L/H/trayler whell	fit new l/h/r brake chamberfit new brake padsfit new brake caliperfit new hub seals. changed diff oil road tested ok.	458644
60 02/11/2014	446429 WEAR SENSOR SCANIA DISC BRAKE		458644
60 02/11/2014	446429 DISC PAD SET SCANIA MB0500		458644
60 02/10/2014	446429 CALIPER BRAKE SCANIA L94 OS	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G134956 Receiving #:136600 Date :2014-02-10	458644
60 02/10/2014	446429 Brakes L/H/trayler whell	remove wheelsbrake caliperhub and brake booster.	458644
60 02/10/2014	446429 SEAL HUB REAR OUTER SCANIA K124EB		458644
60 02/10/2014	446429 SEAL HUB REAR SCANIA K124		458644
60 02/10/2014	446429 GASKET REAR AXLE SCANIA		458644
60 02/07/2014	446354 Ops Entered - Breakdown - Breakdown Road Defect Unaffected	??? unaffected	458644
60 02/07/2014	446429 ABS CONTROL VALVE	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G134877 Receiving #:136498 Date :2014-02-07	458644
60 02/07/2014	446429 Brakes L/H/trayler whell		458644
60 01/29/2014	445075 Mechanic entered - Eng Cool Coolant Low	added coolant.	457813
60 01/23/2014	444382 Ops Entered - Fault - Air Cond Air Conditioner - Route: -	Has been done	457713
60 01/14/2014	442791 5 PIN CHANGE-OVER RELAY WITH DIODE		457466
60 01/14/2014	442791 AIR CON REFRIDGERANT		457466
60 01/14/2014	442791 24 VOLT RELAY PANEL		457466
60 01/14/2014	442791 COMPUTER SLRT/RM-RP		457466
60 01/11/2014	442692 windscreen goes opaque in direct sunlight !! some sort of f	Checked and still serviceable.	457310
60 01/10/2014	442871	Perform Safety Inspection as per checklist	457310
60 01/10/2014	442791 20AMP BLADE FUSE		457310
60 01/10/2014	442791 NARVA INLINE FUSE HOLDER		457310
60 01/10/2014	442791 5 PIN CHANGE-OVER RELAY WITH DIODE		457310
60 01/10/2014	442791 15AMP GLASS FUSE		457310
60 01/10/2014	442791 Air Cond Air Conditioner rear not working	Replace ESP & CCC units rewire entire rear unit from dead short in main loom locate and rear refrigerant leak in system 2 run up & tested OK	457310
60 01/10/2014	442871	complete	457310
60 01/10/2014	442871	Tension ALL Wheel Nuts to OEM Specs	457310
60 01/10/2014	442871	A Service & Bus Safety Inspection	457310
60 01/09/2014	442634 GLOBE FESTOON 24V 5W		457310
60 01/09/2014	442634 LAMP INDICATOR [ORANGE]		457310
60 01/09/2014	442634 GLOBE S/CONTACT 24V-10W		457310
60 01/09/2014	442634 Drv entered - Elec & Light Park Lights	CHANGED BLOWN GLOBE-{OSF TOP }.	457310
60 01/09/2014	442634 Elec & Light - No hazards on bottom RH	REPLACED (OSR side) indicator - corroded.	457310
60 01/09/2014	442634 GLOBE S/CONTACT 24V-10W		457310
60 01/09/2014	442634 Drv entered - Elec & Light Indicators	changed blown globes (osf top).	457310
60 01/09/2014	442668 GLOBE FESTOON 24V 5W		457310
60 01/09/2014	442668 LAMP (RED+AMBER)		457310
60 01/09/2014	442668 Mechanic entered - Elec & Light Park Lights	replaced clearance lamps (nsr and ns. mid) corroded.	457310
60 01/08/2014	442448 Body & Acc (None) broom missing	Operations need to replace broom???	457097
60 01/06/2014	442054 Mechanic entered - Eng Cool Coolant Low	added coolant.	456807
60 01/06/2014	442014 Remove BTS Equipment Fuses	removed	456807
60 01/02/2014	441660 Mechanic entered - Eng Cool Coolant Low	added coolant.	456430
60 12/31/2013	441474 Mechanic entered - Eng Cool Other	replaced leaking boost pump	456430
60 12/31/2013	441472 Mechanic entered - Eng Cool Coolant Low	added coolant.	456430
60 12/31/2013	441435 90LTR BOOST PUMP COACH		456430
60 12/31/2013	441435 Mechanic entered - Eng Cool Other	asst to deoman to change bost pump road test bus ok.	456430
60 12/30/2013	441309 Mechanic entered - Eng Cool Coolant Low	added coolant.	456283
60 12/24/2013	440899 Remove A3 Hold On Poster and Fit A3 Catching a bus poster	removed	455939
60 12/23/2013	440335 LENS TO SUIT 2029 (RED+AMBER)		455717
60 12/23/2013	440335 GLOBE FESTOON 24V5W (17136)		455717
60 12/23/2013	440335 LAMP (RED+AMBER)		455717
60 12/20/2013	440335 Ops Entered - Breakdown - Breakdown Road Defect Unaffected S	CHECKED OUT ABS AND JACKKNIFE UNABLE TO FAULT ROAD TESTED OK REPLACED SIDE LIGHTS	455717
60 12/19/2013	440335 Ops Entered - Breakdown - Breakdown Road Defect Unaffected	roadtest bus for andy on 2 occasions	455717
60 12/19/2013	440335 Ops Entered - Breakdown - Breakdown Road Defect Unaffected	road tested find jack knife light on and vehicle losing power.. c/o	455717
60 12/10/2013	438751 Elec & Light Jack knif light on	Recharged articulation	454804
60 12/06/2013	437470 Accident damage - O/S/R - Acc # DAN 38283. * To be repaired	Checked accident details took photos and arranged repairs etc.	454727
60 12/05/2013	437470 Accident damage - O/S/R - Acc # DAN 38283. * To be repaired	finished acc dam JOB COMPLETED	454555
60 12/05/2013	437470 REPLACE DECALS	Creditor #:GB-ATT001 ATTITUDE SIGNS P/O #:G132632 Receiving #:134216 Date :2013-12-05 OS last 3 panels on trailer	454555
60 12/05/2013	437470 GLOBE FESTOON 24V10W		454555
60 12/05/2013	437470 NUMBER PLATE LAMP		454555
60 12/05/2013	437470 GLOBE STOP AND TAIL 24V 21/5W		454555
60 12/05/2013	437470 GASKET LIGHT 2139+2143+2043		454555
60 12/05/2013	437470 LENS TO SUIT 2319 (RED)		454555
60 12/05/2013	437470 STOP TAIL LIGHT RED		454555
60 12/05/2013	437470 STEEL CLAW CATCHES		454555
60 12/04/2013	437470 Accident damage - O/S/R - Acc # DAN 38283. * To be repaired	finished acc dam ready for painting	454555
60 12/04/2013	437470 Accident damage - O/S/R - Acc # DAN 38283. * To be repaired	Cont repairs on OS corner panel & rear b/bar masked up etch primed primed and painted top coat	454555
60 12/03/2013	437470 Accident damage - O/S/R - Acc # DAN 38283. * To be repaired	Started acc dam ready for painting	454555
60 11/26/2013	436532 Perform Campaign as per Instructions Ensure that appropri	Completed.	454265
60 11/22/2013	436171 interior panel hanging off	refit panel	454099

60	11/15/2013	435024	GLOBE 24V 75/70W H4				453413
60	11/14/2013	435024	Ops Entered - Fault - Elec & Light Headlights - Route: 811	replaced globe.			453249
60	11/11/2013	434276	GLOBE CLEARANCE 24V 5W DOUBLE CONTACT				452915
60	11/11/2013	434276	FESTOON GLOBE 24V/3W				452915
60	11/11/2013	434216	FOOT VALVE	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G131673 Receiving #:133141 Date :2013-11-11			452915
60	11/11/2013	434216	Brakes Replace trayler brake peds	replaced brake pads			452915
60	11/11/2013	434216	Brake foot valve leaks	replaced fut valvle			452915
60	11/11/2013	434216	WEAR SENSOR SCANIA DISC BRAKE				452915
60	11/11/2013	434216	DISC PAD SET SCANIA MB0500				452915
60	11/08/2013	434056	ANDREW	Perform Safety Inspection as per checklist			452915
60	11/08/2013	434004	Lacking Engine Power at Brighton TownHall	Attended Breakdownfound repeated issue on same bus.Dandenong took over			452915
60	11/08/2013	434276	Elec & Light - Replace globes	Replaced			452915
60	11/08/2013	434337	Fit New Myki Decal as Per PTV fitting instructions	Fitted			452915
60	11/08/2013	434056		Tension ALL Wheel Nuts to OEM Specs			452915
60	11/08/2013	434056		A Service & Bus Safety Inspection			452915
60	11/06/2013	433603	Mechanic entered - Eng Cool Coolant Low	added coolant.			452137
60	11/01/2013	432809	IMAGE RELATED REPAIRS TO BUSES	Creditor #:GB-TRA013 TRANSCAL P/O #:G131428 Receiving #:133033 Date :2013-11-06			452780
60	10/30/2013	432963	Body & Acc - Remove exterior decals	Removed & polished			452137
60	10/30/2013	432809	Carry out campaign as per Fleet re-branding Procedure.	Rebranded			451706
60	10/29/2013	431451	CUSTOMER ENQUIRY DECAL				451706
60	10/22/2013	431451	DRIVERS NO DEFECT CHECKLIST DECAL				451039
60	10/22/2013	431451	WARNING MAXIMUM HEIGHT DECAL				451039
60	10/22/2013	431451	EMERGENCY PROCEDURE DECAL				451039
60	10/22/2013	431451	LICENSED TO CARRY DECAL				451039
60	10/22/2013	431451	NO SMOKING GOV REG DECAL				451039
60	10/22/2013	431451	CCTV SURVEILLANCE DECAL				451039
60	10/22/2013	431451	BY LAW PICKUP/SET DOWN DECAL				451039
60	10/22/2013	431451	PLEASE ASSIST DRIVER DECAL				451039
60	10/22/2013	431451	PASSENGERS REQUIRED BY LAW DECAL				451039
60	10/19/2013	430615	Remove A3 Poster 15/8Fit Poster (HOLD ON) as per Campaign	Completed by operations			450302
60	10/08/2013	431451	Perform sticker audit on vehicles ensuring that correct sti	Removed & replaced			449624
60	10/02/2013	428056	GLOBE FESTOON 24V 5W				448942
60	10/02/2013	428056	GLOBE 24V 75/70W H4				448942
60	10/02/2013	428056	DASH WARNING GLOBE MERC/MAN				448942
60	10/02/2013	428056	Mechanic entered - Elec & Light Headlights	change ns head light globeosf side marker lamp globe osf parking light globe			448942
60	09/19/2013	426062		Perform Safety Inspection as per checklist			447734
60	09/19/2013	426062		CARRIED OUT A SERVICE			447734
60	09/19/2013	426062		Tension ALL Wheel Nuts to OEM Specs			447734
60	09/19/2013	426062		A Service & Bus Safety Inspection			447734
60	09/11/2013	424742	Drv entered - Heat & Demist Heater Cold	OK			446501
60	09/07/2013	423437	Remove A3 Marketing Poster 30/9Fit Marketing Poster 15/8	Completed			445252
60	08/19/2013	416795	ANNUAL INSPECTION	Creditor #:GB-ROA001 Road Safety Inspections P/O #:G128240 Receiving #:129902 Date :2013-08-22			444074
60	08/19/2013	420018	Engine warning light on (red)	checked out wirring found wire shorting repaired and road tested ok			443372
60	08/18/2013	416795	Annual Licence	Completed RWC 251692			443372
60	08/16/2013	420018	Engine warning light on (red)	get wirring diagramfor fire arlarm			443372
60	08/14/2013	420058	Body & Acc - Paint rear b/bar	CHECKED OK			443372
60	08/13/2013	420018	Engine warning light on (red)	check out engine door hatch attempt full system reboot and check for any visual signs of plugs or wires broekn fluid leaks and fuel leaks.. non found			443372
60	08/13/2013	420018	Engine warning light on (red)				443372
60	08/13/2013	419957	Body & Acc Check turntable	represurise turntable and road tested ok			443372
60	08/12/2013	419664	EMERGENCY EXIT BUTTON PULL COVER				443372
60	08/12/2013	419664	Mechanic entered - Elec & Light Bell Button	Mount wiring and fit panels back. Fix wiring. Clean Up inside bus. Secure wiring back in turntable ceiling. Need to fit turntable curtains back and sweep bus. c/o			443372
60	08/12/2013	412650	Elec & Light - Cant start from ignition switch - front	Made new wire protection for inside turntable. Fit turntable curtains back. Fit all screws and put panels back. Cleaned up inside bus. Took bus for road test. Replaced Emergency Door cover.			443372
60	08/12/2013	412650	Elec & Light - Cant start from ignition switch - front	took bus for roadtest. everything ok except for turntable warning light coming on with code 18 active. (no hydraulic signal) parked bus in line 1 to be looked at tomorrow.			443372
60	08/09/2013	412650	Elec & Light - Cant start from ignition switch - front	assisted brad with putting panels back. repaired an a/c duct that i broke while assisting him.			443372
60	08/08/2013	412650	Elec & Light - Cant start from ignition switch - front	Got bus moved fixed wiring for starting issue fixed broken wiring started putting wiring & covers back c/o			443372
60	08/08/2013	417416	Body & Acc - Touch up paint work	Moved bus into bodyshop			440758
60	08/08/2013	417416	Body & Acc - Touch up paint work	Moved bus in/out of bodyshop			440758
60	08/08/2013	417416	Body & Acc - Touch up paint work	Repair mask up paint under coat & white unmask bus & clean			440758
60	08/07/2013	412650	Elec & Light - Cant start from ignition switch - front	Checked pass bell n/w and found broken wire under bus replaced with new plug and checked OK but still c/o other jobs			443372
60	08/06/2013	412650	Elec & Light - Cant start from ignition switch - front	Assist Bradman c/o			443372
60	08/06/2013	412650	Elec & Light - Cant start from ignition switch - front	Temp fix starting wire. Earth wire for buttons broken in rear of bus after further diagnosis c/o			443372
60	08/06/2013	412650	FUSE BLADE 10AMP				443372
60	08/05/2013	416941		Rekit quick release valve			443372
60	08/05/2013	416941		Adjust valve clearances			443372
60	08/05/2013	412650	Elec & Light - Cant start from ignition switch - front	Jump started & moved to get under bus cont diagnosis of stop buttons wire not broken under bus c/o			440758
60	08/02/2013	412650	Elec & Light - Cant start from ignition switch - front	Cont diagnosis of stop button fault found broken wire under bus started putting back parts not needed back together			440758
60	08/02/2013	412650	2.5MM SILICONE CABLE RED P/M	Creditor #:GB-MID001 MIDDENDORP ELECTRIC CO. P/L P/O #:G127833 Receiving #:129118 Date :2013-08-05			440758
60	08/01/2013	418274	Air Cond - Found a/c leak in turntable	Tested system found pad fitting on discharge pipe as it enters constatine had loose bolts tension bolts leak check tested OK			440758
60	08/01/2013	412650	Elec & Light Bell Button. No sound or light from next sto	Move bus remove curtains cont diagnosing push button fault waiting on parts to complete bus start issue Continued diagnosis of stop button wiring. Found broken wire underneath bus. Bus needs to be moved to pit. Started putting paneling back together that is not needed to be removed any longer.			440758
60	08/01/2013	412650	Elec & Light - Cant start from ignition switch - front	Assisted Brad			440758
60	08/01/2013	412650	Elec & Light - Cant start from ignition switch - front	Assisted Brad with checking wires moved bus to line 1			440758
60	07/31/2013	412650	Elec & Light Bell Button. No sound or light from next sto	Removed panels & curtain cut/removed cabling found broken wire moved bus into w/shop waiting for parts to fix wiring properly. Cont work on stop button wiring issue. Found a/c leak in t/table c/o			440758
60	07/31/2013	417793	Elec & Light - Park & headlights coming on when engine start	fit new relay			440758
60	07/31/2013	417793	Elec & Light - Bell u/s back of the bus	Ref to w/o # 412650			440758
60	07/31/2013	417793	Elec & Light - No park lights	fit new relay			440758
60	07/31/2013	412650	Elec & Light - Cant start from ignition switch - front	Ass Brad with moving buses to get 60 from the line into w/shop			440758
60	07/31/2013	417416	HINGE DRIVERS COMPARTMENT				440758
60	07/31/2013	417416	GIVE WAY SIGN (LARGE)				440758
60	07/30/2013	416941		Remove intercooler wash intercooler and raditor			443372
60	07/30/2013	412650	Elec & Light Bell Button. No sound or light from next sto	Start removing curtain to t/table to get inside wiring find proper wiring diagrams for starting circuit fault wiring issue between front & mid c/o			440758
60	07/30/2013	412650	Elec & Light Bell Button. No sound or light from next sto	Assisted Brad with wiring diagrams c/o			440758
60	07/29/2013	417416	Vandalism - Clean graffiti - floor seats & side walls	Cleaned			440758
60	07/29/2013	412650	Elec & Light Bell Button. No sound or light from next sto	Assisted Bradman with wiring on passenger buttons c/o			440758
60	07/29/2013	412650	Elec & Light Bell Button. No sound or light from next sto	Finding broken wire in rear of bus looking underneath now checking for coolant leak in t/table c/o			440758
60	07/29/2013	417416	Body & Acc - Touch up paint work	c/o			440758
60	07/29/2013	417416	Body & Acc - replace give way decal - OSR corner window	Replaced			440758
60	07/29/2013	417416	Body & Acc - paint wheels	washed cleaned & painted			440758
60	07/29/2013	417416	Body & Acc - Secure all lower skirt panels	Secured			440758
60	07/29/2013	417416	Body & Acc - Paint till stand	Painted			440758
60	07/29/2013	417416		Move bus in/out body shop			440758
60	07/29/2013	417416	Body & Acc - Replace drivers door hinge	Replaced & adjusted door lock			440758
60	07/29/2013	417416	Body & Acc - Wheel chair ramp - operation & clean	Done			440758
60	07/29/2013	417416	Body & Acc - Clean back seat - rubbish	Cleaned			440758
60	07/29/2013	417416	Body & Acc - Paint exterior mirrors and arms	Painted			440758
60	07/29/2013	417416	Body & Acc - Clean air condition filter secure vents	Cleaned			440758

60 07/26/2013	412650 Elec & Light Bell Button. No sound or light from next sto	Replaced supply relay assisted Brad with wiring test c/o	440758
60 07/26/2013	412650 Elec & Light Bell Button. No sound or light from next sto	Cont finding wiring issue c/o	440758
60 07/26/2013	417131 DIAPHRAGM TYPE 24		443372
60 07/25/2013	416941 FILTER FUEL K124 / LU94A (1411894 / H17WK05)		443372
60 07/25/2013	416941	Clean a/c filters	443372
60 07/25/2013	416941	Replace air dryer canister	443372
60 07/25/2013	416941	Replace hydraulic fan filter and top up oil	443372
60 07/25/2013	416941	Replace power steering filter	443372
60 07/25/2013	416941	Replace final drive oil	443372
60 07/25/2013	416941	Replace fuel filters	443372
60 07/25/2013	416941	Inspect bus as per inspection sheet	443372
60 07/25/2013	416941 Service		443372
60 07/25/2013	416941 RPM BORATE EP LUBE 220		443372
60 07/25/2013	416941 FILTER AIR DRYER SCANIA K124EB (T350W)		443372
60 07/25/2013	416941 FILTER K124EB HYD COOLING FAN		443372
60 07/25/2013	416941 FUEL FILTER ELEMENT SCANIA L94UAB (R90T / H7090WK10)		443372
60 07/25/2013	416941 POWER STEERING FILTER VOLVO		443372
60 07/25/2013	417073 Annaul Body Inspection	Inspected	443372
60 07/25/2013	412650 Elec & Light Bell Button. No sound or light from next sto	Moved bus to line for Brad checked lights to assist with bus 143s diagnosis assisted Brad with checking door bell c/o	440758
60 07/25/2013	412650 Elec & Light Bell Button. No sound or light from next sto	Diagnosing starting & stop button issue wire problem issue in front half of bus c/o	440758
60 07/25/2013	416940 Brakes - Door brake not enough still can drive when door ope	Ref to w/o # 412650	443372
60 07/25/2013	417131 Brakes - Replace OSR booster diaphragm	Replaced	443372
60 07/24/2013	416667 LENS TO SUIT 2030 LAMP(ORANGE)		443372
60 07/23/2013	416507	Perform Safety Inspection as per checklist	443217
60 07/23/2013	416507	Perform Safety Inspection as per checklist	443217
60 07/23/2013	416667 Drv entered - Elec & Light Indicators	Replaced due to wrong lens fitted	443372
60 07/23/2013	416667 Drv entered - Elec & Light Indicators	Checked OK	443372
60 07/17/2013	412650 Elec & Light Bell Button. No sound or light from next sto	Began disassembling panels to diagnose wiring fault bus also not starting from front bus had to go out so put all panels and wiring back	440758
60 07/17/2013	412650 COVER BUS STOPPING SIGN		440758
60 07/17/2013	412650 GLOBE S/CONTACT 24V-10W		440758
60 07/17/2013	412650 Elec & Light Bell Button. No sound or light from next sto	Assisted Brad with closing up bus to go on the road	440758
60 07/17/2013	415360 AIR FILTER SCANIA CLEANED		440758
60 07/16/2013	412650 Elec & Light Bell Button. No sound or light from next sto	Back half of bus stop buttons n/w c/o	440758
60 07/16/2013	415360	D Service & Bus Safety Inspection	442726
60 07/16/2013	415360	D Service & Bus Safety Inspection	442726
60 07/16/2013	415360 TEXAMATIC 1888		442726
60 07/16/2013	415360 ENGINE OIL DELO 400LE 15W40		442726
60 07/16/2013	415360 O RING FILTER KIT K93		442726
60 07/16/2013	415360 FILTER TRANSMISSION ZF 4139-298-038E39HD119		442726
60 07/16/2013	415360 FILTER OIL K124 / L94UAB (H200W02)		442726
60 07/16/2013	415360	Tension ALL Wheel Nuts to OEM Specs	442726
60 07/16/2013	415360	Tension ALL Wheel Nuts to OEM Specs	442726
60 07/16/2013	415360	A Service & Bus Safety Inspection	442726
60 07/12/2013	415073 Body & Acc - Fix driver seat belt	Fixed and adjusted	442507
60 07/10/2013	414387 GLOBE FESTOON 24V-3W		442127
60 07/09/2013	414220 Drv entered - Other	???	441938
60 07/09/2013	414387 Elec & Light - Replace emer exit light globe	Replaced	442127
60 07/07/2013	414130 Elec & Light - Bus wont start	Jump started	441748
60 07/03/2013	413564 Elec & Light - Back rear compartment pax bus stop button n/w	Checked and found wire broken sent to GBS	441327
60 07/03/2013	413564 Elec & Light - Back rear compartment pax bus stop button n/w	Checked with Aaron and found wire broken sent to GBS	441327
60 07/03/2013	413178 EMERGENCY EXIT BUTTON PULL COVER		441128
60 07/02/2013	413178 Elec & Light - Replace emer exit button cover	Replaced	441128
60 07/02/2013	413178 Elec & Light - Replace emer exit button cover	Replaced	441128
60 06/27/2013	412336 LENS TO SUIT 2029 (RED+AMBER)		440379
60 06/26/2013	412336 Elec & Light - Replace NSR clearance lens	Replaced	440379
60 06/24/2013	412051 Elec & Light - Replace globes	Replaced & adjusted clearance light	439729
60 06/21/2013	411340 GLOBE INDICATOR 24V-18W SINGLE CONTACT		439535
60 06/20/2013	411340 Elec & Light - replace indicator globe	Replaced	439535
60 06/18/2013	410474 SCANIA L94UAB MIDDLE L/H CALIP	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G125879 Receiving #:126820 Date :2013-06-19	439375
60 06/18/2013	410474 SCANIA L94UAB MIDDLE R/H CALLI	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G125879 Receiving #:126820 Date :2013-06-19	439375
60 06/18/2013	410474 Brakes - OS middle caliper u/s	Replace NSr caliper (middle) & brake pads & fitted wheels	439353
60 06/18/2013	410474 Brakes - OS middle caliper u/s	Checked and found OS mid axle caliper u/s replaced OSr mid axle brake caliper	439353
60 06/18/2013	410474 WEAR SENSOR SCANIA DISC BRAKE		439353
60 06/18/2013	410474 DISC PAD SET SCANIA MB0500		439353
60 06/17/2013	410457 DRIVE BELT L94-K94		439353
60 06/14/2013	410283 Heat & Demist. Heater not working	Checked OK	439210
60 06/14/2013	410283 Heat & Demist. Heater not working	Checked OK	439210
60 06/14/2013	410457 Elec & Light - Replace LH side marker	Replaced	439353
60 06/14/2013	410457 Elec & Light - Replace alternator belt	Replaced	439353
60 06/14/2013	410474 Brakes - OS middle caliper u/s	Remove OSR wheel to brakes and caliper	439353
60 06/14/2013	410284	A Service & Bus Safety Inspection	439353
60 06/14/2013	410284 GLOBE FESTOON 24V 5W		439353
60 06/14/2013	410284	Tension ALL Wheel Nuts to OEM Specs	439353
60 06/14/2013	410284	A Service & Bus Safety Inspection	439353
60 05/31/2013	408496 Brakes - Brakes locking on	Checked OK	437754
60 05/30/2013	408235 Elec & Light - Replace interior fluro	Replaced	437561
60 05/21/2013	405385 Mechanic entered - Brakes Hand Brake hand brake interlock kn	replaced.	436134
60 05/20/2013	405513 BALD - 275R 22.5 - RECAP - STE	Creditor #:GB-BEA001 BEAUREPAIRES P/O #:K124312 Receiving #:125235 Date :2013-05-20 REPLACE WITH RECAP	435904
60 05/16/2013	405249 D - service	Creditor #:GB-22C001 22 CELSIUS P/O #:G124295 Receiving #:125089 Date :2013-05-16	435496
60 05/16/2013	405547	EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check boltsclamps & fittings; clean condensate drains; clean drip tray	435293
60 05/15/2013	405513 Whls & Tyres - Bald - recap - pos 56	Replaced	435293
60 05/15/2013	405385 KNOB BLOCK VALVE	Creditor #:GB-EAS002 EASTCOAST TRUCK & BUS SERVICE P/O #:G124276 Receiving #:125005 Date :2013-05-15	435293
60 05/14/2013	405614 Whls & TyresReplace N/S rear 7 . 8 . tyres	Replaced	435293
60 05/14/2013	405385 Mechanic entered - Brakes Hand Brake hand brake interlock k	Ordered new knob	435086
60 05/13/2013	405382 Drv entered - Heat & Demist Demisters Cold	Demister switch n/w pulled from spare bus 35 and put into 60	435086
60 05/11/2013	405245 Vandalism - Clean graffiti	Cleaned	435015
60 05/11/2013	405249	Check boost pump condition	435015
60 05/11/2013	405249	Check & replace electric motor brushes	435015
60 05/11/2013	405249	Replace compressor oil	435015
60 05/11/2013	405249	Replace filter drier	435015
60 05/11/2013	405249	D Service	435015
60 05/11/2013	405547	B Service	435293
60 05/11/2013	405547	Replace filter drier	435293
60 05/11/2013	405547	Replace compressor oil	435293
60 05/11/2013	405249	DRIVE PULLEY'S: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;	435015

60 05/11/2013	405249 COMPRESSOR OIL AIR CON			435015
60 05/11/2013	405249 FILTER DRIER 5/8			435015
60 05/11/2013	405249 front unit completed		UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensor pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation	435015
60 05/11/2013	405249		CONDENSOR AREA: Clean condensor coils; check boltsclamps for tension	435015
60 05/11/2013	405249		INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condensor fan grills	435015
60 05/11/2013	405249		EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check boltsclamps & fittings; clean condensate drains; clean drip tray	435015
60 05/11/2013	405249		REFRIGERATION FILTER DRYER: Replace filter dryer; check pump operation;	435015
60 05/11/2013	405249		COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose	435015
60 05/11/2013	405249		DRIVE PULLEY'S: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear	435015
60 05/11/2013	405249		COMPRESSOR DRIVE BELTS: Inspect belt wear; Retension belts;	435015
60 05/11/2013	405249		FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)	435015
60 05/11/2013	405249		Clean R/A & F/A filters; Inspect and report on condition; Replace filter media	435015
60 05/11/2013	405547		UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensor pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation	435293
60 05/11/2013	405547		CONDENSOR AREA: Clean condensor coils; check boltsclamps for tension	435293
60 05/11/2013	405547		INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condensor fan grills	435293
60 05/11/2013	405547		REFRIGERATION FILTER DRYER: Replace filter dryer; check pump operation;	435293
60 05/11/2013	405547		COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose	435293
60 05/11/2013	405547		DRIVE PULLEY'S: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear	435293
60 05/11/2013	405547		DRIVE PULLEY'S: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;	435293
60 05/11/2013	405547		COMPRESSOR DRIVE BELTS: Inspect belt wear; Retension belts;	435293
60 05/11/2013	405547		FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)	435293
60 05/11/2013	405547		Clean R/A & F/A filters; Inspect and report on condition; Replace filter media	435293
60 05/09/2013	404940 Elec & Light - Replace exit globe		Replaced	434796
60 05/02/2013	396859 WEAR SENSOR SCANIA DISC BRAKE			434294
60 05/01/2013	403571 Complete Campaign 16/12 as required		Paint all wheel rims	434280
60 05/01/2013	396859 SWAY BAR LINK SUIT L94UAB & K		Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G123682 Receiving #:124503 Date :2013-05-01	434294
60 05/01/2013	396859 LINK SWAY BAR L94 CENTRE AXLE		Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G123682 Receiving #:124502 Date :2013-05-01 60	434294
60 05/01/2013	396859 VALVE PARK BRAKE SCANIA L94		Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G123682 Receiving #:124501 Date :2013-05-01	434294
60 05/01/2013	396859 Suspension - NR sway bar link balljoint - worn		Replaced	434280
60 05/01/2013	396859 Suspension - front axle sway bar link balljoint worn		Replaced	434280
60 05/01/2013	396859 Diff & Hubs - 78 wheels hub seal leak		Complete L/H drive axle seals and bearings and check R/H side is OK	434280
60 05/01/2013	396859 INNER SEAL REAR AXLE SCANIA L94UAB			434280
60 05/01/2013	396859 OUTER HUB SEAL REAR SCANIA L94UAB+L113CRB			434280
60 05/01/2013	396859 GASKET REAR AXLE SCANIA			434280
60 05/01/2013	403702 Body & Acc - Paint wheels		Painted replaced hub cap torqued w/nuts fuelled & parked	434294
60 05/01/2013	396859 Drv entered - Air System Losing Air			434280
60 05/01/2013	396859 Drv entered - Air System Leaking		replace H/brake valve	434280
60 04/30/2013	402954 WORN - POS 34 - 275/70 R22.5		Creditor #:BEA001 BEAUREPAIRS P/O #:G123486 Receiving #:124469 Date :2013-04-30 REPLACE WITH NEW 275/70 R22.5 AND RETURN CAPS TO GREENDA	434280
60 04/30/2013	396859 Steering - Steering shaft worn in between angle gear and ste		Removed checked and regreased OK	434280
60 04/30/2013	396859 Diff & Hubs - Drive axle LH hub cap oil leaking		Reolaceseals and repak bearings C/Ojob	434280
60 04/29/2013	402954 Whls & Tyres - Replace tyres 34 - worn		Replaced	434280
60 04/29/2013	403249 Perform Campaign 01_13 CCTV and GPS AUDIT inspect vehicles		audited	434280
60 04/29/2013	396859 PLUG H/CAP L94UAB		Creditor #:MUL001 MULTISPARES LTD P/O #:G123519 Receiving #:124330 Date :2013-04-29	434280
60 04/29/2013	396859 DISC PAD SET SCANIA MB0500			434280
60 04/29/2013	396859 CALIPER BRAKE SCANIA L94 NS		Creditor #:MUL001 MULTISPARES LTD P/O #:G123498 Receiving #:124255 Date :2013-04-29	434280
60 04/29/2013	396859 CALIPER BRAKE SCANIA L94 OS		Creditor #:MUL001 MULTISPARES LTD P/O #:G123498 Receiving #:124255 Date :2013-04-29	434280
60 04/29/2013	396859 Brakes - Bus pulling badly to right under brakes		Replace front brake rottorspads and cellipers	434280
60 04/29/2013	396859 FRONT DISC BRAKE ROTORS SCANIA(40F3319)			434280
60 04/29/2013	396859 WEAR SENSOR SCANIA DISC BRAKE			434280
60 04/29/2013	396859 Drv entered - Air System Losing Air		Replace hand brake valve	434280
60 04/22/2013	402286 Brakes Foot valve leaking		Replace foot valve	434215
60 04/22/2013	402286 Brakes - Foot brake valve leak		Replace foot valve	434215
60 04/22/2013	402286 VALVE BRAKE L94 (40G0103)		Creditor #:MUL001 MULTISPARES LTD P/O #:G123257 Receiving #:124022 Date :2013-04-22	434222
60 04/19/2013	0 Imported Service History		Imported Service History	434165
60 04/19/2013	401413 BEARING IDLER POST PULLEY (CURRUM TYPE)			434165
60 04/19/2013	402239 Air Cond - AC belt cracked		Checked OK	434215
60 04/19/2013	402048		A Service & Bus Safety Inspection	434165
60 04/19/2013	402048		Tension ALL Wheel Nuts to OEM Specs	434165
60 04/19/2013	402048		A Service & Bus Safety Inspection	434165
60 04/17/2013	401413 FAN BELT AIR/CON ARTIC VEE BELT B43			434165
60 04/16/2013	401413 Air Cond belts pulley bearings noise		Replaced a/c pulley bearings & belts	434165
60 04/16/2013	401413 Air Cond belts pulley bearings noise		R/tested bus a/c pulley bearings were damaged refitted new one and new a/c belts	434165
60 04/15/2013	401413 Air Cond belts pulley bearings noise		R/tested for whining noise	434165
60 04/15/2013	401413 Air Cond belts pulley bearings noise		R/tested for Andy	434165
60 04/15/2013	401413 Air Cond belts pulley bearings noise		Assisted Alan	434165
60 04/09/2013	400576 Elec & Light - Check switches for interior lights		Checked OK	433643
60 04/08/2013	400368 Elec & Light Interior Lights		Took switches from 76 none in store & fitted	433643
60 04/08/2013	400419 Elec & Light - Interior lights u/s		Took bus to GBS & bought back 143	433643
60 03/19/2013	394652 STARTER DRIVE SUIT JF			431940
60 03/19/2013	397058 BUSH KIT SUIT JF			431940
60 03/19/2013	397058 STARTER SOLENOID SUIT JF			431940
60 03/19/2013	396859 16MM NYLON JOINER			431940
60 03/19/2013	396859 AIR BAG (MID AXLE) SCANIA L94UAB TAG K1241B			431940
60 03/18/2013	397653 Elec & Light Emergency and midle clearence light out		replace globes	431940
60 03/15/2013	396859 Suspension - Middle axle both front airbags - leak		Replace air bags	431734
60 03/15/2013	396859 Suspension - Middle axle both front airbags - leak		Replace air bags	431734
60 03/15/2013	397459 Heat & Demist coolant leak		Repair heater hose leak near rocker cover	431776
60 03/15/2013	397445 Body & Acc replace engine door haches		replaced	431776
60 03/14/2013	397058 Elec & Light Won't start		Remove starter motor rebuiled and fit back - Checked ok	431768
60 03/14/2013	397058 Elec & Light Won't start		Remove starter motor rebuiled and fit back - Checked ok Assist Bradman	431768
60 03/07/2013	394652 Elec & Light - Has a starting fault		jumpstarted and moved bus in order to begin repairing wires. repaired starter wire and found other wires broken. repaired those as well.	431734
60 03/06/2013	394652 Elec & Light - Has a starting fault		continued checking wiring and found a fault in starter signal down to rear of bus. using wiring diagram i isolated the fault to one cable and found a break in the turntable using the current tester.	431734
60 03/06/2013	394652 Elec & Light - Has a starting fault		Assisted Matt with diagnosis	431734
60 03/05/2013	394652 Elec & Light - Has a starting fault		Cont following wiring diagram getting closer found fault with signal getting to starter relay in front elec panel	431734
60 03/04/2013	394652 Elec & Light - Has a starting fault		Continued tracing wiring c/o	431734
60 03/01/2013	394652 Elec & Light - Has a starting fault		Have tested wiring down to t/table and from t/table to rear fault persists c/o	431734
60 02/28/2013	394652 Elec & Light - Has a starting fault		Cont checking wiring everything works as it should	431734
60 02/27/2013	394652 Elec & Light - Has a starting fault		Got access to wiring diagrams via Karls computer began checking bus per the diagram	431734
60 02/26/2013	394652 Elec & Light - Has a starting fault		began checking t/table tried to retrieve wiring diagrams from Scania Multi but couldn't access on the computer	431734
60 02/25/2013	394652 Elec & Light - Has a starting fault		Looked for wiring diagrams but there unavailable checked under a/c duct for a rear electrical centre with no success	431734
60 02/22/2013	394216 SUB -KNIGHTS - OS windscreen chip mark		Knights - 22/02/2013	431734
60 02/22/2013	394216 REPAIR W/SCREEN		Creditor #:KNIO01 KNIGHTS WINDSCREEN REPAIRS P/O #:G120704 Receiving #:121416 Date :2013-02-22	431734
60 02/21/2013	394070 Elec & Light - Cant start from the key		checked wiring near ignition switch and near rear start switch. fualt is not happening	431734
60 02/18/2013	393705 Elec & Light - Starter motor needs fixing		Rebuild s/motor & replaced	431734
60 02/17/2013	393571 Elec & Light - Bus wont start		had to smack s/motor to start	431734

60 02/12/2013	392510 PUNCTURE - WORN - POS 910 - 2	Creditor #:BEA001 BEAUREPAIRES P/O #:G120104 Receiving #:120870 Date :2013-02-12 REPLACE WITH RECAP	430908
60 02/11/2013	392510 Whls & Tyres - Replace tyre pos 910	replaced	430676
60 02/11/2013	389956 SIDEWALL DAMAGE	Creditor #:BEA001 BEAUREPAIRES P/O #:G119340 Receiving #:120823 Date :2013-02-11 SCRAP TYRE	430908
60 02/11/2013	392834 Elec & Light - Bus wont start	Checked and started bus	430908
60 02/08/2013	392786 Elec & Light - Bus wont start	Starter motor engaged on fuel bay started there	430676
60 02/08/2013	392489 Breakdown - Reema & Maryrose Cres - OUT 6.00 pm BACK 7.30 p	Replaced both RHR tyres returned and emptied van	430676
60 02/08/2013	392489 Breakdown - Reema & Maryrose Cres - OUT 6.00 pm BACK 7.30 p	Van 619. Replaced both RHR tyres returned and emptied van	430676
60 02/07/2013	392175 A/CON BELT B10B 21/32X68		430254
60 02/07/2013	392341 Elec & Light - Bus wont start		430468
60 02/06/2013	392175 Air Cond Other	Jump started	430254
60 02/06/2013	392223 Elec & Light - Replace diffuser RH rear	Replaced a/c belt	430254
60 02/06/2013	392223 Eng Cool - Clean radiator	Replaced	430254
60 02/06/2013	389745	Cleaned	430254
60 02/06/2013	389745	A Service & Bus Safety Inspection	428780
60 02/06/2013	389745	Tension ALL Wheel Nuts to OEM Specs	428780
60 02/06/2013	389745	A Service & Bus Safety Inspection	428780
60 02/04/2013	391393 Elec & Light - Bus wont start from front key	changed batteries. tested starting. started bus from ignition switch 40+ times and worked everytime. closed rear floor hatch.	430221
60 02/04/2013	391393 NUT BATTERY TERMINAL NEG (BRASS)		430221
60 02/04/2013	391393 NUT BATTERY TERMINAL NEG (BRASS)		430221
60 02/04/2013	391393 BATTERY 800CCA		430221
60 02/04/2013	391393 BATTERY 800CCA		430221
60 02/01/2013	391393 Elec & Light - Bus wont start from front key	checked bus wont start. michael assisted with starting. after attempting to start an electrical problem occured stopping the bus from getting ignition power.	430221
60 01/30/2013	391116 Elec & Light - Bus wont start	Jump started	430221
60 01/22/2013	389956 Whls & Tyres - side wall damage	Scrapped	428780
60 01/09/2013	388148 Elec & Light - Replace interior light	Replaced	427401
60 01/04/2013	386907 BURST CRACKED - POS 56 - 275	Creditor #:BEA001 BEAUREPAIRES P/O #:K118419 Receiving #:119214 Date :2013-01-04 REPLACE WITH RECAPS	426658
60 01/02/2013	386907 Whls & Tyres - Replace tyre pos 56 - burst cracked	replaced	426311
60 01/02/2013	387201 Elec & Light - Replace interior light	replaced	426521
60 12/31/2012	386946 Whls & Tyres - Replace tyre pos 56	Replaced	426311
60 12/31/2012	386946 Whls & Tyres - Replace tyre pos 56	Replaced & tensioned w/nuts	426311
60 12/31/2012	386809 GLOBE INST 24V 2W		426119
60 12/31/2012	386809 LENS TO SUIT 2557 LAMP		426119
60 12/28/2012	386809 Elec & Light - Replace No plate light	Replaced lens & globe	426119
60 12/21/2012	385734 LOW TREAD - POS 7 - 275/70 R22	Creditor #:BEA001 BEAUREPAIRES P/O #:K118155 Receiving #:118862 Date :2012-12-21 REPLACE WITH RECAP	425518
60 12/21/2012	386045 GLOBE FESTOON 24V5W		425329
60 12/20/2012	385734 Whls & Tyres - Replace tyre pos 7 - low tread	replaced	425107
60 12/20/2012	386045 Elec & Light - Replace NSR indicator	Replaced	425329
60 12/19/2012	385784 Whls & Tyres - Replace tyre 7	Replaced & tensioned w/nuts	425107
60 12/11/2012	384687 Air Cond - Clean a/c filters	Cleaned	424254
60 12/11/2012	384687 Body & Acc - Adjust NS mirror	Adjusted	424254
60 12/06/2012	377683 BELT CRANK-TWIN A/C COMP SCANI	Creditor #:MUL001 MULTISPARES LTD P/O #:G116387 Receiving #:118097 Date :2012-12-06	423603
60 12/04/2012	383801 Elec & Light - Adjust interior light	Adjusted	423179
60 12/03/2012	383581 Elec & Light - Replace interior light	Replaced	422987
60 12/03/2012	383429 DIAPHRAM TYPE20 DEEP DISH		422824
60 12/01/2012	383429 Brakes - Replace NR drive axle brake booster diaphragm	Replaced	422824
60 12/01/2012	383231 FILTER OIL K124 / L94UAB (H200W02)		422809
60 12/01/2012	383231 FILTER TRANSMISSION ZF 4139-298-038E39HD119		422809
60 12/01/2012	383231 O RING FILTER KIT K93		422809
60 12/01/2012	383231 FILTER AIR SCANIA USE AF25066		422809
60 12/01/2012	383231 ENGINE OIL DELO 400LE 15W40		422809
60 12/01/2012	383231 TEXAMATIC 1888		422809
60 12/01/2012	383231	D Service & Bus Safety Inspection	422809
60 12/01/2012	383231	Tension ALL Wheel Nuts to OEM Specs	422809
60 12/01/2012	383231	A Service & Bus Safety Inspection	422809
60 12/01/2012	383231	Tension ALL Wheel Nuts to OEM Specs	422809
60 11/28/2012	382718 LAMP REAR STOP		422160
60 11/28/2012	382718 GLOBE INST 24V 2W		422160
60 11/28/2012	382718 GLOBE FESTOON 24V5W		422160
60 11/28/2012	382781 GLOBE S/CONTACT 24V-10W		422160
60 11/28/2012	382781 LAMP REAR STOP		422160
60 11/27/2012	382781 Elec & Light - replace OSR whole light assembly	Replaced	422160
60 11/26/2012	382718 Elec & Light - replace globes	Replaced	421967
60 11/26/2012	382718 Body & Acc - Replace seat	Replaced	421967
60 11/21/2012	377310 TM 31 A/C COMPRESSOR WITH 8PK	Creditor #:TRA061 TRANSIT REFRIGERATION & AIR CONDITIONING SERVICE P/O #:G116401 Receiving #:117308 Date :2012-11-21	421129
60 11/16/2012	377310 TM 31 A/C COMPRESSOR WITH 8PK	Creditor #:TRA061 TRANSIT REFRIGERATION & AIR CONDITIONING SERVICE P/O #:G115453 Receiving #:117159 Date :2012-11-16	420708
60 11/13/2012	377310 AIR CON REFRIDGERANT		419720
60 11/13/2012	377310 AIR CON REFRIDGERANT		419720
60 11/10/2012	377683 Air Cond - A/C pulley shattered	Repaired by 22c	416510
60 11/10/2012	377683 Air Cond - A/C pulley shattered	Repaired by 22c	416510
60 11/10/2012	377310 Air conditioner inoperative	Worked with 22c to find short in com cable. Run units up found right bank compressor is on its way out and will need to be replaced	416349
60 11/10/2012	377683 SCANIA ARTIC ALT PULLEY GROVED PLASTIC		416510
60 11/07/2012	379830 GLOBE STOP AND TAIL 24V 21/5W		418812
60 11/02/2012	379830 Heat & Demist - secure heater hose connection	Secured	418655
60 11/02/2012	379830 Elec & Light - Replace brake globe	Replaced	418655
60 11/02/2012	379830 Eng Cool - Clean radiator	Cleaned	418655
60 11/02/2012	379830 Brakes - Check brake pads	Removed NSR tyres and checked	418655
60 11/02/2012	379513	A Service & Bus Safety Inspection	418425
60 11/02/2012	379513	Tension ALL Wheel Nuts to OEM Specs	418425
60 11/02/2012	379513	A Service & Bus Safety Inspection	418425
60 11/01/2012	379670 Air Cond - Clean a/c filters	Cleaned	418425
60 10/31/2012	379127 Air Cond - AC belts worn	Replace belts	418060
60 10/31/2012	379127 FAN BELT AIR/CON ARTIC VEE BELT B43		418060
60 10/31/2012	379127 Air Cond - AC belts worn	Replace belts	418060
60 10/31/2012	379615 Eng Cool - Add coolant	Added 9 litres and checked for leak	418267
60 10/31/2012	372477 SAFETY VALVE - 1377964	Creditor #:SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G113886 Receiving #:116540 Date :2012-10-31	418267
60 10/27/2012	377962 Security - Test and repair security camera system		416349
60 10/26/2012	374195 Side wall damage - Scrap	Creditor #:BEA001 BEAUREPAIRES P/O #:G114443 Receiving #:116263 Date :2012-10-26	417341
60 10/26/2012	374195 Side wall damage - Scrap	Creditor #:BEA001 BEAUREPAIRES P/O #:G114443 Receiving #:116274 Date :2012-10-26	417341
60 10/26/2012	372477 LINK SHORT	Creditor #:SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G113386 Receiving #:116221 Date :2012-10-26	417548
60 10/25/2012	378458 Elec & Light - Replace light & diffuser	Replaced	417341
60 10/24/2012	377277 Security - Test and repair security camera system	Repaired	416349
60 10/23/2012	377962 Direct Purchase - ELECTRICAL	Creditor #:LON001 LONSDALE ST ELECTRICS P/O #:G115560 Receiving #:116075 Date :2012-10-23	416929
60 10/19/2012	377683 Air Cond - A/C pulley shattered	Checked a/c - has been reported	416510
60 10/19/2012	377310 SPIGOT FEMALE 1 1/8" #20 MRS42	Creditor #:AIR002 COACHAIR P/O #:G115374 Receiving #:115869 Date :2012-10-19	416349
60 10/19/2012	377310 FLANGE SPIG MALE SINGLE - LARG	Creditor #:AIR002 COACHAIR P/O #:G115374 Receiving #:115869 Date :2012-10-19	416349
60 10/19/2012	377310 GASKET 41 30 IMM FOR SPIGOT MR	Creditor #:AIR002 COACHAIR P/O #:G115374 Receiving #:115869 Date :2012-10-19	416349

60 10/19/2012	377310 FREIGHT	Creditor #:AIR002 COACHAIR P/O #:G115374 Receiving #:115869 Date :2012-10-19	416349
60 10/19/2012	377277 Test and repair security syste	Creditor #:LON001 LONSDALE ST ELECTRICS P/O #:G115360 Receiving #:115895 Date :2012-10-19	416349
60 10/18/2012	377310 Air conditioner inoperative	Remove siezed clutch and bearing parts ordered	416349
60 10/16/2012	377007 Air Cond - Clean a/c filters	Cleaned	416349
60 10/16/2012	377007 Passenger Doors - Adjust passenger door	Adjusted	416349
60 10/04/2012	375409 Elec & Light - Replace emer exit light globe	Replaced	415206
60 09/26/2012	374195 Whls & Tyres - Scrap tyre - sidewall damage	Scrapped reject	414042
60 09/25/2012	373989 GLOBE FESTOON 24V5W		413835
60 09/25/2012	373989 AMBER REFLECTOR		413835
60 09/24/2012	373703 GLOBE S/CONTACT 24V-10W		413731
60 09/24/2012	373703 GLOBE STOP AND TAIL 24V 21/5W		413731
60 09/24/2012	373989 Elec & Light - Replace reflector & NSR clearance light globe	Replaced	413835
60 09/22/2012	373742 Elec & Light - Bus wont start	Jump started	413731
60 09/21/2012	373703 Elec & Light - Replace globes	Replaced tail & bus stopping globes	413731
60 09/21/2012	373693 Eng Cool - Clean radiator	cleaned	413731
60 09/21/2012	373551	A Service & Bus Safety Inspection	413602
60 09/21/2012	373551	Tension ALL Wheel Nuts to OEM Specs	413602
60 09/21/2012	373551	A Service & Bus Safety Inspection	413602
60 09/20/2012	369002 ROAD SAFETY INSPECTIONS	Creditor #:ROA001 Road Safety Inspections P/O #:G113716 Receiving #:114522 Date :2012-09-20	413397
60 09/19/2012	372799 Steering - Steering wheel cover loose	chaeck ok.	411628
60 09/19/2012	373184 Engine oil leaks on engine side cover	steam clean and chaeck oil leak ok	413132
60 09/19/2012	372799 Elec & Light - Indicator not self cancelling	chaeck ok.	411628
60 09/19/2012	372477 Air System High Air Pressure	clean air compressor regulator valuefix air leak from regulator air line road test bus ok.	413132
60 09/18/2012	372477 Air System High Air Pressure	Assemble air dryer and fitted to bus still unloader valve n/w	413132
60 09/17/2012	372477 HALDEX COIL KIT OIL SEPARATOR		413132
60 09/17/2012	372477 AIR DRYER VALVE BLOCK (BLACK B		413132
60 09/16/2012	369002 Annual Licence	Creditor #:MUL001 MULTISPARES LTD P/O #:G113890 Receiving #:114321 Date :2012-09-17	411628
60 09/14/2012	372477 CYCLONE CONDENSER VALVE KIT	- RWC 608687 Passed	413132
60 09/14/2012	372477 Air System High Air Pressure		413132
60 09/14/2012	372477 FILTER AIR DRYER KIT(HALDEX)	Checked and ordered safety valve at air compressor rekit air water seperator change air dryer unloader valve air dryer canister assy still air pressure not unloading danmaged air dryer need to remove c/o	413132
60 09/13/2012	372317 SCANIA ALT BELT TENSIONER K1241B		413036
60 09/12/2012	370111 1368087 WASHER	Creditor #:SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G112935 Receiving #:114135 Date :2012-09-12	412908
60 09/12/2012	372317 Air Cond - Replace twin a/c motor belt tensioner	Replaced	413036
60 09/04/2012	370114 Elec & Light Battery Flat - intermittent non starting	Jump started master switch solenoid OK	411805
60 08/31/2012	370114 Elec & Light Battery Flat - intermittent non starting	Ass Matt	411805
60 08/31/2012	370114 Elec & Light Battery Flat - intermittent non starting	Starting fault	411805
60 08/31/2012	370277 PLASTIC TOP DOOR ROLLER		411805
60 08/31/2012	370277 PLASTIC TRIANGLE HANDSTRAP GREY		411805
60 08/31/2012	370277 PLASTIC SEAT NAME ID		411805
60 08/31/2012	370277 HINGE DRIVERS COMPARTMENT		411805
60 08/30/2012	370114 Elec & Light Battery Flat - intermittent non starting	continued tracing wires. removed air filter to access a junction box. problem not there. put air filter back in. checked wiring from rear to computer plug. couldn't fault. put everything back together jumpstarted bus and had driver turn bus to jack knife and check starting. worked ok.	411805
60 08/30/2012	370114 Elec & Light Battery Flat - intermittent non starting	Ass Matt	411805
60 08/30/2012	370277 Body & Acc - RHR grab handle strap loose	Replaced	411805
60 08/30/2012	370277 Body & Acc - RHR grab handle strap loose	Replaced	411805
60 08/30/2012	370277 Body & Acc - Drivers compartment door hinges - replace stri	Hinges rotated striker pin	411805
60 08/30/2012	370277 Body & Acc - Drivers seat - replace recliner knob	Checked OK	411805
60 08/30/2012	370277 Body & Acc - Drivers seat - replace recliner knob	Replaced lumbar support valve & secure correctly	411805
60 08/30/2012	370277 Body & Acc - Drivers compartment door hinges - replace stri	Hinges rotated striker pin	411805
60 08/30/2012	370277 Body & Acc - Drivers seat adjuster handle missing	Checked OK	411805
60 08/30/2012	370635 Body & Acc - Replace emergency exit decals with safety hamm	Replaced	411805
60 08/30/2012	370635 Body & Acc - Adjust front doors - fit top rollers	Adjusted	411805
60 08/30/2012	370635 Body & Acc - secure all lower skirt panels	Secured	411805
60 08/30/2012	370635 Body & Acc - Replace emergency exit push button under b/bar	Replaced	411805
60 08/30/2012	370635 Body & Acc - adjust rear door - Replace top rollers & secur	Adjusted	411805
60 08/30/2012	370635 Body & Acc - Clean air condition filter secure vents	Cleaned	411805
60 08/30/2012	370635 Body & Acc - Passenger seats & hand grips - repair rear	Repaired	411805
60 08/30/2012	370635 Body & Acc - Hand rails secure - OS handrail to roof	Secured	411805
60 08/30/2012	370635 Body & Acc - front step edges - fit inserts	Fitted	411805
60 08/30/2012	370635 Body & Acc - Drivers foot rest - replace checker plate	Replaced	411805
60 08/30/2012	370635 Body & Acc - Paint till stand	Painted	411805
60 08/30/2012	370635 Body & Acc - Mid door brush loose	Secured	411805
60 08/30/2012	370277 Body & Acc - Drivers seat - replace recliner knob	Checked OK	411805
60 08/30/2012	370277 Body & Acc - RHR grab handle strap loose	Replaced	411805
60 08/30/2012	370277 Body & Acc - Need to refit seat lumber support buttons	Checked OK	411805
60 08/30/2012	370277 Body & Acc - Drivers seat adjuster handle missing	Replaced	411805
60 08/30/2012	370277 Body & Acc - Drivers seat adjuster handle missing	Checked OK	411805
60 08/30/2012	370277 Body & Acc - Need to refit seat lumber support buttons	Checked OK	411805
60 08/30/2012	370277 Body & Acc - Need to refit seat lumber support buttons	Refitted	411805
60 08/29/2012	369939 UNEVENWORN - POS 12 - 275/70	Creditor #:BEA001 BEAUREPAIRIES P/O #:G112973 Receiving #:113481 Date :2012-08-29 REPLACE WITH NEW	411805
60 08/29/2012	370111 Suspension - Front sway bar D bushes worn	Replaced	411805
60 08/29/2012	370111 40y3448 d rubber	Creditor #:MUL001 MULTISPARES LTD P/O #:G113020 Receiving #:113486 Date :2012-08-29	411805
60 08/29/2012	370111 40m1303 steering wheel	Creditor #:MUL001 MULTISPARES LTD P/O #:G113020 Receiving #:113487 Date :2012-08-29	411805
60 08/29/2012	370111 Suspension - Mid axle sway bar D bushes worn	Replaced	411805
60 08/29/2012	370111 40y3408 d rubber	Creditor #:MUL001 MULTISPARES LTD P/O #:G113020 Receiving #:113486 Date :2012-08-29	411805
60 08/29/2012	370111 Drv entered - Air Cond Cooling Fault Light	Coolant leaking at header tank pipe corrected bus OK	411805
60 08/29/2012	370114 Elec & Light Battery Flat - intermittent non starting	found split coolant hose ordered new hose. inspected air compressor for relief valve looks ok. jumpstarted bus and checked starting fault has gone away but will continue to check wiring in engine bay.	411805
60 08/29/2012	370114 Elec & Light Battery Flat - intermittent non starting	Ass Matt	411805
60 08/28/2012	369870 FILTER AIR DRYER KIT(HALDEX)		411805
60 08/28/2012	369869	Adjust valve clearances	411645
60 08/28/2012	369939 Whls & Tyres - Replace tyre pos 12 - uneven worn	Replaced	411805
60 08/28/2012	370111 Suspension - Front sway bar D bushes worn	Replaced	411805
60 08/28/2012	370213 Engine - steamclean chassis & engine	S/cleaned engine	411805
60 08/28/2012	369992 GLOBE FESTOON 24V5W		411805
60 08/28/2012	370114 Elec & Light Battery Flat - intermittent non starting	continued with tracing fault.	411805
60 08/27/2012	369869	Clean a/c filters	411645
60 08/27/2012	369870	Replace fuel filters	411645
60 08/27/2012	369870	Replace final drive oil	411645
60 08/27/2012	369870	Adjust valve clearances	411645
60 08/27/2012	369870	Replace power steering filter	411645
60 08/27/2012	369870	Rekit quick release valve	411645
60 08/27/2012	369870	Replace hydraulic fan filter and top up oil	411645
60 08/27/2012	369870	Replace air dryer canister	411645
60 08/27/2012	369870	Clean a/c filters	411645
60 08/27/2012	369870	Remove intercooler wash intercooler and raditor	411645
60 08/27/2012	369869 POWER STEERING FILTER VOLVO		411645

60 08/27/2012	369869 FUEL FILTER ELEMENT SCANIA L94UAB (R90T / H7090WK10)		411645
60 08/27/2012	369869 FILTER FUEL K124 / LU94A (1411894 / H17WK05)		411645
60 08/27/2012	369869 FILTER K124EB HYD COOLING FAN		411645
60 08/27/2012	369869	Remove intercooler wash intercooler and raditor	411645
60 08/27/2012	369869 Service		411645
60 08/27/2012	369869	Replace fuel filters	411645
60 08/27/2012	369869	Replace final drive oil	411645
60 08/27/2012	369869	Inspect bus as per inspection sheet	411645
60 08/27/2012	369869	Replace power steering filter	411645
60 08/27/2012	369869	Replace hydraulic fan filter and top up oil	411645
60 08/27/2012	369869	Replace air dryer canister	411645
60 08/27/2012	369869 RPM BORATE EP LUBE 220		411645
60 08/27/2012	369869	Inspect vehicle as per RSI Checklist	411645
60 08/26/2012	370014 Elec & Light - Bus wont start	Jump started	411645
60 08/24/2012	368676 Elec & Light - check hard starting	checked starting, starting ok. put steering wheel covers back and let bus go.	411628
60 08/24/2012	369992 Elec & Light - Replace NS clearance light globe	Replaced	411645
60 08/24/2012	370004 Body & Acc - Remove overspray from door button area	Removed	411645
60 08/24/2012	369309 SCREW TORX 8 X 20MM SIDE PANEL		411628
60 08/24/2012	369309 SCREW TORX 8 X 15MM SIDE PANEL		411628
60 08/23/2012	368676 Elec & Light - check hard starting	starting ok from rear	411628
60 08/23/2012	368676 BUSH KIT SUIT JF		411628
60 08/23/2012	368676 STARTER SOLENOID SUIT JF		411628
60 08/23/2012	368676 STARTER DRIVE SUIT JF		411628
60 08/23/2012	368676 Elec & Light - check hard starting	Ass with starter	411628
60 08/23/2012	369309 Body & Acc - Paint wheels (Checked on 07/03/1214/04/1224	Painted	411628
60 08/23/2012	369309 Accident Damaged #35934 Repair rear bumper-bar engine exh	Refitted rear b/bar and repaired tip of the silencer end	411628
60 08/23/2012	369309 UNREPORTED - repair front b/bar repair NS & OS corner	Paint completed fitted rego plate & replaced decals	411628
60 08/22/2012	368676 Elec & Light - check hard starting	REBUILT S/MOTOR AND FIT TO BUS. ATTEMPTED STARTING PROBLEM FROM FRONT need wiring diagram. CARRY OVER.	411628
60 08/22/2012	368676 Elec & Light - check hard starting	Ass Bradman with checking starting circuit c/o	411628
60 08/22/2012	369088 HINGE DRIVERS COMPARTMENT		411628
60 08/22/2012	369088 CENTRA SEAT END CAPS		411628
60 08/22/2012	369309 UNREPORTED - repair front b/bar repair NS & OS corner	Repairs cont sanded grey primed & painted final coat	411628
60 08/22/2012	369309 UNREPORTED - Damage to rear bar	Dismantle the rear bar repaired painted 2pac	411628
60 08/21/2012	369066 Annual Body Inspection	Inspected	411628
60 08/21/2012	368800 Mechanic entered - Elec & Light Other	CHECKED TEETH ON FLY WHEEL FOR DAMAGE. FIT S/MOTOR BACK AND STARTED. took longer due to losing parts and searching for them.	411628
60 08/21/2012	369088 Body & Acc - Polish exterior panels/headers & touch up pain	Polished	411628
60 08/21/2012	369088 Body & Acc - Front of concertina inside needs rectifying ru	Checked OK	411628
60 08/21/2012	369088 Body & Acc - Secure drivers compartment door hinges (Check	Replaced hinge & secured	411628
60 08/21/2012	369088 Body & Acc - Fit end caps to seats as req (Checked on 07/0	Fitted	411628
60 08/21/2012	369088 Body & Acc - Paint exterior mirrors and arms (Checked on07	Painted	411628
60 08/21/2012	369088 Body & Acc - Paint till stand (Checked on 07/03/1214/04/1	Painted	411628
60 08/21/2012	369088 Body & Acc - secure all lower skirt panels (Checked on 07/	Secured	411628
60 08/21/2012	369309 UNREPORTED - repair front b/bar repair NS & OS corner	Started repairs	411628
60 08/20/2012	368800 Mechanic entered - Elec & Light Other starter motor	removed starter motor in preparation of checking ring gear.	411628
60 08/17/2012	368676 Elec & Light - check hard starting	Went to KSB and bought bus back	411628
60 08/16/2012	368658 Ops Entered - Fault - Engine Won't Start - Route: - Take	Went to KSB depot and checked not engage starter motor pinion and ring gear turn engine & started bus	411628
60 08/02/2012	366479 GLOBE FESTOON 24V-3W		409367
60 08/01/2012	366479 Elec & Light - Replace NSr exit light globe	Replaced	409367
60 07/31/2012	362320 Elec & Light Battery Flat	checked wiring at ignition, looks ok. tried to start bus it started. tested multiple times started all times. put bus back together.	409270
60 07/30/2012	365267 HOSE TURBO	Creditor #:SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G111444 Receiving #:112037 Date :2012-07-30	409270
60 07/30/2012	362320 Elec & Light Battery Flat	used computer attempted to diagnose wasn't successful. began checking wiring at rear of bus working ok. began pulling aprt turntable to check continuity between front and rear.	409270
60 07/26/2012	365267 Engine Lacking Power	Found clamp for intercooler pipe fitted	409270
60 07/25/2012	365267 Engine Lacking Power	Started to check turbo someone left boost pipes off cleaned oil in pipes checked turbo started to put pipes back on replaced a/c belts	409270
60 07/25/2012	365267 Direct Purchase - MECHANICAL		409270
60 07/25/2012	362320 Elec & Light Jack light on	Removed floor to access accumalator connected pump and pressurised to spec	409270
60 07/25/2012	362320 Elec & Light Battery Flat	Checked not starting c/o	409270
60 07/17/2012	364280 Drv entered - Trntable Wrning Light	corected	408603
60 07/17/2012	364165	A Service & Bus Safety Inspection	408438
60 07/17/2012	364165	Tension ALL Wheel Nuts to OEM Specs	408438
60 07/17/2012	364165	A Service & Bus Safety Inspection	408438
60 07/05/2012	362393 Mechanic entered - Elec & Light Battery Flat	jumpstarted bus	407101
60 07/05/2012	362850 Elec & Light - Replace interior light globe	Replaced	407189
60 07/04/2012	362081 Whls & Tyres Replace worn tyres pos. 9. 10.		406982
60 07/04/2012	362214 GLOBE S/CONTACT 24V-10W		406982
60 07/04/2012	362320 Elec & Light Jack light on	Check with SD2 programe is not working need to check turntable pressure switch and wire conector	407101
60 07/03/2012	362210 Whls & Tyres Replace tyres pos.9.10	Replaced	406982
60 07/03/2012	362214 Elec & Light clearence O/S/rear U/S	Replace globe	406982
60 07/01/2012	361820 Elec & Light - Bus wont start	Jump started	406653
60 06/25/2012	360772 HEAD LIGHT GLOBE 24V 70/75W		405646
60 06/22/2012	360772 Elec & Light - Replace headlight globe	Replaced	405646
60 06/19/2012	359980 GLOBE FESTOON 24V5W		404911
60 06/18/2012	354023 Elec & Light - Jack knife light on	TEMP FIX WHEEL CHAIR RAMP STRIP FIX SENSOR CONTACT WITH 3mm ALUMINIUM PIECE.	403359
60 06/18/2012	359980 Elec & Light - Replace clearance light globe	Replaced	404911
60 06/15/2012	359428 Suspension - Continually going down and touching ground	change o/s front air bag	404742
60 06/15/2012	359428 FRONT AIR BAG SCANIA L94UAB		404742
60 06/15/2012	359428 Drv entered - Suspension Noisy	chaeck all shokabsober lavalng value and front suspenssion and road test bus ok. jakenief light on chaeck whell speed senser ok need to chaeck accumilator pressure	404742
60 06/15/2012	359428 Ops Entered - Fault - Steering - Route: - Take a Artic bus	chaek ok	404742
60 06/15/2012	354023 Elec & Light Bus want start - Ignition switch U/S - Ordered	checked starting at front and back OK. changed interior fluro light ok.	404742
60 06/15/2012	354023 Elec & Light - Interior tube light out	checked OK	404742
60 06/15/2012	354023 Drv entered - Elec & Light Other	Checked OK	404742
60 06/15/2012	359428 Eng Cool Water pump leaks	check ok	404742
60 06/14/2012	358831 LOW TREAD - POS 8 - 275/70 R22	Creditor #:BEA001 BEAUREPAIRES P/O #:K109470 Receiving #:109922 Date :2012-06-14 REPLACE WITH RECAP	404742
60 06/13/2012	358831 Whls & Tyres - Replace tyre pos 8 - low tread	Replaced	404113
60 06/08/2012	358827 Whls & Tyres - Replace tyre pos 78	Replaced	404113
60 06/07/2012	353926 Replace a/c compressor	Creditor #:CEL001 22 CELSIUS P/O #:G108972 Receiving #:109628 Date :2012-06-07	403666
60 06/06/2012	358103 SCANIA K230 BELT		403666
60 06/06/2012	358621 Body & Acc - Refit w/arch brush	Refitted	403666
60 06/05/2012	353926 FUSE GLASS 10AMP		403515
60 06/05/2012	353926 VOLVO H/LIGHT RELAY DIODE PROTECTED		403515
60 06/05/2012	353926 FUSE HOLDER HEAVY DUTY		403515
60 06/01/2012	354023 Elec & Light - Bus wont start at front	Checked OK	403359
60 05/31/2012	357179 PUMP WIPER-WASHER 24 VOLT		403259
60 05/31/2012	354023 Elec & Light - Intermittent engine start from front	Checked OK	403359
60 05/31/2012	354023 Elec & Light - Jack knife indicator stays on dash	Pulled up floor & checked pressure in t/table OK light still on fault is in wiring bus going on road	403359
60 05/31/2012	354023 Elec & Light - Horn pad falling off	Replaced horn pad	403359

60 05/30/2012	354023 1370248 horn button pad centre	Creditor #::SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G108905 Receiving #:109206 Date :2012-05-30	403079
60 05/29/2012	357179 Wipers & Washers - Wiper washer n/w	Replaced washer motor	403079
60 05/29/2012	350811 SCANIA DIP STICK L94UAB	Creditor #::SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G106969 Receiving #:109126 Date :2012-05-29	403079
60 05/29/2012	354023 Elec & Light - Horn pad falling off	ordered new horn awaiting parts. chcked starting circuit everything tested ok replaced fuses	402980
60 05/29/2012	345814 WEAR SENSOR SCANIA DISC BRAKE		393446
60 05/28/2012	356918 Elec & Light - Bus wont start	Jump started	402980
60 05/25/2012	356391 GLOBE FESTOON 24V5W		402685
60 05/25/2012	356391 Elec & Light park out	Replace globe	402685
60 05/25/2012	356391 GLOBE INST 24V 2W		402685
60 05/24/2012	356272 FILTER OIL K124 / L94UAB (H200W02)		402685
60 05/24/2012	356272 FILTER TRANSMISSION ZF 4139-298-038E39HD119		402685
60 05/24/2012	356272 O RING FILTER KIT K93		402685
60 05/24/2012	356272 FILTER AIR SCANIA USE AF25066		402685
60 05/24/2012	356272 ENGINE OIL DELO 400LE 15W40		402685
60 05/24/2012	356272 TEXAMATIC 1888		402685
60 05/24/2012	356272	D Service & Bus Safety Inspection	402685
60 05/24/2012	356272	Tension ALL Wheel Nuts to OEM Specs	402685
60 05/24/2012	356272	A Service & Bus Safety Inspection	402685
60 05/24/2012	356272	Tension ALL Wheel Nuts to OEM Specs	402685
60 05/24/2012	356272	A Service & Bus Safety Inspection	402685
60 05/23/2012	352306 HIGH PRESSURE SWITCH		402340
60 05/23/2012	352306 FILTER DRIER 5/8		402340
60 05/21/2012	355742 HEAD LIGHT GLOBE 24V 70/75W		402035
60 05/18/2012	355742 Elec & LightReplace N/S head light globe	Changed	402035
60 05/15/2012	353926 24 VOLT RELAY PANEL	Creditor #::AIR002 COACHAIR P/O #:G107864 Receiving #:108462 Date :2012-05-15 bus 60	401180
60 05/15/2012	353926 COMPUTER SLRT/RM-RP	Creditor #::AIR002 COACHAIR P/O #:G107864 Receiving #:108462 Date :2012-05-15	401180
60 05/15/2012	353926 Data Cable 20 Pin Plug	Creditor #::AIR002 COACHAIR P/O #:G107864 Receiving #:108462 Date :2012-05-15	401180
60 05/15/2012	354122 GLOBE FESTOON 24V5W		401180
60 05/10/2012	352306 Repair	Creditor #::CEL001 22 CELSIUS P/O #:G107936 Receiving #:108273 Date :2012-05-10	400731
60 05/08/2012	353926 Air Cond - comp. brg. failure	22 celsius	400176
60 05/08/2012	353881 Elec & Light - check starting problem	Fixed	400176
60 05/08/2012	353881 STARTER SWITCH	Creditor #::SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G107754 Receiving #:108186 Date :2012-05-08 bus 60	400310
60 05/08/2012	354313 Breakdown Chedstone sh. centre - No lights - C/O bus 140 -	Matt fixed	400310
60 05/07/2012	354023 Elec & Light Bus want start - Ignition switch U/S - Ordered		400176
60 05/06/2012	354122 Elec & Light N/S rear clearance light U/S	replace globe	400030
60 05/04/2012	358103 Engine - Replace drive belt	Replaced	400030
60 05/03/2012	353387 Engine - Replace belts	Replaced alt drive twin a/c motor drive & main a/c drive belts	400030
60 04/30/2012	352306 ESP209	Creditor #::AIR002 COACHAIR P/O #:G107459 Receiving #:108262 Date :2012-05-10	400731
60 04/30/2012	352306 FREIGHT	Creditor #::AIR002 COACHAIR P/O #:G107459 Receiving #:108262 Date :2012-05-10	400731
60 04/30/2012	352306	C Service	399962
60 04/30/2012	352306 90LTR BOOST PUMP COACH	Creditor #::ACT001 ACTROL P/O #:G107380 Receiving #:107767 Date :2012-04-30	399962
60 04/30/2012	352306 5/8FLARE DRIER	Creditor #::ACT001 ACTROL P/O #:G107380 Receiving #:107767 Date :2012-04-30 germ spray	399962
60 04/30/2012	352306 desanitizer	CONDENSOR AREA: Clean condensor coils; check boltsclamps for tension	399962
60 04/30/2012	352306	Clean R/A & F/A filters; inspect and report on condition; Replace filter media	399962
60 04/30/2012	352306	FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)	399962
60 04/30/2012	352306	COMPRESSOR DRIVE BELTS: Inspect belt wear; Retension belts;	399962
60 04/30/2012	352306	DRIVE PULLEY'S: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;	399962
60 04/30/2012	352306	DRIVE PULLEY'S: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear	399962
60 04/30/2012	352306	COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose	399962
60 04/30/2012	352306	REFRIGERATION FILTER DRYER: Replace filter dryer; check pump operation;	399962
60 04/30/2012	352306	EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check boltsclamps & fittings; clean condensate drains; clean drip tray	399962
60 04/30/2012	352306	INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condensor fan grills	399962
60 04/30/2012	352306	UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensor pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation	399962
60 04/27/2012	352552 Heat & Demist - Heater boost pump	Changed & filled coolant	400030
60 04/24/2012	351868 GLOBE FESTOON 24V5W		399543
60 04/24/2012	352101 Elec & Light - Replace emergency exit globe	Replaced	399962
60 04/23/2012	351771 Elec & Light - Bus wont start	Jump started at KSB	399543
60 04/23/2012	351803 Elec & Light - Cannot start from drivers cab starts OK from	Moved switch to correct position in rear	399543
60 04/23/2012	351497 GLOBE FESTOON 24V5W		399387
60 04/23/2012	351624 INDICATOR LIGHT FRONT ARTIC		399387
60 04/23/2012	351624 GLOBE INDICATOR 24V-18W SINGLE CONTACT		399387
60 04/23/2012	351868 Elec & Light - Replace OS middle clearance light globe	Replaced	399543
60 04/20/2012	351624 Elec & Light - Replace whole NS indicator bracket assembly	Replaced	399387
60 04/19/2012	351497 Elec & Light - Replace NSR clearance light globe	Replaced	399185
60 04/18/2012	350811 Engine - dipstick missing	Checked OK	398610
60 04/18/2012	350811 Mechanic entered - Elec & Light Headlights O/S head light d	Replaced	398610
60 04/18/2012	350811 Elec & Light - Alternator belt is missing	Replaced	398610
60 04/18/2012	350811 Brakes - Drive axle brake pad only 5mm	Changed both drive axle pads right side pad wear sensor wire	398610
60 04/18/2012	350811 DIRECT BRAKES		398610
60 04/15/2012	350633 Elec & Light - Bus wont start with key	Checked OK started with key	398336
60 04/14/2012	350591 Engine - Oil dip stick missing	Took from 102	398336
60 04/14/2012	350591 Elec & Light - OSF corner indicator lens is cracked	Replaced OS headlight assy	398336
60 04/14/2012	350401	Tension ALL Wheel Nuts to OEM Specs	398233
60 04/14/2012	350401	A Service & Bus Safety Inspection	398233
60 04/14/2012	350401		398233
60 04/14/2012	350401 HEADLAMP HI-LOW RECTANGULAR MK3 B10M		398233
60 04/13/2012	350343 GLOBE FESTOON 24V5W		398033
60 04/12/2012	350343 Elec & Light - Interior tube light out	Replaced	398033
60 04/10/2012	349651 Elec & Light check batteries	Ordered ignition switch changed OK	397605
60 04/10/2012	349651 Elec & Light check batteries	Went to KSB & jump started bus	397605
60 04/10/2012	349651 STARTER LOCK SUIT SCANIA L94U	Creditor #::SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G106581 Receiving #:107075 Date :2012-04-11	397798
60 03/31/2012	348962 Breakdown - Dandenong Station - OUT 2.00 pm BACK 3.00 pm -	Van 619. Jump started	396872
60 03/29/2012	348671 Air Cond - A/C belt needs replacing	Checked belts found 1 compressor bearing faulty	396410
60 03/13/2012	346235 Elec & Light - Replace os top interior light	Replaced	393663
60 03/13/2012	345814 DIRECT BRAKES		393446
60 03/09/2012	343577 BALD - New - Pos 1	Creditor #::BEA001 BEAUREPAIRES P/O #:G104776 Receiving #:105877 Date :2012-03-09 Replace with new - Fitting and balance	393250
60 03/07/2012	345377 Random Vehicle Audit		393191
60 03/07/2012	345814 Brakes - Replace front brake pads	Replaced	393199
60 03/07/2012	345814 Brakes - Replace front brake pads	Replaced	393199
60 03/07/2012	345371	A Service & Bus Safety Inspection	393191
60 03/07/2012	345371	Tension ALL Wheel Nuts to OEM Specs	393191
60 03/07/2012	345371	A Service & Bus Safety Inspection	393191
60 03/06/2012	345034 FAN BELT AIR/CON ARTIC VEE BELT B43		393191
60 03/06/2012	345077 Eng Cool - Add coolant	Added	393191

60 03/05/2012	345034 Air Cond - a/c belt missing	Fitted new belts	393191
60 02/29/2012	344052 BUSH KIT SUIT JF		392483
60 02/29/2012	344052 STARTER SOLENOID SUIT JF		392483
60 02/29/2012	344052 STARTER DRIVE SUIT JF		392483
60 02/28/2012	343391 BUSH KIT SUIT JF		392311
60 02/28/2012	344052 Elec & Light - Starter motor	Rebuild completed	392483
60 02/27/2012	343391 Completed		
60 02/27/2012	343577 Whls & Tyres - Replace tyre pos 1 - bald worn uneven tread	Replaced	392070
60 02/24/2012	343391 S/motor rebuild waiting on parts		
60 02/24/2012	343615 Whls & Tyres - Replace tyre pos 1	R/tested for noisy tyre	392070
60 02/24/2012	343615 Whls & Tyres - Replace tyre pos 1	Replaced & r/tested	392070
60 02/23/2012	343391 Began s/motor rebuild		
60 02/23/2012	343480 Wipers & Washers - Clean out wiper tubes	Cleaned out	391943
60 02/23/2012	343386 Elec & Light - C/O starter motor	Replaced	391943
60 02/13/2012	339263 A/C POST BUSH	Creditor #:PLA001 PLASTIC FOR INDUSTRY P/O #:G103322 Receiving #:105238 Date :2012-02-23 60	391843
60 02/13/2012	341734 Elec & Light - Replace interior light & cover	Replaced	390444
60 02/03/2012	340289 GLOBE FESTOON 24V-3W		389062
60 02/02/2012	340289 Elec & Light - Replace emergency exit light globe	Replaced	389062
60 01/28/2012	339491 Elec & Light - Bus wont start	Jump started	388492
60 01/27/2012	339416 Suspension - Check suspension	Checked OK	388492
60 01/27/2012	338539 FAN BELT A/CON ARTIC 21/32X45		388391
60 01/27/2012	339162 Air Cond - A/c twins compressor bracket cracked	replaced - refer W/O 338 539	388391
60 01/27/2012	339162 Air Cond - A/C compressor bracket plate pivot worn	replaced - refer W/O 338 539	388391
60 01/26/2012	339263 Air Cond - Check a/c post	R/tested for Neven	388360
60 01/25/2012	339263 Air Cond - Check a/c post	Make up a/c post bushes and fitted in bus and fit belts	388360
60 01/24/2012	338539 BELT ALT W/PUMP CRANK SCANIA ARTIC		388360
60 01/24/2012	338539 BEARING ROSTA PULLEY SCANIA ARTIC		388360
60 01/23/2012	338539 Air Cond - A/C post bush worn	Removed belts and bracket fitted new bracket a/c compressor fitted new idler bearing and fitted belts jump started	388360
60 01/23/2012	338539 FAN BELT AIR/CON ARTIC VEE BELT B43		388360
60 01/20/2012	338539 Air Cond - AC belts starting to get cracks	Fitted belts	388360
60 01/20/2012	338539 Air Cond - A/C post bush worn	Removed a/c post	388360
60 01/20/2012	338300 FAN BELT AIR/CON ARTIC VEE BELT B43		388360
60 01/19/2012	338300 Air Cond - Replace a/c belts	Replaced belts	388360
60 01/15/2012	336660	Tension ALL Wheel Nuts to OEM Specs	387658
60 01/15/2012	336660	A Service & Bus Safety Inspection	387658
60 01/15/2012	336660	Done at Roadworthy inspection – Doc 071158	387658
60 01/14/2012	337550 Eng Cool - Check for coolant leak	Moved bus	388219
60 01/14/2012	337550 Eng Cool - Check for coolant leak	R/tested checked for leak mopped floor fit back door brush fuelled & parked	388219
60 01/13/2012	337374 Eng Cool - Rectify coolant leak at ballows	Put back all the rubber beading & bolt in constatina	388219
60 01/13/2012	337374 Eng Cool - Rectify coolant leak at ballows	Put back all the rubber beading & bolt in constatina	388219
60 01/13/2012	337374 Eng Cool - Rectify coolant leak at ballows	Fit new hose connector inside bellows	388219
60 01/12/2012	337331 Elec & Light - Interior tube light loose	Put back into place	388219
60 01/11/2012	336972 Body & Acc - Drivers seat - secure lubricate replace	Repaired By trimshop	387858
60 01/11/2012	336972 Body & Acc - Secure replace seat frames or capsules - NS 4	Repaired By trimshop	387858
60 01/06/2012	329447 5/8FLARE DRIER		387222
60 01/06/2012	329447 AIR CON REFRIDGERANT		387222
60 01/03/2012	335873 Elec & Light - Replace emer exit light globe	Replaced	386881
60 12/29/2011	335063 POS 4 275/70 CAP FLAT	Creditor #-BEA001 BEAUREPAIRES P/O #:K102359 Receiving #:103207 Date :2011-12-29	386311
60 12/28/2011	335063 Whls & Tyres - Replace tyre pos 4 - flat	Replaced	386140
60 12/23/2011	334987 Whls & Tyres - Replace flat tyre 4	Sanded paint of wheel replaced tyre & tensioned w/nuts	386140
60 12/23/2011	334886 GLOBE FESTOON 24V5W		385958
60 12/23/2011	334992 Eng Cool - Add coolant	Added	386140
60 12/21/2011	334886 Elec & Light - Replace OS parker globe	Replaced	385802
60 12/15/2011	333838 Brakes - Rectify air leak at foot valve when apllied	Fit new foot brake valve r/tested OK	385325
60 12/15/2011	333838 40g0103 FOOT VALVE	Creditor #-MUL001 MULTISPARES LTD P/O #:G101844 Receiving #:102673 Date :2011-12-15 60	385325
60 12/14/2011	329447 nitrogen	Creditor #-ACT001 ACTROL P/O #:G101708 Receiving #:102583 Date :2011-12-14	385325
60 12/12/2011	333124 PUMP WIPER-WASHER 24 VOLT		385192
60 12/12/2011	329447 Air Cond - No 2 rear air con with red fault light	Removed and refill right bank evap coil locate blockage in left bank. Cut crushed pipe section out weld new section back in	385192
60 12/12/2011	329447 Body & Acc - Clean air condition filter secure vents	Cleaned	385192
60 12/08/2011	333124 Wipers & Washers - Windscreen washer n/w	Changed washer motor and cleaned bottle	385190
60 12/05/2011	332275 STOP LAMP LENS		384261
60 12/05/2011	332275 GLOBE S/CONTACT 24V-10W		384261
60 12/02/2011	332275 Elec & Light - Replace tail light globe	Replaced	384261
60 11/28/2011	331432 Elec & Light - OS clearance light n/w	Checked OK globe wasnt making proper contact	383356
60 11/24/2011	331003 Passenger Doors - Front door top mounting came off	Refitted	382832
60 11/23/2011	329447 TWIN COMP MOUNT BRACKET	Creditor #-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G100644 Receiving #:101665 Date :2011-11-23	382493
60 11/21/2011	330111 SCANIA L94UAB V STAY BUSH KIT		382081
60 11/21/2011	329447 AIR LUMBAR SWITCH COMPLETE L/H+R/H		382081
60 11/18/2011	323484	Replace hydraulic fan filter and top up oil	378154
60 11/18/2011	323484	Inspect bus as per inspection sheet	378154
60 11/18/2011	323484	Rekit quick release valve	378154
60 11/18/2011	330111 Vandalism - Clean graffiti - floor seats & side walls	Cleaned	382081
60 11/18/2011	330111 Suspension - V bar bush cracked	ass Neven to replace bush	382081
60 11/18/2011	330111 Suspension - V bar bush cracked	ass Neven to replace bush	382081
60 11/18/2011	330111 Suspension - V bar bush cracked	Replaced bush	382081
60 11/18/2011	329447 Body & Acc - Drivers seat - replace covers cushion squab	Replaced & air valve	382081
60 11/18/2011	329888	Tension ALL Wheel Nuts to OEM Specs	382008
60 11/18/2011	329888	D Service & Bus Safety Inspection	382008
60 11/18/2011	329888 TEXAMATIC 1888		382008
60 11/18/2011	329888 ENGINE OIL DELO 400LE 15W40		382008
60 11/18/2011	329888 AIR FILTER SCANIA CLEANED		382008
60 11/18/2011	329888 O RING FILTER KIT K93		382008
60 11/18/2011	329888 FILTER TRANSMISSION ZF 4139-298-038E39HD119		382008
60 11/18/2011	329888 FILTER OIL K124 / L94UAB (H200W02)		382008
60 11/18/2011	329888	Tension ALL Wheel Nuts to OEM Specs	382008
60 11/18/2011	329888	A Service & Bus Safety Inspection	382008
60 11/17/2011	323484	Remove intercooler wash intercooler and raditor	378154
60 11/17/2011	323484	Clean a/c filters	378154
60 11/17/2011	323484	Replace air dryer canister	378154
60 11/17/2011	323484	Replace power steering filter	378154
60 11/17/2011	323484	Replace fuel filters	378154
60 11/17/2011	323484	Replace final drive oil	378154
60 11/17/2011	323484 FILTER AIR DRYER KIT(HALDEX)		382008
60 11/17/2011	329879 Engine - Engine oil leaks (compressor area)	Compressor replaced	382008
60 11/16/2011	323484	Adjust valve clearances	378154

60 11/16/2011	329029 Air System - Slow to build up air	Replace trailer solenoid valve (suspension) replace compressor	382008
60 11/16/2011	329029 LEVEL CONTROL VALVE REPAIR KIT REAR		382008
60 11/16/2011	329029 40A9107 AIR COMP	Creditor #::MUL001 MULTISPARES LTD P/O #:G100596 Receiving #:101396 Date :2011-11-16	382008
60 11/15/2011	329029 Air System - Slow to build up air	Removed trailer airbag solenoid valve replaced solenoid still leaking c/o	382008
60 11/11/2011	318260 SCRAP	Creditor #::BEA001 BEAUREPAIRES P/O #:G98193 Receiving #:101194 Date :2011-11-11	382008
60 11/11/2011	329019 Eng Cool - Add coolant	Added	382008
60 11/11/2011	329029 Air System - Slow to build up air	Had to pick bus up from Moorabbin and return c/o job	382008
60 11/11/2011	328900 Low air at Moorabbin stn	Travel to bus. Check all air pipes ok. Rev high to build air. Return with bus to depot. Found various air leaks.	382008
60 11/10/2011	328848 Air System - Check for air build up	Checked for air build up	382008
60 11/07/2011	327675 Eng Cool - water pump leaking	Checked water pump OK Changed thermostat & r/tested checked air compressor governor air line	381846
60 11/07/2011	327917 LEVEL CONTROL VALVE KIT FRONT		381923
60 11/07/2011	327917 SCANIA UNLOADER VALVE HALDEX		381923
60 11/04/2011	327917 Suspension - Overhaul tag axle airbags solenoid levelling v	Overhauled	381923
60 11/04/2011	327675 WATER PUMP SCANIA L94UAB	Creditor #::MUL001 MULTISPARES LTD P/O #:G99083 Receiving #:100919 Date :2011-11-04 60	381846
60 11/04/2011	327917 Air System - Replace air dryer regulator valve	Replaced	381923
60 11/03/2011	327268 POS 8 275/70 CAP	Creditor #::BEA001 BEAUREPAIRES P/O #:K99989 Receiving #:100849 Date :2011-11-03	381846
60 11/03/2011	327666 Suspension - Check front levelling valve	Checked SD 2 wire connection cleaned and fixed cleared all fault codes r/tested bus OK	381846
60 11/02/2011	327268 Whls & Tyres - Replace tyre pos 8 - side wall burst	Replaced	381430
60 11/01/2011	327262 Whls & Tyres - Check pos 8 NSR tyre low pressure	Changed tyre	381430
60 10/27/2011	326577 AMBER REFLECTOR SIDE MOUNT		380925
60 10/26/2011	326577 Elec & Light - Replace side reflector	Replaced	380925
60 10/26/2011	326581 Brakes - Check for air leak on brakes	R/tested to check	380925
60 10/25/2011	326144 Body & Acc - Middle door back panel came off	ref to w/o # 326127	380491
60 10/21/2011	326127 Body & Acc - Refit middle door brush	Refitted	380256
60 10/20/2011	323707 ROAD SAFETY INSPECTIONS	Creditor #::ROA001 Road Safety Inspections P/O #:G98954 Receiving #:100214 Date :2011-10-20	379891
60 10/16/2011	323707 Annual Licence	- RWC 804044 - Passed	378206
60 10/12/2011	324466 Wipers & Washers - Top up wiper/washer water	Topped up	378738
60 10/10/2011	324246 Body & Acc - Secure door brush screws	Tightened all door brushes & hinges	378421
60 10/08/2011	323484 Service		378154
60 10/08/2011	323484 RPM BORATE EP LUBE 220		378154
60 10/08/2011	323484 FILTER FUEL K124 / LU94A (1411894 / H17WK05)		378154
60 10/08/2011	323484 FUEL FILTER ELEMENT SCANIA L94UAB (R90T / H7090WK10)		378154
60 10/08/2011	323484 POWER STEERING FILTER VOLVO		378154
60 10/08/2011	323484	Inspect vehicle as per RSI Checklist	378154
60 10/08/2011	323829 Engine - Steamclean bus	Cleaned	378206
60 10/07/2011	323546 Air System - takes a very long time to build up air	Ref to w/o # 323524	378154
60 10/06/2011	323524 Air System - Check air pressure not building up	Release brom brake bus OK	378154
60 09/29/2011	322119 Accident - repair centre of concertina bent under side	refer #321362 - sent to Volgren	377660
60 09/27/2011	321735 GLOBE S/CONTACT 24V-10W		377660
60 09/26/2011	321735 Elec & Light - Replace interior light	Replaced	377660
60 09/26/2011	321362 Accident - Accident damage no 34056 - damages in turntable	sent to Volgren -26/09/2011	377660
60 09/23/2011	321579 Annaul Body Inspection	Inspected	377660
60 09/23/2011	321035 GLOBE FESTOON 24V5W		377660
60 09/20/2011	321035 Elec & Light - Replace emergency light	Replace light	377247
60 09/19/2011	320208 POS 5 275/70 CAP FLAT	Creditor #::BEA001 BEAUREPAIRES P/O #:K98012 Receiving #:98885 Date :2011-09-19	376813
60 09/16/2011	320208 Whls & Tyres - Replace tyre pos 5 - flat		376642
60 09/15/2011	320193 Whls & Tyres - Replace tyre pos 5	Replaced	376642
60 09/14/2011	320021 Wipers & Washers - Fill wipers	Filled	376440
60 09/09/2011	318260 POS 7-8 275/70 CAP	Creditor #::BEA001 BEAUREPAIRES P/O #:G97461 Receiving #:98550 Date :2011-09-09	375992
60 09/09/2011	319170 Elec & Light - Rebuild alternators	alt rebuilds	376067
60 09/09/2011	319170 Elec & Light - Rebuild alternators	Completed alt rebuild using parts from previous comp rebuilds as parts are unavailable at this time	376067
60 09/09/2011	318016 Brakes - Air leak from foot brake valve	Rekit brake foot valve and adjust brake valve piston fixed t/table cover cleaned inside bus r/tested bus OK	375992
60 09/08/2011	318016 Eng Cool - Coolant leak	Changed coolant hose near t/table	375992
60 09/08/2011	318016 49G0211M FOOT VALVE KIT	Creditor #::MUL001 MULTISPARES LTD P/O #:G97551 Receiving #:98441 Date :2011-09-08	375992
60 09/08/2011	318016 Brakes - Air leak from foot brake valve	Remove brake valve and start to rekit	375992
60 09/06/2011	318260 replace worn tyre pos 7-8	replaced	375992
60 09/06/2011	318016 Eng Cool - Coolant leak	Ass Matt with coolant problem	375992
60 09/06/2011	318016 Eng Cool - Coolant leak	Cont pulling down t/table	375992
60 09/06/2011	314448 COMM - AM/fm radio n/w & control knob missing (Checked on 0	Fit am/fm radiom n/w checked fuses OK followed wiring loose connection in one of the plugs checked OK	373814
60 09/06/2011	314448 COMM - AM/fm radio n/w & control knob missing (Checked on 0	Ass Brad with radio install & test	373814
60 09/06/2011	318160	Tension ALL Wheel Nuts to OEM Specs	375899
60 09/06/2011	318160	A Service & Bus Safety Inspection	375899
60 09/05/2011	318245 Whls & Tyres - NSR outer tyre low tread	Change tyres 78	375992
60 09/05/2011	317945 Elec & Light - Service Exchange Alternators - Preventative	Moved bus drained coolant removed & fit refurbished alts	375899
60 09/05/2011	317945 Elec & Light - Service Exchange Alternators - Preventative	Ass Brad with alts and began pulling down t/table to find coolant leak	375899
60 09/05/2011	318160	Tension ALL Wheel Nuts to OEM Specs	375899
60 09/05/2011	318160	A Service & Bus Safety Inspection	375899
60 09/02/2011	318016 Eng Cool - Coolant leak	Leaking from bottom of turntable put in line 1 and positioned tray underneath leak c/o	375992
60 09/02/2011	306498 Accident Damaged # 33045 R/R. n/s. No2 lower panel safety d	Touched up readjusted panels	372328
60 09/01/2011	317846 Elec & Light - Replace interior tube light	Replaced	375899
60 09/01/2011	314448 no volume knobTAPE JAM+FRONT P	Creditor #::REB001 CIM CONCEPTS P/O #:G96673 Receiving #:98264 Date :2011-09-01	375686
60 08/30/2011	316886 POS 10	Creditor #::BEA001 BEAUREPAIRES P/O #:K97193 Receiving #:98123 Date :2011-08-30	375256
60 08/30/2011	317517 Elec & Light - Replace interior light cover	replaced	375471
60 08/29/2011	316886 Whls & Tyres - Replace tyre pos 10 - flat	Replaced	375085
60 08/28/2011	316883 Whls & Tyres - Change tyre pos 910	Changed 10 was flat and put 9 in stock	375085
60 08/24/2011	315351 POS 2 275/70 NEW FLAT	Creditor #::BEA001 BEAUREPAIRES P/O #:G96851 Receiving #:97812 Date :2011-08-24	374481
60 08/19/2011	315351 fix puncture pos 2	fixed	373959
60 08/19/2011	315549 Whls & Tyres - Replace tyre pos 2	Replaced & tensioned w/nuts	373989
60 08/19/2011	314227 BRAKE BOOSTER MID AXLE L94UAB		373959
60 08/18/2011	315274 Engine - Bus wont move	explained the problem to Glen	373959
60 08/18/2011	314227 HUB SEAL MIDDLE AXLE SCANIA L94UAB		373959
60 08/18/2011	314227 WEAR SENSOR SCANIA DISC BRAKE		373959
60 08/18/2011	314227 DISC PADS SCANIA L94+0500 MERC		373959
60 08/18/2011	314227 BRAKE ROTOR MIDDLE AXLE SCANIA L94UAB		373959
60 08/17/2011	315044 Eng Cool - Add coolant	Added	373959
60 08/16/2011	314448 COMM - AM/fm radio n/w & control knob missing (Checked on 0	Took radio out for repair	373814
60 08/16/2011	314227 Air System - Air pressure keeps dropping & had to pump up t	Ass Dulkith to finish	373716
60 08/16/2011	314227 Air System - check air slow to build up	Changed OS 3rd axle brake disc brake pad both side r/tested & cleaned work area	373716
60 08/16/2011	314227 Air System - check air slow to build up	Replaced rotor on tag axle on OS	373716
60 08/15/2011	314227 Air System - check air slow to build up	Changed 3rd axle OS brake chamber and checked leak need to replace brake pad	373716
60 08/15/2011	314227 Air System - check air slow to build up	Removed middle axle wheel put back again rotors cracked bus u/s	373716
60 08/13/2011	314227 Air System - check air slow to build up	3rd axle OS brake booster leaking need to change not in store	373716
60 08/12/2011	314227 Air System - check air slow to build up	Checked air system drain water from air tank and found air leak from ABS valve	373716
60 08/10/2011	314162 Elec & Light - Replace interior light and cover	Replaced	373545
60 08/08/2011	313272 HEAD LIGHT GLOBE 24V 70/75W		372933

60 08/05/2011	313272 Elec & Light - Replace OS front headlight globe	Replaced	372933
60 07/29/2011	310630 Heat & Demist - Demister not heating up	Checked Ok	372328
60 07/29/2011	310630 Ops Entered - Fault - Heat & Demist - Route: 811 - Braesid	R/tested	372328
60 07/28/2011	311730 LIMIT SWITCH ENGINE STOP		372328
60 07/28/2011	311730 Elec & Light - rear engine door switch faulty	Fitted new switch on rear door	372328
60 07/28/2011	306498 Accident Damaged # 33045 R/R. n/s. No2 lower panel safety d	C/o	372328
60 07/27/2011	310630 Heat & Demist - Heater n/w blows cold air	Assist sisil	371698
60 07/27/2011	310630 Heat & Demist - Heater n/w blows cold air	Changed the thermostat nothing wrong with thermostat constaina coolant pipe broken fixed need to r/test & check demister	371698
60 07/26/2011	310630 1849060 twin thermostat	Creditor #-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G95613 Receiving #:96634 Date :2011-07-26 60	372085
60 07/26/2011	310630 1755952 gasket	Creditor #-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G95613 Receiving #:96634 Date :2011-07-26 60	372085
60 07/22/2011	301181 Replace Grenda decals x 4	Creditor #-ATT001 ATTITUDE SIGNS P/O #:G92531 Receiving #:96484 Date :2011-07-22	371819
60 07/21/2011	310827 Eng Cool - Add coolant	Added	371819
60 07/20/2011	310630 Heat & Demist - Heater n/w blows cold air	R/tested checked for heater demister thermostat faulty again c/o	371698
60 07/20/2011	310630 Heat & Demist - Has no hot air	R/tested bus checked temp not going over 55	371698
60 07/20/2011	310630 Heat & Demist - Demister n/w it blows cold air	Checked demister for heat N/A checked engine temp with temp gun only come up to 55 max Ass Greg with checking after r/test	371698
60 07/19/2011	310168 GLOBE FESTOON 24V5W		371394
60 07/15/2011	310168 Elec & Light - Replace emergency exit light globe	Replaced	371394
60 07/13/2011	309624 Whls & Tyres - Check OS front tyre	Checked tyre & adjusted pressure	370972
60 07/13/2011	308772 1755952 GASKET	Creditor #-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G94971 Receiving #:96143 Date :2011-07-13 60	370972
60 07/13/2011	308772 1849060 THERMOSTAT	Creditor #-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G94971 Receiving #:96143 Date :2011-07-13 60	370972
60 07/12/2011	309445 Heat & Demist - coolant leak at turntable	Fixed	370972
60 07/12/2011	309445 BOD - NSR tyre brush missing	Checked OK	370972
60 07/12/2011	309445 AS - Air tanks full of water	Done	370972
60 07/12/2011	309281	A Service & Bus Safety Inspection	370972
60 07/12/2011	309281	Tension ALL Wheel Nuts to OEM Specs	370972
60 07/10/2011	309079 Eng Cool - Coolant leak turntable	Fixed bottom side covers coolant leak r/tested checked heaters all OK	370972
60 07/09/2011	308772 Heat & Demist - Heater is n/w	Connected thermostat hose filled coolant completed	370972
60 07/08/2011	308772 Heat & Demist - Heater is n/w	Assist Siri	370972
60 07/08/2011	308772 Heat & Demist - Heater is n/w	Replaced new thermostat valve heating OK	370972
60 07/08/2011	308861	A Service & Bus Safety Inspection	370972
60 07/08/2011	308861	Tension ALL Wheel Nuts to OEM Specs	370972
60 07/07/2011	308772 Heat & Demist Heater Cold - No heating	No heat looks like thermostat is faulty	370972
60 07/07/2011	308772 Heat & Demist - Heater is n/w	same job	370972
60 07/01/2011	365267 t-bolt clamp	Creditor #-BUR001 BURSON AUTO PARTS P/O #:G111441 Receiving #:111885 Date :2012-07-26	409270
60 06/30/2011	306498 plastic seat for job # 5748	Creditor #-MCC002 MCCONNELL SEATS AUSTRALIA P/O #:G94357 Receiving #:95554 Date :2011-06-30	370692
60 06/24/2011	306714 GLOBE FESTOON 24V-3W		369936
60 06/24/2011	306498 CENTRA SEAT END CAPS		369936
60 06/23/2011	306714 Replace emer exit light	Replaced	369936
60 06/22/2011	306314 SUS - RHF airbag leaking	Replaced NSF	369936
60 06/22/2011	306314 SUS - Middle axle front air bag leaking	Checked OK	369936
60 06/22/2011	306314 FRONT AIR BAG SCANIA L94UAB		369936
60 06/22/2011	306498 Replace NS 11 capsule	Assisted carl	369936
60 06/22/2011	306498 Replace NS 11 capsule	Removed	369936
60 06/21/2011	306142 GLOBE FESTOON 24V5W		369936
60 06/20/2011	306142 Replace NS middle rear indicator	Replaced	369936
60 06/17/2011	305949 Replace NS rear parker light globe	Replaced	369936
60 06/16/2011	305625 NS rear tail light n/w	Checked repaired loose contact	369856
60 06/16/2011	305426 GLOBE STOP AND TAIL 24V 21/5W		369622
60 06/15/2011	305426 Replace NSR parker	Replaced	369622
60 06/10/2011	304371 EL - Bus doesn't turn On if turned Off cant start the bus	Ass Brad with repairing broken wires in loom	368539
60 06/10/2011	304371 EL - Bus doesn't turn On if turned Off cant start the bus	Finished wiring & cleaned up	368539
60 06/09/2011	304371 EL - Bus doesn't turn On if turned Off cant start the bus	Found break in wire fixed c/o	368539
60 06/09/2011	304371 EL - Bus doesn't turn On if turned Off cant start the bus	Ass Brad with t/table wiring fault in starting circuit	368539
60 06/08/2011	304371 EL - Bus doesn't turn On if turned Off cant start the bus	Looking for broken wire from front of bus to rear of bus will not start from front	368539
60 06/08/2011	304371 EL - Bus doesn't turn On if turned Off cant start the bus	Trace wire from back of t/table checked with multi meter OK broken wire in front above t/table	368539
60 06/08/2011	304371 EL - Bus doesn't turn On if turned Off cant start the bus	Wont start had to assist driver	368539
60 06/03/2011	303646 CRANK TO PULLEY SCANIA 21/32X67		365723
60 06/03/2011	303415 EL - starting problem - wiring	Jump started had to start from rear with jumper batteries	365723
60 06/03/2011	303415 EL - starting problem - wiring	Checked out wiring found loose connection at rear fixed and cleaned tested OK	365723
60 06/03/2011	303415 EL - Indicators not self cancelling	Checked OK	365723
60 06/03/2011	303415 COOL - Fan belt tensioner lost tension	Checked OK	365723
60 06/02/2011	300167 POS 4 275/70 CAP	Creditor #-BEA001 BEAUREPAIRES P/O #:K92274 Receiving #:94261 Date :2011-06-02	365723
60 06/02/2011	303646 Replace a/c belts	Ass Phil to replace belts	365723
60 06/02/2011	303646 Replace a/c belts	Replaced	365723
60 06/02/2011	303415 EL - starting problem - wiring	Check over wiring in rear fuse box	365723
60 06/02/2011	303646 Check brake pads	Removed NS middle axle tyres to check brake pads	365723
60 06/02/2011	303646 Check brake pads	Removed NS middle wheel to check brake pads	365723
60 06/02/2011	303551	A Service & Bus Safety Inspection	365723
60 06/02/2011	303551	Tension ALL Wheel Nuts to OEM Specs	365723
60 06/02/2011	303551	A Service & Bus Safety Inspection	365723
60 06/01/2011	303415 EL - starting problem - wiring	Checking out starting system go to Scania for wiring diagrams	365723
60 05/31/2011	301379 Check for not starting from front	Checked by laptop and cleared fault code	364539
60 05/31/2011	301379 Check for not starting from front	Fitted switch checked out relays and fuses and switch at engine bay no power from front of bus getting to rear door switch	364539
60 05/27/2011	302621 GLOBE FESTOON 24V-3W		365230
60 05/26/2011	302621 EL - Rear emer exit 2 lights out		365230
60 05/24/2011	302081 Clean a/c filter	Replaced	364764
60 05/24/2011	302089 Replace globes	Cleaned	364764
60 05/24/2011	302089 GLOBE INST 24V 2W	Replaced head & park light globes	364764
60 05/24/2011	302089 HEAD LIGHT GLOBE 24V 70/75W		364764
60 05/24/2011	302089 Check engine hatch sensor		364764
60 05/24/2011	301978 FITTING JOINER 8MM	Jump started and repaired sensor	364764
60 05/23/2011	301379 1425019 STARTER SWITCH		364764
60 05/23/2011	301978 AIR - Air leak LHF wheel arch	Creditor #-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G92562 Receiving #:93656 Date :2011-05-23	364764
60 05/23/2011	301978 Check air leak	same job	364764
60 05/21/2011	295080 AC - repair faulty compressor	Found punctured air line repaired tied lines	360687
60 05/20/2011	301581 HEAD LIGHT GLOBE 24V 70/75W	Finished off clutch repair tested OK	364541
60 05/20/2011	301872 Bus wont start		364764
60 05/19/2011	301581 Replace NS headlight globe	Jump started	364541
60 05/18/2011	301379 Check for not starting from front	Replaced	364539
60 05/18/2011	301181 Replace Grenda decals x 4	Checked out ordered parts	364439
60 05/17/2011	300978 BOD - Drivers area - overhead locker door broken hinges com	Replaced	364439
60 05/12/2011	300167 Replace tyre pos 4 - flat	Replaced broken hinges with new	363770
60 05/12/2011	295080 1865053 A/C CLUTCH	Replaced	360687
60 05/10/2011	300163 Replace NS inner tyre	Creditor #-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G91585 Receiving #:93220 Date :2011-05-12 60	363597
60 05/10/2011	300163	Replaced	363597
		Checked tyre pressures all wheels	363597

60 05/03/2011	299067	GLOBE FESTOON 24V-3W			362425
60 05/03/2011	299067	Em. exit light	Replace globe		362425
60 04/21/2011	298386	EL - needs new rear door inhibitor switch			361776
60 04/21/2011	296128	EL - oil pressure warning light not working	Help Daniel to tracking wires - ready to road test tomorrow	Secured turntable	361519
60 04/21/2011	296128	LIMIT SWITCH ENGINE STOP			361519
60 04/20/2011	296128	EL - oil pressure warning light not working	Started bus ready for road test		361519
60 04/19/2011	296128	EL - oil pressure warning light not working	Help Daniel to tracking wires - ready to road test tomorrow		361519
60 04/19/2011	296128	EL - oil pressure warning light not working	Fixed broken wires wires - ready to road test tomorrow		361519
60 04/18/2011	296128	EL - oil pressure warning light not working	Checked wiring at turntable - cannot find C/O job		361519
60 04/14/2011	295080	a/c compressor	Creditor #:TRA061 TRANSIT REFRIGERATION & AIR CONDITIONING SERVICE P/O #:G90088 Receiving #:91966 Date :2011-04-14 60		360687
60 04/12/2011	293974	DASH PANEL ROUTE BUS			361702
60 04/12/2011	293974	AIR CON REFRIDGERANT			361702
60 04/12/2011	293974	5/8FLARE DRIER			361702
60 04/12/2011	293974	24 VOLT RELAY PANEL			361702
60 04/12/2011	293974	CONTROLLER FOR ESP209			361702
60 04/12/2011	293974	5 PIN CHANGE-OVER RELAY WITH DIODE			361702
60 04/11/2011	296128	EL - oil pressure warning light not working	Found no signal between turntable and front elec centre		361519
60 04/08/2011	296128	GLOBE DASH B7L			361519
60 04/07/2011	296128	LIMIT SWITCH ENGINE STOP			361519
60 04/07/2011	296128	40V2803 OIL PRESSURE SWITCH	Creditor #:MUL001 MULTISPARES LTD P/O #:G90683 Receiving #:91713 Date :2011-04-07 60		361519
60 04/07/2011	296128	EL - oil pressure warning light not working	Checked dash found globe OK checked continously between sender plug & dash plug (pin 51) looks to be broken wire		361519
60 04/06/2011	295876	POS 1-2 275/70 NEW BALANCE WH	Creditor #:BEA001 BEAUREPAIRES P/O #:G90571 Receiving #:91642 Date :2011-04-06		361519
60 04/06/2011	296128	EL - oil pressure warning light not working	Fitted oil pressure sensor oil pressure warning light n/w removed & fitted old sensor back		361519
60 04/05/2011	296128	El - fire alarm staying on	Connector cleaned and fitted checked ok.		361519
60 04/05/2011	296128	EL - oil pressure warning light not working	Test oil pressure sender. Faulty sender. Order new sender.		361519
60 04/05/2011	296128	EL - oil pressure warning light not working	Dash panel removed and fitted back.		361519
60 04/04/2011	295876	balance wheels pos 1-2	wheels wobbly - balance wheels pos 1-2		361511
60 04/04/2011	295080	AC - repair faulty compressor	Left rear system replaced failed fan relay removed both clutches swap & test found unit requires new hub assembly parts ordered		360687
60 04/04/2011	293974	FILTER DRIER 5/8			361511
60 04/04/2011	293974	COMPRESSOR OIL AIR CON			361511
60 04/04/2011	293974	AIR CON REFRIDGERANT			361511
60 04/01/2011	295830	WHL - Front wheels need balancing	Changed both front tyres		361511
60 04/01/2011	295830	WHL - Front wheels need balancing	Changed both front tyres		361511
60 04/01/2011	295080	AC - repair faulty compressor	Replaced both driers vac & charge both system unit still has intermitting short dropping voltage to left bank compressor causing clutch to slip		360687
60 04/01/2011	295730	O RING FILTER KIT K93			361399
60 04/01/2011	295730	FILTER OIL K124 / L94UAB (H200W01)			361399
60 04/01/2011	295730		D Service & Bus Safety Inspection		361399
60 04/01/2011	295730	FILTER TRANSMISSION ZF 4139-298-038E39HD119			361399
60 04/01/2011	295730	FILTER AIR SCANIA USE AF25066			361399
60 04/01/2011	295730	ENGINE OIL DELO 400LE 15W40			361399
60 04/01/2011	295730	TEXAMATIC 1888			361399
60 04/01/2011	295730		Tension ALL Wheel Nuts to OEM Specs		361399
60 04/01/2011	295730		A Service & Bus Safety Inspection		361399
60 04/01/2011	295730		Tension ALL Wheel Nuts to OEM Specs		361399
60 03/28/2011	295080	AC - repair faulty compressor	Mount compressor into position and align locate and repair short in unit		360687
60 03/23/2011	294491	AC - Rear a/c n/w fault light on - rear of bus is hot	Chased up compressor for rear unit measure up and assemble		360079
60 03/22/2011	294256	40bd6830duk bearing	Creditor #:CON001 CONSOLIDATED BEARING CO. P/O #:G89921 Receiving #:90900 Date :2011-03-22 60		359708
60 03/21/2011	294256	Drv entered - Air Cond Air Conditioner	Ref to w/order # 292008		359708
60 03/21/2011	292008	AC - A/C belt cracked	Replaced		357987
60 03/21/2011	292008	AC - Aircon needs looking at front switch	Checked system over found liquide line coc valve weeping at gland packing seal & check all OK		357987
60 03/21/2011	293974	FAN BELT AIR/CON ARTIC VEE BELT B43			359659
60 03/21/2011	293974		Replace compressor oil		359659
60 03/21/2011	293974		Replace filter drier		359659
60 03/21/2011	293974		B Service		359659
60 03/21/2011	293974		CONDENSOR AREA: Clean condensor coils; check boltsclamps for tension		359659
60 03/21/2011	293974		UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensor pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation		359659
60 03/21/2011	293974		Clean R/A & F/A filters; Inspect and report on condition; Replace filter media		359659
60 03/21/2011	293974		FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)		359659
60 03/21/2011	293974		COMPRESSOR DRIVE BELTS: Inspect belt wear; Retension belts;		359659
60 03/21/2011	293974		DRIVE PULLEY'S: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;		359659
60 03/21/2011	293974		DRIVE PULLEY'S: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear		359659
60 03/21/2011	293974		COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose		359659
60 03/21/2011	293974		REFRIGERATION FILTER DRYER: Replace filter dryer; check pump operation;		359659
60 03/21/2011	293974		EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check boltsclamps & fittings; clean condensate drains; clean drip tray		359659
60 03/21/2011	293974		INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condensor fan grills		359659
60 03/11/2011	293020	GLOBE FESTOON 24V-3W			358818
60 03/10/2011	293020	Replace exit light globe	Replaced		358818
60 03/09/2011	290267	POS 1 275/70 NEW	Creditor #:BEA001 BEAUREPAIRES P/O #:G88691 Receiving #:90428 Date :2011-03-09		358593
60 03/09/2011	292813	ENGINE OIL DELO 400LE 15W40			358593
60 03/09/2011	292813	TEXAMATIC 1888			358593
60 03/09/2011	292813		D Service & Bus Safety Inspection		358593
60 03/09/2011	292813		Tension ALL Wheel Nuts to OEM Specs		358593
60 03/09/2011	292813	FILTER OIL K124 / L94UAB (H200W01)			358593
60 03/09/2011	292813	FILTER TRANSMISSION ZF 4139-298-038E39HD119			358593
60 03/09/2011	292813	O RING FILTER KIT K93			358593
60 03/09/2011	292813	FILTER AIR SCANIA USE AF25066			358593
60 03/09/2011	292813		A Service & Bus Safety Inspection		358593
60 03/09/2011	292813		Tension ALL Wheel Nuts to OEM Specs		358593
60 03/02/2011	292008	AC - Aircon needs looking at front switch	Front system n/w efficiently possibly low on gas oil in compressor needs changing OK to run on cooler days		357987
60 02/25/2011	291363	GLOBE FESTOON 24V5W			356819
60 02/23/2011	291363	Add power steering oil	Added		356819
60 02/23/2011	291363	Replace OSR clearance light globe	Replaced		356819
60 02/18/2011	290267	replace worn tyre pos 1	replace worn tyre pos 1		355992
60 02/17/2011	290115	WHL - Front tyres scalloping wearing uneven steering alignm	Replaced tyres		355942
60 02/17/2011	290000	WIPER REFILL SUIT TX600+TX700			355765
60 02/17/2011	290055	AC - AC works for about 20 mins then ER 1 comes up	Checked OK		355992
60 02/17/2011	290055	EL - Side indicator cracked	Replaced lens		355942
60 02/17/2011	290055	LENS TO SUIT 2030 LAMP(ORANGE)			355942
60 02/17/2011	290055	HORN 24VLT	Replaced horn		355992
60 02/17/2011	290055	EL - Horn volume has died	Replaced		355765
60 02/15/2011	290000	Replace wiper blades	Checked		355501
60 02/14/2011	289700	Remove NS middle axle tyre and check brake pads	Checked OK		355501
60 02/14/2011	289700	Remove NS middle axle tyre and check brake pads			355326
60 02/14/2011	289609		A Service & Bus Safety Inspection		355326
60 02/14/2011	289609		Tension ALL Wheel Nuts to OEM Specs		355326

60 02/14/2011	289609	A Service & Bus Safety Inspection	355326
60 02/11/2011	289626 Clean graffiti	Cleaned	355093
60 02/10/2011	288996 BROOM HANDLE (8232715)		354385
60 02/10/2011	288996 BROOM HEAD (09803211)		354385
60 02/09/2011	289205 VAN - clean graffiti	fixed	354624
60 02/08/2011	288996 Replace broom	Replaced	354385
60 02/01/2011	287928 Clean graffiti	Cleaned	353342
60 01/31/2011	287358 GLOBE FESTOON 24V10W		352788
60 01/31/2011	287550 LENS TO SUIT 2029 (RED+AMBER)		352950
60 01/31/2011	287550 GLOBE FESTOON 24V5W		352950
60 01/31/2011	287436 BOD - Right side windscreen has a chip in it in drivers lin	done by Knights	352950
60 01/31/2011	287436 SUB - Chip in windscreen RHS eye level	done by Knights	352950
60 01/31/2011	287436 SUB - Repair windscreen - sub/con - Knights	done by Knights	352950
60 01/31/2011	287436 REPAIR SCREEN	Creditor #:KNIO01 KNIGHTS WINDSCREEN REPAIRS P/O #:G87868 Receiving #:88886 Date :2011-01-31	352950
60 01/28/2011	287556 Clean graffiti	Cleaned	352950
60 01/28/2011	286900 STARTER SOLENOID SUIT JF		352788
60 01/28/2011	286900 BUSH KIT SUIT JF		352788
60 01/28/2011	287550 Replace RH centre red/amber lens	Replaced	352950
60 01/28/2011	286900 STARTER DRIVE SUIT JF		352788
60 01/27/2011	275859 Service	Finished starter rebuild	342241
60 01/27/2011	284891 POS 9-10 CAPS	Creditor #:BEA001 BEAUREPAIRS P/O #:K87076 Receiving #:88816 Date :2011-01-27	352788
60 01/27/2011	287358 EL - amber clearance light nw	REplaced	352788
60 01/25/2011	286853 GLOBE FESTOON 24V5W		352788
60 01/25/2011	286853 GLOBE FESTOON 24V-3W		352788
60 01/25/2011	286900 Rebuild starter motor refer to w/o 275528	rebuild starte motor refer to w/o 275528	352788
60 01/25/2011	286900 Rebuild starter motor refer to w/o 275528	Starter rebuild process	352788
60 01/24/2011	286853 EL - exit light nw	fixed	352788
60 01/24/2011	286853 EL - side indicator nw	fixed	352788
60 01/19/2011	285929 COMM - CCTV n/w	Repaired by Buscam	352696
60 01/19/2011	286121 COMM - CCTV n/w	Ref to w/order # 285929	352788
60 01/19/2011	286127 WEAR SENSOR SCANIA DISC BRAKE		352788
60 01/18/2011	285929 COMM - CCTV n/w	Checked cameras with monitor attached found rear camera u/s	352696
60 01/18/2011	286127 BOD - Torn rear seat	Replaced	352788
60 01/18/2011	286127 BOD - RHR seat base ripped	Replaced	352788
60 01/18/2011	286127 BRK - low pad warning lamp coming on	Checked all brake pads OK checked and found NS middle axle wear sensor wire broken replaced new one r/tested OK	352788
60 01/18/2011	286127 BRK - low pad warning lamp coming on	Take middle axle wheels off with kumar & help with brakes	352788
60 01/17/2011	282705 AC - aircon nw	same job	352674
60 01/17/2011	282705 AC - aircon nw	same job	352674
60 01/17/2011	282705 AC - Rear a/c comes up with fault - very hot in rear	Teset front unit found unit has lost alternator signal run hot wire run unit up tested OK	352674
60 01/17/2011	282705 AC - Rear air con faulty	same job	352674
60 01/17/2011	282705 Drv entered - Cool & AC Sys Not Operating	same job	352674
60 01/17/2011	282705 AC - aircon nw	same job	352674
60 01/17/2011	282705 AC - aircon nw	same job	352674
60 01/17/2011	285683 GASKET LIGHT 2139+2143+2043		352871
60 01/17/2011	285683 LENS TO SUIT 2319 (RED)		352871
60 01/15/2011	285793 Add coolant	Added	352366
60 01/12/2011	285683 Replace brake light	Replaced lens & gasket	352871
60 01/07/2011	284891 Replace both rear right wheels	Changed and washed both	351501
60 01/04/2011	284695 Replace left side indicator light	Replaced	350851
60 12/29/2010	282674 POS 6 CAP	Creditor #:BEA001 BEAUREPAIRS P/O #:K86443 Receiving #:87770 Date :2010-12-29	350193
60 12/29/2010	283547 INDICATOR LIGHT FRONT ARTIC		349817
60 12/24/2010	282705 RELAY SOLID STATE		349567
60 12/24/2010	283556 Clean a/c filter	Cleaned	349887
60 12/24/2010	283394 BR - Brakes hanging on	Checked Ok	349817
60 12/23/2010	283547 Replace front LH side indicator	Replaced	349817
60 12/20/2010	282852 Clean graffiti	Cleaned	349397
60 12/20/2010	282705 AC - Rear a/c n/w front isn't great	same as	349567
60 12/20/2010	282705 AC - Back a/c faulty	Removed seized left bank compressor clutch coil replaced both evap relays condensor relay not yet done new compressor has been ordered	349567
60 12/20/2010	282802 Check bus wont move	Went to KSB depot checked bus found front ramp twisted one side rectified checked and came back to GBS	349397
60 12/18/2010	282512	A Service & Bus Safety Inspection	349165
60 12/18/2010	282512	Tension ALL Wheel Nuts to OEM Specs	349165
60 12/18/2010	282512	A Service & Bus Safety Inspection	349165
60 12/17/2010	282674 Replace tyre pos 6 - bald	Replaced	349366
60 12/16/2010	282447 Replace RH centre tyres	Replaced	349165
60 12/13/2010	280850 POS 2 CAP	Creditor #:BEA001 BEAUREPAIRS P/O #:K85767 Receiving #:87145 Date :2010-12-13	348332
60 12/13/2010	281999 Clearance light u/s	Found loose connection	348468
60 12/13/2010	281846 Not building up air	Went to KSB No problem found with air but found fire symbol on dash found loose wire on rear start button switch box fixed	348468
60 12/09/2010	281486 Clean graffiti	Cleaned	347942
60 12/08/2010	281292 Clean graffiti	Cleaned	347512
60 12/06/2010	280972 Chnage w/nuts	Changed	347043
60 12/06/2010	280975 WHL - Tyres 78 4 & 5mm	Replaced rear tyres	347279
60 12/06/2010	280850 replace worn tyre pos 2	replace worn tyre pos 2	347043
60 12/06/2010	280955 Rear door internal bottom brush on metal frame came off scr	Replaced brush panel on centre door	347279
60 12/06/2010	274781 supply and fit decals	Creditor #:ATT001 ATTITUDE SIGNS P/O #:G84006 Receiving #:86817 Date :2010-12-06	347043
60 12/03/2010	280463 Add water to wipers	Added	346847
60 12/03/2010	280447 GLOBE INDICATOR 24V-18W SINGLE CONTACT		346674
60 12/02/2010	280447 Replace r/r brake light	Replaced	346674
60 12/02/2010	280447 EL - OS top brake light out	same as	346674
60 11/30/2010	279951 GLOBE FESTOON 24V5W		346109
60 11/30/2010	279951 GLOBE FESTOON 24V-3W		346109
60 11/29/2010	279951 Replace globes	Replaced emer exit & NS indicator	346109
60 11/25/2010	279314 GLOBE FESTOON 24V-3W		345502
60 11/24/2010	277155 ROAD SAFETY INSPECTIONS	Creditor #:ROA001 Road Safety Inspections P/O #:G84561 Receiving #:86224 Date :2010-11-24	345502
60 11/24/2010	279314 Replace emer exit light globe	Replaced	345502
60 11/24/2010	279314 Replace emer exit light globe	Replaced	345502
60 11/19/2010	278734 Possible air pressure gauge	Checked both air pressure gauge working OK	344820
60 11/17/2010	278461 Clean graffiti	Cleaned	344603
60 11/16/2010	278241 Fire alarm on dash	Checked gave job to Greg	344454
60 11/16/2010	278241 Fire alarm on dash	Found loose connection	344454
60 11/14/2010	277155 inspect for rsi -	BC 129328 passed	343290
60 11/04/2010	275528 FAN BELT AIR/CON ARTIC VEE BELT B43		342658
60 11/04/2010	275528 BEARING IDLER PULLEY A/CON		342658
60 11/04/2010	275528 IDLER PULLEY SCANIA ARTIC(No Groove Plastic)		342658
60 11/04/2010	275528 CRANK TO PULLEY SCANIA 21/32X67		342658
60 11/04/2010	275528 BELT CRANK-TWIN A/C COMP SCANIA ARTIC		342658

60 11/04/2010	275528 BELT ALT W/PUMP CRANK SCANIA ARTIC		342658
60 11/04/2010	275528 SCANIA ALT BELT TENSIONER K1241B		342658
60 11/04/2010	276651 Replace stop/tail light & clearance light	Replaced	342803
60 11/04/2010	276651 GLOBE STOP AND TAIL 24V 21/5W		342803
60 11/04/2010	276651 GLOBE FESTOON 24V5W		342803
60 11/03/2010	275528 ST - Power steering pipes leaking at arctic area	Checked OK	342658
60 11/03/2010	275528 Change idler belt tensioner bearing	Changed alternator belt tensioner 4 a/c belts	342658
60 11/03/2010	275528 EL - Speedo light n/w	Changed globe OK	342658
60 11/03/2010	275528 BR - OS rear brake pad wear indicator wire rubbed thru on r	Fixed wear pad wire	342658
60 11/03/2010	275528 BR - OS centre axle brake caliper slide missing cover - dir	checked ok	342658
60 11/03/2010	275528 AIR - Air leak from safety valve at air dryer	Changed air safety valve	342658
60 11/01/2010	275528 1111195 14.3 bar safety valve	Creditor #:BAN001 BANLAY PTY LTD P/O #:G83823 Receiving #:85461 Date :2010-11-01	342471
60 10/29/2010	275995 NUMBER PLATE LAMP		342241
60 10/29/2010	275995 GLOBE INST 24V 2W		342241
60 10/29/2010	275995 GLOBE INDICATOR 24V-18W SINGLE CONTACT		342241
60 10/29/2010	275995 GLOBE FESTOON 24V5W		342241
60 10/29/2010	275995 LENS TO SUIT 2029 (RED+AMBER)		342241
60 10/28/2010	275859 STARTER SOLENOID SUIT JF		342241
60 10/28/2010	275859 BUSH KIT SUIT JF		342241
60 10/28/2010	275995 Replace globes as req	Replace No plate RHR indicator & LH clearance lights	342241
60 10/28/2010	275528 LAMP (RED+AMBER)		342223
60 10/28/2010	275528 LENS TO SUIT 2029 (RED+AMBER)		342223
60 10/28/2010	275528 GLOBE FESTOON 24V5W		342223
60 10/28/2010	275528 GLOBE+HOLDER INSTRUMENT (GREY)		342223
60 10/28/2010	274781 WIRE MESH PUNCH PANEL kit	Creditor #:VOL001 VOLGREN AUSTRALIA P/L P/O #:G83943 Receiving #:85276 Date :2010-10-28	342241
60 10/27/2010	274703	Adjust valve clearances	342102
60 10/27/2010	274703	Replace coolant filter in engine cooling system	342102
60 10/27/2010	274703	Replace power steering filter	342102
60 10/27/2010	274703	Adjust valve clearances	342102
60 10/27/2010	274703	Replace power steering filter	342102
60 10/27/2010	275528 EL - replace starter motor	Completed starter motor rebuild	342223
60 10/27/2010	275528 EL - replace starter motor	Replaced starter motor	342223
60 10/27/2010	275528 EL - replace starter motor	Completed starter motor rebuild	342223
60 10/27/2010	275528 STARTER MOTOR SCANIA K93+L94		342223
60 10/27/2010	275528 Fit lights when bus comes out of body shop	Fitted	342223
60 10/27/2010	268405 Fabricate NS punch panel mesh shield	Fabricated new	342223
60 10/26/2010	274781 UNREPORTED - Accident Damage # 32095.Replace & paint NS No	Sand out runs n/s 8 o/s 12 and repaint remask and unmask rest of bus. Make order and measure for n/s punch panel mesh and frame. c/o	342223
60 10/26/2010	274781 UNREPORTED - Accident Damage # 32095.Replace & paint NS No	Refitted clow catches on panel n/s 11	342223
60 10/26/2010	274781 UNREPORTED - Accident Damage # 32095.Replace & paint NS No	Refitted wheel arch rubber on panel o/s 11. Secured panel 12o/sreplacedmissing bolts.Refitted emergency exit decal (push buttonunderpanel) n/s. Refitted rubber door seal on bus 60 centre door. Parked bus on pit one end of day.	342223
60 10/25/2010	275295 AC - A/C compressor bearing u/s	Remove all belts & spin up on all three compressor & idlers all bearings seem OK. will need to run up to normal operation temp and check	342223
60 10/25/2010	274781 BOD - paint rear bumper bar	same as acc dam	342223
60 10/25/2010	268405 LENS TO SUIT 2029 (RED+AMBER)		336440
60 10/25/2010	274781 UNREPORTED - Accident Damage # 32096. Repair & paint OS No	Prepare prime sand mask up for painting	342223
60 10/25/2010	274781 UNREPORTED - Accident Damage # 32095.Replace & paint NS No	Also rear bumper	342223
60 10/25/2010	274781 UNREPORTED - Accident Damage # 32095.Replace & paint NS No	Sanded grey primer masked panels and painted NS 349 & OS 101112 & painted NS corner & clip in strip	342223
60 10/25/2010	274781 UNREPORTED - Accident Damage # 32095.Replace & paint NS No	Sanded grey primer masked panels and painted NS 349 & OS 101112 & painted NS corner & clip in strip	342223
60 10/25/2010	274781 UNREPORTED - Accident Damage # 32097. Repair & paint rear b	Painted	342223
60 10/22/2010	274703 FUEL BOWL L94UAB+B12		342102
60 10/22/2010	274848 FIRE EXTINGUISHER 2.5KG		342223
60 10/22/2010	274781 BOD - Battery cover struts u/s	Replaced	342223
60 10/22/2010	274781 UNREPORTED - Accident Damage # 32095.Replace & paint NS No	NS3 - removed decals sand prep & prime sand primed ready for painting	342223
60 10/22/2010	274781 UNREPORTED - Accident Damage # 32095.Replace & paint NS No	NS4 - drill holes & fitted panel	342223
60 10/22/2010	274781 UNREPORTED - Accident Damage # 32097. Repair & paint rear b	Sanded rear b/bar removed decals of OS panels 111213 repaired damaged areas applied body filler sanded	342223
60 10/22/2010	274781 UNREPORTED - Accident Damage # 32095.Replace & paint NS No	NSR - trailer corner polished side etc	342223
60 10/22/2010	274781 UNREPORTED - Accident Damage # 32095.Replace & paint NS No	NS10 - repaired polish	342223
60 10/22/2010	274781 UNREPORTED - Accident Damage # 32095.Replace & paint NS No	NS8 - Removed decals sand panel	342223
60 10/21/2010	274848 REAR AIR BAG (MID AXLE) SCANIA L94UAB		342102
60 10/21/2010	274781 BOD - Paint till stand	Painted	342223
60 10/21/2010	274781 BOD - Battery hold down clamp needs repair	Made new clamp	342223
60 10/21/2010	274781 BOD - Remove Grendas name address & weight - OSF No 1 panel	Removed & polished	342223
60 10/21/2010	274781 DO NOT OVERTAKE TURNING DECAL		342223
60 10/21/2010	274781 REAR MARKER DECAL		342223
60 10/21/2010	274781 BOD - Battery cover struts u/s	Ordered	342223
60 10/21/2010	274781 BOD - paint wheels	Cleaned & painted	342223
60 10/21/2010	274781 BOD - Paint exterior mirrors and arms	Painted	342223
60 10/21/2010	274781 BOD - Clean air condition filter secure vents	Cleaned	342223
60 10/21/2010	274781 BOD - Polish front bumper bar	Polished	342223
60 10/21/2010	274781 BOD - Polish exterior panels/headers & touch up paint work	Polished	342223
60 10/21/2010	274781 BOD - Battery hold down clamp needs repair	Checked electrics OK	342223
60 10/21/2010	274781 BOD - secure all lower skit panels	Secured	342223
60 10/21/2010	274781 BOD - Replace marker plates - charter coaches	Replaced	342223
60 10/21/2010	274781 BOD - Secure passenger seats arm rest & hand grips - rear u	Repaired with sikaflex rear seats	342223
60 10/21/2010	274781 BOD - Clean graffiti - floor seats & side walls	Cleaned	342223
60 10/21/2010	274781 BOD - Replace Licensed to carry (No) seat (No) adult passen	Replaced on back window	342223
60 10/21/2010	268405 2MM X 1200MM X 2400MM FLAT ALUMINIUM		336440
60 10/21/2010	274781 UNREPORTED - Accident Damage # 32096. Repair & paint OS No	Removed damaged panel and started to make new ones	342223
60 10/21/2010	274781 UNREPORTED - Accident Damage # 32095.Replace & paint NS No	Fabricated panel No 3 & fitted to the bus	342223
60 10/20/2010	274703	Replace air dryer canister	342102
60 10/20/2010	274703	Replace hydraulic fan filter and top up oil	342102
60 10/20/2010	274703	Rekit quick release valve	342102
60 10/20/2010	274703	Replace power steering filter	342102
60 10/20/2010	274703	Replace final drive oil	342102
60 10/20/2010	274703 FILTER AIR DRYER KIT(HALDEX)		342102
60 10/20/2010	274703 RPM BORATE EP LUBE 220	Replace coolant filter in engine cooling system	342102
60 10/20/2010	274703	Clean a/c filters	342102
60 10/20/2010	274703	Remove intercooler wash intercooler and raditor	342102
60 10/20/2010	274703	Inspect bus as per inspection sheet	342102
60 10/20/2010	274703 HYDRAULIC FILTER L94UAB		342102
60 10/20/2010	274703 FILTER FUEL K124 / LU94A (1411894 / H17WK05)		342102
60 10/20/2010	274703 FUEL FILTER ELEMENT SCANIA L94UAB (R90T / H7090WK10)		342102
60 10/20/2010	274703 POWER STEER FILTER B10M		342102
60 10/20/2010	274703	Inspect bus as per inspection sheet	342102
60 10/20/2010	274703	Replace fuel filters	342102
60 10/20/2010	274669 ANN - annual body inspection	Inspected	342102

60 10/20/2010	274848 LHS mid axle rear airbag leaking	Replaced	342102
60 10/20/2010	274848 EN - Engine oil leak at water pump area	same as	342102
60 10/20/2010	274848 Oil leak from oil cooler behind water pump	Sealed oil cooler mounting bracket to engine	342102
60 10/20/2010	274848 Steamclean bus	Cleaned	342102
60 10/20/2010	274848 Fire ext out of date	Replaced	342102
60 10/20/2010	274753 Replace fire extinguisher	Replaced	342102
60 10/19/2010	262363 Service	completed rebuild.	330821
60 10/19/2010	274403 Bus will not start at Brighton town hall	Check for non start. check rear start switch. Trace to faulty starter motor. Hit starter ok	341676
60 10/18/2010	274476 Repair & paint wheel arch panel	Repaired & painted	341676
60 10/12/2010	273545 Won't start ok Brighton Townhall.	Go to Brighton & give starter & tap with hammer & bus started ok.	340616
60 10/12/2010	273558 Breakdown - Brighton Terminus - OUT 3.45 pm BACK 4.00 pm -	Attended by Moorabbin Transit started bus OK	340616
60 10/06/2010	272978 WIP - LH washer jet blocked	Cleaned & topped up water	340144
60 10/06/2010	272978 Clean a/c filter	Cleaned	340144
60 10/01/2010	272209 EL - Horn needs replacing	same as	339517
60 10/01/2010	272209 Please fix the horn	Made working OK	339517
60 09/30/2010	272088 GLOBE STOP AND TAIL 24V 21/5W		339344
60 09/30/2010	272088 Bottom right rear park & brake light u/s	Replaced	339344
60 09/29/2010	271945 Remove graffiti	Cleaned	339210
60 09/29/2010	272055 Not starting	Starting motor solenoid replaced	339210
60 09/29/2010	272055 Not starting	Checked starter & replaced OK	339210
60 09/28/2010	271693 WHEEL NUT SQUIRREL		339111
60 09/28/2010	271693 LENS TO SUIT 2029 (RED+AMBER)		339111
60 09/25/2010	271693 Replace squirrels	Replaced	339111
60 09/25/2010	271693 Replace clearance lens	Replaced	339111
60 09/25/2010	271432 FILTER OIL K124 / L94UAB (H200W01)		338909
60 09/25/2010	271432 FILTER TRANSMISSION ZF 4139-298-038E39HD119		338909
60 09/25/2010	271432 O RING FILTER KIT K93		338909
60 09/25/2010	271432 FILTER AIR SCANIA USE AF25066		338909
60 09/25/2010	271432 ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL		338909
60 09/25/2010	271432 TEXAMATIC 1888		338909
60 09/25/2010	271432	D Service & Bus Safety Inspection	338909
60 09/25/2010	271432	Tension ALL Wheel Nuts to OEM Specs	338909
60 09/25/2010	271432	Tension ALL Wheel Nuts to OEM Specs	338909
60 09/25/2010	271432	A Service & Bus Safety Inspection	338909
60 09/25/2010	271432	A Service & Bus Safety Inspection	338909
60 09/16/2010	269127 POS 3 275/70 NEW	Creditor #:BEA001 BEAUREPAIRES P/O #:G81888 Receiving #:83535 Date :2010-09-16	337596
60 09/10/2010	268405 N/S #5 PANEL ON TRAILER (PUNCH	Creditor #::VOL001 VOLGREN AUSTRALIA P/L P/O #:G81701 Receiving #:83273 Date :2010-09-10	336854
60 09/08/2010	269127 replace worn tyre pos 3-4	replace worn tyre pos 3-4	336548
60 09/07/2010	268405 SUS - Mid axle air bag cracked (Checked 10/05/10 05/07/10	Removed n/s middle axle. Tyres and changed brake pad sensor wire. New 2 tyres for n/s middle axle. Changed o/s marker lights globes x 3 road tested fueled and parked.	336440
60 09/07/2010	268405 Random Vehicle Audit	Checked	336440
60 09/07/2010	268405 Repair nsr panel catch	Repaired	336440
60 09/07/2010	268884 ABS light staying on	Looking for fault	336440
60 09/07/2010	268884 ABS light staying on	Checking out to find broken contact for low pads	336440
60 09/06/2010	268884 ABS light staying on	Wire broken somewhere cant find	336440
60 09/06/2010	268235 WEAR SENSOR SCANIA DISC BRAKE		336440
60 09/06/2010	268235 DISC PADS SCANIA L94+0500 MERC		336440
60 09/06/2010	268631 Replace front brake pads	Replaced	336440
60 09/06/2010	267896 BRAKE ROTOR DRIVE AXLE SCANIA	Creditor #:TRA004 TRADE BRAKE+CLUTCH CO. P/O #:G81522 Receiving #:83005 Date :2010-09-06	336440
60 09/03/2010	268235 WEAR SENSOR SCANIA DISC BRAKE		336440
60 09/03/2010	268235 Replace N/S/R brake pads	Replaced	336440
60 09/02/2010	268405 VAN - Graffiti in bus	DION - Cleaned	336440
60 09/02/2010	268557 Refit a/c cover screws	Refitted	336440
60 09/02/2010	268235 Replace N/S/R brake pads	Assist with rebuilding hubs/discs	336440
60 09/02/2010	268235 Replace N/S/R brake pads	Fitted both sides disc hubs & calipers	336440
60 09/02/2010	268405 ACC - panel damage LHS	Ordered NS 5 trailer panel	336440
60 09/01/2010	268235 Replace N/S/R brake pads	Assemble the part and start again wrong part.	336440
60 08/30/2010	267896 WHEEL NUT SQUIRREL		336440
60 08/30/2010	267896 WEAR SENSOR SCANIA DISC BRAKE		336440
60 08/30/2010	267896 DISC PADS SCANIA L94+0500 MERC		336440
60 08/30/2010	267896 Replace N/S/R brake pads		336440
60 08/27/2010	267213 WEAR SENSOR SCANIA DISC BRAKE		336440
60 08/26/2010	267213 Replace O/S/ midlle axle brake kalliper and brake pads	Replaced OS middle axle brake calipers new brake pads. Replaced NS middle axle brake pads & r/tested	336440
60 08/26/2010	267213 DISC PADS SCANIA L94+0500 MERC		336440
60 08/26/2010	267213 K002963 SCANIA MID AXLE CALIPE	Creditor #:TRA004 TRADE BRAKE+CLUTCH CO. P/O #:G81291 Receiving #:82584 Date :2010-08-26 60	336440
60 08/24/2010	267213 Replace O/S/ midlle axle brake kalliper and brake pads	Remove middle brake tyres both side on the pit. Put back all the tyres and park outside the pit. Remove o/s middle brake caliper.	336440
60 08/20/2010	266717 Add coolant	Added	336215
60 08/20/2010	266717 Add coolant	Added	336215
60 08/17/2010	266127 GLOBE FESTOON 24V-3W		335730
60 08/16/2010	266127 Replace inside tube globes	Replaced	335730
60 08/02/2010	262363 Service	continued c/o	330821
60 07/27/2010	263675 Bus sluggish	checked ok	332141
60 07/23/2010	262363 Service	continued c/o	330821
60 07/20/2010	262363 Service	Pulled down starter. Got Brad to clean parts.	330821
60 07/20/2010	262363 STARTER DRIVE SUIT JF		330821
60 07/20/2010	262363 Service	clean parts.	330821
60 07/13/2010	261730 VAN - Graffiti on floor	cleaned	330298
60 07/05/2010	260492 Random Vehicle audit	Inspected at service	329118
60 07/05/2010	260490	A Service & Bus Safety Inspection	329118
60 07/05/2010	260490	Tension ALL Wheel Nuts to OEM Specs	329118
60 07/05/2010	260490	A Service & Bus Safety Inspection	329118
60 07/05/2010	260490 AIR FILTER SCANIA CLEANED		329118
60 06/29/2010	260080 VAN - Graffiti on floor	Cleaned	328630
60 06/29/2010	259611 CONSUMABLE DELIVERY CHARGE	Creditor #:AIR002 AIR INTERNATIONAL TRANSIT P/O #:G78738 Receiving #:80323 Date :2010-06-29	328498
60 06/29/2010	259611 sbz003	Creditor #:AIR002 AIR INTERNATIONAL TRANSIT P/O #:G78738 Receiving #:80323 Date :2010-06-29	328498
60 06/29/2010	259611 sbz002	Creditor #:AIR002 AIR INTERNATIONAL TRANSIT P/O #:G78738 Receiving #:80323 Date :2010-06-29 60	328498
60 06/29/2010	259902 GLOBE INST 24V 2W		328279
60 06/27/2010	259902 Replace front rear parking lamp	Replaced	328279
60 06/25/2010	259611 AC - A/C gone to fault blowing cold air	Ass Bruce with fitting compressor	328279
60 06/25/2010	259455 GLOBE DASH B7L		328151
60 06/25/2010	259455 EL - Replace interior light globe	Changed	328151
60 06/25/2010	259455 EL - Cabin light n/w	Changed	328151
60 06/25/2010	259455 EL - Replace dash light globe	Changed	328151
60 06/25/2010	259699 ACC - Panel damage left side	Temp repairs to panel	328279
60 06/25/2010	256268 Assisted bruce with service		324966
60 06/25/2010	256268 AIR CON REFRIDGERANT		324966

60 06/16/2010	258554	EL - Flat battery - wooden bracket broken	Changed batteries & sort out other batteries	326930
60 06/15/2010	258404	Bus wont start	Jump started	326928
60 06/12/2010	257994	EL - Interior light n/w	REPLACE FESTOON GLOBE	326743
60 06/11/2010	257994	GLOBE FESTOON 24V-3W		326743
60 06/11/2010	256268	5/8FLARE DRIER		324966
60 06/11/2010	256268	FILTER DRIER 5/8		324966
60 06/09/2010	257724	Emergency exit lights		326237
60 06/09/2010	257651	FLASHER RELAY SUIT SCANIA K124IB		325866
60 06/08/2010	257651	EL - Leftside indicators n/w		325866
60 06/02/2010	256777	GLOBE FESTOON 24V-3W	KEYSBOROUGH DEPOT - replace flasher relay. drive and return from Keysborough depot.	325314
60 06/02/2010	256777	Replace emergency globe		325314
60 06/01/2010	256268	DIGI-TEMP	Replaced	324966
60 05/31/2010	255891	EL - check fault in fire warning system	Creditor #:ACT001 ACTROL (AC:330639) P/O #:G77993 Receiving #:79458 Date :2010-06-01	324966
60 05/31/2010	255891	EL - check fault in fire warning system	Checked out loom in turntable and rear of bus found loose plug behind stop control switch at rear	324966
60 05/31/2010	256268	Assisted Bruce with service rear unit removed compressor fo	Fuelled & parked	324966
60 05/31/2010	256268			324966
60 05/31/2010	256268		UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensor pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation	324966
60 05/31/2010	256268		CONDENSOR AREA: Clean condensor coils; check boltsclamps for tension	324966
60 05/31/2010	256268		INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condensor fan grills	324966
60 05/31/2010	256268		EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check boltsclamps & fittings; clean condensate drains; clean drip tray	324966
60 05/31/2010	256268		REFRIGERATION FILTER DRYER: Replace filter dryer; check pump operation;	324966
60 05/31/2010	256268	Remove compressor & strip found head and valve plate gaskets	COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose	324966
60 05/31/2010	256268		DRIVE PULLEY'S: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear	324966
60 05/31/2010	256268		DRIVE PULLEY'S: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;	324966
60 05/31/2010	256268		COMPRESSOR DRIVE BELTS: Inspect belt wear; Retension belts;	324966
60 05/31/2010	256268	failed	FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)	324966
60 05/31/2010	256268	front unit only	Clean R/A & F/A filters; Inspect and report on condition; Replace filter media	324966
60 05/27/2010	255891	THR - 3 second delay in accelerating	unable to fix this	324966
60 05/27/2010	255891	STR - Power steering oil leak near turntable n/s	fixed leak in turntable	324966
60 05/27/2010	255891	ENG - No power when a/c is on	unable to fix this	324966
60 05/27/2010	255891	EN - Cracked belts	changed a/c belts	324966
60 05/27/2010	255891	CRANK TO PULLEY SCANIA 21/32X67		324966
60 05/27/2010	255891	FAN BELT AIR/CON ARTIC VEE BELT B43		324966
60 05/27/2010	255891	EL - engine fire warning lamp on	checked out fire warning played around wire connection tested ok.	324966
60 05/27/2010	255891	ELE - radio on/off knob missing	no knobs in stock	324966
60 05/27/2010	255891	ELEC - dash globe needs replacing	Checked ok	324966
60 05/27/2010	255679	GLOBE INDICATOR 24V-18W SINGLE CONTACT		324966
60 05/27/2010	256109	BREAK - Breakdown. Dingley Village. Out 1:30pm in 2:30pm	c/o bus 143. checked wiring broken contact somewhere in loom.	324966
60 05/26/2010	255891	EL - engine fire warning lamp on	fire alarm staying on - checked alarms and connection checked wiring alarm staying on u/s	324966
60 05/25/2010	255679	ELE - top left rear hazard light is out	replaced globe	324603
60 05/25/2010	255814	BODY - 2/h side back external rubber window seal hanging out	refitted rubber seal washed bus refueled and parked	324787
60 05/24/2010	255505	ELE - jump start bus	jump started	324603
60 05/24/2010	255505	ELE - jump start bus	jump started	324603
60 05/21/2010	253950	POS 2 275/70 NEW FLAT	Creditor #-BEA001 BEAUREPAIRES P/O #:G77372 Receiving #:79066 Date :2010-05-21	324443
60 05/12/2010	253950	fix flat tyre pos 2	Replaced	323161
60 05/11/2010	253893	Ticket machine playing up	referred to JZ	323078
60 05/11/2010	251656	ignition barrel + key	Creditor #-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G76634 Receiving #:78663 Date :2010-05-11 60	323078
60 05/11/2010	253991	BREAKDOWN - Heatherton Rd near Princes Hwy. Flat tyre.	c/o bus 102. Pos 2 tyre flat.	323078
60 05/11/2010	253991	BREAKDOWN - Heatherton Rd near Princes Hwy. Flat tyre.	Take van 619 change wheel on road	323078
60 05/10/2010	252535	POS 3 275/70 CAP	Creditor #-BEA001 BEAUREPAIRES P/O #:G76942 Receiving #:78643 Date :2010-05-10	322958
60 05/10/2010	253758	Bus wont start	Jump started	322958
60 05/10/2010	253758	Bus wont start	Jump started	322958
60 05/10/2010	253724		Tension ALL Wheel Nuts to OEM Specs	322958
60 05/10/2010	253724		A Service & Bus Safety Inspection	322958
60 05/10/2010	253724		A Service & Bus Safety Inspection	322958
60 05/05/2010	253244	DEST - Desto faulty	Given to Ralph to repair bus doesn't do that run	322393
60 05/03/2010	252794	AC - Front a/c n/w - - + defect # 79296 79358 79383	Found right bank relay had lost contact on No 1 evap fan motor clean contacts and tested OK	321939
60 05/03/2010	252794	AC - Front a/c n/w - - + defect # 79296 79358 79383	Assist Bruce to fix relay for evap fan	321939
60 04/30/2010	252627	Replace tyre 3	Replaced	321669
60 04/30/2010	252627	Replace tyre 3	Replaced	321669
60 04/30/2010	252627	Replace tyre 3	Replaced	321669
60 04/30/2010	252535	replace worn tyre pos 3	Replaced	321669
60 04/28/2010	249555	POS 1-2 275R NEW	Creditor #-BEA001 BEAUREPAIRES P/O #:G76209 Receiving #:78244 Date :2010-04-28	321282
60 04/27/2010	251656	STARTER MOTOR SCANIA K93+L94		320673
60 04/27/2010	251656	Load test and check charge rate	replaced starter motor and ignition switch. replaced struts rear o/s door.	320673
60 04/27/2010	251656	300N GAS STAY 10-21-247L		320673
60 04/23/2010	251897	Clean a/c filter	Cleaned	320938
60 04/21/2010	251652	Flat batterys Brighton Town Hall.	Go to Brighton town hall and found starter motor faulty smack with hammerand bus started. Return to depot.	320673
60 04/20/2010	251434	GLOBE FESTOON 24V-3W		320529
60 04/20/2010	251434	Replace exit light globe	Replaced	320529
60 04/17/2010	251253	Breakdown - Oakleigh station - OUT 12.30 pm BACK 1.00 pm -	Used van 619. Jump started	320082
60 04/16/2010	251066	Clean a/c filter	Cleaned	319925
60 04/15/2010	250825	GLOBE STOP AND TAIL 24V 21/5W		319491
60 04/14/2010	250825	Drivers side rear lower brake light n/w	Replaced globe	319491
60 04/12/2010	250395	Replace emergency exit globe	Replaced	319076
60 04/12/2010	250395	GLOBE FESTOON 24V-3W		319076
60 04/09/2010	250183	Clean a/c filter	Cleaned	318794
60 04/09/2010	250215	Bus wont start	Jump started	318794
60 04/09/2010	250215	Bus wont start	Jump started	318794
60 04/08/2010	250062	Bus wont start	Jump started	318679
60 04/08/2010	249943	EL - Faulty ignition switch - intermittent	Checked OK	318679
60 04/08/2010	249943	EL - Faulty ignition switch - intermittent	Checked OK	318679
60 04/06/2010	249555	Replace tyre pos 12 - worn	Replaced	317674
60 04/06/2010	249566	GLOBE STOP AND TAIL 24V 21/5W		317674
60 04/03/2010	249651	Breakdown - Springvale Station - OUT 12.15 pm BACK 1.30 pm	Used van 619. Bus started OK drove back to depot	317862
60 04/01/2010	249566	Clean wiper jets	Cleaned	317674
60 04/01/2010	249566	Change tyre # 12	Changed tyres	317674
60 04/01/2010	249566	Change tyre # 12	Changed tyres	317674
60 04/01/2010	249428	GLOBE STOP AND TAIL 24V 21/5W		317569
60 04/01/2010	249566	Change o/s brake light globe	Replaced globe	317674
60 04/01/2010	249566	Change o/s brake light globe	Replaced globe	317674
60 04/01/2010	249496	ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL		317674
60 04/01/2010	249496	TEXAMATIC 1888		317674
60 04/01/2010	249496		D Service & Bus Safety Inspection	317674
60 04/01/2010	249496		Tension ALL Wheel Nuts to OEM Specs	317674
60 04/01/2010	249496	FILTER AIR SCANIA USE AF25066		317674

60 04/01/2010	249496 O RING FILTER KIT K93		317674
60 04/01/2010	249496 FILTER TRANSMISSION ZF 4139-298-038E39HD119		317674
60 04/01/2010	249496 FILTER OIL K124 / L94UAB (H200W01)		317674
60 04/01/2010	249565 TEXAMATIC 1888		317674
60 04/01/2010	249565 ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL		317674
60 04/01/2010	249565 FILTER AIR SCANIA USE AF25066		317674
60 04/01/2010	249565 O RING FILTER KIT K93		317674
60 04/01/2010	249565 FILTER TRANSMISSION ZF 4139-298-038E39HD119		317674
60 04/01/2010	249565 FILTER OIL K124 / L94UAB (H200W01)		317674
60 04/01/2010	249565	D Service & Bus Safety Inspection	317674
60 04/01/2010	249565	Tension ALL Wheel Nuts to OEM Specs	317674
60 04/01/2010	249496	A Service & Bus Safety Inspection	317674
60 04/01/2010	249496	Tension ALL Wheel Nuts to OEM Specs	317674
60 04/01/2010	249565	A Service & Bus Safety Inspection	317674
60 04/01/2010	249565	Tension ALL Wheel Nuts to OEM Specs	317674
60 03/31/2010	249428 R/H stop light	Replaced globe	317569
60 03/31/2010	249373 Go to Brighton terminus to start bus.	Drive to Brighton terminus to start broken down bus found bus wasn't thereand returned to depot.	317569
60 03/30/2010	249215 Bus wont start	Jump started	317359
60 03/30/2010	249215 Bus wont start	Jump started	317359
60 03/26/2010	248868 Clean a/c filter	Cleaned	316932
60 03/25/2010	248842 Bus wont start	Jump started	316806
60 03/25/2010	248842 Bus wont start	Jump started	316806
60 03/24/2010	248611 Replace a/c belt	Replaced	316563
60 03/24/2010	248611 FAN BELT AIR/CON ARTIC VEE BELT B43		316563
60 03/24/2010	248611 Replace a/c belt	Replaced	316563
60 03/24/2010	248611 Replace a/c belt	Replaced	316563
60 03/19/2010	248135 Clean a/c filter	Cleaned	316172
60 03/19/2010	248135 Bus wont start	Jump started	316172
60 03/11/2010	247293 Had problems starting bus at Brighton sounds like starter m	Checked bus working OK driver may be operating the a/c with out bus running	315226
60 03/11/2010	247240 Bus not starting Brighton Townhall.	Go to Brighton & start bus on key without boost pack.	315226
60 03/11/2010	247284 BOD - Check side panels loose	Checked OK	315226
60 03/09/2010	246772 AIR S - Losing air too much - + defcet # 79688	checked air leak found one hose cracked from joiner.	314463
60 03/09/2010	246772 5/16inch AIR LINE JOINER		314463
60 03/07/2010	246874 Breakdown - Cheltenham Rd - OUT 9.45 pm BACK 10.25 pm - Lea	NO C/O. Full throttle build up air & move to red square (fitted air joiner)	314805
60 03/04/2010	246512 Clean a/c filter	Cleaned	314252
60 03/04/2010	246558 Replace emergency exit globe	Replaced	314252
60 03/04/2010	246558 GLOBE FESTOON 24V-3W		314252
60 03/02/2010	246062 GLOBE FESTOON 24V-3W		313922
60 03/01/2010	362081 BALD - Recap 275R 22.5 - Pos	Creditor #:BEA001 BEAUREPAIRES P/O #:K110491 Receiving #:111076 Date :2012-07-09 Replace with recap	407515
60 03/01/2010	246062 Replace emergency exit globe	Replaced	313795
60 02/26/2010	245878 Bus wont start	Jump started	313638
60 02/25/2010	245911 Flat batterys Brighton terminus.	Go to Brighton & found bus not there & return to depot.	313474
60 02/25/2010	245798 Flat batterys Brighton terminus.	Ref to w/order # 245911	313474
60 02/25/2010	245799 Flat batterys Brighton terminus.	Ref to w/order # 245911	313474
60 02/18/2010	244985 Clean a/c filer	Cleaned	312571
60 02/18/2010	244785 GLOBE FESTOON 24V5W		312571
60 02/18/2010	244982 Replace new filter cloth to both filter frames	Replaced both	312571
60 02/18/2010	244785	A Service & Bus Safety Inspection	312699
60 02/18/2010	244785	A Service & Bus Safety Inspection	312454
60 02/18/2010	244785	Tension ALL Wheel Nuts to OEM Specs	312454
60 02/13/2010	244482 Indicator light on dash not flashing when indicating - l/h	Checked OK	312109
60 02/12/2010	244343 Clean a/c filter	Cleaned	311928
60 02/10/2010	244062 Replace front top lhs indicator globe	Replaced	311641
60 02/10/2010	244062 GLOBE INDICATOR 24V-18W SINGLE CONTACT		311641
60 02/10/2010	244062 Replace front top lhs indicator globe	Checked OK	311798
60 02/09/2010	243977 Bus wont start	Jump started	311484
60 02/05/2010	243369 Drv entered - Passenger Doors Faulty Controls	Checked door found middle door cover loose	311012
60 02/05/2010	243502 Replace emergency light globe	Replaced	311145
60 02/05/2010	243502 GLOBE FESTOON 24V-3W		311145
60 02/04/2010	240510 POS 9-10 275R CAP	Creditor #:BEA001 BEAUREPAIRES P/O #:G73790 Receiving #:75991 Date :2010-02-04	311012
60 02/01/2010	242888 GLOBE FESTOON 24V-3W		310632
60 02/01/2010	242888 Replace emergency exit globe	Replaced	310413
60 01/29/2010	242640 Clean a/c filter	Cleaned	310219
60 01/29/2010	242601 Breakdown - Brighton Terminus - OUT 8.20 - bus wont start	Attended by Moorabbin Transit	310219
60 01/22/2010	242136 jump start bus	jump started.	309448
60 01/21/2010	241993 Clean a/c filter	Cleaned	309301
60 01/21/2010	241953 Bus wont start	Jump started	309301
60 01/14/2010	241226 Clean a/c filter	Cleaned	308048
60 01/14/2010	241258 GLOBE FESTOON 24V-3W		308048
60 01/14/2010	241258 Drv entered - Elec & Light Interior Lights	Replace emergency light globe	308048
60 01/11/2010	240903 A/C n/w - no power for take off	Checked weather is too hot	307882
60 01/09/2010	235605 Drv entered - Cool & AC Sys Other		307788
60 01/08/2010	240706 change o/s rear tyre	changed tyre	307788
60 01/08/2010	240510 Replace tyre pos 910 - worn	Replaced	307788
60 01/08/2010	235605 AIR CON REFRIDGERANT		307788
60 01/08/2010	240705 repair saloon light and cover	replaced	307788
60 01/08/2010	240473 Service	A Service & Bus Safety Inspection	307607
60 01/08/2010	240473 Service	A Service & Bus Safety Inspection	307788
60 01/08/2010	240473	Tension ALL Wheel Nuts to OEM Specs	307607
60 01/08/2010	240473 LENS TO SUIT 2029 (RED+AMBER)		307788
60 01/07/2010	240517 GLOBE S/CONTACT 24V-10W		307788
60 01/07/2010	240517 replace step light globe	replaced.	307607
60 12/30/2009	235605 Front a/c n/w		306693
60 12/30/2009	235605 air conditioner not working		306693
60 12/24/2009	239436 GLOBE FESTOON 24V-3W		306564
60 12/24/2009	239436 Replace emergency exit globe	Replaced	306399
60 12/21/2009	235009 ROAD SAFETY INSPECTIONS	Creditor #:ROA001 Road Safety Inspections P/O #:G72073 Receiving #:74848 Date :2009-12-21	305937
60 12/21/2009	237097 PUNCH PANEL N/S RADIATOR	Creditor #:VOL001 VOLGREN AUSTRALIA P/L P/O #:G72680 Receiving #:74860 Date :2009-12-21 60	306111
60 12/15/2009	237793 POS 7-8 275-70R CAP	Creditor #:BEA001 BEAUREPAIRES P/O #:G72923 Receiving #:74737 Date :2009-12-15	305267
60 12/15/2009	238605 GLOBE FESTOON 24V-3W		305267
60 12/15/2009	238605 Replace emergency exit globe	Replaced	305267
60 12/10/2009	235605 A/C n/w blowing fan air not cold air		304692
60 12/10/2009	235605 Air con not working front fault light on		304692
60 12/10/2009	235605 No front air cond		304692
60 12/10/2009	235605 Front a/c n/w blowing hot air out red light is on	replace valve and head gasket top up refridgerant tested ok	304692

60	12/10/2009	235605	Drv entered - Cool & AC Sys Poor		304692
60	12/10/2009	235605	Drv entered - Air Cond Cooling Fault Light		304692
60	12/08/2009	237925	GLOBE FESTOON 24V-3W		304390
60	12/08/2009	237925	Replace emergency light globe	Replaced	304390
60	12/08/2009	231599	Two way u/s	Ref to w/order # 237939	304538
60	12/08/2009	237939	No 2way radio	Replaced	304390
60	12/08/2009	237939	2way radio only working sometimes	Replaced 2way	304390
60	12/07/2009	237814	Change tyre pos 78	Changed	304199
60	12/07/2009	237814	Change tyre pos 78	Replaced & torqued w/nuts	304199
60	12/07/2009	237814	Change tyre pos 78	Changed	304199
60	12/07/2009	237793	Replace tyre pos 78 - worn	Replaced	304199
60	12/07/2009	237827	AMBER REFLECTOR SIDE MOUNT		304199
60	12/07/2009	237827	Replace amber reflector	Replaced	304199
60	12/04/2009	237635	Middle back stabilizer bar bushes worn	Replaced bushes	304123
60	12/01/2009	235432	REPAIR 2 WAY	Creditor #-:REB001 CIM CONCEPTS P/O #:G72174 Receiving #:74287 Date :2009-12-01 60	303547
60	11/30/2009	237097	Near radiator body panel damage	Temp repairs to n/s rear radiator panel	303356
60	11/28/2009	235605	A/C n/w front	Searched store for parts have not arrived yet	301618
60	11/26/2009	236715	Change reverse buzzer	Changed	303083
60	11/26/2009	236715	Change reverse buzzer	Fixed new reverse buzzer	303185
60	11/26/2009	236715	Check brake pads	Removed tyres 56 to check	303083
60	11/26/2009	236715	Check brake pads	Removed tyres 56 to check	303185
60	11/26/2009	236334		Tension ALL Wheel Nuts to OEM Specs	302644
60	11/26/2009	236334		A Service & Bus Safety Inspection	302644
60	11/26/2009	236334		A Service & Bus Safety Inspection	303083
60	11/23/2009	236348	Bus wont start	Jump started	302644
60	11/23/2009	236348	Bus wont start	Jump started	302469
60	11/23/2009	236347	Add coolant	Added	302469
60	11/16/2009	234868	POS 5 275/70 CAP (FIX PUNCTUR	Creditor #-:BEA001 BEAUREPAIRES P/O #:G72039 Receiving #:73802 Date :2009-11-16	301618
60	11/16/2009	235605	A/C n/w front	Run commission test found TX valve failure traced back to failed valve plates put back together	301618
60	11/16/2009	235605	T.X.VALVE SLRT		301618
60	11/16/2009	235546	Replace emergency exit globe	Replaced	301618
60	11/16/2009	235546	GLOBE FESTOON 24V-3W		301618
60	11/15/2009	235009	Annual inspection	BC 139440	301183
60	11/13/2009	235432	GLOBE STOP AND TAIL 24V 21/SW		301618
60	11/13/2009	235432	No brake & park light r/h bottom	Replaced	301459
60	11/13/2009	235432	No 2way	Been sent for repair	301459
60	11/12/2009	231599	Two way u/s	Removed 2way & sent for repair	297474
60	11/11/2009	235192	GLOBE INST 24V 2W		301333
60	11/11/2009	235192	Replace stopping sign globe	Replaced	301183
60	11/10/2009	234868	fix flat tyre pos 5	Replaced	301022
60	11/09/2009	234772	Replace tyre # 5	Replaced cleaned rims & torqued w/nuts	300870
60	11/09/2009	234772	Replace tyre # 5	Replaced cleaned rims & torqued w/nuts	300870
60	11/09/2009	234772	Replace tyre # 5	Replaced cleaned rims & torqued w/nuts	300870
60	11/09/2009	234760	Bus wont start	Jump started	300870
60	11/05/2009	232758		Adjust valve clearances	298791
60	11/05/2009	232758		Adjust valve clearances	300754
60	11/05/2009	234499	Oil leak N/S of the turntable	S/cleaned checked OK	300668
60	11/05/2009	234499	Steamclean bus	Cleaned	300668
60	11/05/2009	234499	Bus stopping sign globe need to be changed	Changed	300668
60	11/05/2009	234499	Bus stopping sign globe need to be changed	Changed	300754
60	11/05/2009	234499	GLOBE S/CONTACT 24V-10W		300754
60	11/02/2009	234280	Fuel & park bus	Fuelled & parked	300405
60	10/28/2009	233680	Polish exterior panels/headers & touch up paint work	Polished	299806
60	10/28/2009	233680	Paint wheels	Painted	299806
60	10/28/2009	233680	Replace Grenda name address - O/S/F No 1 panel	Replaced	299806
60	10/28/2009	233680	Replace mud flaps - N/S/F O/S/F	Replaced	299806
60	10/28/2009	233680	Paint exterior mirrors and arms	Painted	299806
60	10/28/2009	233680	Secure all lower skit panels	Secured	299806
60	10/28/2009	233680	Polish front bumper bar	Polished	299806
60	10/28/2009	233680	Adjust middle doors	Adjusted	299806
60	10/28/2009	233680	Secure seat capsules - N/S 46 - O/S 7 & fit end caps	Secured & fitted end caps	299806
60	10/28/2009	233680	Replace emergency exit decals with safety hammers	Replaced	299806
60	10/28/2009	233680	Replace Licensed to carry (No) seat (No) adult passengers	Replaced	299806
60	10/28/2009	233680	Remove timetable holder	Removed	299806
60	10/28/2009	233680	Clean graffiti - floor seats & side walls	Cleaned	299806
60	10/28/2009	233680	Replace interior decals - priority seating N/S & O/S	Replaced	299806
60	10/28/2009	233680	Paint till stand	Painted	299806
60	10/28/2009	233680	Clean air condition filter secure vents	Cleaned	299806
60	10/28/2009	233680	Drivers seat - replace cushion	Replaced	299806
60	10/26/2009	232758		Remove intercooler wash intercooler and raditor	299678
60	10/26/2009	232758		Remove intercooler wash intercooler and raditor	298791
60	10/20/2009	232758	Service	Clean a/c filters. completed.	298791
60	10/20/2009	232758		Replace coolant filter in engine cooling system	298791
60	10/20/2009	232758	RPM BORATE EP LUBE 220		298791
60	10/20/2009	232758	FILTER AIR DRYER KIT(HALDEX)		298791
60	10/20/2009	232758	HYDRAULIC FILTER L94UAB		298791
60	10/20/2009	232758	FILTER FUEL K124 / LU94A (1411894 / H17WK05)		298791
60	10/20/2009	232758	FUEL FILTER ELEMENT SCANIA L94UAB (R90T / H7090WK10)		298791
60	10/20/2009	232758	POWER STEER FILTER B10M		298791
60	10/20/2009	232758	Service	Replace air dryer cansiter. completed.	298791
60	10/20/2009	232758	Service	Replace hydralic fan filter and top up oil. completed.	298791
60	10/20/2009	232758		Rekit quick release valve . N/A.	298791
60	10/20/2009	232758	Service	Replace power steering filter. completed.	298791
60	10/20/2009	232758	Service	Replace final drive oil. completed.	298791
60	10/20/2009	232758	Service	Replace fuel filters. completed.	298791
60	10/20/2009	232758	Service	Inspect bus as per inspection sheet. Completed.	298791
60	10/20/2009	232780	Annual body inspection	Annual body inspected	298791
60	10/20/2009	232917	Middle axle O/F/F air bag leak	checked ok.	298791
60	10/20/2009	232916	Middle axle N/F/F airbag leak	checked ok.	298791
60	10/20/2009	232661	clean a/c filter	cleaned a/c filter	298791
60	10/20/2009	233122	Fuel and park bus	fuel and park bus	298791
60	10/20/2009	232992	replace screns for middle door brush	replaced screns for middle door brush	298791
60	10/15/2009	231599	REPAIR 2 WAY	Creditor #-:REB001 CIM CONCEPTS P/O #:G71275 Receiving #:72901 Date :2009-10-15	298198
60	10/13/2009	231874	clean a/c filter	cleaned a/c filter	297786
60	10/12/2009	231566		Tension ALL Wheel Nuts to OEM Specs	297571

60 10/12/2009	231566 Service	D Service & Bus Safety Inspection. completed.	297786
60 10/12/2009	231566 Service	D Service & Bus Safety Inspection. completed.	297571
60 10/12/2009	231566 TEXAMATIC 1888		297571
60 10/12/2009	231566 ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL		297571
60 10/12/2009	231566 FILTER AIR SCANIA USE AF25066		297571
60 10/12/2009	231566 O RING FILTER KIT K93		297571
60 10/12/2009	231566 FILTER TRANSMISSION ZF 4139-298-038E39HD119		297571
60 10/12/2009	231566 FILTER OIL K124 / L94UAB (H200W01)		297571
60 10/12/2009	231566	Tension ALL Wheel Nuts to OEM Specs	297571
60 10/12/2009	231566	A Service & Bus Safety Inspection	297571
60 10/09/2009	231599 Two way u/s	Checked 2way OK	297474
60 10/08/2009	231465 horn not loud enough horn button broken	Fit horn button	297474
60 10/08/2009	231465 horn not loud enough horn button broken	Remove and order parts	297474
60 10/08/2009	231599 Two way u/s	Remove two way send for repairs	297474
60 10/08/2009	231601 Left mirror arm loose	Tighten mirror bolts	297474
60 10/06/2009	231324 graffiti	cleaned graffiti	297140
60 10/06/2009	231316 left mirror arm loose	tighten mirror bolts	297140
60 10/02/2009	231185 coolant topup	coolant top up	296794
60 09/30/2009	229005 POS 1 275R NEW	Creditor #:BEA001 BEAUREPAIRES P/O #:G70428 Receiving #:72522 Date :2009-09-30	296383
60 09/29/2009	230594 GLOBE FESTOON 24V-3W		296267
60 09/29/2009	230594 Replace emergency exit globe	Replaced	296267
60 09/22/2009	230032 MINI WEDGE GLOBE 24V-1.2W		295595
60 09/22/2009	230032 Door bell light n/w on dash	Replaced bell light on dash	295481
60 09/16/2009	229347 GLOBE FESTOON 24V-3W		294744
60 09/16/2009	229347 Replace emergency exit globe	Replaced	294744
60 09/14/2009	229005 Replace tyre pos 1 - punctured	Replaced	294116
60 09/14/2009	229084 Replace # 1 tyre	Replaced torqued w/nuts & moved buses	294385
60 09/14/2009	229084 Replace # 1 tyre	Replaced	294385
60 09/07/2009	228129 1356776 washers drag link	Creditor #:SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G70167 Receiving #:71890 Date :2009-09-07 60	293405
60 09/07/2009	228129 1897667 DRAG LINK	Creditor #:SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G70167 Receiving #:71890 Date :2009-09-07 60	293405
60 09/05/2009	228333 GLOBE+HOLDER INSTRUMENT (GREY)	Defect # 77526 also. Fit indicator globe	293405
60 09/05/2009	228333 Indicator lights on dash n/w	Defect # 77526 also. Fit indicator globe	293405
60 09/04/2009	228129 Drag link front end ball joint worn 2 mm play side & up/do	Replaced drag link	293102
60 09/04/2009	228129 Drag link front end ball joint worn 2 mm play side & up/do	Replaced drag link	293102
60 09/03/2009	228129 Drag link front end ball joint worn 2 mm play side & up/do	Checked drag link and ordered parts	293102
60 09/02/2009	227951 GLOBE INDICATOR 24V-18W SINGLE CONTACT		293102
60 09/02/2009	227951	A Service & Bus Safety Inspection	293102
60 09/02/2009	227951	Tension ALL Wheel Nuts to OEM Specs	292965
60 09/02/2009	227951	A Service & Bus Safety Inspection	292965
60 08/27/2009	227410 Add coolant	Added	292170
60 08/26/2009	227341 GLOBE FESTOON 24V5W		292170
60 08/26/2009	227341 LAMP INDICATOR [ORANGE]		292170
60 08/26/2009	227341 The right hand side flasher is broken	Replaced light assembly fuelled & parked	291893
60 08/25/2009	227123 Add coolant	Added	291690
60 08/21/2009	226829 Top left light is n/w	Checked and all lights are working	291328
60 08/19/2009	226695 GLOBE FESTOON 24V-3W		291059
60 08/19/2009	226695 repalce emergency exit globe	Replaced globe	290827
60 08/18/2009	226533 GLOBE FESTOON 24V-3W		290827
60 08/18/2009	226533 Replace emergency exit globe	Replaced	290557
60 08/14/2009	226129 Add coolant	Added	290201
60 08/07/2009	225574 Clean graffiti	Cleaned	289244
60 08/06/2009	223697 ignition switch	Creditor #:BAN001 BANLAY PTY LTD P/O #:G68917 Receiving #:70917 Date :2009-08-06 60	289084
60 08/03/2009	224928 GLOBE FESTOON 24V-3W		288457
60 08/03/2009	224928 Replace emergency exit globe	Replaced	288457
60 07/31/2009	223697 Bus doesn't start with the ignition key	Ass Greg with bus	288457
60 07/31/2009	223697 Bus doesn't start with the ignition key	Fitted new key and lock assembly	287551
60 07/28/2009	224455 REAR AIR BAG (DRIVE AXLE) SCANIA L94UAB		288104
60 07/28/2009	224455 Change N/S rear airbag	Changed airbag & parked	287956
60 07/28/2009	224337	A Service & Bus Safety Inspection	288104
60 07/28/2009	224337	Tension ALL Wheel Nuts to OEM Specs	287956
60 07/28/2009	224337	A Service & Bus Safety Inspection	287956
60 07/24/2009	223697 Bus doesn't start with the ignition key	Ass Greg with checking atarting problems	287551
60 07/24/2009	223697 Bus doesn't start with the ignition key	Checked out ignition switch playing up ordered new switch	287551
60 07/22/2009	223697 Bus wont start	Jump started	287551
60 07/22/2009	223697 Bus wont start	Jump started	287401
60 07/21/2009	223697 Bus wont start	Went to jump start but was not batteries	287266
60 07/21/2009	223610 GLOBE FESTOON 24V-3W		287266
60 07/21/2009	223610 Replace emergency exit globe	Replaced	287266
60 07/17/2009	223329 BEARING IDLER POST PULLEY (CURRUM TYPE)		286942
60 07/17/2009	223329 CRANK TO PULLEY SCANIA 21/32X67		286942
60 07/17/2009	223329 FAN BELT A/CON ARTIC 21/32X45		286942
60 07/17/2009	223329 Replace A/C idler pulley	Replaced belts	286942
60 07/17/2009	223329 Replace A/C idler pulley	Replaced bearing and belts	286942
60 07/15/2009	223097 GLOBE FESTOON 24V-3W		286617
60 07/15/2009	223097 Replace emergency light	Replaced	286617
60 07/14/2009	222937 GLOBE INST 24V 2W		286348
60 07/14/2009	222937 Right front parking light n/w	Replaced globe	286348
60 07/06/2009	222220 GLOBE FESTOON 24V-3W		285331
60 07/06/2009	222220 Replace emergency exit globe	Replaced	285331
60 06/30/2009	221693 LAMP (RED+AMBER)		284774
60 06/30/2009	221693 GLOBE FESTOON 24V5W		284774
60 06/29/2009	221693 N/S rear clearance light n/w	Replaced globe & light assembly	284774
60 06/24/2009	221212 GLOBE FESTOON 24V-3W		284250
60 06/24/2009	221212 Replace emergency exit globe	Replaced	284082
60 06/24/2009	221166 GLOBE HIGH BEAM 24V70W H1		284250
60 06/24/2009	221166 Drive side no head light - high beam stuck	Replaced globe checked OK	284082
60 06/22/2009	220867 Add coolant	Added	283760
60 06/16/2009	220421 Replace N/S/F & O/S/F tyres	Replaced & painted	283281
60 06/16/2009	220421 Replace N/S/F & O/S/F tyres	Replaced torqued & painted	283185
60 06/16/2009	220366 GLOBE FESTOON 24V-3W		283281
60 06/16/2009	220366	A Service & Bus Safety Inspection	283281
60 06/16/2009	220366	Tension ALL Wheel Nuts to OEM Specs	283185
60 06/16/2009	220366	A Service & Bus Safety Inspection	283185
60 06/15/2009	219505 POS 9 275/70 REAR CAP	Creditor #:BEA001 BEAUREPAIRES P/O #:G67554 Receiving #:69434 Date :2009-06-15	283008
60 06/12/2009	220163 Clean graffiti	Cleaned	282820

60 06/10/2009	219927	GLOBE FESTOON 24V-3W			282694
60 06/10/2009	219927	Replace emergency exit globe	Replaced		282516
60 06/05/2009	219505	Replace tyre pos 910 - worn out	Replaced		282039
60 06/05/2009	219541	Replace tyre # 910	Replaced		282192
60 06/05/2009	219541	Replace tyre # 910	Replaced		282192
60 06/05/2009	219541	Replace tyre # 910	Move out to w/shop Replace tyres & torque w/nuts		282192
60 05/25/2009	218385	GLOBE FESTOON 24V-3W			280524
60 05/25/2009	218385	Replace emergency exit globe	Replaced		280524
60 05/22/2009	218200	Change belts	Changed		280336
60 05/22/2009	218200	FAN BELT AIR/CON ARTIC VEE BELT B43			280336
60 05/22/2009	218200	Change belts	Changed		280336
60 05/22/2009	218200	Change belts	Fitted		280336
60 05/21/2009	218063	Add coolant	Added		280169
60 05/18/2009	217761	CRANK TO PULLEY SCANIA 21/32X67			279894
60 05/18/2009	217761	Replace belts	Replaced		279894
60 05/18/2009	217761	Replace belts	Replaced A/C belts		279641
60 05/14/2009	216707	POS 7-8 275/70 REAR CAP	Creditor #-BEA001 BEAUREPAIRES P/O #:G66661 Receiving #-68619 Date :2009-05-14		279323
60 05/14/2009	217454	Replace emergency exit globe	Replaced		279323
60 05/14/2009	217454	GLOBE FESTOON 24V-3W			279323
60 05/13/2009	215059	BOOST PUMP EXCHANGE	Creditor #-AIR002 AIR INTERNATIONAL TRANSIT P/O #:G66111 Receiving #-68569 Date :2009-05-13 60		279323
60 05/09/2009	217033	Breakdown - Hemming St Dandenong - OUT 10.30 pm BACK 11.40	Used van. Jump started		278510
60 05/07/2009	216877	Change tyres N/S/R rear	Changed		278298
60 05/07/2009	216696	Random Vehicle Audit	Completed at service		278115
60 05/07/2009	216689	ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL			278115
60 05/07/2009	216689	AIR FILTER SCANIA CLEANED			278115
60 05/07/2009	216689	O RING FILTER KIT K93			278115
60 05/07/2009	216689	FILTER TRANSMISSION ZF 4139-298-038E39HD119			278115
60 05/07/2009	216689	FILTER OIL K124 / L94UAB (H200W01)			278115
60 05/07/2009	216689		Tension ALL Wheel Nuts to OEM Specs		278115
60 05/07/2009	216689		D Service & Bus Safety Inspection		278115
60 05/07/2009	216689	TEXAMATIC 1888			278115
60 05/07/2009	216689		A Service & Bus Safety Inspection		278115
60 05/07/2009	216689		Tension ALL Wheel Nuts to OEM Specs		278115
60 04/30/2009	215059	0368030 ORING	Creditor #-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G66437 Receiving #-68142 Date :2009-04-30		277370
60 04/30/2009	215059	1801737 GASKET	Creditor #-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G66437 Receiving #-68142 Date :2009-04-30		277370
60 04/30/2009	216101	GLOBE FESTOON 24V5W			277370
60 04/30/2009	216101	GLOBE S/CONTACT 24V-10W			277370
60 04/30/2009	216101	STOP LAMP LENS			277370
60 04/30/2009	216101	GLOBE STOP AND TAIL 24V 21/5W			277370
60 04/30/2009	216101	Replace red brake lens	Replaced		277370
60 04/30/2009	216101	Replace top brake globe	Replaced		277370
60 04/30/2009	216101	Replace park light	Replaced		277370
60 04/29/2009	215985	Add coolant	Added		277136
60 04/28/2009	215059	Replace turbo	BEN: R/tested & checked turbo		277043
60 04/28/2009	215059	Replace turbo	R/tested checked turbo		277043
60 04/27/2009	215059	Replace turbo	BEN: Replaced boost pump & turbo		277043
60 04/27/2009	215059	Replace turbo	Fitted turbo & boost pump		277043
60 04/27/2009	215059	CLAMP 1433190	Creditor #-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G66219 Receiving #-67983 Date :2009-04-27 60		277043
60 04/27/2009	215059	GASKET 1511652	Creditor #-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G66219 Receiving #-67983 Date :2009-04-27 60		277043
60 04/27/2009	215059	TURBO 1766754	Creditor #-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G66219 Receiving #-67983 Date :2009-04-27 60		277043
60 04/27/2009	215059	TURBO CLAMP SCANIA L94UAB			277043
60 04/24/2009	215059	Replace turbo			277043
60 04/24/2009	215059	Replace turbo	BEN: Start inserting turbo		277043
60 04/23/2009	215059	Replace turbo			277043
60 04/23/2009	215059	Replace turbo	BEN: Remove turbo		277043
60 04/22/2009	215325	Bus lacking power at Brighton Terminus.	Removed turbo		277043
60 04/22/2009	215352	Breakdown - Brighton Terminus - OUT 4.00 pm BACK 5.00 pm -	Drive to Brighton terminus & c/o bus & bring bus back to MT depot.		276889
60 04/21/2009	215059	Heating not working	Att by Moorabbin Transit . Turbo shaft broken (replaced turbo)		276889
60 04/21/2009	215059	Heating not working	Blown fuse on boost pump		276889
60 04/21/2009	215059	Heating not working	Checked found fuse blown needs new boost pump		276889
60 04/21/2009	215059	RELAY 24V MERC 0500LE INDICATORS			276758
60 04/20/2009	215059	Heating not working	Checked demister taps		276758
60 04/20/2009	215059	Heating not working	Found electrical fault on boost pump		276758
60 04/17/2009	214790	24V INVERTER 4-13W			276549
60 04/17/2009	214790	Transformer no good	Replaced		276549
60 04/17/2009	212961	Replace O/S rear clip in strip & paint (Checked 5/2/09 ser	Secured clip in strip		276549
60 04/17/2009	212961	Drivers window sliders - repair (Checked 5/2/09 servicable	Removed window & slider replaced sliding belt replaced windows & sliding track		275409
60 04/14/2009	214424	GLOBE FESTOON 24V-3W			276171
60 04/14/2009	214424	Replace emergency exit globe	Replaced		276171
60 04/09/2009	214236	Bus wont start	Jump started		276056
60 04/09/2009	214236	Bus wont start	Jump started		276056
60 04/06/2009	213891	Bus wont start	Jump started		275409
60 04/03/2009	213547	Repair saloon light	Repaired		275409
60 04/03/2009	213547	Repair concertino suport	Ass Greg with repairs to concertina		275409
60 04/03/2009	213547	Repair concertino suport	Repaired concertina r/tested		275409
60 04/02/2009	213547	GUIDING PROFILE SCANIA TURNTABLE			275409
60 04/02/2009	213547	Repair idler pulley	Repaired		275409
60 04/02/2009	212961	SLIDING CARRIAGE SCANIA TURNTABLE			275409
60 04/02/2009	213547	Repair concertino suport	Repairing concertina damage go to Volgren to weld part start to put back together		275409
60 03/30/2009	212961	Drivers window sliders - repair (Checked 5/2/09 servicable	Parts ordered		275409
60 03/06/2009	210342	COMPRESSOR OIL AIR CON	Creditor #-ACT001 ACTROL (AC:330639) P/O #:G64771 Receiving #-66719 Date :2009-03-06 BUS 60		275409
60 03/05/2009	210342	EVAPORATOR/CONDENSOR MOTOR BRUSHES			275409
60 03/05/2009	210342	FILTER DRIER 5/8			275409
60 03/05/2009	210342	AIR CON REFRIDGERANT			275409
60 03/04/2009	210342	Service as per list. Removed both small comps and check valv	UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensorpressure switches; check evaporator auto fan speed; check de-ice cut out/in;check operation of fresh air ram; check electrical centre connections lightsand operation		275409
60 03/03/2009	210342		Check boost pump condition		275409
60 03/03/2009	210342		Check & replace electric motor brushes		275409
60 03/03/2009	210342		Replace compressor oil		275409
60 03/03/2009	210342		Replace filter drier		275409
60 03/03/2009	210342		D Service		275409
60 03/03/2009	210342		C Service		275409
60 03/03/2009	210342		B Service		275409
60 03/03/2009	210342		Replace filter drier		275409
60 03/03/2009	210342		Replace compressor oil		275409
60 03/03/2009	210342	FRONT UNIT ONLY. Fit new 2nd hand valve plate to unloader si	UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensorpressure switches; check evaporator auto fan speed; check de-ice cut out/in;check operation of fresh air ram; check electrical centre connections lightsand operation		275409
60 03/03/2009	210342		CONDENSOR AREA: Clean condensor coils; check boltsclamps for tension		275409

60 03/03/2009	210342	INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condensor fan grills	275409
60 03/03/2009	210342	EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check boltsclamps & fittings; clean condensate drains; clean drip tray	275409
60 03/03/2009	210342	REFRIGERATION FILTER DRYER: Replace filter dryer; check pump operation;	275409
60 03/03/2009	210342	COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose	275409
60 03/03/2009	210342	DRIVE PULLEY'S: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear	275409
60 03/03/2009	210342	DRIVE PULLEY'S: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;	275409
60 03/03/2009	210342	COMPRESSOR DRIVE BELTS: Inspect belt wear; Retension belts;	275409
60 03/03/2009	210342	FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)	275409
60 03/03/2009	210342	Clean R/A & F/A filters; Inspect and report on condition; Replace filter media	275409
60 02/25/2009	209736	GLOBE FESTOON 24V-3W	275409
60 02/25/2009	209736	REPLACE EMERGENCY EXIT GLOBE	275409
60 02/24/2009	209697	JUMP START BUS	275232
60 02/24/2009	209697	JUMP START BUS	275409
60 02/13/2009	205338	SUPPLY AND FIT DECALS	273771
60 02/11/2009	208537	GLOBE FESTOON 24V-3W	273376
60 02/11/2009	208537	Replace emergency exit globe	273376
60 02/06/2009	208124	Replace flurosent light	272928
60 02/05/2009	206703	REPAIR THROTTLE	272754
60 02/05/2009	207928		272928
60 02/05/2009	207928		272754
60 02/05/2009	207928		272754
60 02/03/2009	207789	N/S rear section clearance light covers missing	272280
60 01/23/2009	206703	1530697 SENDER T13	271153
60 01/22/2009	206703	No throttle at all and comes good	271130
60 01/21/2009	206703	No throttle at all and comes good	271130
60 01/21/2009	206703	No throttle at all and comes good	271130
60 01/21/2009	206779	GLOBE+HOLDER INSTRUMENT (GREY)	271130
60 01/21/2009	206779	Replace dash lights	271130
60 01/21/2009	206831	Breakdown - Dandenong Nth - OUT 6.00 am BACK 7.30 am - No a	271130
60 01/19/2009	206552	Check for NO acceleration	270813
60 01/19/2009	206535	LED CLEARANCE LIGHT (RED AMBER)	270813
60 01/19/2009	206535	Replace dash light globe	270813
60 01/09/2009	200858	D BUSH STABILIZER BAR FRONT	269728
60 01/09/2009	205338	Accident damage no 18926 - Replace o/s trailer panels 123	269728
60 01/09/2009	205338	AMBER REFLECTOR SIDE MOUNT	269728
60 01/08/2009	205338	Polish exterior panels/headers & touch up paint work	269728
60 01/08/2009	205338	Accident damage no 18926 - Replace o/s trailer panels 123	269728
60 01/07/2009	200858	Check stabilised bar bushes - ordered bushes	269728
60 01/07/2009	205338	Accident damage no 18926 - Replace o/s trailer panels 123	269728
60 01/07/2009	205338	Body damage near fuel filler	269728
60 01/07/2009	205338	O/S body damage	269728
60 01/06/2009	200858	EMERGENCY EXIT LIGHT	269728
60 01/06/2009	200858	Replace emergency light cover	269728
60 01/06/2009	205338	Accident damage no 18926 - Replace o/s trailer panels 123	269728
60 01/05/2009	200858	Check stabilised bar bushes - ordered bushes	269728
60 01/05/2009	200858	Check stabilised bar bushes - ordered bushes	269728
60 12/31/2008	205021	Fit 2way radio	269384
60 12/23/2008	204481	Replace emergency light	268622
60 12/23/2008	204481	GLOBE FESTOON 24V-3W	268622
60 12/23/2008	204481	INTERIOR LIGHT COVER SUIT 570E200	268622
60 12/22/2008	204098	Check rear A/C	268355
60 12/19/2008	204098	Check 2way	268355
60 12/19/2008	204098	RELAY SOLID STATE	268522
60 12/18/2008	204098	Check rear A/C	268259
60 12/17/2008	204111	Right rear tyre on trailer losing tread & tyre looks out of	268259
60 12/17/2008	204052	Rear A/C red fault light on	268259
60 12/17/2008	204052	Drv entered - Air Cond Cooling Fault Light	268259
60 12/17/2008	204098	Check fluros	268259
60 12/17/2008	203998		268259
60 12/17/2008	203998		268259
60 12/17/2008	203998	AIR FILTER SCANIA CLEANED	268259
60 12/17/2008	203998		268259
60 12/15/2008	203826	Bus wont start	267620
60 12/08/2008	203277	Bus wont start	266662
60 12/03/2008	202895	REPLACE BELTS	266027
60 12/03/2008	202895	FAN BELT AIR/CON ARTIC VEE BELT B43	266027
60 12/02/2008	181524	2MM X 1200MM X 2400MM FLAT ALU	266027
60 12/02/2008	202720	Replace red lens	265796
60 12/02/2008	202709	Replace red lens	265796
60 12/02/2008	202709	LENS TO SUIT 2319 (RED)	265796
60 11/27/2008	202308	Top left parking light	265198
60 11/20/2008	201619	REPLACE FLUORESCENT TUBE	264326
60 11/18/2008	201148	ROAD SAFETY INSPECTIONS	264145
60 11/16/2008	201148	Annual inspection BC 115056	263513
60 11/14/2008	201023	REPLACE FLUORESCENT TUBE	263513
60 11/14/2008	201023	REPLACE FLUORESCENT TUBE	263513
60 11/12/2008	200858	Check stabilised bar bushes - ordered bushes	263209
60 11/12/2008	200779	A service	263209
60 11/12/2008	200779		263209
60 11/12/2008	200779	A service	263209
60 11/11/2008	200363	Paint rear bumper bar	263209
60 11/11/2008	200732	Paint front bumper bar	263209
60 11/11/2008	200734	Replace seat cushin No.9	263209
60 11/11/2008	200802	Secure all lower skit panels	263209
60 11/11/2008	200808	Replacelong vehicle decal - rear window - artic only	263209
60 11/11/2008	200808	Replacelong vehicle decal - rear window - artic only	263209
60 11/11/2008	200809	Replace emergency exit push button under b/bar	263209
60 11/11/2008	200812	Paint wheels	263209
60 11/11/2008	200363	Paint till stand	262911
60 11/11/2008	200363	Secure capsules - N/S rear No 5 trailer	263209
60 11/11/2008	200363	Clean graffiti - seats side walls	263209
60 11/11/2008	200363	Clean air condition filter secure vents	263209
60 11/11/2008	200363	Secure rear engine hatch door	263209
60 11/11/2008	200363	SCREW TORX 8 X 15MM SIDE PANEL	263209
60 11/11/2008	200363	PLATE CLAMPING SIDE PANEL	263209

60 11/11/2008	200801 Replace 23 panels O/S rear trailer & paint decals	Complited	263209
60 11/11/2008	200805 Repair 45 panels paint decals O/S trailer	Complited	263209
60 11/11/2008	200807 Repair & paint No 2 N/S trailer panel & decals	Completed	263209
60 11/11/2008	200817 N/S/R damage	Completed	263209
60 11/11/2008	200363 Rear bumper damage	C/O job	263209
60 11/11/2008	200363 LONG VEHICLE DECAL		263209
60 11/11/2008	200806 Repair & paint N/S 45 panels & decals - trailer	Completed	263209
60 11/10/2008	200364 O/S trailer - sway bar ball joint boot cracked (Checked 02/	C/O job	262911
60 11/10/2008	200364 Rust around bolt under A/C compressor	Checked OK	263209
60 11/10/2008	200364 Rust around bolt under A/C compressor	Checked OK	263209
60 11/10/2008	200364 Full steamclean	Completed	263209
60 11/10/2008	200364 Steamclean and check bell housing oil leak (Checked on 04/0	Check OK	263209
60 11/10/2008	200364 Full steamclean	Completed	263209
60 11/10/2008	200414 REPLACE EXIT LIGHT	REPLACE GLOBE	263209
60 11/10/2008	200414 GLOBE FESTOON 24V-3W		263209
60 11/10/2008	200364 Remove intercooler wash intercooler and radiator	Washed	263209
60 11/10/2008	200364 Coolant leak around N/S rear boost pump	Checked OK	263209
60 11/10/2008	200364 Remove intercooler wash intercooler and radiator	Washed	263209
60 11/10/2008	200363 Paint exterior mirrors and arms	Painted	263209
60 11/10/2008	200363 CENTRA CUSHION CLIP RH		263209
60 11/10/2008	200363 O/S/F bumper damaged		263209
60 11/10/2008	200363 Repair & paint rear bumper bar		263209
60 11/05/2008	181524 2MM X 1200MM X 2400MM FLAT ALU	Creditor #-:SMA001 SMART ALUMINIUM P/O #:G61198 Receiving #:63344 Date :2008-11-05 60	262479
60 11/03/2008	181975 POS 9 275/70R FLAT REAR CAP	Creditor #-:BEA001 BEAUREPAIRES P/O #:G61312 Receiving #:63270 Date :2008-11-03	262250
60 10/31/2008	182246 Replace fluroscent tube	Replaced	261990
60 10/29/2008	182000 ASSIST MECHANIC TO REPLACE TYRE POS 9		261638
60 10/29/2008	182000 ASSIST MECHANIC TO REPLACE TYRE POS 9	Replaced	261831
60 10/29/2008	181975 FIX FLAT TYRE POS 9	Replaced	261638
60 10/27/2008	181725 Replace tyre pos 2 - uneven wear	Replaced	261129
60 10/24/2008	181521	Replace final drive oil	261129
60 10/24/2008	181521	Replace power steering filter	261129
60 10/24/2008	181521	Replace hydraulic fan filter and top up oil	261129
60 10/24/2008	181521	Replace air dryer cansiter	261129
60 10/24/2008	181521	Inspect bus as per inspection sheet	261319
60 10/24/2008	181521	Adjust valve clearances	261129
60 10/24/2008	181521	Adjust valve clearances	261129
60 10/24/2008	181521	Replace hydraulic fan filter and top up oil	261319
60 10/24/2008	181521	Inspect bus as per inspection sheet	261129
60 10/24/2008	181521 GLOBE FESTOON 24V5W		261319
60 10/24/2008	181521	Replace fuel filters	261129
60 10/23/2008	181521	Adjust valve clearances	261129
60 10/23/2008	181521	Rekit quick release valve	261129
60 10/23/2008	181521 POWER STEER FILTER B10M		261129
60 10/23/2008	181521 FUEL FILTER ELEMENT SCANIA L94UAB (R90T / H7090WK10)		261129
60 10/23/2008	181521 FILTER FUEL K124 / LU94A (1411894 / H17WK05)		261129
60 10/23/2008	181521 HYDRAULIC FILTER L94UAB		261129
60 10/23/2008	181521 FILTER AIR DRYER KIT(HALDEX)		261129
60 10/23/2008	181521 RPM BORATE EP LUBE 220		261129
60 10/23/2008	181521	Replace coolant filter in engine cooling system	261129
60 10/23/2008	181521	Clean a/c filters	261129
60 10/23/2008	181521	Remove intercooler wash intercooler and raditor	261129
60 10/23/2008	181521	Adjust valve clearances	261129
60 10/23/2008	181524 Annual Body Inspection	Completed	261129
60 10/15/2008	180704 Mid air bag with small crack	Replaced airbag	260293
60 10/15/2008	180704 N/S F/rear air bag with small crack	Checked OK	260293
60 10/15/2008	180704 REAR AIR BAG (MID AXLE) SCANIA L94UAB		260382
60 10/15/2008	180704 Tighten turntable bolt and check		260293
60 10/15/2008	180704 DISC PADS SCANIA L94+0500 MERC		260382
60 10/15/2008	180704 WEAR SENSOR SCANIA DISC BRAKE		260382
60 10/15/2008	180704 Rear brake pads low approx 8mm	Replaced pads	260293
60 10/07/2008	179663 POS 7+8+9+10 275/70R REAR CAPS	Creditor #-:BEA001 BEAUREPAIRES P/O #:G60613 Receiving #:62541 Date :2008-10-07	259171
60 10/02/2008	179745 Replace rear tyres	Replaced rear tyres	258663
60 10/02/2008	179663 Replace tyre pos 78910 - bald	Replaced	258663
60 10/02/2008	179901 Replace inner panel bracket	Replaced	258663
60 10/02/2008	179901 LARGE CORNER GUSSET		258755
60 10/02/2008	179901 PLATE CLAMPING SIDE PANEL		258755
60 10/02/2008	179901 SCREW TORX 8 X 20MM SIDE PANEL		258755
60 10/02/2008	179594 FILTER OIL K124 / L94UAB		258494
60 10/02/2008	179594 FILTER TRANSMISSION ZF 4139-298-038		258494
60 10/02/2008	179594 O RING FILTER KIT K93		258494
60 10/02/2008	179594 FILTER AIR SCANIA USE AF25066		258494
60 10/02/2008	179594 ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL		258494
60 10/02/2008	179594 TEXAMATIC 1888		258494
60 10/02/2008	179594	D Service	258494
60 10/02/2008	179594	Tension ALL Wheel Nuts to OEM Specs	258494
60 10/02/2008	179594 GLOBE S/CONTACT 24V-10W		258663
60 10/02/2008	179594	D Service	258494
60 10/02/2008	179594		258494
60 10/02/2008	179594	Tension ALL Wheel Nuts to OEM Specs	258494
60 09/29/2008	179464 A.B.S Warning light comes onif you restart it clears but	Checked ABS light no fault checked power and starting engine is fine	258068
60 09/23/2008	178900 No stop light	Replaced brake light globe	257308
60 09/18/2008	178471 EMERGENCY EXIT GLOBE		256609
60 09/18/2008	178471 GLOBE FESTOON 24V-3W		256609
60 09/17/2008	178383 EMERGENCY EXIT GLOBE		256286
60 09/17/2008	178383 GLOBE FESTOON 24V-3W		256447
60 09/11/2008	177936 Replace emergency exit light globe	Replaced	255731
60 09/11/2008	177936 GLOBE FESTOON 24V-3W		255731
60 09/10/2008	176810 POS 1/2/3/4 275 70R 3 FRONT CA	Creditor #-:BEA001 BEAUREPAIRES P/O #:G59652 Receiving #:61758 Date :2008-09-10	255731
60 08/29/2008	176810 Replace tyre pos 1234 - bald	Replaced	253876
60 08/29/2008	175970 Grease nipple broken on tailshaft	Checked OK	253876
60 08/29/2008	176824 R/R. REAR (DRIVE) AXLE WHEELS & CHECK ALL BRAKES.	Checked OK	253876
60 08/28/2008	175970 O/S/R middle axle air bag leaking	Checked Ok	253876
60 08/28/2008	175970 N/S/R middle axle air bag leaking	Checked Ok	253876
60 08/28/2008	175970 Coolant leak near filling tank	Replaced hose	253876
60 08/28/2008	175970 1746824 CALIPER BOOTS	Creditor #-:BAN001 BANLAY PTY LTD P/O #:G59603 Receiving #:61424 Date :2008-08-28 60	253876

60 08/28/2008	175970	Check & replace front and middle axle rotors & pads as requ	Complete middle axles brakes & r/test	253876
60 08/28/2008	175970	While driving ABS light comes on	Checked OK	253876
60 08/28/2008	175970	N/S/R middle axle brake pads low	Checked OK	253876
60 08/28/2008	175970	O/S/R middle axle brake pads low	Checked OK	253876
60 08/28/2008	175970	O/S/F brake pad low	Checked OK	253876
60 08/28/2008	175970	N/S/F brake pad low	Checked OK	253876
60 08/28/2008	175970	Check & replace front and middle axle rotors & pads as requ		253876
60 08/27/2008	175970	OUTER HUB SEAL REAR SCANIA L94UAB+L113CRB		253876
60 08/27/2008	175970	SEAL INNER REAR AXLE SCANIA		253876
60 08/27/2008	175970	BRAKE CALIPER PISTON BOOT B12BLE		253876
60 08/27/2008	175970	Check & replace front and middle axle rotors & pads as requ	Battle with caliper bolts remove caliper & clean parts grease bearings & fit new hub seals	253876
60 08/27/2008	175970	Check & replace front and middle axle rotors & pads as requ	Removed & replaced middle discs	253876
60 08/26/2008	175970	Check & replace front and middle axle rotors & pads as requ	Strip middle axle disc battled with bolts	253876
60 08/22/2008	175970	WEAR SENSOR SCANIA DISC BRAKE		253876
60 08/22/2008	175970	Check & replace front and middle axle rotors & pads as requ	Started removing middle axle disc	253876
60 08/21/2008	175970	DISC BRAKE ROTORS	Creditor #:TRA004 TRADE BRAKE+CLUTCH CO. P/O #:G59412 Receiving #:61244 Date :2008-08-21 60	253876
60 08/21/2008	175970	DISC PADS SCANIA	Creditor #:TRA004 TRADE BRAKE+CLUTCH CO. P/O #:G59412 Receiving #:61244 Date :2008-08-21 60	253876
60 08/21/2008	175970	BRAKE ROTOR MIDDLE AXLE SCANIA	Creditor #:TRA004 TRADE BRAKE+CLUTCH CO. P/O #:G59412 Receiving #:61244 Date :2008-08-21 60	253876
60 08/21/2008	175970	Check & replace front and middle axle rotors & pads as requ	Refitted front brakes	253876
60 08/20/2008	175970	Check & replace front and middle axle rotors & pads as requ	Strip N/S front rotors	253876
60 08/20/2008	175970	Check & replace front and middle axle rotors & pads as requ	Removed both front rotors	253876
60 08/19/2008	175970	Check brakes	Removed front wheel to check brakes brakes are very low bus U/S	253876
60 08/18/2008	175867			253603
60 08/18/2008	175867		Tension ALL Wheel Nuts to OEM Specs	253603
60 08/18/2008	175867			253876
60 08/14/2008	175585	Replace emergency exit globe	Replaced	253287
60 08/14/2008	175585	GLOBE FESTOON 24V-3W		253287
60 08/12/2008	174853	POS 4 275/70R NEW	Creditor #:BEA001 BEAUREPAIRS P/O #:G59005 Receiving #:61011 Date :2008-08-12	252939
60 08/06/2008	174894	Change flat tyre	Changed	252187
60 08/06/2008	174853	Replace tyre pos 4 - bald punctured	Replaced	252187
60 08/06/2008	174894	Change flat tyre	Changed	252187
60 07/29/2008	174166	Replace emergency exit globe	Replaced	250922
60 07/29/2008	174166	GLOBE FESTOON 24V-3W		250922
60 07/19/2008	173434	Fit door brush screws	Fitted	249803
60 07/16/2008	172485	1327015 HAZARD SWHITCH	Creditor #:MUL001 MULTISPARES LTD P/O #:G58187 Receiving #:60187 Date :2008-07-16 60	249249
60 07/14/2008	172485	Hazard lights switch fallen under dash unable to switch off		249079
60 07/14/2008	172485	Drv entered - Elec & Light Hazard Lights	Replaced hazard switch	248823
60 07/09/2008	172348	NELT TENSIONER 1371788	Creditor #:MUL001 MULTISPARES LTD P/O #:G58144 Receiving #:60008 Date :2008-07-09 40N0903 BUS60	248452
60 07/09/2008	172647	Annual random audit	Completed audit	248452
60 07/09/2008	172702	Front heater don't work	Repaired front heater	248452
60 07/09/2008	172646		Completed A service	248452
60 07/09/2008	172646		Tension ALL Wheel Nuts to OEM Specs	248452
60 07/07/2008	172485	Hazard lights switch fallen under dash unable to switch off	Strip dash to switch hazards off	248254
60 07/07/2008	172485	Hazard lights switch fallen under dash unable to switch off	Temp repairs ordered parts	248095
60 07/05/2008	172415	Drivers side washers U.S		248095
60 07/05/2008	172415	Drv entered - Wipers & Washers Washers Not Working	Cleaned wiper washer lines	248095
60 07/04/2008	172348	BELT ALT W/PUMP CRANK SCANIA ARTIC		248095
60 07/04/2008	172348	Replaced a/c. belt & re-align compressors.	rep. a/c. belt re-aligned compressors	247985
60 07/04/2008	172348	Replaced a/c. belt & re-align compressors.	rep. a/c. belt re-aligned compressors	247985
60 07/03/2008	172267	BELT ALT W/PUMP CRANK SCANIA ARTIC		247985
60 07/03/2008	172267	BELT CRANK-TWIN A/C COMP SCANIA ARTIC		247985
60 07/03/2008	172267	A/C.Belts came off.	checked sent on road - No a/c.	247821
60 07/03/2008	172267	Service	Refitted a/c. belts	247985
60 07/01/2008	171956	IDLER PULLEY SCANIA ARTIC(No Grove Plastic)		247661
60 07/01/2008	171956	FAN BELT AIR/CON ARTIC VEE BELT B43		247661
60 07/01/2008	171956	CRANK TO PULLEY SCANIA 21/32X67		247661
60 07/01/2008	171956	BELT CRANK-TWIN A/C COMP SCANIA ARTIC		247661
60 07/01/2008	171956	BELT ALT W/PUMP CRANK SCANIA ARTIC		247661
60 07/01/2008	171956	SCANIA ALT BELT TENSIONER K1241B		247661
60 07/01/2008	171956	Replace main drive belt & repair/replace idler pulleys as r	rep. all belts & idlers r/tested & all o/k.	247459
60 06/30/2008	171933	Jack knife display when slow moving it is dangerous for whe	R/tested OK	247283
60 06/27/2008	171660	Rear A/C fault light on	Trace and repair fault in wiring	247115
60 06/24/2008	169733	POS 1	Creditor #:BEA001 BEAUREPAIRS P/O #:G56780 Receiving #:50601 Date :2008-06-24	246548
60 06/24/2008	168394	POS 1	Creditor #:BEA001 BEAUREPAIRS P/O #:G56054 Receiving #:50605 Date :2008-06-24	246548
60 06/06/2008	170071	Replace emergency exit globe	Replaced	244467
60 06/06/2008	170071	GLOBE FESTOON 24V-3W		244467
60 06/05/2008	170038	Breakdown - Springvale South - OUT 3.00 pm BACK 3.45 pm - G	C/O bus 145. Unable to fault bus	244309
60 06/03/2008	169733	Rep. tyre pos. 1 Flat spots	Rep. tyre pos. 1 Flat spots.	243906
60 06/02/2008	169710	Replace N/S/F tyre	Replaced	243672
60 06/02/2008	169621			243672
60 06/02/2008	169621		Tension ALL Wheel Nuts to OEM Specs	243672
60 06/02/2008	169621			243672
60 05/31/2008	169573	Front air bag going up & down when stopped	Checked OK	243672
60 05/31/2008	169573	Heater not working	Open heater taps	243672
60 05/31/2008	169573	Replace 2 seat cushions	Replaced	243672
60 05/28/2008	169227	Replace emergency exit light globe		243069
60 05/28/2008	169227	Replace emergency exit light globe	Replaced	243069
60 05/28/2008	169227	GLOBE FESTOON 24V-3W		243069
60 05/23/2008	168744	Replace emergency exit globe	Replaced	242493
60 05/23/2008	168744	GLOBE FESTOON 24V-3W		242751
60 05/20/2008	168394	Replaced tyre pos.1 - Bald	rep. tyre pos.1	241904
60 05/11/2008	167728	Suspension too high when travelling passengers can not get	Checked suspension height lower & normal	240752
60 05/07/2008	167395	Large A/C belt cracked and 1 missing		240181
60 05/07/2008	167395	Ribbed A/C belt needs replacing starting to come apart	Replaced A/C belt	240181
60 05/07/2008	167395	BELT CRANK-TWIN A/C COMP SCANIA ARTIC		240181
60 04/30/2008	166747	Replace A/C belts	Replaced	239185
60 04/30/2008	166743	Bus wont start	Jump started	239185
60 04/29/2008	166632	CRANK TO PULLEY SCANIA 21/32X67		238999
60 04/29/2008	166632	FILTER OIL K124 / L94UAB		238999
60 04/29/2008	166632	FILTER TRANSMISSION ZF 4139-298-038		238999
60 04/29/2008	166632	O RING FILTER KIT K93		238999
60 04/29/2008	166632	AIR FILTER SCANIA CLEANED		238999
60 04/29/2008	166632	ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL		238999
60 04/29/2008	166632	TEXAMATIC 1888		238999
60 04/29/2008	166632		D Service	238999

60 04/29/2008	166632	Tension ALL Wheel Nuts to OEM Specs	238999
60 04/29/2008	165733 AIR CON REFRIDGERANT		239185
60 04/29/2008	166632		238999
60 04/29/2008	166632	Tension ALL Wheel Nuts to OEM Specs	238999
60 04/24/2008	166319 Replace air con belt	Replaced	238516
60 04/22/2008	166084 Replace emergency exit globe	Replaced by Abdul	238202
60 04/22/2008	166084 GLOBE FESTOON 24V-3W		238350
60 04/18/2008	165733 Front air cond. not working in front section.		237648
60 04/16/2008	163417 POS 7+8		237417
60 04/07/2008	164745 FAN BELT AIR/CON ARTIC VEE BELT B43	Repair crack flare on left bank TX vac & gas	236264
60 04/05/2008	164745 Air con belt split - small one	Creditor #:BEA001 BEAUREPAIRES P/O #:G53896 Receiving #:48681 Date :2008-04-16 CAPS REAR	236105
60 03/18/2008	163417 Replace tyres pos. 7 & 8 - bald.	Replaced bottom belt	233771
60 03/17/2008	163375 Change tyres N/S/R	REP. TYRE POS. 7 & 8	233771
60 03/17/2008	163343	Changed & cleaned rim	233771
60 03/17/2008	163343 GLOBE INST 24V 2W	Tension ALL Wheel Nuts to OEM Specs	233895
60 03/17/2008	163343 Service		233771
60 03/15/2008	163257 No 1 air con not working	rep. dash controller	233580
60 03/15/2008	163257 A/C. Not cooling - blows warm air.	rep. dash controller all checked o/k.	233580
60 03/11/2008	162417 VALVE + HEAD GASKET SET	Creditor #:AIRO02 AIR INTERNATIONAL TRANSIT P/O #:G53685 Receiving #:47732 Date :2008-03-11	233108
60 03/06/2008	162417 Start service. Repair crack incross over left condensor coil	UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensor pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation	232550
60 03/06/2008	162417 Complete service remove replace valve plate & head gaskets	UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensor pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation	232550
60 03/04/2008	162417	C Service	232550
60 03/04/2008	162417	Replace compressor oil	232550
60 03/04/2008	162417	Replace filter drier	232550
60 03/04/2008	162417	B Service	232550
60 03/04/2008	162417	Clean R/A & F/A filters; Inspect and report on condition; Replace filter media	232550
60 03/04/2008	162417	FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)	232550
60 03/04/2008	162417	COMPRESSOR DRIVE BELTS: Inspect belt wear; Retension belts;	232550
60 03/04/2008	162417	DRIVE PULLEY'S: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;	232550
60 03/04/2008	162417	DRIVE PULLEY'S: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear	232550
60 03/04/2008	162417	COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose	232550
60 03/04/2008	162417	REFRIGERATION FILTER DRYER: Replace filter dryer; check pump operation;	232550
60 03/04/2008	162417	EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check boltsclamps & fittings; clean condensate drains; clean drip tray	232550
60 03/04/2008	162417	INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condensor fan grills	232550
60 03/04/2008	162417	CONDENSOR AREA: Clean condensor coils; check boltsclamps for tension	232550
60 03/04/2008	162417 Service rear unit as per list. Replace burnt terminals on	UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensor pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation	232550
60 03/04/2008	162417 5/8FLARE DRIER		232710
60 03/04/2008	162417 AIR CON REFRIDGERANT		232710
60 03/04/2008	162417 FILTER DRIER 5/8		232710
60 03/03/2008	162421 Repair to O/S trailer panel as required	Fit claw catch rear engine flap	232448
60 02/25/2008	153849 0489986 V BAR	Creditor #:BAN001 BANLAY PTY LTD P/O #:G50611 Receiving #:47443 Date :2008-02-25	231457
60 02/21/2008	159586 BUSH KIT SUIT JF STARTER MOTOR	Creditor #:PJL001 PJL DIESEL ELECTRIC P/O #:G52529 Receiving #:47387 Date :2008-02-21	231086
60 02/21/2008	159586 STARTER SOLENOID	Creditor #:PJL001 PJL DIESEL ELECTRIC P/O #:G52529 Receiving #:47387 Date :2008-02-21	231086
60 02/21/2008	159586 STARTER DRIVE SUIT JF	Creditor #:PJL001 PJL DIESEL ELECTRIC P/O #:G52529 Receiving #:47387 Date :2008-02-21	231086
60 02/06/2008	160401 Drv entered - Cool & AC Sys Not Operating	Found short at power board causing both condensor relays to fail	229029
60 02/06/2008	160401 RELAY SOLID STATE		229169
60 02/05/2008	159586 Service	Completed starter rebuild	227919
60 02/05/2008	160261 Mid axle hub sealing - n/s	Replaced seal replaced hub with grease instead of oil r/tested Ok	228850
60 02/05/2008	160261 HUB SEAL TAG AXLE SCANIA L94UAB		229029
60 02/05/2008	160261 Mid axle hub sealing - n/s	A. Halliwell. Removed N/S/M hub & hub seal cleaned and inspect bearings refit bearings and new hub seal r/tested & rechecked	229029
60 02/04/2008	160315 Replace O/S rear tyres	Replaced	229029
60 02/04/2008	160315 Replace headlight & park light globe	Replaced	229029
60 02/04/2008	160223 Service		228850
60 02/04/2008	160223	Tension ALL Wheel Nuts to OEM Specs	228850
60 02/04/2008	160223 AIR FILTER SCANIA CLEANED		228850
60 02/04/2008	160223 GLOBE INST 24V 2W		228850
60 02/04/2008	160223 HEAD LIGHT GLOBE 24V 70/75W		228850
60 02/04/2008	160223 Service	Changed air cleaner	229029
60 02/02/2008	160095 GLOBE FESTOON 24V5W		228850
60 02/01/2008	160095 Turn blinker out left side rear side	rep. globe	228666
60 01/29/2008	159586 Service	Cont starter rebuild	227919
60 01/29/2008	159679 Indicatro wont cancel	Steering wheel already fitted with s/steel indicator cancellor	228095
60 01/25/2008	159586 Service	Strip and order parts	227919
60 01/22/2008	159250 Indicators wont cancel itself	Repaired flashers	227536
60 01/22/2008	159250 Check starting curcuit - wont start sometime from key	Changed starter repaired indicator cancellor on steering wheel	227536
60 01/22/2008	159250 SCANIA STARTER MOTOR K93+L94		227698
60 01/21/2008	159187 Bus not starting at Brighton terminus.	bridge starter motor and return to depot	227308
60 01/21/2008	159155 Breakdown - Brighton - Starter motor not engaging - OUT 8.3	Attended by Moorabbin transit	227308
60 01/16/2008	158778 Wont start	Checked starter unable to fault	226734
60 01/15/2008	158757 Flat batterys Brighton terminus.	Checked batteries at Brighton terminus checked electrical system. Remove cover & checked power for starter no power to starter bridged solenoid to start bus. Req att.	226597
60 01/15/2008	158772 Breakdown - Brighton - Wont start - Dep 3.20 Ret 4.20	Attended by M/Transit - started from starter motor - GBS to repair	226597
60 01/09/2008	158212 Drv entered - Engine Lacking Power	Replaced seal and bracket on turbo intake pipe	225976
60 01/09/2008	158241 Replace N/S/R clearance lamp	Replaced	225976
60 01/09/2008	158241 GLOBE FESTOON 24V5W		225976
60 01/09/2008	158241 LAMP (RED+AMBER)		225976
60 01/09/2008	158212 Drv entered - Air System Leaking	R/tested	225976
60 01/09/2008	158212 TURBO CLAMP SCANIA L94UAB		225976
60 01/05/2008	157956 Replaced globe	rep. globe	225561
60 01/05/2008	157956 GLOBE+HOLDER INSTRUMENT (GREY)		225561
60 01/03/2008	157726 Fit O/S rear clearance lamp	Fitted	225134
60 01/03/2008	157726 LAMP (RED+AMBER)		225134
60 12/21/2007	157010 Service	A SERVICE	224101
60 12/21/2007	157010	Tension ALL Wheel Nuts to OEM Specs	224101
60 12/21/2007	157010 Service	A SERVICE	224101
60 12/21/2007	157010 Service	CLEANED UP GRAFFITTI	224101
60 12/21/2007	157010 Service	CLEANED UP GRAFFITTI	224101
60 12/14/2007	156453 Replaced globe	rep. globe	222853
60 12/14/2007	156453 GLOBE FESTOON 24V-3W		223110
60 11/27/2007	153574 ALUM BUMPER BAR	Creditor #:VOL001 VOLGREN AUSTRALIA P/L P/O #:G50543 Receiving #:45230 Date :2007-11-27	220635
60 11/23/2007	154843 Check tension on ^V bar bolt thru to diff.	checked o/k.	220136
60 11/23/2007	154843 Check tension on ^V bar bolt thru to diff.	checked o/k.	220136
60 11/21/2007	153849 V Bar bush cracked (Checked on 6/12/0624/01/0716/03/07	Replaced V bar	219815
60 11/21/2007	153849 V Bar bush cracked (Checked on 6/12/0624/01/0716/03/07	Replaced V bar	219815
60 11/21/2007	153849 Low air warning signal sender disconnected (warning keeps c	Replaced	219815
60 11/20/2007	153849 V Bar bush cracked (Checked on 6/12/0624/01/0716/03/07	Removed V bar	219815

60 11/20/2007	153849 V Bar bush cracked (Checked on 6/12/0624/01/0716/03/07	Removed V bar	219815
60 11/19/2007	153849 GLOBE FESTOON 24V5W		219815
60 11/18/2007	154000 Annual Inspection - BC 111591	Annual Inspection - BC 111591	219815
60 11/13/2007	153849 Steamclean all bus for RSI	Cleaned	219815
60 11/13/2007	153849 1361131 SENDER LOW AIR	Creditor #:BAN001 BANLAY PTY LTD P/O #:G50611 Receiving #:44920 Date :2007-11-13	219815
60 11/13/2007	153849 Low air warning signal sender disconnected (warning keeps c	Replaced	219815
60 11/12/2007	153849 V Bar bush cracked (Checked on 6/12/0624/01/0716/03/07		219815
60 11/12/2007	153849 Replace lock pin for O/S/R rear air bag		219815
60 11/12/2007	153849 Low air warning signal sender disconnected (warning keeps c		219815
60 11/12/2007	153849 INDICATOR LIGHT FRONT ARTIC		219815
60 11/12/2007	153849 O/S/F indicator lens cracked	Replaced assembly	219815
60 11/12/2007	153849 Coolant leak from header tank bottom hose	Repaired	219815
60 11/12/2007	153849 Remove wheel and check O/S mid axle brake pads	Checked OK	219815
60 11/09/2007	153662 Paint wheels	Paint	219815
60 11/09/2007	153662 Secure replace paint exterior mirrors and arms	Secure and paint	219815
60 11/09/2007	153662 Polish exterior panels/headers & touch up paint work	Polish and touch up	219815
60 11/09/2007	153662 Replace mud flaps - O/S/R trailer	Replace	219815
60 11/09/2007	153662 Polish & touch up front bumper bar	Polish and touch	219815
60 11/09/2007	153662 Secure all lower skit panels	Secured	219815
60 11/09/2007	153662 BOLT BUMPER 12MM X60MM BUTTON HEAD		219815
60 11/09/2007	153662 SCREW TORX 8 X 20MM SIDE PANEL		219815
60 11/09/2007	153662 REAR MARKER DECAL L/H		219815
60 11/09/2007	153662 REAR MARKER DECAL R/H		219815
60 11/09/2007	153662 Repair & repaint rear bumper bar & repaint	Repaired and paint	219815
60 11/09/2007	153662 Accident damage no 13621 - Polish n/s/r bumper bar corner	Repair	219815
60 11/08/2007	153574 Paint till stand	Painted	219815
60 11/08/2007	153574 Wheel chair ramp- operation & clean	Cleaned	219815
60 11/08/2007	153574 Secure clean adjust front mid & rear doors	Secured & cleaned	219815
60 11/08/2007	153574 Replace seat end cover caps as required	Replaced	219815
60 11/08/2007	153574 Replace passenger hand grips No 14 O/S & No 12 N/s	Replaced	219815
60 11/08/2007	153574 Clean air condition filter secure vents	Cleaned	219815
60 11/08/2007	153574 Clean graffiti - seats side walls in rear section	Cleaned	219815
60 11/08/2007	153574 Replace dash warning light decal - relaminate & fit	Replaced	219815
60 11/08/2007	153574 POWDER COATED NOTICE BOARDS		219815
60 11/08/2007	153574 CENTRA SEAT END CAPS		219815
60 11/08/2007	153574 Fit notice board	Fitted	219815
60 11/08/2007	153574 Polish & touch up lower panels No 7-8-9-10 & replace emerge	Polished & touched up	219815
60 11/07/2007	153429	Inspect bus as per inspection sheet	219612
60 11/07/2007	153429	Replace fuel filters	219612
60 11/07/2007	153429	Replace final drive oil	219612
60 11/07/2007	153429	Adjust valve clearances	219612
60 11/07/2007	153429	Replace power steering filter	219612
60 11/07/2007	153429	Rekit quick release valve	219612
60 11/07/2007	153429	Replace hydraulic fan filter and top up oil	219612
60 11/07/2007	153429	Replace air dryer cansiter	219612
60 11/07/2007	153429 POWER STEER FILTER B10M		219612
60 11/07/2007	153429 FILTER ELEMENT SCANIA L94UAB		219612
60 11/07/2007	153429 FILTER FUEL K124 / LU94A		219612
60 11/07/2007	153429 HYDRAULIC FILTER L94UAB		219612
60 11/07/2007	153429 FILTER AIR DRYER KIT(HALDEX)		219612
60 11/07/2007	153429 RPM BORATE EP LUBE 220		219612
60 11/07/2007	153429	Replace coolant filter in engine cooling system	219612
60 11/07/2007	153429	Clean a/c filters	219612
60 11/07/2007	153429	Adjust valve clearances	219815
60 10/31/2007	153073 FILTER OIL K124 / L94UAB		219118
60 10/31/2007	153073 FILTER TRANSMISSION ZF 4139-298-038		219118
60 10/31/2007	153073 O RING FILTER KIT K93		219118
60 10/31/2007	153073 AIR FILTER SCANIA CLEANED		219118
60 10/31/2007	153073 ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL		219118
60 10/31/2007	153073 TEXAMATIC 1888		219118
60 10/31/2007	153073	Tension ALL Wheel Nuts to OEM Specs	219118
60 10/31/2007	153073	D Service	219118
60 10/31/2007	153073		219118
60 10/31/2007	153073	Tension ALL Wheel Nuts to OEM Specs	219118
60 10/30/2007	152945 Annual body check	Completed	219027
60 10/30/2007	152925 Jackknife warning light is coming on.	Erase fault code r/test fault code did not come back fuelled and parked	219027
60 10/09/2007	151445 Drv entered - Suspension Leaning	Check suspension for leaks is OK	216430
60 10/08/2007	149133 POS 7+8+10	Creditor #:BEA001 BEAUREPAIRES P/O #:G49104 Receiving #:44137 Date :2007-10-08	216281
60 10/08/2007	151194 GLOBE FESTOON 24V-3W		216281
60 10/06/2007	151194 Emergency Exit light u/s	Replace globe	216281
60 10/05/2007	151164 Flat batteries	Jump start	216110
60 10/04/2007	149698 CLUTCH PACK FK40	Creditor #:AIR002 AIR INTERNATIONAL TRANSIT P/O #:G49319 Receiving #:44068 Date :2007-10-04	216110
60 10/04/2007	149698 CONSUMABLE DELIVERY CHARGE	Creditor #:AIR002 AIR INTERNATIONAL TRANSIT P/O #:G49319 Receiving #:44068 Date :2007-10-04	216110
60 09/24/2007	150115 Dash light u/s	Replace globe	214948
60 09/24/2007	150115 GLOBE+HOLDER INSTRUMENT (GREY)		214948
60 09/21/2007	149698 Drv entered - Heat & Demist Demisters Cold	Removed broken stud fromcrank shaft nose. Remove replace complete clutch assembly replace belts run up & check	214496
60 09/21/2007	149698 CRANK TO PULLEY SCANIA 21/32X67		214948
60 09/21/2007	149698 FAN BELT AIR/CON ARTIC VEE BELT B43		214948
60 09/17/2007	149728 Tidy up a/c idler post	Removed belts from pulley cable tied idler post in place	214343
60 09/12/2007	149250 Jack knife warning light and ABS warning light comes on - B	Road tested OK	213853
60 09/11/2007	149133 Replaced tyre pos.7 /8 /10 bald.	rep. tyres pos7 8 10 - Bald.	213669
60 09/10/2007	149080 Replace tyre pos 7-8-9-10	Replaced	213508
60 09/10/2007	149080 Replace tyre pos 7-8-9-10	Replaced rear tyres	213508
60 09/10/2007	149080 Replace brake light lens N/S/R/L	Replaced	213508
60 09/10/2007	149080 LENS TO SUIT 2319 (RED)		213508
60 09/10/2007	149080 Replace rear seat	Replaced	213508
60 09/10/2007	149050	Tension ALL Wheel Nuts to OEM Specs	213508
60 09/10/2007	149050		213508
60 09/06/2007	148816 GLOBE+HOLDER INSTRUMENT (GREY)		213185
60 09/05/2007	148816 Replace 1 dash globe	Replaced	213013
60 08/02/2007	146041 Replace salloon tube	Replaced	208632
60 08/02/2007	146041 Replace hand rail screw	Replaced	208632
60 08/02/2007	145958	Tension ALL Wheel Nuts to OEM Specs	208632
60 08/02/2007	145958		208632

60 08/02/2007	145958	GLOBE INST 24V 2W		208632
60 08/02/2007	145958			208632
60 07/31/2007	145747	Graffiti on rear of vehicle.	Cleaned	208285
60 07/26/2007	144885	Service	Completed starter motor rebuild	206630
60 07/25/2007	144885	BUSH KIT SUIT JF	Creditor #:PJL001 PJL DIESEL ELECTRIC P/O #:G46907 Receiving #:42329 Date :2007-07-25	207234
60 07/25/2007	144885	STARTER SOLENOID SUIT JF	Creditor #:PJL001 PJL DIESEL ELECTRIC P/O #:G46907 Receiving #:42329 Date :2007-07-25	207234
60 07/25/2007	144885	STARTER DRIVE SUIT JF	Creditor #:PJL001 PJL DIESEL ELECTRIC P/O #:G46907 Receiving #:42329 Date :2007-07-25	207234
60 07/25/2007	144885	Service	Continued to rebuild starter	206630
60 07/25/2007	145224	Left side rear clearance light out	Replaced globe	207234
60 07/25/2007	145224	GLOBE FESTOON 24V5W		207234
60 07/20/2007	144885	Service	start to rebuild starter	206630
60 06/30/2007	143416	N/S washer not working	cleaned out washer jets	204376
60 06/25/2007	142990	Replace small A/C belts	Replaced	203656
60 06/25/2007	142990	FAN BELT AIR/CON ARTIC VEE BELT B43		203826
60 06/25/2007	142990	Replace 1 steplight globe	Replaced	203656
60 06/25/2007	142990	Replace 1 emergency exit cover	Replaced	203656
60 06/25/2007	142990	Replace alternator tensioner & idler pulley	replaced	203656
60 06/25/2007	142990	EMERGENCY EXIT BUTTON PULL COVER		203826
60 06/25/2007	142990	GLOBE INDICATOR 24V-18W SINGLE CONTACT		203826
60 06/25/2007	142990	GLOBE FESTOON 24V-3W		203826
60 06/25/2007	142990	Replace emergency exit globe	Replaced	203656
60 06/25/2007	142930			203656
60 06/25/2007	142930		Tension ALL Wheel Nuts to OEM Specs	203656
60 06/25/2007	142930			203826
60 06/22/2007	142793	Replace interior light fluro	Replaced	203440
60 06/21/2007	142746	Top n/s. stop light u/s.	Replaced globe	203264
60 06/21/2007	142746	GLOBE INDICATOR 24V-18W SINGLE CONTACT		203440
60 06/18/2007	142415	Wont start all the time	Replace starter motor	202882
60 06/18/2007	142415	SCANIA STARTER MOTOR K93+L94		202964
60 06/15/2007	142242	Bus not starting Brighton terminus.	Go to Brighton & start bus by hitting starter motor & return to depot.	202758
60 06/15/2007	142286	Top rear tail light not working	Replace globe	202758
60 06/15/2007	142286	GLOBE S/CONTACT 24V-10W		202882
60 06/15/2007	142318	Breakdown - Brighton - wont start - Dep 3.00 Ret 3.45	Starter motor faulty - Knock starter motor and started	202758
60 05/26/2007	140682	Service	rep. globe	200460
60 05/25/2007	140682	Top left stop light u/s.	rep. globe	200460
60 05/25/2007	140682	STOP LAMP LENS		200634
60 05/25/2007	140702	Make up cover plate.	fitted cover plate	200460
60 05/17/2007	139809	1335482 WIPER RELAY	Creditor #:BAN001 BANLAY PTY LTD P/O #:G43935 Receiving #:40731 Date :2007-05-17	199466
60 05/16/2007	140066	Engine does not start from ignition key only from the rear	Repaired engine door switch	199316
60 05/16/2007	139994	Replace interior fluro light	Replaced	199316
60 05/16/2007	140066	Brake light not working	Replaced globe	199316
60 05/15/2007	139952	Change front tyres	Changed	199191
60 05/15/2007	139592	POS 1	Creditor #:BEA001 BEAUREPAIRES P/O #:G43812 Receiving #:40695 Date :2007-05-15	199191
60 05/15/2007	139882	Annual random audit	Completed	199191
60 05/15/2007	139881	FILTER OIL K124 / L94UAB		199191
60 05/15/2007	139881	FILTER TRANSMISSION ZF 4139-298-038		199191
60 05/15/2007	139881	O RING FILTER KIT K93		199191
60 05/15/2007	139881	FILTER AIR SCANIA USE AF25066		199191
60 05/15/2007	139881	ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL		199191
60 05/15/2007	139881	TEXAMATIC 1888		199191
60 05/15/2007	139881		D Service	199191
60 05/15/2007	139881		Tension ALL Wheel Nuts to OEM Specs	199191
60 05/15/2007	139881			199191
60 05/15/2007	139881		Tension ALL Wheel Nuts to OEM Specs	199191
60 05/14/2007	139809	Wipers do not stop in the off position	Replaced wiper switch arm and wiper relay	199018
60 05/11/2007	139624	Replace N/S/F tyre	Replaced	198974
60 05/11/2007	139592	Replaced tyre pos.1 - Flat	Replaced	198974
60 05/11/2007	139624	Replace N/S/F tyre	Replaced	198974
60 05/09/2007	138667	clear fault codes	Creditor #:BAN001 BANLAY PTY LTD P/O #:G43272 Receiving #:40545 Date :2007-05-09	198561
60 05/07/2007	138667	1492875 EDC TEMP SENSOR	Creditor #:BAN001 BANLAY PTY LTD P/O #:G43379 Receiving #:40458 Date :2007-05-07	198133
60 05/04/2007	138667	Service	ASSIST WITH REPAIRS.	198103
60 05/04/2007	138667	Service	Fit wires in junction box air cleaner and road test	198103
60 05/03/2007	138667	Service	CHECKED E.D.C SENDER	198103
60 05/03/2007	138667	Service	ASSIST WITH REPAIRS.	198103
60 05/02/2007	138667	EDC light stays on	Replaced hose at header tank Ass Greg	198103
60 05/02/2007	138667	EDC light stays on	Repaired coolant leak near header tank	198103
60 05/02/2007	138667	EDC light stays on	Removed air cleaner ordered parts	198103
60 05/01/2007	138667	EDC light stays on	Took to Banlay went for part checked out EDC loom	198103
60 05/01/2007	138667	EDC light stays on	Assisted in finding fault	198103
60 04/23/2007	138142	Replace N/S rear clearance lens	Replaced	197669
60 04/23/2007	138142	LAMP (RED+AMBER)		197669
60 04/17/2007	137729	Replace fluro	Replaced	196875
60 04/11/2007	137298	Coolant leak	Repaired coolant leak on T connection on breather hoses	196273
60 04/02/2007	136724	Tail light out	Replaced globe	195478
60 04/02/2007	136724	GLOBE INDICATOR 24V21W SINGLE CONTACT		195478
60 03/27/2007	136279	Replace exit light globe	Replaced	194933
60 03/27/2007	136279	GLOBE FESTOON 24V-3W		194933
60 03/26/2007	136160	Replace exit light globe	Replaced	194761
60 03/26/2007	136160	GLOBE FESTOON 24V-3W		194761
60 03/21/2007	135815	Check tyre pressure	Adjusted pressure	194018
60 03/21/2007	135569	POS 3+4+5+6	Creditor #:BEA001 BEAUREPAIRES P/O #:G40789 Receiving #:39211 Date :2007-03-21	194307
60 03/19/2007	135569	TYRES WORN POS 3+4+5+6	Replaced	193769
60 03/17/2007	135501	Replaced globe	rep. globe	193769
60 03/16/2007	135480	Replaced tyres pos.9 & 10 bald.	rep. tyres	193769
60 03/16/2007	135429		A service	193769
60 03/16/2007	135429		Tension ALL Wheel Nuts to OEM Specs	193769
60 03/16/2007	135429	Service	A service	193769
60 03/11/2007	135022	L/H middle on side indicator lens missing	Replace lens	192825
60 03/11/2007	135022	Hazzaed light rear u/s	Checked ok	192825
60 03/11/2007	135022	LENS TO SUIT 2030 LAMP		192825
60 02/19/2007	132843	LENS TO SUIT 2030 LAMP		190375
60 02/19/2007	132843	Service both units as per list	Replaced evap relay. Replace head & valve plate gaskets. Pressure test & vac test. Replace unloader stem	190375
60 02/16/2007	133242	Check electrical loom in turntable	Check wiring loom	190375
60 02/16/2007	133242	Check electrical loom in turntable	Check wiring loom	190375
60 02/13/2007	132843	FAN BELT AIR/CON ARTIC		190375

60 02/13/2007	132843	FILTER DRIER 5/8	190375
60 02/13/2007	132843	5/8FLARE DRIER	190375
60 02/13/2007	132843	AIR CON REFRIDGERANT	190375
60 02/13/2007	132843	GASKET FLANGE	190375
60 02/13/2007	132843	RELAY SOLID STATE	190375
60 02/13/2007	132843	CRANK TO PULLEY SCANIA 21/32X67	190375
60 02/13/2007	132843		190375
60 02/13/2007	132843	Replace compressor oil	190375
60 02/13/2007	132843	Replace filter drier	190375
60 02/13/2007	132843	B Service	190375
60 02/13/2007	132843	Found compressor failed commission test. Foun unloader assembly N/S	190375
60 02/13/2007	132843	Clean R/A & F/A filters; Inspect and report on condition; Replace filter media	190375
60 02/13/2007	132843	FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)	190375
60 02/13/2007	132843	COMPRESSOR DRIVE BELTS: Inspect belt wear; Retension belts;	190375
60 02/13/2007	132843	DRIVE PULLEY'S: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;	190375
60 02/13/2007	132843	DRIVE PULLEY'S: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear	190375
60 02/13/2007	132843	COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose	190375
60 02/13/2007	132843	REFRIGERATION FILTER DRYER: Replace filter dryer; check pump operation;	190375
60 02/13/2007	132843	EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check boltsclamps & fittings; clean condensate drains; clean drip tray	190375
60 02/13/2007	132843	INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condensor fan grills	190375
60 02/13/2007	132843	CONDENSOR AREA: Clean condensor coils; check boltsclamps for tension	190375
60 02/13/2007	132843	UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensor pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation	190375
60 01/24/2007	131460	Tension ALL Wheel Nuts to OEM Specs	188653
60 01/24/2007	131460	A SERVICE	188653
60 01/09/2007	128740	Front section of air conditioner blows hot air.	186951
60 01/09/2007	128740	COMPRESSOR OIL AIR CON	187271
60 01/08/2007	128740	Front section of air conditioner blows hot air.	186951
60 01/05/2007	128740	COMPLETE GASKET SET	186951
60 01/05/2007	128740	CONSUMABLE DELIVERY CHARGE	186951
60 12/21/2006	129306	Rear a/c no power showing on	185508
60 12/21/2006	128740	BASE GASKET	185508
60 12/21/2006	128740	VLAVE PLATE GASKET	185508
60 12/21/2006	128740	CONSUMABLE DELIVERY CHARGE	185508
60 12/14/2006	128740	Air conditioner blows hot air.	184851
60 12/06/2006	128107		183819
60 12/06/2006	128107		183819
60 12/06/2006	128107		183819
60 12/04/2006	127764	Bus slow on take off.	183579
60 12/04/2006	127764	Bad air leaks - takes long time to build up air	183579
60 11/30/2006	127761	BATTERY 800CCA	183445
60 11/30/2006	127761	Replace batteries	183263
60 11/30/2006	127761	Bus wont start	183263
60 11/30/2006	127764	Bad air leaks - takes long time to build up air	183263
60 11/22/2006	126237	ROAD SAFETY INSPECTIONS	182567
60 11/19/2006	126237	Annual Inspection - BC 097997	182162
60 11/18/2006	126623	Interior light u/s	182162
60 11/17/2006	126515	Front axle stabiliser bushes worn.	182162
60 11/17/2006	126515	Steam clean all bus.	182162
60 11/16/2006	125903	Air dryer leaking on exhaust.(Checked on 6/9/06 serviceable	182084
60 11/16/2006	125903	Air dryer leaking on exhaust.(Checked on 6/9/06 serviceable	182162
60 11/15/2006	125903	A/C.idler for crank belt tensioner & tensioner pulley need	182162
60 11/15/2006	126262	Rear bumper bar damaged	182162
60 11/15/2006	126262	Repair & repaint N/S panel No 11Repair & repaint N/S/R cl	182162
60 11/15/2006	125903	Air dryer leaking on exhaust.(Checked on 6/9/06 serviceable	182084
60 11/15/2006	125903	SCANIA AIR DRYER REPAIR KIT L94UAB	182162
60 11/14/2006	125903	A/C.idler for crank belt tensioner & tensioner pulley need	182162
60 11/14/2006	126247	Replace Air Supply decal	182162
60 11/14/2006	126247	Repair & repaint O/S/R lower panels 91011&12Decals to b	182162
60 11/14/2006	126247	Secure clean adjust rear doors - loose middle door	182162
60 11/14/2006	126247	Replace Emergency Exit Push Button Under B/Bar	182162
60 11/14/2006	126247	Polish exterior panels/headers & touch up paint work	182162
60 11/14/2006	126247	L/H/S panel No 7-8-9 and body rail. Damaged below window	182162
60 11/14/2006	126247	N/S/F body scratched	182162
60 11/14/2006	126247	Polish & touch up front bumper bar	182162
60 11/14/2006	126247	Paint wheels	182162
60 11/14/2006	126247	O/S/R body scratched	182162
60 11/14/2006	125903	A/C IDLER PULLEY BEARING	182162
60 11/14/2006	125904	Polish exterior panels/headers & N/S top header & touch up	182162
60 11/14/2006	125904	O/S/R Trailer damaged	182162
60 11/14/2006	125904	Polish & touch up N/S lower panel No 3Replace N/S lower p	182162
60 11/14/2006	125904	N/S/F Bumper damage	182162
60 11/13/2006	126145	Secure clean & adjust front middle & rear doors	182162
60 11/13/2006	126145	Secure rubbish bin and broom	182162
60 11/13/2006	126145	Secure replace passenger hand grips R/H/S No 12	182162
60 11/13/2006	126145	Drivers seat - secure lub replace	182162
60 11/13/2006	126145	Wheel chair ramp - operation and clean	182162
60 11/13/2006	126145	Secure front of rear door hand rail/modesty panel	182162
60 11/13/2006	126145	Secure rear of middle door modesty panel	182162
60 11/13/2006	125904	Front fibreglass damage	182162
60 11/13/2006	125904	Accident damage no 12075 - Repair o/s rtrailer panels 345	182162
60 11/10/2006	125903	Drive axle n/s.outer rim U.S.	182162
60 11/10/2006	125901	Replace o/s/r. air bag	182084
60 11/10/2006	125903	Pully Idler Scania Artic (No Grove Plastic)	182162
60 11/10/2006	125903	A/C.idler for crank belt tensioner & tensioner pulley need	182162
60 11/10/2006	125903	BEARING (ALTERNATOR)SCANIA PULLEY	182162
60 11/10/2006	125903	Dip stick tube - needs to be fitted properly	182162
60 11/10/2006	125903	Slight oil leak bell-housing	182162
60 11/10/2006	126036	Indicators wont self cancel.	182162
60 11/10/2006	125903	Repair engine oil dip stick outer cable.	182162
60 11/10/2006	125901	Replace O/S/F indicator lens	182162
60 11/10/2006	125904	Clean air condition filter secure vent X 2	182162
60 11/10/2006	125904	Paint wheels	182162
60 11/10/2006	125904	Clean air condition filter secure vents	182162
60 11/10/2006	125904	Replace Air Supply decal	182162
60 11/10/2006	125904	Paint till stand	182162
60 11/10/2006	125904	Replace Exit Only on middle door	182162
		Replaced all gaskets	
		Creditor #:AIR002 AIR INTERNATIONAL TRANSIT P/O #:37587 Receiving #:37518 Date :2007-01-05 60	
		Creditor #:AIR002 AIR INTERNATIONAL TRANSIT P/O #:37587 Receiving #:37518 Date :2007-01-05 60	
		No a/c compressor off for repairs	
		Creditor #:AIR002 AIR INTERNATIONAL TRANSIT P/O #:37149 Receiving #:37311 Date :2006-12-21	
		Creditor #:AIR002 AIR INTERNATIONAL TRANSIT P/O #:37149 Receiving #:37311 Date :2006-12-21	
		Creditor #:AIR002 AIR INTERNATIONAL TRANSIT P/O #:37149 Receiving #:37311 Date :2006-12-21	
		Run unit up found comp had high suction pressure remove compressor & pull down found valve plate and base gaskets had blown apart	
		Tension ALL Wheel Nuts to OEM Specs	
		Checked OK	
		Overhauled air dryer & roadtested	
		Replaced	
		Jumpstarted	
		Check air build up	
		Creditor #:ROA001 Road Safety Inspections P/O #:36292 Receiving #:36459 Date :2006-11-22	
		Annual Inspection - BC 097997	
		Replace globe	
		Fit shims	
		Steam clean	
		Removed air dryer & rekittd. Refitted & checked OK	
		Began to remove air dryer assisted Tristram	
		Fitted A/C Idler bearing pulley belts & adjusted	
		prepared & repainted	
		prepared & repainted	
		Started to remove air dryer. Then had to refit to move bus	
		Fitted A/C Idler bearing pulley belts & adjusted	
		Replaced	
		Repainted	
		Replaced	
		Polished	
		Repaired	
		Repaired	
		Polished	
		Creditor #:CON001 CONSOLIDATED BEARING CO. P/O #:36215 Receiving #:36246 Date :2006-11-14 60	
		polished & touched up	
		repaired & touched up.	
		polished & touched up	
		repainted bumper bar	
		secured & adjusted	
		secured o/k	
		secured grips	
		checked o/k.	
		cleaned & checked ramp	
		secured hand rail	
		secured rear of midle door modesty panel	
		repaired & touched up	
		repaired polished & touched up	
		Repaired	
		Replaced	
		Waiting on parts	
		Glued pipe in	
		Checked OK	
		Replaced steering wheel	
		Glued pipe in	
		Replaced	
		cleaned o/k	
		painted wheels	
		cleaned filters	
		rep. decal	
		repainted	
		Replace decal	

60 11/10/2006	125904 Clean back seat - rubbish	Clean back seat rubbish	182162
60 11/10/2006	125904 Secure replace paint exterior mirrors and arms	Secured and painted exterior mirrors and arms	182162
60 11/10/2006	125904 Secure all lower skit panels	Secured panels	182162
60 11/10/2006	125904 Replace fleet number on dash - in yellow	Replace dash flit number	182162
60 11/10/2006	125904 Clean graffiti - floor seats side walls	Cleaned floor and seats and walls	182084
60 11/10/2006	125904 Replace Exit Only on rear doors	Replace decal	182162
60 11/10/2006	125903 Air dryer leaking on exhaust.(Checked on 6/9/06 serviceable	Ordered parts	182084
60 11/10/2006	125904 Accident damage No 12227 Repair / replace n/s. lower panel	repaired & touched up	182162
60 11/10/2006	125904 Accident damage no 12075 - Repair o/s rtrailer panels 345	repaired	182162
60 11/09/2006	125803	Replace hydraulic fan filter and top up oil	182012
60 11/09/2006	125803	Replace air dryer cansiter	182012
60 11/09/2006	125803 POWER STEER FILTER B10M		182012
60 11/09/2006	125803 FILTER ELEMENT SCANIA L94UAB		182012
60 11/09/2006	125803 FILTER FUEL K124 / LU94A		182012
60 11/09/2006	125803 HYDRAULIC FILTER L94UAB		182012
60 11/09/2006	125803 FILTER AIR DRYER KIT(HALDEX)		182012
60 11/09/2006	125803 RPM BORATE EP LUBE 220		182012
60 11/09/2006	125803	Replace coolant filter in engine cooling system	182012
60 11/09/2006	125803	Clean a/c filters	182012
60 11/09/2006	125803 REAR AIR BAG (DRIVE AXLE) SCANIA L94UAB		182084
60 11/09/2006	125803		182162
60 11/09/2006	125803 INDICATOR LIGHT FRONT ARTIC		182162
60 11/09/2006	125803	Inspect bus as per inspection sheet	182012
60 11/09/2006	125803		182012
60 11/09/2006	125803	Replace fuel filters	182012
60 11/09/2006	125803	Replace final drive oil	182012
60 11/09/2006	125803	Adjust valve clearances	182012
60 11/09/2006	125803	Replace power steering filter	182012
60 11/09/2006	125803	Rekit quick release valve	182012
60 11/09/2006	125901 Replace n/s/r. air bag	Replaced N/S/R front	182084
60 11/09/2006	125901 Replace n/s/r. air bag	Replaced N/S/R front	182162
60 10/31/2006	125186 Annual body check list		181259
60 10/25/2006	124753 Annual body check		180646
60 10/25/2006	124834 Short compressor belts cracked		180646
60 10/18/2006	124243 GLOBE INDICATOR 24V21W SINGLE CONTACT		179821
60 10/18/2006	124243 INDICATOR LIGHT FRONT ARTIC		179821
60 10/18/2006	124243 Left front indicator broken (opposite driver side)		179676
60 10/16/2006	123597 POS 1		179319
60 10/16/2006	123839 FILTER TRANSMISSION ZF 4139-298-038		179149
60 10/16/2006	123839 O RING FILTER KIT K93		179149
60 10/16/2006	123839 FILTER AIR SCANIA USE AF25066		179149
60 10/16/2006	123839 ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL		179149
60 10/16/2006	123839 TEXAMATIC 1888		179149
60 10/16/2006	123839	D Service	179149
60 10/16/2006	123839	Tension ALL Wheel Nuts to OEM Specs	179149
60 10/16/2006	123839 FILTER OIL K124 / L94UAB		179149
60 10/16/2006	123839		179149
60 10/16/2006	123839	Tension ALL Wheel Nuts to OEM Specs	179149
60 10/11/2006	122156 POS 7+8+9+10		178820
60 10/11/2006	123597 Replaced tyre pos. 1 Flat.		178820
60 10/11/2006	123597 Replaced tyre pos. 1 Flat.		178820
60 10/03/2006	122505 FIT WEAR PLATE TO TURNTABLE		177612
60 09/26/2006	122505 Fit wear plate on turntable floor		176794
60 09/21/2006	122236 STARTER SOLENOID SUIT JF		176280
60 09/21/2006	122236 BUSH KIT SUIT JF		176280
60 09/21/2006	122236 STARTER DRIVE SUIT JF		176280
60 09/21/2006	122236 JF24V 4KW BRUSH SET		176280
60 09/21/2006	122236 Service		176280
60 09/20/2006	122125 Change tyres		176167
60 09/20/2006	122125 Change tyres	Assisted to change tyres	176167
60 09/20/2006	122125 Bin missing	Changed tyre pos 7-8-9-10 & cleaned & painted rims	176167
60 09/19/2006	122156 BALD POS 7+8+9+10	Replaced	176005
60 09/07/2006	118386 SCANIA FUSE HOLDER SOCKET	Replaced	174204
60 09/07/2006	118386 SCANIA FUSE HOLDER SOCKET	Creditor #::BAN001 BANLAY PTY LTD P/O #:34543 Receiving #:34685 Date :2006-09-07	174204
60 09/07/2006	118386 SCANIA FUSE HOLER SOCKET	Creditor #::BAN001 BANLAY PTY LTD P/O #:34543 Receiving #:34685 Date :2006-09-07	174204
60 09/07/2006	118386 SCANIA FUEL HOLDER SEAL	Creditor #::BAN001 BANLAY PTY LTD P/O #:34543 Receiving #:34685 Date :2006-09-07	174204
60 09/06/2006	121204 Replace 1 dash globe	Replaced	174204
60 09/06/2006	121176	Tension ALL Wheel Nuts to OEM Specs	174204
60 09/06/2006	121176		174204
60 09/06/2006	121176		174204
60 09/06/2006	121176 GLOBE+HOLDER INSTRUMENT		174204
60 09/06/2006	121176		174052
60 09/05/2006	119735 16X5 1/2 BOLT+NUT		174052
60 09/04/2006	121051 Drv entered - Elec & Light Headlights		173920
60 09/04/2006	121051 Drv entered - Elec & Light Headlights		173920
60 09/04/2006	118458 HEAD LIGHT GLOBE 24V 70/75W		173920
60 09/04/2006	118458 GLOBE INST 24V 2W		173920
60 09/01/2006	119735 IDLER POST B SECT PULLEY		173753
60 08/24/2006	119735 A/C belts missing	Creditor #::AIR002 AIR INTERNATIONAL TRANSIT P/O #:34287 Receiving #:34550 Date :2006-09-01	172855
60 08/24/2006	119735 REPAIR S/MOTOR	Fit new idler post	172855
60 08/22/2006	119735 Torque wheel nuts	Creditor #::PGL001 P.G.LIGHTNING P/O #:34358 Receiving #:34365 Date :2006-08-24	172231
60 08/22/2006	119735 GLOBE INDICATOR 24V21W SINGLE CONTACT	Torqued	172231
60 08/22/2006	119735 Dip stick missing		172231
60 08/22/2006	119735 Replace positive battery terminal		172231
60 08/22/2006	119735 Replace top rear brake light & lens	Replaced	172231
60 08/22/2006	119735 STOP LAMP LENS	Replaced	172231
60 08/22/2006	119735 WING NUT BRASS BATTERY TERMINAL POSITIVE		172231
60 08/22/2006	119735 Road test		172762
60 08/22/2006	119735 Clean interior & exterior	Tested & parked	172231
60 08/21/2006	119735 BELT ALT W/PUMP CRANK SCANIA ARTIC	Cleaned	172231
60 08/21/2006	119735 A/CON BELT SCANIA ARTIC 21/32x65		172231
60 08/21/2006	119735 SCANIA ALT BELT TENSIONER K1241B		172231
60 08/21/2006	119735 Pully Idler Scania Artic (No Grove Plastic)		172231
60 08/21/2006	119735 A/C belts missing	Replaced alternator belts and adjuster pulley and fitted oil filter	172231
60 08/21/2006	119735 D/STICK BRACKET	Creditor #::BAN001 BANLAY PTY LTD P/O #:34219 Receiving #:34244 Date :2006-08-21	172231
60 08/21/2006	119735 D/STICK STRAP	Creditor #::BAN001 BANLAY PTY LTD P/O #:34219 Receiving #:34244 Date :2006-08-21	172231

60 08/21/2006	119735 d/stick tube	Creditor #:BAN001 BANLAY PTY LTD P/O #:34219 Receiving #:34244 Date :2006-08-21	172231
60 08/21/2006	119735 SCANIA DIP STICK L94UAB	Creditor #:BAN001 BANLAY PTY LTD P/O #:34219 Receiving #:34244 Date :2006-08-21	172231
60 08/21/2006	119735 D/STICK CAP	Creditor #:BAN001 BANLAY PTY LTD P/O #:34219 Receiving #:34244 Date :2006-08-21	172231
60 08/21/2006	119735 SCANIA STARTER MOTOR K93+L94		172231
60 08/17/2006	119735 Bus wont start - fuse out and burnt wires	Starter motor U/S	172231
60 08/17/2006	119735 Bus wont start - fuse out and burnt wires	Fit 70 amp fuse holder and repair wiring	172231
60 08/09/2006	119178 GLOBE FESTOON 24V-3W		172231
60 08/09/2006	119178 Fit exit globe	Fitted globe	172231
60 08/07/2006	118386 FUSE HOLDER	Creditor #:BAN001 BANLAY PTY LTD P/O #:33760 Receiving #:33909 Date :2006-08-07	172231
60 08/07/2006	118386 FUSE SUIT SCANIA MASTER SWITC	Creditor #:BAN001 BANLAY PTY LTD P/O #:33760 Receiving #:33909 Date :2006-08-07	172231
60 08/01/2006	118458 Assist with elec problem	Repaired	172231
60 08/01/2006	118458 Assist with elec problem	Assisted	172231
60 07/31/2006	118386 Breakdown - Dandenong - No electric power - Dep - 6.45 Ret	Checked electrical system found fuse burnt - drove back to depot	172231
60 07/31/2006	118386 Breakdown - Dandenong - No electric power - Dep - 6.45 Ret	Checked electrical system found fuse burnt - drove back to depot	172068
60 07/28/2006	118201 Plate loose under exhaust pipe. Rattling sound	Had to shape belly plate so it wedged in properly	171889
60 07/26/2006	118144 A/CON BELT SCANIA ARTIC 21/32X65		171734
60 07/26/2006	118144 Replaced A/C. BELTS		171556
60 07/25/2006	117925 GLOBE STOP AND TAIL 24V 21/SW		171372
60 07/25/2006	117925 Tail light out bottom left		171372
60 07/15/2006	117308 Air conditioner not heating.	Replaced globe	170176
60 07/15/2006	117308 COMPUTER SLRT/RM-RP	repaired & rep. CCC 007-4 climate control unit runs up o/k.	170363
60 07/11/2006	117032 Refitted engine cover		169509
60 07/07/2006	116800 GLOBE+HOLDER INSTRUMENT	refitted engine cover	169271
60 07/07/2006	116800 Replace das light globes		169271
60 07/07/2006	116706	Replace dash light globes	169271
60 07/07/2006	116706	Serviced	169271
60 07/07/2006	116706	Tension ALL Wheel Nuts to OEM Specs	169271
60 07/07/2006	116706	Serviced	169271
60 07/07/2006	116706	Replaced 4 dash light globes	169271
60 06/27/2006	116037 Clearance light out left side rear	Replace globe	167832
60 06/07/2006	114063 POS 9+10	Creditor #::BEA001 BEAUREPAIRS P/O #:32299 Receiving #:32542 Date :2006-06-07	165615
60 06/07/2006	114063 POS 7+8	Creditor #::BEA001 BEAUREPAIRS P/O #:32299 Receiving #:32542 Date :2006-06-07	165615
60 06/02/2006	114435 Middle door top come loose	secured door top roller	165050
60 06/02/2006	114237 AIR DRIER REG KIT	Creditor #:BAN001 BANLAY PTY LTD P/O #:32398 Receiving #:32458 Date :2006-06-02	165050
60 06/01/2006	114237 Replace o/s. boost pump.	checked o/k.	164850
60 06/01/2006	114237 Starter motor rubbing on hydraulic pipe on top of motor.	secured	164850
60 06/01/2006	114237 Header tank coolant hose needs replacing.	repaired	164850
60 06/01/2006	114237 WEAR SENSOR SCANIA DISC BRAKE		164850
60 06/01/2006	114237 DISC PADS SCANIA		164850
60 06/01/2006	114237 O/S/R/R. Brakes low.	checked o/k.	164850
60 06/01/2006	114237 Middle axle brakes low.	Replaced pads o/k	164850
60 05/30/2006	114063 Replaced tyres. pos.78910 - bald.	REP TYRES 78910. Bald.	164537
60 05/29/2006	114003 Annual random audit	audit completed	164357
60 05/29/2006	114003 Annual random audit	audit completed	164357
60 05/29/2006	114068 Service	ASSISTED WITH REPAIRS	164537
60 05/29/2006	114068 Replaced o/s/r. trailer brake pads & sensor.	rep. o/s/r. disc pads.	164357
60 05/29/2006	114002 WEAR SENSOR SCANIA DISC BRAKE		164357
60 05/29/2006	114002 DISC PADS SCANIA		164357
60 05/29/2006	114002	A SERVICE	164357
60 05/29/2006	114002	Tension ALL Wheel Nuts to OEM Specs	164357
60 05/29/2006	114002	A SERVICE	164357
60 05/18/2006	113357 No throttle at all .	c/o. bus from station refitted elect. plug & checked o/k.	163352
60 05/18/2006	113389 replaced globe/tube.	rep. light tube	163352
60 05/17/2006	111634 Jack knife light on	Creditor #:BAN001 BANLAY PTY LTD P/O #:31526 Receiving #:32008 Date :2006-05-17	163190
60 05/16/2006	113176 GLOBE STOP AND TAIL 24V 21/SW		163015
60 05/16/2006	113176 Replaced globe		163015
60 05/09/2006	112519 Replace pos 12 tyre worn	REP. GLOBE	162173
60 05/09/2006	112519 WEAR SENSOR SCANIA DISC BRAKE	REP. TYRES 1& 2	162173
60 05/09/2006	112519 DISC PADS SCANIA		162173
60 05/08/2006	112515 Flat spot on n/s. front tyre (banging)	Replace front tyres	834
60 05/08/2006	112515 Front pads low	Replace o/s front pads	834
60 05/08/2006	112515 Front pads low	Replace n/s front pads	834
60 05/04/2006	112195 Secure A/C. adjuster bolt.	secured adj. bolt.	161485
60 05/01/2006	111889 FAN+ALT BELT TWIN PULLEY		161003
60 05/01/2006	111889 A/CON BELT SCANIA ARTIC 21/32X65		161003
60 05/01/2006	111907 Blown belt	Replace belts	161003
60 05/01/2006	111889 Replace a/c belt s	Replace belts	161003
60 05/01/2006	111886 Brake pulling to left	Road test - ok	161003
60 04/28/2006	111827 Front a/c not working	Check and road test - ok	160750
60 04/28/2006	111799 Clearance light buib left side centre	Replace globe	160750
60 04/28/2006	111799 GLOBE FESTOON 24V5W		160750
60 04/26/2006	111634 Jack knife light on	Check Jack knife system - found low on oil pressure in tun table cylinder	160750
60 04/24/2006	111531 Breakdown - Jack knife light stays on dash & low power- 60	c/o. bus returned to depot has electrical defects - active faults - 13 - 18 - 12	160649
60 04/18/2006	110560 POS 5	Creditor #::BEA001 BEAUREPAIRS P/O #:31185 Receiving #:31365 Date :2006-04-18	159959
60 04/12/2006	110918 Replaced broom	rep. globe	159460
60 04/12/2006	110918 BROOM HEAD (09803211)		159634
60 04/12/2006	110918 BROOM HANDLE (8232715)		159634
60 04/08/2006	110663 GLOBE FESTOON 24V-3W		159198
60 04/08/2006	110667 BELT ALT W/PUMP CRANK SCANIA ARTIC		159198
60 04/07/2006	110560 Replaced tyre pos. 5 valve stem leaks.	rep. tyre pos.5 valve u/s.	159198
60 04/07/2006	110640 replaced tyre o/s. middle inner tyre.	rep. tyre	159198
60 04/07/2006	110663 Replaced globe.	REP. GLOBE	159198
60 04/07/2006	110667 Replaced alternator belts.	rep. alt. belts.	159198
60 04/07/2006	110611 FILTER OIL K124 / L94UAB		159198
60 04/07/2006	110611 FILTER TRANSMISSION ZF 4139-298-038		159198
60 04/07/2006	110611 O RING FILTER KIT K93		159198
60 04/07/2006	110611 ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL		159198
60 04/07/2006	110611 TEXAMATIC 1888		159198
60 04/07/2006	110611	Tension ALL Wheel Nuts to OEM Specs	159198
60 04/07/2006	110611	D Service	159198
60 04/07/2006	110611	Tension ALL Wheel Nuts to OEM Specs	159198
60 04/07/2006	110611	D Service	159198
60 03/21/2006	107310	UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensor pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation	152395
60 03/15/2006	107939 POS 4	Creditor #::BEA001 BEAUREPAIRS P/O #:30321 Receiving #:30633 Date :2006-03-15	153711
60 03/01/2006	107939 REPLACE BALD TYRE POS 4	rep. tyre	153631
60 02/28/2006	107894 Pre- trip safety check.	Pre trip inspection check and steam clean bus	153458

60 02/28/2006	107931 N/S middle tyres bald	Replace N/S middle tyres	153458
60 02/28/2006	107782 Front A/C. U/S.	Repair and check front A/C/ unit	153458
60 02/28/2006	107894 GLOBE FESTOON 24V-3W	Replace water valve kit - repair inlet pipe where it inters roof	153458
60 02/28/2006	107936 Equipment bridge rubber N/S - U/S	rep. rubber	153458
60 02/28/2006	107846 Service	assist with repairs	153458
60 02/28/2006	107846 Check interior & exterior for damage or vandalism & repair	checked & secured seats blinds	153458
60 02/28/2006	107792 EMERGENCY EXIT BUTTON PULL COVER	cleaned a/c. filter removed graffitti from seats polished exterior panels.	153458
60 02/28/2006	107792 accident damage no 10708 - Poilsh n/s trailer from door to	polished o/k.	153297
60 02/28/2006	107792 Accident damage repairs - Repair & repaint o/s/r. fibre g	repaired by Volgren. 01.03.06	153297
60 02/27/2006	107782 Front A/C. U/S.	Repair and check front A/C/ unit	153297
60 02/27/2006	107848 flat batteries	Jump started	153297
60 02/22/2006	107310 AIR CON REFRIDGERANT		152830
60 02/21/2006	107310	Clean R/A & F/A filters; Inspect and report on condition; Replace filter media	152395
60 02/21/2006	107310	FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)	152395
60 02/21/2006	107310	COMPRESSOR DRIVE BELTS: Inspect belt wear; Retension belts;	152395
60 02/21/2006	107310	DRIVE PULLEY'S: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;	152395
60 02/21/2006	107310	DRIVE PULLEY'S: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear	152395
60 02/21/2006	107310	COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose	152395
60 02/21/2006	107310	REFRIGERATION FILTER DRYER: Replace filter dryer; check pump operation;	152395
60 02/21/2006	107310	EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check boltsclamps & fittings; clean condensate drains; clean drip tray	152395
60 02/21/2006	107310	INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condensor fan grills	152395
60 02/21/2006	107310	CONDENSOR AREA: Clean condensor coils; check boltsclamps for tension	152395
60 02/20/2006	107310 WATER VALVE SPARE PARTS KIT		152395
60 02/17/2006	107146 A/C not working	Checked working OK	152114
60 02/17/2006	107184 Very bad acceration with a/c on	Check all functions on A/C is OK - road tested is OK - only fault that come up was ER1 on front unit on start up.	152114
60 02/14/2006	106932 GLOBE STOP AND TAIL 24V 21/5W		151894
60 02/14/2006	106932 GLOBE INDICATOR 24V21W SINGLE CONTACT		151894
60 02/14/2006	106932 REVERSE+PARK LIGHT CLEAR		151894
60 02/14/2006	106932 Broken rear tail and reverce light on right side	Replace O/S/R brake and reverce light [accident damage]	151894
60 02/14/2006	106932 STOP TAIL LIGHT RED		151894
60 02/02/2006	106152 Check warning & dash lights.	CHECK O/K.	150473
60 01/31/2006	105976 Broken l/h/f lower flasher lens	Replace n/s/f indicator assemble - accident damage	150136
60 01/31/2006	105976 INDICATOR LIGHT FRONT ARTIC		150136
60 01/27/2006	105694 5 Globes u/s. (clearance / park)	Checked found fuse blown - repair short in trailer	149957
60 01/27/2006	105694 GLOBE FESTOON 24V5W		149957
60 01/27/2006	105694 Bad small inside bus	Checked ok	149957
60 01/23/2006	105512 A/C not working	Checked ok - Run for 10mins and cools to 21 deg	149580
60 01/19/2006	105302 Brocken clearance light and indicator light	Replace side marker light and indicator light	149337
60 01/19/2006	105302 LENS TO SUIT 2029 (RED+AMBER)		149337
60 01/19/2006	105302 LAMP INDICATOR [ORANGE]		149337
60 01/19/2006	105302 GLOBE FESTOON 24V5W		149337
60 01/18/2006	105113 A/C not working	-Removed buzz bar	149249
60 01/18/2006	105188 Replace all brake pads on all axles	Replaced short and burned positive cable- removed buzzbar	149249
60 01/18/2006	105188 Replace all brake pads on all axles	Checked brake pads OK	148997
60 01/17/2006	105113 A/C not working	Checked brake pads OK	148997
60 01/17/2006	105113 Jack knife light and ABS light on bus would drive	Found ERS - low voltages code coming up	148997
60 01/17/2006	105113 Jack knife light and ABS light on bus would drive	Clean up N/S middle axdle speed sensor	148997
60 01/16/2006	105090 Dahs light U/S	Clean up N/S middle axdle speed sensor	148997
60 01/16/2006	105090 GLOBE INST 24V 2W	Replace dash light globe	148997
60 01/16/2006	105030		148997
60 01/16/2006	105030	A service	148997
60 01/16/2006	105030	A service	148997
60 01/16/2006	105030	Tension ALL Wheel Nuts to OEM Specs	148997
60 01/11/2006	104649 Short in door system - doors wont open and brake warning li	Checked found fuel heater fuse blown - repair loom in turntable	148442
60 01/10/2006	104673 Breakdown - Braeside - Doors wont open and brakes locked on	Found door system blowing fuse and locking doors and brakes	148442
60 12/24/2005	103855 Slow to take off	Road test unable to locate fault	147005
60 12/12/2005	103048 CRANK TO PULLEY SCANIA 21/32X67		145730
60 12/12/2005	103048 Drive belts front to A/C. broken & cracked.	replaced belts	145730
60 12/01/2005	101146 POS 5+6	Creditor #-BEA001 BEAUREPAIRES P/O #:28317 Receiving #:28704 Date :2005-12-01	144230
60 11/30/2005	102225 Service	ASSIST WITH REPAIRS	144068
60 11/30/2005	102225	Tension ALL Wheel Nuts to OEM Specs	144068
60 11/30/2005	102225		144068
60 11/29/2005	102219 Replaced globes-interior	rep. globe	143877
60 11/23/2005	101201 ROAD SAFETY INSPECTIONS	Creditor #-ROA001 Road Safety Inspections P/O #:28333 Receiving #:28540 Date :2005-11-23	143003
60 11/23/2005	101723 Clean and adjust o/s windscreen washer jet	cleaned washer jets	143003
60 11/23/2005	101112 SWAY BAR BUSH	Creditor #-BAN001 BANLAY PTY LTD P/O #:28283 Receiving #-28538 Date :2005-11-23	143003
60 11/23/2005	101723 Replace n/s/f air bag - cracked - when rasied	rep. air bag	143003
60 11/23/2005	101723 FRONT AIR BAG SCANIA L94UAB		143003
60 11/20/2005	101201 Annual Inspection - BC 091724	Annual Inspection - BC 091724	142618
60 11/18/2005	101112 Wipers not centering.	replaced relay.	142618
60 11/17/2005	101112 40V2227 WIPER SWITCH	Creditor #-MUL001 MULTISPARES LTD P/O #:28316 Receiving #:28384 Date :2005-11-17	142618
60 11/16/2005	101112 Replace O/S/R. Tyres	rep. tyres - o/s/r.	142618
60 11/16/2005	101112 ' V ' Bushes u/s.	CHECKED O/K.	142618
60 11/16/2005	101112 Steam clean engine & gearbox.	cleaned up engine & g/box.	142618
60 11/16/2005	101175 LENS TO SUIT 2319		142618
60 11/16/2005	101175 Polish touch - up n/s.top front & rear headers & corner pan	POLISHED & TOUCHED UP	142618
60 11/16/2005	101175 Replace driver's seat base with 200mm box	REPLACED WITH 200MM. BOX.	142618
60 11/16/2005	101175 UNION STRAIGHT AIR LINE FITTING		142618
60 11/16/2005	101175 Service	Steam clean bus.	142618
60 11/16/2005	101175 Replace licenced to carry/seat decal exterior.	REP.LICENCED TO CARRY	142618
60 11/16/2005	101175 Touch -up rear bumper bar	POLISH & TOUCHED UP	142618
60 11/16/2005	101175 Repaint till tray Mirror arms & heads.	REPAINTED MIRROR ARMS &TILL TRAY.	142618
60 11/16/2005	101112 Check middle & rear disc brake pads / bolt inside /.		142618
60 11/15/2005	101112 Wipers not centering.	readjusted	142618
60 11/15/2005	101112 Replace wipers	replaced wipers	142618
60 11/15/2005	101112 WIPER BLADE ARTIC 28inch		142618
60 11/15/2005	101112 Replace wipers	replaced wipers	142618
60 11/15/2005	101146 Replaced tyres pos. 5 & 6 Bald.	replaced tyres 5 & 6	142618
60 11/15/2005	101112 Rear stablizer bushes u/s.	replaced bushes	142618
60 11/15/2005	101112 A/C .pipe rubbing thru. header tank & alternator..	repositioned	142618
60 11/15/2005	101112 Repair muffler heat shield.	repaired shield	142618
60 11/15/2005	101112 Rear n/s. stop light out.	replaced globe	142618
60 11/15/2005	101112 N/S/R. Emergenc ey hammer cable broken.	refitted	142618
60 11/15/2005	101112 rego light out.	replaced globe	142618
60 11/15/2005	101112 SWF SPRING LOADED DOOR SWITCH		142618
60 11/15/2005	101152 Replace emergency exit under bumper bar.	checked o/k.	142618

60 11/15/2005	101152	Secure seat frames o/s 5 & 6.	secured seats	142618
60 11/15/2005	101112	Replace o/s. demister duct.	replaced duct.	142618
60 11/15/2005	101112	CENTRA SEAT END CAPS		142618
60 11/15/2005	101152	Secure all lower skirt panels.	secured panels	142618
60 11/15/2005	101152	Fit arm cushion to drivers partition.	fitted arm pad	142618
60 11/15/2005	101152	Repair No3 drivers blind refit cord.	repaired	142618
60 11/15/2005	101152	Clean a/c. vents	cleaned up	142618
60 11/15/2005	101152	Replace passenger No 5 hand grip.	repainted wheels	142618
60 11/15/2005	101112	EMERGENCY HAMMERS		142618
60 11/15/2005	101152	Repaint wheels.	repaintedwheels	142618
60 11/15/2005	101152	RISER DRIVER SEAT 200MM		142618
60 11/15/2005	101152	Repaint wheels.		142618
60 11/15/2005	101152	Repaint front bumper bar.	assist to paint	142618
60 11/15/2005	101143	Accident damage no 10029 - Replace n/s emergency exit decal	polished & touched up	142618
60 11/15/2005	101143	Accident Damage No 8884 * Front bumper bar - n/s corner fib	Repaired by Volgren	142618
60 11/14/2005	100409	POS 7+8+9+10		142618
60 11/08/2005	100322	HUMP HOSE TURBO		142618
60 11/04/2005	100409	Replace pos 78910 tyres - bald		142618
60 11/03/2005	100322	GLOBE S/CONTACT 24V-10W		142256
60 11/03/2005	100322	FILTER AIR DRYER KIT(HALDEX)		142256
60 11/03/2005	100322	HYDRAULIC FILTER L94UAB		142256
60 11/03/2005	100322		Inspect bus as per inspection sheet	142256
60 11/03/2005	100322		Adjust valve clearances	142256
60 11/03/2005	100322		Clean a/c filters	142256
60 11/03/2005	100322	FILTER FUEL K124 / LU94A		142256
60 11/03/2005	100322		Replace coolant filter in engine cooling system	142256
60 11/03/2005	100322	RPM BORATE EP LUBE 220		142256
60 11/03/2005	100322		Replace final drive oil	142256
60 11/03/2005	100322		Replace fuel filters	142256
60 11/03/2005	100322	POWER STEER FILTER B10M		142256
60 11/03/2005	100322		Replace air dryer cansiter	142256
60 11/03/2005	100322		Replace hydralic fan filter and top up oil	142256
60 11/03/2005	100322		Rekit quick release valve	142256
60 11/03/2005	100322	FILTER FUEL SCANIA L94UAB		142256
60 11/03/2005	100322		Adjust valve clearances	142256
60 11/03/2005	100322		Replace power steering filter	142256
60 11/03/2005	100324	Annual body check	check completed	142256
60 10/15/2005	99101	GLOBE FESTOON 24V-3W		140615
60 10/15/2005	99101	Replaced exit light globe.	rep. globe	140615
60 10/11/2005	94928	Front heater will not go over 16.5 C - to cold.	Replaced power board - no eart pulse - send to M/V.	140025
60 10/11/2005	98716	Leaking coolant from rear unit	Fitted new M-V - modify wiring to suit.	140025
60 10/11/2005	98716	LAMP (RED+AMBER)		140025
60 10/10/2005	98716	24 VOLT RELAY PANEL		140025
60 10/10/2005	98716	WATER VALVE SPARE PARTS KIT		140025
60 09/30/2005	98115	Coolant leak from A/C at rear roof.	Road tested & checked o/k.	139199
60 09/30/2005	98068		Tension ALL Wheel Nuts to OEM Specs	139199
60 09/30/2005	98068	ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL		139199
60 09/30/2005	98068	FILTER AIR SCANIA USE AF25066		139199
60 09/30/2005	98068	O RING FILTER KIT K93		139199
60 09/30/2005	98068	FILTER TRANSMISSION ZF 4139-298-038		139199
60 09/30/2005	98068		D Service	139199
60 09/30/2005	98068	TEXAMATIC 1888		139199
60 09/30/2005	98068	FILTER OIL K124 / L94UAB		139199
60 09/30/2005	98068			139199
60 09/30/2005	98068		Tension ALL Wheel Nuts to OEM Specs	139199
60 09/20/2005	95739	ELEC PROBLEM IN SUSPENSION	Creditor #:.BAN001 BANLAY PTY LTD P/O #:.26668 Receiving #:.27125 Date :2005-09-20	137862
60 09/14/2005	97060	Replace o/s 2 clearanse light & 1 indicator light.	Replaced 1 indicator light & 2 clearance lights.	137168
60 09/14/2005	97060	LAMP (RED+AMBER)		137168
60 09/14/2005	97060	LAMP INDICATOR [ORANGE]		137168
60 09/14/2005	97060	GLOBE FESTOON 24V5W		137168
60 08/30/2005	95739	REAR AIR BAG (DRIVE AXLE) SCANIA L94UAB		135702
60 08/30/2005	95739	Suspension light sign showed on dash bod.	Picket bus from BANLEY - replaced n/s/r trailer air bag & road tested.	135702
60 08/29/2005	95739	Suspension light sign showed on dash bod.	Checked wiring.	135702
60 08/26/2005	95739	Suspension light sign showed on dash bod.	Checked wiring.	135702
60 08/25/2005	95739	Suspension light sign showed on dash bod.	Checked out suspension - rear not working./	135702
60 08/24/2005	95658	Air bag light on & air pressure on 5 bar at Moorabbin stn.	Go to Moorabbin Stn to check for air susp fault. Air bags checked ok & air pressure normal. Susp fault light staying on. No other fault found.	135408
60 08/24/2005	95890	Breakdown - Low air pressure air bag light on.Moorabbin st	checked on site by Moorabbin Transit o/k. was checked next day by Grendas found fault in suspension system.	135408
60 08/23/2005	95292	Replace o/s/r trailer air bag.	Replaced o/s/r front trailer air bag.	135224
60 08/23/2005	95273	REAR AIR BAG (BELLOWS COMPLETE	Creditor #:.BAN001 BANLAY PTY LTD P/O #:.26470 Receiving #:.26535 Date :2005-08-23	135408
60 08/18/2005	95292	Replace o/s/r trailer air bag.	Removed o/s/r front trailer air bag & fitted back no new in store.	135224
60 08/18/2005	95273	Short fan belt cracket to main compressor.	Replaced A/C belts.	135224
60 08/18/2005	95273	FAN+ALT BELT TWIN PULLEY		135224
60 08/12/2005	94928	Front heater will not go over 16.5 C - to cold.	Checked A/C - unable to fix A/C - road tested.	134617
60 08/12/2005	94928	Front passengers light too much reflection.	Checked passengers light o/k.	134617
60 08/09/2005	93981	POS 9	Creditor #:.BEA001 BEAUREPAIRS P/O #:.26061 Receiving #:.26208 Date :2005-08-09	134098
60 08/04/2005	94135	A/C No - 1 ERROR.	Make up discharge hose & fit - vac system down & charge - replaced left evap relay - run unit up & test.	133535
60 08/04/2005	94135	AIR CON REFRIDGERANT		133535
60 08/04/2005	94135	RELAY SOLID STATE		133535
60 08/04/2005	94135	ALUMINIUM NO 12 STRAIGHT FLARE		133535
60 08/04/2005	94135	STEEL NO12 90DEG O RING FITTING		133535
60 08/02/2005	94135	A/C No - 1 ERROR.	Inspect bus - oder in parts.	133535
60 08/02/2005	94135	A/C No - 1 ERROR.	Inspect bus - oder in parts.	133535
60 08/02/2005	94135	BROOM HANDLE (8232715)		133535
60 08/02/2005	94135	BROOM HEAD (09803211)		133535
60 08/02/2005	94135	New broom required.	Replaced broom.	133535
60 08/01/2005	93981	Replace tyre position - 9 - bald. Odometer - 133350.		133242
60 07/29/2005	93799			133089
60 07/19/2005	93172	GAS STAY 500N		132067
60 07/19/2005	93172	Rear engine door struts not holding door up.	Replaced rear engide door struts.	132067
60 07/12/2005	91389	RECALL CAMPAIGN	Creditor #:.BAN001 BANLAY PTY LTD P/O #:.25269 Receiving #:.25627 Date :2005-07-12	131158
60 07/11/2005	92579	air bag	Creditor #:.BAN001 BANLAY PTY LTD P/O #:.25585 Receiving #:.25620 Date :2005-07-11 BUS 60	131131
60 07/11/2005	92579	Air leak on o/s air bag.	Replaced o/s air bag.	131131
60 07/11/2005	92579	Air leak on o/s air bag.	Replaced o/s air bag.	131131
60 06/28/2005	91472	MASTER SWITCH RELAY	Creditor #:.BAN001 BANLAY PTY LTD P/O #:.25286 Receiving #:.25377 Date :2005-06-28	129648
60 06/23/2005	91472	No electric power.	Fitted new master switch relay.	129331

60 06/22/2005	91472 No electric power.	Check out & remove master relay & order new one.	129331
60 06/21/2005	91389 Campain Recall - TC041131 - Tension centre axle bolts		129174
60 06/20/2005	91330 A/C Idler pulley adjuster screw almost out	Repaired A/C adjuster & fitted pin.	128995
60 06/15/2005	91055 Annual random audit	Checked.	128414
60 06/15/2005	91056 24V INVERTER 4-13W		128414
60 06/15/2005	91056 Repair interior lights.	Checked & replaced 1 interior light inverter .	128414
60 06/15/2005	91039		128414
60 06/06/2005	90491 Belts have crack in them.A/C belts.	Replaced A/C belts.	127379
60 06/06/2005	90491 A/CON BELT SCANIA ARTIC 21/32X65		127379
60 06/06/2005	89977 TURNTABLE FRAME	Creditor #-VOL001 VOLGREN AUSTRALIA P/L P/O #:24810 Receiving #:24917 Date :2005-06-06 REPAIR TURNTABLE FRAME	127379
60 06/03/2005	90383 Door Number 2 will not open or close - missing bolt.	Replaced bolt & secured door No 2.	127196
60 05/30/2005	89977 Repair turntable frame broken		126957
60 05/24/2005	89352 POS 8	Creditor #-BEA001 BEAUREPAIRS P/O #:24606 Receiving #:24626 Date :2005-05-24	126631
60 05/20/2005	89342 Replace n/s drive axle inner tyre.	Replaced n/s drive axle inner globe.	126308
60 05/20/2005	89352 Repair tyre position - 8 - flat. Odometer - 126389.		126308
60 05/14/2005	88931 GLOBE INDICATOR 24V21W SINGLE CONTACT		125641
60 05/13/2005	87712 POS 4	Creditor #-BEA001 BEAUREPAIRS P/O #:24104 Receiving #:24404 Date :2005-05-13	125306
60 05/13/2005	88931 N/S top brake light not working.	rep globe.	125469
60 05/13/2005	88935 Service	r/tested o/k.	125469
60 05/13/2005	88935 Breakdown- Wont start Dandy Stn. left at 5.00pm. took van	Breakdown dandy stn. jump started returned to depot checked all systems o/k.	125469
60 05/13/2005	88966 Wont start - Dandenong Stn. Left at 5.00pm. took van 203 j		125469
60 05/10/2005	88559 Replace wiper switch.	Replaced wiper switch.	125071
60 05/09/2005	88559 Replace wiper switch.	Removed wiper switch & ordered part.	125071
60 05/09/2005	88480 Breakdown at - KEYSBOROUGH - smok coming from wiper switch.	Return bus to depot.	125071
60 05/06/2005	88277 flasher relay 40V2402 (140178	Creditor #-MUL001 MULTISPARES LTD P/O #:24265 Receiving #:24262 Date :2005-05-06 charge to bus 60fit to bus 63	124876
60 05/05/2005	88277 O/S indicator not working.	Replaced flasher rele.	124516
60 04/28/2005	87805		123784
60 04/27/2005	87689 Replace n/s drive axle inner tyre.	Replaced n/s drive axle inner tyre.	123738
60 04/27/2005	87712 Replace tyre position - 4 - blown out.Odometer - 123713.		123738
60 04/21/2005	84939 POS 8 & 7	Creditor #-BEA001 BEAUREPAIRS P/O #:23177 Receiving #:23940 Date :2005-04-21 FIT GBS STOCK (2)	123273
60 04/21/2005	87468 Drivers cabin door lower pivot is u/s.	replaced both door hinges	123273
60 04/21/2005	87468 HINGE DRIVERS COMPARTMENT		123273
60 04/07/2005	86427 Jump start	Jump started	121416
60 03/15/2005	84939 Replace tyres position - 7 - 8 - bald.Odometer - 119470.		119234
60 03/15/2005	84939 MICHELIN RECAP 275-70R 22.5		119398
60 03/15/2005	84978 Replace n/s rear tyre.	Replaced n/s rear tyre.	119398
60 03/15/2005	84921 AIR FILTER SCANIA CLEANED		119234
60 03/15/2005	84921 FILTER TRANSMISSION ZF 4139-298-038		119234
60 03/15/2005	84921 O RING FILTER KIT K93		119234
60 03/15/2005	84921 ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL		119234
60 03/15/2005	84921 TEXAMATIC 1888		119234
60 03/15/2005	84921	D Service	119234
60 03/15/2005	84921 FILTER OIL K124 / L94UAB		119234
60 03/15/2005	84921		119234
60 03/09/2005	84694 R/H/S park light not working.	Replaced o/s front park light globe.	118908
60 03/09/2005	84694 GLOBE INST 24V 2W		118908
60 03/08/2005	81295 check samples refer to R Goat	Creditor #-ATT001 ATTITUDE SIGNS P/O #::22028 Receiving #:22954 Date :2005-03-08	118722
60 03/04/2005	84377 Whilst checking for oil engine started by driver.	Checked engine will not start with door open.	118390
60 03/03/2005	82091 MAKE UP HOSE	Creditor #-DAN013 DANDENONG RADIATOR SERVICE P/L P/O #:22447 Receiving #:22895 Date :2005-03-03	118306
60 03/02/2005	84256 Turntable making a loud squeaking noise on either left or r	Removed concertina cover & lubricated turn table.	118041
60 03/01/2005	82757 20 WIRE DATA CABLE	Creditor #-REA002 READ RITE PTY LTD P/O #::19707 Receiving #:22815 Date :2005-03-01	117868
60 02/28/2005	83998 Replace exit light globe.	Replaced exit light globe.	117666
60 02/28/2005	83998 GLOBE FESTOON 24V-3W	Replaced exit light globe.	117666
60 02/25/2005	83904 Upper steering column loose at pivot.	Striped front steering column cover & tightened bolts.	117483
60 02/10/2005	82757 RELAY SOLID STATE		115983
60 02/10/2005	82757 24 VOLT RELAY PANEL		115983
60 02/10/2005	82757 AIR CON REFRIDGERANT		115983
60 02/10/2005	82757 FILTER DRIER 5/8		115983
60 02/10/2005	82757 FAULT ON HEAT CYCLE.	Repaired A/C.	115983
60 02/10/2005	82757 5/8FLARE DRIER		115983
60 02/10/2005	82757	UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensor pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation	115983
60 02/09/2005	82758 Repair main fuse wiring.	Make up fuse holder & fit 70 Amp fuse.	115983
60 02/09/2005	82758 70AMP FUSIBLE LINK		115983
60 02/09/2005	82757	Check boost pump condition	115983
60 02/09/2005	82757 FAULT ON HEAT CYCLE.	CHECKED ALL . FOUND SIGNAL WIRE TO MOD. VALVE U/S.*NEEDTOREPLACE	115983
60 02/09/2005	82757	Replace compressor oil	115983
60 02/09/2005	82757	Replace filter drier	115983
60 02/09/2005	82757	D Service	115983
60 02/09/2005	82757 CLAVIS 68 MINERAL OIL		115983
60 02/09/2005	82757	Check & replace electric motor brushes	115983
60 02/09/2005	82757	C Service	115983
60 02/09/2005	82757	Replace compressor oil	115983
60 02/09/2005	82757	B Service	115983
60 02/09/2005	82757	Replace filter drier	115983
60 02/09/2005	82757	Clean R/A & F/A filters; Inspect and report on condition; Replace filter media	115983
60 02/09/2005	82757	FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)	115983
60 02/09/2005	82757	COMPRESSOR DRIVE BELTS: Inspect belt wear; Retension belts;	115983
60 02/09/2005	82757	UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensor pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation	115983
60 02/09/2005	82757	CONDENSOR AREA: Clean condensor coils; check boltsclamps for tension	115983
60 02/09/2005	82757	INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condensor fan grills	115983
60 02/09/2005	82757	EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check boltsclamps & fittings; clean condensate drains; clean drip tray	115983
60 02/09/2005	82757	REFRIGERATION FILTER DRYER: Replace filter dryer; check pump operation;	115983
60 02/09/2005	82757	COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose	115983
60 02/09/2005	82757	DRIVE PULLEY'S: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear	115983
60 02/09/2005	82757	DRIVE PULLEY'S: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;	115983
60 02/08/2005	82666 No electrical power Nepean H'wy Cheltenham. 9:30-10:30. C/o	Go to bus at Cheltenham & found main fuse was blown. By-pass fuse & take bus back to MT depot.	115933
60 02/08/2005	82662 Breakdown at - SOUTLAND SHOPS - no power / blow main fuse /	Replaced main fuse.	115933
60 02/07/2005	82091 Service		115748
60 02/04/2005	82091 AIR CON REFRIDGERANT		115581
60 01/31/2005	28273 ADJ TEMP	Creditor #-REA002 READ RITE PTY LTD P/O #:6650 Receiving #:22183 Date :2005-01-31	115100
60 01/31/2005	82091 Service	CHECKED FOUND ESP209 DISPLAYINGMPI & LPI OPEN CIRCUIT.	115100
60 01/31/2005	82091 Front A/C U/S - Rear A/C not working at all	ALSO 2ndRELAY FROM BACK HAS RED LIGHT ON.	115100
60 01/28/2005	80506 BOOST PUMP EXCHANGE	Creditor #-REA002 READ RITE PTY LTD P/O #:21760 Receiving #:22158 Date :2005-01-28	114573
60 01/24/2005	50538 WARRANTY RECALL RAO21662	Creditor #-SCA001 SCANIA AUSTRALIA PTY LTD P/O #::12853 Receiving #:22071 Date :2005-01-24	114110
60 01/21/2005	81750 Front left and rear right clearance lights out	Replace globe	113557

60 01/21/2005	81748 A service	Complit A ser.	113557
60 01/21/2005	81748 Aservice	Assist	113557
60 01/18/2005	81564 Inter. light U/S	Replace tube	113204
60 01/17/2005	81515 Replace exit light globe	Rep. globe	113122
60 01/14/2005	81295 Service	repainted all new panels	113122
60 01/14/2005	81295 Service	refitted all panels	113122
60 01/13/2005	81295 Accident damage - 8063 - Replace o/s trailer panels 23ref	removed all damaged panels.	112958
60 12/31/2004	80615 Bottom left side stop light u/s.	Checked stop lights all o/k.	111669
60 12/30/2004	80506 Loosing coolant large amount.	Replaced boost pump & coolant - road tested & steam cleaned.	111485
60 12/22/2004	80254 To slow on take off.	Checked & road tested / slow take off with A/C on / normal.	110824
60 12/16/2004	77175 TUBRO	Creditor #:BAN001 BANLAY PTY LTD P/O #:20676 Receiving #:21381 Date :2004-12-16 REPLACE TUBRO - WARRANTY	
60 12/16/2004	68780 TURBO REPLACEMENT	Creditor #:BAN001 BANLAY PTY LTD P/O #:17926 Receiving #:21382 Date :2004-12-16 WARRANTY	
60 12/15/2004	79841 FAN+ALT BELT TWIN PULLEY		109986
60 12/15/2004	79841 A/C compressor belt cracked.	Replaced A/C belts.	109986
60 12/07/2004	79373 Replace 2x dash light globes.	Replaced dash light globes.	108835
60 12/07/2004	79339		108521
60 12/07/2004	79339 Secure o/s rear seat.		108521
60 12/07/2004	79339 MINI WEDGE GLOBE 24V-1.2W		108835
60 12/06/2004	79237 Replace exit light globe.	Replaced exit light globe.	108521
60 12/06/2004	79237 GLOBE FESTOON 24V-3W		108521
60 11/30/2004	78888 A/C. on bus not working.	Checked & road tested.	107698
60 11/26/2004	77960 CHASSIS REPAIRS	Creditor #:ROA001 Road Safety Inspections P/O #:21021 Receiving #:20985 Date :2004-11-26	
60 11/26/2004	77953 POS 3 10 5 & 4	Creditor #:BEA001 BEAUREPAIRS P/O #:20940 Receiving #:20976 Date :2004-11-26 FIT 2 BY GBS CASES	
60 11/24/2004	78503 A/C not working in rear.	Checked A/Cfound relays u/s.Replaced relays.	106870
60 11/24/2004	78503 RELAY SOLID STATE		106870
60 11/21/2004	77960 GLOBE INST 24V 2W		106599
60 11/21/2004	77960 Annual Inspection - BC083192	Annual Inspection - BC083192	106225
60 11/17/2004	77953 Replace pos 34510 tyres - bald		106225
60 11/17/2004	77918 Replace n/s rear tyres.	Replaced n/s rear tyres	106225
60 11/17/2004	77918 Replace o/s rear tyres.	Replaced o/s rear tyres	106225
60 11/17/2004	77918 Replace n/s rear drive axle tyres.	Replaced n/s rear drive axle tyres	106225
60 11/17/2004	77918 O/S rear shocker damage.	Replaced o/s rear shocker	106225
60 11/17/2004	77918 Steam clean all bus.	Steam cleaned all bus	106225
60 11/17/2004	77918 STOP LAMP LENS		106225
60 11/17/2004	77918 LENS TO SUIT 2557 LAMP		106225
60 11/17/2004	77918 Repair water leak at o/s rear of motor.	Repaired water leak	106225
60 11/16/2004	77175 Direct Purchase - MECHANICAL	Creditor #:ASS001 Associated Towing P/O #:20679 Receiving #:20718 Date :2004-11-16 TURBO FAILURE	
60 11/16/2004	77917 Cracked rear V bar bush.	Checked rear V bar bush o/k.	106225
60 11/16/2004	77917 Front stabiliser link has to be replaced.	Checked front stabiliser link o/k.	106225
60 11/16/2004	77917 Top ball joint is u/s.	Checked top ball joint o/k.	106225
60 11/16/2004	77917 Oil leak at engine bell housing.	Checked for oil leak at engine bell housing o/k.	106225
60 11/16/2004	77138 Fit external air supply line and decal	Fitted external air supply line & decal	105823
60 11/15/2004	77138 RUBBER BOOT FOR AIR LINE ON BUS		106074
60 11/15/2004	77138 AIR LINE COUPLING FOR AIR SYSTEM		106074
60 11/15/2004	77138 ADAPTOR/JOINER		106074
60 11/11/2004	77587 Replace passengers bus "STOPPING SIGN "	Replaced passengers bus " STOPPING SIGN "	105825
60 11/05/2004	77175 Turbo failed - pumping engine oil in intake and muffler	Take to " BANLAY "	105825
60 11/05/2004	77175 Turbo failed - pumping engine oil in intake and muffler	Take to " BANLAY "	105825
60 11/05/2004	77137	Replace final drive oil	105823
60 11/05/2004	77137	Replace air dryer cansiter	105823
60 11/05/2004	77137	Inspect bus as per inspection sheet	105823
60 11/05/2004	77137 FILTER FUEL K124 / LU94A		105823
60 11/05/2004	77137 HYDRAULIC FILTER L94UAB		105823
60 11/05/2004	77137 FILTER AIR DRYER KIT(HALDEX)		105823
60 11/05/2004	77137 RPM BORATE EP LUBE 220		105823
60 11/05/2004	77137	Replace coolant filter in engine cooling system	105823
60 11/05/2004	77137	Clean a/c filters	105823
60 11/05/2004	77137	Adjust valve clearances	105823
60 11/05/2004	77137	Replace power steering filter	105823
60 11/05/2004	77137	Replace hydraulic fan filter and top up oil	105823
60 11/05/2004	77137	Rekit quick release valve	105823
60 11/05/2004	77137	Replace fuel filters	105823
60 11/05/2004	77137 POWER STEER FILTER B10M		105823
60 11/05/2004	77137 FILTER FUEL SCANIA L94UAB		105823
60 11/04/2004	77179 Checked engine - no power.	checked found turbo broken shaft. Removed clamp for bus 102.	105823
60 11/04/2004	77012 Repair & paint rear bumper bar.	Repair & prepaired rear bumper bar	105701
60 11/04/2004	77012 Paint wheels.		105701
60 11/04/2004	77012 Touch up paint work.	Touched up paint work	105701
60 11/04/2004	77012 Paint mirror arms.	Painted mirror arms	105701
60 11/04/2004	77012 Replace safety school crossing decal midd & rear.	Replaced safety school crossing decal	105701
60 11/04/2004	77068 Accident damage no 7030 - Repair o/s/r trailer cornercorne	Repaired accident damage - Repaired o/s/r trailer corner - corner bumper bar & painted.	105701
60 11/04/2004	77068 Accident damage no 7030 - Repair o/s/r trailer cornercorne	Repaired accident damage - Repaired o/s/r trailer corner - corner bumper bar & painted.	105701
60 11/04/2004	77068 Accident damage no 7430 - Polish o/s cornerrepair o/s/r co	Repaired accident damage - polished o/s cornerrepaired o/s/r corner bumper bar & painted	105823
60 11/04/2004	77068 Accident damage no 7430 - Polish o/s cornerrepair o/s/r co	Repaired accident damage - polished o/s cornerrepaired o/s/r corner bumper bar & painted	105701
60 11/03/2004	77012 Replace exit only on rear door.	Replaced exit only on rear door.	105701
60 11/03/2004	77012 Replace drivers seat decal.	Replaced drivers seat decals	105701
60 11/03/2004	77012 Adjust rear & middle doors.	Adjusted rear & middle doors	105701
60 11/03/2004	77012 BRACKET FOR CHECK STRAP DOOR HINGE		105701
60 11/03/2004	77012 CHECK STRAP DRIVERS DOOR HINGE		105701
60 11/03/2004	77012 Polish exterior panels / headers.	Polished exterior panels / headers	105701
60 11/03/2004	77012 Polish front bumper bar.	Repair & prepare rear bumper bar	105701
60 11/03/2004	77012 Polish all skit panels.	Polished all skit panels	105701
60 11/03/2004	77012 Clean A/C filter.	Cleaned A/C filter	105701
60 11/03/2004	77012 Secure seat frame trailer No 6 o/s.	Secured seat fram intrailer No 6	105701
60 11/03/2004	77012 Secure hand rail rivert at trailer.	Secured hand rail	105701
60 11/03/2004	77012 Fit holding strap to driver's compartment door.	Fitted holding strap to driver's compartment	105701
60 11/03/2004	77012 Repair drivers blind.	Repaired drivers blind.	105701
60 10/26/2004	76492 Inspection wiring harness in turntable for damage and repai		105333
60 10/26/2004	76458 Annual body check	Checked body.	105249
60 10/14/2004	75810 Trailer A/C blowing hot air.	Checked A/C working o/k - cleaned filter.	103946
60 10/14/2004	75735 BROOM HANDLE (8232715)		103946
60 10/14/2004	75735 BROOM HEAD (09803211)		103946
60 10/14/2004	75760		103946
60 10/13/2004	75735 Broken broom.	Replaced broom.	103749
60 10/13/2004	65097 Direct Purchase - BODYWORK	Creditor #:ATT001 ATTITUDE SIGNS P/O #:16989 Receiving #:20017 Date :2004-10-13 SUPPLY AND DECALS	

60 10/05/2004	75145 Warranty Recall - RC - 040161	Checked by Banlay - OK	102825
60 09/28/2004	74687 GLOBE FESTOON 24V5W	Replaced o/s rear clearance lamp assembly.	102018
60 09/28/2004	74687 O/S clearance light not working.	Replaced o/s rear clearance lamp assembly.	102018
60 09/28/2004	74687 LAMP (RED+AMBER)	Replaced o/s rear clearance lamp assembly.	102018
60 09/28/2004	74615 PADS 1527633	Creditor #:BAN001 BANLAY PTY LTD P/O #:19839 Receiving #:19619 Date :2004-09-28 BUS 60	
60 09/27/2004	74642 Loud whining noise l/h/f over 60 Km.	Road tested & checked for noise -replaced front tyres.	101898
60 09/27/2004	74586 GLOBE FESTOON 24V-3W		101898
60 09/27/2004	74586 Replace exit light globe.	Replaced exit light globe.	101898
60 09/27/2004	74615 Drive axle brakes low.	Replaced drive axle brake pads.	101898
60 09/27/2004	74615 Drive axle brakes low.	Replaced drive axle brake pads.	101898
60 09/14/2004	73809 Damaged valve leaking		100435
60 09/07/2004	73271 FLOURESENT TUBE ENDS TOMB-STONES		99433
60 09/06/2004	29468 REPLACE IDLER POST	Creditor #:REA002 READ RITE PTY LTD P/O #:7001 Receiving #:19206 Date :2004-09-06 WARRANTY	
60 09/06/2004	73271 repairs to interior light & refit lens.	repaired light fitting.	99264
60 09/02/2004	72986 O/S head light low bim out.	Replaced o/s head light globe.	98797
60 09/02/2004	72986 HEAD LIGHT GLOBE 24V 70/75W		98797
60 09/02/2004	72997 ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL		98797
60 09/02/2004	72997 TEXAMATIC DEXRON 111		98797
60 09/02/2004	72997 FILTER OIL K124 / L94UAB		98797
60 09/02/2004	72997 FILTER TRANSMISSION ZF 4139-298-038		98797
60 09/02/2004	72997 O RING FILTER KIT K93		98797
60 09/02/2004	72997 AIR FILTER SCANIA CLEANED		98797
60 09/02/2004	72997	D Service	98797
60 09/02/2004	72997		98797
60 08/31/2004	72817 Bus to slow on take of.	Checked & road tested o/k.	98448
60 08/31/2004	72817 Bus to slow on take of.	Checked & road tested o/k.	98448
60 08/19/2004	72057 Replace exit light globe.	Replaced exit light globe.	97004
60 08/19/2004	72057 GLOBE FESTOON 24V-3W	Replaced exit light globe.	97004
60 08/11/2004	70965 POS 9 & 10	Creditor #:BEA001 BEAUREPAIRES P/O #:18685 Receiving #:18629 Date :2004-08-11	
60 08/03/2004	70965 Repair tyres position - 9 - 10 - bald. Odometer - 94928.		94919
60 08/02/2004	70942 Replace o/s rear tyres.	Replaced o/s rear tyres.	94656
60 08/02/2004	70892		94656
60 07/22/2004	70271 Replaced drivers compartment door hinges.	Replaced hinges on drivers compartment door.	93342
60 07/20/2004	69929 AIR CONDITIONING REPAIR	Creditor #:REA002 READ RITE PTY LTD P/O #:18305 Receiving #:18092 Date :2004-07-20	
60 07/19/2004	69988 Replace exit light globe.	Replaced exit light globe.	92803
60 07/19/2004	69988 GLOBE FESTOON 24V-3W		92803
60 07/16/2004	69929 A/C blowing cold air.		92803
60 07/15/2004	69854 N/S head light not working.	Checked A/C.	92640
60 06/30/2004	68780 Replace tubro - warranty	Replaced head light globe n/s.	91312
60 06/16/2004	67946 Head light need adjusment.	Adjusted head light	89623
60 06/16/2004	67946 Drivers side blind need repair - won't stay down.	Side blinde replaced.	89623
60 06/16/2004	67946 DRIVERS BLIND		89623
60 06/09/2004	67619 Annual random audit	Checked.	88912
60 06/09/2004	67621 O/S clearance & indicator light smashed.	Replaced o/s/r clearance & indicator lights.	88912
60 06/09/2004	67621 LAMP (RED+AMBER)		88912
60 06/09/2004	67621 GLOBE FESTOON 24V5W		88912
60 06/09/2004	67620		88912
60 06/01/2004	66996 FAN+ALT BELT TWIN PULLEY		87870
60 06/01/2004	66996 A/C belts cracked.	Replaced A/C belts.	87773
60 05/13/2004	64847 POS 8	Creditor #:BEA001 BEAUREPAIRES P/O #:16877 Receiving #:16756 Date :2004-05-13	
60 05/10/2004	65401 Temp gauge not working.	Road tested temp gauge working o/k.	85175
60 05/07/2004	65097 Accident damage no 6285 - Polish o/s/r corner (Checked on	Polished o/s/r corner	84930
60 05/06/2004	65097 Accident damage no 6285 - Polish o/s/r corner (Checked on	Polished o/s/r corner	84930
60 05/06/2004	65097 Accident damage no 6266 - Repair o/s trailer panels 2345	Repair o/s trailer panels.	84930
60 05/03/2004	64847 Replaced tyre pos. no 8 - cracked in side wall .		84688
60 05/03/2004	64846 Replaced tyre pos. no 8 - cracked in side wall .		84688
60 04/30/2004	64735 Worn brake pads warning light is on and stays on always.		84607
60 04/22/2004	63850	REPAIRED WARNING LIGHT SENSOR.	83666
60 04/21/2004	63773 Steel plate under exhaust comming loose	Repaired exhaust cover under rear of bus.	83407
60 04/08/2004	63050 Drivers side window cant slide .	Lubricated & clean window tracks.	82073
60 04/07/2004	62510 AIR CONDITIONING REPAIR	Creditor #:REA002 READ RITE PTY LTD P/O #:16316 Receiving #:16035 Date :2004-04-07	
60 04/01/2004	62510 Large A/C compressor belt wheel screaming.	Replaced belts &adjusted all belts.	80958
60 03/31/2004	62362 BOOST PUMP EXCHANGE		80778
60 03/31/2004	62362 Big water leak r/h/s.	Replaced boost pump.	80778
60 03/16/2004	61461 N/S/R tyre leaks.	Checked n/s/r tyre o/k.	79052
60 03/15/2004	61285 33MM LOOSE WHEEL NUT INDICATOR		78866
60 03/15/2004	61285 Fit rear wheel nut indicators (5 indicators per rear wheel	Fitted rear wheel nut indicators.	78528
60 03/15/2004	61374 Repair door interlock - not operating - Replace pressure se	Replaced pressure sender.	78866
60 03/15/2004	61374 PRESSURE SWITCH L94UAB DOOR BRAKE		78866
60 03/15/2004	61284 AIR FILTER SCANIA CLEANED		78528
60 03/15/2004	61284 O RING FILTER KIT K93		78528
60 03/15/2004	61284 FILTER TRANSMISSION ZF 4139-298-038		78528
60 03/15/2004	61284 FILTER OIL K124 / L94UAB		78528
60 03/15/2004	61284 GLOBE S/CONTACT 24V-10W		78866
60 03/15/2004	61284 ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL		78528
60 03/15/2004	61284 TEXAMATIC DEXRON 111		78528
60 03/15/2004	61284	D Service	78528
60 03/15/2004	61284		78528
60 02/16/2004	59405 Replaced A/C 100A fuse.	replaced fuse in roof panel still no power at control panel.	75150
60 02/12/2004	59405 No air conditioning in front.	replaced fuse in roof panel still no power at control panel.	74970
60 02/04/2004	58821 Check and adjust A/C belts.	Checked and adjusted A/C belts.	73921
60 02/03/2004	58694 Header tank dry.	Replaced booster pump and bleed cooling system.	73546
60 02/03/2004	58694 RELAY WATER LEVEL B10M		73741
60 01/19/2004	57990 Replace front tyres.	Replaced front tyres.	72171
60 01/19/2004	57990 Replace rear passengers seat.	Replaced passengers seat.	72171
60 01/19/2004	57978 GLOBE INST 24V 2W		72171
60 01/19/2004	57978		72171
60 01/19/2004	57978 AIR FILTER SCANIA CLEANED		72171
60 01/19/2004	57978 LENS TO SUIT 2029 (RED+AMBER)		72171
60 01/15/2004	57675 Temp repair accident damage.	Temp repaired accident damage.	71835
60 01/14/2004	57550 Need to replace o/s drive axle shocker.	Removed and checked o/k.	71674
60 01/05/2004	56286 NO POWER	Creditor #:BAN001 BANLAY PTY LTD P/O #:14532 Receiving #:14331 Date :2004-01-05 WARRANTY	
60 12/23/2003	56612 GLOBE STOP AND TAIL		69582
60 12/23/2003	56612 HEAD LIGHT GLOBE 24V 70/75W		69582
60 12/23/2003	56612 N/S lower stop light u/s.	Replaced n/s stop light globe.	69582

60 12/23/2003	56612 O/S head light and park light out.	Replaced head light glob and park light globe.	69582
60 12/18/2003	56286 Very sluggish on take off.	Road tested and checked.	69411
60 12/17/2003	56286 Very sluggish on take off.	Road tested and checked.	69411
60 12/11/2003	55912 O/S head light out.	No fault foundno driver found.	68927
60 12/10/2003	53820 ACCIDENT DAMAGE - DECAL	Creditor #:ATT001 ATTITUDE SIGNS P/O #:13809 Receiving #:13976 Date :2003-12-10	
60 12/09/2003	55617 Replace exit light globe.	Replaced globe.	68594
60 12/09/2003	55617 GLOBE FESTOON 24V-3W		68594
60 12/01/2003	55042		67609
60 11/25/2003	54226 CHASSIS REPAIRS	Creditor #:ROA001 Road Safety Inspections P/O #:13910 Receiving #:13687 Date :2003-11-25	
60 11/25/2003	54104 POS 6	Creditor #:BEA001 BEAUREPAIRES P/O #:13877 Receiving #:13670 Date :2003-11-25 FIT GBS TYRE	
60 11/23/2003	54226 Annual Inspection - BC077056	Annual Inspection - BC077056	66690
60 11/18/2003	53756 POS 3	Creditor #:BEA001 BEAUREPAIRES P/O #:13780 Receiving #:13494 Date :2003-11-18	
60 11/17/2003	54104 Replaced tyre pos. no 9 - low tread.		66586
60 11/17/2003	54104 MICHELIN TYRE 275-70R 22.5		66586
60 11/17/2003	54153 Top pivot on middle door need fixing .	Fixed.	66597
60 11/17/2003	54166 Check electric.	Fited emergency exit decalsrepaired till tray.	66597
60 11/17/2003	54104 LENS REV+INT LIGHT		66597
60 11/17/2003	54104 HANDSTRAP GREY		66597
60 11/13/2003	53821 Replace emergency decals.	Replaced	66586
60 11/13/2003	53821 Replace exterior emergency decals.	Replaced	66586
60 11/13/2003	53821 Paint wheels.	Painted	66586
60 11/13/2003	53821 Check lub and adjust front and rear doors.	Fixed	66586
60 11/13/2003	54030 Repair and paint trailer panels.	Repaired and painted.	66586
60 11/13/2003	53820 Repair and paint o/s trailer panels No - 1-2-3-4.	Repaired and painted.	66586
60 11/12/2003	53938 Remove o/s trailer clearance and indicator lights.	Removed.	66586
60 11/12/2003	53821 Secure drivers sun blind.	Secured	66586
60 11/12/2003	53821 Polish n/s mid rail.	Polished	66586
60 11/12/2003	53821 Polish front and rear headers.		66586
60 11/12/2003	53821 Paint wheels.	Painted	66586
60 11/12/2003	53821 Secure n/s seat No - 6 - 11.	Secured	66586
60 11/12/2003	53821 Secure o/s seat No - 4.	Secured	66586
60 11/12/2003	53821 Secure hand rails	Secured	66586
60 11/12/2003	53821 Secure rear modesty panels.	Secured	66586
60 11/12/2003	53821 Paint front and rear bumpers.	Polished	66586
60 11/12/2003	53821 Paint till stand and mirror arms.	Painted	66586
60 11/12/2003	53821 Check lub and adjust drivers seat.	Fixed	66586
60 11/12/2003	53821 Secure n/s trailer panels	Secured	66586
60 11/12/2003	53821 Check lub and adjust front and rear doors.	Fixed	66586
60 11/12/2003	53729 DISC PADS SCANIA	Creditor #:TRA004 TRADE BRAKE+CLUTCH CO. P/O #:13754 Receiving #:13419 Date :2003-11-12	
60 11/12/2003	53820 Repair and paint o/s trailer panels No - 1-2-3-4.	Repaired and painted.	66586
60 11/11/2003	53756 Replace tyre position - 3 - damaged / warranty /.Odometer -		66514
60 11/11/2003	53729 Steam clean all bus.		66514
60 11/11/2003	53729 Steam clean all bus.		66514
60 11/11/2003	53729 Oil leak at dip-stick tube.	Repaired	66514
60 11/11/2003	53729 SCREW TORX 8 X 15MM SIDE PANEL		66586
60 11/11/2003	53729 LARGE CORNER GUSSET		66586
60 11/11/2003	53729 Front and middle axle brakes to check / getting low /.	Checked	66586
60 11/11/2003	53729 WEAR SENSOR SCANIA DISC BRAKE		66586
60 11/11/2003	53729 Front and middle axle brakes to check / getting low /.	Checked	66586
60 11/10/2003	53729 A/C belts to replace / start to crack /.	Replaced	66514
60 11/10/2003	53729 BELT ALT W/PUMP CRANK SCANIA ARTIC		66514
60 11/10/2003	53729 A/CON BELT SCANIA ARTIC 21/32X65		66514
60 11/10/2003	53729 FAN+ALT BELT TWIN PULLEY		66514
60 11/10/2003	53729 A/C pipe rubs on alternator at top.	Secured	66514
60 11/10/2003	53729 A/C belts to replace / start to crack /.	Replaced	66514
60 11/10/2003	53729 Alternator belt to replace / split /.	Replaced	66514
60 11/10/2003	53729 Front and middle axle brakes to check / getting low /.	Checked	66514
60 11/06/2003	53489 FILTER FUEL K124 / LU94A		66077
60 11/06/2003	53489 HYDRAULIC FILTER L94UAB		66077
60 11/06/2003	53489	Clean a/c filters	66077
60 11/06/2003	53489 RPM BORATE EP LUBE 220		66077
60 11/06/2003	53489	Replace coolant filter in engine cooling system	66077
60 11/06/2003	53489 POWER STEER FILTER B10M		66077
60 11/06/2003	53489 FILTER FUEL SCANIA L94UAB		66077
60 11/06/2003	53489 DRYER KIT {HALDEX}B10B+B12+L94UAB+B7R		66077
60 11/06/2003	53489 GLOBE INST 24V 2W		66077
60 11/06/2003	53489 LENS TO SUIT 2319		66077
60 11/06/2003	53489	Inspect bus as per inspection sheet	66077
60 11/06/2003	53489	Replace fuel filters	66077
60 11/06/2003	53489	Replace final drive oil	66077
60 11/06/2003	53489	Replace hydralic fan filter and top up oil	66077
60 11/06/2003	53489	Replace air dryer cansiter	66077
60 11/06/2003	53489	Adjust valve clearances	66077
60 11/06/2003	53489	Replace power steering filter	66077
60 11/06/2003	53489	Rekit quick release valve	66077
60 11/06/2003	53552 Annual body check	Checked.	66229
60 11/06/2003	53588 Check electris.	Replaced n/s bottom stop light globe and number plate light globe	66229
60 10/31/2003	53216 Fit sight glass for header tank	Fitted sight glass.	65952
60 10/31/2003	53216 GLASS SIGHT EXPANSION TANK		65952
60 10/31/2003	53216 DECAL EXPANSION TANK		65952
60 10/30/2003	53245 Electrical check and repair.	Checked and repaired.	65794
60 10/30/2003	53216 Fit sight glass for header tank		65794
60 10/13/2003	51266 TURNTABLE PLATE		
60 10/09/2003	51851 n/s. mirror needs tightening.	Creditor #:VOL001 VOLGREN AUSTRALIA P/L P/O #:13279 Receiving #:12846 Date :2003-10-13	63919
60 10/01/2003	51266 N/S middle damaged.	sesured o/k.	63228
60 10/01/2003	51283 GLOBE FESTOON 24V-3W	Repaired by Volgren	63228
60 10/01/2003	51283		63228
60 09/22/2003	50538 Recall campaign - RAO21661		62698
60 09/19/2003	50521 GLOBE STOP AND TAIL		62698
60 09/19/2003	50521 No bottom brake lights.	Replaced globes.	62698
60 09/18/2003	47613 POS 7+8	Creditor #:BEA001 BEAUREPAIRES P/O #:11993 Receiving #:12351 Date :2003-09-18	
60 09/09/2003	49682 CONSUMABLE DELIVERY CHARGE	Creditor #:BAN001 BANLAY PTY LTD P/O #:12359 Receiving #:12107 Date :2003-09-09	
60 09/09/2003	49682 DIRECT BRAKES	Creditor #:BAN001 BANLAY PTY LTD P/O #:12359 Receiving #:12107 Date :2003-09-09	
60 09/08/2003	49682 N/S front and rear indicators not working.	Repaired flasher unit.	61331
60 09/08/2003	49682 Replace brake padel load sensor switch	Replaced foot valve potentiometer and road test o/k.	61331

60 09/03/2003	48506 AIR CONDITIONING REPAIR	Creditor #:REA002 READ RITE PTY LTD P/O #:12261 Receiving #:12022 Date :2003-09-03	
60 09/03/2003	47571 REPLACE RELAY	Creditor #:REA002 READ RITE PTY LTD P/O #:11975 Receiving #:12021 Date :2003-09-03	
60 09/01/2003	48907 WASHER BOTTLE FILLER	Creditor #.:VOL001 VOLGREN AUSTRALIA P/L P/O #:12374 Receiving #:11961 Date :2003-09-01	
60 08/29/2003	48907 Accident damage no - 4911 - Remove front bumper bar repair	Checked.	60426
60 08/29/2003	48907 Accident damage no 5321 - Remove and repair n/s/f corner bu	Repaired.	60426
60 08/28/2003	48905 10mm HEATER HOSE X 2Mtr	Creditor #:BUR001 BURSON AUTO PARTS P/O #:12377 Receiving #:11898 Date :2003-08-28	
60 08/28/2003	48905 Header tank small hose cracked.	Replaced hose.	60426
60 08/28/2003	48907 Accident damage no 5321 - Remove and repair n/s/f corner bu	Repaired.	60426
60 08/21/2003	48506 Replace solid state relay - in front a/c		59865
60 08/21/2003	48511 Jackknife light came on and jamed the brakes while bus was m	Repaired.	59865
60 08/21/2003	48558 Road test and check electric.	Road tested and checked electric o/k.	59865
60 08/21/2003	48511 DIODE EXCITER		59865
60 08/21/2003	48459 Accident damage no 5314 - Poilsh o/s trialer panel no 6	Poilshed by drivers	59865
60 08/19/2003	48381 Check batteries.	Jump started and checked batteries.	59682
60 08/08/2003	47571 Replace a/c solid state relay	WARRANTY REPAIRS.	58251
60 08/08/2003	47613 Repair tyres position - 7 - 8 - bald. Odometer - 58441.		58251
60 08/08/2003	47603 ENGINE OIL DELO 400 15W-40 MULTIGRADE		58251
60 08/08/2003	47603 AIR FILTER SCANIA CLEANED		58251
60 08/08/2003	47603 O RING FILTER KIT K93		58251
60 08/08/2003	47603 FILTER TRANSMISSION ZF 4139-298-038		58251
60 08/08/2003	47603 FILTER OIL K124 / L94UAB		58251
60 08/08/2003	47603 GLOBE INST 24V 2W		58251
60 08/08/2003	47603 TEXAMATIC DEXRON 111		58251
60 08/08/2003	47603	D Service	58251
60 08/08/2003	47603		58251
60 07/25/2003	46541 FAN+ALT BELT TWIN PULLEY		56706
60 07/25/2003	46541 Belt cracked.	Replaced A/C belts.	56706
60 06/25/2003	44557 Annual random audit	Checked.	53266
60 06/25/2003	43640 POS 1+2	Creditor #.:BEA001 BEAUREPAIRES P/O #:10879 Receiving #:10591 Date :2003-06-25	
60 06/25/2003	44524		53266
60 06/23/2003	44347 Jack knife light and ABS light comes on power to motor goes	Checked nothing found.	52998
60 06/13/2003	43640 Need balance tyres position - 1 - 2 - to balance. Odometer		51731
60 06/12/2003	43698 Road test .	Road test for tyres.	51731
60 06/12/2003	43592 Front wheel wobble	Road test and replaced front tyres .Painted 1 wheel.	51731
60 06/12/2003	43592 Front wheel wobble	Road test and replaced front tyres.	51731
60 06/11/2003	43506 L/H indicator needs replacing.	Replaced l/h indicator light.	51376
60 06/11/2003	43506 INDICATOR LIGHT FRONT ARTIC		51376
60 06/07/2003	43346 L/H bottom break light not working.	Replaced nglobe.	50711
60 06/07/2003	43346 GLOBE STOP AND TAIL		50976
60 06/05/2003	43191 Replace exit light globe.	Replaced globe.	50550
60 06/05/2003	43191 GLOBE FESTOON 24V-3W		50550
60 06/04/2003	43116 White light sequence out of sequence with violet interior l	Rewired switch with diode.	50387
60 05/27/2003	42551 Breakdown at - DINGLEY - Indicators u/s. O/S side indicato	Replaced lamp	49117
60 05/27/2003	42551 LENS TO SUIT 2030 LAMP		49117
60 05/26/2003	42384 Trailer brake pads low need replacing.	Replaced pads and road test.	48756
60 05/26/2003	42384 Trailer brake pads low need replacing.	Replaced pads and road test.	48756
60 05/26/2003	42384 DISC PADS SCANIA		49028
60 05/21/2003	42131		48562
60 05/21/2003	42131 GLOBE FESTOON 24V-3W		48562
60 05/21/2003	42131 LENS TO SUIT 2319		48562
60 05/21/2003	42131 LENS TO SUIT 2557 LAMP		48562
60 05/20/2003	42137 Repair n/s mirror arm.	Repaired n/s mirror arm.	48170
60 05/20/2003	41463 REPLCE AS REQUIRED	Creditor #.:ATT001 ATTITUDE SIGNS P/O #:10380 Receiving #:10151 Date :2003-05-20	
60 05/14/2003	41686 Destination lights u/s.	Repaired by " VOLGREN "	47827
60 05/13/2003	41643 Paint wheels.	Painted wheels.	47827
60 05/13/2003	41463 Accident Damage no 4352 Replace n/s front section of artic	Repaired.	47827
60 05/13/2003	41463 AMBER REFLECTOR SIDE MOUNT		47827
60 05/12/2003	41454 Drivers side mirror broken.	Replaced mirror.	47646
60 05/12/2003	41463 Accident Damage no 4352 Replace n/s front section of artic	Repaired.	47827
60 05/05/2003	41020 EMERGENCY EXIT LIGHT		46460
60 05/05/2003	41020 GLOBE FESTOON 24V-3W		46768
60 05/05/2003	41020 Replaced exit light lens and globe.	Replaced lens and globe.	46460
60 04/10/2003	39238 POS 10	Creditor #.:BEA001 BEAUREPAIRES P/O #:9718 Receiving #:9283 Date :2003-04-10	
60 04/04/2003	39238 Replace tyre position - 10 - flat. Odometer - 44124.	REPLACED	44044
60 04/04/2003	39272 Replaced tyre position 10.	Replaced tyre.	44044
60 04/01/2003	38971 O/S/R indicator lens crack.	Replaced lens.	43700
60 04/01/2003	38971 LENS TO SUIT 2030 LAMP		43700
60 04/01/2003	38984		43700
60 03/28/2003	38782 While driving straight line jack knife light came on. Bus wo	Checked o/k.	43057
60 03/28/2003	38787 Replace o/s stop light globe.	Replaced globe.	43057
60 03/28/2003	38787 GLOBE STOP AND TAIL		43137
60 03/25/2003	38484 Accident damage no - 3996 Replace emergency exit low floor	Repaired	42901
60 03/25/2003	38484 Accident damage no -3759 Poilsh rear bumper bar and touch up	Repaired	42901
60 03/25/2003	38484 Accident damage No - 3678 Repair o/s/r corner bumper bar and	Repaired	42901
60 02/25/2003	34562 POS 9	Creditor #.:BEA001 BEAUREPAIRES P/O #:8486 Receiving #:8505 Date :2003-02-25	
60 02/24/2003	36496 BRAZILLIAN MIRROR L/H		39263
60 02/24/2003	36496 ENGINE OIL DELO SHP MULTIGRADE		39017
60 02/24/2003	36496 FILTER AIR SCANIA USE AF25066		39017
60 02/24/2003	36496 O RING FILTER KIT K93		39017
60 02/24/2003	36496 FILTER TRANSMISSION ZF 4139-298-038		39017
60 02/24/2003	36496 FILTER OIL K124 / L94UAB		39017
60 02/24/2003	36496	D Service	39017
60 02/24/2003	36496 TEXAMATIC DEXRON 111		39017
60 02/24/2003	36496		39017
60 02/18/2003	33790 POS 7+8+9	Creditor #.:BEA001 BEAUREPAIRES P/O #:8263 Receiving #:8364 Date :2003-02-18	
60 02/18/2003	33790 POS 10	Creditor #.:BEA001 BEAUREPAIRES P/O #:8263 Receiving #:8364 Date :2003-02-18	
60 02/12/2003	35513 Front left indicator cover broken.	Replaced cover.	37462
60 02/12/2003	35513 INDICATOR LIGHT FRONT ARTIC		37462
60 02/05/2003	35087 Check over for warranty	Checked.	36430
60 02/03/2003	34895 Replace exit light globe.	Replaced globe.	35931
60 02/03/2003	34895 GLOBE FESTOON 24V-3W		35931
60 01/30/2003	34562 Replace tyre position - 9 - flat. Odometer - 35682.		35601
60 01/29/2003	34494 Wheel wobble when braking ..	Repaired brakes and road test.	35450
60 01/29/2003	34542 A/C. sounds like rock grinder ..	Adjusted A/C compressor.	35601
60 01/29/2003	34495 Front replce pads and remove check middle axle		35601

60 01/29/2003	34495 Front replce pads and remove check middle axle	Replaced front and midle axle brake pads.	35450
60 01/29/2003	34495 DISC PADS SCANIA		35601
60 01/29/2003	34495 WEAR SENSOR SCANIA DISC BRAKE		35601
60 01/23/2003	34293 Front A/C not working.	Tested o/k.	35124
60 01/21/2003	18091 SLOW ON TAKE OFF	Creditor #::SCA001 SCANIA AUSTRALIA PTY LTD P/O #:3722 Receiving #:7916 Date :2003-01-21	
60 01/16/2003	33790 Reolace tyres Pos. Nos 789 Bald. * No 10 Bald & side wall		34209
60 01/16/2003	33791 Replace drive axle tyres	Replaced	34209
60 01/16/2003	33791 Service		34209
60 01/16/2003	33758		34029
60 01/16/2003	33758 PUMP WIPER-WASHER 24 VOLT		34209
60 01/16/2003	33758 Service		34209
60 01/08/2003	33331 Accelerator very slow to respond - 10 to 15 seconds no good	Check gear box system clear codes and road test - OK	33153
60 01/07/2003	21115 BROOM BRAKE	Creditor #::BAN001 BANLAY PTY LTD P/O #:4486 Receiving #:7672 Date :2003-01-07	
60 01/04/2003	33171 Temp gauge do not work.	Checked and tested o/k.	32960
60 12/30/2002	32879 A/C not cold.	Cleaned filters and checked o/k.	32328
60 12/20/2002	32578 GLOBE FESTOON 24V-3W		31406
60 12/20/2002	32578 Replace exit light globe.	Replaced globe.	31406
60 12/17/2002	32388 R/H/S lower stop light out.	Replaced globe.	30700
60 12/17/2002	32388 GLOBE STOP AND TAIL		30700
60 12/10/2002	31841 All brake pads low.	Checked all brakes o/k.	29919
60 12/10/2002	31841 GLOBE FESTOON 24V-3W		30000
60 12/09/2002	31828 Replace exit light globe.	Replaced globe.	29919
60 12/09/2002	31828 GLOBE FESTOON 24V-3W		29919
60 12/04/2002	31537 GLOBE FESTOON 24V-3W		29573
60 12/04/2002	31537 GLOBE STOP AND TAIL		29573
60 12/04/2002	31537		29573
60 11/28/2002	31188 Replace 2x exit light globe.	Replaced globes.	28521
60 11/28/2002	31188 GLOBE FESTOON 24V-3W		28521
60 11/26/2002	30736 CHASSIS REPAIRS	Creditor #::ROA001 Road Safety Inspections P/O #:7428 Receiving #:7068 Date :2002-11-26	
60 11/26/2002	30930 O/S/R top brake light lens cracked.	rEPLACED LENS.	28073
60 11/25/2002	30930 O/S/R top brake light lens cracked.	rEPLACED LENS.	28073
60 11/24/2002	30736 Annual Inspection - BC 067792	Annual Inspection - BC 067792	27405
60 11/20/2002	30631 REPAIR SIDE GLASS	Creditor #::KNI001 KNIGHTS WINDSCREEN REPAIRS P/O #:7367 Receiving #:6969 Date :2002-11-20	
60 11/20/2002	30582 Re-paint wheels (white)	Painted wheels.	27161
60 11/20/2002	30582 Repair front window blind or re-place	Replaced blind.	27161
60 11/20/2002	30582 Secure No.3 door (trailer) modesty panel	Secured.	27161
60 11/20/2002	30582 Polish front bumper bar	Polished front bumper bar.	27161
60 11/20/2002	30582 Polish n/s/ff & n/s/r top corners	Polished front and rear headers.	27161
60 11/20/2002	30582 Re-paint wheels (white)	Painted wheels.	27161
60 11/20/2002	30582 Check security of all lower panels n/s & o/s	Checked o/s and n/s panels for security.	27161
60 11/20/2002	30582 Repair front window blind or re-place	Replaced blind.	27161
60 11/20/2002	30582 Replace screw in front o/s No.1 hand rail	Fited screw in handrail.	27161
60 11/20/2002	30582 Clean front & rear a/c filters - internally	Cleaned filters A/C.	27161
60 11/20/2002	30582 DRIVERS BLIND ISUZU 987X1000MM		27405
60 11/20/2002	30582 Check behind rear 5 seater base	Checked.	27161
60 11/20/2002	30631 Poilish n/s/trailer side windows x3		27405
60 11/08/2002	29990	Clean a/c filters	25823
60 11/08/2002	29990	Replace final drive oil	25823
60 11/08/2002	29990	Replace coolant filter in engine cooling system	25823
60 11/08/2002	29990 RPM BORATE EP LUBE 220		25823
60 11/08/2002	29990 HYDRAULIC FILTER L94UAB		25823
60 11/08/2002	29990 FILTER FUEL K124 / LU94A		25823
60 11/08/2002	29990	Inspect bus as per inspection sheet	25823
60 11/08/2002	29990	Replace fuel filters	25823
60 11/08/2002	29990	Adjust valve clearances	25823
60 11/08/2002	29990	Replace power steering filter	25823
60 11/08/2002	29990	Rekit quick release valve	25823
60 11/08/2002	29990	Replace hydralic fan filter and top up oil	25823
60 11/08/2002	29990	Replace air dryer cansiter	25823
60 11/08/2002	29990 POWER STEER FILTER B10M		25823
60 11/08/2002	29990 FILTER FUEL SCANIA L94UAB		25823
60 11/08/2002	29994 Steam clean all bus.	Steam cleaned.	25823
60 11/08/2002	29994 FILTER FUEL SCANIA L94UAB		25823
60 11/08/2002	29994 POWER STEER FILTER B10M		25823
60 11/08/2002	29994 FILTER FUEL K124 / LU94A		25823
60 11/08/2002	29994 HYDRAULIC FILTER L94UAB		25823
60 11/08/2002	29998 Steam clean all bus.	Steam cleaned.	25823
60 11/08/2002	29999 Tighten up all around panels.	Tightened up all panels.	25823
60 11/08/2002	29959 Annual body check	Checked.	25823
60 11/08/2002	29959 BUSHING HORN BUTTON SCANIA(kit of 4)		25823
60 11/01/2002	29415 POS 7	Creditor #::BEA001 BEAUREPAIRS P/O #:6988 Receiving #:6650 Date :2002-11-01	
60 10/31/2002	29595 Radio only works in back section of bus.	Checked and adjusted speaker control switch.	25031
60 10/30/2002	29468 Replace a/c idler post cracked	Replaced by "READ RITE"	24930
60 10/30/2002	29415 Replace tyre position - 7 - Cracked side wall. Odometer - 24		24930
60 10/30/2002	29467 A/CON BELT SCANIA ARTIC		24930
60 10/30/2002	29467 PULLEY TO COMP SCANIA L94UAB		24930
60 10/30/2002	29467 Replace a/c belts	Replaced A/C belts.	24930
60 10/29/2002	29409 Replace rear tyre position - 7.	Replaced tyre.	24805
60 10/29/2002	29366 Rear door does not close fully.	Fixed rear door.	24805
60 10/29/2002	29365		24805
60 10/24/2002	29100 REAR DOOR DOES NOT CLOSE	CHECKED O/K.	24146
60 10/11/2002	28273 Rear a/c unit not working properly	CHECKED-FOUND COMPUTER FAULT (NOT FIXED)	22588
60 10/10/2002	28259 Replace warning light globe	Replaced warning globe	22414
60 10/10/2002	28259 GLOBE FESTOON 24V-3W		22414
60 10/08/2002	28067 Replace stop light globe.		22011
60 10/08/2002	28067 GLOBE STOP AND TAIL	Replaced globe.	22011
60 10/05/2002	27887 CHECK REAR A/C.		21591
60 10/04/2002	27325 HEXAGON SCREW	Creditor #::BAN001 BANLAY PTY LTD P/O #:6216 Receiving #:6106 Date :2002-10-04	
60 10/04/2002	27325 M10 HEX NUT	Creditor #::BAN001 BANLAY PTY LTD P/O #:6216 Receiving #:6106 Date :2002-10-04	
60 10/04/2002	27325 SPACING SLEEVE	Creditor #::BAN001 BANLAY PTY LTD P/O #:6216 Receiving #:6106 Date :2002-10-04	
60 09/30/2002	27533 Rear A/C fan noisy.	Cleared fan from grille.Cleaned air intake A/Cfilters.	21004
60 09/26/2002	27325 Modify a/c mounting	A/C modify.	20881
60 09/26/2002	27325 MANIFOLD WASHER VOLVO		20881
60 09/13/2002	26491 FILTER OIL K124 / L94UAB		19583
60 09/13/2002	26491 FILTER TRANSMISSION ZF 4139-298-936		19583

60 09/13/2002	26491 O RING FILTER KIT K93		19583
60 09/13/2002	26491 FILTER AIR SCANIA USE AF25066		19583
60 09/13/2002	26491 ENGINE OIL DELO SHP MULTIGRADE		19583
60 09/13/2002	26491 TEXAMATIC DEXRON 111		19583
60 09/13/2002	26491 AIR FILTER SCANIA CLEANED		19583
60 09/13/2002	26491	D Service	19583
60 09/13/2002	26491		19583
60 09/02/2002	25687 Bolt missing at alternator bracket.		18117
60 08/28/2002	25443 N/S stop light u/s.	Replaced missing bolt on adjuster pulley. Replaced globe.	17404
60 08/28/2002	25443 GLOBE INDICATOR 24V21W SINGLE CONTACT		17404
60 07/26/2002	23607 Replace o/s clearance lens.	Replaced lens.	13149
60 07/26/2002	23607 LENS TO SUIT 2029 (RED+AMBER)		13149
60 07/02/2002	22228 Warranty - repair oil collector.		11474
60 07/01/2002	0 Imported Service History	Imported Service History	0
60 07/01/2002	22139		11474
60 06/27/2002	21960 Air system not building air quick enough	Checked o/k.	11289
60 06/27/2002	20913 FIT DECALS TO BUS	Creditor #::ATT001 ATTITUDE SIGNS P/O #::4533 Receiving #:4300 Date :2002-06-27	
60 06/26/2002	21827 Air bag too low r/r.	Checked air bags suspension operation.	
60 06/17/2002	20913 AMBER REFLECTOR SIDE MOUNT		11088
60 06/17/2002	20913 Accident damage - No 2217	REPAIRED	9925
60 06/17/2002	20913 Re-fit front bumper bar & decals	RE-FITTED BAR & DECALS - ALSO FITTED O/S/R PANELS	9925
60 06/14/2002	20913 Service	REFIT O/S/R SIDE PANELS FRONT BUMPER REPAIR & PAINT	9925
60 06/13/2002	21115 Fit broom brake - Scania warranty		9810
60 06/13/2002	20913 Accident damage - No 2217	REPAIRS TO FRONT BUMPER BAR	9810
60 06/12/2002	20913 Paint panels	PAINTED	9810
60 06/11/2002	20913 Accident damage - No 2217 Remove front bumper bar repair	IN PROGRESS	9629
60 06/11/2002	20913 Remove no: 12 - 13 o/s/r panels - manufacture new ones & pri	IN PROGRESS	9810
60 06/05/2002	20706 Trailer a/c unit flashing cool and not heating		9347
60 06/03/2002	20542 Power steering oil leak at consitina.Loosing power - 20Kmh		9073
60 05/29/2002	17772 DIRT IN FUEL TANK	Creditor #::BAN001 BANLAY PTY LTD P/O #::4253 Receiving #:3795 Date :2002-05-29	
60 05/29/2002	14492 BATTERY+OIL CAP+	Creditor #::BAN001 BANLAY PTY LTD P/O #::2863 Receiving #:3791 Date :2002-05-29 FUEL LEAK	
60 05/28/2002	19525 SPLIT P7	Creditor #::BEA001 BEAUREPAIRES P/O #::4021 Receiving #:3764 Date :2002-05-28	
60 05/28/2002	20229 Sel call for bus - 60 - is - 58.		8184
60 05/16/2002	19525 Replace tyre position - 7 - split. Odometer - 006920.		6911
60 05/15/2002	19560 Replace o/s outer tyre	REPLACED TYRE	6747
60 05/15/2002	19433		6747
60 05/15/2002	19433 Service	A SERVICE & R/TESTED	6747
60 05/09/2002	19115 Re-fill power steering reservoir	FE-FILLED	5984
60 04/30/2002	18526 Throttle - no power on take off on hills	REPAIRS UNDER WARRANTY	5417
60 04/22/2002	18091 Too slow on take off	Repair under warranty	5417
60 04/16/2002	17772 Warranty - No power on take off - looks like not getting	Found dirt in fuel line	5095
60 04/15/2002	17750 Breakdown - no power - 3.30 - Springvale c/o bus 1		5095
60 03/27/2002	16107 1ST SERVICE	Creditor #::BAN001 BANLAY PTY LTD P/O #::3245 Receiving #:3003 Date :2002-03-27	
60 03/24/2002	16737 Repair a/c under -WARRANTY	Repaired under warranty	4854
60 03/24/2002	16737 A/C u/s.		4854
60 03/19/2002	16456 Check engine system for lack of power	Unable to locate fault	4665
60 03/15/2002	14182 TYRE POS 345678910	Creditor #::BEA001 BEAUREPAIRES P/O #::2791 Receiving #:2850 Date :2002-03-15 ALL RECAPS	
60 03/14/2002	16107 Warranty service		4338
60 03/04/2002	15630 A/S Blowing hot air.	Checked o/k.	2876
60 02/25/2002	15234 2nd A/C unit not working.		1788
60 02/20/2002	14979 Delay longer than other new artics.	CHECKED O/K.	1028
60 02/12/2002	14492 Battery flat in the mornings		416
60 02/12/2002	14492 Fuel leaks		416
60 02/12/2002	14492 Oil filler cap rubbering on a/c belts		416
60 02/12/2002	14492 Service		416
60 02/07/2002	14314 New registration - BC - 051768	New bus	11080
60 02/07/2002	14172 Service		11080
60 02/07/2002	14172 NUT HAND RAIL CLAMP (280010)		11080
60 02/06/2002	14182 REPLACE ALL TYRES POSITION Nos 345678910 .		11080
60 02/06/2002	14172 D HANDLE LENLOCK CHROME PLATED		11080
60 02/06/2002	14172 SWITCH-SOLENOID STARTER		11080
60 02/06/2002	14172 BROOM HANDLE (8232715)		11080
60 02/06/2002	14172 BROOM HEAD (09803211)		11080
60 02/06/2002	14172 Service	FIT UP AS REQ DECALS	11080
60 02/06/2002	14172 PASSENGER COUNTER		11080
60 02/06/2002	14172 TIME TABLE HOLDER		11080
60 02/05/2002	14172 Fit decals		11080
60 02/05/2002	14172 SAFETY TRIANGLE DECAL		11080
60 02/05/2002	14172 SAFETY TRIANGLES 3 PER BOX		11080