Veh#	Date	W/O#	Description	Notes	Odometer
796	10/28/2026	1379243		remove decals from inside of bus	1212266
796	10/27/2026	1379243		removed decals/glue	1212266
796	10/27/2026	1379243	Remove all Ventura + PTV decals including orange honeycomb l	Removed all ptv related decals job completed	1212266
796	09/30/2026	1364312		COMPLETED 16.08.2026	1212266
796	09/07/2026	1366821	Direct Purchase - MECHANICAL	Creditor #:GB-ROA001 ROAD SAFETY INSPECTIONS P/O #:G418040 Receiving #:445582 Date :2026-09-08 RSI	1212266
796	09/02/2026	1366821		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1212266
796	09/02/2026	1366821		VEHICLE SAFETY INSPECTION	1212266
796	09/02/2026	1366821		ANNUAL SAFETY INSPECTION SERIAL # RSI 080642 WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25 completed	1212266
796	09/02/2026	1366821		Assisting	1212266
796	09/02/2026	1366939	Consumables		1212266
796	09/02/2026	1366939	Mechanic entered - Elec and Light OTHER rear door N/s out s	replaced superior light (Step light)	1212266
796	09/02/2026	1366958	Consumables		1212266
796	09/02/2026	1366958	Consumables		1212266
796	09/02/2026	1366853	Consumables		1212266
796	09/02/2026	1366853	Consumables		1212266
796	09/02/2026	1366958	Mechanic entered - Body Other rust under front .	clean and paint.	1212266
796	09/02/2026	1366853	Mechanic entered - Body Other N/S front seat leg broken.	replaced front N/s seat leg. completed/	1212266
796	09/01/2026	1366431	Consumables		1212266
796	09/01/2026	1366431	Consumables		1212266
796	09/01/2026	1366431		replaced seat leg centre rear seat	1212266
796	09/01/2026	1366431	Mechanic entered - Body Other O/S pas-seat mount broken	fitted back welded mount	1212266
796	08/31/2026	1366219	Mechanic entered - Elec and Light Exterior Lights N/R top pa	Checked bus and found n.s rear top park light not working checked upstairs and electrical room for spare light but couldnt find any ended up using a new one.Checked and found that it was the actual light. Changed the plug to a douche plug for more secure connection and tested. Completed	1212266
796	08/31/2026	1366219	LIGHT LED STOP/TAIL RED 9 LED - 3 LED PARKER		1212266
796	08/31/2026	1366219	Consumables		1212266
796	08/31/2026	1366166		completed	1212266
796	08/31/2026	1366166	Body (None) Carry out Final Inspection For RSI	carried out final inspection for RSI	1212266
796	08/31/2026	1366166		Assist Sisil with minor repairs from RSI	1212266
796	08/25/2026	1361163		Replaced and secured seat	1212266
796	08/25/2026	1361162		Replaced and secured seats	1212266
796	08/25/2026	1361162	Consumables		1212266
796	08/25/2026	1361162	Consumables		1212266
796	08/25/2026	1361163	Consumables		1212266
796	08/25/2026	1361163	Consumables		1212266
796	08/24/2026	1361162	FOLDING SEAT REPAIR	Creditor #:GB-RP AUTO RP AUTO UPHOLSTERY PTY LTD P/O #:G416480 Receiving #:444400 Date :2026-08-24	1212266
796	08/24/2026	1361163	FOLDING SEAT REPAIR	Creditor #:GB-RP AUTO RP AUTO UPHOLSTERY PTY LTD P/O #:G416480 Receiving #:444400 Date :2026-08-24	1212266
796	08/20/2026	1363199		CARRY OUT A/C - B SERVICE AS PER CHECK LIST il or drier dont need to changed as unit has done less then 20K since last drier and oil change tested drier and PH tested oil tested ok	1212266
796	08/20/2026	1363199			1212266
796	08/14/2026	1361947		VEHICLE SAFETY INSPECTION Carried out safety inspection as per checklist	1212266
796	08/14/2026	1361947		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Tensioned wheel nuts with darnel to 650nm	1212266
796	08/14/2026	1361947		Assist with carrying out safety inspection as per checklist tensioned wheel nuts with Indika to 650nm and applied silicone to seal window	1212266
796	08/14/2026	1361947	SAUSAGE BLACK BOSTIK 24199		1212266
796	08/14/2026	1361977	Mechanic entered - Fluid Leaks Other Oil wet mark on hydroli	Washed engine bay & oil wetmark	1212266
796	08/14/2026	1361977		Assist wash	1212266
796	08/12/2026	1361163	Mechanic entered - Body Passenger Seat Torn O/S fold down se	Removed torn seat and ready to send for replacing C/O	1212266
796	08/12/2026	1361099	Mechanic entered - Body Other Rust under chassis	Shaved rust and painted over	1212266
796	08/12/2026	1361099	Mechanic entered - Body Other Rear door safety edges need ad	Shaved rust off and painted over	1212266
796	08/12/2026	1361162	Mechanic entered - Body Other N/S fold down seat plastic cov	Removed fold down seats with no plastic cover to be sent for replace C/O	1212266
796	08/12/2026	1361162	Mechanic entered - Body Other N/S fold down seat plastic cov		1212266
796	08/12/2026	1361163	Mechanic entered - Body Passenger Seat Torn O/S fold down se		1212266
796	08/12/2026	1361099	Consumables		1212266
796	08/12/2026	1361099	Consumables		1212266
796	08/11/2026	1360893	SWITCH BELL PUSH (340037)		1212266
796	08/11/2026	1360893	Mechanic entered - Elec and Light Other N/S/R stop bell not	Replaced button working fine	1212266
796	08/11/2026	1361000	Mechanic entered - Elec and Light Interior Lights Dash switc	checked bus and find the globe is gone.then pulled the dash apart and pulled old globe out and put new one and checked ok.Complete.	1212266
796	08/11/2026	1360893	Consumables		1212266
796	08/11/2026	1361000	Consumables		1212266
796	08/11/2026	1360800	Mechanic entered - Body Other AMF radio need securing	checked bus and find radio is secured but tp cover not sitting in properly then manage to put it and checked ok.Complete.	1212266
796	08/11/2026	1360900	BRUSH WHEELARCH LENGTH QTY 1		1212266
796	08/11/2026	1360900	BRUSH WHEELARCH LENGTH QTY 1		1212266
796	08/11/2026	1360872	Mechanic entered - Body Other Decals need replacing (priorit	Replaced decals	1212266
796	08/11/2026	1360872	DECAL EMERGENCY EXIT HAMMER		1212266
796	08/11/2026	1360872		Replaced decals	1212266
796	08/11/2026	1360900	WHEEL ARCH RUBBER 2.5M PER WHEEL P/M		1212266
796	08/11/2026	1360900	Mechanic entered - Body Other Front wheel arches need replac	Replaced wheel arch brushes and 1 wheel arch rubber	1212266
796	08/11/2026	1360939	DECAL MAX SAFE CARRY BLACK ON WHITE		1212266
796	08/11/2026	1360939	Mechanic entered - Body Other Safe carrying capacity needs r	Replaced	1212266
796	08/11/2026	1360946	Mechanic entered - Body Other O/S/R corner of seats worn	Replaced both corner seats	1212266
796	08/11/2026	1360946	URBAN TOP HAND RAIL 840 790MM LONG		1212266
796	08/11/2026	1360800	Consumables		1212266
796	08/11/2026	1360800	Consumables		1212266
796	08/11/2026	1360872	Consumables		1212266
796	08/11/2026	1360872	Consumables		1212266
796	08/11/2026	1360900	Consumables		1212266
796	08/11/2026	1360900	Consumables		1212266
796	08/11/2026	1360939	Consumables		1212266
796	08/11/2026	1360939	Consumables		1212266
796	08/11/2026	1360946	Consumables		1212266
796	08/11/2026	1360946	Consumables		1212266
796	08/07/2026	1359981		Assist with carrying out pre rsi check tensioned wheel nuts with Indika to 650nm & steam cleaned under chassis rims and engine bay	1212266
796	08/07/2026	1359981		PRE ANNUAL SAFETY INSPECTION CHECK Carried out pre rsi check & steamed cleaned under chassis rims engine bay	1212266
796	08/07/2026	1359981		CARRY OUT CCTV - B SERVICE AS PER CHECK LIST Tensioned wheel nuts with darnel	1212266
796	08/07/2026	1360215	Mechanic entered - Body Other Bus needs steam clean	Completed	1212266
796	08/07/2026	1360215	Consumables		1212266
796	08/07/2026	1360215	Consumables		1212266
796	08/07/2026	1360030	Mechanic entered - Air System Other Silencer missing in air	Replaced Silencer.	1212266
796	08/04/2026	1359208		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST carried out fire safety Inspection as per check list.Complete.	1212266
796	05/26/2026	1343411	Driver Tablet Entered -A/C Heating - Not Cooling	Run bus up to operating temperature found compressor not engauging traced back ti bad connector replaced connector tested heat and cool modes tested windscreen boost fan all tested ok	1212266
796	05/26/2026	1343410	Driver Tablet Entered -A/C Heating - Not Cooling	Run bus up to operating temperature found clutch not engauging traced back to bad connection replaced connector run up and tested heeat and cool modes tested windscreen boost fan all tested ok	1212266
796	05/26/2026	1342987	LIGHT LED STOP/TAIL RED 9 LED - 3 LED PARKER		1212266
796	05/26/2026	1342987		inspected bus and find LED lights work ok.Complete.	1212266
796	05/26/2026	1342987		Replaced LED light then tested. Completed	1212266
796	05/26/2026	1342987	Consumables		1212266

796	05/23/2026	1342928		VEHICLE SAFETY INSPECTION Completed		1212266
796	05/23/2026	1342928		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS With Abraham		1212266
796	05/23/2026	1342987	Mechanic entered - Elec and Light Exterior Lights N/S bottom	checked bus and find faulty LED light.tried changing it and no light in stock.C/O.		1212266
796	05/23/2026	1342936		CARRY OUT CCTV - A SERVICE AS PER CHECK LIST carried out CCTV A Service as per check list.Complete.		1212266
796	03/23/2026	1329361	LIGHT LED STOP/TAIL RED 9 LED - 3 LED PARKER			1211917
796	03/23/2026	1329361	Driver Tablet Entered -Elec and Light - Exterior Lights	removed and replaced n/s/r bottom brake light		1211917
796	03/23/2026	1329361	Consumables			1211917
796	03/23/2026	1329424		CARRY OUT FIRE EXTINGUISHER TEST & TAG checked fire extinguisher is up to date		1211917
796	02/27/2026	1323808	Mechanic entered - Elec and Light Flat Batteries	Replace two batteries and checked new ones are charing fine Complete.		1211413
796	02/27/2026	1323808	BATTERY EXSN94SCMF 1450AAC EMFN150L			1211413
796	02/27/2026	1323808		checked 2x batteries and checked ok.Complete.		1211413
796	02/27/2026	1323808		Helped replace both batteries. Completed.		1211413
796	02/27/2026	1323808	Consumables			1211413
796	02/26/2026	1323237		Assisted Satheesh with carrying out Vehicle Safety Inspection as per checklist. Tensioned all wheel nuts to 650nm with Satheesh		1211413
796	02/26/2026	1323237		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Re-tensioned wheel nuts with Antony.		1211413
796	02/26/2026	1323237		VEHICLE SAFETY INSPECTION completed as per the check list. Fixed the loosen bolts on Poles and seats.		1211413
796	12/04/2025	1307061		fixed fuel leak from hand pimer and fuel line steam clean after road test check leak all ok		1210508
796	12/03/2025	1307041		VEHICLE SAFETY INSPECTION completed as per check list.		1210508
796	12/03/2025	1307041		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS done with Nick.		1210508
796	12/03/2025	1307061	Mechanic entered - Engine Other fuel prime pump leaking.	ordered the parts .c/o		1210508
796	12/03/2025	1307061	Mechanic entered - Engine Other fuel prime pump leaking.			1210508
796	10/28/2025	1288493	WHEEL ARCH RUBBER 2.5M PER WHEEL P/M	STOCK BOOKING CORRECTION		1210508
796	10/28/2025	1288493	Consumables			1210508
796	09/16/2025	1288001	CARRYOUT ANNUAL INSPECTION	Creditor #:GB-ROA001 ROAD SAFETY INSPECTIONS P/O #:G394969 Receiving #:420636 Date :2025-09-30		1209932
796	09/10/2025	1288001	Service	VEHICLE SAFETY INSPECTION - Assisting		1209713
796	09/10/2025	1288001		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS - Assisting		1209713
796	09/10/2025	1288001		ANNUAL SAFETY INSPECTION SERIAL #RSI 072599 PASS 10/9/2025 WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25 - Assisting completed		1209713
796	09/10/2025	1289503	Mechanic entered - Elec and Light Interior Lights	Replaced N/S front park light to Led and checked new one is working fine Complete.		1209713
796	09/10/2025	1289503	LAMP LED FRONT PARK LIGHT WHITE			1209713
796	09/10/2025	1289503	Consumables			1209713
796	09/08/2025	1289032		Assisted Abraham.		1209713
796	09/08/2025	1289032	Mechanic entered - Wheels and Tyres Wheel Nut Retension Rete	Retensioned wheel nuts w/ Guri pos.5/6		1209713
796	09/08/2025	1289032	Consumables			1209713
796	09/08/2025	1289011	Carry out final inspection for RSI	carried out final spection for RSI		1209713
796	09/08/2025	1289011		completed final inspection		1209713
796	09/08/2025	1289011	Consumables			1209713
796	09/08/2025	1289011	Consumables			1209713
796	09/05/2025	1288400	Mechanic entered - Wipers and Washers Wipers Not_Clearing Sc	Replaced 2x wiper blades and adjuested.		1209713
796	09/05/2025	1288400	WIPER BLADE 32 INCH TX800			1209713
796	09/05/2025	1288493	Mechanic entered - Wheels and Tyres Worn Rear inner tyre wor	Replaced run out used 5m tyre for (pos 5) N/S/R/I. Tensioned wheel nuts with Justin 209727km		1209713
796	09/05/2025	1288493	BRUSH WHEELARCH LENGTH 75mm (2.5M PER WHEEL)			1209713
796	09/05/2025	1288493	WHEEL ARCH RUBBER 2.5M PER WHEEL P/M			1209713
796	09/05/2025	1288493	Consumables			1209713
796	09/05/2025	1288194		Removed and replaced new Alt belt and adjuested A/C belt.		1209713
796	09/05/2025	1288391	Mechanic entered - Elec and Light Other Gear selector D ba	removed repaired and reolaced blown out globes.		1209713
796	09/05/2025	1288391	BUSMINDER CABLE USB A TO C TYPE 5V3A			1209713
796	09/05/2025	1288391		Assist to Indika		1209713
796	09/05/2025	1288391	Consumables			1209713
796	09/05/2025	1288483	Mechanic entered - Elec and Light Other Dash switch backing	Replaced dash switch globes and secure switch.		1209713
796	09/05/2025	1288483	Consumables			1209713
796	09/05/2025	1288484	Mechanic entered - Body Other Secure electrical cable under	Secure electrical cable.		1209713
796	09/05/2025	1288485	Mechanic entered - Body Mirrors Exterior O/S mirror need to	Tightened mirror		1209713
796	09/05/2025	1288486	Mechanic entered - Body Other Grab handles need to be secure	Replaced 1x Grab handle		1209713
796	09/05/2025	1288486	HANDLE GRAB GREY STRAP BRV001			1209713
796	09/05/2025	1288491		removed and replaced front wheel arch rubber replaced wheel brush larch		1209713
796	09/05/2025	1288491	Mechanic entered - Body Other front wheel arch brush worn			1209713
796	09/05/2025	1288492	Mechanic entered - Body Front_Door Operation Faulty Front do	Adjuested.		1209713
796	09/05/2025	1288484	Consumables			1209713
796	09/05/2025	1288484	Consumables			1209713
796	09/05/2025	1288485	Consumables			1209713
796	09/05/2025	1288485	Consumables			1209713
796	09/05/2025	1288486	Consumables			1209713
796	09/05/2025	1288486	Consumables			1209713
796	09/05/2025	1288491	Consumables			1209713
796	09/05/2025	1288491	Consumables			1209713
796	09/05/2025	1288492	Consumables			1209713
796	09/05/2025	1288492	Consumables			1209713
796	09/04/2025	1288082		PRE ANNUAL SAFETY INSPECTION CHECK carried out PRRE annual safety inspection as per check list tensioned all wheel nuts with Zubz		1209713
796	09/04/2025	1288082		CARRY OUT CCTV - B SERVICE AS PER CHECK LIST		1209713
796	09/04/2025	1288194	Mechanic entered - Engine Belts_Loose Noisy Missing Drive be	No belt parts been order waiting for parts. C/O Replaced Alternator belt		1209713
796	09/04/2025	1288194	BELT MICRO V SERPENTINE BELT 8	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G394644 Receiving #:419056 Date :2025-09-04		1209713
796	09/04/2025	1288264	Mechanic entered - Fluid Leaks Rear of bus power steering oi	Repaired. and replaced 2x Clamps		1209713
796	09/04/2025	1288273	Mechanic entered - Elec and Light Interior Lights O/S row al	Changed two saloon light and it starts working Complete.		1209713
796	09/04/2025	1288192	SWITCH BELL PUSH YELLOW RED BUTTON HORIZ WIRED			1209713
796	09/04/2025	1288192	Mechanic entered - Elec and Light Other N/S disability stop	Replaced the disability stop button and checked new one is working fine Complete.		1209713
796	09/04/2025	1288271	Mechanic entered - Elec and Light Exterior Lights Rego plate	Changed number plate light and found it still not working looked for connection but fine found a broken wire crimmped it and found the light working fine Complete.		1209713
796	09/04/2025	1288192	Consumables			1209713
796	09/04/2025	1288271	Consumables			1209713
796	09/04/2025	1288273	Consumables			1209713
796	08/31/2025	1287004		FIRE EXTINGUISHER TEST & TAG - COMPLETED BY ATS FIRE		1209130
796	08/26/2025	1285459	Mechanic entered - Elec and Light Flat Batteries	jump started.		1209130
796	08/26/2025	1285459	Consumables			1209130
796	08/14/2025	1282764		VEHICLE SAFETY INSPECTION completed as per the check list.		1209344
796	08/14/2025	1282764		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Re-tensioned wheel nuts with satheesh.		1209344
796	08/14/2025	1282764		completed and Re-tensioned wheel nuts with Aaron. oil marks around the Bell Housing Steam cleaned and monitoring the route cause.		1209344
796	08/14/2025	1282785	Mechanic entered - Warning Lights Engine	Oil pressure sensor faulty Part Ordered Remove old faulty sensor and replace with new one		1209344
796	08/14/2025	1282785	SWITCH OIL PRESSURE SCANIA 188	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G393329 Receiving #:417523 Date :2025-08-14		1209344
796	08/14/2025	1282859	Mechanic entered - Engine Other Serpentine belt frayed	Ordered belt from Knox		1209344
796	08/14/2025	1282859		Remove frayed serpentine belt and replace with new one		1209344
796	08/14/2025	1282859	BELT MICRO V SERPENTINE BELT 8 RIB 2135mm LONG 1389048			1209344
796	08/14/2025	1282797	Mechanic entered - Body Other engine inspection cover latch	replaced rivets as it was missing one and the second one was loose		1209344
796	08/14/2025	1282797	Consumables			1209344
796	08/07/2025	1281247		CARRY OUT A/C - A SERVICE AS PER CHECK LIST Remove and replaced L/P switch service as per list		1209250

796	08/07/2025	1281247	SWITCH LOW PRESSURE A/C			1209250
796	08/01/2025	1279888		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST Multiple wire was resting on top of battery clamp secured then with rubber pipe. Battery wire under chassis near driver rear air-tank & front tyre secured with conduit. Carried out fire safety inspection as per checklist. Complete		1209170
796	06/27/2025	1269583		fitted back all the parts that removed to take off the breather. topped up all the levels. steram cleaned the engine bay done road test and checked after road test all ok now. done PTI as well.		1208910
796	06/24/2025	1269583		cleaned the breather ansd gaskit surface fitted new gaskit to the breather and installed back the breather .c/o		1208910
796	06/16/2025	1269583	GASKET INJ PUMP GEAR COVER L	Creditor #:GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G389041 Receiving #:412876 Date :2025-06-16		1208910
796	06/12/2025	1269583	HOSE ELBOW BREATHER CRANKCASE	Creditor #:GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G389041 Receiving #:412692 Date :2025-06-12 RCD 12/6/25		1208910
796	06/10/2025	1269583		Assisted.		1208910
796	06/10/2025	1269583	Mechanic entered - Fluid Leaks Rear of bus Front engine main	removed all the belts crank pullies check and found that oil leaking from crankcase ventilation cover gaskit. removed all the parts in front of cover and removed the cover . oreder the partsc/o		1208910
796	05/22/2025	1265692		VEHICLE SAFETY INSPECTION carried out safety inspection as per check list sisil carried over		1208910
796	05/22/2025	1265692		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1208910
796	05/22/2025	1265692		completed		1208910
796	05/22/2025	1265781	Mechanic entered - Elec and Light Interior Lights tube light	remove old invertor and replace with new one		1208910
796	05/22/2025	1265781	INVERTER 24V 15-36W (KIRG)			1208910
796	05/22/2025	1265781	Consumables			1208910
796	05/15/2025	1264627	PTI Tablet Entered -Elec and Light - Rear near side lower p	Refit wire checked ok		1208687
796	05/15/2025	1264628	PTI Tablet Entered -Elec and Light - headlights not working	replaced fuse		1208687
796	05/15/2025	1264627	Consumables			1208687
796	05/15/2025	1264628	Consumables			1208687
796	03/31/2025	1255814		CARRY OUT FIRE EXTINGUISHER TEST & TAG checked 2/25 next due 08/25.		1208369
796	03/04/2025	1250075		CARRY OUT CCTV - A SERVICE AS PER CHECK LIST Complete CCTV A Service as per check list.		1207701
796	02/26/2025	1248443		VEHICLE SAFETY INSPECTION Assisted Guri.		1207701
796	02/26/2025	1248443		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Tensioned wheel nuts w/ Guri.		1207701
796	02/26/2025	1248443		completed safety inspection and tensioned the wheel nuts with Abraham		1207701
796	02/18/2025	1246094	PERFORM CAMPAIGN 02/25 2025 PTV FARE DECAL REPLACEMENT	DECAL NOT REQUIRED ON THIS BUS		1207593
796	12/18/2024	1234328	Driver Tablet Entered -A/C Heating - Not Coolingpossible co	Bus did not show Tested found unit was down 2KG refrigerant traced back too gland discharge service valve tension and test ok run unit too 19C and heated too 26C tested ok		1207316
796	12/18/2024	1234328	AIR CON REFRIDGERANT			1207316
796	12/03/2024	1231157		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1206858
796	12/03/2024	1231157		VEHICLE SAFETY INSPECTION		1206858
796	12/03/2024	1231157		Carried out Safety inspection as per check list. Tension all wheel nuts with Lachlan Replaced 2x gas strut in Engine bay		1206858
796	12/03/2024	1231157				1206858
796	12/03/2024	1231157		Assisted Indika and Lachlan. Completed checklist as per work orders.		1206858
796	12/03/2024	1231157	STRUT GAS STAY 350Nm 565mm LONG			1206858
796	12/03/2024	1231157		Assisted Indika carry out safety inspection as per checklist and tnsioned all wheel nuts with Indika. replaced 2x gas struts for engine bay hatch		1206858
796	11/15/2024	1226407	Mounting Compressor Coachair	Creditor #:GB-COA001 COACHAIR PTY LTD P/O #:G375849 Receiving #:398610 Date :2024-11-18		1206281
796	11/13/2024	1227023	Driver Tablet Entered -Elec and Light - Exterior Lights left	checked the circuit change the globe and globe base		1206099
796	11/13/2024	1227023	Consumables			1206099
796	11/11/2024	1226407		Ac clutch was not engaging due to its wire rubbing to ac compressor. The wire was damaged soldered the wire & put heat shrink to secure it. Checked ac clutch still not engaging. Ac clutch wire was rubbing to conmpresoor soldered it and put heat shrink to secure it but still the clutch not engaging. Regas the system and a		1205849
796	11/11/2024	1226407	Workshop Tablet Entered -A/C Heating - Not Cooling	Coach Air notes Repaired Gas Leak Replaced 1evp fan motor Pressure test vaccume then recharge the system		1205849
796	11/11/2024	1226407	MOTOR A/C EVAPORATOR FAN	Creditor #:GB-DAN013 DANDENONG RADIATORS PTY LTD P/O #:G375837 Receiving #:398149 Date :2024-11-11		1205849
796	11/11/2024	1226407	Workshop Tablet Entered -A/C Heating - Not Cooling	As above		1205849
796	11/11/2024	1226407	Workshop Tablet Entered -A/C Heating - Not Cooling	low on gas due to leak fixed the leak ac clutch wire was damaged repaired the wire x1 fan motor replaced due to was not working regas the system now the entire ac system working again. Complete		1205849
796	11/11/2024	1226407	Driver Tablet Entered -A/C Heating - Not Cooling	As above		1205849
796	11/11/2024	1226407	Driver Tablet Entered -A/C Heating - Not Cooling	Asabove		1205849
796	10/14/2024	1220837	PERFORM CAMPAIGN 11/24 CHECK & ENSURE ALL BUS DRIVE AXLE WH	Complete campain 11/24.		1205171
796	09/25/2024	1216105		Remove and replaced discharge hose locate and repair electrical fault in excite circuit run up tested ok		1204971
796	09/25/2024	1216105	AIR CON REFRIDGERANT			1204971
796	09/24/2024	1216105	DASH 16 REFRIGERANT HOSE	Creditor #:GB-22C001 22 CELSIUS P/O #:G372961 Receiving #:395147 Date :2024-09-24		1204971
796	09/23/2024	1216105	Workshop Tablet Entered -A/C Heating - Not Cooling	Commission tested and pressure tested system found discharge hose has failed parts ordered not completed carry over		1204971
796	09/23/2024	1216105	NITROGEN DRY E SIZE			1204971
796	09/13/2024	1213920	RSI INSPECTION 2024	Creditor #:GB-ROA001 ROAD SAFETY INSPECTIONS P/O #:G372171 Receiving #:394808 Date :2024-09-19		1204708
796	09/11/2024	1213920		VEHICLE SAFETY INSPECTION		1204708
796	09/11/2024	1213920		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1204708
796	09/11/2024	1213920		ANNUAL SAFETY INSPECTION SERIAL #RSI 050052. PASS. 11/9/2024 WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25 carried out rsi		1204708
796	09/11/2024	1213920		Assisted.		1204708
796	09/06/2024	1212975	Consumables			1204297
796	09/06/2024	1212975		completed with zubair		1204297
796	09/06/2024	1212975	DECAL EMERGENCY EXIT ROCK BLACK/WHITE			1204297
796	09/06/2024	1212983	Mechanic entered - Body Other o/s/r wheel arch panel loose	removed and replaced latch		1204297
796	09/06/2024	1212983	STEEL CLAW CATCHES (SET UES2132)			1204297
796	09/06/2024	1212975	Carry out final inspection for RSI	carried out final inspection		1204297
796	08/29/2024	1210886		COMPLETED BY ATS 20/8/2024		1204136
796	08/20/2024	1208714	Mechanic entered - Engine Other oil leak under engine and on	Gave engine and gearbox very good steam clean with floor hatches off then took the bus for long road test checked on pit when returned and can see the bellhousing gasket is where oil is weeping after the 45min road test it is not dripping oil only sweating atm. Spoke to dulkeith bus will be monitored if the weep gets any		1203799
796	08/20/2024	1208534	Consumables			1204038
796	08/20/2024	1208719	Consumables			1203799
796	08/20/2024	1208534	Mechanic entered - Elec and Light Exterior Lights N/S/R/top	parts ordered.		1203799
796	08/20/2024	1208534		lights check light in question has intermittent fault. nil stock parts ordered.		1203799
796	08/20/2024	1208719	Mechanic entered - Elec and Light Interior Lights o/f saloon	checked all interior lights working ok.Complete		1203799
796	08/20/2024	1208534	RP10203 seat base	Creditor #:GB-RP RP AUTO UPHOLSTERY PTY LTD P/O #:G370766 Receiving #:392760 Date :2024-08-21		1204038
796	08/20/2024	1208534	Consumables			1203799
796	08/20/2024	1208534	Mechanic entered - Body Other Rear modersty panal mirror loo	tightened.		1203799
796	08/20/2024	1208534	DECAL PLEASE HOLD ON BLACK ON YELLOW			1203799
796	08/20/2024	1208534	Mechanic entered - Body Other Rear door emerjuncy sticker in	nil stock. parts form submitted.		1203799
796	08/20/2024	1208534	Mechanic entered - Body Other please hold on sticker rear mo			1203799
796	08/20/2024	1208534	Mechanic entered - Body Passenger Seat Torn	stock on hand are too wide to fit in track. seat back to go for repairs parts form submitted. seat back rest fitted and secured to be removed next school hols.		1203799
796	08/20/2024	1208534		seat back rest fitted back and secured. to be removed and sent for repairs next school hols.		1203799
796	08/19/2024	1208418		PRE ANNUAL SAFETY INSPECTION CHECK completed		1203799
796	08/19/2024	1208418		CARRY OUT CCTV - B SERVICE AS PER CHECK LIST		1203799
796	08/19/2024	1208277		CARRY OUT A/C - B SERVICE AS PER CHECK LIST Service as per list tested oil and drier both tested ok no oil or drier change due too not enough hours		1203799
796	08/19/2024	1208277		CARRY OUT A/C - A SERVICE AS PER CHECK LIST Service as per list		1203799
796	08/12/2024	1207013		Assisted Guri. Completed checklist as per work order		1203573
796	08/12/2024	1207013		VEHICLE SAFETY INSPECTION completed as per check list.		1203573
796	08/12/2024	1207013		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS done with ben		1203573
796	08/12/2024	1207031	Consumables			1203573
796	08/12/2024	1207031	Driver Tablet Entered -Body - Windows Frontstone chip nee	Checked & stick windsceen sticker.		1203573
796	08/06/2024	1205700	Consumables			1203573
796	08/06/2024	1205700	Mechanic entered - Body Other Front door top panel comes off	Secured panel.		1203573
796	07/31/2024	1204349	Workshop Tablet Entered -Body - Front_Door Operation Faulty	check front door and adjuested sensetiv edg secure cover doors ok.		1203399
796	07/25/2024	1203210	PERFORM CAMPAIGN 08/24 CHECK AND REPLACE WHERE REQUIRED ACCR	checked - o.k.		1203126
796	07/18/2024	1201769	Driver Tablet Entered -Elec and Light - Indicators Not Worki	Checked all indicators working completed		1202911
796	07/18/2024	1201769	Driver Tablet Entered -Elec and Light - Indicators Not Worki	Checked all indicators working completed		1202911
796	07/18/2024	1201769	Consumables			1202911
796	06/19/2024	1195391		TRANSMISSION CHECK AS PER CHECK LIST Completed		1202385
796	06/18/2024	1195025	Driver Tablet Entered -front door button not working	checking the system checked the relays fuses change the swich and working now		1202385

796	06/18/2024	1195025	Consumables			1202385
796	06/18/2024	1195085	Driver Tablet Entered -Body - Front_Door Operation Faulty	check and fixed front passanger door solonide value doors ok.		1202385
796	06/18/2024	1195085	Consumables			1202385
796	06/03/2024	1191869	Driver Tablet Entered -Engine - Warning Light Engine not sta	recieved part re-placed starter motor and checked ok.Complete.		1201820
796	06/03/2024	1191869	STARTER MOTOR SCANIA L94 0571420 IM038	transfer from Oakleigh - shonah		1201820
796	05/31/2024	1191869	Driver Tablet Entered -Engine - Warning Light Engine not sta	ordered part with Richel and she organized it and we gonna get the part from oakliegh.C/O.		1201820
796	05/20/2024	1189358		VEHICLE SAFETY INSPECTION completed as per check list.		1201579
796	05/20/2024	1189358		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS done with Ben		1201579
796	05/20/2024	1189459	Driver Tablet Entered -Suspension - Soft Front suspension b	check and could not found anything wrong with front suspension . done road test all ok.		1201579
796	05/20/2024	1189454	Mechanic entered - Elec and Light Exterior Lights o/s/f indi	check and found that indicator was not fitted properly removed the indicator got the water out and fitted back properly.		1201579
796	05/20/2024	1187449		check all the lights and it was all ok.		1201579
796	05/20/2024	1189457	Mechanic entered - Elec and Light Interior Lights o/s middle	replaced the saloon light.		1201579
796	05/20/2024	1187449	Consumables			1201579
796	05/20/2024	1189454	Consumables			1201579
796	05/20/2024	1189457	Consumables			1201579
796	05/20/2024	1189455	Mechanic entered - Body Other n/s/r safety yellow strip come	cleaned the surface and fitted back the strip .		1201579
796	05/20/2024	1189320		CARRY OUT CCTV - A SERVICE AS PER CHECK LIST complate CCTV A service as per checklist		1201579
796	05/20/2024	1189320		CARRY OUT CCTV - A SERVICE AS PER CHECK LIST		1201579
796	05/09/2024	1175106	BEARING BALL AIRCON			1200155
796	05/09/2024	1175106		Replaced compressor with second hand one change loom to suit compressor make up vac and charge with reclaimed refrigerant run up tested ok		1200155
796	05/09/2024	1187449	Workshop Tablet Entered -Elec and Light - Exterior LightsN/S			1200155
796	05/01/2024	1175106	A/C Heating Air Conditioning not working			1200155
796	05/01/2024	1175106		Removed nose cone remove face plate crank shaft was rusty back into compressor try too clean crank up with steel wool fit shaft seal reassemble pressure test seal still weeping chasing second O5G or price on TM55 upgrade job not completed carry over		1200155
796	04/29/2024	1185042	Mechanic entered - Elec and Light Flat Batteries	re-placed battery and the main positive terminal for battery broke.re-placed and checked ok.Complete.		1200155
796	04/29/2024	1185042	NUT BRASS BATTERY TERMINAL POSITIVE + MA14HDP			1200155
796	04/29/2024	1185042	BATTERY 1350CCA POS ON LHS EMFN150L			1200155
796	04/29/2024	1185042	Consumables			1200155
796	04/28/2024	1179248		completed b service as per check list with haysun and tensioned all wheel nuts with haysin		1200155
796	04/28/2024	1179248	Consumables			1200155
796	04/28/2024	1179248	Consumables			1200155
796	04/28/2024	1179248	Consumables			1200155
796	04/22/2024	1183850	Mechanic entered - Elec and Light Flat Batteries	jump started.		1200426
796	04/22/2024	1183850	Consumables			1200426
796	03/29/2024	1175106	05G-SS SHAFT SEAL CARRIER 05G	Creditor #:GB-22C001 22 CELSIUS P/O #:G360885 Receiving #:382739 Date :2024-03-31		1200155
796	03/28/2024	1179392	Mechanic entered - Body Other steam clean the bus	steam cleaned the bus		1200155
796	03/28/2024	1179248	OIL ENGINE MOBIL DELVAC MODERN 15W-40 MIN			1200155
796	03/28/2024	1179248	OIL ATF STEERING DEX-3 VALVOLINE			1200155
796	03/28/2024	1179248		completed as per check list and tensioned the wheel nuts with Jimmy		1200155
796	03/28/2024	1179248	O-RING LOWER SPINNER FILTER SCANIA L94 K124			1200155
796	03/28/2024	1179248	O-RING LARGE UPPER SPINNER FILTER SCANIA			1200155
796	03/28/2024	1179248	FILTER FUEL SCANIA VARIOUS MODELS			1200155
796	03/28/2024	1179248	FILTER ZF ECOMAT GEARBOX 4139-298-038 3098081			1200155
796	03/28/2024	1179248	FILTER OIL SCANIA VARIOUS MODELS			1200155
796	03/28/2024	1179248	OIL SAMPLE TEST KIT			1200155
796	03/28/2024	1179248	PAPER SPINNER FILTER OIL INSERT SCANIA VARIOUS MODELS			1200155
796	03/28/2024	1179248	Consumables			1200155
796	03/28/2024	1179248	Consumables			1200155
796	03/28/2024	1179248	Consumables			1200155
796	03/07/2024	1175106	A/C Heating Air Conditioning not cooling	Pressure tested unit and compressor found shaft seal weeping Parts ordered not completed carry over		1199444
796	02/29/2024	1173541	PERFORM CAMPAIGN 01/24 REMOVAL OF OLD NO SMOKING DECALS	completed		1199073
796	02/28/2024	1172934		COMPLETED BY ATS		1199073
796	02/26/2024	1172180		replaced park brake valve. tested all ok now.		1199073
796	02/26/2024	1172180	VALVE PARK BRAKE SCANIA SR3 4	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G360087 Receiving #:380333 Date :2024-02-26		1199073
796	02/24/2024	1172150		VEHICLE SAFETY INSPECTION Completed.		1199073
796	02/24/2024	1172150		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Done with Ben.		1199073
796	02/24/2024	1172180	Mechanic entered - Brakes Other Park brake valve leaking ne	Parts on order.		1199073
796	01/22/2024	1162507	DECAL YOU ARE TRAVELLING ON	Creditor #:GB-LAB010 LABEL CONCEPTS P/O #:G357386 Receiving #:377874 Date :2024-01-23		1198385
796	01/20/2024	1162507		sticker fitted. Complete.		1198385
796	01/09/2024	1162507	Body Reardecal Youare traveling on Bus796 missing	Parts Order 9/1/24		1198385
796	01/04/2024	1161293	PERFORM CAMPAIGN 10/23 POSITIONING OF 2024 PTV FARES	Rail Bus		1198385
796	12/15/2023	1158272	Consumables			1198285
796	12/15/2023	1158272	Driver Tablet Entered -Elec and Light - Horn not working	checked horn and working but contact for horn switch is not good re-paired it with solder and make bridge for contact to earth wire and checked it ok. Complete.		1198285
796	12/06/2023	1156481	Driver Tablet Entered -Wipers and Washers - Wipers Not_Clear	tested wipers cleaning properly		1197710
796	12/06/2023	1156480	Driver Tablet Entered -Air System - Air_Leak Rear	checked for leaks with kuma no leaks found		1197710
796	12/04/2023	1155382	DIRECT PURCHASE - BUS INSPECTI	Creditor #:GB-ROA001 ROAD SAFETY INSPECTIONS P/O #:G355443 Receiving #:374911 Date :2023-12-05		1197710
796	12/01/2023	1155382		VEHICLE SAFETY INSPECTION completed		1197710
796	12/01/2023	1155382		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1197710
796	12/01/2023	1155382		ANNUAL SAFETY INSPECTION SERIAL #RSI 058687 PASS 01/12/23 WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25		1197710
796	12/01/2023	1155382				1197710
796	11/29/2023	1155053		completed		1197710
796	11/29/2023	1155053	Carry out final inspection for RSI	completed		1197710
796	11/29/2023	1155053	Consumables			1197710
796	11/21/2023	1152793	Suspension Frontn sway bar bushe Worn	Rplaced		1196903
796	11/21/2023	1152793	Suspension Frontn sway bar bushe Worn	Rplaced		1196903
796	11/21/2023	1152793	Body Front and R/h rear mud flap broken	ReplacedN/S frontAssisted.		1196903
796	11/21/2023	1153392	Mechanic entered - Body Other Steam cleaning to be done.	completed.		1196903
796	11/21/2023	1152793	Consumables			1196903
796	11/21/2023	1153392	Consumables			1196903
796	11/20/2023	1152793	BodyR/H faldown seat gas stay worn	Replaced		1196903
796	11/20/2023	1152793	BodyFolding seat gas stays out	Replaced		1196903
796	11/20/2023	1152756				1196903
796	11/20/2023	1152793	Body steam clean angine and check for oil leak	Cleaned and checked ok		1196903
796	11/20/2023	1152793	STRUT GAS STAY LIFT UP SEAT			1196903
796	11/20/2023	1152756	Consumables			1196903
796	11/17/2023	1152793	Suspension Rear sway bar links ball joits rubbers cracks	Replace sway bar links		1196903
796	11/17/2023	1152793	Elec and Light F/ and rear door outher light cower coroded	cleaned and painted		1196903
796	11/17/2023	1152793	Elec and Light Dashlight globes out	Fixed		1196903
796	11/17/2023	1152793	Consumables			1196903
796	11/17/2023	1152756	BodyNeed road t4est for sppido aquracy and brake temperatur	Done		1196903
796	11/17/2023	1152756	BodyNeed road t4est for sppido aquracy and brake temperatur	Assisting		1196903
796	11/17/2023	1152793	Body Polish N/S panels	Polished		1196903
796	11/16/2023	1152346		Road tested Speedo and brake temperature done.		1196903
796	11/16/2023	1152793	LINK RR SWAY BAR D AXLE SCANIA	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G354468 Receiving #:373725 Date :2023-11-17		1196903

796	11/16/2023	1152793	BUSH FRONT SWAY BAR SCANIA K23	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G354468 Receiving #:373725 Date :2023-11-17		1196903
796	11/16/2023	1152793	MUDFLAP 605MM X 330MM	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G354468 Receiving #:373725 Date :2023-11-17		1196903
796	11/15/2023	1152346		.		1196903
796	11/15/2023	1152346		PRE ANNUAL SAFETY INSPECTION CHECK		1196903
796	11/15/2023	1152346		CARRY OUT CCTV - B SERVICE AS PER CHECK LIST		1196903
796	11/15/2023	1152357	Elec and Light L/H/F indicator light out	Replaced		1196903
796	11/15/2023	1152357	LAMP CLEAR FRT INDICATOR WRAP-AROUND			1196903
796	11/15/2023	1152372	Elec and Light Front and rear door outher lights U/S	assisting		1196903
796	11/15/2023	1152372	Elec and Light Front and rear door outher lights U/S	Repaire		1196903
796	11/15/2023	1152357	Consumables			1196903
796	11/15/2023	1152372	Consumables			1196903
796	11/02/2023	1150292		VEHICLE SAFETY INSPECTION Completed safety service. Also saloon cover re fitted		1196903
796	11/02/2023	1150292		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1196903
796	10/25/2023	1148641		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST assist Lochi to do fire safety Inspection as per check list. Complete.		1196903
796	10/25/2023	1148641		complete fire safety inspection as per check list		1196903
796	10/13/2023	1123774	DRIVE SOLID STATE 1TB (17128E-	Creditor #:GB-STR100 STREAMAX AUSTRALIA P/O #:G348903 Receiving #:371470 Date :2023-10-16		1196903
796	10/04/2023	1144078	Driver Tablet Entered -A/C Heating - Not Cooling	Locate and repair electrical fault in safety circuit		1196637
796	08/25/2023	1136180		drive tested the bus for Haysun		1195900
796	08/25/2023	1136180	Mechanic entered - Gearbox Driveline Other Differential pini	Job done by Haysun.		1195900
796	08/25/2023	1136180		put the bus on air and removed the tail shaft and r/r the diff seal and steam cleaned the bus		1195900
796	08/25/2023	1136192	Mechanic entered - Brakes Other Off side rear brake caliper	Accidentally enter wrong bus # supposed to be for Bus 631 job.		1195900
796	08/24/2023	1136180	NUT DIFF PINION SCANIA R660 40	Creditor #:GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G349517 Receiving #:367982 Date :2023-08-25		1195900
796	08/24/2023	1136180	SEAL DIFF PINION SCANIA R660 4	Creditor #:GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G349517 Receiving #:367982 Date :2023-08-25		1195900
796	08/23/2023	1123774		order new memory card for har hardrive re-placed and checked it recording ok and working fine. Complete.		1195900
796	08/22/2023	1135086	*** PHOTOS TAKEN BY GERALD *** - Accident #55211- REAR	Accident close 17/7/2023 through performance monitor		1195900
796	08/18/2023	1138633	Service	CARRY OUT FIRE EXTINGUISHER TEST & TAG Completed by ATS		1195900
796	08/18/2023	1138633		Assisting		1195900
796	08/17/2023	1134145	PERFORM CAMPAIGN 05/23 POSITIONING OF NO SMOKING NO VAPING	Done by Refuelers		1195900
796	08/14/2023	1123774		check cctv system found dvr showing correct date and time but operations cannot access footage suspected faulty harddrive found and repaired faulty cctv camera		1195900
796	08/14/2023	1123774		checked over DVR. Due to issues with viewing footage i have ordered a new HDD. Feda will be adjusting drivers and rear door camera.		1195900
796	08/14/2023	1123774		went t check the Hard drive at operation and still not connecting to Ceiba and showing different date. pascal ordered new hard drive unit and waiting for part.C/O.		1195900
796	08/11/2023	1132836		assisted		1195900
796	08/11/2023	1132836		completed wheel nut retension with abraham pos 2		1195900
796	08/10/2023	1132495		VEHICLE SAFETY INSPECTION Completed.		1195900
796	08/10/2023	1132495		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Done with Sujeong.		1195900
796	08/10/2023	1132513	Consumables			1195900
796	08/10/2023	1132513	Mechanic entered - Wheels and Tyres Worn Position 2 tyre wor	Removed front tyre position 2 fitted good run out tyre same thread. Tensoned wheel nuts with Sujeong.		1195900
796	08/10/2023	1132514	Consumables			1195900
796	08/10/2023	1132515	Consumables			1195900
796	08/10/2023	1132515	Mechanic entered - Elec and Light Other Dis able off side st	Removed and replace bell push for wheel chair passenger botton. Test ok.		1195900
796	08/10/2023	1132515	BELL PUSH FOR WHEEL CHAIR PASS			1195900
796	08/10/2023	1132514	Mechanic entered - Elec and Light Interior Lights Saloon lig	Removed and replace two saloon lights. test ok.		1195900
796	08/01/2023	1130317	PERFORM CAMPAIGN 02/23 POSITIONING OF 2023 PTV FARES	completed.		1195666
796	07/31/2023	1129960	Accident#54054-Offside-middle	Checked no damages detected.		1195666
796	07/27/2023	1129278	Consumables			1195135
796	07/27/2023	1129278	Elec and Light- FM Radio has fallen inside the dash when dri	Remove dash and retreive radio refit and secure and refit dash		1195135
796	07/21/2023	1128185		CARRY OUT CCTV - A SERVICE AS PER CHECK LIST complate CCTV A service as per checklist		1193940
796	07/20/2023	1127874		CARRY OUT A/C - A SERVICE AS PER CHECK LIST		1193633
796	07/20/2023	1127874		Assisting Carried out A service and repair by Cold drive.		1193633
796	07/20/2023	1127874	AIR CONDITIONING REPAIR	Creditor #:PT-COL004 COLD DRIVE PTY LTD P/O #:PE347402-1 Receiving #:365629 Date :2023-07-27 Carryout AC A service and repair		1195437
796	07/18/2023	1127129	PTI Tablet Entered -Elec and Light - Indicators Not Working	Replaced blown o/s/f indicator globe checked light now works		1192495
796	07/18/2023	1127129	Consumables			1192495
796	07/11/2023	1121836	REFLECTOR RED 94MM X 4MM NR84052BL			1191347
796	07/11/2023	1121836	DECAL PTV O - DRIVER REAR CORNER			1191347
796	07/11/2023	1121836	PTV SIDE LOGO			1191347
796	07/11/2023	1121836		fit up rest of bus cleaned and detailed fit lights adjusted engine hatch sensor patched front n/s decal and fit ptv side decal		1191347
796	07/11/2023	1121836		fit up rest of bus cleaned bus out detailed dash		1191347
796	07/11/2023	1121836	DECAL MAX SAFE CARRY WHITE LETTERING ON CLEAR			1191347
796	07/10/2023	1121836	LAMP LED NUMBER PLATE EXIT LIGHT(250120)(27771)			1191347
796	07/10/2023	1121836		fit up decal M and O fit rear bar cut + rewired and soldered rear lights		1191347
796	07/10/2023	1121836	DECAL PTV M - REAR ENGINE			1191347
796	07/10/2023	1121836		fitted back centre bumper cut out light fixtures o/s back bumper		1191347
796	07/10/2023	1121836	LAMP LED REVERSE RECTANGULAR			1191347
796	07/10/2023	1121836	LAMP LED REVERSE RECTANGULAR			1191347
796	07/10/2023	1121836	DECAL DO NOT OVERTAKE 100MM X 300MM			1191347
796	07/06/2023	1121836		prep and paint repairs prep and paint wheel white		1191347
796	07/06/2023	1121836	PAINT ENAMEL GLOSS WHITE 4LT			1191347
796	07/04/2023	1121836	SHEET ALUMIN 240cm X 120cm X 2.5mm			1191347
796	07/04/2023	1121836		sand and fibre glass o/s corner panel sand o\s rear fibreglass and repair o\s rear corner panel and bog and sand		1191347
796	07/03/2023	1123774	CCTV Timestamp Incorrect. Last date of recording is 6 Janu	checked hard drive unit and find out a camera not working and when checked with new camera find camera ok but when follow up the wire and then find some one plugged the camera plug into audio. plugged to camera plug and checked working ok. then checked for time stamp issue and find time stamp is working ok a		1191347
796	07/03/2023	1123774		inspect cctv system found camera 5 not working inspected wiring and found camera had been plugged into wrong connector inspect time stamp issue and found dvr showing correct dates and recording ok removed hard drive and had dvr checked but is showing incorrect on computer replaced time stamp button bus nee		1191347
796	06/30/2023	1121836		refit rear cross member and tighten all bolts and cut tubbing and sand and paint		1191347
796	06/29/2023	1121836		lining up back brace		1191347
796	06/29/2023	1121836		lining up back brace		1191347
796	06/27/2023	1121836	BUMPER REAR CENTRE VOLGREN FUTURE BUS			1191347
796	06/27/2023	1121836		fitted up back bumper drilled holes re tapped the holes removal of sticker cleaned by sanding crack at rear plate then welded		1191347
796	06/27/2023	1121836				1191347
796	06/27/2023	1121836		fitted up back bumper drilled holes re tapped the holes removal of sticker cleaned by sanding crack at rear plate then welded		1191347
796	06/23/2023	1121836	SAUSAGE WHITE SIKA			1191347
796	06/23/2023	1121836	SOUND INSULATION 2.4M X 1.3M X 28MM P/M			1191347
796	06/23/2023	1121836	PLASTIC EMERGENCY STEP			1191347
796	06/23/2023	1121836		the rear lid isolation drilled gas struts emergency step cut out from back hatch and glued hinge drill and nut hinge isulation on rear hatch sealed with tape pulled o/s rear pillar		1191347
796	06/23/2023	1121836		the rear lid isolation drilled gas struts emergency step cut out from back hatch and glued hinge drill and nut hinge isulation on rear hatch sealed with tape pulled o/s rear pillar		1191347
796	06/22/2023	1121836		removing back door hatch stripped and fitted locks from back hatchfitted hinge removed bck bracet tap new holes		1191347
796	06/22/2023	1121836		removing back door hatch stripped and fitted locks from back hatchfitted hinge removed bck bracet		1191347
796	05/18/2023	1115352		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1190703
796	05/18/2023	1115352	Service	VEHICLE SAFETY INSPECTION Complete		1190703
796	05/18/2023	1115352	Service	VEHICLE SAFETY INSPECTION Complete		1190703
796	03/29/2023	1106299	LAMP LED FRONT PARK LIGHT WHITE			1189533
796	03/29/2023	1106299	Mechanic entered - Elec and Light Exterior Lights O/S/F top	Removed and fitted new LED park light lamp.		1189533
796	03/27/2023	1099258	BELT MICRO V SERPENTINE BELT 8 RIB 2135mm LONG 1389048	BOOKED TWICE IN ERROR		1189533
796	03/27/2023	1105639	Mechanic entered - Elec and Light Other alternator belt broc	try to change the belt but need more time made the spaser into the alternator loks like good now fixed		1189533
796	03/27/2023	1105639	PULLEY IDLER (SMOOTH STL) SCAN	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G340123 Receiving #:357390 Date :2023-03-27		1189533

796	03/27/2023	1105639	BELT MICRO V SERPENTINE BELT 8	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G340123 Receiving #:357390 Date :2023-03-27		1189533
796	03/27/2023	1105639	PULLEY IDLER PLASTIC GROOVED S	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G340123 Receiving #:357390 Date :2023-03-27		1189533
796	03/27/2023	1105639	Consumables			1189533
796	03/17/2023	1102908		replaced tensioner rod and bushes for a/c belt. started bus and checked for movement tested ok		1189388
796	03/16/2023	1102908				1189388
796	03/16/2023	1103426		CARRY OUT FIRE EXTINGUISHER TEST & TAG Completed by ATS		1189388
796	03/15/2023	1102908	TENSIONER BELT SCANIA SR4 L94 K230 1859654 1503113			1189388
796	03/15/2023	1102908	CAP OIL FILLER SCANIA L94UAB 1	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G339417 Receiving #:356600 Date :2023-03-15		1189388
796	03/15/2023	1102908	BELT AIR CON	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G339417 Receiving #:356600 Date :2023-03-15		1189388
796	03/15/2023	1102908	BELT MICRO V SERPENTINE BELT 8	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G339417 Receiving #:356604 Date :2023-03-15		1189388
796	03/15/2023	1102908	DIPSTICK ENGINE OIL 753MM SCAN	Creditor #:GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G339427 Receiving #:356607 Date :2023-03-15		1189388
796	03/15/2023	1102908	Breakdown Overheating/Cooling System coolant leaking fan	replaced alternator belt aswell as a/c belts. replaced faulty alternator tensioner. found a/c pump mount to have a broken weld once started so removed a/c belts and tensioner to have mount re welded. refit belts and replaced oil fill cap and dipstick		1189388
796	03/08/2023	1101729	Consumables			1189388
796	03/08/2023	1101729		checked off side top parker and found globe holder to be faulty replaced and tested tested ok. checked near side top parker globe and found globe to be faulty. replaced and tested. tested ok		1189388
796	03/08/2023	1101729	LAMP REVERSE/CLEARANCE CLEAR			1189388
796	03/08/2023	1101729	Workshop Tablet Entered -Elec and Light - Exterior Lights of	checked light and find out the globe holder bracket was broken and re-placed with new one and checked it working ok. Complete. top park lights next to desto was faulty. Complete.		1189388
796	03/06/2023	1101138	Mechanic entered - Engine Will Not Start in Neutral diesel r	carried out cracking and bleeding fuel system to get bus started running well.		1188678
796	03/06/2023	1099258	BELT MICRO V SERPENTINE BELT 8 RIB 2135mm LONG 1389048			1188678
796	03/06/2023	1099258		replaced alternator belt.		1188678
796	03/06/2023	1099258		assist Lochi to re-place the belt. Complete.		1188678
796	02/27/2023	1099258	BELT MICRO V SERPENTINE BELT 8	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G338366 Receiving #:355420 Date :2023-02-27		1188678
796	02/24/2023	1099239		VEHICLE SAFETY INSPECTION Completed check list.		1188678
796	02/24/2023	1099239		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Done with Ben.		1188678
796	02/24/2023	1099258	Mechanic entered - Engine Other Alternator belt damaged need	Checked belts at stock room no availabe stock. Reported to Kuma parts need to order. Carry/over parts on order.		1188678
796	02/24/2023	1099255	Mechanic entered - Air System Air_Leak Front Air leaking fro	Rectify found out air line supply hose damaged rubbing on chassi. Cut removed and fitted new hose joint Test ok.		1188678
796	02/10/2023	1096079	CONNECTOR STRAIGHT BRASS 6MM			1188678
796	02/10/2023	1096079	Air System Air_Leak Front	Repair driver seat air leak.		1188678
796	02/10/2023	1096079	CONNECTOR STRAIGHT BRASS 8MM			1188678
796	02/03/2023	1094592	Drv entered - Engine Belts_Loose Noisy Missing	Already replaced the belts and reff : w/o1094079		1188678
796	02/01/2023	1094079	Breakdown Not Starting Alternator fan broken	carreied out went to break down and got bus back to workshop and carried out removing damaged belt and ordering parts.		1188678
796	02/01/2023	1094079	Breakdown Not Starting Alternator fan broken	Replaced belt		1188678
796	02/01/2023	1094079	BELT MICRO V SERPENTINE BELT 8	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G336676 Receiving #:353776 Date :2023-02-01		1188678
796	01/14/2023	1091102	Vandalism Vandalism/ Graffiti Interior	cleaned and painted over int graffiti		1187981
796	12/28/2022	1088264		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST carried out as per check list		1187981
796	12/22/2022	1087626	Consumables			1187981
796	12/22/2022	1087626	RE ATTACH O/S INTERIOR A/C DUCT	installed cover		1187981
796	12/21/2022	1087626	RE ATTACH O/S INTERIOR A/C DUCT	repaired air con pod		1187981
796	12/19/2022	1087070	Consumables			1187981
796	12/19/2022	1087070	Mechanic entered - Body Other a/c duct loose.	removed a/c ductcheck a/c duct all crack. email sent to bodyshop to book bus in for repair - LDM 20-12-22		1187981
796	12/19/2022	1087070	Mechanic entered - Body Other a/c duct loose.	replaced frayed alt belt.		1187981
796	12/19/2022	1087070	BELT MICRO V SERPENT 8 RIB 2135mm LNG(1389048)			1187981
796	12/17/2022	1086999	Consumables			1187981
796	12/17/2022	1086999	Mechanic entered - Elec and Light Exterior Lights o/s/f/t pa	remove drivers blindand lightfit globe and refit all.		1187981
796	12/16/2022	1086791	Mechanic entered - Elec and Light Indicators Not Working O/S	REMOVE DRIVERS BLINDCHANGE GLOBEREFIT BLIND.		1187981
796	12/16/2022	1086791	Consumables			1187981
796	12/15/2022	1086581	Mechanic entered - A/C Heating Other belt twisted.	untwist belt and adjust.		1187981
796	12/08/2022	1084411	ANNUAL SAFTEY INSPECTION	Creditor #:GB-ROA001 ROAD SAFETY INSPECTIONS P/O #:G333623 Receiving #:350995 Date :2022-12-09		1187865
796	12/02/2022	1084411		VEHICLE SAFETY INSPECTION		1187383
796	12/02/2022	1084411		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1187383
796	12/02/2022	1084411		ANNUAL SAFETY INSPECTION SERIAL #RSAI 050957. WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25		1187383
796	12/02/2022	1084411		Assisting		1187383
796	12/02/2022	1084435	Elec and Light Alternator belt broken	Replaced		1187383
796	12/02/2022	1084435	Elec and Light Alternator belt broken	Replaced		1187383
796	12/02/2022	1084435	Consumables			1188625
796	12/02/2022	1084435	BELT MICRO V SERPENTINE BELT 8	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G333643 Receiving #:351804 Date :2022-12-22		1188625
796	12/01/2022	1084223	Carry out final inspection for RSI	carried out final inspection for RSI		1187383
796	12/01/2022	1084223	Carry out final inspection for RSI	assisted with light and door check		1187383
796	11/26/2022	1083239	Drv entered - Wipers and Washers Wipers Not_Clearing Screen	fixed wiper washer and adjuested wiper blades bus ok.		1186607
796	11/26/2022	1083239	Drv entered - Body Windows Front	check wront window all ok secure lock bus ok.		1186607
796	11/21/2022	1080827	Mechanic entered - Fluid Leaks Rear of bus oil leak front ma	fitted pulley hub to crankshaft. re-assebled belts test drive checked all fluid levels. all ok		1186607
796	11/21/2022	1080823	Mechanic entered - Fluid Leaks Rear of bus trans input shaft	test drive checked all fluid levels and checked for leaks. all ok		1186607
796	11/18/2022	1080827	Mechanic entered - Fluid Leaks Rear of bus oil leak front ma	installed new front seal. waiting for new front hub for replacement.		1186607
796	11/18/2022	1080827	HUB CRANKSHAFT DC901 SCANIA L9	Creditor #:GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G332774 Receiving #:349606 Date :2022-11-21		1186607
796	11/17/2022	1080827	Mechanic entered - Fluid Leaks Rear of bus oil leak front ma	reoved pulleys and front main seal for replacement. cleaned and prepared area for new seal install.		1186607
796	11/17/2022	1080822	Mechanic entered - Fluid Leaks Rear of bus hydraulic res lea	tightened line connection at top of hydraulic res		1186607
796	11/17/2022	1080827	Mechanic entered - Fluid Leaks Rear of bus oil leak front ma	Assisted Stuart. removed front main seal and cleaned down all surfaces and parts.		1186607
796	11/17/2022	1080823	Mechanic entered - Fluid Leaks Rear of bus trans input shaft	as above		1186607
796	11/17/2022	1080827	SEAL FRT CRANK DC903 B01 SCANI	Creditor #:GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G332669 Receiving #:349512 Date :2022-11-18		1186607
796	11/16/2022	1080823	Mechanic entered - Fluid Leaks Rear of bus trans input shaft	replaced inputshaft seal fitted trans to bus. filled coolant and trans fluid (re-used fluid from gearbox.)		1186607
796	11/16/2022	1080823	Mechanic entered - Fluid Leaks Rear of bus trans input shaft	Assisted Stuart. manauvered transmission back into position and fitted transmission to vehicle after refilling trans fluid from from draining. refitted all electrical fittings and mountings etc. lowered vehicle and refilled coolant ran vehicle to run fluid through and retopped coolant.		1186607
796	11/16/2022	1080826	Mechanic entered - Body Other N/S panel behind rear Pax door	Went to remove bolts remaining in thread could not vicegrip or hit too turn as had seized in thread. drilled through bolts in order to loosen. removed bolts and retapped thread. replaced with new bolts.		1186607
796	11/16/2022	1080826	PLASTIC WASHER			1186607
796	11/15/2022	1080823	SEAL FRT COVER ZF GEARBOX ECOMAT 2 49D8504			1186607
796	11/15/2022	1080823	Mechanic entered - Fluid Leaks Rear of bus trans input shaft	prepared and removed gearbox and torque converter for trans inputshaft seal replacment.		1186607
796	11/15/2022	1080823	Mechanic entered - Fluid Leaks Rear of bus trans input shaft	Assisted to clean the Gear box.		1186607
796	11/14/2022	1080703		PRE ANNUAL SAFETY INSPECTION CHECK service completed as per work order		1186607
796	11/14/2022	1080703		CARRY OUT CCTV - B SERVICE AS PER CHECK LIST carried out service as per work order		1186607
796	11/14/2022	1080703		Assisted Stuart. Completed checklist and service items as needed per work order. torqued wheels to spec. washed down engine bay from on top and underneath.		1186607
796	11/14/2022	1080800	Mechanic entered - Wheels and Tyres Other front wheel arch b	replaced damaged wheel arch brushes		1186607
796	11/14/2022	1080800	WHEEL ARCH BRUSH 12065			1186607
796	11/14/2022	1080800	Consumables			1186607
796	11/14/2022	1080822	Mechanic entered - Fluid Leaks Rear of bus hydraulic res lea	cleaned around resoviour to identify source of leak		1186607
796	11/14/2022	1080823	Mechanic entered - Fluid Leaks Rear of bus trans input shaft			1186607
796	11/14/2022	1080827	Mechanic entered - Fluid Leaks Rear of bus oil leak front ma	C/O		1186607
796	11/14/2022	1080823	Mechanic entered - Fluid Leaks Rear of bus trans input shaft			1186607
796	11/14/2022	1080824	Mechanic entered - Elec and Light Interior Lights x2 Saloon	replaced 2x salloon fluro lights. repaired 1 x salloon light mounting		1186607
796	11/14/2022	1080824	Mechanic entered - Elec and Light Interior Lights x2 Saloon	Assisted Stuart. removed and replaced fluro lights. repaired one light mounting.		1186607
796	11/14/2022	1080802	Mechanic entered - Elec and Light Exterior Lights front N/S	remove indicator assembly and replace with new . Checked all working. Stuart double checked all work done.		1186607
796	11/14/2022	1080802	LAMP CLEAR FRT INDICATOR WRAP-AROUND			1186607
796	11/14/2022	1080821	Mechanic entered - Dash Switches Not Working reverse button			1186607
796	11/14/2022	1080821	Mechanic entered - Dash Switches Not Working reverse button	Got new button face/tile and replaced ensured functional.		1186607
796	11/14/2022	1080825	Mechanic entered - Elec and Light Horn horn not working	reconnected wiring terminals to horn under bus		1186607
796	11/14/2022	1080825	Mechanic entered - Elec and Light Horn horn not working	Assisted Stuart. cleaned terminals under bus while testing and reconnected.		1186607

796	11/14/2022	1080802	Consumables			1186607
796	11/14/2022	1080821	Consumables			1186607
796	11/14/2022	1080824	Consumables			1186607
796	11/14/2022	1080825	Consumables			1186607
796	11/14/2022	1080820	PAD BRAKE PEDAL MERCEDES 0405 VOLVO			1186607
796	11/14/2022	1080826	Mechanic entered - Body Other N/S panel behind rear Pax door	C/O		1186607
796	11/14/2022	1080820	Mechanic entered - Body Other accelerator pedal pad missing	replaced missing accelerator pedle pad		1186607
796	11/14/2022	1080826	Mechanic entered - Body Other N/S panel behind rear Pax door	C/O		1186607
796	10/27/2022	1059279	TPAF- R/2022/53839/MR - O/S/R CORNER BUMPER DAMAGE	stripped down rear took rear engine hatch off. replaced hinge rubber in o/s rear panel. cut straightened and rewelded rear bar mounting bracket		1186137
796	10/27/2022	1059279	TPAF- R/2022/53839/MR - O/S/R CORNER BUMPER DAMAGE	modified rear fiberglass bar cut exhaust hole repaired rear o/s pillar. repaired rear header and engine hatch saftey sensor bracket		1186137
796	10/21/2022	1076794		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST complated fire safety inspection		1186137
796	10/15/2022	1075545		VEHICLE SAFETY INSPECTION		1185513
796	10/15/2022	1075545		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1185513
796	10/15/2022	1075545		Asssisted.		1185513
796	10/12/2022	1074916	Body replace front panal lock.	fitted new freebie penal lock		1185380
796	10/07/2022	1073818		SERVICE MOISTURE EJECTOR Assisted Matt in removing Tappet covers and turning the flywheel to check/adjust valve clearance refitted valve covers		1185112
796	10/07/2022	1073818		CARRY OUT TUNE-UP SERVICE AS PER CHECK LIST		1185112
796	10/07/2022	1073818		Carried out Tune up service as per scania L94 specs did each cylinder one by one. Moisture ejector not replaced due to parts fitted to bus being fairly clean.		1185112
796	10/07/2022	1073902	PERFORM CAMPAIGN 10/22 WEAR A FACE MASK WHILE TRAVELLING D	completed.		1185112
796	10/06/2022	1073818	GASKET ROCKER CVR DC903 B01 SC	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G330236 Receiving #:347073 Date :2022-10-11		1185380
796	10/03/2022	1059279	21788 - F/GLASS ENGINE DOOR	Creditor #:EA-VOL001 VOLGREN AUSTRALIA PTY LTD P/O #:EA325683 Receiving #:346743 Date :2022-10-05		1185112
796	09/01/2022	1067151	Completed by ATS	CARRY OUT FIRE EXTINGUISHER TEST & TAG		1184294
796	08/30/2022	1059087	Accident#53839-offside rear	Repair completed by east coast		1184294
796	08/29/2022	1066549		Tensioned all rear wheel nuts w/ Kuma.		1184294
796	08/29/2022	1066133	Mechanic entered - Fluid Leaks Rear of bus Power steering ho	Fit the new power steering line from tank secured line topped up oil and bleed through power steering washed engine bay and took bus for road test checked on return no oil leaks.		1184294
796	08/26/2022	1062964	suspension replace both o/s rear shock absorbers.	Job fixed 22/8/2022		1184294
796	08/26/2022	1065161	Drv entered - Steering Pulling			1184294
796	08/26/2022	1065161	Drv entered - Steering Pulling	Test drove bus as part of other work no steering pulling found driving fine.		1184294
796	08/26/2022	1066133	Mechanic entered - Fluid Leaks Rear of bus Power steering ho			1184294
796	08/26/2022	1066133	Mechanic entered - Fluid Leaks Rear of bus Power steering ho	removed power steering hose cut top of hose to make it flush with the hydraulic resiovor and steam cleaned		1184294
796	08/26/2022	1066133	MAKE NEW HOSE FROM SAMPLE FOR	Creditor #:GB-ENZ001 ENZED DANDENONG P/O #:G327886 Receiving #:344260 Date :2022-08-26		1184294
796	08/26/2022	1062966	Brakes replace o/s rear break booster.			1184294
796	08/26/2022	1062966	Brakes replace o/s rear break booster.	Finished off with Brake test and road test all passed no air leaks found.		1184294
796	08/25/2022	1062965	Brakes replace n/s front break booster diaphragm.	fitted New Brake booster With new fitting O/F. Did nt removed the any wheel		1184294
796	08/25/2022	1062965	Brakes replace n/s front break booster diaphragm.	Assisted.		1184294
796	08/25/2022	1059279	BUMPER CORNER REAR O/S	Creditor #:EA-VOL001 VOLGREN AUSTRALIA PTY LTD P/O #:EA325683 Receiving #:344215 Date :2022-08-26		1184294
796	08/25/2022	1059087	Accident#53839-offside rear	As bove		1184294
796	08/24/2022	1062965	Part - 326976 T-Union	Creditor #:GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:G327612 Receiving #:344141 Date :2022-08-25		1184294
796	08/23/2022	1065161	Drv entered - Steering Pulling			1184294
796	08/23/2022	1062965	BRAKE CHAMBER 24 SCANIA L94 F	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G327460 Receiving #:343892 Date :2022-08-23		1184294
796	08/22/2022	1062964	suspension replace both o/s rear shock absorbers.	Inspected rear shock absorbers found N/S/R/F to be in more leaky than O/S/R/F replaced both the N/S/R/F and O/S/R/R shockers with Tayla.		1184294
796	08/22/2022	1062964	suspension replace both o/s rear shock absorbers.	removed and fitted new shockers		1184294
796	08/22/2022	1062965	Brakes replace n/s front break booster diaphragm.	Replaced N/S front booster no more leaks on that side found front O/S is leaking put parts order in.		1184294
796	08/22/2022	1062966	Brakes replace o/s rear break booster.	Removed wheels and carried out removal of boosters. Swapped fittings and fitted new boosters. Booster bolts tension to 180mn		1184294
796	08/22/2022	1062966	Brakes replace o/s rear break booster.	Lifted up the rear of the bus and removed the rear wheels wound off the rear brakes and removed both boosters fit over air fittings to new boosters and fit back to bus tensioned holding nuts to 180nm fit the rear wheels back and tensioned all wheel nuts withTayla. Still need to perform brake test once other brake jobs ar		1184294
796	08/22/2022	1059087	BUZZER REVERSING 24V 102DB(NR72602)			1184294
796	08/22/2022	1059087	LAMP LED REVERSE RECTANGULAR			1184294
796	08/22/2022	1059087	LAMP RED/AMBER MARKER	fitted right hand side indicatorreverse and brake lights and changed reverse buzzer and fitted new side marker lights and run wiring for left hand side reverse light and fitted new light and checked all of them working ok. Complete.		1184294
796	08/17/2022	1061360	BODYSHOP - replace o/s/r access panel rubber hinge	fit driver rear stickerreflectors 2 red2 amberdo not overtake sticker		1184294
796	08/17/2022	1061360	DECAL PTV G			1184294
796	08/17/2022	1061360	'GIVE WAY' DECAL 240MM X 225MM			1184294
796	08/17/2022	1061360	DECAL DO NOT OVERTAKE 100MM X 300MM			1184294
796	08/16/2022	1061360	BODYSHOP - replace o/s/r access panel rubber hinge	cut onld hinges of old panels prepped hinges. bodyfilled and finefilled rear center bar		1184294
796	08/16/2022	1059279	PANEL SPLASH SHIELD			1184294
796	08/16/2022	1059279	TPAF- R/2022/53839/MR - O/S/R CORNER BUMPER DAMAGE	fit back rear bumper rear sticker		1184294
796	08/13/2022	1062964	SHOCK ABSORBER REAR SCANIA L94	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G326961 Receiving #:343344 Date :2022-08-15		1184294
796	08/13/2022	1062965	BRAKE CHAMBER 24 SCANIA L94 F	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G326961 Receiving #:343344 Date :2022-08-15		1184294
796	08/12/2022	1062809	Steering replace powe steering reservoir.(accident)	Topped up with fresh oils both power steering and hydrualic fan bleed power steering system till no noise. Moved bus over to wash bay and cleaned the engine bay free of oil cleaned up mess left over at eastcoast. Checked for leaks no more leaking		1184294
796	08/12/2022	1062965	Brakes replace n/s front break booster diaphragm.			1184294
796	08/12/2022	1062966	Brakes replace o/s rear break booster.			1184294
796	08/12/2022	1062966	BRAKE CHAMBER RR 24/30 16MM SCANIA K310UB 2147775			1184294
796	08/11/2022	1062809	Steering replace powe steering reservoir.(accident)	Assisted		1184294
796	08/11/2022	1062809	Steering replace powe steering reservoir.(accident)	Drained both fan oil and power steering oil removed broken power steering tank and repaired the oil lines replaced oil fan lines tried to top up oil but working outside it was raining sideway.		1184294
796	08/10/2022	1059279	TPAF- R/2022/53839/MR - O/S/R CORNER BUMPER DAMAGE	prep and paint repairs paint wheels white		1184294
796	08/09/2022	1059279	TPAF- R/2022/53839/MR - O/S/R CORNER BUMPER DAMAGE	prep for paint work		1184294
796	08/09/2022	1059279	TPAF- R/2022/53839/MR - O/S/R CORNER BUMPER DAMAGE	removed sticker removed rear bar for paintshop rewired reverse siren		1184294
796	08/08/2022	1061360	BODYSHOP - replace o/s/r access panel rubber hinge	fabricated o/s/r panel		1184294
796	08/08/2022	1061360	ERAZER WHEEL VINYL ZAPPER			1184294
796	08/08/2022	1059279	TPAF- R/2022/53839/MR - O/S/R CORNER BUMPER DAMAGE			1184294
796	08/08/2022	1059279	PAINT SPRAY CAN MATT BACK 400G			1184294
796	08/06/2022	1059279	0492632 - HOSE	Creditor #:EA-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:EA325714 Receiving #:342923 Date :2022-08-08		1184294
796	08/06/2022	1059279	2961600 - OIL TANK CAN USE 29	Creditor #:EA-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:EA325714 Receiving #:342923 Date :2022-08-08		1184294
796	08/06/2022	1059279	0484041 - HOSE	Creditor #:EA-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:EA325714 Receiving #:342923 Date :2022-08-08		1184294
796	08/06/2022	1059279	0484040 - HOSE	Creditor #:EA-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:EA325714 Receiving #:342923 Date :2022-08-08		1184294
796	08/05/2022	1061360	BODYSHOP - replace o/s/r access panel rubber hinge	manufatcured new top hinge for o/s rear panel fit new rubbers fit up panels		1184294
796	08/05/2022	1061360	C2 UPPER WHEEL ARCH HINGE 2MT			1184294
796	08/05/2022	1061360	HINGE RUBBER FOR COBALT 2			1184294
796	08/05/2022	1059279	F/GLASS REAR BUMPER	Creditor #:EA-VOL001 VOLGREN AUSTRALIA PTY LTD P/O #:EA326440 Receiving #:342748 Date :2022-08-05		1184294
796	08/05/2022	1059279	PANEL BUMPER REAR CENTRE VOLGREN CR228			1184294
796	08/05/2022	1059279	TPAF- R/2022/53839/MR - O/S/R CORNER BUMPER DAMAGE	modified and fit up rear bar manufactured rear bar bracket fit up engine hatch door started fab on gas struct mounts		1184294
796	08/04/2022	1059279	TPAF- R/2022/53839/MR - O/S/R CORNER BUMPER DAMAGE	repaired engine hatch painted inner side fit fireproofing repaired and welded engine hatch sensor bracket trial fit rear bar		1184294
796	08/03/2022	1059279	TPAF- R/2022/53839/MR - O/S/R CORNER BUMPER DAMAGE	removed decal g and k repaired waist rail primed all repairs fit emergency step in engine bay hatch		1184294
796	08/03/2022	1059279	ERAZER WHEEL VINYL ZAPPER			1184294
796	08/03/2022	1059279	PLASTIC EMERGENCY STEP			1184294
796	08/02/2022	1059279	TPAF- R/2022/53839/MR - O/S/R CORNER BUMPER DAMAGE	repaired o/s rear header ready for paint removed sticker		1184294
796	08/01/2022	1059279	Decal K	Creditor #:EA-LAB010 LABEL CONCEPTS P/O #:EA325682 Receiving #:342704 Date :2022-08-04		1184294
796	07/26/2022	1059279	REAR BUMPER CENTRE	Creditor #:EA-VOL001 VOLGREN AUSTRALIA PTY LTD P/O #:EA325683 Receiving #:342085 Date :2022-07-28		1184294
796	07/26/2022	1059279	11631 - REVERSING BEEPER	Creditor #:EA-VOL001 VOLGREN AUSTRALIA PTY LTD P/O #:EA325683 Receiving #:342085 Date :2022-07-28		1184294
796	07/26/2022	1059279	DEADNER SOUND SHEET(Mtrs)	Creditor #:EA-VOL001 VOLGREN AUSTRALIA PTY LTD P/O #:EA325683 Receiving #:342085 Date :2022-07-28		1184294
796	07/26/2022	1059279	11744 - Gas Stay	Creditor #:EA-VOL001 VOLGREN AUSTRALIA PTY LTD P/O #:EA325683 Receiving #:342085 Date :2022-07-28		1184294
796	07/26/2022	1059279	16634 - engine hatch switch	Creditor #:EA-VOL001 VOLGREN AUSTRALIA PTY LTD P/O #:EA325683 Receiving #:342085 Date :2022-07-28		1184294
796	07/25/2022	1059087	Accident#53839-offside rear	Bus at east coast and repairing		1184294

796	07/23/2022	1058912		VEHICLE SAFETY INSPECTION don.		1184294
796	07/23/2022	1058912		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1184294
796	07/19/2022	1057952		CARRY OUT A/C - B SERVICE AS PER CHECK LIST		1184294
796	07/19/2022	1057952	FILTER DRYER 5/8 3K171124 A/C			1184294
796	07/19/2022	1057952	OIL COMPRESSOR AIR CONDITIONING			1184294
796	07/19/2022	1057952	RELAY 5 PIN CHANGE-OVER C/W DIODE			1184294
796	07/19/2022	1057952		CARRY OUT A/C - A SERVICE AS PER CHECK LIST Started service job not completed carryover		1184294
796	06/08/2022	1049250		Rewire top off compressor and test		1183211
796	06/08/2022	1050680	Ops Entered - Fault - Body Drivers Seat Belt - BUCKEL BROKEN	removed and replaced new seat belt buckle		1183211
796	06/08/2022	1050680	BUCKLE S/SAFE STEM 340422 340287			1183211
796	06/08/2022	1050680	Consumables			1183211
796	05/31/2022	1049250	AIR CON REFRIDGERANT			1182635
796	05/31/2022	1049250		Tested found wiring over compressor has gone brittle temp repair as bus was due to go out will need bus back to replace loom above compressor top up refrigerant		1182635
796	05/31/2022	1049372		CARRY OUT CCTV - A SERVICE AS PER CHECK LIST Carried out A Service on CCTV.		1182635
796	05/27/2022	1048761	Drv entered - A/C Heating Demister Not Heating	Checked - driver and saloon 24C abmbient 11C. Bus has no demister. No fault found. A/C was turned off. Notified OPS to share info for drivers that A/C must be on all the time.		1182367
796	05/27/2022	1048761	Drv entered - A/C Heating Not Cooling	Multi entered		1182367
796	05/27/2022	1048761	Drv entered - A/C Heating Not Heating	Multi entered		1182367
796	05/19/2022	1047118	Ops Entered - Fault - - interia light change lights in the	replaced light tube in bus		1181378
796	05/19/2022	1047118	Consumables			1181378
796	05/19/2022	1047118	Consumables			1181378
796	05/11/2022	1045507	Consumables			1180736
796	05/11/2022	1045507	Consumables			1180736
796	05/11/2022	1045507	Body Water Leaks Roof DISABLE SECTION O/S DRIVER HAS PH	resealed roof and side windows		1180736
796	05/06/2022	1044700	Consumables			1180031
796	05/06/2022	1044700	Consumables			1180031
796	05/06/2022	1044700	Mechanic entered - Wheels and Tyres Wheel Nut Retension p 3+	RETENSION 3+4		1180031
796	05/06/2022	1044700	Mechanic entered - Wheels and Tyres Wheel Nut Retension p 3+	RETENSION 3+4		1180031
796	05/06/2022	1043825	Ops Entered - Fault - A/C Heating Warning Light On - INTEE	Controller supplied and replaced by Dave (ColdDrive).		1180031
796	05/06/2022	1042051	Replace A/C controller check	Creditor #:CT-COL004 COLD DRIVE PTY LTD P/O #:CT320232 Receiving #:336921 Date :2022-05-11		1180736
796	05/05/2022	1043825	Consumables			1180208
796	05/05/2022	1043825	Consumables			1180208
796	05/05/2022	1043825	Drv entered - Elec and Light Interior Lights	Replaced stalk		1180031
796	05/05/2022	1044280	PERFORM CAMPAIGN 03/22 QR CODE & SELECTED COVID19 DECAL REM	removed		1180031
796	05/05/2022	1044280	Consumables			1180736
796	05/05/2022	1044280	Consumables			1180736
796	05/05/2022	1044280	Consumables			1180736
796	05/05/2022	1044280	Consumables			1180736
796	05/05/2022	1044280	Consumables			1180736
796	05/05/2022	1044280	Consumables			1180736
796	05/05/2022	1044280	OIL SAMPLE KIT AMPOL			1180031
796	05/05/2022	1044280	FILTER FUEL SCANIA L94 1372444			1180031
796	05/05/2022	1044280	FILTER OIL SCANIA K93 L94 1117285 2059778			1180031
796	05/05/2022	1044280	O-RING LARGE SPINNER FILTER SCANIA L94 & K230			1180031
796	05/05/2022	1044280		CARRY OUT B SERVICE AS PER CHECK LIST carried out B service as per checklist ordered new indicator stalk tightened loose tyre valve (P4)		1180031
796	05/05/2022	1044280		Assisting completed B service		1180031
796	05/05/2022	1044280	O-RING SPINNER FILTER SCANIA L94			1180031
796	05/05/2022	1044280	PAPER SPINNER FILTER OIL INSERT SCANIA L94			1180031
796	05/05/2022	1044280	FILTER ZF ECOMAT GEARBOX(4139-298-038)(1193281)			1180031
796	05/05/2022	1044280	SWITCH INDICATOR STALK SCANIA	Creditor #:CT-MUL001 MULTISPARES LTD P/O #:CT320902 Receiving #:336931 Date :2022-05-11		1180736
796	05/03/2022	1043189	Mechanic entered - Engine Other replace alt and water pump b	replaced main belt\ water pump/ alternator belt		1179852
796	05/03/2022	1043825	Drv entered - Elec and Light Interior Lights	high beams would not stay on found faulty high beam relay and ordered new part installed new relay and it didn't fix problem ordered new indicator stalk		1179852
796	05/03/2022	1043825	RELAY	Creditor #:CT-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:CT320726 Receiving #:336544 Date :2022-05-05		1180208
796	05/03/2022	1043825	CONSUMABLE DELIVERY CHARGE	Creditor #:CT-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:CT320726 Receiving #:336544 Date :2022-05-05		1180208
796	05/03/2022	1043856	Consumables			1179852
796	05/03/2022	1043856	Consumables			1179852
796	05/03/2022	1043856	Mechanic entered - Body Other front bumber minor scratches	repaired front bumper and touch up		1179852
796	05/02/2022	1043189	BELT MICRO V SERPENT 8 RIB 213	Creditor #:CT-MUL001 MULTISPARES LTD P/O #:CT320576 Receiving #:336250 Date :2022-05-02		1179675
796	05/01/2022	1042051	Drv entered - A/C Heating Warning Light On	Multi entered ref WO#1043825.		1179675
796	05/01/2022	1042051	Ops Entered - Fault - A/C Heating Not Cooling - Route: KWR	Multi entered ref WO#1043825.		1179675
796	04/29/2022	1043145		VEHICLE SAFETY INSPECTION		1179496
796	04/29/2022	1043145		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1179496
796	04/29/2022	1043189	Mechanic entered - Engine Other replace alt and water pump b	orderd belt		1179496
796	04/21/2022	1041496	WIPER BLADE ASSY 1000mm N102(TRP1000)			1178922
796	04/21/2022	1041496	Drv entered - Wipers and Washers Wipers Not_Clearing Screen	booked parts and replaced windscreen wipers		1178922
796	04/21/2022	1041496	Ops Entered - Fault - Wipers and Washers Wipers Not_Clearing	booked parts and replaced windscreen wipers		1178922
796	04/21/2022	1041496	Ops Entered - Fault - Body Water Leaks Roof - Route: KWR -	checked for signs of leaking no signs of leaking found		1178922
796	04/21/2022	1041496	Consumables			1178922
796	03/17/2022	1035592	Vandalism - Film Replacement	Done by GlassProtech - Shonah		1175645
796	03/17/2022	1035592	Vandalism - Film Replacement	Assisting		1175645
796	03/17/2022	1035633	Ops Entered - Fault - A/C Heating Not Cooling - Route: -	Tested - on setting 19C pick up point has 19C saloon blowing 17C ambient temp 27C. No fault found.		1175645
796	03/17/2022	1035635	Drv entered - Elec and Light Horn WHEN TURNING CORNERS HOR	Turning steering wheel several times end to end - no fault found. Horn working good.		1175645
796	03/17/2022	1035635	Consumables			1175645
796	03/16/2022	1035592	REPAIR VANDALISED WINDOWS	Creditor #:CT-GLA010 GLASSPROTECH MELBOURNE P/O #:CT315972B Receiving #:333472 Date :2022-03-18		1175818
796	03/01/2022	1032546	Ops Entered - Fault - A/C Heating Not Cooling - Route: KWR	Checked A/C and found working normally. Output temp 18 degrees. No fault found.		1173869
796	02/16/2022	1029160	Consumables			1172475
796	02/16/2022	1029160	Consumables			1172475
796	02/16/2022	1029160	Mechanic entered - Body Other front panel open	removed and repaired front panel lock		1172475
796	02/15/2022	1028993	Mechanic entered - Wheels and Tyres Wheel Nut Retension spee	retension wheels 3+4+5+6		1172475
796	02/15/2022	1028993	Mechanic entered - Wheels and Tyres Wheel Nut Retension spee	retension wheels 3+4+5+6		1172475
796	02/15/2022	1028993	Consumables			1172475
796	02/14/2022	1028678		TRANSMISSION CHECK AS PER CHECK LIST completed check		1172401
796	02/14/2022	1028678		Assisting Assisted withTransmission check and Safety Inspection.		1172401
796	02/14/2022	1028678		VEHICLE SAFETY INSPECTION completed VSI		1172401
796	02/14/2022	1028678		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS completed retension		1172401
796	02/14/2022	1028763	Consumables			1172401
796	02/14/2022	1028763	Mechanic entered - Wheels and Tyres Worn pos 3 and 4 worn	assisted dave with pos 3 and 4 tyre replacement		1172401
796	02/14/2022	1028763	TYRE 295/80R22.5 RECAP			1172401
796	02/14/2022	1028763	Mechanic entered - Wheels and Tyres Worn pos 3 and 4 worn	Replaced tyres on Pos 3 & 4.		1172401
796	02/14/2022	1028750	Mechanic entered - Brakes Other replaced rear brake pads	replaced O/S rear brake pads		1172401
796	02/14/2022	1028750	BRAKE PAD SET SCANIA MERC BENZ 0500LE			1172401
796	02/14/2022	1028750	SENSOR WEAR KIT BLOCK TYPE-AXLE SET SCANIA(1794440)			1172401
796	02/14/2022	1028750	Mechanic entered - Brakes Other replaced rear brake pads	Replaced brake pads and wear sensors on L/H/RR.		1172401
796	02/07/2022	1027185		CARRY OUT FIRE EXTINGUISHER TEST & TAG		1172229

796	02/07/2022	1027185		Done by ATS Purchase Order CT315000 on 2nd Feb 2022		1172229
796	02/02/2022	1023760	Please check and repair door b	Creditor #:CT-CAR008 CARDINIA P/O #:CT314574 Receiving #:330737 Date :2022-02-04		1172026
796	02/02/2022	1023760	Consumables			1172026
796	01/21/2022	1023760	Elec and Light Warning Light On Dash	repaired by Cardinia Auto Elec		1171278
796	01/21/2022	1023760	Consumables			1172026
796	01/21/2022	1023760	Brakes Park_Brake Not Releasing when you stop the brakes	Checked that the RPD was working. It was. Cleaned and parked up bus.		1171278
796	01/20/2022	1023760	Elec and Light Warning Light On Dash	Couldn't find any fault light on the dash. It could have been related to the RPD and brakes.		1171278
796	01/20/2022	1023760	Brakes Park_Brake Not Releasing when you stop the brakes	Checked for brake releasing. The only problem I could find was the RPD not working correctly. It stopped working completely. I performed all the basic checks but it didn't fix the problem. We ended up getting Graeme to diagnose the problem and repair it.		1171278
796	01/20/2022	1023759	PERFORM CAMPAIGN 20/20 PRE SUMMER PREVENTATIVE MAINTENANCE C	Campaign complete.		1171278
796	01/12/2022	1022344	REMOVE OLD 2020 DECAL AND FIT NEW 2022 DECAL POSITION AS ST	completed campaign		1169851
796	01/11/2022	1022002	Drv entered - A/C Heating Not Cooling	ran aircon for 15 minutes recorded 31 degree at the start 15 minutes later vents read 17.9 degrees		1169544
796	12/30/2021	1020327	Engine Noisy or Rattling accel pedal	lubricated pedal pivot		1168141
796	12/24/2021	1019694	Mechanic entered - Elec and Light Exterior Lights Front L/H	removed and replaced new globe		1167799
796	12/24/2021	1019694	Consumables			1167799
796	12/15/2021	1018119	Booked for Smart Track to be removed at 730am	Done by Amtex.		1167080
796	12/15/2021	1018119	Consumables			1167080
796	12/15/2021	1018140	Body - inside panel need secure.	removed and repaire broken interior panel		1167080
796	12/15/2021	1018140	Consumables			1167080
796	12/15/2021	1018140	Consumables			1167080
796	12/11/2021	1017191	Mechanic entered - A/C Heating Belt Loose or_Missing	Fitted new belts.		1166331
796	12/10/2021	1017191	Mechanic entered - A/C Heating Belt Loose or_Missing	Ordered belts		1166331
796	12/10/2021	1017191	Mechanic entered - A/C Heating Belt Loose or_Missing	Assisting removed broken a\c belt [waiting on new belt]		1166331
796	12/10/2021	1017191	BELT V-BELT HI-POWER 17x239	Creditor #:CT-MUL001 MULTISPARES LTD P/O #:CT312608 Receiving #:327861 Date :2021-12-13		1166567
796	12/10/2021	1013830	SOLENOID VALVE 3/2 1/4 N/C 24V DOOR RAM			1166331
796	12/10/2021	1013830	Consumables			1166331
796	12/10/2021	1013830	Consumables			1166331
796	12/09/2021	1015051	CARRY OUT YEARLY INSPECTION	Creditor #:CT-ROA001 ROAD SAFETY INSPECTIONS P/O #:CT311927 Receiving #:327866 Date :2021-12-13		1166567
796	12/08/2021	1016793	No 889 desto in this bus	Uploaded desto file		1166184
796	12/08/2021	1016793	Consumables			1166184
796	12/06/2021	1016228	Drv entered - Elec and Light Horn	found fault in wiring below steering wheel repaired wire horn is working now		1165897
796	12/06/2021	1016228	Consumables			1165897
796	12/03/2021	1015760	Drv entered - Elec and Light Indicators Not Working	spaced mounting work well		1165770
796	12/03/2021	1015762	Indicator arm not holding	spaced mounting work well		1165770
796	12/03/2021	1015760	Consumables			1165770
796	12/03/2021	1015762	Consumables			1165770
796	12/01/2021	1015051		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1165200
796	12/01/2021	1015051		VEHICLE SAFETY INSPECTION		1165200
796	12/01/2021	1015051		Assisting		1165200
796	12/01/2021	1015051		ANNUAL SAFETY INSPECTION SERIAL # RSI 042589_____ WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25		1165200
796	11/30/2021	1014890		fitted new part to door and is working normal		1165200
796	11/30/2021	1014890	Consumables			1165200
796	11/26/2021	1013816	Drv entered - Elec and Light Indicators Not Working	Replaced indicator stork.		1165000
796	11/26/2021	1013699	Drv entered - Elec and Light AM-FM Radio	Replaced AM/FM radio.		1165000
796	11/26/2021	1013699	Consumables			1165000
796	11/26/2021	1013816	Consumables			1165000
796	11/26/2021	1013830	SOLENOID VALVE 3/2 1/4 N/C 24V DOOR RAM			1165000
796	11/26/2021	1013830	Drv entered - Body Front_Door Operation Faulty can not shut	wrong part delivered waiting on parts		1165000
796	11/26/2021	1013830	Drv entered - Body Front_Door Operation Faulty can not shu	Twice entered.		1165000
796	11/26/2021	1014200	Mechanic entered - Body Other Passenger bell stuck on.	Cleaned pax button's contacts.		1165000
796	11/26/2021	1013830	VALVE SOLENOID VALVE	Creditor #:CT-SMC001 SMC CORPORATION (AUSTRALIA) PTY LTD P/O #:CT311720 Receiving #:327031 Date :2021-12-01		1165494
796	11/26/2021	1013830	Consumables			1165494
796	11/26/2021	1014200	Consumables			1165000
796	11/25/2021	1013816	Drv entered - Elec and Light Indicators Not Working	Indicator stork U/S. Keeps canceling. Need to order a new stork.		1164723
796	11/25/2021	1013819	Elec and Light Exterior Lights R/H side clearance light out.	Repaired the wiring on the clearance light.		1164723
796	11/25/2021	1013823	Drv entered - Elec and Light AM-FM Radio	Radio on order - fer WO#1013699.		1164723
796	11/25/2021	1013699	RADIO 12/24V 3' LCD MULTIMEDIA	Creditor #:CT-MUL001 MULTISPARES LTD P/O #:CT311574 Receiving #:326646 Date :2021-11-25		1165000
796	11/25/2021	1013816	SWITCH INDICATOR SCANIA L94 14	Creditor #:CT-MUL001 MULTISPARES LTD P/O #:CT311574 Receiving #:326649 Date :2021-11-25		1165000
796	11/25/2021	1013819	Consumables			1164723
796	11/25/2021	1013823	Consumables			1164723
796	11/25/2021	1013798	no driver saftey screen fitted	Screen no provided to this model.		1164723
796	11/25/2021	1013805	Can not close the door from the outside of the bus	Multi entered - parts on order ref WO#1013655		1164723
796	11/25/2021	1013805	Drv entered - Body Front_Door Operation Faulty	Multi entered - parts on order ref WO#1013655		1164723
796	11/25/2021	1013830	Drv entered - Body Front_Door Operation Faulty can not shu	Ordered solenoid		1164723
796	11/25/2021	1013798	Consumables			1164723
796	11/25/2021	1013805	Consumables			1164723
796	11/24/2021	1013699	Drv entered - Elec and Light AM-FM Radio	Checked and there seems to be power to the head unit. My need to order a new head unit.		1164723
796	11/24/2021	1013655	Random check and chassis wash.	Random check complete.		1164723
796	11/24/2021	1013655	Random check and chassis wash.	completed chassis wash and random check		1164723
796	11/24/2021	1013655	Consumables			1164723
796	11/17/2021	1012167	the desto dose not have 888 or 889 in itbus is not in th	Uploaded desto files.		1163697
796	11/17/2021	1012167	Consumables			1163697
796	11/15/2021	1011629	the horn keeps going off by itself somtime stays on for 1	removed steering wheel check carbon brush cover horn spring loaded if seized and clean stator r/r busted fuse and tested ok now		1163436
796	11/15/2021	1011629	Consumables			1163436
796	11/11/2021	1010185	Mechanic entered - Suspension Other frt l/h air bag leaking	Replaced air bag		1162790
796	11/11/2021	1009632	STEERING WHEEL SCANIA 1545452	Creditor #:CT-MUL001 MULTISPARES LTD P/O #:CT310305RET Receiving #:325704 Date :2021-11-11		1162973
796	11/11/2021	1010822	Mechanic entered - Fluid Leaks Other hyd fan oil resevior p	REMOVED FITTING FITTED NEW COPPER WASHER TESTED OK NOW		1162790
796	11/11/2021	1009633	Mechanic entered - Elec and Light Other r/h high beam corrod	R/R R/H HIGH BEAM LAMP AND ADJUST LENS		1162790
796	11/11/2021	1009633	HEAD LAMP INSERT HELLA 90MM L/FLOOR 0500 (9314365038525)			1162790
796	11/11/2021	1009633	Consumables			1162790
796	11/10/2021	1010185	AIRBAG FRT 14MM SCANIA K230U	Creditor #:CT-MUL001 MULTISPARES LTD P/O #:CT310443 Receiving #:325705 Date :2021-11-11		1162973
796	11/09/2021	1010101	Mechanic entered - Wheels and Tyres Wheel Nut Retension roto	retension wheel nuts		1162642
796	11/09/2021	1010101	Mechanic entered - Wheels and Tyres Wheel Nut Retension roto	Retensioned both front wheel nuts. (Odometer 162785kms).		1162642
796	11/09/2021	1010101	Consumables			1162642
796	11/09/2021	1009632	WHEEL STEERING WHEEL NEW SCANI	Creditor #:CT-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:CT310439 Receiving #:325606 Date :2021-11-10		1162790
796	11/09/2021	1006775	CLEANER GRAFFITI REMOVER AMERASE PER LITRE			1162642
796	11/09/2021	1006775	Accident 52704 - NEAR SIDE REAR	replaced new rebranding decal		1162642
796	11/09/2021	1006775	LATCH DOOR COOLANT HATCH 1/4 TURN			1162642
796	11/09/2021	1006775	LAMP RED/AMBER MARKER			1162642
796	11/09/2021	1006775	AMBER REFLECTOR			1162642
796	11/08/2021	1009607	PAINT LACQUER SPRAY HIGH GLOSS WHITE 400G			1162642
796	11/08/2021	1009607	Mechanic entered - Wheels and Tyres Other both frt wheel rim	painted rims 1+2 with white paint		1162642
796	11/08/2021	1009607	Consumables			1162642
796	11/08/2021	1009598	Mechanic entered - Engine Other alternator belt split	Replaced belt		1162785

796	11/08/2021	1009602	Mechanic entered - Body Other both side rear engine 4x gas s	Replaced gas struts.		1162642
796	11/08/2021	1009602	Consumables			1162790
796	11/08/2021	1009601	WEAR SENSOR KIT BLOCK TYPE-AXLE SET SCANIA(1794440)			1162642
796	11/08/2021	1009601	BRAKE PAD SET SCANIA MERC BENZ 0500LE			1162642
796	11/08/2021	1009601	Mechanic entered - Brakes Other both side frt rotors in min	Assisted Roberto with rotor replacement		1162642
796	11/08/2021	1009601	Mechanic entered - Brakes Other both side frt rotors in min	r/r rotors and brake pads		1162642
796	11/05/2021	1009536				1162328
796	11/05/2021	1009536		CARRY OUT CCTV - B SERVICE AS PER CHECK LIST check cctv operation all good		1162328
796	11/05/2021	1009632	Mechanic entered - Steering Other steering wheel cover to mu	rEPLACED STEERING WHEEL.		1162328
796	11/05/2021	1009632	STEERING WHEEL SCANIA 1545452	Creditor #:CT-MUL001 MULTISPARES LTD P/O #:CT310305 Receiving #:325603 Date :2021-11-10		1162790
796	11/05/2021	1009598	Mechanic entered - Engine Other alternator belt split	Ordered belt		1162328
796	11/05/2021	1009598	8pk2135tm BELT MICRO V SERPENT	Creditor #:CT-MUL001 MULTISPARES LTD P/O #:CT310285 Receiving #:325263 Date :2021-11-05 796		1162562
796	11/05/2021	1009596	Mechanic entered - Elec and Light Other indicator stalk l/h	r/r indicator stalk and tested o.k now		1162328
796	11/05/2021	1009596	40v4703	Creditor #:CT-MUL001 MULTISPARES LTD P/O #:CT310285 Receiving #:325262 Date :2021-11-05 796		1162562
796	11/05/2021	1009596	Consumables			1162562
796	11/05/2021	1009602	Mechanic entered - Body Other both side rear engine 4x gas s	Ordered gas struts		1162328
796	11/05/2021	1009602	strut 350nm x 425mm	Creditor #:CT-UNI001 UNIVERSAL ENGINEERS SUPPLIES P/O #:CT310295 Receiving #:325609 Date :2021-11-10		1162790
796	11/05/2021	1009601	Mechanic entered - Brakes Other both side frt rotors in min	Ordered rotors		1162328
796	11/05/2021	1009602	BRAKE DISC FRT SCANIA K230UB F	Creditor #:CT-MUL001 MULTISPARES LTD P/O #:CT310289 Receiving #:325258 Date :2021-11-05		1162562
796	11/05/2021	1009585		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST Done by Graham (CardiniaAuto).		1162328
796	11/05/2021	1009585	Annual fire safety inspection	Creditor #:CT-CAR008 CARDINIA P/O #:CT310299 Receiving #:325486 Date :2021-11-09		1162785
796	10/27/2021	1006775	Supply D11 PTV decal.	Creditor #:CT-TRA005 TRANSCAL P/O #:CT309704 Receiving #:325266 Date :2021-11-05		1162562
796	10/26/2021	1007543	Mechanic entered - Wheels and Tyres Wheel Nut Retension p 1	Retensioned position 1 and 2. (Odometer 161359kms).		1161329
796	10/26/2021	1007543	Mechanic entered - Wheels and Tyres Wheel Nut Retension p 1	retension 1;2		1161329
796	10/26/2021	1007543	Consumables			1161329
796	10/26/2021	1006775	Accident 52704 - NEAR SIDE REAR	repaired rear bumper \ repaired corner [needs rebrand decal]		1161329
796	10/25/2021	1006907	WEAR SENSOR KIT BLOCK TYPE-AXLE SET SCANIA(1794440)			1161329
796	10/25/2021	1006775	Accident 52704 - NEAR SIDE REAR	repaired fibra glass \ mounted rear bumper		1161329
796	10/22/2021	1006896	Mechanic entered - Elec and Light Interior Lights Fluro ligh	replaced fluro socket		1161329
796	10/22/2021	1006896	FLURO TUBE HOLDERS			1161329
796	10/22/2021	1006896	Consumables			1161329
796	10/21/2021	1006861		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS completed retension		1161329
796	10/21/2021	1006861		VEHICLE SAFETY INSPECTION completed VSI		1161329
796	10/21/2021	1006861		assisted rodney with safety inspection and wheel nut retension changed the fuel filter oil filter and spinner filter while assisting with B service		1161329
796	10/21/2021	1006896	Mechanic entered - Elec and Light Interior Lights Fluro ligh	orderd part		1161329
796	10/21/2021	1006907	Mechanic entered - Brakes Other front brake pads low	replaced front brake pads and wires		1161329
796	10/21/2021	1006907	BRAKE PAD SET SCANIA MERC BENZ 0500LE			1161329
796	10/21/2021	1006775	Accident 52704 - NEAR SIDE REAR	replaced rear bumper line up engine hatch [needs fibra glass job]		1161329
796	10/21/2021	1006861	FILTER FUEL FILTER SCANIA SR4 (1372444)			1161329
796	10/21/2021	1006861	FILTER OIL SCANIA S4 & K			1161329
796	10/21/2021	1006861		CARRY OUT B SERVICE AS PER CHECK LIST Carried out B and Transmission Service.		1161329
796	10/21/2021	1006861	PAPER SPINNER FILTER OIL INSERT SCANIA L94			1161329
796	10/21/2021	1006861	FILTER ZF ECOMAT GEARBOX 4139-298-038 1193281			1161329
796	10/21/2021	1006861	O-RING SPINNER FILTER SCANIA ->| ENG#6203049 40A7701			1161329
796	10/21/2021	1006861	O-RING LARGE SPINNER FILTER SCANIA 40A7703			1161329
796	10/21/2021	1006861	OIL SAMPLE KIT AMPOL			1161329
796	10/21/2021	1006861	Consumables			1161329
796	10/21/2021	1006861	Consumables			1161329
796	10/12/2021	1003285	Mechanic entered - Engine Other Oil Leaks - Front crank seal	found rear of sump slightly wet tightend sump bolts and found fan oil dripping at reseroir tightend hose clamps test drove could not see leaks		1159982
796	10/12/2021	1003285	Mechanic entered - Engine Other Oil Leaks - Front crank seal	Assisted Rod with tightening sump bolts and engine clean		1159982
796	10/11/2021	1003984	Elec and Light Two Way Radio2-Way needs to be changed	changed 2 WAY RADIO		1159982
796	10/11/2021	1003984	Consumables			1160197
796	10/08/2021	1003984	Please reprogeham for 796 Pake	Creditor #:CT-CSE001 CSE CROSSCOM PTY LTD P/O #:CT308480 Receiving #:323599 Date :2021-10-13		1160197
796	10/06/2021	1003285	Mechanic entered - Engine Other Oil Leaks - Front crank seal	found enging and trans very dirty with oil removed engine and trans hatch and steam cleaned engine and trans top and bottom completed short test drive and could not find leak posibly needs to be checked after next run and monitored		1159464
796	10/06/2021	1003984	Elec and Light Two Way Radio2-Way needs to be changed	swaped out 2 way radio from 785 and placed radio on supervisors desk to be reprogramed		1159464
796	09/03/2021	996983	PERFORM CAMPAIGN 17/21 QR CODE DECAL FITMENT TO ALL BUSES	complete		1155369
796	08/20/2021	993601		CARRY OUT FIRE EXTINGUISHER TEST & TAG		1153571
796	08/20/2021	993601		complete		1153571
796	08/18/2021	992768		VEHICLE SAFETY INSPECTION Carried out Safety inspection		1153011
796	08/18/2021	992768		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1153011
796	08/18/2021	992854	Mechanic entered - Wheels and Tyres Worn N/S/R Inner and out	Replaced worn tyres with 2x Runout tyres		1153011
796	08/18/2021	993005	Mechanic entered - Wheels and Tyres Wheel Nut Retension N/S/	Completed retension		1153011
796	08/18/2021	992854	Consumables			1153011
796	08/18/2021	993005	Consumables			1153011
796	08/18/2021	992855	Mechanic entered - Suspension Other Front Sway Bar 'D' Bushe	Replaced worn 'D' Rubbers with new items from stock.		1153011
796	08/18/2021	992855	BUSH FRT SWAY BAR SCANIA K230UB 0469081 1919010 40MM			1153011
796	08/18/2021	992766	Mechanic entered - Engine Other dipstick tube loose.	secure dipstick tube.		1153011
796	08/18/2021	992855	Mechanic entered - Elec and Light Exterior Lights N/S/F Step	removed step light cover and replaced blown fluro checked for operation all ok		1153011
796	08/18/2021	992855	Mechanic entered - Elec and Light Interior Lights 1X Saloon	removed cover replaced blown fluro checked for operation all ok		1153011
796	08/18/2021	992855	Mechanic entered - Dash Dash_Lights Not Working 1x Dash Ligh	removed cluster and replaced blown dash globe checked for operation and re assembled.		1153011
796	08/18/2021	992855	Consumables			1153011
796	08/18/2021	992855	Mechanic entered - Body Front_Door Operation Faulty Front Do	bottom Plug Under sensitive edge rubber not in place resecured plug with sealant allowed sufficient time to dry before testing when tested worked fine added new rivets to top panel to resecure.		1153011
796	08/18/2021	992855	Mechanic entered - Body Other O/S/F Wheel Arch Brush Not sec	re secured wheel arch brush rubber to body		1153011
796	08/18/2021	992855	Mechanic entered - Body Other 1X N/S/R Seat base bracket to	removed seat base cushion gained access to broken bracket grinded base for proper earth welded bead along bracket to resecure checked for play all ok allowed weld to cool before re assembling		1153011
796	08/18/2021	992855	Consumables			1153011
796	07/26/2021	987906	CCTV CCTV not recording cannot download.	double entry		1151464
796	07/26/2021	987906	CCTV CCTV not recording cannot read on computer in ops -	checked CCTV recording ok. no video losses. there maybe a technical issue with ops computer.		1151464
796	07/17/2021	986246	Mechanic entered - Elec and Light Exterior Lights n/s headli	fit globe.		1150762
796	07/17/2021	986246	Consumables			1150762
796	07/15/2021	985922	Mechanic entered - Engine Other Dip stick tube comes off	Fit hose clamp and cable ties		1150424
796	07/15/2021	985853	Accident # 52291 - o/s drivers mirror smashed - no other da	replaced smashed o.s drivers mirror and adjusted . all okay		1150424
796	07/15/2021	985853	MIRROR R/H 380mm SHORT (UES1411D)			1150424
796	07/14/2021	985589		CARRY OUT A/C - A SERVICE AS PER CHECK LIST - O302815 carried out by cold drive jimmy		1150424
796	07/14/2021	985589	AIR CONDITIONING REPAIR	Creditor #:VB-COL004 COLD DRIVE PTY LTD P/O #:O302815 Receiving #:317571 Date :2021-07-23 carry out 12 month a/c service as required		1151290
796	06/03/2021	976425	NR94432 12 Volt LED Reverse L	Creditor #:VB-ASHDOW ASHDOWN INGRAM P/O #:O300099 Receiving #:314374 Date :2021-06-08 Bus 796		1146265
796	06/03/2021	976425	Consumables			1146265
796	05/28/2021	977046		CARRY OUT CCTV - A SERVICE AS PER CHECK LIST carried out as per check list		1144965
796	05/26/2021	976604	Mechanic entered - Wheels and Tyres Wheel Nut Retension nee	carried out retorque as required		1144965
796	05/26/2021	976604	Consumables			1144965
796	05/26/2021	976425	SENSOR WEAR SENSOR KIT BLOCK TYPE-AXLE SET SCANIA 1794440			1144965
796	05/25/2021	976265		VEHICLE SAFETY INSPECTION done.		1144965
796	05/25/2021	976265		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1144965

796	05/25/2021	976425	Mechanic entered - Engine Other Belt idle pully u/s	r/r idle pullyok.		1144965
796	05/25/2021	976425	Mechanic entered - Elec and Light Interior Lights Dash switc	r/r globeok.		1144965
796	05/25/2021	976425	Mechanic entered - Elec and Light Interior Lights Rear saloo	Modifed to led lightok.		1144965
796	05/25/2021	976425	Consumables			1144965
796	05/25/2021	976425	Mechanic entered - Body Other Cut rear pax seat back handle	fixed with siliconok.		1144965
796	05/25/2021	976425	Mechanic entered - Body Other Rear door decal u/s	removed & fitted new decaleok.		1144965
796	05/25/2021	976425	PULLEY IDLER (SMOOTH STL) SCANIA L94UAB 1779801			1144965
796	05/25/2021	976425	Mechanic entered - Body Other noise from rear modesty panel	Drilling and riveting ok		1144965
796	05/25/2021	976425	Consumables			1144965
796	05/25/2021	976425	LED STRIP LIGHT (READY MADE)			1144965
796	05/25/2021	976425	SET DISC PAD SET SCANIA / MERCEDES 0500			1144965
796	05/25/2021	976425	Mechanic entered - Brakes Other worn rear break pad	r/r rear brake padok.		1144965
796	05/19/2021	975235	Mechanic entered - Elec and Light Exterior Lights O/S headli	Replaced globe		1144381
796	05/19/2021	975235	Consumables			1144381
796	05/13/2021	974086		TRANSMISSION CHECK AS PER CHECK LIST carried out as per check list		1144037
796	05/11/2021	973620	Mechanic entered - BusMinder Other Magnetic stand broken	Fitted new magnetic stand		1143727
796	05/11/2021	973620	MAGNETIC PHONE STAND(BUS MINDER)			1143727
796	05/11/2021	973620	Consumables			1143727
796	05/05/2021	972468	Mechanic entered - Elec and Light Exterior Lights High beam	Checked and found loose relay fit back and test all okay		1143362
796	05/05/2021	972468	Consumables			1143362
796	05/04/2021	972116	Mechanic entered - Wheels and Tyres Wheel Nut Retension N/S	carried out retorque as required		1143261
796	05/04/2021	972116	Consumables			1143261
796	05/03/2021	971779	rear brakes getting hot	Rear Hub Seal U/S. disassembled brakes removed disc cleaned hub and disc replaced grease replaced front and rear hub seals reassembled. Road tested Brake tested temp checked all ok both sides 21 degrees measured at hub		1143261
796	05/03/2021	971779	SEAL RR HUB INNER SCANIA K230UB 1740992 109952B			1143261
796	05/03/2021	971779	SEAL RR HUB OUTER SCANIA K230UB 1409890			1143261
796	05/03/2021	971833	Mechanic entered - Brakes Other	repaired on work order -971779		1143261
796	04/27/2021	970737	Mechanic entered - Engine Other coolant level over fill	had to find hose tap to drain coolant carry out coolant drain now level ok		1142819
796	04/27/2021	970737	Mechanic entered - Elec and Light Exterior Lights reverse le	supply new part carry out remove lens and whole assembly supply new led fitted led crimp new connection all tested ok		1142819
796	04/27/2021	970737	LAMP LED REVERSE LAMP RECTANGULAR			1142819
796	04/27/2021	970737	Mechanic entered - Elec and Light Other electrical wire need	resecure new loom behind bumper all tested ok		1142819
796	04/27/2021	970788	Mechanic entered - Elec and Light Exterior Lights front & re	r/r fluro tubesbut still n/w.		1142819
796	04/27/2021	970788	Consumables			1142819
796	04/27/2021	970737	Consumables			1142819
796	04/27/2021	970788	Mechanic entered - Body Other loose exterior panel screws.	tighten screwsok.		1142819
796	04/27/2021	970788	Mechanic entered - Body Other front exterior panel lock u/s.	removed & check for part. need to order for part.		1142819
796	04/27/2021	970788	Mechanic entered - Body Other missing front panel screws.	fitted new screwsok.		1142819
796	04/27/2021	970788	Mechanic entered - Body Other noisy from front modesty panel	removed & checked for part. need to order for part.		1142819
796	04/27/2021	970788	Mechanic entered - Body Other cut rear pax seat back handle.	fixed with siliconok.		1142819
796	04/27/2021	970788	Mechanic entered - Body Other loose drivers door lock screws	tighten screwsok.		1142819
796	04/27/2021	970788	Mechanic entered - Body Other missing reflectors.	replaced reflectors		1142819
796	04/27/2021	970788	REFLECTOR AMBER 94mm X 44MM (84051)			1142819
796	04/27/2021	970788	BUTTON SEAT BUTTON FAT BOY L/H			1142819
796	04/27/2021	970788	Mechanic entered - Air System Other drivers seat air switch	r/r air switchok.		1142819
796	04/27/2021	970600	FILTER OIL SCANIA S4 & K			1142819
796	04/27/2021	970600	FILTER FUEL FILTER SCANIA SR4 (1372444)			1142819
796	04/27/2021	970600	FILTER DRYER SCANIA/VOLVO (1375997) (3090288-6) (49G8704W)			1142819
796	04/27/2021	970600	SPINNER FILTER KIT ALL SCANIA			1142819
796	04/27/2021	970600		CARRY OUT C SERVICE AS PER CHECK LIST carry out c serv as per work order all check ok		1142819
796	04/27/2021	970600	OIL SAMPLE KIT CALTEX			1142819
796	04/27/2021	970600	FILTER ZF ECOMAT GEARBOX 4139-298-038 1193281			1142819
796	04/27/2021	970600	FILTER STEERING FILTER (153468) (0153468)(349619)			1142819
796	04/27/2021	970600	FILTER STEERING FILTER (153468) (0153468)(349619)			1142819
796	04/27/2021	970600	FILTER HYD COOLING FAN SCANIA L94UAB 1354074			1142819
796	04/27/2021	970600	Consumables			1142819
796	04/27/2021	970600	Consumables			1142819
796	04/27/2021	970600		CARRY OUT B SERVICE AS PER CHECK LIST		1142819
796	04/27/2021	970600	Consumables			1142819
796	04/27/2021	970600	Consumables			1142819
796	04/19/2021	968992	Mechanic entered - Wheels and Tyres Wheel Nut Retension o/s/	Retension completed		1141401
796	04/19/2021	968992	Consumables			1141401
796	04/19/2021	968993	Mechanic entered - Suspension Other O/S/F air bag air line l	Replaced leaking air line fitting		1141401
796	04/19/2021	968993	Mechanic entered - Engine Other Groove idler pulley worn	Replaced pulley		1141401
796	04/19/2021	968993	Mechanic entered - Elec and Light Interior Lights One saloon	Replaced fluro		1141401
796	04/19/2021	968993	Mechanic entered - Elec and Light Interior Lights Drivers re	Replaced inverter		1141401
796	04/19/2021	968993	Mechanic entered - Elec and Light Exterior Lights Both outsi	Replaced both the fluros		1141401
796	04/19/2021	968993	Mechanic entered - Elec and Light Other Indicators not cance	Replaced indicator stalk		1141401
796	04/19/2021	968993	PULLEY IDLER SCANIA (1514087)			1141401
796	04/19/2021	968993	INVERTER 24 Volt 36 Watt MAN			1141401
796	04/19/2021	968993	Mechanic entered - BusMinder Other Magnet base broken	Fixed broken magnet base as nil in stock new bases		1141401
796	04/19/2021	968993	SWITCH INDICATOR SCANIA L94 1402448			1141401
796	04/19/2021	968993	Consumables			1141401
796	04/19/2021	968993	Mechanic entered - Body Other Drivers myki machine loose	Tight up hinge screws		1141401
796	04/19/2021	968723	SPINNER FILTER KIT ALL SCANIA			1141401
796	04/19/2021	968723	FILTER FUEL FILTER SCANIA SR4 (1372444)			1141401
796	04/19/2021	968723		CARRY OUT B SERVICE AS PER CHECK LIST		1141401
796	04/19/2021	968723	FILTER ZF ECOMAT GEARBOX 4139-298-038 1193281			1141401
796	04/19/2021	968723	FILTER OIL SCANIA S4 & K			1141401
796	04/19/2021	968723	OIL SAMPLE KIT CALTEX			1141401
796	04/19/2021	968723	Consumables			1141401
796	04/19/2021	968723	Consumables			1141401
796	04/16/2021	968608	TYRE 295/80R22.5 RECAP			1141401
796	04/16/2021	968608	Mechanic entered - Wheels and Tyres Flat or Leaking Inner O/	Replaced inner O/S/R tyre with retread tyre new		1141401
796	04/16/2021	968608	Consumables			1141401
796	04/13/2021	967778	Ops Entered - Fault - Air System - Route: 767 - Southland	repaired air leak at drivers seat . all okay		1140964
796	04/01/2021	957133	Direct Purchase - BODYWORK	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS SERVICE P/O #:O293994 Receiving #:309813 Date :2021-04-08 resecure passenger seats as required		1140645
796	03/27/2021	964308	PERFORM CAMPAIGN 10/21 FITMENT OF AUTHORISED OPERATOR DECAL	done		1139162
796	03/26/2021	963551	Mechanic entered - Wheels and Tyres Other o/s/r tyres u/s	removed o/s/r tyres replaced o/s/r tyres ok		1139162
796	03/26/2021	963551	TYRE 295/80R22.5 RECAP			1139162
796	03/26/2021	964216	Mechanic entered - Wheels and Tyres Wheel Nut Retension o/s/	Completed retension		1139162
796	03/26/2021	963551	Consumables			1139162
796	03/26/2021	964216	Consumables			1139162
796	03/26/2021	963840	Place new poster over the top attach hangers to hand rails	complete		1139162
796	03/11/2021	959959	PERFORM CAMPAIGN 09/21 POSITIONING OF 2021 PTV FARES & COVI	complete		1137465

796	03/06/2021	957133	Mechanic entered - Body Other 2 x Seats Loose support Brac	sent to bodyshop - O293994 - KPS AND CB		1137149
796	03/06/2021	957133	Consumables			1140645
796	02/25/2021	956857		VEHICLE SAFETY INSPECTION Carried out safety inspection		1136880
796	02/25/2021	956857		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1136880
796	02/25/2021	957065	Consumables			1136967
796	02/25/2021	957065	Mechanic entered - Elec and Light Exterior Lights Step Light	replaced fluros on front and rear step lights checked and reassembled		1136880
796	02/25/2021	957065	Mechanic entered - Elec and Light Interior Lights O/S/R Salo	Removed cover and replaced blown fluro checked and re assembled cover		1136880
796	02/25/2021	957065	Consumables			1136967
796	02/25/2021	957065	Mechanic entered - Body Other Safety tape - front seats miss	replaced safety tape to both front seats		1136880
796	02/25/2021	957065	Mechanic entered - Body Other O/S/F Wheel Arch Brush Missing	replaced wheel arch brush with spare from body shop added to bus and cut to size		1136880
796	02/20/2021	955773	Leave old poster in and fit you must wear a maskover the	complete		1136424
796	02/15/2021	953724		CARRY OUT FIRE EXTINGUISHER TEST & TAG		1136157
796	02/15/2021	953724		complete		1136157
796	02/05/2021	951418	Keep ol poster in holder and place Travel off Peak and Sav	done by refullers on 04/02/2021		1135585
796	02/03/2021	950885	Consumables			1135585
796	02/03/2021	950885	Mechanic entered - Elec and Light Exterior Lights N/S/F mark	Replaced led marker light		1135531
796	02/03/2021	950885	LAMP LED SIDE MARKER RED/AMBER			1135531
796	01/25/2021	948889	Consumables			1135088
796	01/25/2021	949085	Consumables			1135088
796	01/25/2021	949085	Consumables			1135088
796	01/25/2021	948889	Consumables			1135088
796	01/25/2021	948889	Mechanic entered - Wheels and Tyres Flat or Leaking n/s/r/o	r/r tyreok.		1134574
796	01/25/2021	948889	TYRE 295/80R22.5 RECAP			1134574
796	01/25/2021	949085	Mechanic entered - Wheels and Tyres Wheel Nut Retension need	Completed retension		1134574
796	01/22/2021	948804	Ops Entered - Fault - CCTV has no recording on harddrive -	O291793 - repaired by ash from bwere		1134574
796	01/19/2021	947692	Consumables			1134574
796	01/19/2021	947692	Consumables			1134574
796	01/19/2021	947692	Mechanic entered - Body Other Drivers N/S Mirror smashed	removed broken mirror and replaced with second hand mirro from workshop checked and adjusted ok - accident number # 51646		1134574
796	01/19/2021	947787	Please fit A3 poster over COVID-19 poster and hangers to be	complete		1134574
796	01/19/2021	947991	Removed N/S/F window COVID-19 & MYKI decals and reposition	complete		1134574
796	01/07/2021	945088	Consumables			1133073
796	01/07/2021	945088	Consumables			1133073
796	01/07/2021	945088	Mechanic entered - Body Other wheel arch rubber trim falling	re fitted and secured trim can confirm issue is rectified		1132936
796	01/04/2021	944337	Consumables			1132664
796	01/04/2021	944337	Consumables			1132664
796	01/04/2021	944337	Mechanic entered - Wheels and Tyres Wheel Nut Retension Ret	carried out retorque as required		1132501
796	12/30/2020	943792	Mechanic entered - Brakes Other O/S/R brakes heating up	Checked o/s/r brakes found hub seal leaking removed hub replaced hub seal and inner outer bearings measured rotor and found okay fit back hub with new lock tab checked caliper found okay fit back old brake pads as it was still 90% Fit new pad sensor and brake booster road tested and found ok temperature ok		1132462
796	12/30/2020	943792	SEAL RR HUB INNER SCANIA K230UB 1740992 109952B			1132462
796	12/30/2020	943792	BEARING ROLLER BEARING			1132462
796	12/30/2020	943792	SENSOR WEAR SENSOR KIT BLOCK TYPE-AXLE SET SCANIA 1794440			1132462
796	12/30/2020	943792	LOCK WASHER RR HUB SCANIA K230UB 273023			1132462
796	12/30/2020	943792	BRAKE BOOSTER SCANIA L94UAB (35CLE0100)			1132462
796	12/22/2020	942725	Mechanic entered - Brakes Other rear brake hot	Adjusted all brake okbrake tested all ok after checked rear brake pads is 60%front brake pads is 70%rear temp is o/s 34 n/s temp is 31%front o/s temp is 30%n/s temp is 31 all ok		1132063
796	12/07/2020	939860	Mechanic entered - Elec and Light Exterior Lights O/S/R top	Replaced led light assy		1130802
796	12/07/2020	939860	L.E.D.STOP+TAIL LIGHT			1130802
796	12/07/2020	939860	Consumables			1130929
796	12/01/2020	938042	DIRECT PURCHASE - BUS INSPECTI	Creditor #:VB-FLE001 FLEETCHECK BUS PTY LTD P/O #:O288622 Receiving #:301428 Date :2020-12-03		1130594
796	12/01/2020	938545	DECAL - the 'you are travelling on bus' missing from front	complete		1130448
796	12/01/2020	938545	Consumables			1130540
796	11/30/2020	938042		VEHICLE SAFETY INSPECTION		1130366
796	11/30/2020	938042		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1130366
796	11/30/2020	938042		ANNUAL SAFETY INSPECTION SERIAL #___L 157488 GREEN SHEET _____WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLESAFETY INSPECTION LINE TIME ON THE W/O TO 0.25		1130366
796	11/25/2020	936355	Mechanic entered - Body Other disable ramp sensor n/w	CHECK WHEEL CHAIR RAMP OPENDOORS CAN BE CLOSED BUT DOOR BRAKES ARE ONBUS OK TO USE.		1130020
796	11/25/2020	936355	Consumables			1130223
796	11/25/2020	936645	PERFORM CAMPAIGN 27/20 UPDATED INTERNAL BUS NUMBER DECALS	complete		1130020
796	11/21/2020	935549	SAFETY WARNING TRIANGLE SET			1129915
796	11/21/2020	935549	AIRBAG FRT 14MM SCANIA K230UB 2024284 2809671 2024289			1129915
796	11/21/2020	935549	Consumables			1129915
796	11/21/2020	935605		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST done as per check list		1129915
796	11/20/2020	935549	Mechanic entered - Suspension Other worn o/s/f air bag.	r/r air bagok.		1129915
796	11/20/2020	935549	Mechanic entered - Elec and Light Interior Lights dash switc	r/r globeok.		1129915
796	11/20/2020	935549	Consumables			1129915
796	11/20/2020	935549	Mechanic entered - Body Other safety triangle u/s.	r/r safety triangleok.		1129915
796	11/20/2020	935549	Mechanic entered - Body Other loose pax seat braket bolts.	tighten boltsok.		1129915
796	11/20/2020	935549	Mechanic entered - Body Other missing floor rubber strip.	fitted new rubber stripok.		1129915
796	11/20/2020	935549	Mechanic entered - Body Other pri rsi.	done.		1129915
796	11/18/2020	934471	Remove old poster and fit you must wear a face mask when t	complete		1129717
796	11/18/2020	934551	PERFORM CAMPAIGN 26/20 REAR EXIT DECAL MAKE YOUR MARK & SE	complete		1129717
796	11/11/2020	932464	Mechanic entered - Suspension Other front d-rubber u/s	Replaced Front sway Bar 'D' Bushes with new ones from stock ok		1129113
796	11/11/2020	932464	BUSH FRT SWAY BAR SCANIA K230UB 0469081 1919010 40MM			1129113
796	11/09/2020	931508		PRE ANNUAL SAFETY INSPECTION CHECK carry out as per work order check ok		1128925
796	11/09/2020	931508		CARRY OUT CCTV - B SERVICE AS PER CHECK LIST carry out as per work order check ok		1128925
796	11/09/2020	931710	AIRBAG REAR 16MM SCANIA K230 / K270 2024287 2024290			1128925
796	11/09/2020	931710	Mechanic entered - Suspension Other n/s/r front-rear airbag	remove bag refit new bag check ok		1128925
796	11/09/2020	931710	ELBOW FITTING TWIN 16MM RR AIRBAG SCANIA L94UAB			1128925
796	11/09/2020	931728	Mechanic entered - Body Other n/s-o/s disable seat backing l	carry out remove refit check ok		1128925
796	11/09/2020	931728	Mechanic entered - Body Other disable ramp edge loose	fabricated bracket resecure ramp check ok		1128925
796	11/09/2020	931728	Consumables			1129015
796	11/02/2020	930334	Elec and Light osr bottom indicator nw	replaced osr bottom light ok		1128657
796	11/02/2020	930334	SEALED L.E.D REAR INDICATOR LAMP KIT			1128657
796	11/02/2020	930334	Consumables			1128813
796	10/29/2020	929641	Fit new Myki Decals & refit COVID-19 decals new position f	complete		1128193
796	10/16/2020	926618	DIRECT PURCHASE GLASS	Creditor #:VB-ALP003 ALPHA BUS GLASS PTY LTD P/O #:O285714 Receiving #:298156 Date :2020-10-16 # 51272 - unreported accident - desto glass cracked		1126346
796	10/15/2020	926618	Accident # 51272 - unreported cracked desto glass	desto glass replaced by alpha		1126151
796	10/13/2020	926022	PERFORM CAMPAIGN 20/20 VEHICLE TOLLWAY ETAG FITMENT	fit etag		1126096
796	09/28/2020	922624		complete		1124703
796	09/28/2020	922624		CARRY OUT FIRE EXTINGUISHER TEST & TAG		1124703
796	09/24/2020	922022	both battery u/s	went to jump batterys. found both batterys under 6 volts. replaced both battery . these batterys were last replaced on 26-7-17		1124146
796	09/24/2020	922022	BATTERY 1030CCA POS ON LHS EMFN150L			1124146
796	09/24/2020	922022	Consumables			1124311
796	09/21/2020	921303	Mechanic entered - Body Other Front wiper motor hatch not lo	Tighten up loose n/s lock mechanism and lock up the hatch		1123822
796	09/21/2020	921303	Consumables			1124002
796	09/18/2020	918812	OIL SAMPLE KIT CALTEX			1123249

796	09/18/2020	918812	Consumables			1123425
796	09/17/2020	920721	Mechanic entered - Wheels and Tyres Wheel Nut Retension o/s/	carried out wheel nut retension		1123088
796	09/17/2020	920721	Consumables			1123249
796	09/15/2020	920036		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1122623
796	09/15/2020	920036		VEHICLE SAFETY INSPECTION		1122623
796	09/15/2020	920086	Mechanic entered - Wheels and Tyres Other o/s/r/outer tyre u	replaced o/s/r/outer tyre ok		1122623
796	09/15/2020	920086	Consumables			1122885
796	09/15/2020	920086	TYRE 295/80R22.5 RECAP			1122623
796	09/15/2020	920086	TYRE 295/80R22.5 RECAP			1122885
796	09/15/2020	920131	BUSH SWAY BAR REAR (1904248)			1122623
796	09/15/2020	920131	Mechanic entered - Suspension Other both rear sway bar bushi	replaced both rear sway bar bushing x4		1122623
796	09/15/2020	920086	Mechanic entered - Suspension Other both front D rubber u/	replaced both front D rubber ok		1122623
796	09/15/2020	920086	BUSH FRT SWAY BAR SCANIA K230UB 0469081 1919010 40MM			1122623
796	09/15/2020	920086	Mechanic entered - Elec and Light Other frontrear step ligh	replaced frontrear step light tube x2		1122623
796	09/15/2020	920086	Mechanic entered - Elec and Light Other tombstone u/s	replaced front step light tombstone x1		1122623
796	09/15/2020	920086	TOMBSTONE			1122623
796	09/15/2020	920086	Mechanic entered - Elec and Light Other dash R.P.M light not	replaced dash R.P.M light globe ok		1122623
796	09/15/2020	920086	Mechanic entered - Elec and Light Other both rear saloon lig	replaced both rear saloon light cover ok		1122623
796	09/15/2020	920086	Consumables			1122885
796	09/15/2020	920086	DIFFUSER LIGHT COVER ELLAMP 3mtr LONG			1122623
796	09/15/2020	920086	Mechanic entered - Elec and Light Other both front saloon li	replaced both front saloon light tube x3		1122623
796	09/15/2020	920086	Mechanic entered - Body Other front door top panel loose	repaired front door top panel ok		1122623
796	09/15/2020	920086	Consumables			1122885
796	09/08/2020	918848	Mechanic entered - Body Other front pax seats top hinge pins	knocked back in pins as required		1121922
796	09/08/2020	918848	Mechanic entered - Body Other loose screws on exterior panel	tightened screws all ok		1121922
796	09/08/2020	918848	Consumables			1121985
796	09/08/2020	918812		CARRY OUT B SERVICE AS PER CHECK LIST carried out all service work as required		1121922
796	09/08/2020	918812	FILTER ZF TRANS ECOMAT (1193281-1)(4139 298 038 01)			1121922
796	09/08/2020	918812	FILTER FUEL FILTER SCANIA SR4 (1372444)			1121922
796	09/08/2020	918812	Oil Filter SCANIA S4 & K			1121922
796	09/01/2020	866431	DIRECT PURCHASE ACCIDENT	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS SERVICE P/O #:O266351-CR Receiving #:295712 Date :2020-09-10 #50-151 Mick to Replace		1122075
796	08/29/2020	916934	battery load test and check	load tested both batteries ok. bus starting no problem.		1120128
796	08/29/2020	916934	Consumables			1120361
796	08/27/2020	916654	jump start	jump started bus . checked charge rate . 27.3 volts		1120061
796	08/27/2020	916654	Consumables			1120128
796	08/13/2020	913649	hand brake sometimes leaking air	replaced handbrake valve . rechecked for leaks - all okay		1118574
796	08/13/2020	913649	VALVE PARK BRAKE SCANIA SR3 4 0469271 0570866			1118574
796	08/06/2020	911626	Remove old A3 Poster and fit with You can no longer top up	fitted A3 poster		1118087
796	08/05/2020	911026	SWITCH PRESSURE SWITCH SCANI	Creditor #:VB-MUL004 MULTISPARES OAKLEIGH P/O #:O281089 Receiving #:293123 Date :2020-08-06		1118142
796	08/05/2020	911026	Consumables			1118142
796	08/05/2020	911026	Consumables			1118142
796	08/04/2020	911026	Mechanic entered - Air System Warning Light On Low air press	Checked and replaced faulty air pressure switch . PN 1361131		1118020
796	07/20/2020	907684	Fault#:37712 - Ops Entered - Fault - Breakdown Not Starting	bus was moved to oakleigh . this b/down defect was moved with the bus in tims . repair carried out at seaford . no idea who went to the breakdown		1116453
796	07/09/2020	905807	Mechanic entered - Body Other Front hatch lock u/s	Replaced damage lock from scrap bus		1115454
796	07/09/2020	905807	Consumables			1115908
796	07/06/2020	904846	Fault#:37675 - Ops Entered - Fault - Breakdown Not Starting	breakdown carried out by Jarek - jump start bus		1114789
796	07/06/2020	904889	load test and checked batteries as required - bus had jump	load tested and checked batterys as per precedure . batts x 2 - 12volts + after sitting for 2 hrs . checked charge rate . 27.8 volts .		1114789
796	07/06/2020	904889	Consumables			1115224
796	07/04/2020	904674	Dip stick tube repair	Assisting		1114789
796	07/04/2020	904674	Dip stick tube repair	Connected topside tube to hose.		1114789
796	07/01/2020	903921		TRANSMISSION CHECK AS PER CHECK LIST carry out trans check.		1114467
796	07/01/2020	903751	AIR CONDITIONING REPAIR	Creditor #:VB-COL004 COLD DRIVE PTY LTD P/O #:O278467 Receiving #:291001 Date :2020-07-09 carry out ac-b as required		1115454
796	06/30/2020	903751		CARRY OUT A/C - B SERVICE AS PER CHECK LIST - cammy cold drive PO#: O278467		1114467
796	06/30/2020	903751		CARRY OUT A/C - A SERVICE AS PER CHECK LIST		1114467
796	06/24/2020	902873	Mechanic entered - Wheels and Tyres Wheel Nut Retension need	retorque all rear wheel nuts.		1113403
796	06/24/2020	902873	Consumables			1113548
796	06/23/2020	902554		done.		1113331
796	06/23/2020	902554		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1113331
796	06/23/2020	902700	Mechanic entered - Body Other loose pax seat base bolt.	tighten pax seat base boltsok.		1113331
796	06/23/2020	902700	Mechanic entered - Body Other pax seat under cover not secur	fixed pax seatok.		1113331
796	06/23/2020	902700	Mechanic entered - Body Other drivers door locker n/w.	fixed door lockerok.		1113331
796	06/23/2020	902700	Mechanic entered - Body Other noisy from rear modesty panel.	fixed rear modesty panelok.		1113331
796	06/23/2020	902700	SET DISC PAD SET SCANIA / MERCEDES 0500			1113331
796	06/23/2020	902700	Consumables			1113403
796	06/23/2020	902700	Mechanic entered - Brakes Other worn rear brake pad.	r/r rear brake padsok.		1113331
796	06/19/2020	902098	Air_Leak Front under dash	Drivers suspension seat button not pushed all the way in. Checked OK		1112542
796	06/10/2020	899814	Fit A3 Poster in poster frame and fit decals as requested i	carried out campaign as required		1111767
796	06/06/2020	899197	Vandalism - interior graffiti	cleaned and painted over interior graffiti		1111228
796	06/06/2020	899045		CARRY OUT CCTV - A SERVICE AS PER CHECK LIST carried out as per check list		1111228
796	05/21/2020	895782	Elec and Light middle int light nw	fit new fluro light.		1109875
796	05/21/2020	895782	Consumables			1110018
796	05/15/2020	894469	Mechanic entered - Warning Lights Other HANDBRAKE LIGHT STAY	also reported demister n/wroad testget hotcould not fault demister.		1109023
796	05/15/2020	894469	Consumables			1109023
796	05/14/2020	894469	CHECK VALVE SCANIA L113CRL 2274810 448450			1109023
796	05/14/2020	894469	SWITCH PARK BRAKE SWITCH SCANIA			1109023
796	05/14/2020	894469	Mechanic entered - Warning Lights Other HANDBRAKE LIGHT STAY	FIT NEW AIR PRESSURE SWITCH AND AIR TANK CHECK VALVE.		1109023
796	05/04/2020	891937	Mechanic entered - Wheels and Tyres Wheel Nut Retension Rete	retorque all front wheel nuts.		1106866
796	05/04/2020	891937	Consumables			1108116
796	04/29/2020	890347	DIRECT PURCHASE - MECHANICAL G	Creditor #:VB-BIG010 BIG WHEELS TRUCK ALIGNMENT P/O #:O273970 Receiving #:285724 Date :2020-04-30 check and rectify wheel alignment		1106675
796	04/29/2020	890347	Consumables			1106675
796	04/24/2020	890347	wheel alignment required	to go to Big Wheel dandy PO#: O273970		1106247
796	04/24/2020	890347	DIRECT PURCHASE - MECHANICAL G	Creditor #:VB-BIG010 BIG WHEELS TRUCK ALIGNMENT P/O #:O273970 Receiving #:285676 Date :2020-04-30 check and rectify wheel alignment		1106675
796	04/20/2020	889001	DIRECT PURCHASE - GLASS	Creditor #:VB-GLA010 GLASSPROTECH MELBOURNE P/O #:O273444 Receiving #:284813 Date :2020-04-20 door windscreen & driverside window tinting		1105865
796	04/20/2020	889001	Consumables			1106106
796	04/20/2020	889282	Mechanic entered - Air System Other DRIVER SEAT AIR LEAKS	repaired DRIVER SEAT AIR LEAKS OK		1105732
796	04/17/2020	889001	Body - Windows Front TINTING	COMPLETED		1105732
796	04/09/2020	887379	A4 notification to be printed off in colour laminated and	carried out campaign on 08/04/2020		1105015
796	04/03/2020	885893	Mechanic entered - Wheels and Tyres Wheel Nut Retension need	retorque all front wheel nuts.		1104631
796	04/03/2020	885893	Consumables			1104758
796	04/01/2020	885494		VEHICLE SAFETY INSPECTION done.		1104554
796	04/01/2020	885494		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1104554
796	04/01/2020	885595	Mechanic entered - Wheels and Tyres Worn worn front tyres.	r/r front tyresok.		1104554
796	04/01/2020	885595	Consumables			1104631

796	04/01/2020	885595	Mechanic entered - Elec and Light Exterior Lights rear door	r/r fluro tubeok.			1104554
796	04/01/2020	885595	Mechanic entered - Elec and Light Exterior Lights o/s/f clea	fixed wiringok.			1104554
796	04/01/2020	885595	Mechanic entered - Elec and Light Interior Lights front step	r/r fluro tubeok. r/r tube holdersok.			1104554
796	04/01/2020	885595	Mechanic entered - Elec and Light Interior Lights rear saloo	r/r fluro tubeok.			1104554
796	04/01/2020	885595	Consumables				1104631
796	04/01/2020	885595	Mechanic entered - Brakes Other worn front brake pad.	r/r front brake padsok.			1104554
796	04/01/2020	885595	TOMBSTONE				1104554
796	04/01/2020	885595	TWO WAY JOINER				1104554
796	04/01/2020	885595	SET DISC PAD SET SCANIA / MERCEDES 0500				1104554
796	04/01/2020	885595	TYRE 295/80R22.5 NEW				1104554
796	03/31/2020	885177	Mechanic entered - Elec and Light Flat Batteries	jump start.			1104392
796	03/31/2020	885177	Consumables				1104554
796	03/24/2020	883224	Remove old poster and fit Reduce Your Risk of Coronavirus	carried out campaign as required			1103543
796	03/24/2020	883324	Tape off front Seats of All Route and Rail Buses with spec	carried out campaign as required			1103543
796	03/23/2020	881850	DIRECT PURCHASE - VANDALISM	Creditor #:VB-GLA010 GLASSPROTECH MELBOURNE P/O #:O271521 Receiving #:282971 Date :2020-03-26 graffiti window film replacement - Audit 255 Stage 1			1103781
796	03/20/2020	881850	Vandalism - Vandalism/ Graffiti Interior: Protective window	O271521 carried by glass protect			1102170
796	03/19/2020	881569	Mechanic entered - Elec and Light Other pax bell switch u/s.	r/r pax bell switchok.			1102170
796	03/19/2020	881569	Consumables				1102313
796	03/19/2020	881569	Mechanic entered - Body Other missing roof panel screws.	fitted new screwsok.			1102170
796	03/19/2020	881569	Mechanic entered - Body Other pax hand grab not secure.	fixed pax hand grabok.			1102170
796	03/19/2020	881569	Mechanic entered - Body Other loose lauggage racks screws.	fixed lauggage racksok.			1102170
796	03/19/2020	881569	SWITCH- STOP-YELLOW (62628)				1102170
796	03/19/2020	881569	Consumables				1102313
796	03/19/2020	881436		CARRY OUT B SERVICE AS PER CHECK LIST done.			1102170
796	03/19/2020	881436	Oil Filter SCANIA S4 & K				1102170
796	03/19/2020	881436	KIT O-RING OIL SPINNER FILTER SCANIA ABOVE ENG #6203050				1102170
796	03/19/2020	881436	FILTER FUEL FILTER SCANIA SR4 (1372444)				1102170
796	03/19/2020	881436	FILTER ZF TRANS ECOMAT (1193281-1)(4139 298 038 01)				1102170
796	03/19/2020	881436	Consumables				1102313
796	03/19/2020	881436	Consumables				1102313
796	03/19/2020	881436	Consumables				1102313
796	03/14/2020	880563	Vandalism - interior graffiti	cleaned and paint over interior graffiti			1101758
796	03/11/2020	879332	Mechanic entered - Elec and Light Flat Batteries	fabricated a bracket and fitted master solenoid. tested ok			1101429
796	03/11/2020	879332	SWITCH BATTERY MASTER SCANIA K124IB 2127157 2079254				1101429
796	03/11/2020	879332	Consumables				1101632
796	03/10/2020	879332	Mechanic entered - Elec and Light Flat Batteries	carry out jumpstart but it was isolation switch faulty gave the switch a tap now working			1101277
796	03/06/2020	878998	Mechanic entered - Elec and Light Flat Batteries	Jump Started Bus			1100873
796	03/06/2020	878998	Consumables				1101051
796	03/04/2020	878415	Mechanic entered - Elec and Light Exterior Lights n/s/f park	fit globe.			1100544
796	03/04/2020	878415	Consumables				1100873
796	03/02/2020	878088	Mechanic entered - Elec and Light Exterior Lights O/S head l	Replaced globe			1100450
796	03/02/2020	878088	Consumables				1100544
796	02/28/2020	877597		complete			1099400
796	02/28/2020	877597		CARRY OUT FIRE EXTINGUISHER TEST & TAG			1099400
796	02/26/2020	877083	Mechanic entered - Elec and Light Other N/S front lower park	inspected all lights couldn't fault at time of test			1098981
796	02/26/2020	877083	Consumables				1099190
796	02/21/2020	875943	Mechanic entered - Engine Other Main belt broken	Replaced main engine belt			1098589
796	02/21/2020	875943	BELT MICRO V SERPENTINE BELT 8 RIB 2135mm LONG (1389048)				1098589
796	02/20/2020	875531	Fault#:37397 - Ops Entered - Fault - Breakdown Warning Ligh	double entry			1098457
796	02/20/2020	875531	Fault#:37397 - Ops Entered - Fault - Breakdown Warning Light	Replaced leaking coolant hose top up coolant wash and road test			1098457
796	02/20/2020	875531	HOSE TRANSMISSION COOLING HOSE				1098457
796	02/20/2020	875531	Ops Entered - Fault - Warning Lights Temperature - Route:	double entry			1098457
796	02/17/2020	874805	Mechanic entered - Air System Other front air bags cannot ad	found front height sensor loose resecured and tested ok			1098011
796	02/13/2020	874026	Mechanic entered - Engine Belts_Loose Noisy Missing A/C Belt	Replaced A/C Belts x2			1096697
796	02/13/2020	874026	BELT V-BELT HI-POWER 17x2335mm				1096697
796	02/13/2020	874096	Mechanic entered - Engine Other A/C belts flipped loose	replaced belts tightened and tested ok			1096697
796	02/13/2020	874096	BELT V-BELT HI-POWER 17x2390mm VOLVO B10B				1096697
796	02/08/2020	872697		VEHICLE SAFETY INSPECTION			1095716
796	02/08/2020	872697		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS			1095716
796	02/08/2020	872698	Mechanic entered - A/C Heating Other a/c belt u/s	a/c belts u/s			1095716
796	02/08/2020	872698	BELT V-BELT HI-POWER 17x2335mm				1095716
796	02/08/2020	872698	Mechanic entered - Engine Other engine belt idler bearing u/	R&R bearing all okay			1095716
796	02/08/2020	872698	PULLEY IDLER (SMOOTH STL) SCANIA L94UAB 1779801				1095716
796	02/08/2020	872698	FILTER AIR FILTER (395773) AF25066				1095716
796	02/08/2020	872698	Mechanic entered - Engine Other engine air filter u/s	replaced engine air filter ok			1095716
796	02/08/2020	872698	Mechanic entered - Elec and Light Other dash speedo light no				1095716
796	02/08/2020	872698	Mechanic entered - Elec and Light Other frontrear step ligh	replaced frontrear step light tube ok			1095716
796	02/08/2020	872698	Consumables				1095860
796	02/05/2020	871950	PERFORM CAMPAIGN 01/20 POSITIONING OF 2020 PTV FARES & PRIO	carried out campaign as required			1095334
796	01/30/2020	866431	DIRECT PURCHASE ACCIDENT	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS SERVICE P/O #:O266351 Receiving #:278281 Date :2020-01-30 # 50151 - mick to replace body panels x2 to n/s of bus			1094698
796	01/10/2020	866431	Accident # 50151 - damage to n/s mid	repaired by mick on p/o - O266351			1091027
796	01/02/2020	864741	Fault#:37205 - Ops Entered - Fault - Breakdown Not Starting	Attended breakdown jump started bus reminded drivers to start bus at intervals of half an hour As they leave master switch on for two way radio			1089350
796	12/16/2019	862047	Mechanic entered - Elec and Light Other Master Switch Soleno	Replaced Solenoid and tested ok			1088346
796	12/16/2019	862047	Consumables				1088479
796	12/16/2019	859516	Direct Purchase - BODYWORK	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS SERVICE P/O #:O264155 Receiving #:275112 Date :2019-12-16 fit wheel arch rubber/brush as required			1088479
796	12/16/2019	859516	Consumables				1088479
796	12/09/2019	860519	Mechanic entered - Body Front_Door Operation Faulty door swi	fit good second hand switch. checked operation of pasenger doors . all okay			1087550
796	12/09/2019	860519	Consumables				1087899
796	12/06/2019	859886		CARRY OUT FIRE EXTINGUISHER TEST & TAG			1087550
796	12/06/2019	859886		completed			1087550
796	12/05/2019	859516	Mechanic entered - Wheels and Tyres Wheel Nut Retension bot	retensioned both rears			1087397
796	12/05/2019	859516	Consumables				1087550
796	12/05/2019	859516	Mechanic entered - Body Other FRONT O/S WHEEL BRUSH MISSING	done by mick - PO#: O264155			1087397
796	12/05/2019	859516	Mechanic entered - Body Other FRONT N/S WHEEL BRUSH DAMAGE	done by mick			1087397
796	12/05/2019	859516	Mechanic entered - Body Other FIRE EXTIN DECAL MISSING	done			1087397
796	12/05/2019	859598	A3 Poster Frame Adhesive Decal Campaign please remove old	fitted new A3 decal			1087397
796	12/03/2019	858385	Drv entered - BusMinder Damaged	checked condition and bus minder operation. could not fault			1086982
796	12/03/2019	858385	Consumables				1087270
796	12/02/2019	858207	Mechanic entered - Wheels and Tyres Other o/s rear inner tyr	replaced o/s rear inner tyre			1086982
796	12/02/2019	858207	Mechanic entered - Wheels and Tyres Wheel Nut Retension whee	ok			1086982
796	12/02/2019	858299	Mechanic entered - Wheels and Tyres Other both rear	ok			1086982
796	12/02/2019	858207	TYRE 295/80R22.5 RECAP				1086982
796	12/02/2019	858207	Consumables				1087111

796	12/02/2019	858299	Consumables			1087111
796	12/02/2019	858295	transmission mount bolt needs replacing	removed trans mount bolt bus number 879put in bus number 796tightened trans mount bolts ok		1086982
796	12/02/2019	858295	DIRECT PURCHASE - MECHANICAL G	Creditor #:VB-WOL002 WOLFCHESTER AUSTRALIA PTY LTD P/O #:O263816 Receiving #:274217 Date :2019-12-05 wolfchester to supply bolts x 2 and air line reducers x 10 as required		1087397
796	12/02/2019	858295	F3422 06 04 11 Plug	Creditor #:VB-WOL002 WOLFCHESTER AUSTRALIA PTY LTD P/O #:O263816 Receiving #:274217 Date :2019-12-05 wolfchester to supply bolts x 2 and air line reducers x 10 as required		1087397
796	12/02/2019	858295	CONSUMABLE DELIVERY CHARGE	Creditor #:VB-WOL002 WOLFCHESTER AUSTRALIA PTY LTD P/O #:O263816 Receiving #:274217 Date :2019-12-05		1087397
796	12/02/2019	858207	Mechanic entered - Elec and Light Other dash speedo light no	replaced dash speedo light globe		1086982
796	12/02/2019	858207	SENSOR WEAR SENSOR KIT BLOCK TYPE-AXLE SET L94UB (1794440)			1086982
796	12/02/2019	858207	Mechanic entered - Elec and Light Other rear brake pad wire	replaced both rear brake pads ok		1086982
796	12/02/2019	858207	Consumables			1087111
796	12/02/2019	858207	Mechanic entered - Body Other n/s middle seat top- broken	replaced n/s middle seat top hinge rivets		1086982
796	12/02/2019	858207	Mechanic entered - Body Other o/s middle seat braket cracked	o/s middle seat braket welding		1086982
796	12/02/2019	858207	Mechanic entered - Body Other o/s grab handle missing	replaced o/s grab handle		1086982
796	12/02/2019	858207	HANDLE GRAB HARD PLASTIC PASSENGER (GREY)			1086982
796	12/02/2019	858207	Consumables			1087111
796	12/02/2019	858207	SET DISC PAD SET SCANIA / MERCEDES 0500			1086982
796	12/02/2019	858207	Mechanic entered - Brakes Other both rear brake pads u/s	ok		1086982
796	11/27/2019	857314		VEHICLE SAFETY INSPECTION		1086721
796	11/27/2019	857314		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1086721
796	11/27/2019	857314		ANNUAL SAFETY INSPECTION SERIAL #___K 199898 GREEN SHEET_____WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLESAFETY INSPECTION LINE TIME ON THE W/O TO 0.25		1086721
796	11/27/2019	857314	DIRECT PURCHASE - BUS INSPECTI	Creditor #:VB-FLE001 FLEETCHECK BUS PTY LTD P/O #:O263428 Receiving #:273628 Date :2019-11-28		1086721
796	11/27/2019	857377	Mechanic entered - Body Other o/s red reflector missing	supply part carry out refit reflector check ok		1086721
796	11/27/2019	857377	Consumables			1086721
796	11/21/2019	856177	TOMBSTONE			1085530
796	11/21/2019	856177	Mechanic entered - Elec and Light Interior Lights sallon lig	carry out replace toomstone holderredrill new hole crimp new connector refit fluro check ok		1085530
796	11/21/2019	856177	Consumables			1085722
796	11/20/2019	855857		CARRY OUT TUNE-UP SERVICE AS PER CHECK LIST carry out tune up as per work order check/ road test ok		1085530
796	11/20/2019	855857		SERVICE MOISTURE EJECTOR		1085530
796	11/20/2019	855857	GASKET ROCKER CVR DC903 B01 SCANIA L94UAB 1425921			1085530
796	11/14/2019	854581		TRANSMISSION CHECK AS PER CHECK LIST CARRY OUT AS PERWORK OREDER CHECK OK		1084424
796	11/14/2019	854513		CARRY OUT CCTV - B SERVICE AS PER CHECK LIST CARRY OUT AS PER WORK ORDER CHECK OK		1084424
796	11/14/2019	854513		PRE ANNUAL SAFETY INSPECTION CHECK		1084424
796	11/14/2019	843862	Mechanic entered - Wheels and Tyres Other O/S/R/I TYRE VALVE	CARRY OUT R/R CHECK OK		1084424
796	11/14/2019	843862	Consumables			1084616
796	11/14/2019	843862	Switch Rear Stop Scania			1084424
796	11/14/2019	843862	Mechanic entered - Elec and Light Other eng stop toggle swit	CARRY OUT R/R CHECK OK		1084424
796	11/14/2019	843862	Mechanic entered - Elec and Light Exterior Lights N/S FRONT/	DAMAGE SCREW CARRY OUT R/R CHECK OK		1084424
796	11/14/2019	843862	Mechanic entered - Elec and Light Other DASH SALOON LIGHT SW	CARRY OUT R/R CHECK OK		1084424
796	11/14/2019	843862	Consumables			1084616
796	11/06/2019	843862	BELT V-BELT HI-POWER 17x2310mm			1083225
796	11/06/2019	843862	LED NO PLATE+EXIT LIGHT (26674)			1083225
796	11/02/2019	852320	Wheels and Tyres - retension both frt	retorqued both front wheel nuts ok		1082919
796	11/02/2019	852320	Consumables			1083121
796	11/02/2019	852321	TORQUE ROD FRONT UPPER SCANIA K230 (1438475)			1082919
796	11/02/2019	852321	Suspension NSF upper t/rod bushes us	replaced n/s/f t/rod ok		1082919
796	11/02/2019	852322	Body sunblind os screws need to be secured	removed sunblind replaced sunblind screws ok		1082919
796	11/02/2019	852322	Consumables			1083121
796	11/01/2019	851960	TYRE 295/80R22.5 NEW			1082919
796	11/01/2019	851960	Wheels and Tyres FRT VIBRATION	Replaced frt tyres retensioned wheel nuts and rebooked for retension. road tested ok no vibration		1082919
796	11/01/2019	851960	Consumables			1083121
796	11/01/2019	852198	Ops Entered - Fault - Steering Pulling - Route: 733 - Came	completed on work order - 851960		1082919
796	11/01/2019	851958		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST carried out fire safe as per check list		1082919
796	11/01/2019	852047		instructed to close off by fleet - ben willis via group e-mail		1082919
796	11/01/2019	852047		CARRY OUT CCTV - A SERVICE AS PER CHECK LIST		1082919
796	10/27/2019	850714	Mechanic entered - Engine Other Oil filter seal leaking	Reseal and check for leaks		1081979
796	10/25/2019	850367	Consumables			1082359
796	10/25/2019	850367	OIL COLLECTOR AIR DRIER -SCANIA 40G0006			1081979
796	10/25/2019	850367	Mechanic entered - Elec and Light Interior Lights Saloon lig	Replaced fluro		1081979
796	10/25/2019	850367	Consumables			1082359
796	10/25/2019	850367	BUTTON SEAT BUTTON FAT BOY L/H			1081979
796	10/25/2019	850367	Mechanic entered - Body Drivers Seat Controls Height adjuste	Replaced with new adjuster		1081979
796	10/25/2019	850367	AIRBAG REAR SCANIA K230 / K270 2024287 2024290			1081979
796	10/25/2019	850367	Mechanic entered - Air System Air_Leak Rear	Replaced condenser valve - Job done by -RG		1081979
796	10/25/2019	850367	Mechanic entered - Air System Other AIR LEAK FROM CONDENSER	Replaced air bag		1081979
796	10/25/2019	850367	Mechanic entered - Air System Air_Leak Rear	leak at oil seperatorrebook.		1081979
796	10/25/2019	850504	Consumables			1082359
796	10/25/2019	850504	Consumables			1082359
796	10/25/2019	850504	Consumables			1082359
796	10/25/2019	850504	KIT O-RING OIL SPINNER FILTER SCANIA ABOVE ENG #6203050			1081979
796	10/25/2019	850504	FILTER ZF TRANS ECOMAT (1193281-1)(4139 298 038 01)			1081979
796	10/25/2019	850504	FILTER FUEL FILTER SCANIA SR4 (1372444)			1081979
796	10/25/2019	850504	Oil Filter SCANIA S4 & K			1081979
796	10/25/2019	850504		CARRY OUT B SERVICE AS PER CHECK LIST Completed B service		1081979
796	10/21/2019	844683	Consumables			1081721
796	10/21/2019	844683	Direct Purchase - BODYWORK	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS SERVICE P/O #:O258889 Receiving #:270408 Date :2019-10-21 mick to fit wheel arch brush as required		1081647
796	10/15/2019	848213	Consumables			1081066
796	10/15/2019	848213	Mechanic entered - Elec and Light Next Stop Button Stop Bell	Checked Next stop Bells All ok		1080914
796	10/03/2019	845847	Consumables			1079703
796	10/03/2019	845847	Ops Entered - Fault - Elec and Light Next Stop Button - Ro	checked operation of passenger bell . could not fault		1079514
796	09/26/2019	844683	Consumables			1079081
796	09/26/2019	844683	wheel arch brush missing	O258889 - carried out by mick		1078878
796	09/24/2019	843837	Consumables			1078734
796	09/24/2019	843837	Mechanic entered - Wheels and Tyres Wheel Nut Retension O/S/	Completed retension		1078359
796	09/24/2019	843837	BRACKET MIRROR ARM LH			1078359
796	09/24/2019	843837	Consumables			1078734
796	09/23/2019	843768		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Carried out safety inspection		1078359
796	09/23/2019	843768		VEHICLE SAFETY INSPECTION		1078359
796	09/23/2019	843837	BUSH FRT SWAY BAR SCANIA K230UB 0469081 1919010 40MM			1078359
796	09/23/2019	843837	Mechanic entered - Suspension Other Front 'D' Rubbers U/S	Replaced and adjusted tie rod Replaced front 'D' Rubbers		1078359
796	09/23/2019	843837	Mechanic entered - Steering Excessive Play Tie rod U/S	replaced complete tie rod		1078359
796	09/23/2019	843837	TIE ROD ASSY SCANIA L94/K230/N310 1897333			1078359
796	09/23/2019	843862	Consumables			1078591
796	09/23/2019	843862	INVERTER 24 Volt 36 Watt MAN			1078359
796	09/23/2019	843862	Mechanic entered - Elec and Light Interior Lights nsr saloon	replaced inverter and wired up ok		1078359

796	09/23/2019	843837	Consumables			1078591
796	09/23/2019	843837	LAMP LED SIDE MARKER RED/AMBER			1078359
796	09/23/2019	843837	Mechanic entered - Elec and Light Exterior Lights O/S/F Side	Replaced O/S/F Marker light		1078359
796	09/23/2019	843837	Mechanic entered - Elec and Light Exterior Lights Step Light	Replaced step lights x2		1078359
796	09/21/2019	843899	Vandalism Vandalism/ Graffiti Interior	carried out interior vandelisem painting		1078527
796	09/13/2019	842181	Consumables			1077697
796	09/13/2019	842181	Mechanic entered - Wheels and Tyres Wheel Nut Retension Rete	retensioned nsr		1077545
796	09/12/2019	842034	Consumables			1077545
796	09/12/2019	842034	TYRE 295/80R22.5 RECAP			1077375
796	09/12/2019	842034	Mechanic entered - Wheels and Tyres Worn Pos 3 worn	Replaced worn pos 3 tyre and match pos4 with new retreads . Pos 4 left as a runout		1077375
796	08/23/2019	837382	CCTV - 6 month service - johnny bwere	o256267 - carried out by johnny from bwere electrics		1074414
796	08/21/2019	837382	DIRECT PURCHASE - ELECTRICAL	Creditor #:VB-BWE001 BWERE ELECTRICS PTY LTD P/O #:O256267 Receiving #:265493 Date :2019-08-23 6 month service		1074414
796	08/10/2019	834938	Vandalism Vandalism/ Graffiti Interiorrear side windows	carried out interior vandelisem painting as required		1072987
796	08/09/2019	834403	Consumables			1072987
796	08/09/2019	834403	Elec and Light - NS HEAD LIGHT NW - REPORTED BY REFUELLERS	fit globe.		1072692
796	08/07/2019	833931	cold drive to reprogram carrier controller as required	O254904 - reprogrammed by cold drive		1072623
796	08/06/2019	833931	AIR CONDITIONING REPAIR	Creditor #:VB-COL004 COLD DRIVE PTY LTD P/O #:O254904 Receiving #:264436 Date :2019-08-12 reprogram carrier a/c controller		1072987
796	07/13/2019	828609	Consumables			1069509
796	07/13/2019	828609	Mechanic entered - Wheels and Tyres Wheel Nut Retension fron	retorqued front both tyres wheel nuts ok		1069320
796	07/13/2019	828600	FITTING ELBOW			1069320
796	07/13/2019	828600	Mechanic entered - Suspension Other o/s/r/r air bag u/s	replaced o/s/r/r air bag replaced air bag fitting ok		1069320
796	07/12/2019	828346				1069320
796	07/12/2019	828346		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1069320
796	07/12/2019	828346		VEHICLE SAFETY INSPECTION		1069320
796	07/12/2019	828415	Double Back-Disable	Creditor #:VB-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:O252754 Receiving #:261898 Date :2019-07-16		1069765
796	07/12/2019	828415	Double Seat Base	Creditor #:VB-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:O252754 Receiving #:261898 Date :2019-07-16 retrim 3 double seat base as required		1069765
796	07/12/2019	828415	Vandalism - pax seat x 3 vandalised	removed and sent away for retrimming PO#: O252754 replaced pax seat base x3 ok		1069320
796	07/12/2019	828459	BUSH SHOCK ABSORBER			1069320
796	07/12/2019	828459	Mechanic entered - Suspension Other Front Lower Shock absorb	Replaced Front Lower Shock Rubbers		1069320
796	07/12/2019	828459	AIRBAG REAR SCANIA K230 / K270 (2024287) (1726242)			1069320
796	07/12/2019	828459	Mechanic entered - Suspension Other O/S/R/F O/S/R/R N/S/R/	O/S/R/F and N/S/R/F Air Bags Replaced O/S/R/R not replaced due to bus being needed		1069320
796	07/12/2019	828365	SEAL DIFF PINION SCANIA R660 1502385			1069320
796	07/12/2019	828365	Mechanic entered - Gearbox Driveline Other diff seal oil lea	replaced diff seal ok		1069320
796	07/12/2019	828365	SEAL REAR TRANSMISSION SR 4 SCANIA			1069320
796	07/12/2019	828365	Mechanic entered - Gearbox Driveline Other trans oil seal le	replaced trans trat seal ok		1069320
796	07/12/2019	828365	Mechanic entered - Engine Other engine oil leaks	repaired engine oil leaks from to the oil pipe fitting ok		1069320
796	07/12/2019	828365	Consumables			1069496
796	07/12/2019	828365	TOMBSTONE			1069320
796	07/12/2019	828365	Mechanic entered - Elec and Light Exterior Lights	Rear Step Light Not working Replaced Step light Globe		1069320
796	07/12/2019	828365	Mechanic entered - Elec and Light Interior Lights Rear Saloo	replaced saloon light tombstone x2 ok		1069320
796	07/12/2019	828365	Mechanic entered - Elec and Light Interior Lights Rear Saloo	Replaced Tombstones X2 and Fitted Globes		1069320
796	07/12/2019	828365	Mechanic entered - Brakes Other Front Brake Pads U/S	Replaced Front Pad And Re Run Bridge wires on both sides		1069320
796	07/12/2019	828365	SET DISC PAD SET SCANIA / MERCEDES 0500			1069320
796	07/06/2019	826917	Ops Entered - Fault - Engine Low Power - Route: 733 - Camer	checked and found the high idle on. this will cut throttle over 1000rpm unless brakes apply. also checked with SD2 and found 28 - speed signal and 22 - brake switch faults recorded but inactive. keep monitoring and check for foot brakes valve if it happens again.		1068457
796	06/21/2019	824519	Consumables			1067191
796	06/21/2019	824456	Consumables			1067191
796	06/21/2019	824519	Consumables			1067191
796	06/21/2019	824519	Mechanic entered - Wheels and Tyres Wheel Nut Retension Rete	Retension completed		1067039
796	06/21/2019	824456	TYRE 295/80R22.5 NEW			1067039
796	06/21/2019	824456	Mechanic entered - Wheels and Tyres Damaged O/S/F tyre damag	Replaced damage tyre with a new one		1067039
796	06/19/2019	823762		CARRY OUT A/C - A SERVICE AS PER CHECK LIST - O250684		1066733
796	06/18/2019	823762	AIR CONDITIONING REPAIR	Creditor #:VB-COL004 COLD DRIVE PTY LTD P/O #:O250684 Receiving #:260320 Date :2019-06-27 carry out 12 month service as required		1067579
796	05/21/2019	818149	Mechanic entered - Engine Other OIL LIGHT FLICKERING ON DAS	FOUND OIL PRESSURE SWITCH U/SNIL STOCKREMOVE FROM BUS 884 AND FITROAD TEST OK..		1062611
796	05/21/2019	818149	Switch Oil Pressure Scania Se	Creditor #:VB-MUL004 MULTISPARES OAKLEIGH P/O #:O248530 Receiving #:257079 Date :2019-05-22		1062719
796	05/20/2019	818028	LINK SWAYBAR SCANIA K230 1766014 20486 01			1062541
796	05/20/2019	818028	Mechanic entered - Suspension Other Front sway bar link worn	Replaced both links		1062541
796	05/20/2019	817940	Consumables			1062611
796	05/20/2019	818029	Consumables			1062611
796	05/20/2019	817940	Consumables			1062611
796	05/20/2019	818029	Consumables			1062611
796	05/20/2019	817940	Lights saloon light n/w.			1062541
796	05/20/2019	818029	LAMP LED NUMBER PLATE & EXIT LIGHT (250120) (2559)			1062541
796	05/20/2019	818029	Mechanic entered - Elec and Light Other Rear emergency exit	Replaced exit light replaced fluro fittednew cover for switch		1062541
796	05/20/2019	818030	Consumables			1062611
796	05/20/2019	818030	Consumables			1062611
796	05/20/2019	818030	CATCH ASSY- OJOP			1062541
796	05/20/2019	818030	Mechanic entered - Body Other Seat hand grab been cut panel	Repaired with sila flex and tight screws Fitted rear seat latch		1062541
796	05/20/2019	817940	Consumables			1062611
796	05/20/2019	817940	Consumables			1062611
796	05/20/2019	817940	Consumables			1062611
796	05/20/2019	817940	Consumables			1062611
796	05/20/2019	817940	Consumables			1062611
796	05/20/2019	817940	Consumables			1062611
796	05/20/2019	817940	KIT O-RING OIL SPINNER FILTER SCANIA ABOVE ENG #6203050			1062541
796	05/20/2019	817940	FILTER FUEL FILTER SCANIA SR4 (1393640)			1062541
796	05/20/2019	817940		CARRY OUT B SERVICE AS PER CHECK LIST		1062541
796	05/20/2019	817940	Oil Filter SC S4 & K			1062541
796	05/20/2019	817940	FILTER ZF TRANS ECOMAT (1193281-1)(4139 298 038 01)			1062541
796	05/20/2019	817940	FILTER FUEL FILTER SCANIA SR4 (1372444)			1062541
796	05/15/2019	816952	bus leaking coolant from water pump.	checked and tightend water pump housing . rechecked for coolant leaks all okay		1061939
796	05/12/2019	815329	Please remove all old poster and fit MYKI has gone mobil	fleet support completed this campaign		1061060
796	05/04/2019	812818		CARRY OUT FIRE EXTINGUISHER TEST & TAG		1060279
796	05/04/2019	812818		completed		1060279
796	05/01/2019	812655	Mechanic entered - Suspension Other rear stuck in raise posi	tested ok		1060279
796	05/01/2019	811712	1881260 Oil Pressure Sender	Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:O246624 Receiving #:255224 Date :2019-05-02		1060427
796	05/01/2019	799333	DIRECT PURCHASE - ELECTRICAL	Creditor #:VB-BWE001 BWERE ELECTRICS PTY LTD P/O #:O241648 Receiving #:257030 Date :2019-05-21 rectify video at channel 5 rear camera		1062611
796	04/30/2019	812655	VALVE TAG / RR AXLE LVL CNTRL SCANIA L94UAB 481830			1060279
796	04/30/2019	812655	Mechanic entered - Suspension Other rear stuck in raise posi	fit new rear leveling valve blockorder new oil sender. fit new oil sender switch.		1060279
796	04/26/2019	811712	SEALING RING	Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:O246416 Receiving #:254746 Date :2019-04-29 796		1060279
796	04/24/2019	811712	Mechanic entered - Fluid Leaks Rear of bus leaking coolant f	R&R air compressor		1060279
796	04/24/2019	811712	Mechanic entered - Fluid Leaks Rear of bus leaking oil from	fixed coverok.		1060279
796	04/24/2019	811712	40A5704 Gasket	Creditor #:VB-MUL004 MULTISPARES OAKLEIGH P/O #:O246401 Receiving #:254749 Date :2019-04-29		1060279

796	04/24/2019	811712	AIR COMPRESSOR RR DRIVE	Creditor #:VB-MUL004 MULTISPARES OAKLEIGH P/O #:O246401 Receiving #:254749 Date :2019-04-29		1060279
796	04/24/2019	811712	GASKET (40A2628)			1060279
796	04/24/2019	811712	PUMP WATER PUMP SCANIA S4			1060279
796	04/23/2019	811655	HANDLE GRAB HANDLE PASSENGER			1060279
796	04/23/2019	811655	EDGE STEP EDGE YELLOW 43mm			1060279
796	04/23/2019	811655		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1060279
796	04/23/2019	811655		VEHICLE SAFETY INSPECTION done.		1060279
796	04/23/2019	811712	Mechanic entered - Fluid Leaks Rear of bus leaking oil from	resealed engine block side covers. checked operation all okay		1060279
796	04/12/2019	810150	Consumables			1057803
796	04/12/2019	810150	passenger doors not working	reset benware node. checked operation of doors all okay		1057696
796	04/05/2019	808500	Consumables			1056801
796	04/05/2019	808500	Mechanic entered - Body Other cant adjust strreing wheel.	free up steering wheel lock.		1056486
796	04/03/2019	808160	Consumables			1056486
796	04/03/2019	808160	Mechanic entered - Body Rear_Door Operation Faulty	Checked for rear door getting stuck half way found top bracket loose and alignment out adjusted door		1056310
796	03/27/2019	806541		carried out transmission check as required		1055334
796	03/27/2019	806541		TRANSMISSION CHECK AS PER CHECK LIST		1055334
796	03/25/2019	805956	Consumables			1055204
796	03/25/2019	805956	Mechanic entered - Body Other n/s rearvision mirror broken.	removefit good second hand mirror.		1055029
796	03/22/2019	805516	Consumables			1054646
796	03/22/2019	805513	Consumables			1054646
796	03/22/2019	805516	Nut Retension Retension both rear wheels	carried out w/o - 805513		1054646
796	03/22/2019	805513	rear retorque required	retensioned both rears		1054646
796	03/20/2019	803283	HARNESS LOW PAD WIRING REAR L94			1054364
796	03/20/2019	803283	Brakes smoke coming off o/s rear wheel brake appears to be	Fitted new pad wear sensor fitted n/s/r booster fit wheels back adjusted brakes wash and road test Checked diff oil		1054364
796	03/19/2019	803283	40G8429Knorr RH Brake Caliper	Creditor #:VB-MUL004 MULTISPARES OAKLEIGH P/O #:O243613 Receiving #:252104 Date :2019-03-22		1054646
796	03/19/2019	803283	40G8428knorr LH Brake Caliper	Creditor #:VB-MUL004 MULTISPARES OAKLEIGH P/O #:O243613 Receiving #:252104 Date :2019-03-22		1054646
796	03/19/2019	803283	SET DISC PAD SET SCANIA / MERCEDES 0500			1054364
796	03/19/2019	803283	SENSOR WEAR SENSOR KIT BLOCK TYPE-AXEL SET L94UB (1794440)			1054364
796	03/19/2019	803283	LOCK WASHER REAR AXLE SCANIA 273023			1054364
796	03/19/2019	803283	SEAL REAR AXLE CAP SCANIA 1765061 120310			1054364
796	03/19/2019	803283	Brakes smoke coming off o/s rear wheel brake appears to be	Assembled both side hub with new disc repack grease on hubs and fit back Dismantle calipers and assemble with new ones ahd mount on with new pads and sensors		1054364
796	03/18/2019	803283	BRAKE BOOSTER SCANIA L94UAB (35CLE0100)			1054364
796	03/18/2019	803283	Brakes smoke coming off o/s rear wheel brake appears to be	Dismantle the calipers and fit new o/s/r booster		1054364
796	03/18/2019	803283	Consumables			1054476
796	03/18/2019	803283	Consumables			1054476
796	03/18/2019	803283	Consumables			1054476
796	03/18/2019	803283	SEAL INNER REAR AXLE SCANIA	Creditor #:VB-MUL004 MULTISPARES OAKLEIGH P/O #:O243613 Receiving #:252105 Date :2019-03-22		1054646
796	03/16/2019	803283	Brakes smoke coming off o/s rear wheel brake appears to be	Removed n/s/r hub clean parts and assemble new rotors both side		1054364
796	03/16/2019	803283	BRAKE DISC FRT SCANIA K230UB 1858351 1402272			1054364
796	03/15/2019	803283	Brakes smoke coming off o/s rear wheel brake appears to be	Removed o/s/r hub clean parts removed wheels and check n/s/r too		1054364
796	03/13/2019	803283	Brakes smoke coming off o/s rear wheel brake appears to b	checked and found both rear rotors over heated and osr had hub seal leaking too. this may have caused for osr smoking.		1054364
796	03/07/2019	802329	Consumables			1053253
796	03/07/2019	802329	Consumables			1053253
796	03/07/2019	802329	Consumables			1053253
796	03/07/2019	802329	AIRBAG REAR SCANIA K310			1052807
796	03/07/2019	802329	Button Shift D HORIZONTAL SERIES 3			1052807
796	03/07/2019	802329	BELT V-BELT HI-POWER 17x2515mm			1052807
796	03/07/2019	802329	BELT V-BELT HI-POWER 17x2515mm			1052807
796	02/26/2019	796557	DIRECT PURCHASE - VANDALISM	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS SERVICE P/O #:O240748 Receiving #:250516 Date :2019-03-01 rectify passenger seat coming off wall as required		1051869
796	02/21/2019	799596	Consumables			1051021
796	02/21/2019	799596	Mechanic entered - Body Other ns rear view mirror loose	removed the mirror arm and the broken bracket from body. fitted a second hand bracket. fitted arm and mirror. ok		1050913
796	02/20/2019	799246	Vandalism glass film replaced x 1	film replaced by glass protect on p/o - O241586		1050832
796	02/20/2019	799372	Mechanic entered - Elec and Light Exterior Lights o/s./f hea	r/r globeok.		1050832
796	02/20/2019	799333	cctv video loss	repaired by johnny - O241648		1050832
796	02/19/2019	799246	DIRECT PURCHASE - VANDALISM	Creditor #:VB-GLA010 GLASSPROTECH MELBOURNE P/O #:O241586 Receiving #:250026 Date :2019-02-22 X 1 FILM		1051021
796	02/12/2019	797306	Accident#:47793 - Ops Entered - Accident - Bus Hitting Obje	repaired at bodyshop on p/o - O241013		1049986
796	02/08/2019	796557	Mechanic entered - Body Other os middle seat has come off th	dropped the bus at Dandenong body shop.		1049986
796	02/08/2019	796557	passenger seat has broken off the wall	passenger seat repaired at bodyshop - O240748		1049986
796	02/08/2019	796557	Consumables			1050151
796	02/07/2019	787786	spinner filter spinndel to install	installed spinner		1049986
796	02/05/2019	795705		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1049986
796	02/05/2019	795705		VEHICLE SAFETY INSPECTION		1049986
796	01/30/2019	794227	Consumables			1049651
796	01/30/2019	794227	Mechanic entered - Elec and Light Exterior Lights o/s/f bott	FIT GLOBE.		1049295
796	01/26/2019	793779	KIT A SERVICE KIT SCANIA K310UB (2277578)			1048632
796	01/26/2019	793779	Mechanic entered - Body Other ns front mirror arm assembley	remove broken remain part replace new arm with new bolts ajust it		1048632
796	01/21/2019	787955	Engine - spinner filter shaft u/s	installed spinner shaft onto bus .		1047730
796	01/18/2019	792258	Please remove old 2018 fare decals and fit new 2019 fare de	carried out campaign as required		1047730
796	01/15/2019	791404	Consumables			1047461
796	01/15/2019	791404	Mechanic entered - Elec and Light Exterior Lights o/s/f park	r/r globeok.		1047299
796	01/10/2019	790428	Consumables			1045997
796	01/10/2019	790428	ROCKER SWITCH			1045847
796	01/10/2019	790428	Mechanic entered - Elec and Light Other frt door nw	diagnosed and found frt door switch us nw at times. replaced switch ok.		1045847
796	01/09/2019	790053	Consumables			1045847
796	01/09/2019	790053	L.E.D.STOP+TAIL LIGHT			1045567
796	01/09/2019	790053	Mechanic entered - Elec and Light Exterior Lights n/s/r brak	removerewire and fit new stop light.		1045567
796	01/02/2019	788755	Engine needs jump start	jump started bus		1043571
796	12/27/2018	787842	Consumables			1043292
796	12/27/2018	787842	Mechanic entered - Wheels and Tyres Wheel Nut Retension need	retorque all o/s/r wheel nuts.		1042901
796	12/27/2018	787991	AIR CONDITIONING REPAIR	Creditor #:VB-COL004 COLD DRIVE PTY LTD P/O #:O237727 Receiving #:246053 Date :2019-01-07 rectify a/c not working as required		1045299
796	12/27/2018	787991	A/C Heating not working	O237727 - cold drive		1042901
796	12/24/2018	787786	Consumables			1043079
796	12/24/2018	787786	Mechanic entered - Wheels and Tyres Worn worn o/s/r tyres.	r/r tyresok.		1042901
796	12/24/2018	787786	BELT MICRO V SERPENTINE BELT 8 RIB 2135mm LONG (1389048)			1042901
796	12/24/2018	787786	TYRE 295/80R22.5 RECAP			1042901
796	12/24/2018	787786	Mechanic entered - Engine Other alts belt u/s.	r/r beltok.		1042901
796	12/24/2018	787786	Mechanic entered - Engine Other missing speener filter coope	part not in store need to order.		1042901
796	12/24/2018	787747	Consumables			1043079
796	12/24/2018	787747	Consumables			1043079
796	12/24/2018	787747	Consumables			1043079
796	12/24/2018	787747	FILTER FUEL FILTER SCANIA SR4 (1393640)			1042901
796	12/24/2018	787747	FILTER DRYER SCANIA/VOLVO (1375997) (3090288-6) (49G8704W)			1042901
796	12/24/2018	787747	FILTER ZF TRANS ECOMAT (1193281-1)(4139 298 038 01)			1042901

796	12/24/2018	787747	FILTER FUEL FILTER SCANIA SR4 (1372444)			1042901
796	12/24/2018	787747	KIT O-RING OIL SPINNER FILTER SCANIA ABOVE ENG #6203050			1042901
796	12/24/2018	787747	Oil Filter SC S4 & K			1042901
796	12/24/2018	787747	FILTER AIR FILTER (395773) AF25066			1042901
796	12/24/2018	787747	FILTER P/STEER SCANIA VOLVO MERCEDES (349619-7) (2192404)			1042901
796	12/24/2018	787747	FILTER HYD COOLING FAN SCANIA SR3 (1354074)			1042901
796	12/24/2018	787747				1042901
796	12/24/2018	787747	Consumables			1043079
796	12/24/2018	787747	Consumables			1043079
796	12/24/2018	787747	Consumables			1043079
796	12/24/2018	787747		CARRY OUT B SERVICE AS PER CHECK LIST		1042901
796	12/13/2018	783744	DIRECT PURCHASE - ENGINE	Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:O236058 Receiving #:244899 Date :2018-12-17 rectify leak around bell housing as required - bic repair		1042196
796	12/12/2018	785494	A/C Heating - AC nw (Lindsay booked in for Cold Drive)	Cold Drive checked this O236768		1041105
796	12/12/2018	785494	AIR CONDITIONING REPAIR	Creditor #:VB-COL004 COLD DRIVE PTY LTD P/O #:O236768 Receiving #:245333 Date :2018-12-20 check and rectify AC nw		1042756
796	12/04/2018	783539		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1039927
796	12/04/2018	783539		VEHICLE SAFETY INSPECTION		1039927
796	12/04/2018	783539	DIRECT PURCHASE - BUS INSPECTI	Creditor #:VB-FLE001 FLEETCHECK BUS PTY LTD P/O #:O235934 Receiving #:243942 Date :2018-12-05		1040811
796	12/04/2018	783539		ANNUAL SAFETY INSPECTION SERIAL #____J453608_____WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLESAFETY INSPECTION LINE TIME ON THE W/O TO 0.25		1039927
796	12/04/2018	783744	Fluid Leaks - oil leaks arond bell housing air compressor	O236058		1039927
796	12/04/2018	783744	BIC REPAIRS - rectify and clean engine oil leak - Serial J	O236058 - repaired at scania		1039927
796	12/01/2018	787955	40A7713 Spinner Rotor	Creditor #:VB-MUL004 MULTISPARES OAKLEIGH P/O #:O237738 Receiving #:246099 Date :2019-01-07		1045299
796	11/29/2018	782592	CCTV carry out 6 month service - bewere johnny	carried out by johnny from bewere - O235611		1038927
796	11/22/2018	781246	Consumables			1038564
796	11/22/2018	781246	Mechanic entered - Body Other	Replaced damage n/s mirrior and tighten bols for mirrior arm		1038354
796	11/22/2018	781246	MIRROR L/H 380mm SHORT (UES1411E)			1038354
796	11/14/2018	779335		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST carried out fire safe as oper check list		1036735
796	11/10/2018	778610	Consumables			1036425
796	11/10/2018	778610	Mechanic entered - Wheels and Tyres Wheel Nut Retension both	retorque all front wheel nuts.		1036215
796	11/08/2018	778234	FILTER ZF TRANS ECOMAT (1193281-1)(4139 298 038 01)			1035922
796	11/08/2018	778234	FILTER FUEL FILTER SCANIA SR4 (1372444)			1035922
796	11/08/2018	778234	KIT O-RING OIL SPINNER FILTER SCANIA ABOVE ENG #6203050			1035922
796	11/08/2018	778234	Oil Filter SC S4 & K			1035922
796	11/08/2018	778234		PRE ANNUAL SAFETY INSPECTION CHECK done.		1035922
796	11/08/2018	778340	Consumables			1036215
796	11/08/2018	778340	TYRE 295/80R22.5 NEW			1035922
796	11/08/2018	778340	Mechanic entered - Wheels and Tyres Worn o/s/f tyre worn.	r/r front tyresok.		1035922
796	11/08/2018	778340	Consumables			1036215
796	11/08/2018	778340	Mechanic entered - Elec and Light Indicators Not Working sal	fixed saloon light ok.		1035922
796	11/08/2018	778340	Consumables			1036215
796	11/08/2018	778340	Mechanic entered - Body Other stauchion pole braket screw mi	fixed poleok.		1035922
796	11/08/2018	778340	Mechanic entered - Body Other n/s/f mirror loose.	tighten boltsok.		1035922
796	11/08/2018	778234	Consumables			1036215
796	11/08/2018	778234	Consumables			1036215
796	11/08/2018	778234		CARRY OUT B SERVICE AS PER CHECK LIST done.		1035922
796	11/05/2018	777711	Engine wont start	jump started bus		1035767
796	11/02/2018	777275	AIRBAG O/S/F SCANIA K230UB (2024284)			1035298
796	11/02/2018	777275	Mechanic entered - Suspension Leaning n/s/f leaking	removefit new n/s/f air bag.		1035298
796	11/01/2018	782592	DIRECT PURCHASE - ELECTRICAL	Creditor #:VB-BWE001 BWERE ELECTRICS PTY LTD P/O #:O235611 Receiving #:243477 Date :2018-11-29		1039146
796	11/01/2018	777004	Consumables			1035623
796	11/01/2018	777004	Ops Entered - Fault - Body Front_Door Operation Faulty - Ro	reposition and secure top guide roller.		1035298
796	10/30/2018	776507	Consumables			1035298
796	10/30/2018	776507	Ops Entered - Fault - Elec and Light Exterior Lights - Rout	clean terminals at plugnow ok.		1034928
796	10/20/2018	774718	Consumables			1032965
796	10/20/2018	774718	Mechanic entered - Wheels and Tyres Wheel Nut Retension need	Job done by -SA		1032868
796	10/18/2018	774266		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1032730
796	10/18/2018	774266		VEHICLE SAFETY INSPECTION done.		1032730
796	10/18/2018	774382	Consumables			1032868
796	10/18/2018	774382	Mechanic entered - Wheels and Tyres Damaged damaged o/s/r/i	replaced o/s/r inner tyre with run out tyre . tensioned wheel nuts all okay		1032730
796	10/18/2018	774382	Consumables			1032868
796	10/18/2018	774382	Mechanic entered - Elec and Light Interior Lights saloon lig	r/r fluro tubesok.		1032730
796	10/18/2018	774382	Mechanic entered - Elec and Light Interior Lights dash switc	r/r globesok.		1032730
796	10/18/2018	774382	Consumables			1032868
796	10/18/2018	774382	Consumables			1032868
796	10/18/2018	774382	Mechanic entered - Body Other missing rear no smoking decale	fitted new decaleok.		1032730
796	10/05/2018	771089	Consumables			1030330
796	10/05/2018	771089	Consumables			1030330
796	10/05/2018	771089	Body - n/s gutter rubber has come off	resecured all okay		1030215
796	10/05/2018	771228	REMOVE AND REPLACE A3 POSTER TO ALL ROUTE VEHICLES	carried out campaign as required		1030215
796	10/01/2018	769922	PERFORM CAMPAIGN 26/18 CHASSIS WASH & UNDER CARRIAGE CHECK	carried out under chassis clean as required		1029629
796	09/26/2018	769231		CARRY OUT FIRE EXTINGUISHER TEST & TAG		1029289
796	09/26/2018	769231		closed off as completed as per instruction from paul bell		1029289
796	09/08/2018	764946	Consumables			1025893
796	09/08/2018	764946	Front park light is not working	replaced globe		1025270
796	09/07/2018	764834	Consumables			1025893
796	09/07/2018	764834	Mechanic entered - Elec and Light Exterior Lights nsr width	replaced broken light and checked ok		1025270
796	09/07/2018	764834	LAMP LED SIDE MARKER RED/AMBER			1025270
796	09/03/2018	763570		TRANSMISSION CHECK AS PER CHECK LIST		1025270
796	09/03/2018	763708	PERFORM CAMPAIGN 11/18 VENTURA BUS MINDER INSTALLATION	fitted DC5V usb outlet socket and wired up		1025270
796	09/03/2018	763703	PERFORM CAMPAIGN 17/18 INTERNAL BUS NUMBERS	internal bus numbers are all on		1025270
796	09/01/2018	763377	Consumables			1025888
796	09/01/2018	763377	Consumables			1025888
796	09/01/2018	763377	Body Front_Door Operation Faulty- slow to 0pen	checekd over doors and lubed up cleaned and all good to go		1025270
796	08/30/2018	762925	Mechanic entered - Body Rear_Door Operation Faulty	rear door no operation. check it out and found RPD at fault. rear door now working.		1024876
796	08/30/2018	762925	Service	checked could not fault.		1024876
796	08/30/2018	762925	Consumables			1025049
796	08/30/2018	762925	Consumables			1025049
796	08/24/2018	760384	DIRECT PURCHASE - MECHANICAL GENERAL			1024653
796	08/24/2018	760384	Gearbox Driveline (None) trans output shaft seal leaking			1024653
796	08/24/2018	760384	Gearbox Driveline (None) trans output shaft seal leaking			1024653
796	08/23/2018	760384	Plug KOSTAL Ecomat 2/4	Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS P/O #:K227812 Receiving #:236176 Date :2018-09-03		1025888
796	08/23/2018	760384	Gearbox Driveline (None) trans output shaft seal leaking			1024653
796	08/21/2018	759797	Consumables			1024653
796	08/21/2018	759797	Consumables			1024653

796	08/21/2018	759797	Body (None) eng bay o/s trans body upright cracked			1024653
796	08/21/2018	760768	Accident#:47452 - Ops Entered - Accident - Bus Hitting Obje	ECTB CARRY OUT REPAIRS		1024653
796	08/20/2018	760384	Gearbox Driveline (None) trans output shaft seal leaking	Replace output shaft seal with tool		1024653
796	08/20/2018	760273	Consumables			1024653
796	08/20/2018	760273	Consumables			1024653
796	08/20/2018	760273	Body Front_Door Operation Faulty - Check front door operat	Check and adjust doors- all ok		1024653
796	08/20/2018	759797	Body (None) eng bay o/s trans body upright cracked	fitted rear bar repaired upright		1024653
796	08/17/2018	759921	V STAY ASSEMBLY SCANIA L94UAB			1024653
796	08/17/2018	759921	Suspension RECTIFY REAR V ROD GOT EXESSIVE MOVEMENT	helped Darren pull out V-Rod by droping whole axel. and removing. re-installed axel and tightend all bolts.		1024653
796	08/17/2018	759921	Suspension RECTIFY REAR V ROD GOT EXESSIVE MOVEMENT	remove diff and remove & replace V rod. refit diff		1024653
796	08/17/2018	759797	Body (None) eng bay o/s trans body upright cracked	remove rear bar and repair need to remove gear box to repair upright		1024653
796	08/16/2018	759644	Driver reports a loud banging noise from rear of bus during	V rod bush needs replacing. VOR BUS SENT KNOX WORKSHOP Replaced vrod and broken crossmember		1024653
796	08/15/2018	759500	Consumables			1024653
796	08/15/2018	759500	Drv entered - Body Front_Door Operation Faulty	Checked door operation. Remove sticky goo from edge rubber Test ok		1024407
796	08/15/2018	759500	Consumables			1024653
796	08/10/2018	758481	Consumables			1023935
796	08/10/2018	758481	Consumables			1023935
796	08/10/2018	758479	Consumables			1023935
796	08/10/2018	758479	Consumables			1023935
796	08/10/2018	758481	Body Front_Door Operation Faulty	repaired front door.		1023608
796	08/10/2018	758479	Body Front_Door Operation Faulty- when front door button p	refitteed broken reverts doors ok.		1023608
796	08/07/2018	757514				1023116
796	08/07/2018	757514		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1023116
796	08/07/2018	757514		VEHICLE SAFETY INSPECTION		1023116
796	08/07/2018	757627	PULLEY IDLER SCANIA (1514087)			1023116
796	08/07/2018	757627	Mechanic entered - Engine Noisy or Rattling eng belt idler	replace eng idler pulley		1023116
796	08/07/2018	757626	Consumables			1023116
796	08/07/2018	757626	LAMP FLUORESCENT TUBE 36 Watt			1023116
796	08/07/2018	757626	Mechanic entered - Elec and Light Interior Lights	replace fluoro tubes		1023116
796	08/07/2018	757707	Consumables			1023116
796	08/07/2018	757707	Consumables			1023116
796	08/07/2018	757707	Mechanic entered - Body Other panel above rear door needs re	took aprt oold panel and replaced with new planel		1023116
796	08/06/2018	757243	Wheels and Tyres Wheel Nut Retension Rear axle @ 10225	Assisting		1022537
796	08/06/2018	757243	Wheels and Tyres Wheel Nut Retension Rear axle @ 10225	Retensioned rear axle.		1022537
796	08/04/2018	756331	Wheels and Tyres Worn n/s/r/i/o tread low 3mm and o/s/r/o	Replaced N/S/R tyres using new caps & replaced valve extension		1022537
796	08/04/2018	756331	VALVE FLEXIBLE TYRE EXTENSION VALVE 180mm LONG			1022537
796	08/04/2018	756331	TYRE 295/80R22.5 RECAP			1022537
796	08/01/2018	756331	Wheels and Tyres Worn n/s/r/i/o tread low 3mm and o/s/r/o	checked ok.		1021804
796	08/01/2018	756330	Drv entered - Fluid Leaks Front of bus windscreen leak need	water leaking from windscreen.ok to use.		1021804
796	07/26/2018	755082	WIPER REFILL 1000mm MULTI FIT			1020941
796	07/26/2018	755082	Drv entered - Wipers and Washers Wipers Loose	put new wiper blades on		1020941
796	07/18/2018	753172	AIR CONDITIONING REPAIR	Creditor #:IB-COL004 COLD DRIVE PTY LTD P/O #:V225295 Receiving #:232867 Date :2018-07-25 replace burnt out boost pump supplied by invicta		1020579
796	07/18/2018	753172	PUMP BOOST PUMP COACH 90 Ltr			1019244
796	07/18/2018	753172	A/C Heating Demister Not Heating			1019244
796	07/18/2018	753172	Drv entered - A/C Heating Not Heating	gary from cold drive carry out repairs		1019244
796	07/13/2018	752145	Consumables			1018910
796	07/13/2018	752145	Ops Entered - Fault - Elec and Light Electric - burning sme	Checked and could not fault		1018910
796	07/13/2018	752145	Drv entered - Elec and Light AM-FM Radio			1018910
796	07/13/2018	752145	Drv entered - Elec and Light AM-FM Radio	Repair connection		1018910
796	06/29/2018	748854	Body Rear_Door Operation Faulty	rear door sensitive edge switch faulty.replaced switch.ok.		1015934
796	06/29/2018	748854	Consumables			1016196
796	06/28/2018	748854	Body Rear_Door Operation Faulty	repaired switch.		1015652
796	06/28/2018	743597	Service	completed		1015652
796	06/27/2018	748587	PERFORM CAMPAIGN 13/18 VENTURA ROUTE BUS DECAL UPDATE	COMPLETED		1015418
796	06/27/2018	748478	PERFORM CAMPAIGN 16/18 2019 REGISTRATION LABEL REPLACEMENT	COMPLETED		1015418
796	06/21/2018	723425	Consumables			1014215
796	06/21/2018	723425	Body NSR PANEL DAMAGE-REPORTED BY GEOFF TODD	SECURED OK NEEDS TO SEND TO ECTB		1013529
796	06/21/2018	723425	Body NSR PANEL DAMAGE-REPORTED BY GEOFF TODD			1013529
796	06/20/2018	733410	DIRECT PURCHASE - GLASS	Creditor #:IB-ALP003 ALPHA BUS GLASS PTY LTD P/O #:V223406 Receiving #:230769 Date :2018-06-29 replace windscreen		1015934
796	06/20/2018	746541	CCTV camera behind driver a bit blury	Refocused CCTV camera		1013529
796	06/19/2018	745703	Direct Purchase - BODYWORK	Creditor #:IB-EAS003 EASTCOAST TRUCK & BUS SERVICE P/O #:V222351 Receiving #:230264 Date :2018-06-22 Repair door ram cover.		1014215
796	06/19/2018	745703	Consumables			1013821
796	06/15/2018	745703	power steering line above fuel pump needs securing at clamp	secured line by adjusting clamp.		1013010
796	06/15/2018	745703	Switch Lights N/W Guage Lights N/W	Replaced blown globes		1013010
796	06/15/2018	745703	Consumables			1013258
796	06/15/2018	745703	Both Doors Sensitive edge N/W	Adjusted sensitive edge		1013010
796	06/15/2018	745703	Panel above front door loose	Secure panel above door		1013010
796	06/15/2018	745731	Cold Drive carried out A/C B Service	CARRY OUT A/C - B SERVICE AS PER CHECK LIST		1013010
796	06/15/2018	745731	Cold Drive carried out A/C A Service	CARRY OUT A/C - A SERVICE AS PER CHECK LIST		1013010
796	06/13/2018	745731	AIR CONDITIONING REPAIR	Creditor #:IB-COL004 COLD DRIVE PTY LTD P/O #:V222354 Receiving #:229832 Date :2018-06-18 B Service. replace dryer replace compressor oil replace return air filter replace low pressure switch evac/regas		1013258
796	06/12/2018	743597	KIT SWITCH OVERRIDE RPD			1012230
796	06/09/2018	744496	Elec and Light Indicators Not staying on.	Checked ok.		1012230
796	06/09/2018	744496	Consumables			1012230
796	06/08/2018	744150	Consumables			1012230
796	06/08/2018	744150	Mechanic entered - Body Other n/s/m seat	drill out bolts and refit with new M10 bolts to seat.		1012111
796	06/08/2018	744150	Mechanic entered - Body Other seat base bolt broken rh side			1012111
796	06/08/2018	744266	Consumables			1012230
796	06/08/2018	744266	Consumables			1012230
796	06/08/2018	744266	Consumables			1012230
796	06/08/2018	744266	O-RING KIT OIL SPINNER FILTER SCANIA UP TO ENG #6203049			1012111
796	06/08/2018	744266	FILTER ZF TRANS ECOMAT (1193281-1)(4139 298 038 01)			1012111
796	06/08/2018	744266	FILTER FUEL FILTER SCANIA SR4 (1372444)			1012111
796	06/08/2018	744266	Oil Filter SC S4 & K			1012111
796	06/08/2018	744266				1012111
796	06/08/2018	744266		Assisting		1012111
796	06/08/2018	744266		CARRY OUT B SERVICE AS PER CHECK LIST complete.		1012111
796	06/08/2018	744266	Consumables			1012230
796	06/08/2018	744266	Consumables			1012230
796	06/08/2018	744266		CARRY OUT A SERVICE AS PER CHECK LIST complete.		1012111
796	06/08/2018	744266	Consumables			1012230
796	06/07/2018	743403	Service	Finished off VSI		1011897
796	06/07/2018	744047	Consumables			1012111
796	06/07/2018	744149	Consumables			1012111

796	06/07/2018	744149	Mechanic entered - Elec and Light	Interior Lights lights abo	replaced saloon fluro globes above driver	1011897
796	06/07/2018	744047	Drv entered - Elec and Light	Indicators Not self cancelling	Replaced indicator stalk.	1011897
796	06/07/2018	744150	Mechanic entered - Body	Other n/s/m seat	Drill out broken bolt. from seat . remove seat to use bus. need M10 tap to cut thred in fioor.	1011897
796	06/06/2018	743851	Consumables			1011897
796	06/06/2018	743851	Mechanic entered - Wheels and Tyres	Wheel Nut Retension rete	retension n/s/r wheel nuts	1011675
796	06/06/2018	743851	Mechanic entered - Wheels and Tyres	Wheel Nut Retension rete	retension n/s/r wheel nuts	1011675
796	06/06/2018	743597	PERFORM CAMPAIGN 07/18 RPD DASH MOUNTED OVERRIDE SWITCH INS		completed wiring	1011675
796	06/05/2018	743403			TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1011448
796	06/05/2018	743403			VEHICLE SAFETY INSPECTION	1011448
796	06/05/2018	743547	Consumables			1011675
796	06/05/2018	743547	TYRE 295/80R22.5 RECAP			1011448
796	06/05/2018	743547	Mechanic entered - Wheels and Tyres	Worn n/s/r outer 3mm	fitted tyre on N/S/R/O with 6 mm on it.	1011448
796	05/29/2018	741908	PERFORM CAMPAIGN 15/18 A3 POSTER CHANGE - MYKI AUTO TOP UP		COMPLETE	1010014
796	05/16/2018	738952	Consumables			1007714
796	05/16/2018	738952	Elec and Light	Interior Lights step lights N/W	replaced globe.	1007362
796	04/19/2018	733866	Consumables			1002612
796	04/19/2018	733866	Body	Indicators don't cancel.	Replaced faulty indicator stalk.	1002397
796	04/18/2018	733410	Drv entered - Vandalism	Vandalism/ Graffiti Interior	cleaned	1002218
796	04/18/2018	733410	Body	Chip in windscreen	checked ok until next service	1002218
796	04/18/2018	733410	Consumables			1002397
796	04/17/2018	733408	Consumables			1002218
796	04/17/2018	733408	Wheels and Tyres	Wheel Nut Retension O/S/R	complete with revian	1002218
796	04/17/2018	733411	Mechanic entered - Vandalism	Vandalism/ Graffiti Interior RO	FITTED NEW ROLL TOPS X3 REPAIRED ALL TORN SEATS FIXED BROKEN SEAT BASES PAINTED GRAFFITIT	1002218
796	04/17/2018	732036	Suspension O/S/F/U torque rod & O/S/R/L torque rod bushs wo		replaced both rods all checked ok then road tested all fine	1002218
796	04/17/2018	733409	Fluid Leaks	Wash and check transmission oil leaks.	Washed and check ok at this stage	1002218
796	04/17/2018	733410	Body-	panel above front passenger door needs tightening very	secured all ok	1002218
796	04/17/2018	732036	Air System	accumalator valve leaking	no fault found all ok	1002218
796	04/16/2018	733004	Consumables			1002218
796	04/16/2018	733004	Elec and Light	Interior Lights 2nd last saloon LED light	Checked fuse and switch ok. Drilled ceiling rivets and checked lamp ok Checked wiring found plug disconnected. Connected plug checked and tested saloon light work ok.	1002054
796	04/11/2018	732036	Direct Purchase - MECHANICAL		Creditor #:IB-MUL001 MULTISPARES LTD P/O #:V217564 Receiving #:224880 Date :2018-04-11 40y0909 torque rod lower rear	1001745
796	04/11/2018	732036	Direct Purchase - MECHANICAL		Creditor #:IB-MUL001 MULTISPARES LTD P/O #:V217564 Receiving #:224878 Date :2018-04-11 40y0917zf torque rod front upper	1001745
796	04/10/2018	731862			Assisting	1001745
796	04/10/2018	731862			TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1001745
796	04/10/2018	731862			VEHICLE SAFETY INSPECTION	1001745
796	04/10/2018	732038	Consumables			1001745
796	04/10/2018	731974	Consumables			1001745
796	04/10/2018	732038	TYRE 295/80R22.5 RECAP			1001745
796	04/10/2018	732038	Wheels and Tyres	Flat or Leaking O/S/R/I flat.	Replaced O/S/R tyres	1001745
796	04/10/2018	731974	TYRE 295/80R22.5 RECAP			1001745
796	04/10/2018	731974	Mechanic entered - Wheels and Tyres	Worn o/s/r	replaced o/s rear tyres.	1001745
796	04/10/2018	732036	Suspension O/S/F/U torque rod & O/S/R/L torque rod bushs w		PARTS IN BUS FOR REPAIRS	1001745
796	04/10/2018	732036	Air System accumalator valve leaking			1001745
796	04/04/2018	730694	PERFORM CAMPAIGN 06/18 REPLACEMENT OF NO ACCESS / PARK BRAK		CAMPAIGN CARRIED OUT	1000532
796	03/22/2018	728430	Body-	front screen/blind will not stay down	checekd all ok	998423
796	03/20/2018	727749	Consumables			998177
796	03/20/2018	727749	Mechanic entered - Elec and Light	Exterior Lights right hand	fixed front head light pannel and replaced globe.	997907
796	03/07/2018	725221	Please remove any old poster and fit new ones multi choice		COMPLETE	995957
796	03/02/2018	723434	DIRECT PURCHASE - MECHANICAL G		Creditor #:VB-WES001 WESTY P/O #:K214850 Receiving #:222188 Date :2018-03-02 FUEL TANK BRACKETS--STEEL	994990
796	03/01/2018	723782			TRANSMISSION CHECK AS PER CHECK LIST	994990
796	03/01/2018	723434	Body Fuel tank bracket cracked.		repaired fuel tank brackets refitted and refitted fuel tank	994990
796	03/01/2018	723782	Consumables			994990
796	03/01/2018	723782	Consumables			994990
796	03/01/2018	723782	Consumables			994990
796	03/01/2018	723782			CARRY OUT A SERVICE AS PER CHECK LIST	994990
796	02/28/2018	723434	Body Fuel tank bracket cracked.		removed tank and brackets	994990
796	02/28/2018	720502	Direct Purchase - BODYWORK		Creditor #:IB-EAS003 EASTCOAST TRUCK & BUS SERVICE P/O #:V214075 Receiving #:222082 Date :2018-03-01 Carry out accident repair to mirror.	994990
796	02/21/2018	721350	Mechanic entered - Body	Drivers Seat Controls No air to driv	removed and replaced drivers seat.second hand seat.	993693
796	02/21/2018	719640	Service		new external door button fitted.	993693
796	02/16/2018	720625	Vandalism	Vandalism/ Graffiti Interior roll top damage	Checked and only minor- Will monitor	992829
796	02/16/2018	720398	Mechanic entered - Air System	Air_Leak Doors	replaced air vale at front door.	992829
796	02/16/2018	720502	Accident#:46833 - Ops Entered - Accident - Bus Hitting Obje		Mobile mick carried out repairs.	992829
796	02/14/2018	719640	CLIPPARD VALVE DOOR OPEN/CLOSE		Creditor #:IB-SMC001 SMC PNEUMATICS (AUST) PTY LTD P/O #:V213768 Receiving #:221080 Date :2018-02-15	992542
796	02/14/2018	719640	Mechanic entered - Body	Other Air leak at front door extern	Ordered new external door button.	992185
796	02/13/2018	719452	Body seat mounting /spacing n/s 5th last passenger seat loo		Refer to w/o #707774	991934
796	02/07/2018	717863	Steering - Noise when turning on full lock		Checked ok	990980
796	02/07/2018	717863	Consumables			991255
796	02/07/2018	717991	Consumables			991255
796	02/07/2018	717991	Elec and Light	Next Stop Buttons not working	checked ok.	990980
796	02/07/2018	717863	Ops Entered - Fault - Elec and Light	Next Stop Button in di	Checked ok	990980
796	02/07/2018	717863	Ops Entered - Fault - Elec and Light	Next Stop Button in di	Checked ok	990980
796	02/07/2018	717863	Drv entered - Elec and Light	Next Stop Button	Checked ok	990980
796	02/07/2018	717863	Drv entered - Elec and Light	Next Stop Button	Checked ok	990980
796	02/07/2018	717863	Ops Entered - Fault - Elec and Light	Next Stop Button - Ro	Checked ok	990980
796	02/07/2018	717863	Air System	Accumulator solenoid valve leaking.	Checked not leaking	990980
796	02/07/2018	718146	Perform Campaign 27/17 Positioning of 2018 PTV Fares Decals		COMPLETE	990980
796	02/06/2018	717611			Assisting	990778
796	02/06/2018	717611			TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	990778
796	02/06/2018	717611			VEHICLE SAFETY INSPECTION	990778
796	01/27/2018	715720	Mechanic entered - Air System	Air_Leak Front Air leaking fro	Traced air leak & repair damaged pipe	989214
796	01/08/2018	712149			SERVICE MOISTURE EJECTOR	984158
796	01/08/2018	712149			CARRY OUT TUNE-UP SERVICE AS PER CHECK LIST done	984158
796	01/08/2018	712073	Mechanic entered - Engine	Other flat batts.	jump start.	984158
796	01/08/2018	712149	Consumables			985076
796	01/08/2018	712149	Consumables			985076
796	01/08/2018	712149	Consumables			985076
796	01/08/2018	712149			CARRY OUT B SERVICE AS PER CHECK LIST done	984158
796	01/08/2018	712149	FILTER FUEL FILTER ETHANOL SCANIA SR4 (H17WK04)			984158
796	01/08/2018	712149	FILTER OIL SCANIA SR4 [EARLY] K320 (LF3730) (H200W20)			984158
796	01/08/2018	712149	O-RING LARGE SPINNER FILTER SCANIA (1769799)			984158
796	01/08/2018	712149	O-RING SPINNER FILTER SCANIA (1769798)			984158
796	01/08/2018	712149	FILTER TRANSMISSION ZF (4139-298-038) (4139 298 038 01)			984158
796	01/08/2018	712149	Consumables			985076
796	01/08/2018	712149	Consumables			985076

796	01/08/2018	712149	Consumables			985076
796	01/08/2018	712149		CARRY OUT A SERVICE AS PER CHECK LIST		984158
796	01/04/2018	708387	DIRECT PURCHASE - BUS INSPECTI	Creditor #:VB-ROA002 ROAD SAFETY INSPECTIONS P/O #:K209820 Receiving #:217805 Date :2018-01-04		984158
796	01/04/2018	711469	Elec and Light Next Stop Button n/w	checked operation of all passenger buttons . checked could not fault		984158
796	12/29/2017	710640	Mechanic entered - Engine Other Mount cracked REFER RSI DEF	replaced both front engine mounts		983445
796	12/22/2017	705457	Service	GARY FROM COLD DRIVE CARRY OUT REPAIRS		983139
796	12/20/2017	705457	PUMP BOOST PUMP COACH 90 Ltr			982415
796	12/18/2017	705457	Drv entered - Fluid Leaks Rear of bus	Leaking from boost pump waiting on parts. Topped up coolant and washedoff area.		980912
796	12/15/2017	708387		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		980912
796	12/15/2017	708387		VEHICLE SAFETY INSPECTION		980912
796	12/15/2017	708387		CARRY OUT ASI/VSI AS PER RELEVANT CHECK LIST		980912
796	12/15/2017	708387		ANNUAL SAFETY INSPECTION SERIAL # RSI 010250		980912
796	12/15/2017	708459		PRE ANNUAL SAFETY INSPECTION CHECK		980912
796	12/15/2017	705457	Mechanic entered - Suspension Soft V rod bush worn			980912
796	12/15/2017	708445	Mechanic entered - Suspension Noisy Front D rubbers failed i	Replaced front D rubbers		980912
796	12/15/2017	705457	Direct Purchase - MECHANICAL	Creditor #:IB-MUL001 MULTISPARES LTD P/O #:V209704 Receiving #:216929 Date :2017-12-19 40y3408		981629
796	12/15/2017	705457	Direct Purchase - MECHANICAL	Creditor #:IB-MUL001 MULTISPARES LTD P/O #:V209704 Receiving #:216929 Date :2017-12-19 40Y3105		981629
796	12/15/2017	705457	Consumables			981381
796	12/15/2017	705457	Elec and Light Pad wear light on dash - electrical fault.			980912
796	12/13/2017	707774	Body - Passenger seat base loose	removed seat replaced mounts and refitted seat.		980502
796	12/13/2017	707774	Consumables			980912
796	12/06/2017	706256	Mechanic entered - Elec and Light Next Stop Button Wheelchar	Removed side panel and found wiring rubbing on chassis repaired wiring removed edge to stop further rubbing.		979031
796	12/06/2017	706256	Consumables			979673
796	12/01/2017	705457	A/C Heating Boost pump leaking N/S/R	turned heater taps off. orded parts		977612
796	11/30/2017	705154	Drv entered - Elec and Light Indicators Not Working	indicator self cancelling not working.		977612
796	11/15/2017	701737	A/C Heating Not Heating	Checked ok garry cold drive.		975328
796	11/06/2017	699864		VEHICLE SAFETY INSPECTION		973277
796	11/06/2017	699864		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		973277
796	11/06/2017	699864	Consumables			974048
796	11/06/2017	699864	Consumables			974048
796	11/06/2017	699864	Consumables			974048
796	11/06/2017	699864	Consumables			974048
796	11/06/2017	699864	Consumables			974048
796	11/06/2017	699864		CARRY OUT A SERVICE AS PER CHECK LIST		973277
796	11/02/2017	699022	Consumables			973508
796	11/02/2017	699022	Drv entered - Elec and Light Indicators Not Working	replaced globe.faulty wiring on pax button on wheel chair area.		973277
796	11/02/2017	699022	Drv entered - Elec and Light Next Stop Button			973277
796	11/02/2017	699147	Please remove the 2 x Do Not Enter decals at the exterio	completed		973277
796	11/02/2017	699134	Remove old poster and fit new A3 Posters and hangers	completed		973277
796	11/01/2017	698836	PERFORM 19/17 DOOR BRAKE INTERLOCK FITMENT AUDIT	COMPLETED		972969
796	10/24/2017	696472	Drv entered - Elec and Light Indicators Not Working	Checked all indicators for operation and self cancelling. ok.		970995
796	10/21/2017	694263	Mechanic entered - Body Other Next stop buttons that activat	all checked ok		970428
796	10/16/2017	694263	Mechanic entered - Body Other Next stop buttons that activat	wheel chair next stop disconnected.needs to check wiring.bus was due on road.		968925
796	10/13/2017	694063	FIT ANTI GRAFFITI/SAFETY FILM			968434
796	10/13/2017	694063	DIRECT PURCHASE - GLASS	Creditor #:IB-GLA010 GLASSPROTECH MELBOURNE P/O #:V204700 Receiving #:211945 Date :2017-10-13		968434
796	10/06/2017	692037	Mechanic entered - Elec and Light Exterior Lights left headl	Replaced blown head light globe.		967078
796	09/30/2017	690672		CARRY OUT FIRE EXTINGUISHER TEST & TAG		966182
796	09/30/2017	690672		APPLIANCE TAGGING CARRY OUT INSPECTION		966182
796	09/25/2017	689008	PERFORM CAMPAIGN 09/17 REAR DOOR WARNING SIGNS	COMPLETE		965133
796	09/25/2017	689067	Remove old A3 Posters with Seniors Festival please leave	COMPLETE		965133
796	09/22/2017	688249	Consumables			965133
796	09/22/2017	688249	Elec and Light - Bus not starting from ignition	Checked bus starting. Checked 10 times and started every time from they key.		964542
796	09/22/2017	688249	Consumables			965133
796	09/20/2017	687905	Breakdown#:33771 - Ops Entered - Breakdown - Breakdown Road	Go to Chirnside Park. Bus will not start. Checked batts 25v. Ok. Start bus from rear & checked charge rate. 27.2v Ok. Bus continued in service.		964306
796	09/19/2017	687426		carried out safety inspection.		963691
796	09/19/2017	687426		VEHICLE SAFETY INSPECTION		963691
796	09/18/2017	687011	Consumables			964124
796	09/18/2017	687011	Mechanic entered - Elec and Light Exterior Lights top r/h f	Replace OSFU park light & 3 saloon light fluros		963691
796	09/18/2017	687011	Consumables			964124
796	09/16/2017	686926	Wheels and Tyres rear axle wheel nut retenion	retension rear wheels.o/s and n/s		963691
796	09/16/2017	686927	Warning Lights Brakes warning light	inspected brake warning lights.no warning lights lights appears on dash.		963691
796	09/15/2017	685016	Consumables			963691
796	09/15/2017	685016	Consumables			963691
796	09/15/2017	685016	Consumables			963691
796	09/15/2017	685016	FILTER FUEL FILTER ETHANOL SCANIA SR4 (H17WK04)			963341
796	09/15/2017	685016	Consumables			963691
796	09/15/2017	685016	Consumables			963691
796	09/15/2017	685016	Consumables			963691
796	09/08/2017	684576	Mechanic entered - Brakes Warning Light On	Checked wiring at the back found OK checked wiring on the N/S front from inside by bypassing the whole wiring and found OK. O/S/F needs checking.		961694
796	09/07/2017	685016		TRANSMISSION CHECK AS PER CHECK LIST		961694
796	09/07/2017	685122	Mechanic entered - Wheels and Tyres Wheel Nut Retension All	Completed retension.		961694
796	09/07/2017	684576	HARNESS LOW PAD WIRING REAR	Creditor #:IB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:V202259 Receiving #:209761 Date :2017-09-13		962078
796	09/07/2017	685016	FILTER TRANSMISSION ZF (4139-298-038) (4139 298 038 01)			961694
796	09/07/2017	685016	FILTER FUEL FILTER ETHANOL SCANIA SR4 (H17WK04)			961694
796	09/07/2017	685016	KIT O-RING OIL SPINNER FILTER SCANIA ABOVE ENG #6203050			961694
796	09/07/2017	685016	FILTER OIL SCANIA SR4 [EARLY] K320 (LF3730) (H200W20)			961694
796	09/07/2017	685016		CARRY OUT B SERVICE AS PER CHECK LIST Completed service		961694
796	09/07/2017	685016	Consumables			962078
796	09/07/2017	685016	Consumables			962078
796	09/07/2017	685016	Consumables			962078
796	09/07/2017	685016		CARRY OUT A SERVICE AS PER CHECK LIST		961694
796	09/07/2017	685016	Consumables			962078
796	09/07/2017	685016	Consumables			962078
796	09/07/2017	685016	Consumables			962078
796	09/05/2017	684576	WEAR SENSOR SCANIA DISC BRAKE 49G8410			961608
796	09/05/2017	684576	SET DISC PAD SET SCANIA / MERCEDES 0500			961608
796	09/05/2017	684576	Mechanic entered - Brakes Warning Light On	Found that N/S/R pads were worn Replaced all rear pads and sensors. Found that N/S/R harness was also faulty no part in stock. Have ordered. Put wheels back on and tensioned. Road tested brake tested and checked temps. Serviceable.		961608
796	09/04/2017	684323	Consumables			961608
796	09/04/2017	684323	Consumables			961608
796	09/04/2017	684323	Mechanic entered - Elec and Light Exterior Lights o/s high b	replaced globe ok		961362
796	08/25/2017	682350	Consumables			959880
796	08/25/2017	682350	SWITCH INDICATOR SCANIA (L94UAB) (40V4703)			959547
796	08/25/2017	682350	INDICATOR STALK SCANIA SERIES 4 (1402448)			959547

796	08/24/2017	682350	Ops Entered - Fault - Elec and Light Next Stop Button - Ro	check next stop operation fit new globe to stopping sign and remove rags from bell assembly test ok		959547
796	08/24/2017	682350	Elec and Light. blinkers dont self cancel and dont make a n	check indicator and switch operation fit new indicator switch and space out for correct self cancel operation test ok		959547
796	08/24/2017	682350	INDICATOR STALK SCANIA SERIES 4 (1402448)			959547
796	08/24/2017	682463	Consumables			959547
796	08/24/2017	682463	Ops Entered - Fault - Body Drivers Seat not raising	Test seat. (Does not lift to full height & several swiches & controls damaged) Fitted C/O seat & Test OK		959547
796	08/21/2017	681313	Consumables			958996
796	08/21/2017	681313	Wheels and Tyres Wheel Nut Retension Front Axle	Retensioned both front wheels @ 958832 kms		958749
796	08/21/2017	681140	TYRE 295/80R22.5 NEW			958749
796	08/19/2017	681140	TYRE 295/80R22.5 NEW			958749
796	08/19/2017	681140	Drv entered - Steering Pulling	Replaced both front tyres using new steer tyres & painted rims road tested & checked for pulling OK at this time		958749
796	08/19/2017	681140	Drv entered - Steering Pulling	done road test.slightly pullying to L/H side need to change the tyre .o/s/f tyre not even		958749
796	08/19/2017	681134	Consumables			958749
796	08/19/2017	681134	Drv entered - Elec and Light Indicators Not Working	repair indicator wiring		958749
796	08/10/2017	679263	Consumables			957077
796	08/10/2017	679263	Wheels and Tyres Wheel Nut Retension N/S/R	Retension N/S/R wheels @ 956914 kms		956841
796	08/10/2017	679381	Please remove old posters and fit new one along with hangers	Remove replace		956841
796	08/08/2017	678359	Consumables			956657
796	08/08/2017	678359	TYRE 295/80R22.5 RECAP	Creditor #:IB-TYR002 TYRES4U P/O #:V199680 Receiving #:206793 Date :2017-08-08		956361
796	08/07/2017	678359	TYRE 295/80R22.5 RECAP			956142
796	08/05/2017	678359	Wheels and Tyres Worn n/s/r/i tread low	Replaced both N/S/R tyres using new caps		956142
796	08/05/2017	678359	TYRE 295/80R22.5 RECAP			956142
796	08/01/2017	609436	ELECTRICAL REPAIR	Creditor #:IB-BWE001 BWERE ELECTRICS PTY LTD P/O #:V199648 Receiving #:206813 Date :2017-08-08		956361
796	07/31/2017	677218	PERFORM CAMPAIGN 17/16 DASH SWITCH LABELLING	Labels and switch inserts installed as required.		954669
796	07/28/2017	676675		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS wheel nut retensions done		954243
796	07/28/2017	676675		VEHICLE SAFETY INSPECTION safety done		954243
796	07/28/2017	676765	Mechanic entered - Gearbox Driveline Other Output shaft sea	not excessive at this time		954243
796	07/28/2017	676765	Fluid Leaks (None) No fluid in sight glass	topped up all ok		954243
796	07/28/2017	676765	Consumables			954439
796	07/28/2017	676765	Drv entered - Elec and Light Next Stop Button	checked all ok		954243
796	07/28/2017	676675	Consumables			954439
796	07/28/2017	676675	Consumables			954439
796	07/28/2017	676675		CARRY OUT A SERVICE AS PER CHECK LIST a service done		954243
796	07/26/2017	675567	Consumables			954067
796	07/26/2017	675567	Mechanic entered - Elec and Light Flat Batteries	Load tested and replaced batteries.		953897
796	07/26/2017	675567	BATTERY 800CCA			953897
796	07/22/2017	675567	Mechanic entered - Elec and Light Flat Batteries	Checked batts 23.5v. Crank's very slowly. Jump start bus. Checked charge rate.27.5v. Fitted date 2014		953018
796	07/14/2017	673836	Consumables			951703
796	07/14/2017	673836	Consumables			951703
796	07/14/2017	673836	Remove old Green 2016/17 registration Label and/ or Blue EF	ok		951098
796	07/14/2017	673727	PERFORM CAMPAIGN 05/17 BUS DESTINATION PROGRAM UPDATE	ok		951098
796	07/12/2017	673294	Breakdown#:33529 - Ops Entered - Breakdown - Breakdown Road	SOUTHEN BREAK DOWN VAN SENT TO INVESTIGATE JUMP START BUS		950518
796	07/05/2017	672141	Consumables			949781
796	07/05/2017	672141	LAMP FLUORESCENT TUBE 18W			949519
796	07/05/2017	672141	Mechanic entered - Elec and Light Exterior Lights both door	replace and fit 2 new globes REPLACED BY DAMIAN		949519
796	06/27/2017	670176	FIT ANTI GRAFFITI/ SAFETY FILM			947136
796	06/20/2017	670176	DIRECT PURCHASE - VANDALISM	Creditor #:IB-GLA010 GLASSPROTECH MELBOURNE P/O #:V195696 Receiving #:203423 Date :2017-06-27 FIT ANTI GRAFFITI/ SAFETY FILM		947136
796	06/15/2017	667566	A/C Heating Belt Loose or_Missing a/c compressor cooked	COLD DRIVE CARRY OUT REPAIRS		945183
796	06/15/2017	667566	HEATER-DEMISTER VALVE TAP MERC 0500 (DHV4008)			945183
796	06/15/2017	667566	RECIEVER DRYER CARRIER CM7			945183
796	06/15/2017	667566	MOTOR CONDENSOR FAN AC353			945183
796	06/15/2017	667566	AIR CONDITIONING REPAIR	Creditor #:IB-COL004 COLD DRIVE PTY LTD P/O #:V196667 Receiving #:203863 Date :2017-06-30 A SERVICE NEW RETURN AIR FILTER REPAIRED WIRING TO UNLOADER		948636
796	06/15/2017	667566		CARRY OUT A/C - A SERVICE AS PER CHECK LIST		945183
796	06/13/2017	666919	Consumables			945183
796	06/13/2017	666919	Mechanic entered - Elec and Light Flat Batteries	Jump start bus		944619
796	06/08/2017	666370				944195
796	06/08/2017	666370		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		944195
796	06/08/2017	666370		VEHICLE SAFETY INSPECTION		944195
796	06/08/2017	666370		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		944195
796	06/08/2017	666370		VEHICLE SAFETY INSPECTION		944195
796	06/08/2017	666473	Consumables			944619
796	06/08/2017	666473	Mechanic entered - Dash Switches Not Working	replaced GLOBES		944195
796	06/07/2017	666217	A/C Heating (None) Water leaking down the inside of the O	GARY FROM COLD DRIVE CARRY OUT CHECK OVER		944195
796	06/05/2017	665641	Consumables			943952
796	06/05/2017	665641	Mechanic entered - Elec and Light Flat Batteries	Jump start bus		943473
796	06/01/2017	664845	Consumables			943473
796	06/01/2017	664845	Consumables			943473
796	06/01/2017	664845	Direct Purchase - BODYWORK	Creditor #:IB-SMC001 SMC PNEUMATICS AUST P/L P/O #:V194991 Receiving #:201971 Date :2017-06-02 CARRY OUT REPAIRS TO DOORS		943297
796	05/31/2017	664856	Body - OS passenger seat bolt broken 3rd row	Remove broken bolt & secure seat		942952
796	05/31/2017	664845	Body emergency exit button not working	Checked emergency exit switches. OK		942952
796	05/31/2017	664844	Body (None) engin hatch struts needs replacing side struts	Fitted new struts		942952
796	05/31/2017	664842	STRUT GAS STAY 350Nm 430mm LONG			942952
796	05/31/2017	664842	STRUT GAS STAY 500Nm 502mm LONG			942952
796	05/31/2017	664842	Mechanic entered - Body Other strut missing off hatch	Replaced struts		942952
796	05/31/2017	664814	Body - Wheel chair ramp brake n/w	Checked ramp operation. OK.		942952
796	05/31/2017	664845	Consumables			943297
796	05/31/2017	664845	Consumables			943297
796	05/31/2017	664844	Consumables			943297
796	05/31/2017	664844	Consumables			943297
796	05/31/2017	664842	Consumables			943297
796	05/31/2017	664842	Consumables			943297
796	05/31/2017	664814	Consumables			943297
796	05/31/2017	664814	Consumables			943297
796	05/31/2017	664856	Consumables			943297
796	05/31/2017	664856	Consumables			943297
796	05/31/2017	664811	Brakes - Door brakes n/w front & rear	CHecked door brake operation OK		942952
796	05/25/2017	663503	Drv entered - Wipers and Washers Wipers Noisy	Checked OK. Only noise is the normal cluncking of the wiper linkages under the dash.		941144
796	05/16/2017	661575	Fit A3 Poster/Hangers	Completed		938996
796	05/16/2017	661575	Consumables			940564
796	05/13/2017	661032	Body - Paint metal beneath BDC to limit sun reflection	painted myki area all ok do not drive saturday		938996
796	05/13/2017	661032	Consumables			940076
796	05/13/2017	661032	Consumables			940076
796	05/12/2017	660665	REVERSE ALARM 12-24v 72608			938996
796	05/12/2017	660665				938996

796	05/12/2017	660665	Consumables		940076
796	05/12/2017	660665	Consumables		940076
796	05/12/2017	660665	Consumables		940076
796	05/11/2017	660665		CARRY OUT C SERVICE AS PER CHECK LIST c service nearly done diff oil mdone c service done and replaced reversre beeper as required	938996
796	05/11/2017	660665		CARRY OUT B SERVICE AS PER CHECK LIST b service done	938996
796	05/11/2017	660665	Consumables		939900
796	05/11/2017	660665	Consumables		939900
796	05/11/2017	660665	Consumables		939900
796	05/11/2017	660665		CARRY OUT A SERVICE AS PER CHECK LIST a service done	938996
796	05/11/2017	660665	FILTER AIR FILTER OUTER SCANIA SR3 SR4 AF2506		938996
796	05/11/2017	660665	Consumables		939900
796	05/11/2017	660665	Consumables		939900
796	05/11/2017	660665	Consumables		939900
796	05/01/2017	637819	Consumables		937868
796	05/01/2017	637819	ELECTRICAL REPAIR	Creditor #:IB-BWE001 BWERE ELECTRICS PTY LTD P/O #:V193652 Receiving #:200505 Date :2017-05-16 Supply and fit RPD	940076
796	04/13/2017	656332	Consumables		935153
796	04/13/2017	656332	Mechanic entered - Elec and Light Flat Batteries	jump started.	935111
796	04/07/2017	655360		Assisting	935111
796	04/07/2017	655360		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	935111
796	04/07/2017	655360		VEHICLE SAFETY INSPECTION	935111
796	03/20/2017	651886	Elec and Light Exterior Lights head lights pointing wrong	Headlights pointing correct direction. No fault found	930408
796	03/16/2017	651225	REGULATOR BOSCH 140AMP 1197311315 (VR3014G)		929708
796	03/16/2017	651225	Breakdown#:33270 - Ops Entered - Breakdown - Breakdown Road	Trace fault with alt light on. Replaced faulty alt brush pack. Test. OK. charging 27.5v	929708
796	03/11/2017	650526	Consumables		929445
796	03/11/2017	650526	Consumables		929445
796	03/11/2017	650526	Body Front_Door Operation Faulty buttuns under front bumpe	door buttons under bumper test ok. No fault found	928887
796	03/10/2017	650291	Elec and Light Exterior Lights o/s top park light in desto	Fit new park light globe	928887
796	03/10/2017	650291	GLOBE 24V 5W BAYONET (17181)		928887
796	02/22/2017	644769	Consumables		926312
796	02/22/2017	644769	Consumables		926312
796	02/22/2017	644769	STRUT GAS STAY 500Nm 330mm LONG VOLGREN (17201)		924911
796	02/22/2017	646862	Please remove any old poster and fit either Good News for T	Completed Campaign	924911
796	02/21/2017	644769	Bolts	Creditor #:IB-BEA001 BEARING WHOLESALERS P/O #:V188002 Receiving #:195326 Date :2017-03-03	927231
796	02/21/2017	644769	Suspension (None) n/s/f shocker loose	secured	924911
796	02/21/2017	644769	steering	Replaced drag link	924911
796	02/21/2017	646322	GLOBE 24V 21/5W STOP/TAIL		924911
796	02/21/2017	646322	Elec and Light Exterior Lights - o/s/f/ indicator n/w	replace globe	924911
796	02/21/2017	644769	Mechanic entered - Body Other Battery hatch gas struts are	replaced struts	924911
796	02/21/2017	644769	Body (None) emergency exit advertising decal not cut cor	cut decals	924911
796	02/21/2017	644769	Mechanic entered - Body Rear_Door Operation Faulty Rear doo	adjusted	924911
796	02/17/2017	645242		TRANSMISSION CHECK AS PER CHECK LIST	924911
796	02/17/2017	645242		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	924911
796	02/17/2017	645242		VEHICLE SAFETY INSPECTION	924911
796	02/17/2017	644769	Mechanic entered - Wipers and Washers Wipers Not_Clearing S	Replaced inserts	924911
796	02/17/2017	645242	Direct Purchase - MECHANICAL	Creditor #:IB-MUL001 MULTISPARES LIMITED P/O #:V187805 Receiving #:194310 Date :2017-02-20 40L2217ZF	925735
796	02/17/2017	644769	Steering Excessive Play Mechanic entered - Steering Exces		924911
796	02/17/2017	645242	Mechanic entered - Steering Excessive Play Drag link rear ba	Ordered parts	924911
796	02/17/2017	645756	Engine (None) secure radiator to header hose top of radiat	Secured	924911
796	02/17/2017	644769	Elec and Light Exterior Lights - N/S Headlight dull	Replaced headlight assembly	924911
796	02/17/2017	644769	H1 LOW BEAM 100MM	Creditor #:IB-MUL001 MULTISPARES LIMITED P/O #:V187743 Receiving #:194171 Date :2017-02-17	925098
796	02/17/2017	645751	Consumables		925921
796	02/17/2017	645751	Consumables		925921
796	02/17/2017	644769	Body (None) secure perimeter seat hinge at wall		924911
796	02/17/2017	645751	Body (None) secure n/s/f wheel arch guard	Refitted wheel arch brush	924911
796	02/17/2017	645242	Consumables		925921
796	02/17/2017	645242	Consumables		925921
796	02/17/2017	645242	Consumables		925921
796	02/17/2017	645242		CARRY OUT A SERVICE AS PER CHECK LIST	924911
796	02/17/2017	645242	IDLER PULLEY SCANIA ARTIC (No Groove Plastic)		924911
796	02/16/2017	645234	PERFORM CAMPAIGN 01/17 SMARTRAK DRIVER CONTROL CONSOLE AUDIT	Performed Audit	924911
796	02/15/2017	644769	Elec and Light Exterior Lights - N/S Headlight dull	New headlight ordered	924911
796	02/08/2017	632974	DIRECT PURCHASE - VANDALISM	Creditor #:IB-TRI001 TRIM IMPROVEMENTS P/O #:V183454 Receiving #:194358 Date :2017-02-21	925735
796	02/07/2017	643240	Fit New 2107 Large and Small Fares Small Concessionand AO	Fit new decals	923610
796	02/01/2017	632974	DIRECT PURCHASE - VANDALISM	Creditor #:IB-TRI001 TRIM IMPROVEMENTS P/O #:V183454 Receiving #:194361 Date :2017-02-21 REPAIR RECOVER SEATS AS REQUIRED	925735
796	01/31/2017	641849	A3 POSTER CHANGE X 4 ENDING JAN 2017 PLEASE SEE CAMPAIGN A	Replaced posters	921539
796	01/24/2017	640604	Consumables		920970
796	01/24/2017	640604	Elec and Light Interior Lights some saloon lights not work	Got all saloon lights working	920732
796	01/23/2017	639987	Direct Purchase - BODYWORK	Creditor #:IB-A1W001 A-1 Windscreens P/O #:V186036 Receiving #:192484 Date :2017-01-30 SUPPLY AND FIT NEW DOOR GLASS	921539
796	01/20/2017	638931	Consumables		920558
796	01/20/2017	638931	GLOBE 24V 70W H1		919394
796	01/20/2017	638931	Mechanic entered - Elec and Light Exterior Lights N/S low be	remove and replace N/S low beam globe.	919394
796	01/20/2017	638931	Consumables		920558
796	01/20/2017	638931	Consumables		920558
796	01/20/2017	638931	Body Front_Door Operation Faulty	Checked OK at this time	919394
796	01/20/2017	639987	MIRROR L/H 380mm SHORT BM01		919394
796	01/20/2017	639987	ARM MIRROR N/S ARTIC UES 2066900		919394
796	01/20/2017	639987	Accident#:44842 - Ops Entered - Accident - Bus Hitting Objec	replace broken arm and mirror wipe and clean all up	919394
796	01/14/2017	638931	Body Front_Door Operation Faulty	inspect door operation system switch circuits N/W due to active door alarm activated	915744
796	01/11/2017	638195	Consumables		918774
796	01/11/2017	638195	GLOBE 24V 70W H1		915744
796	01/11/2017	638195	HEAD LAMP INSERT HELLA 100MM L/FLOOR 0500 29204		915744
796	01/11/2017	638195	Mechanic entered - Elec and Light Exterior Lights OS head li	Replaced O/S head light & globe	915744
796	01/09/2017	637819	PERFORM CAMPAIGN 08/16 BUS ROLLAWAY PREVENTION DEVICE (RPD)	BEN WERE ELEC PERFORM CAMPAIGN 08/16 BUS ROLLAWAY PREVENTION DEVICE (RPD)RETROFIT	915744
796	01/09/2017	637819	Consumables		918161
796	01/05/2017	636920	WIPER REFILL 1mt MULTI FIT		915744
796	01/05/2017	636920	Wipers and Washers Wipers Not Clearing Screen o/s wiper in	replaced wiper insert and check linkages reposition wiper arm	915744
796	01/05/2017	636920	AIR CONDITIONING REPAIR	Creditor #:IB-COL004 COLD DRIVE PTY LTD P/O #:V185220 Receiving #:191853 Date :2017-01-18 repaired broken wiring to compressor	919394
796	01/05/2017	636920	A/C Heating Not Cooling	GARY FROM COLDDRIVE CARRY OUT REPAIRS	915744
796	01/05/2017	636920	A/C Heating Not Cooling	GARY FROM COLDDRIVE CARRY OUT REPAIRS	915744
796	01/05/2017	636920	A/C Heating Not Cooling	GARY FROM COLDDRIVE CARRY OUT REPAIRS	915744
796	12/28/2016	635169		Finished of saftey inspection door service and driver seat	915744
796	12/28/2016	635384	Consumables		915899
796	12/28/2016	635384	L.E.D.STOP+TAIL LIGHT		915744

796	12/28/2016	635384	GLOBE 24V1.2WWEDGE (HLW241.20)(47706)(SWFLED)(E-596FWLED)			915744
796	12/28/2016	635384	Mechanic entered - Elec and Light Exterior Lights stop/tail	Replaced blown switch globes and faulty o/s/l stop/tail LED light assem		915744
796	12/28/2016	635384	Consumables			915899
796	12/28/2016	635384	Consumables			915899
796	12/28/2016	635384	FILTER FUEL FILTER SCANIA SR4 (H17WK04)			915744
796	12/28/2016	635384	FILTER TRANSMISSION ZF (4139-298-038) (4139 298 038 01)			915744
796	12/28/2016	635384	FILTER OIL SCANIA SR4 [EARLY] K320 (LF3730) (H200W20)			915744
796	12/28/2016	635384	KIT O-RING OIL SPINNER FILTER SCANIA ABOVE ENG #6203050			915744
796	12/28/2016	635384		CARRY OUT B SERVICE AS PER CHECK LIST ok		915744
796	12/28/2016	635384	Consumables			915899
796	12/28/2016	635384	Consumables			915899
796	12/28/2016	635384		CARRY OUT A SERVICE AS PER CHECK LIST complete a plus b service		915744
796	12/24/2016	635169		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		915744
796	12/24/2016	635169		VEHICLE SAFETY INSPECTION		915744
796	12/17/2016	633969	Consumables			914801
796	12/17/2016	633969	Consumables			914801
796	12/17/2016	633969	Body (None) LIGHT COVER ABOVE DRIVER FALLEN OFF	refitted		914502
796	12/15/2016	633554		ANNUAL SAFETY INSPECTION SERIAL # RSI 006356		914280
796	12/15/2016	633661	Mechanic entered - Wipers and Washers Wipers Not Working WIP	Replaced refill		914280
796	12/15/2016	633661	HANDLE GRAB HANDLE PASSENGER			914280
796	12/15/2016	633661	ASSY WIPER BLADE ASSY 1000mm (TRP1000 is Refill)			914280
796	12/13/2016	632974	Vandalism Vandalism/ Graffiti Interior slashed seats	Ian Bristow carry out graffiti paint over		913772
796	12/13/2016	632974	Engine (None) wash and check oil leaks	wash3ed and checekd ok		913772
796	12/13/2016	632974	Consumables			914034
796	12/13/2016	632974	Consumables			914034
796	12/13/2016	632977	Direct Purchase - BODYWORK	Creditor #:IB-VOL001 VOLGREN AUSTRALIA P/O #:V183465 Receiving #:189963 Date :2016-12-19 28976		914801
796	12/13/2016	632977	Direct Purchase - BODYWORK	Creditor #:IB-VOL001 VOLGREN AUSTRALIA P/O #:V183465 Receiving #:189963 Date :2016-12-19 Coolant Door		914801
796	12/13/2016	633215	Body (None) rear bumper needs securing	secured rear bumper		913772
796	12/13/2016	632974	Body no drivers door to store wallett	fitted door back on put new hingue and latch on checekd ok		913772
796	12/13/2016	632974	Body (None) collant flap missing	fitted new coolant door		913772
796	12/13/2016	633215	Consumables			914034
796	12/13/2016	633215	Consumables			914034
796	12/13/2016	632977	Consumables			914034
796	12/13/2016	632977	Consumables			914034
796	12/12/2016	632793		PRE ANNUAL SAFETY INSPECTION CHECK carryout pre annual inspection checkover		913772
796	12/12/2016	632945	Consumables			914034
796	12/12/2016	632945	TYRE 295/80R22.5 RECAP			913772
796	12/12/2016	632945	Mechanic entered - Wheels and Tyres Damaged	fit 2 new recaps to o/s/r put 1 original into stock 12mm and send 1 damaged side wall tyre for repair / scrap		913772
796	12/12/2016	632976	Mechanic entered - Vandalism Vandalism/ Graffiti Interior	clean grafitti from rear seats		913772
796	12/12/2016	632974	Vandalism Vandalism/ Graffiti Interior slashed seats	sent away to be repaired		913772
796	12/12/2016	632976	Mechanic entered - Vandalism Vandalism/ Graffiti Interior	clean fresh grafitti from seat bases & wall trim ingrained grafitti still evident		913772
796	12/12/2016	632974	LAMP FLUORESCENT TUBE 18W			913772
796	12/12/2016	632974	BUSH SWAY BAR FRONT SCANIA SR4 & K230 0469081 1919010			913772
796	12/12/2016	632974	Mechanic entered - Suspension Noisy d rubbers worn saloon l	REPLACED ALL d rubbers replaced lights sent seats away to be repaired		913772
796	12/12/2016	632974	Engine (None) wash and check oil leaks	washed and checekd over leaks		913772
796	12/12/2016	632963	Consumables			914034
796	12/12/2016	629021	Consumables			914034
796	12/12/2016	629021	SENSOR BRAKE PAD (49G8411)			913772
796	12/12/2016	629021	Elec and Light Warning Light On Dash - Brake pad wear ligh	check brake pad sensor wiring on all wheels remove n/s/r wheels & replaced faulty sensor wiring test ok		913772
796	12/12/2016	632963	GLOBE 24V1.2WWEDGE (HLW241.20)(47706)(SWFLED)(E-596FWLED)			913772
796	12/12/2016	632963	Mechanic entered - Dash Dash_Lights Not Working	replaced faulty switch light globes and clean contacts test ok		913772
796	12/12/2016	632952	Consumables			914034
796	12/12/2016	632952	Consumables			914034
796	12/12/2016	632974	Body (None) collant flap missing	have ordered part 12/12//16		913772
796	12/12/2016	632974	Body (None)	ok		913772
796	12/12/2016	632974	Mechanic entered - Body Other	secure loose body panels & cut emergency exit advertising decal		913772
796	12/12/2016	632974	Body no drivers door to store wallett			913772
796	12/12/2016	632977	Mechanic entered - Body Other	top washer bottle & bleed windscreen washer lines test ok		913772
796	12/12/2016	632974	Mechanic entered - Body Other	cut emergency exit advertising decal and secure all loose body panels		913772
796	12/12/2016	632952	Mechanic entered - Body Other	remove damaged o/s/r seat and weld cracked mounting bracket repaint and fit test ok		913772
796	12/10/2016	632725	Consumables			914034
796	12/10/2016	632725	Wheels and Tyres Wheel Nut Retension front axle	retension wheel nuts on both front wheels		913772
796	12/05/2016	629021	Elec and Light Warning Light On Dash - Brake pad wear ligh	Try to trace fault in low pad circuit Remove front wheels & test pad sensors OK re-fit wheels.		912207
796	12/05/2016	629497	Ops Entered - Accident - - REAR - Route: 679 - Ringwood St	ECTB CARRY OUT REPAIRS ON REBRAND		912207
796	12/02/2016	629021	Elec and Light Warning Light On Dash - Brake pad wear lig	elec fault		912207
796	12/02/2016	629021	Warning Lights Brake pad ware	elec fault		912207
796	11/23/2016	629497	Warning Lights Brake pad orange elec fault	Bypassed n/s/f sensor. Fault still active. Needs further diagnosing ran out of time.		909857
796	11/23/2016	629452		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST Carried out fire safety inspection. Passed		909857
796	11/21/2016	629021	Warning Lights low Brake padware	elec fault		909857
796	11/19/2016	628795	Consumables			910156
796	11/19/2016	628795	Consumables			910156
796	11/19/2016	628795	Drv entered - Body Drivers Seat Leaning	Checked seat Base OK		909857
796	11/17/2016	628296	Consumables			909857
796	11/17/2016	628296	Campaign 14/16 Destination signs Setting and loadig Files.	Completed		909052
796	11/14/2016	625394	Consumables			909052
796	11/14/2016	625394	Consumables			909052
796	11/14/2016	625394	BRACKET MIRROR-LONG			906621
796	11/14/2016	625394	ARM MIRROR N/S ARTIC UES 2066900			906621
796	11/09/2016	626852	Fit A3 poster to holder either Explore Melbourne or PTV Ap	Replaced		907612
796	11/07/2016	626252	Consumables			907612
796	11/07/2016	626252	Consumables			907612
796	11/07/2016	626252	Door Latch	Creditor #:IB-VOL001 VOLGREN AUSTRALIA P/O #:V179363 Receiving #:187309 Date :2016-11-11 Bus 796		907862
796	11/07/2016	626252	Body (None) roof panels falling off light panels and ligh	repaired roof panel		907389
796	11/02/2016	625394	ARM MIRROR N/S ARTIC UES 2066900			906621
796	11/02/2016	625394	MIRROR LH 380MM SHORT BM01			906621
796	11/02/2016	625394	Body n/s mirror missing	remove mirror on N/S/F and braket fit new bolts and nuts.		906621
796	10/31/2016	625041		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		906621
796	10/31/2016	625041		VEHICLE SAFETY INSPECTION vehicle saftey done		906621
796	10/31/2016	625041	Consumables			906621
796	10/31/2016	625041	Consumables			906621
796	10/31/2016	625041	Consumables			906621
796	10/31/2016	625041		CARRY OUT A SERVICE AS PER CHECK LIST		906621
796	10/25/2016	623622	Wheels and Tyres Wheel Nut Retension front axle	retension front axle to 650nm		905369

796	10/24/2016	623604	Consumables			905544
796	10/24/2016	623604	Mechanic entered - Body Other N/S mirror damaged	Replaced smashed n/s mirror with second hand one. Tests ok		905369
796	10/21/2016	623116	Engine (None) wash and check trans and engine oil leals	wash eng/trans test drive inspect for leaks no leaks found		904844
796	10/21/2016	623116	WEAR SENSOR SCANIA DISC BRAKE 40G8401			904844
796	10/21/2016	623116	Warning Lights Brakes semi circles amber	remove both front wheels and inspect all brake system for wiring issues trace wiring problem to from front pad wiring to chassis		904844
796	10/21/2016	623116	Warning Lights Brakes semi circles amber	help scott fix pad wear sensor wiring		904844
796	10/21/2016	623116	Warning Lights Brakes semi circles amber	Checked for low pad light on. New pads in front. Rear pads. OK adjust air dryer pressure to 10+ bar. Light fault intermittant		904844
796	10/21/2016	623116	DIRECT PURCHASE - MECHANICAL GENERAL			904844
796	10/18/2016	622265	DIRECT PURCHASE - VANDALISM	Creditor #:IB-GLA010 GLASSPROTECH MELBOURNE P/O #:V179457 Receiving #:185947 Date :2016-10-20		904844
796	10/18/2016	622418	Consumables			904586
796	10/18/2016	622418	LIGHT FLUORESCENT TUBE 18W			904000
796	10/18/2016	622418	Elec and Light Exterior Lights front door exit light n.w	Replaced blown external step light fluro		904000
796	10/17/2016	622265	Vandalism Vandalism/ Graffiti Exterior Window film repla	L1		904000
796	10/17/2016	622367	WEAR SENSOR SCANIA DISC BRAKE 40G8401			904000
796	10/17/2016	622367	Mechanic entered - Brakes Foot_Brakes Pulling	remove and replace front genuine disc rotors and pads clean abs sensor and parts refit all components and tension Low pad light still flickering on dash after fitting new pads to front		904000
796	10/01/2016	619020	BRAKE PADS SCANIA HIGH SPEED	Creditor #:IB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:V178213 Receiving #:184880 Date :2016-10-06		902557
796	10/01/2016	619020	BRAKE DISC SCANIA SR4 AND K SR	Creditor #:IB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:V178213 Receiving #:184880 Date :2016-10-06		902557
796	09/28/2016	619020	Ops Entered - Fault - Steering Shakes/ Wobbles - when drivin	Replaced front wheels. Road tested and found wobble still there. Ordered new scania rotors.		901867
796	09/28/2016	619020	TYRE 295/80R22.5 NEW			901867
796	09/28/2016	619020	Body (None)Interior Light cover feel off.	Refitted light cover.		901867
796	09/26/2016	618272	Consumables			901867
796	09/26/2016	618272	Consumables			901867
796	09/26/2016	618272	A3 Poster Change please remove old poster and fit Vitorian	Replaced A3 Poster		901350
796	09/16/2016	613509	COVER			896039
796	09/16/2016	613509	OIL FILLER CAP - SCANIA L94UAB			896039
796	09/16/2016	613251	DIRECT PURCHASE - AIR CONDITIO	Creditor #:IB-BEA001 BEARING WHOLESALERS P/O #:V176086 Receiving #:183416 Date :2016-09-16 VEE BELT		899865
796	09/16/2016	613251	Consumables			899982
796	09/16/2016	613251	Consumables			899982
796	09/16/2016	613251	DIRECT PURCHASE - AIR CONDITIO	Creditor #:IB-BEA001 BEARING WHOLESALERS P/O #:V176086 Receiving #:183416 Date :2016-09-16 PUSH-FIT EQUAL TUBE TEE		899865
796	09/16/2016	613251	DIRECT PURCHASE - AIR CONDITIO	Creditor #:IB-BEA001 BEARING WHOLESALERS P/O #:V176086 Receiving #:183416 Date :2016-09-16 PUSH-FIT REDUCING UNION		899865
796	09/02/2016	613509	Mechanic entered - A/C Heating Belt Loose or_Missing	Replaced a/c belts (.25 smoko)		896039
796	09/01/2016	613509	Mechanic entered - Suspension Leaning	Replaced 3 rear air bags & order 1 new bag Replaced 4th rear air bag		896039
796	09/01/2016	613509	AIRBAG REAR DRIVE AXLE SCANIA L94UAB (2024287)			896039
796	09/01/2016	613509	OIL FILLER CAP - SCANIA L94UAB			896039
796	09/01/2016	613509	Steering Shakes/ Wobbles	Not excessive		896039
796	09/01/2016	613509	Steering (None) n/s tie rod needs alignment	Adjust NS tie rod to correct postion		896039
796	09/01/2016	613509	Engine oil leak	washed checked ok		896039
796	09/01/2016	613509	Trans output seal leaking	washed checked ok		896039
796	09/01/2016	613427	GLOBE 24V 5W (HLG245)			896039
796	09/01/2016	613427	TUBES FLUORESCENT 18W			896039
796	09/01/2016	613427	GLOBE 24V1.2WWEDGE (HLW241.20)(47706)(SWFLED)(E-596FWLED)			896039
796	09/01/2016	613427	Mechanic entered - Elec and Light Interior Lights	Replaced blown sitchdash and door lights		896039
796	09/01/2016	613509	Consumables			897100
796	09/01/2016	613509	Consumables			897100
796	09/01/2016	613509	struts for side panel both sides	check ok at this stage		896039
796	08/31/2016	613320	Service	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		896039
796	08/31/2016	613320	Service	VEHICLE SAFETY INSPECTION		896039
796	08/31/2016	613251	Mechanic entered - A/C Heating Belt Loose or_Missing	New belts ordered (.50 lunch)		896039
796	08/31/2016	612841	Consumables			897100
796	08/31/2016	612841	Elec and Light Interior Lights light on near side above do	LED's faulty. Fit new LED step lights. Now test ok. Adjusted door speeds to make doors operate safer and as the are supposed to.		896039
796	08/31/2016	613251	FILTER FUEL SCANIA SR4(H17WK04)			896039
796	08/31/2016	613251	Consumables			897100
796	08/31/2016	613251	O-RING KIT OIL SPINNER FILTER SCANIA ABOVE ENG #6203050			896039
796	08/31/2016	613251	FILTER OIL SCANIA SR4 EARLY K320 (LF3730)(2059778)(H200W20)			896039
796	08/31/2016	613251	FILTER ZF TRANS ECOMAT 124 4139-298-038 E39HD119 1193281-1			896039
796	08/31/2016	613251		CARRY OUT B SERVICE AS PER CHECK LIST		896039
796	08/31/2016	613251	Consumables			897100
796	08/31/2016	613251	Consumables			897100
796	08/31/2016	613251		CARRY OUT A SERVICE AS PER CHECK LIST		896039
796	08/31/2016	613251	Consumables			897100
796	08/30/2016	612841	Elec and Light Interior Lights light on near side above do			896039
796	08/29/2016	612750	Drv entered - Vandalism Vandalism Graffiti Interior	IAN BRISTOW CARRY OUT GARFFITI PAINT OUT		896039
796	08/29/2016	612750	Vandalism Vandalism/ Graffiti Interior graffiti shadows o	IAN BRISTOW CARRY OUT GARFFITI PAINT OUT		896039
796	08/29/2016	612814	Consumables			896557
796	08/29/2016	612814	LAMP LED AMBER FLASHER ELRLRA			896039
796	08/29/2016	612814	Elec and Light Exterior Lights botoom near side indicator	Replaced light		896039
796	08/26/2016	612233	Consumables			896298
796	08/26/2016	612233	Please remove old poster and fit new Legacy poster	Replaced Poster		896039
796	08/24/2016	611610	Consumables			895761
796	08/24/2016	611610	Elec and Light Exterior Lights - top right front p/light n	replace globe		894936
796	08/23/2016	611358	Consumables			895501
796	08/23/2016	611358	Ops Entered - Fault - Elec and Light Exterior Lights- very d	checked all working		894936
796	08/22/2016	611305	Consumables			895224
796	08/22/2016	611305	PLEASE REMOVE ANY OLD POSTERS & FIT NEW A3 POSTER	Replace poster		894936
796	08/11/2016	609436	-Replace Drivers Camera with a 2.1mm Thoreb unit-Place a b	Fit new 2.1mm camera and adjust. Tests ok		889579
796	08/11/2016	609436	In line with Campaign:1. Identify CCTV DVR type fitted to	CCTV upgraded settings adjusted and talking to network.		889579
796	08/11/2016	609410	Consumables			893115
796	08/11/2016	609435	Consumables			893115
796	08/11/2016	609410	Ops Entered - Fault - o/s mirror vibrating extremely badly.	Secured the mirror to remove a little vibration. Vibrates only at idle because of the engine idling low. Tests ok		889579
796	08/11/2016	609435	Body drivers security door broken	Secured drivers door		889579
796	08/10/2016	606221	Consumables			892776
796	08/10/2016	606221	Tombstone T8 + T12			889579
796	08/08/2016	606221	Tombstone T8 & T12			890579
796	08/02/2016	607699	Consumables			890823
796	08/02/2016	607699	Body Front_Door Operation Faulty Getting Stuck Sometimes	cleaned and lubed doors and pivots little bit worn but checked ok		890470
796	08/02/2016	607699	Air System (None) air from front door	cleaned and lubed doors and pivots little bit worn but checked ok		890470
796	08/01/2016	607385	AIR CONDITIONING REPAIR	Creditor #:IB-COL004 COLD DRIVE PTY LTD P/O #:V174070 Receiving #:180586 Date :2016-08-11 A/C REPAIRS		892264
796	08/01/2016	607385	demister dogging windows badly	GARY FROM COLD DRIVE CHECKED OVER BUS NO FAULT FOUND		889846
796	07/30/2016	605622	WHEEL NUTS RE-TENSION	WHEEL NUTS RE-TENSIONED		889846
796	07/28/2016	606803	Consumables			889846
796	07/28/2016	606221	Consumables			889846
796	07/28/2016	606221	GLOBE 24V 10W SINGLE CONTACT [BOX 10]			889579
796	07/28/2016	606221	FLURO TUBE 36W			889579

796	07/28/2016	606221	Tombstone T8 + T12			889579
796	07/28/2016	606221	GLOBE 24V 1.2W WEDGE HLW241.2 (47706)(SWFLED)(E-596FWLED)			889579
796	07/28/2016	606221	Mechanic entered - Elec and Light Other Multiple repairs	Replaced blown switch light repaired 3x saloon lights replaced missing safety trianlge replaced blown bus stopping sign globes and repaired open circuit to o/s/f side light. Meeting and lunch in between		889579
796	07/28/2016	606221	Elec and Light desto light n/w exterior	Desto lighting is ok. No fault		889579
796	07/28/2016	606803	Elec and Light Exterior Lights o/s front lower ind n/w	Working ok after tapping light		889579
796	07/28/2016	606221	Consumables			889846
796	07/28/2016	606221	Consumables			889846
796	07/28/2016	606221	BISCHER SWITCH DOORS	Creditor #:IB-SMC001 SMC PNEUMATICS AUST P/L P/O #:V173556 Receiving #:179911 Date :2016-08-03		890470
796	07/28/2016	606221	Mechanic entered - Body Front_Door Operation Faulty and rear	Ordered new bircher switches		889579
796	07/28/2016	606785	PERFORM CAMPAIGN 04/16 DRIVERS WALLETS AND MAP POCKET INSTA	completed		889579
796	07/28/2016	606785	Consumables			889846
796	07/28/2016	606785	Consumables			889846
796	07/27/2016	606221	Drv entered - Steering Shakes/ Wobbles	Checked front tyres & tie rod ends OK. Road test. Slight wobble at times. OKto use REBOOK		887061
796	07/26/2016	605622	DISPOSAL CHARGE	Creditor #:IB-MIC002 MICHELIN AUSTRALIA P/O #:V173292 Receiving #:179811 Date :2016-08-02		890130
796	07/26/2016	605622	FITTING	Creditor #:IB-MIC002 MICHELIN AUSTRALIA P/O #:V173292 Receiving #:179811 Date :2016-08-02		890130
796	07/26/2016	605622	295/80R22.5 RECAMIC DRIVE PATT	Creditor #:IB-MIC002 MICHELIN AUSTRALIA P/O #:V173292 Receiving #:179811 Date :2016-08-02		890130
796	07/23/2016	605622	TYRE 295/80R22.5 RECAP			887061
796	07/23/2016	605622	VALVE FLEXIBLE TYRE EXTENSION VALVE 210mm LONG			887061
796	07/23/2016	605622	Wheels and Tyres Flat or Leaking O/S/R/I flat.	Fitted 1 new cap & 1 near new S/H cap to OSR		887061
796	07/21/2016	604818	FRANCHISEE CASE	Creditor #:IB-MIC002 MICHELIN AUSTRALIA P/O #:V173026 Receiving #:179166 Date :2016-07-26		888511
796	07/21/2016	604818	DISPOSAL CHARGE	Creditor #:IB-MIC002 MICHELIN AUSTRALIA P/O #:V173026 Receiving #:179166 Date :2016-07-26		888511
796	07/21/2016	604818	BALANCE OFF VEHICLE	Creditor #:IB-MIC002 MICHELIN AUSTRALIA P/O #:V173026 Receiving #:179166 Date :2016-07-26		888511
796	07/21/2016	604818	FITTING	Creditor #:IB-MIC002 MICHELIN AUSTRALIA P/O #:V173026 Receiving #:179166 Date :2016-07-26		888511
796	07/21/2016	604818	295/80R22.5 RECAMIC DRIVE PATT	Creditor #:IB-MIC002 MICHELIN AUSTRALIA P/O #:V173026 Receiving #:179166 Date :2016-07-26		888511
796	07/21/2016	604818	295/80R22.5 XZE2+	Creditor #:IB-MIC002 MICHELIN AUSTRALIA P/O #:V173026 Receiving #:179166 Date :2016-07-26 295/80r22.5 x multi z tl		888511
796	07/20/2016	605062	Consumables			887812
796	07/20/2016	605062	INDICATOR STALK SCANIA SERIES 4 1402448			887061
796	07/20/2016	605062	Ops Entered - Fault - Indictor not self cancelling	Changed out indicator stalk. Tests ok		887061
796	07/19/2016	604739	Service	TRANSMISSION CHECK AS PER CHECK LIST		887061
796	07/19/2016	604737	Service	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		887061
796	07/19/2016	604737	Service	VEHICLE SAFETY INSPECTION		887061
796	07/19/2016	604818	Wheels and Tyres Worn N/S/F & O/S/R/I tyres worn.	Replaced O/S/R/I and N/S/F tyres with runouts.		887061
796	07/19/2016	604739	Consumables			887465
796	07/19/2016	604739	Consumables			887465
796	07/19/2016	604739	Service	CARRY OUT A SERVICE AS PER CHECK LIST		887061
796	07/07/2016	602423	Consumables			884652
796	07/07/2016	602423	Drv entered - Elec and Light Interior Lights	Removed		883516
796	07/07/2016	602423	Elec and Light Interior Lights. Front interior lights are	Saloon lights reflecting on windscreen first light on N/S/F needs to be removed.		883516
796	07/02/2016	601322	Consumables			883136
796	07/02/2016	601322	Consumables			883136
796	07/02/2016	601322	Body (None)N/Side mirror arm bent	Straightened N/S mirror arm & refitted mirror head		882745
796	07/01/2016	600534	WHEEL ALIGNMENT	Creditor #:IB-AIR001 AIR ANYWHERE P/O #:V171144 Receiving #:177795 Date :2016-07-05 Air anywhere carry out wheel alignment		883838
796	06/29/2016	600831	Consumables			882453
796	06/29/2016	600831	Body - Interior panel has fallen from roof	repair broken roof ducting and fit repair all damaged wiring to lighting speakers and emergency exit equipment repair and refit broken a/c intirior ducting		882054
796	06/28/2016	600534	Requires wheel alignment	Air anywhere carry out wheel alignment		882054
796	06/28/2016	598506	AIR CONDITIONING REPAIR	Creditor #:IB-TRA012 TRACS (WA) PTY LTD P/O #:V171504 Receiving #:177555 Date :2016-06-30 REFER TO INVOICE FOR REPAIRS		882289
796	06/22/2016	599329	Consumables			881385
796	06/22/2016	599329	Elec and Light - O/S headlight n/w	Both headlights working secured N/S headlight		880949
796	06/20/2016	598837	Consumables			880949
796	06/20/2016	598837	DIRECT PURCHASE - GLASS	Creditor #:IB-A1W001 A-1 Windscreens P/O #:V170512 Receiving #:176648 Date :2016-06-23 A1 supply and fit Windscreen		881199
796	06/20/2016	598837	Body Windows Front screen cracked by pot hole in road	A1 SUPPLY AND FIT NEW SCREEN		880492
796	06/17/2016	596918	Consumables			880806
796	06/17/2016	596918	GLOBE 24V 21W SINGLE CONTACT (HLR2421)			880492
796	06/17/2016	596918	Elec and Light left front Indicator n/w	Replaced blown indicator globe.		880492
796	06/17/2016	598506	Service	TRACS CARRY OUT A/C - B SERVICE AS PER CHECK LIST		880492
796	06/17/2016	598506	Service	TRACS CARRY OUT A/C - A SERVICE AS PER CHECK LIST		880492
796	06/10/2016	596918	Ops Entered - Fault - interior lights too bright. can't see	Front saloon fluros need to be removed because the saloon lights arnt turning off.		879150
796	06/04/2016	599782	Consumables			878360
796	06/04/2016	599782	Please remove any old poster and fit new A3 poster and add	complete		867921
796	06/01/2016	582817	AIR CONDITIONING REPAIR	Creditor #:IB-TRA012 TRACS (WA) PTY LTD P/O #:V171066 Receiving #:176895 Date :2016-06-27 REFER TO INVOICE FOR REPAIRS		882054
796	05/30/2016	594464		finish off safety inspection		876936
796	05/30/2016	594464	Service	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Wheel nuts tensioned		876936
796	05/30/2016	594464	Service	VEHICLE SAFETY INSPECTION		876936
796	05/30/2016	594513	Mechanic entered - Wipers and Washers Wipers Loose blade piv	Secured blade pivot point using spacer. Wipers secure and test ok		876936
796	05/30/2016	594513	Mechanic entered - Steering Excessive Play in steering wheel	Tightened up adjustment mechanism. Tests ok		876936
796	05/30/2016	594513	Coolant fill door missing	cheecked ok		876936
796	05/30/2016	594464	Consumables			877172
796	05/30/2016	594513	Consumables			877172
796	05/30/2016	594464	FLURO TUBE 36W			876936
796	05/30/2016	594464	GLOBE WEDGE 24V 1.2W HLW241.2 47706 SWFLED E-596FWLED			876936
796	05/30/2016	594464	Mechanic entered - Elec and Light Interior Lights switch lig	Replaced blown switch light globes Replaced all blown saloon lights		876936
796	05/30/2016	594513	TUBES FLUORESCENT 18W			876936
796	05/30/2016	594513	Mechanic entered - Elec and Light Exterior Lights	Front external step light fluro replaced. More fluro tubes on order. Replace rear door light when they arrive Replaced rear light fluro		876936
796	05/30/2016	594513	SYMBOL (FRONT DOOR) SWF SWITCH			876936
796	05/30/2016	594513	SYMBOL (REAR DOOR) SWF SWITCH			876936
796	05/30/2016	594513	Require front door switch	fit new switch symbols		876936
796	05/30/2016	594513	Dash switches need securing	Dash switches secured		876936
796	05/30/2016	594513	Consumables			877172
796	05/30/2016	594513	Consumables			877172
796	05/30/2016	594513	BISCHER SWITCH DOORS			876936
796	05/30/2016	594513	Mechanic entered - Body Front_Door Operation Faulty	Fit new bircher switch for front leaf sensitive edge. Tests ok		876936
796	05/30/2016	594513	Mechanic entered - Body Other Screw missing from rear modest	Replaced missing bolt. Panel secured		876936
796	05/30/2016	594593	Consumables			877172
796	05/30/2016	594593	Consumables			877172
796	05/30/2016	594593	Consumables			877172
796	05/30/2016	594593	O-RING KIT OIL SPINNER FILTER SCANIA ABOVE ENG #6203050			876936
796	05/30/2016	594593	FILTER OIL SCANIA SR4 EARLY K320 (LF3730)(2059778)(H200W20)			876936
796	05/30/2016	594593	FILTER TRANSMISSION ZF 4139-298-038/4139 298 038 01			876936
796	05/30/2016	594593	FILTER FUEL SCANIA SR4(H17WK04)			876936
796	05/30/2016	594593		CARRY OUT B SERVICE AS PER CHECK LIST		876936
796	05/30/2016	594593	Consumables			877172
796	05/30/2016	594593	Consumables			877172
796	05/30/2016	594593	Consumables			877172

796	05/30/2016	594593		CARRY OUT A SERVICE AS PER CHECK LIST		876936
796	05/28/2016	594355	Consumables			877172
796	05/28/2016	594355	GLOBE H1 24V 70W			876936
796	05/28/2016	594355	Ops Entered - Fault - near side head light n/w	changed out blown headlight globe		876936
796	05/10/2016	590392	Consumables			873373
796	05/10/2016	590392	Consumables			873373
796	05/10/2016	590392	DIRECT PURCHASE - GLASS	Creditor #:IB-A1W001 A-1 Windscreens P/O #:V167704 Receiving #:173777 Date :2016-05-13 Supply and fit new windscreen		874026
796	05/10/2016	590392	Mechanic entered - Body Windows Front front window cracked	A1 WINDSCREEN supply and fit new screen		873082
796	05/10/2016	590392	Body Windows Front. front window leaking more water from	A1 WINDSCREEN supply and fit new screen		873082
796	05/09/2016	590551	WIRE & PLUG KIT MOISTURE EJECTOR			873082
796	05/09/2016	590551	CYCLONE CONDENSER VALVE KIT			873082
796	05/09/2016	590551	Service	CARRY OUT TUNE-UP SERVICE AS PER CHECK LIST		873082
796	05/09/2016	590551	Service	SERVICE MOISTURE EJECTOR		873082
796	05/09/2016	590551	Service	CARRY OUT TUNE-UP SERVICE AS PER CHECK LIST		873082
796	05/09/2016	590551	Service	SERVICE MOISTURE EJECTOR		873082
796	05/07/2016	590393	Consumables			873373
796	05/07/2016	590393	Ops Entered - Fault - Thoreb system beeping loud occasionall	checked ok		873082
796	05/07/2016	586891	Consumables			873373
796	05/07/2016	586891	Consumables			873373
796	05/07/2016	590392	Drv entered - Body Windows Front SMALL CHIP	big crack needs replacing		873082
796	05/07/2016	586891	BUTT HINGE BLACK (49080)			873082
796	05/07/2016	586891	Body drivers compartment door missing.	fitted new drivers door checked ok		873082
796	05/07/2016	586891	Drv entered - driver security door missing	new door fitted		873082
796	05/07/2016	586891	Body a/c ducting on o/s behind driver has droppe down bes	re screwed and secured panel to make safe		873082
796	05/05/2016	586891	Consumables			873082
796	05/05/2016	586891	GLOBE 24V 5W BAYONETT 17181			872444
796	05/05/2016	586891	Ops Entered - Fault - Top left p/l n/w front	Replaced globe NST park light		872444
796	05/01/2016	586524	DIRECT PURCHASE - VANDALISM	Creditor #:IB-TRI001 TRIM IMPROVEMENTS P/O #:V166113 Receiving #:174015 Date :2016-05-17 RECOVER SLASHED SEATS		874563
796	04/29/2016	589040	Saloon lights not working	Saloon lights replaced		871927
796	04/29/2016	589040	FLURO TUBE 36W			871927
796	04/29/2016	589040	GLOBE WEDGE 24V 1.2W HLW241.2 47706 SWFLED E-596FWLED			871927
796	04/29/2016	589040	Switch lights not working	Switch lights replaced		871927
796	04/18/2016	586891	Consumables			870547
796	04/18/2016	586891	Drivers door stuck wont open	Removed drivers door latch has been bent out of shape		869997
796	04/14/2016	586524	N/S/F seat slashed			869997
796	04/14/2016	586524	Consumables			870201
796	04/14/2016	586524	Ops Entered - Fault - Body Passenger Seat Torn x2	JIMMY FROM TRIMIMPROVEMENTS CARRY OUT REPAIRED SEAT AS REQUIRED		869997
796	04/12/2016	585809	N/S/M seat slashed	Two seat cushions replaced to remove slashed cushions.		868444
796	04/12/2016	585809	Consumables			869760
796	04/12/2016	585809	Body - Seats slashed	Two seat cushions replaced to remove slashed cushions.		868444
796	04/12/2016	585809	Drv entered - Body Passenger Seat Torn	Two seat cushions replaced to remove slashed cushions.		868444
796	04/12/2016	585809	Body Passenger Seat Torn first seat cushion on near side.	Two seat cushions replaced to remove slashed cushions.		868444
796	04/12/2016	585809	Body Passenger Seat Torn front nearside	Removed seat base for reco.		868444
796	04/11/2016	585809	DIRECT PURCHASE - VANDALISM	Creditor #:IB-TRI001 TRIM IMPROVEMENTS P/O #:V165881 Receiving #:172149 Date :2016-04-19 REPAIR SLASHED SEATS AS REQUIRED		870547
796	04/06/2016	564230	DISPOSAL CHARGE	Creditor #:IB-MIC002 MICHELIN AUSTRALIA P/O #:V165459 Receiving #:171316 Date :2016-04-07		868444
796	04/05/2016	584456	Consumables			868163
796	04/05/2016	584456	Ops Entered - Fault - Body Front_Door sticking	Cleaned and lubricated doors. Opening ok.		867542
796	04/01/2016	583995	Service	VEHICLE SAFETY INSPECTION		867542
796	04/01/2016	583995	Service	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		867542
796	04/01/2016	583995	Service	VEHICLE SAFETY INSPECTION		867542
796	04/01/2016	583995	Mechanic entered - Steering Pulling	Road test bus & inspect steering & suspension. Requires wheel alignment. (many new componets have been replaced in the steering & suspension)		867542
796	04/01/2016	582817	AIR CONDITIONING REPAIR	Creditor #:IB-TRA012 TRACS (WA) PTY LTD P/O #:V166633 Receiving #:172407 Date :2016-04-21 REPAIRS TO AC AS REQUIRED		870720
796	04/01/2016	583995	Consumables			867633
796	04/01/2016	583995	Consumables			867633
796	04/01/2016	583995	Service	CARRY OUT A SERVICE AS PER CHECK LIST		867542
796	03/23/2016	582817	Ops Entered - Fault - A/C Heating Not Cooling - blowing war	GARY FROM TRACS CARRY OUT REPAIRS AS REQUIRED		866328
796	03/23/2016	582817	Ops Entered - Fault - A/C Not Cooling blowing warm air. fa	GARY FROM TRACS CARRY OUT REPAIRS AS REQUIRED		866328
796	03/23/2016	582817	Ops Entered - Fault - A/C Heating Not Cooling - blowing hot	GARY FROM TRACS CARRY OUT REPAIRS AS REQUIRED		866328
796	03/23/2016	582817	A/C Heating Not Cooling	GARY FROM TRACS CARRY OUT REPAIRS AS REQUIRED		866328
796	03/23/2016	582817	A/C Heating Not Cooling	GARY FROM TRACS CARRY OUT REPAIRS AS REQUIRED		866328
796	03/21/2016	582295	FILTER FUEL SCANIA L94UAB (H7090WK30)			865654
796	03/21/2016	582295	Mechanic entered - Engine Other engine not starting.	Found fuel bowl sucking air into fuel system. Replaced filter and fitted 2nd hand bowl.		865654
796	03/21/2016	582298	Consumables			866037
796	03/21/2016	582298	Body Drivers Seat Controls - Drivers seat base rake adjust	Checked seat controls. Working ok.		865654
796	03/21/2016	582298	Body N/S Mirror Loose	Tightened mirror head.		865654
796	03/05/2016	579840	FRONT AIR BAG SCANIA L94UAB			862505
796	03/05/2016	579840	Suspension Leaning - N/S/F Air bag	Replaced N/S/F air bag traced ELC fault warning light ON reset fault codes come good road tested retested for fault no fault found OK		862505
796	03/01/2016	571884	Consumables			862505
796	03/01/2016	571884	DIRECT PURCHASE ACCIDENT	Creditor #:IB-EAS003 EASTCOAST TRUCK & BUS SERVICE P/O #:V161023 Receiving #:170871 Date :2016-03-31 PO# for Bus# 796 Acc# 42396		867112
796	02/29/2016	578826	GLOBE 24V 21W SINGLE CONTACT HLR2421			861766
796	02/29/2016	578826	Ops Entered - Fault - Elec and Light Exterior Lights reversi	Replaced reverse globe.		861766
796	02/29/2016	578826	Consumables			862276
796	02/26/2016	578433	The Campaign requires all Bus destinations systems to be in	completed		861766
796	02/26/2016	578433	Consumables			862007
796	02/19/2016	577061	Drv entered - AC Heating Not Cooling	REFER TO FAULT # 572105		859938
796	02/19/2016	577061	Ops Entered - Fault - A/C Heating Not Cooling - Route: 663	REFER TO FAULT # 572105		859938
796	02/19/2016	577061	Ops Entered - Fault - A/C Heating Not Cooling	REFER TO FAULT # 572105		859938
796	02/19/2016	577061	Ops Entered - Fault - A/C Heating Not Cooling - Route: 670	REFER TO FAULT # 572105		859938
796	02/19/2016	577061	Drv entered - AC Heating Not Cooling	GARY FROM TRACS CARRY OUT REPAIRS AS REQUIRED		859938
796	02/19/2016	577061	Drv entered - AC Heating Not Cooling	REFER TO FAULT # 572105		859938
796	02/19/2016	577061	Consumables			860412
796	02/19/2016	577061	Ops Entered - Fault - Body Windows Front - Route: 663 - Li	REFER TO FAULT # 572105		859938
796	02/13/2016	575826	Consumables			859515
796	02/13/2016	575826	Body (None) near side external mirror loose	Secure mirror head		858377
796	02/11/2016	575454	Consumables			859146
796	02/11/2016	575454	Campaign 23_15 A3 Poster Change	Complete		858377
796	02/02/2016	573688	Service	TRANSMISSION CHECK AS PER CHECK LIST		857222
796	02/02/2016	573675	Service	VEHICLE SAFETY INSPECTION		857222
796	02/02/2016	573675	Service	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		857222
796	02/02/2016	573675	Service	VEHICLE SAFETY INSPECTION		857222
796	02/02/2016	573740	Consumables			857222
796	02/02/2016	573740	Consumables			857222
796	02/02/2016	573740	Consumables			857222

796	02/02/2016	573740	Consumables		857222
796	02/02/2016	573740	FILTER FUEL SCANIA SR4(H17WK04)		857222
796	02/02/2016	573740	O-RING KIT OIL SPINNER FILTER SCANIA ABOVE ENG #6203050		857222
796	02/02/2016	573740	FILTER TRANSMISSION ZF 4139-298-038/4139 298 038 01		857222
796	02/02/2016	573740	Service	CARRY OUT B SERVICE AS PER CHECK LIST	857222
796	02/02/2016	573740	FILTER OIL SCANIA SR4 EARLY K320 (LF3730)(2059778)(H200W20)		857222
796	02/02/2016	573740	Consumables		857222
796	02/02/2016	573740	Consumables		857222
796	02/02/2016	573740	Consumables		857222
796	02/02/2016	573740	Consumables		857222
796	02/02/2016	573740	Service	CARRY OUT A SERVICE AS PER CHECK LIST	857222
796	02/02/2016	573740	Service	CARRY OUT A SERVICE AS PER CHECK LIST	857222
796	02/01/2016	570833	AIR CONDITIONING REPAIR	Creditor #:IB-TRA012 TRACS (WA) PTY LTD P/O #:V161693 Receiving#:167393 Date :2016-02-04 found low gas charge leak located at thecompressor discharge hose. removed and replaced hopse. pressure testedand checked for further leaks ok. changed dryer and tested clutch droppingout forund corrosion on plugs at con	857222
796	02/01/2016	560839	TIE ROD ASSY K230	Creditor #:IB-MUL001 MULTISPARES LIMITED P/O #:V158660 Receiving #:164677 Date :2015-12-04	849174
796	02/01/2016	549466	DIRECT PURCHASE - VANDALISM	Creditor #:IB-EAS003 EASTCOAST TRUCK & BUS SERVICE P/O #:V156322-1 Receiving #:167350 Date :2016-02-04 prep ans painted graffit replaced windows as required	857222
796	01/27/2016	572275	Ops Entered - Fault - Steering Shakes/ Wobbles - Route: 663	drive vehicle minor brake shudder detected monitor for further ware	855512
796	01/27/2016	572273	Drv entered - Steering Shakes Wobbles	drive vehicle minor brake shudder detected monitor for further ware	855512
796	01/22/2016	571884	Body Passenger Seat Torn. Slashed seats	repaired seats	854991
796	01/22/2016	571884	Body Rear Bar Damage	Repaied by E.C.T.B PO# for Bus# 796 Acc# 42396	854991
796	01/20/2016	570833	Ops Entered - Fault - A/C Heating Not Cooling	Refer to fault # 570749	854462
796	01/20/2016	570833	A/C Heating Not Cooling	Refer to fault # 570749	854462
796	01/20/2016	570833	A/C Heating Not Cooling	Refer to fault # 570749	854462
796	01/20/2016	570833	Drv entered - AC Heating Not Cooling	Refer to fault # 570749	854462
796	01/20/2016	570833	Drv entered - AC Heating Not Cooling	GARRY FROM TRACS REPAIRS AS REQUIRED HOSE NEED REPLACING	854462
796	01/14/2016	570098	PERFORM CAMPAIGN 22/15 POSITIONING OF 2016 PTV FARES DECALS	complete	854035
796	01/14/2016	569993	Camapign 20/15 Audit & Update of Safety Decals.Requires a	Completed	854035
796	12/21/2015	560479	DIRECT PURCHASE - BUS INSPECTI	Creditor #:IB-ROA003 ROAD SAFETY INSPECTIONS P/L P/O #:V159654 Receiving #:165564 Date :2015-12-22	851599
796	12/17/2015	560479	Service	ANNUAL SAFETY INSPECTION (RWC #001157)	846564
796	12/17/2015	565474	Mechanic entered - Gearbox Driveline Other Trans cooler oil	Washed trans and trans cooler roadtest and check leaks not excesive at this time ok	846564
796	12/17/2015	565474	Consumables		851009
796	12/17/2015	565474	PASSENGER GRAB HANDLE		846564
796	12/17/2015	565474	Mechanic entered - Body Other n/s/r passenger grab handle da	Fit new passenger grab handle ok	846564
796	12/14/2015	564230	WHEEL NUTS RE-TENSION Bookback from W/O:564230 REAR AXLE RE	WHEEL NUTS RE-TENSION Bookback from W/O:564230 REAR AXLE RE-TENSION	849896
796	12/11/2015	564382	Brakes Foot_Brakes Leaking Air	Replaced foot brake valve adjusted potentiometer road tested and checked retarder and brake operation ok	849896
796	12/10/2015	564230	TYRE RECAP 295/80R22.5		849896
796	12/10/2015	564230	Consumables		850047
796	12/10/2015	564230	Check N/S/R tyres 2 weeks before RSI	Replaced 2x n/s/r tyres ok	849896
796	12/10/2015	564255	Engine oil leaks	Washed engine and trans roadtest and check for leaks ok at this time	849896
796	12/10/2015	564233	LIGHT COVER/DIFFUSER ELLAMP 3METER LENGHT		849896
796	12/10/2015	564233	Mechanic entered - Elec and Light Interior Lights Saloon lig	Replaced broken saloon light difuser ok	849896
796	12/08/2015	560839	CENTRA SEAT END CAPS		849174
796	12/08/2015	560839	Consumables		849723
796	12/08/2015	561736	DIRECT PURCHASE - AIR CONDITIO	Creditor #:IB-EAS003 EASTCOAST TRUCK & BUS SERVICE P/O #:V158707 Receiving #:164859 Date :2015-12-08 Checked and topped up refrigerant as required	849174
796	12/07/2015	561924	Direct Purchase - BODYWORK	Creditor #:IB-SMC001 SMC PNEUMATICS AUST P/L P/O #:V158869 Receiving #:165108 Date :2015-12-15 bircher switching unit	850455
796	12/07/2015	560839	VALVE FOOTBRAKE	Creditor #:IB-MUL001 MULTISPARES LIMITED P/O #:V159101 Receiving #:164772 Date :2015-12-08 foot brake valve	849000
796	12/04/2015	563276	VALVE SOLENOID ACCUMULATOR ZF (0501 316 527 01 49D2909)		847094
796	12/04/2015	563276	BUSH SWAY BAR FRONT SCANIA SR4 & K230 0469081 1919010		847094
796	12/04/2015	563276	D-rubber bushes worn	replaced front swaybar rubbers clean up w/shop bay	847094
796	12/04/2015	563276	Tie rod assemably needs replacing	replaced tierod bar assembly refer w.o. 560839	847094
796	12/04/2015	563276	Alucumlator valve leaking	replaced trans accumulator solenoid valve refer w.o. 560839	847094
796	12/04/2015	563276	RH tacho light not working	Replced globe	847094
796	12/02/2015	561924	Drv entered - Passenger Doors	Replaced bircher relay ex-793 fit new one 793	847094
796	12/01/2015	560479	HEAD LAMP INSERT HELLA 100MM L	Creditor #:IB-WHI002 WHITEHORSE TRUCK CENTRE P/O #:V158774 Receiving #:164847 Date :2015-12-08	849174
796	12/01/2015	561924	Direct Purchase - BODYWORK	Creditor #:IB-SMC001 SMC PNEUMATICS AUST P/L P/O #:V158727 Receiving #:164766 Date :2015-12-08 bus 796- bircher switch	849000
796	12/01/2015	562531	Consumables		848312
796	12/01/2015	562531	Remove Old Poster and Fit new All Night Public Transport Po	Carried out	847094
796	11/30/2015	561924	Drv entered - Passenger Doors	Bircher faulty ordered parts	847094
796	11/30/2015	561568	Consumables		847992
796	11/30/2015	561568	Consumables		847992
796	11/30/2015	561568	Consumables		847992
796	11/30/2015	561568	Service	CARRY OUT A SERVICE AS PER CHECK LIST	847094
796	11/27/2015	561786	Drv entered - Ticket Equip	Checked ok	847094
796	11/27/2015	561786	Drv entered - AC Heating Not Cooling	Refer to fault # 561885	847094
796	11/27/2015	561786	A/C Heating Not Cooling	Carried out Service as per checklist. Tested Cooling working correctly. Tested Demister Function. working correctly. Jack	847094
796	11/27/2015	561786	Drv entered - Heat & Demist	Refer to fault # 561885	847094
796	11/27/2015	561740	Elec door alarm light flashing and door playing up . mechan	adjusted door op	847094
796	11/27/2015	561771	Service	CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST Carried out fire safety inspection. Pass	847094
796	11/27/2015	561736	Service	CARRY OUT A/C - B SERVICE AS PER CHECK LIST	847094
796	11/27/2015	561736	Service	CARRY OUT A/C - A SERVICE AS PER CHECK LIST	847094
796	11/25/2015	560770	Consumables		847094
796	11/25/2015	560770	Front leaf of front door sensitive edge not working	door speed not correct doors jamming closed cannot open. sensitive edge n/w ?	846786
796	11/24/2015	560839	2 N/S folding seat base back covers damaged	Secured seat covers.	846564
796	11/24/2015	560839	1st N/S seat base torn	No change over seat base.	846564
796	11/24/2015	560839	Both tie rod ends needs replacing	checked & ordered tierod bar	846564
796	11/24/2015	560839	Both tie rod ends needs replacing	Ordered new tie rod.	846564
796	11/24/2015	560839	Steering shaft uni-joint at steering box U/S	checked steering shaft minor axial movement ok	846564
796	11/24/2015	560839	Steering shaft uni-joint at steering box U/S	Ordered steering uni.	846564
796	11/24/2015	560839	O/S A/C duct screws missing	Secured AC duct.	846564
796	11/24/2015	560839	Accumulator valve leaks when master switch is off	checked & order new valve	846564
796	11/24/2015	560839	Oil filter neck + cap damaged by A/C belt	Oil filler neck not rubbed through. AC belt not rubbing on filler cap.	846564
796	11/24/2015	560839	Accumulator valve leaks when master switch is off		846564
796	11/24/2015	560770	O/S alternator belt idler pulley melted	Checked pulley. was not melted!	846564
796	11/24/2015	560479	GLOBE H1 24V 70W		846564
796	11/24/2015	560479	Mechanic entered - Elec and Light Exterior Lights o/s H.ligh	replace head light globe	846564
796	11/24/2015	560839	O/S headlight broken	Waiting on parts.	846564
796	11/24/2015	560770	Door open + door brake interlock lights not working	replaced blown dash lights	846564
796	11/24/2015	560770	Globes not working in Next Stop light	Replaced blown globe	846564
796	11/24/2015	560770	Door ok light not working	Replaced blown globe	846564
796	11/24/2015	560770	N/S hammer alarm not working	Re-connected n/s emergency hammer	846564
796	11/24/2015	560770	Saloon lights not working	Replaced blown fluro tubes	846564
796	11/24/2015	560770	Dash switches not labled	Fit dash switch labels	846564
796	11/24/2015	560770	Switch lights not working	Replaced blown globe	846564
796	11/24/2015	560839	Consumables		846786

796	11/24/2015	560839	O/S double folding seat end cap missing	ordered seat end cap		846564
796	11/24/2015	560839	No.1 O/S + No.2 N/S windows loose	apply silicon to loose windows		846564
796	11/24/2015	560839	O/S double folding seat end cap missing	Ordered cap		846564
796	11/24/2015	560839	Wheelchair ramp load sticker wrong (ramp 200kg - sticker 30	Ian is sorting out wheel chair ramp decals.		846564
796	11/24/2015	560839	No.1 O/S + No.2 N/S windows loose	Secured windows.		846564
796	11/24/2015	560839	Safety triangles damaged	Replaced safety triangle.		846564
796	11/24/2015	560770	Several panel screws loose	Secured loose panel screws		846564
796	11/24/2015	560770	FLURO TUBE 36W			846564
796	11/24/2015	560770	GLOBE WEDGE 24V 1.2W HLW241.2 (47706 SWFLED E-596WLED)			846564
796	11/24/2015	560770	GLOBE S/CONTACT 24V-10W			846564
796	11/24/2015	560770	Front leaf of front door sensitive edge not working			846564
796	11/24/2015	560839	Foot valve leaking from exhaust port when applied	checked & ordered valve		846564
796	11/24/2015	560839	Foot valve leaking from exhaust port when applied			846564
796	11/23/2015	560459	Service	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		846564
796	11/23/2015	560459	Service	VEHICLE SAFETY INSPECTION		846564
796	11/23/2015	560479		ANNUAL SAFETY INSPECTION (RWC #)		846564
796	11/23/2015	560480	Service	PRE ANNUAL SAFETY INSPECTION CHECK		846564
796	11/23/2015	560479	Elec and Light Exterior Lights offside headlight lens brok	Fitted 2nd hand head lamp and ordered new one. 2nd hand one has a broken adjuster.		846564
796	11/05/2015	557178	Elec and Light Warning Light On Dash when going over bumps	road test for MB		842616
796	11/05/2015	557178	TUBES FLUORESCENT 18W			842616
796	11/05/2015	557178	Elec and Light Warning Light On Dash when going over bumps	Took bus for road test could not even fault under extreme conditions		842616
796	11/05/2015	557178	Ops Entered - Fault - Elec and Light Next Stop Button - Rou	All next stop buttons and lamps test ok.		842616
796	11/05/2015	557178	Consumables			843602
796	11/05/2015	557178	Body (None)front door exit light not working	Replaced fluro light		842616
796	11/05/2015	557023	Service	CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST Carried out firesafety inspection. Passed		842616
796	11/04/2015	556790	Consumables			843315
796	11/04/2015	556790	SEAT BELT BUCKLE (GREY)			842616
796	11/04/2015	556790	Body Drivers Seat Belt buckle broken	Replaced seat belt buckle		842616
796	10/28/2015	555908	Elec and Light Next Stop Button broken	could not get to fault. Good to go back to work		841890
796	10/14/2015	553124	Elec and Light - n/s/t/f park light	job duplicate. disregard		838697
796	10/14/2015	553123	GLOBE 24V 5W BAYONETT 17181			838697
796	10/14/2015	553123	Elec and Light - n/s/t/f park light	Replaced blown globe		838697
796	10/08/2015	552137	Consumables			838392
796	10/08/2015	551927	Consumables			838392
796	10/08/2015	552137	Replace A3 poster with Victorian Seniors Festival Poster	completed		837781
796	10/08/2015	551927	Campaign 11/15. Fit 2 x Supplied Decals to Internal Saloo	completed		837781
796	10/06/2015	550088	DIRECT PURCHASE - VANDALISM	Creditor #:IB-GLA010 GLASSPROTECH MELBOURNE P/O #:V156401 Receiving #:161920 Date :2015-10-06 WINDOWS L1233a4/R1233a4		837562
796	10/06/2015	551142	Front O/S upper torque rod bush perished	Checked ok		837330
796	10/06/2015	551142	Air leak in fronr of diff	Checked ok		837330
796	10/06/2015	551142	HYDRAULIC HOSE	Creditor #:IB-PIR001 PIRTEK BAYSWATER P/O #:V156571 Receiving #:161924 Date :2015-10-06 hose assembly + rubber lined clamp		837562
796	10/06/2015	551142	Wash engine and transmission	Washed and checked leaks ok		837330
796	10/06/2015	551142	Fuel tank bracket cracked	checked could not see any cracks		837330
796	10/06/2015	551142	Fluid Leaks Rear of bus coolant	Fitted new hyd hose topped up hyd oil replaced water with coolant washed off oil road tested ok		837330
796	10/06/2015	551424	Complete task as instructed in Fleet Campaign 09/15	Completed as per campaign		837562
796	10/06/2015	551142	Indicators not self cancelling	checked working as normal		837330
796	10/06/2015	551142	Consumables			837781
796	10/06/2015	551142	Body Windows Front Chip in drivers side of windscreen	Ok at this time		837330
796	10/06/2015	551142	Drivers console on dash needs securing	Secured console		837330
796	10/05/2015	551142	DIRECT PURCHASE - TOWING	Creditor #:IB-EAG001 EAGLE TOWING AND SALVAGE P/O #:V156903 Receiving #:162245 Date :2015-10-13 Tow vehicle from Boronia to Lilydale		838697
796	10/05/2015	551142	Fluid Leaks Rear of bus coolant	Travelled to Boronia station topped up with water checked for leaks foundfan motor hose blown out removed axle and waited for tow truck		837330
796	10/01/2015	550713	Consumables			837562
796	10/01/2015	550713	as per Campaign 08/15Fit Hi Vis Vest DecalFit Coat Hook i	completed as per campaign 08/15		837330
796	10/01/2015	549466	DIRECT PURCHASE ACCIDENT	Creditor #:IB-EAS003 EASTCOAST TRUCK & BUS SERVICE P/O #:V156322 Receiving #:162204 Date :2015-10-13 UNREPORTED ACCIDENT WORK REF 41745 - EC RO 193138		838697
796	09/30/2015	550088	Vandalism Vandalism/ Graffiti Interiorglass protect fit	WINDOWS L1.2.3.3A.4/R1.2.3.3A.4		837330
796	09/30/2015	549704	DO NOT OVERTAKE DECAL			837330
796	09/30/2015	549704	Mechanic entered - Body Other	Fit do not overtake turning vehicle decal as required ok		837330
796	09/30/2015	549801	MUDFLAP UNIVERSAL			837330
796	09/30/2015	550348	Air System Air Not Building_Up front brake cuircuit low a	Fit new 4 way protection valve check for air leaks and connect guages to check pressures OK		837330
796	09/30/2015	550348	4 WAY VALVE -MB0305- KNORR BREMSEY DART			837330
796	09/30/2015	549704	Consumables			837330
796	09/30/2015	549704	Consumables			837330
796	09/30/2015	549704	Consumables			837330
796	09/30/2015	549704	FILTER DRYER SCANIA/VOLVO (1375997)(49G8704W)			837330
796	09/30/2015	549704		Finsh service		837330
796	09/29/2015	549801	Drivers side wiper arm pivot loose	Tightened up wiper arm pivot		837330
796	09/29/2015	549801	Disabled ramp light not working	Tested ramp signal light. could not fault		837330
796	09/29/2015	549801	Rear O/S mud flap missing	Replaced rear o/s mud flap		837330
796	09/29/2015	549801	Front door front leaf sensitive edge not working	Reparied front door sensitive edges		837330
796	09/29/2015	549704	FILTER AIR OUTER SCANIA SR3 SR4 AF2506 395773 E218L			837330
796	09/29/2015	549704	FILTER HYD COOLING FAN SCANIA SR3 (E90HD149)			837330
796	09/29/2015	549704	FILTER FUEL SCANIA L94UAB (H7090WK30)			837330
796	09/29/2015	549704	FILTER FUEL SCANIA SR4(H17WK04)			837330
796	09/29/2015	549704	FILTER OIL SCANIA SR4 EARLY K320 (LF3730)(2059778)(H200W20)			837330
796	09/29/2015	549704	FILTER P/STEER SCANIA VOLVO M/BENZ 0153468-1585618-0-153468			837330
796	09/29/2015	549704	FILTER TRANSMISSION ZF 4139-298-038/4139 298 038 01			837330
796	09/29/2015	549704	O-RING KIT OIL SPINNER FILTER SCANIA ABOVE ENG #6203050			837330
796	09/29/2015	549704	Service	C SERVICE AS PER CHECK LIST		837330
796	09/29/2015	549704	Consumables			837330
796	09/29/2015	549704	Consumables			837330
796	09/29/2015	549704	Consumables			837330
796	09/29/2015	549704	Service	B SERVICE AS PER CHECK LIST		837330
796	09/29/2015	549704	Consumables			837330
796	09/29/2015	549704	Consumables			837330
796	09/29/2015	549704	Consumables			837330
796	09/29/2015	549704	Service	A SERVICE AS PER CHECK LIST		837330
796	09/28/2015	549466	Accident (None)UNREPORTED ACCIDENT WORK REF 41745			836675
796	09/23/2015	548512	Update destination Files and Check display	COMPLETED CAMPAIGN		836675
796	09/08/2015	545778	Body (None) O/S seat mounting rail broken	remove and replace seat mount rail and repair broken seat mount bolts in body drill and tap new.		836675
796	09/07/2015	545353	Service	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		836675
796	09/07/2015	545353	FRONT AIR BAG SCANIA L94UAB			836675
796	09/07/2015	545353	Service	VEHICLE SAFETY INSPECTION		836675
796	09/07/2015	545573	Suspension Leaning o/s/f air bag needs replcing	replace o/s front air bag		836675
796	09/07/2015	545573	Body (None) seat base and pole to floor broken	weld up broken seat pole replace stripped bolts.		836675

796	09/07/2015	545573	FRONT AIR BAG SCANIA L94UAB			836675
796	09/07/2015	545573	Body (None) Rear seat needs securing	repair loose/broken salloon seating		836675
796	09/07/2015	545353	Consumables			837273
796	09/07/2015	545353	Consumables			837273
796	09/07/2015	545353	Consumables			837273
796	09/07/2015	545353	Service	A SERVICE AS PER CHECK LIST		836675
796	08/28/2015	543343	WHEEL ARCH BRUSH/ Mt			835749
796	08/27/2015	543343	Fluid Leaks (None) Engine oil leaking	nipped up loose sump bolts washed off run and checked ok		826919
796	08/27/2015	543343	Fluid Leaks (None) Transmission leaking oil	washed off and checked ok		826919
796	08/27/2015	543343	Consumables			835749
796	08/27/2015	536787	Consumables			835749
796	08/27/2015	536787	Elec and Light (None) next stop bell not working.	checked working ok		826919
796	08/27/2015	543343	Elec and Light Exterior Lights Rear outside step light dul	replaced light tube		826919
796	08/27/2015	543343	Body (None) Front wheel arch brushes need replacing	replaced both wheel arch brushes		826919
796	08/26/2015	543343	Fluid Leaks (None) Transmission leaking oil			826919
796	08/26/2015	543343	Fluid Leaks (None) Engine oil leaking			826919
796	08/26/2015	536787	Elec and Light (None) next stop bell not working.			826919
796	08/26/2015	536787	Elec and Light (None) next stop bell not working.			826919
796	08/26/2015	543343	Elec and Light Exterior Lights Rear outside step light dul	Replaced fluros		826919
796	08/26/2015	543343	Body Water Leaks RoofWater leaking in at windscreen.	rebook		826919
796	08/26/2015	543343	Body (None) Front wheel arch brushes need replacing			826919
796	08/26/2015	543343	Body (None) Front door guide rail needs replacing	Replaced guide rail		826919
796	08/25/2015	543343	Wipers and Washers Wiper inserts need replacing	replaced inserts		826919
796	08/25/2015	543343	Drv entered - AC Heating Not Heating	checked ok no fault found		826919
796	08/25/2015	543343	GLOBE WEDGE 24V 1.2W HLW241.2 (47706 SWFLED E-596WLED)			826919
796	08/25/2015	543343	TUBES FLUORESCENT 18W			826919
796	08/25/2015	543343	Elec and Light (None) Switch lights not working	replaced globes		826919
796	08/25/2015	543343	DECAL SAFETY TRIANGLES			826919
796	08/25/2015	543343	1MT MULTI FIT WIPER REFILL			826919
796	08/25/2015	543343	Elec and Light Interior Lights Saloon lights not working	replaced saloon light tubes x6		826919
796	08/25/2015	543343	Body (None) Dash cluster not screwed to dash	fitted screws		826919
796	08/25/2015	543343	Body (None) Safety triangle decal needs to be fitted	replaced decal		826919
796	08/21/2015	542585	Service	TRANSMISSION CHECK AS PER CHECK LIST		826919
796	08/21/2015	542585	Service	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		826919
796	08/21/2015	542585	Service	VEHICLE SAFETY INSPECTION		826919
796	08/21/2015	542585	FILTER FUEL SCANIA SR4(H17WK04)			826919
796	08/21/2015	542585	Consumables			834641
796	08/21/2015	542585	Consumables			834641
796	08/21/2015	542585	FILTER TRANSMISSION ZF 4139-298-038/4139 298 038 01			826919
796	08/21/2015	542585	O-RING KIT OIL SPINNER FILTER SCANIA			826919
796	08/21/2015	542585	FILTER OIL SCANIA SR4 EARLY K320 (LF3730)(2059778)(H200W20)			826919
796	08/21/2015	542585	Service	B SERVICE AS PER CHECK LIST		826919
796	08/21/2015	542585	Consumables			834641
796	08/21/2015	542585	Consumables			834641
796	08/21/2015	542585	Service	A SERVICE AS PER CHECK LIST		826919
796	08/20/2015	542284	Complete Campaign 6/15 A3 Marketing Poster Change	Complete		826919
796	08/20/2015	542238	Audit Route buses for correct Decals and positions. Replace	Complete		826919
796	08/13/2015	536787	GLOBE 24V 5W BAYONETT			832553
796	08/13/2015	536787	Elec and Light Exterior Lights top right park light n/w	Replaced globe		832553
796	08/10/2015	540234	Consumables			832187
796	08/10/2015	540234	GLOBE H1 24V 70W			831519
796	08/10/2015	540234	Elec and Light Exterior Lights - nearside headlight n/w	Replaced headlight globe		831519
796	07/11/2015	534957	WHEEL NUTS RE-TENSION Bookback from W/O:534957 Wheels and Ty	WHEEL NUTS RE-TENSIONED		824405
796	07/09/2015	534880	Service	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		824405
796	07/09/2015	534880	Service	VEHICLE SAFETY INSPECTION		824405
796	07/09/2015	534957	Consumables			825070
796	07/09/2015	534957	TYRE NEW 295/80R22.5			824405
796	07/09/2015	534957	Wheels and Tyres Wornn O/S/F tyre tread low	Replaced both front tyres and tensioned wheel nuts to specifications		824405
796	07/09/2015	534967	Engine stalling after restart	Checked fault codes reset edc unit checked ok		824405
796	07/09/2015	534880	Consumables			825070
796	07/09/2015	534880	Consumables			825070
796	07/09/2015	534880	Consumables			825070
796	07/09/2015	534880	Service	A SERVICE AS PER CHECK LIST		824405
796	06/25/2015	532859	L.E.D SIDE MARKER RED/AMBER			821444
796	06/25/2015	532859	Elec and Light - O/S rear clearance light missing	Replaced clearance light.		821444
796	06/22/2015	532143	TOGGLE SWITCH DASH 5/16th			821264
796	06/22/2015	532143	Engine not starting Fuel problem	Checked over stop switch u/s in rear control box fitted new switch		821264
796	05/29/2015	527206	Knob Control	Creditor #:IB-EAS003 EASTCOAST TRUCK & BUS SERVICE P/O #:V150943 Receiving #:156338 Date :2015-05-29		816309
796	05/23/2015	527206	Head light switch broke into pieces when driver turned ligh	Replaced head switch knob ex 735		815265
796	05/21/2015	527206	Elec and Light - Saloon light switches broken	Replaced head switch knob ex 735		813836
796	05/21/2015	527206	Elec and Light Exterior Lights Headlight switch broken.	Ordered parts		813836
796	05/16/2015	526108	Steering shaft needs replacing - wear in uni at steering box	Replaced shaft		813836
796	05/16/2015	526455	FILTER TRANSMISSION ZF (4139-298-038)(4139 298 038 01)			813836
796	05/16/2015	526455	Trans oil and filter need to be replaced	Service trans		813836
796	05/16/2015	526108	Indicators not self cancelling when turning right.	Checked indicator operation OK		813836
796	05/16/2015	526108	Front sensitive edge needs adjusting	Checked sensitive edge operation OK		813836
796	05/16/2015	526108	Perimeter seat trim come off	Secure seat base backs		813836
796	05/14/2015	526108	D-rubbers worn	Checked swaybar rubbers worn but ok		814023
796	05/14/2015	526108	Steering shaft needs replacing - wear in uni at steering box	Measured shaft & ordered parts		814023
796	05/14/2015	526108	Constant clicking at transmission accumulator solenoid	Washed engine & trans check wiring & clean contacts / connector plugs at retarder & accumulator solenoids		814023
796	05/14/2015	526108	GLOBE WEDGE 24V 1.2W HLW241.2 (47706 SWFLED E-596WLED)			814023
796	05/14/2015	526108	Door ok amd switch lights not working	Replaced switch light globes & resecure switch blocks		814023
796	05/14/2015	526108	O/S/F emergency exit hammer buzzer not connected	Checked hammer wiring & buzzer operation no fault found at this time		814023
796	05/14/2015	526108	N?S/R saloon light not working	Replaced fluro globe		814023
796	05/14/2015	526108	Front step light not working	Replaced fluro globe & fit new fluro tube end & modify wiring		814023
796	05/14/2015	526108	FLURO TUBE 36W			814023
796	05/14/2015	526108	TUBES FLUORESCENT 18W			814023
796	05/14/2015	526108	Tie Rod Angle Drive to Box	Creditor #:IB-EAS003 EASTCOAST TRUCK & BUS SERVICE P/O #:V150943 Receiving #:155369 Date :2015-05-14		813836
796	05/14/2015	526108	Decal Wheelchair Symbol Single sided print 120 x 120mm			814023
796	05/14/2015	526108	DECAL 2 WHEEL CHAIR SPACES			814023
796	05/14/2015	526108	DECAL-NO SMOKING			814023
796	05/14/2015	526108	N/S/R no smoking decal to be fitted	Fitted no smoking decal		814023
796	05/14/2015	526108	Front of bus disabled decal needs replacing	Removed old damaged decals & fitted new decals		814023

796	05/14/2015	525852	Consumables			814208
796	05/14/2015	525852	Consumables			814208
796	05/14/2015	525852	Service	finish part of service / safety inspection		814023
796	05/13/2015	525852	Service	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		813836
796	05/13/2015	525852	Service	VEHICLE SAFETY INSPECTION		813836
796	05/13/2015	525852	Service	B SERVICE AS PER CHECK LIST		813836
796	05/13/2015	525852	FILTER FUEL SCANIA SR4(H17WK04)			813836
796	05/13/2015	525852	O-RING KIT OIL SPINNER FILTER SCANIA			813836
796	05/13/2015	525852	FILTER OIL SCANIA SR3 (0173171)(173171)(H10W02)			813836
796	05/13/2015	525852	Consumables			814023
796	05/13/2015	525852	Consumables			814023
796	05/13/2015	525852	Service	A SERVICE AS PER CHECK LIST		813836
796	05/09/2015	525291	Replace See Something Say Something Poster	Replace See Something Say Something Poster		812503
796	04/21/2015	522375	INDICATOR SWITCH SCANIA L94UAB 40v4703			809029
796	04/21/2015	522375	Exterior Lights locked on stawk jammed.	Replaced indicator switch		809029
796	04/20/2015	522166	ALT DRIVE BELT L94UB			808730
796	04/20/2015	522166	Mechanic entered - Engine Belts_Loose Noisy Missing	Replaced damaged belt		808730
796	04/14/2015	519153	Engine idler pulley bearing to be replaced	eng idler replaced		807532
796	04/14/2015	519153	PULLEY IDLER K230			807532
796	04/14/2015	519153	BELT POLY SCANIA			807532
796	04/14/2015	519153	Engine belt to be relpaced	engine belt replaced		807532
796	04/08/2015	520058	WHEEL NUTS RE-TENSION Bookback from W/O:519723 Off side rear	WHEEL NUTS RE-TENSIONED		806704
796	04/07/2015	519723	Consumables			806704
796	04/07/2015	519723	EXTENSION FLEXIBLE TYRE VALVE 210mm LONG			806396
796	04/07/2015	519723	TYRE RECAP 295/80R22.5			806396
796	04/07/2015	519723	Off side rear tyres one tyre 40psi the other 60psi.	Replaced O/S/R tyres		806396
796	04/01/2015	519153	Engine idler pulley bearing to be replaced			805647
796	03/31/2015	519153	Drv entered - Suspension Kneeling System	Repair electrical		805647
796	03/31/2015	519153	Kneeling System not working.	Repair electrical		805647
796	03/31/2015	519153	Raise and Lower and Kneel buttons not operating.	Repair electrical		805647
796	03/31/2015	519153	Drv entered - Other	Repair electrical		805647
796	03/31/2015	519153	Consumables			805778
796	03/31/2015	519153	LIGHT DIFFUSER 3M LENGHT			805647
796	03/31/2015	519153	SYMBOL (REAR DOOR) SWF SWITCH			805647
796	03/31/2015	519153	GLOBE WEDGE 24V 1.2W HLW241.2 (47706 SWFLED E-596WLED)			805647
796	03/31/2015	519153	GLOBE WEDGE 24V 1.2W HLW241.2 (47706 SWFLED E-596WLED)			805647
796	03/31/2015	519153	COURTESY LAMP LED			805647
796	03/31/2015	519153	Height raise light on and will not kneel	Check connector on unit off. refit and secured		805647
796	03/31/2015	519153	Tacho lights not working	Replced globes		805647
796	03/31/2015	519153	Door ok light not working	Replaced globes		805647
796	03/31/2015	519153	Rear door switch lens missing	Fitted switch cover		805647
796	03/31/2015	519153	Saloon lights not working	Replaced fluro tube		805647
796	03/31/2015	519153	Front step light not working	Replaced with led lamp		805647
796	03/31/2015	519153	O/S/R light defuser not long	Replaced diffuser		805647
796	03/31/2015	519153	Consumables			805778
796	03/31/2015	519153	DECAL PRIORITY SEATING			805647
796	03/31/2015	519153	FLURO TUBE 24V 18W 24'			805647
796	03/31/2015	519153	O/S 3rd saloon seat bracket broken at floor	Removed bracket and weld.removed broken bolt and replaced		805647
796	03/31/2015	519153	Disabled decal to be replaced	replaced decal		805647
796	03/21/2015	517271	Consumables			804095
796	03/21/2015	517271	Next stop coming on when doors are closed automatically	Checked bell operation OK		803858
796	03/19/2015	516907	Service	TRANSMISSION CHECK AS PER CHECK LIST		803858
796	03/19/2015	516907	Service	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		803858
796	03/19/2015	516907	Service	VEHICLE SAFETY INSPECTION		803858
796	03/19/2015	516907	Consumables			803985
796	03/19/2015	516907	Consumables			803985
796	03/19/2015	516907	Consumables			803985
796	03/19/2015	516907	Service	A SERVICE AS PER CHECK LIST		803858
796	03/19/2015	516907	Service	A SERVICE AS PER CHECK LIST		803858
796	03/06/2015	515083	Consumables			801010
796	03/06/2015	515083	COMPLETE VEHICLE DETAILS AUDIT CHECK LIST	COMPLETE VEHICLE DETAILS AUDIT CHECK LIST		799860
796	03/02/2015	512404	GASKET REAR AXLE SCANIA 40F1300			797621
796	02/27/2015	513750	WHEEL NUTS RE-TENSION Bookback from W/O:512404 N/S/R/I tyre	WHEEL NUTS RE-TENSIONED		797621
796	02/26/2015	512404	Consumables			798744
796	02/26/2015	512404	TYRE RECAP 295/80R22.5			797621
796	02/26/2015	512404	N/S/R/I tyre damged	Replaced N/S/R tyres.		797621
796	02/26/2015	512404	WEAR SENSOR SCANIA DISC BRAKE 40G8401			797621
796	02/26/2015	512404	DISC PAD SET SCANIA MB0500			797621
796	02/26/2015	512404	FRONT DISC BRAKE ROTORS SCANIA(40F3319)			797621
796	02/26/2015	512404	BRAKE CALIPER L94 RHR/LHF			797621
796	02/26/2015	512404	BRAKE CALIPER L94 LHR/RHF			797621
796	02/26/2015	512404	Brake pad warning light on dash.	Greased bearings and hubs on O/S/R and fitted new calipers to brackets. Fitted O/S/R hub and rear brakes. N/S/R 133`c O/S/R 128`c.		797621
796	02/24/2015	512966	A3 Poster Change	campaign completed		797621
796	02/24/2015	512965	A3 Poster Change	campaign completed		797621
796	02/24/2015	512404	Brake pad warning light on dash.	Cleaned all hub parts. All ready for assembling.		797621
796	02/23/2015	512820	buzzer for next stop not working	Check all switch works fine		797621
796	02/23/2015	512404	Brake pad warning light on dash.	Stripped rear brakes and ordered parts.		797621
796	02/20/2015	512404	Brake pad warning light on dash.	Checked brakes. O/S/R has sensor melted on outer pad. N/S/R/I tyre side wall is split open.		797621
796	02/17/2015	511895	Consumables			798153
796	02/17/2015	511895	Locker door from driver's compartment door - hinge broken	Refitted drivers door		797621
796	02/12/2015	511122	Amber engine light on dash driver complaining of lack of p	Refer bus 766 fault		797061
796	02/10/2015	510766	Consumables			796823
796	02/10/2015	510766	Mirrors Exterior nearside attaching arm needs tightening.	Tighten mirror head		796630
796	02/09/2015	510398	Ops Entered - Accident - Collision in Yard - Arrive Lilydale			795357
796	02/08/2015	510398	L.E.D SIDE MARKER RED/AMBER			795357
796	02/08/2015	510398	Ops Entered - Accident - Collision in Yard - Arrive Lilydale	Fitted new light & repair damaged wiring		795357
796	01/31/2015	509254	Service	CCTV Hard Drive Check		794575
796	01/31/2015	509254	Service	Door Service		794575
796	01/22/2015	503413	Consumables			793727
796	01/22/2015	503413	Passenger Seat broken (offside front area)	Fitted up new wall rail and fitted up seat		793727
796	01/21/2015	503413	GLOBE WEDGE 24V 1.2W HLW241.2 (47706 SWFLED E-596WLED)			793727
796	01/21/2015	503413	GLOBE+HOLDER INSTRUMENT (GREY)			793727
796	01/21/2015	503413	Dash switch lights not working	Replaced globes		793727

796	01/21/2015	503413	Passenger Seat broken (offside front area)	Removed wall mount for seat removed u/s wall mount cut new wall mount to size		793727
796	01/21/2015	503413	First forward facing O/S seat loose at base	Replaced bollards with new ones and secured seat		793727
796	01/21/2015	503413	Water Leak above 1st forward facing seat on offside of bus i	Put in bus wash and checked for leak ok no leak found		793727
796	01/21/2015	503413	First forward facing O/S seat loose at base			793727
796	01/21/2015	503413	Passenger stop bell loose	Replaced missing mounting screw		793727
796	01/21/2015	503413	5th seat from rear O/S loose at base	Replaced missing seat base bollard		793727
796	01/20/2015	0	Imported Service History	Imported Service History		793727
796	01/20/2015	506714	AIR CONDITIONING REPAIR	Creditor #:IB-ABA001 AB AUTO AIR P/O #:V147588 Receiving #:149934 Date :2015-01-28 SPPLY AND REPLACE EVP FANS X 6		794005
796	01/20/2015	506714	Drv entered - Cool & AC Sys Poor	AB AUTO AIR REPLACED EVAP FANS		793727
796	01/20/2015	507624	O/S/F clearance light not working	Replace park light globe		793727
796	01/20/2015	507624	GLOBE 24V 5W BAYONETT			793727
796	01/20/2015	507590	Consumables			793727
796	01/20/2015	507590	Consumables			793727
796	01/20/2015	507590	OIL ENGINE DELO 400LE 15W40 (LU18)	Engine Oil		793727
796	01/20/2015	507590	Service	A - Service & Bus Safety Inspection complete		793727
796	01/20/2015	507590	FILTER FUEL SCANIA SR4(H17WK04)	Fuel Filter		793727
796	01/20/2015	507590	Service	Tension ALL Wheel Nuts to OEM Specs		793727
796	01/20/2015	507590	O-RING KIT OIL SPINNER FILTER SCANIA	Kit . filter Cent		793727
796	01/20/2015	507590	FILTER OIL SCANIA SR4 EARLY K320 (LF3730)(2059778)(H200W20)	Filter Oil		793727
796	01/20/2015	507590	HYDRAULIC TORQUE FLUID 414	Torque fluid		793727
796	01/20/2015	507590	FILTER TRANSMISSION ZF (4139-298-038)(4139 298 038 01)	Filter ZF Trans		793727
796	01/20/2015	507590	Consumables			793727
796	01/20/2015	507590	Consumables			793727
796	01/20/2015	507590	Service	Tension ALL Wheel Nuts to OEM Specs		793727
796	01/20/2015	507590	Service	A - Service & Bus Safety Inspection		793727
796	01/14/2015	506714	Drv entered - Air Cond Other	Refer to Fault # 516579		792720
796	01/14/2015	506714	Drv entered - Cool & AC Sys Poor	AB AUTO AIR REQUIRES EVAP FANS		792720
796	12/22/2014	503413	Passenger Seat broken (offside front area)	Removed seat seat mounting rail broken requires parts		788534
796	12/12/2014	500797	ADJUSTER DRIVERS SEAT	Creditor #:IB-EAS003 EASTCOAST TRUCK & BUS SERVICE P/O #:V146047 Receiving #:148473 Date :2014-12-12 929527-45		787713
796	12/12/2014	500797	SHOCKER ISRI SEAT	Creditor #:IB-EAS003 EASTCOAST TRUCK & BUS SERVICE P/O #:V146047 Receiving #:148473 Date :2014-12-12		787713
796	12/11/2014	499444	AIR CONDITIONING REPAIR	Creditor #:IB-ABA001 AB AUTO AIR P/O #:V146480 Receiving #:149075 Date :2015-01-02 REPAIRED GAS LEAK CHARGE AND TEST SYSTEM		789858
796	12/11/2014	499444	Service	AB AUTO REPAIRED A?G GAS LEAK AS REQUIRED CHARGE AND TEST SYSTEM OK		787532
796	12/09/2014	500797	Service			786108
796	12/08/2014	500436	DIRECT PURCHASE - BUS INSPECTI	Creditor #:IB-ROA003 ROAD SAFETY INSPECTIONS P/L P/O #:V146300 Receiving #:148643 Date :2014-12-18		788290
796	12/08/2014	500797	Drv entered - Suspension Hard	Checked suspension ok		786108
796	12/08/2014	500797	Drv entered - Body & Acc Drivers Seat Cushion	Replaced drivers seat reco'd ex 797 and ordered new shock for old seat.		786108
796	12/07/2014	500436		RSI INSPECTION [R.W.C # 336179]		786108
796	12/07/2014	500436		RSI INSPECTION [R.W.C # 336179]		786108
796	12/07/2014	0	Imported Service History	Imported Service History		786108
796	12/03/2014	500049	Complete AM/FM radio saloon speaker modification	Completed Campign		785844
796	12/01/2014	499444	Bus seems to be bottoming out on shockers.	Roadtested to check for bus bottoming out ok		785087
796	12/01/2014	499444	A/C blowing warm air	Checked over A/C system Low on gas requires repair by A/C technician		785087
796	12/01/2014	499444	A/C NOT WORKING	Refer to to Fault # 509022		785087
796	12/01/2014	499444	Drivers seat set to drivers weight seems to be bottoming out	Checked drivers seat ok		785087
796	11/16/2014	497324	Remove old decal and fit new Authorised Officers Decal DO N	Completed Campaign		782135
796	11/16/2014	497323	Remove Legacy Poster and replace with See Something Say So	Completed Campaign		782135
796	11/14/2014	496133	SCANIA ALT BELT TENSIONER K124	Creditor #:IB-EAS003 EASTCOAST TRUCK & BUS SERVICE P/O #:V145160 Receiving #:147448 Date :2014-11-14 38564 RP WALLIS		781209
796	11/12/2014	496133	A/C filter needs replacing	Replace a/c filter		781164
796	11/12/2014	496133	Front door front leaf sensitive not working	Sensitive edge strip full of water		781164
796	11/12/2014	496133	O/S/L brake light dull	Inspect all stop lights all ok		781164
796	11/12/2014	496133	Alt belt Tensioner pulley noisy	Replace alt tensioner bearing		781164
796	11/12/2014	496133	Grab handle clamp broken O/S	Repair passenger grab handles		781164
796	11/12/2014	496133	Panel above front door not secure	Repair broken door panel above front door		781164
796	11/11/2014	495875	1MT MULTI FIT WIPER REFILL			781164
796	11/11/2014	495875	Wiper refill needs replacing	Replace wiper blades		781164
796	11/11/2014	495875	Graffiti on o/s/r seat back	Remove graffiti inside rear of bus repair rear seat		781164
796	11/11/2014	495875	N/S/R seat base damaged	Repaired damaged seat		781164
796	11/11/2014	495875	Wash and check engine oil leaks	Wash drive inspect engine for leaks		781164
796	11/11/2014	495875	Drive selector button light not working	Replace gear selector light globe		781164
796	11/11/2014	495875	GLOBE WEDGE 24V 1.2W HLW241.2 (47706 SWFLED E-596WLED)			781164
796	11/11/2014	495875	FLURO TUBE 24V 18W 24'			781164
796	11/11/2014	495875	Front Step light not working	Replace step light globe		781164
796	11/11/2014	495875	Switch ligt not working	Replace dash light globe		781164
796	11/11/2014	495875	N/S tacho light not working	Replaced globe		781164
796	11/11/2014	495875	Drivers blind guide rail on nearside hanging loose.	Repair drivers blind		781164
796	11/11/2014	495875	N/S mirror vibrating at idle	Repair mirror mount tighten loose mount		781164
796	11/11/2014	495875	vynal under rubbish bin peeling	Stick down vynal flooring neer front bin		781164
796	11/11/2014	495845	Service	Door Service		781164
796	11/11/2014	495845	Service	CCTV Hard Drive Check		781164
796	11/11/2014	495884	Consumables			0
796	11/11/2014	495884	Consumables			0
796	11/11/2014	495884	Consumables			0
796	11/11/2014	495884	Consumables			0
796	11/11/2014	495884	Service	Tension ALL Wheel Nuts to OEM Specs		781164
796	11/11/2014	495884	Service	A - Service & Bus Safety Inspection		781164
796	11/07/2014	495167	Service	Inspect vehicle as per RSI Checklist		780779
796	11/07/2014	492673	STABILIZER BAR BUSH FRONT L94UAB			780779
796	11/07/2014	492673	Front sway bar D rubbers needs replacing	Replaced D rubber bushes.		780779
796	11/01/2014	492673	Bearing Front Wheel Series 4	Creditor #:IB-EAS003 EASTCOAST TRUCK & BUS SERVICE P/O #:V144707 Receiving #:147062 Date :2014-11-01		779498
796	11/01/2014	492673	BRAKE CALIPER SCANIA	Creditor #:IB-EAS003 EASTCOAST TRUCK & BUS SERVICE P/O #:V144707 Receiving #:147062 Date :2014-11-01		779498
796	11/01/2014	492673	BRAKE CALIPER OSF	Creditor #:IB-EAS003 EASTCOAST TRUCK & BUS SERVICE P/O #:V144707 Receiving #:147062 Date :2014-11-01		779498
796	10/29/2014	493407	Wheel Nuts Re-Tension Bookback from W/O:492730 N/S/F brake c	Wheel Nuts Re-Tensioned		778580
796	10/27/2014	492730	N/S/F brake cailper holding	Refitted o/s/f hub replaced rotor and pads		778150
796	10/27/2014	492730	DISC PAD SET SCANIA MB0500			778150
796	10/27/2014	492730	WEAR SENSOR SCANIA DISC BRAKE 40G8401			778150
796	10/27/2014	492730	N/S/F brake cailper holding	Replaced calipers wheel bearings and brake pads road tested N/S/F 73 dec C O/S/F 78 deg C		778150
796	10/24/2014	492761	A/C not blowing air into the Bus	Check ok		778150
796	10/24/2014	492730	Consumables			0
796	10/24/2014	492730	Fire extingusher used	Replaced fire extingusher		778150
796	10/24/2014	492730	Ops Entered - Breakdown - Breakdown Change Over Request - R	Went to Chirnside Park S/C wound off N/S/F brake caliper and returned with bus to depot		778150
796	10/24/2014	492730	N/S/F brake cailper holding	Strip o/s/f brakes and replace wheel bearing		778150
796	10/24/2014	492730	N/S/F brake cailper holding	Disasemable front brakes		778150
796	10/24/2014	492730	FRONT DISC BRAKE ROTORS SCANIA(40F3319)			778150

796	10/21/2014	492061	Drv entered - Steering Pulls Left	Road test checked brake temps n/s/f114 and o/s/f111 checkedtyrepressures ok to run		777190
796	10/02/2014	488894	Graffiti at rear seat	Cleaned graffiti from rear seats and wall		773540
796	10/02/2014	488894	Check play in steering column unis	Checked steering column unis ok at this time		773540
796	10/02/2014	488894	Wash and check engine oil leaks	Washed engine roadtest checked leaks ok at this time		773540
796	10/02/2014	488894	Dash swicthes needs securing	Secured dash switches as required		773540
796	10/02/2014	488894	GLOBE WEDGE 24V 1.2W HLW241.2 (47706 SWFLED E-596WLED)			773540
796	10/02/2014	488894	WHEEL ARCH BRUSH/ Mt			773540
796	10/02/2014	488894	Dash light not working	Replaced dash light globes		773540
796	10/02/2014	488894	Check wiring to first N/S em exit hammer	Checked wiring and emergency hammer alarm function ok at this time		773540
796	10/02/2014	488894	Consumables			0
796	10/02/2014	488894	Rear seat base needs securing	Secured rear seat base as required		773540
796	10/02/2014	488894	Front wheel arch bushes needs replacing	Replaced front wheel arch brushes both sides		773540
796	10/02/2014	488894	Slight Air leak at O/S/R booster	Tightened clamp on o/s/r brake booster and checked for air leaks ok		773540
796	09/30/2014	488193	Service	Transmission /check as per Check List		772825
796	09/30/2014	488192	Service	A - Service & Bus Safety Inspection		772825
796	09/30/2014	488192	Service	Tension ALL Wheel Nuts to OEM Specs		772825
796	09/30/2014	488192	Service	A - Service & Bus Safety Inspection		772825
796	09/29/2014	488192	ENGINE OIL DELO 400LE 15W40 (LU18)	Engine Oil		772825
796	09/29/2014	488192	FILTER FUEL K124 / LU94A (1411894 / H17WK05)	Fuel Filter		772825
796	09/29/2014	488192	FILTER TRANSMISSION ZF 4139-298-038E39HD119	Filter ZF Trans		772825
796	09/29/2014	488192	HYDRAULIC TORQUE FLUID 414	Torque fluid		772825
796	09/29/2014	488192	FILTER OIL K124 / L94UAB (H200W20)2059778	Filter Oil		772825
796	09/29/2014	488192	O RING FILTER KIT K93	Kit . filter Cent		772825
796	09/19/2014	486680	GIVE WAY SIGN (LARGE)			771382
796	09/19/2014	486680	GLOBE WEDGE 24V 1.2W HLW241.2 (47706 SWFLED E-596WLED)			771382
796	09/19/2014	486680	FLURO TUBE 24V 18W 24			771382
796	09/19/2014	486680	Nearside Headlight not working.	C heck and adjusted		771382
796	09/19/2014	486680	rear door step light not working	Replaced tube and replaced saloon light fluro tube		771382
796	09/19/2014	486680	Battery flat and not starting from key with jump batteries	Check battery ok. adjusted engine hatch isolator switch		771382
796	09/19/2014	486680	Engine tray needs securing	Tray mount secured		771382
796	09/19/2014	486680	Give way deacl needs replacing	Replaced decal		771382
796	09/19/2014	486680	2nd forward facing O/S saloon seat loose	Secured seat mount		771382
796	09/15/2014	485866	Drv entered - Elec & Light Headlights	Replaced globe		770407
796	09/15/2014	485866	GLOBE H1 24V 70W			770407
796	09/10/2014	484956	Service	Tension ALL Wheel Nuts to OEM Specs		770032
796	09/10/2014	484956	Service	A - Service & Bus Safety Inspection		770032
796	08/23/2014	481685	Remove old A3 poster & replace with Legacy or Penalty Fares	Completed campaign		765594
796	08/22/2014	480979	Engine & transmission need washing & checking for leaks?	Washed checked not excessive		765594
796	08/22/2014	481499	LIGHT DIFFUSER 3M LENGHT			765594
796	08/22/2014	481499	saloon light cover broken	Replaced diffuser		765594
796	08/20/2014	480979	Ops Entered - Fault - Body & Acc Drivers Seat Mount - Route	Inspected drivers seat - could not fault		765351
796	08/20/2014	480973	Service	CCTV Hard Drive Check		765351
796	08/20/2014	480973	Service	Door Service and repairs		765351
796	08/02/2014	477905	Wipers condition & operation needs checking?	Checked wiper & washer operation filled washer bottle & bleed washers working OK		762599
796	08/02/2014	477905	Graffiti on rear passenger seats	Removed graffiti		762599
796	08/02/2014	477905	FLURO TUBE 24V 18W 24'			762599
796	08/02/2014	477905	GLOBE WEDGE 24V 1.2W			762599
796	08/02/2014	477905	Switch lights & front door switch light N/W	Replaced globes		762599
796	08/02/2014	477905	Front door step light N/W	Replaced fluro tube		762599
796	08/02/2014	477905	Drv entered - Elec & Light Cab Light	Refer to fault # 492067		762599
796	08/02/2014	477905	Drv entered - Elec & Light Interior Lights	Replaced saloon light fluro tubes		762599
796	07/23/2014	476094		A - Service & Bus Safety Inspection		760909
796	07/23/2014	476094		Tension ALL Wheel Nuts to OEM Specs		760909
796	07/23/2014	476094		A - Service & Bus Safety Inspection		760909
796	07/12/2014	473987	Fit Wheel Nut Pointers to all wheel nuts on the front axle	Completed campaign		758758
796	07/12/2014	473987	Fit Tyre Valve Extensions To All Inner Rear Axle Wheels	Completed campaign		758758
796	07/12/2014	473987	Remove Fair Evasion A3 Poster & Replace with MYKI AUTO TOP	Completed campaign		758758
796	07/12/2014	473987	Fit New Myki Decal as Per PTV fitting instructions	Completed campaign		758758
796	07/12/2014	473987	Fit Myki decals as requiredFit Recruitment decal as requi	Completed campaign		758758
796	06/18/2014	468407	COVER	Creditor #:IB-EAS003 EASTCOAST TRUCK & BUS SERVICE P/O #:V139258 Receiving #:142057 Date :2014-06-18		753958
796	06/14/2014	468407	Rear seat base damaged and needs securing and frame cracked	Weld up seat frame		752634
796	06/14/2014	468407	Engine oil filler cap needs replacing	Replaced filler cap		752634
796	06/14/2014	468407	GLOBE WEDGE 24V 1.2W			752634
796	06/14/2014	468407	Switch lights not working	Replaced globe		752634
796	06/14/2014	468407	O/S rear bumper needs securing	Secured bumper		752634
796	06/12/2014	468407	Rear seat base damaged and needs securing and frame cracked	Replaced base frame needs welding		752634
796	06/12/2014	468407	Wash and check engine and trans oil leaks	Washed check ok		752634
796	06/12/2014	468407	Drivers sun blind needs securing	Secured sun blind		752634
796	06/11/2014	468035	FILTER OIL K124 / L94UAB (H200W20)2059778	Filter Oil		752228
796	06/11/2014	468035	HYDRAULIC TORQUE FLUID 414	Torque fluid		752228
796	06/11/2014	468035	FILTER FUEL K124 / LU94A (1411894 / H17WK05)	Fuel Filter		752228
796	06/11/2014	468035	ENGINE OIL DELO 400LE 15W40 (LU18)	Engine Oil		752228
796	06/11/2014	468035	Service	Tension ALL Wheel Nuts to OEM Specs		752228
796	06/11/2014	468035	Service	A - Service & Bus Safety Inspection		752228
796	06/11/2014	468035	FILTER TRANSMISSION ZF 4139-298-038E39HD119	Filter ZF Trans		752228
796	06/11/2014	468035	O RING FILTER KIT K93	Kit . filter Cent		752228
796	06/11/2014	468035	Service	A - Service & Bus Safety Inspection		752228
796	06/11/2014	468035	Service	A - Service & Bus Safety Inspection		752228
796	06/02/2014	466660	O/S headlight not working.	Replaced head light globe		750690
796	06/02/2014	466660	GLOBE H1 24V 70W			750690
796	05/30/2014	466256	FLURO INVERTER 24V 40W			750436
796	05/30/2014	466256	FLURO TUBE 24V 18W 24'			750436
796	05/30/2014	466256	Saloon lghts not working	Replaced fluro tube and inverter working OK		750436
796	05/26/2014	441532	FITTING	Creditor #:IB-MIC002 MICHELIN AUSTRALIA P/O #:V133577 Receiving #:141037 Date :2014-05-26		749677
796	05/26/2014	441532	295/80R22.5 RECAMIC DRIVE PATT	Creditor #:IB-MIC002 MICHELIN AUSTRALIA P/O #:V133577 Receiving #:141037 Date :2014-05-26		749677
796	05/26/2014	465030	Service			749560
796	05/26/2014	465030	Service	Tension ALL Wheel Nuts to OEM Specs		749560
796	05/26/2014	465030	Service	A - Service & Bus Safety Inspection		749560
796	05/22/2014	464557		CCTV Hard Drive Check		749221
796	05/22/2014	464557		Door Service		749221
796	05/17/2014	463701	Perform Campaign 1_14 School Bus Light Globe Check Check	Completed campaign		748416
796	05/17/2014	463700	Remove A3 Marketing Poster CATCHING A BUSFit A3 Marketing	Completed campaign		748416
796	05/07/2014	461553	Drv entered - Air Cond Air Conditioner	Checked A/C operation working OK		746145

796	05/07/2014	443560	Transmission output shaft seal leaking	Checked for leaks OK at this time		746145
796	05/07/2014	461553	Amber engine light on	Road tested no engine light came on checked fault codes 22 28 32 33 and 61 cleared fault codes		746145
796	05/01/2014	456445	MINOR REPAIR PUNCTURE	Creditor #:IB-MIC002 MICHELIN AUSTRALIA P/O #:V137635 Receiving #:140223 Date :2014-05-06		746107
796	04/23/2014	459211	Drv entered - Other	Refer to fault # 474027		744708
796	04/23/2014	459211	GLOBE WEDGE 24V 1.2W			744708
796	04/23/2014	459211	Lights too bright affecting drivers vision.	Replaced globes		744708
796	04/23/2014	459211	Drv entered - Comm Equip Controls	Checked 2way operation working OK at this time		744708
796	04/11/2014	457638	Graffiti on seats in front of rear seat.	Removed graffiti		743126
796	04/11/2014	457638	Driver's cabin door not opening.	Repaired drivers door latch		743126
796	04/10/2014	457395		Transmission /check as per Check List		742912
796	04/07/2014	456445	N/S/F tyre punctured	Replaced N/S/F tyre using new steer tyre		742131
796	04/03/2014	455965	GLOBE WEDGE 24V 1.2W			741306
796	04/03/2014	455965	GLOBE 24V 5W BAYONETT			741306
796	04/03/2014	455965	Switch and door ok lights not working	Replaced globes		741306
796	04/03/2014	455965	O/S/F top parker light not working	Replaced globe		741306
796	04/03/2014	455965	Drivers seat base has excessive movent up and down	Checked over drivers seat tightened pivot bolts OK		741306
796	04/03/2014	455756	HYDRAULIC TORQUE FLUID 414	Hydraulic oil		741306
796	04/03/2014	455756	Diff Oil Borate EP 460	diff oil		741306
796	04/03/2014	455756	Service	Service as per check list		741306
796	04/03/2014	455756	FILTER AIR DRYER KIT(HALDEX)	Filter Air Dryer		741306
796	04/03/2014	455756	FUEL FILTER ELEMENT SCANIA L94UAB/volvo (R90T / H7090WK10)	Raycor filter		741306
796	04/03/2014	455756	FILTER K124EB HYD COOLING FAN	Hydraulic filter		741306
796	04/03/2014	455756	POWER STEERING FILTER VOLVO	Power steering filter		741306
796	04/03/2014	455756	Service	Tension ALL Wheel Nuts to OEM Specs		741306
796	04/03/2014	455756	Service	A - Service & Bus Safety Inspection		741306
796	03/31/2014	455024	W/S washers N/W	Replaced washer hose bleed & checked operation working OK		740640
796	03/31/2014	455024	Engine needs washing & checking for leaks?	Washed engine road tested & checked for leaks no leaks found at this time		740640
796	03/31/2014	455024	O/S/F emergency exit hammer buzzer N/W	Repaired wiring connection to hammer switch working OK		740640
796	03/31/2014	455024	DECAL BREAK GLASS WITH ROCK			740640
796	03/31/2014	455024	WINDSCREEN WASHER HOSE BLACK per mt			740640
796	03/31/2014	455024	Rear window external rock decal peeling off	Replaced decal		740640
796	03/31/2014	455024	N/S/R passenger seat base needs securing & latch needs secur	Adjusted and secured latch & seat bases		740640
796	03/31/2014	455024	Drv entered - Body & Acc Drivers Seat Mount	Checked seat mount OK at this time		740640
796	03/31/2014	454960		Tension ALL Wheel Nuts to OEM Specs		740640
796	03/31/2014	454960		A - Service & Bus Safety Inspection		740640
796	03/24/2014	453781	VALVE SOLENOID ELC			739301
796	03/24/2014	453781	Suspension raise/lower not working	Traced fault replaced soleniod valve & checked for leaks and operation working ok		739301
796	03/19/2014	452901		Adjust Tappets		738627
796	03/19/2014	452774		Adjusted tappets		738627
796	03/19/2014	447713	Direct Purchase - MECHANICAL	Creditor #:IB-AIR001 AIR ANYWHERE P/O #:V136652 Receiving #:138470 Date :2014-03-25 PLEASE CARRY OUT WHHEL ALIGNMENT		739341
796	03/19/2014	452951	Rectify steering shimmy	Changed front tyres and brakes pads		733954
796	03/19/2014	452951	Rectify steering shimmy	replaced tyres (supplied by ibl) alignment carried out		733954
796	03/19/2014	447713	Steering wheel very shimmy on rough roads	Refer to fault # 465570		733954
796	03/19/2014	447713	Drv entered - Steering Shimmy	Checked over steering components replaced front wheels & organised wheelalignment replaced front brake pads road tested & checked for shimmy OK at this time		733954
796	03/19/2014	452960	front brake pads worn			733954
796	03/19/2014	452960	front brake pads worn	replace front brake pads		733954
796	03/18/2014	452774		Adjusted tappets		738627
796	03/01/2014	443560	AIR CONDITIONING REPAIR	Creditor #:IB-ABA001 AB AUTO AIR P/O #:V136207 Receiving #:137833 Date :2014-03-11 REPAIRED LEAK AT H/P SWITCH & PIPE SUPPORT MOUNT		737718
796	03/01/2014	447713	TIE ROD ASSY K230	Creditor #:IB-EAS003 EASTCOAST TRUCK & BUS SERVICE P/O #:V134443 Receiving #:137020 Date :2014-02-21		735118
796	03/01/2014	445065	Repair Kit Scania Hydraulic fa	Creditor #:IB-EAS003 EASTCOAST TRUCK & BUS SERVICE P/O #:V134443 Receiving #:137020 Date :2014-02-21		735118
796	02/25/2014	449278	Driver compartment door	Repaired and secured drivers compartment door		735416
796	02/25/2014	449248		CCTV Hard Drive Check		735416
796	02/25/2014	449248		Door Service		735416
796	02/17/2014	447713	Engine needs washing & checking for leaks?	Washed engine and checked		733954
796	02/17/2014	447713	Dash switches need securing	Secured switches on dash		733954
796	02/17/2014	447713	HORN 24V HELLA			733954
796	02/17/2014	447713	FLURO TUBE 24V 18W 24			733954
796	02/17/2014	447713	Horn needs attention quiet?	Replaced horn fitted new		733954
796	02/17/2014	447713	Saloon light N/W	Replaced fluro tube		733954
796	02/17/2014	447713	N/S/F emergency exit hammer buzzer N/W	Cleaned switch on hammer holder		733954
796	02/17/2014	447713	N/S Mirror requires tightening on pole.	Secured and tighened n/s mirror		733954
796	02/17/2014	447713	Drv entered - Body & Acc Mirrors Exterior	Secured mirror		733954
796	02/07/2014	446423	FILTER FUEL K124 / LU94A (1411894 / H17WK05)	Fuel Filter		732768
796	02/07/2014	446423	ENGINE OIL DELO 400LE 15W40	Engine Oil		732768
796	02/07/2014	446423		Tension ALL Wheel Nuts to OEM Specs		732768
796	02/07/2014	446423		A - Service & Bus Safety Inspection		732768
796	02/07/2014	446423	HYDRAULIC TORQUE FLUID 414	Torque fluid		732768
796	02/07/2014	446423	O RING FILTER KIT K93	Kit . filter Cent		732768
796	02/07/2014	446423	FILTER OIL K124 / L94UAB (H200W02)	Filter Oil		732768
796	02/07/2014	446423	FILTER TRANSMISSION ZF 4139-298-038E39HD119	Filter ZF Trans		732768
796	02/07/2014	446423		A - Service & Bus Safety Inspection		732768
796	02/03/2014	443560	Drv entered - Air Cond Air Conditioner	Refer to fault # 461102		732036
796	02/03/2014	443560	BELT FAN 21/32X93MM			732036
796	02/01/2014	445065	TOW BUS TO DEPOT	Creditor #:IB-EAG001 EAGLE TOWING AND SALVAGE P/O #:V134582 Receiving #:136488 Date :2014-02-07 Tow bus from Waverley Gardens to Lilydale depot (ECTB attended breakdown 28/01/2014)		732768
796	01/31/2014	445468	MIRROR METAGAL L/H (UES1411E)			731802
796	01/31/2014	445468	Nearside external mirror bottom spotter mirror cracked.	Replaced mirror head		731802
796	01/29/2014	445065	Hydraulic fluid leak at fan pump	Traced hydraulic leak replaced hydraulic relief valve using S/H parts washed engine & back of bus road tested OK		731374
796	01/25/2014	444727	Remove A3 Hold On Poster and Fit A3 Catching a bus poster	Completed campaign		730782
796	01/23/2014	444363	Drv entered - Vandalism Graffiti	Cleaned off graffiti		730455
796	01/16/2014	443560	Drv entered - Air Cond Cooling Fault Light	AB Auto Air traced fault replaced A/C belts secured A/C hoses & pipes resealed fittings rechecked for leaks recharged A/C system working OK		729756
796	01/16/2014	443560	Drv entered - Air Cond Cooling Fault Light	Refer to fault # 461102		729756
796	01/16/2014	443560	Air Conditioner not cool	Refer to fault # 461102		729756
796	01/16/2014	443560	Air Conditioner - not cool.	Refer to fault # 461102		729756
796	01/16/2014	443560	Drv entered - Air Cond Air Conditioner	Refer to fault # 461102		729756
796	01/16/2014	443560	Transmission output shaft seal leaking	Washed off transmission and checked for leaks ok to run but output sealneeds needs rechecking for leaks OK		729756
796	01/11/2014	442917	BATTERY 800CCA			729014
796	01/11/2014	442917	Battery condition needs checking?	Tested batteries U/S replaced batteries & jump cable checked charge rate OK		729014
796	01/10/2014	442797	GLOBE 24V 5W BAYONETT			729014
796	01/10/2014	442797	N/S top clearance light N/W	Replaced globe		729014
796	01/10/2014	442787		A - Service & Bus Safety Inspection		729014
796	01/10/2014	442787		A - Service & Bus Safety Inspection		729014
796	01/10/2014	442787		Tension ALL Wheel Nuts to OEM Specs		729014
796	01/05/2014	441963		RSI Inspection (RWC # 676408)		728219

796	01/05/2014	441963	SWITCH INSERT DOOR ALARM RED		728219
796	01/05/2014	441963	LAMP DOUBLE WARNING SWF		728219
796	01/05/2014	441963	GLOBE WEDGE 24V 1.2W		728219
796	01/04/2014	441952	Remove BTS Equipment Fuses	Removed fuses	728219
796	12/31/2013	441532	TYRE VALVE EXTENSION 210mm LONG		727789
796	12/31/2013	441532	O/S/R/O tyre side wall blown out	Replaced both O/S/R tyres using new caps	727789
796	12/19/2013	439924	N/S high beam head light needs replacing reflector U/S	Replaced n/s head light	726273
796	12/18/2013	439924	H7 MAIN BEAM 24V 90MM POS.	Creditor #:IB-MUL001 MULTISPARES LIMITED P/O #:V133173 Receiving #:134640 Date :2013-12-18	726273
796	12/18/2013	439924	PLASTIC STEP EDGE YELLOW		726033
796	12/17/2013	439852		Inspect vehicle as per RSI Checklist	726033
796	12/17/2013	439924	Emergency exit lights dull	Replaced led lamp	726033
796	12/17/2013	439924	LIGHT DIFFUSER 3M LENGHT		726033
796	12/17/2013	439924	FLURO TUBE 18W		726033
796	12/17/2013	439924	LED FRONT POSITION MARKER LIGHT		726033
796	12/17/2013	439924	Reverse beeper N/W	Replaced terminal connector working OK	726033
796	12/17/2013	439924	2 saloon lights N/W	Replaced fluro tube and replaced diffuser	726033
796	12/17/2013	439924	O/S/R ducting broken & falling down	Repaired and secured ducting	726033
796	12/17/2013	439924	DO NOT OVERTAKE TURNING DECAL		726033
796	12/17/2013	439924	1st N/S grab handle broken	Replaced handle	726033
796	12/17/2013	439924	DNOT decal needs replacing	Replaced decal	726033
796	12/17/2013	439924	Trim coming away from front ramp area	Replaced ruber trim	726033
796	12/05/2013	437850		CCTV Hard Drive Check	724145
796	12/05/2013	437850		Door Service	724145
796	12/03/2013	436714	DISPOSAL CHARGE	Creditor #:IB-MIC002 MICHELIN AUSTRALIA P/O #:V132536 Receiving #:134144 Date :2013-12-04	723926
796	12/03/2013	436714	FITTING	Creditor #:IB-MIC002 MICHELIN AUSTRALIA P/O #:V132536 Receiving #:134144 Date :2013-12-04	723926
796	12/03/2013	436714	295/80R22.5 RECAMIC DRIVE PATT	Creditor #:IB-MIC002 MICHELIN AUSTRALIA P/O #:V132536 Receiving #:134144 Date :2013-12-04	723926
796	11/27/2013	436714	N/S/R/O tyre side wall worn	Replaced both N/S/R tyres using new caps	722735
796	11/26/2013	436399	SCANIA L94UAB V STAY BUSH KIT		722735
796	11/26/2013	436399	TORQUE ROD BUSH SUIT V STAY SCANIA		722735
796	11/26/2013	436399	V-BAR BUSH NEEDS REPLACING	Replaced V bar bushes & refitted bar	722735
796	11/26/2013	436399	V-BAR BUSH NEEDS REPLACING	Attempted to remove V bar	722735
796	11/25/2013	436399	V-BAR BUSH NEEDS REPLACING	Started to remove V bar	722735
796	11/25/2013	436399	V-BAR BUSH NEEDS REPLACING	Assisted in setting up for V bar replacement	722735
796	11/20/2013	434328	REPAIR/REPLACE SEAT COVER/FOAM	Creditor #:IB-TRI001 TRIM IMPROVEMENTS P/O #:V132088 Receiving #:133561 Date :2013-11-21	722374
796	11/18/2013	435462	Drv entered - Steering Shimmy	Road tested & checked for steering shimmy could not fault at this time	721698
796	11/18/2013	435447	Engine & transmission need washing & checking for leaks?	Washed off transmission and engine road tested and checked for leaks ok	721698
796	11/18/2013	435447	Rear external step light N/W	Refitted light tube working ok	721698
796	11/18/2013	435447	Switch light N/W	Replaced globe	721698
796	11/18/2013	435447	GLOBE WEDGE 24V 1.2W		721698
796	11/18/2013	435447	Interior cover above rear door needs securing	Replaced screws with bolts	721698
796	11/14/2013	434940		Tension ALL Wheel Nuts to OEM Specs	721381
796	11/14/2013	434940		A - Service & Bus Safety Inspection	721381
796	11/11/2013	434328	Drv entered - Wipers & Washers Washers Not Working	Filled washer bottle & checked washer operation OK	720613
796	11/11/2013	434328	Drv entered - Vandalism Graffiti	Cleaned graffiti and replaced slashed seat bases	720613
796	11/08/2013	433920	Squealing noise in rear wheels.	Checked for noise slight brake squeal checked pads ok washed out brake dust	720082
796	10/24/2013	430788	N/S/F & O/S/F sway bar links needs replacing	Replaced sway bar links	717409
796	10/19/2013	431116	Remove A3 Poster 15/8Fit Poster (HOLD ON) as per Campaign	Completed campaign	716472
796	10/18/2013	430788	LINK SWAY BAR	Creditor #:IB-MUL001 MULTISPARES LIMITED P/O #:V130880 Receiving #:132249 Date :2013-10-18	716472
796	10/17/2013	430788	N/S/F & O/S/F sway bar links needs replacing	Ordered new sway bar links	716136
796	10/17/2013	430788	V bar bush needs replacing	Checked bush worn but still ok for service	716136
796	10/05/2013	428702	Perform sticker audit on vehicles ensuring that correct sti	Carried out campaign	714773
796	09/30/2013	425035	IMAGE RELATED REPAIRS TO BUSES	Creditor #:IB-TRA001 TRANSCAL P/O #:V128939 Receiving #:131567 Date :2013-10-02	714059
796	09/27/2013	427404	Graffiti on passenger seat backs	Removed graffiti	713442
796	09/27/2013	427404	A/C hoses & pipes need securing at O/S/R wall panel	Secured hoses	713442
796	09/27/2013	427404	FLURO TUBE 18W		713442
796	09/27/2013	427404	Saloon light N/W	Replaced saloon light fluro tubes	713442
796	09/26/2013	427273	FILTER AIR SCANIA USE AF25066		713442
796	09/26/2013	427273	FILTER OIL K124 / L94UAB (H200W02)	Filter Oil	713442
796	09/26/2013	427273	HYDRAULIC TORQUE FLUID 414	Torque fluid	713442
796	09/26/2013	427273	FILTER TRANSMISSION ZF 4139-298-038E39HD119	Filter ZF Trans	713442
796	09/26/2013	427273	FILTER FUEL K124 / LU94A (1411894 / H17WK05)	Fuel Filter	713442
796	09/26/2013	427273	O RING FILTER KIT K93	Kit . filter Cent	713442
796	09/26/2013	427273	ENGINE OIL DELO 400LE 15W40	Engine Oil	713442
796	09/26/2013	427273		Tension ALL Wheel Nuts to OEM Specs	713442
796	09/26/2013	427273		A - Service & Bus Safety Inspection	713442
796	09/26/2013	427273		A - Service & Bus Safety Inspection	713442
796	09/23/2013	426577		Transmission /check as per Check List	712824
796	09/23/2013	426576		CCTV Hard Drive Check	712824
796	09/23/2013	426576		Door Service	712824
796	09/21/2013	426496	Complete Campaign 16/12 as required	Completed campaign	712824
796	09/12/2013	425035	Carry out campaign as per Fleet re-branding Procedure.	Removed decals	710917
796	09/12/2013	425035	Carry out campaign as per Fleet re-branding Procedure.	Removed decals	710917
796	09/11/2013	424316	BALANCE OFF VEHICLE	Creditor #:IB-MIC002 MICHELIN AUSTRALIA P/O #:V129376 Receiving #:130924 Date :2013-09-16	711511
796	09/11/2013	424316	FITTING	Creditor #:IB-MIC002 MICHELIN AUSTRALIA P/O #:V129376 Receiving #:130924 Date :2013-09-16	711511
796	09/11/2013	424316	295/80R22.5 XZE2+	Creditor #:IB-MIC002 MICHELIN AUSTRALIA P/O #:V129376 Receiving #:130924 Date :2013-09-16	711511
796	09/11/2013	424663	Moisture ejector leaking air	Tightened leaking fittings & washed off OK	710809
796	09/09/2013	424316	O/S/F tyre tread low	Replaced O/S/F tyre	710306
796	09/09/2013	424350	GLOBE+HOLDER INSTRUMENT (GREY)		710306
796	09/09/2013	424350	GLOBE WEDGE 24V 1.2W		710306
796	09/09/2013	424350	FLURO TUBE 18W		710306
796	09/09/2013	424350	Switch lights N/W	Replaced globes	710306
796	09/09/2013	424350	Speedo & tacho lights N/W	Replaced dash light globe	710306
796	09/09/2013	424350	Saloon lights N/W	Replaced fluro tubes	710306
796	09/09/2013	424350	DO NOT OVERTAKE TURNING DECAL		710306
796	09/09/2013	424350	DNOTV decal faded	Replaced decal	710306
796	09/09/2013	424350	N/S/R seat base loose	Secured seat base	710306
796	09/09/2013	424297		Tension ALL Wheel Nuts to OEM Specs	710306
796	09/09/2013	424297		A - Service & Bus Safety Inspection	710306
796	08/24/2013	421884	Remove A3 Marketing Poster 30/9Fit Marketing Poster 15/8	Complete campaign	707719
796	08/10/2013	419548	Perform Campaign as per Instructions Ensure that appropri	Carried out campaign	705025
796	08/02/2013	418301	AM/FM Aerial missing	Replaced aerial with second hand parts	702668
796	07/30/2013	417579	Engine drive belt needs replacing	Replaced belt	702286
796	07/30/2013	417579	GLOBE WEDGE 24V 1.2W		702286

796	07/30/2013	417579	BELT POLY SCANIA		702286
796	07/30/2013	417579	Engine needs washing & checking for leaks?	Washed off bell housing road tested and checked for leaks ok at this time	702286
796	07/30/2013	417579	Switch lights N/W	Replaced switch light globes	702286
796	07/30/2013	417579	Hydraulic reservoir needs washing & checking for leaks?	Washed off reservoir and checked for leaks replaced filter housing o ring and tightened up loose return line fitting	702286
796	07/30/2013	417504		A - Service & Bus Safety Inspection	702286
796	07/30/2013	417504		Tension ALL Wheel Nuts to OEM Specs	702286
796	07/17/2013	415507	Direct Purchase - BODYWORK	Creditor #:IB-GLA002 GLASS ASSIST P/O #:V127136 Receiving #:128366 Date :2013-07-18 S & F WINDSCREEN	700450
796	07/17/2013	415507	Cracked windscreen	Elite replaced windscreen	700257
796	07/17/2013	415505	Ops Entered - Fault - Body & Acc Windows - Route: 693 - Be	Refer to fault # 437103	700257
796	07/17/2013	415505	Cracked windscreen	Elite replaced windscreen	700257
796	07/08/2013	413944	Suspension will not reset	Traced fault replaced n/s/r level sensor with good s/hand sensor tested operation ok	698304
796	07/06/2013	413781	GLOBE H1 24V 70W		698304
796	07/06/2013	413781	N/S headlight not working	Replaced headlight globe	698304
796	07/05/2013	413543	Service	CCTV Hard Drive Check	698094
796	07/05/2013	413543	Service	Door Service	698094
796	06/27/2013	412098	Smoke coming from AC belts.	Finished testing vehicles a/c system and componants working ok at this time	696744
796	06/26/2013	412098	REFRIDGERANT OIL CARRIER R134a COMPATIBLE		696744
796	06/26/2013	412098	AIR CON REFRIDGERANT		696744
796	06/26/2013	412098	BELT AIR CONDITIONING		696744
796	06/26/2013	412098	SEAL SHAFT O5G A/C COMPRESSOR		696744
796	06/26/2013	412098	RECIEVER/DRYER A/C CAPRI 280 & GR60		696744
796	06/26/2013	412098	Smoke coming from AC belts.	Removed siezed a/c pulley assembely fitted new shaft seal kit fitted second handshaft seal retaining bracket and pulley clutch coil and clutch armature replacedreceiver dryer charged system with gas (6.5kg R134a) to be tested at a later date	696744
796	06/19/2013	410880	GLOBE WEDGE 24V 1.2W		695051
796	06/19/2013	410880	Indicator tell tail light n/w	Replaced dash globe	695051
796	06/19/2013	410880	Internal indicator tell tale lights not working.	Refer to fault # 432903	695051
796	06/13/2013	409992	Batteries need replacing	Tested batteries and Fitted 1 S/H battery Tested OK	693983
796	06/13/2013	409776	Air leaking from foot valve when brakes applied	Replaced foot valve	693983
796	06/12/2013	409776	Engine dip stick needs replacing	Replaced dip stick	693983
796	06/12/2013	409776	FLURO TUBE 18W		693983
796	06/12/2013	409776	Saloon lights need replacing	Replaced fluro	693983
796	06/12/2013	409776	FOOT BRAKE VALVE	Creditor #:IB-MUL001 MULTISPARES LIMITED P/O #:V125586 Receiving #:126522 Date :2013-06-12	693983
796	06/12/2013	409776	Air leaking from foot valve when brakes applied	Inspect & order parts	693983
796	06/12/2013	409776	SCANIA DIP STICK L94UAB		693983
796	06/12/2013	409776	CLIPPARD VALVE DOOR OPEN/CLOSE		693983
796	06/12/2013	409776	External door switch leaking air	Replaced switch	693983
796	06/11/2013	409479	B Service	Assist with QAM ect	693983
796	06/11/2013	409479	O RING FILTER KIT K93	Kit . filter Cent	693983
796	06/11/2013	409479	FILTER OIL K124 / L94UAB (H200W02)	Filter Oil	693983
796	06/11/2013	409479	HYDRAULIC TORQUE FLUID 414	Torque fluid	693983
796	06/11/2013	409479	FILTER TRANSMISSION ZF 4139-298-038E39HD119	Filter ZF Trans	693983
796	06/11/2013	409479	FILTER FUEL K124 / LU94A (1411894 / H17WK05)	Fuel Filter	693983
796	06/11/2013	409479	ENGINE OIL DELO 400LE 15W40	Engine Oil	693983
796	06/11/2013	409479	B Service	Tension ALL Wheel Nuts to OEM Specs	693983
796	06/11/2013	409479	B Service	A - Service & Bus Safety Inspection	693983
796	06/11/2013	409479	B Service	A - Service & Bus Safety Inspection	693983
796	06/03/2013	408456	DISC PAD SET SCANIA MB0500		692916
796	06/03/2013	408456	Rear brake pads getting low	Replaced rear brake pads	692916
796	05/27/2013	407267	Drv entered - Air Cond Cooling Fault Light	Checked a/c operation and componants working ok at this time no faultsfound	691377
796	05/21/2013	406430	Shimmy whilst drving.	Road tested and checked steering shimmy very minor ok to run	690133
796	05/21/2013	406116	PLASTIC STEP EDGE YELLOW		690133
796	05/21/2013	406116	Rear door step edge missing	Replaced rear step tread	690133
796	05/20/2013	406116	Mechanic entered - Elec & Light Park Lights	Replaced o/s park light globe	689340
796	05/20/2013	406116	GLOBE 24V 2W BA29		689340
796	05/20/2013	406248	Drv entered - Elec & Light Indicators O/S/F/L indicator li	Refitted electrical plug	689340
796	05/17/2013	405988	Drv entered - Wipers & Washers Loose	Checked wiper operation and condition lubricated squeaking linkagesworking ok at this time	689340
796	05/17/2013	406066	GLOBE 24V 21W SINGLE CONTACT		689340
796	05/17/2013	406066	N/S lower front indicator not working.	Replaced light globe	689340
796	05/16/2013	405862	Drv entered - Elec & Light Park Lights	Refitted saloon light defuser	689076
796	05/09/2013	404754	Washers N/W	Checked washer operation OK could not fault at this time	687887
796	05/09/2013	404754	FLURO TUBE 18W		687887
796	05/09/2013	404754	Saloon light N/W	Replaced fluro tube	687887
796	05/09/2013	404724		Tension ALL Wheel Nuts to OEM Specs	687887
796	05/09/2013	404724		A - Service & Bus Safety Inspection	687887
796	05/02/2013	403628	Drv entered - Vandalism Graffiti	Cleaned graffiti from seat bases	686036
796	04/23/2013	402197	FITTING	Creditor #:MIC050 MICHELIN AUSTRALIA PTY LTD P/O #:V123342 Receiving #:124217 Date :2013-04-29	685125
796	04/23/2013	402197	295/80R22.5 RECAMIC DRIVE PATT	Creditor #:MIC050 MICHELIN AUSTRALIA PTY LTD P/O #:V123342 Receiving #:124217 Date :2013-04-29	685125
796	04/22/2013	402157		Transmission /check as per Check List	683824
796	04/22/2013	402197	O/S/R/I tyre tread low	Replaced both O/S/R tyres	683824
796	04/17/2013	401653	Rear N/S bottom indicator only working about 30-40 percent.	Checked rear indicator operation all working at 100% OK at this time	682828
796	04/15/2013	401228		Door Service	682365
796	04/15/2013	401228		CCTV Hard Drive Check	682365
796	04/05/2013	399399	SENSOR COOLANT TEMP L94	Creditor #:EAS002 EASTSIDE TRUCK & BUS SERVICE P/O #:V122407 Receiving #:123665 Date :2013-04-15	682365
796	04/03/2013	399399	PANEL SCREW 6X30		680158
796	04/03/2013	399399	Clamp on turbo intake broken	Replaced turbo clamp	680158
796	04/03/2013	399399	Amber engine warning light coming on intermittantly.	Traced engine fault checked fault codes replaced coolant sender roadtested OK	680158
796	04/03/2013	399399	FLURO TUBE 18W		680158
796	04/03/2013	399399	Front external door light N/W	Replaced fluro tube	680158
796	04/03/2013	399399	Saloon light N/W	Fitted new fluro tube	680158
796	04/03/2013	399399	Panel screws missing	Fitted new screw	680158
796	04/03/2013	399373	AIR DRYER CANISTER VOLVO+ NL202	Filter Air Dryer	680158
796	04/03/2013	399373	FUEL FILTER ELEMENT SCANIA L94UAB (R90T / H7090WK10)	Raycor filter	680158
796	04/03/2013	399373	HYDRAULIC TORQUE FLUID 414	Hydraulic oil	680158
796	04/03/2013	399373	FILTER K124EB HYD COOLING FAN	Hydraulic filter	680158
796	04/03/2013	399373	POWER STEERING FILTER VOLVO	Power steering filter	680158
796	04/03/2013	399373	Diff Oil Borate EP 460	diff oil	680158
796	04/03/2013	399373		Service as per check list	680158
796	04/03/2013	399373		Tension ALL Wheel Nuts to OEM Specs	680158
796	04/03/2013	399373		A - Service & Bus Safety Inspection	680158
796	03/18/2013	397382	Rear brake linings getting low	Removed wheels and checked brake linings ok til next service	678367
796	03/15/2013	396933	Orange engine warning light staying on	Traced wiring for EDC temperature sensor & tested from boxtosensor2.800k ohms at 24deg C OK traced fault in coolantsensorcircuitsecured EDC ECU & earth wire tested system & roadtested OK	678207
796	03/15/2013	396933	Passenger buzzer - only one button working	Checked all buzzer buttons all OK at this time	678207
796	03/03/2013	395336	Service	RSI Inspection (RWC 921000)	676414
796	03/01/2013	395022	Transmission Slipping	Road tested could not fault at this time	676245

796	03/01/2013	395022	Drv entered - Engine Wont Start	Checked starting could not fault at this time OK		676245
796	03/01/2013	395022	Dash Light engine light coming on and off frequently.	Traced fault in temperature circuit 4.6 v across sender terminals swapped sender using S/H sender & tested 3.8v road tested OK		676245
796	02/28/2013	395022	Transmission Slipping	Started tracing fault with engine/transmission checked fault codes		676245
796	02/25/2013	394443	Drv entered - Gearbox Slip	Refer to fault # 416051		675507
796	02/25/2013	394443	Drv entered - Engine Wrning Light	Checked & removed engine & transmission fault codes removed stones from drivers area & pedals road tested OK		675507
796	02/23/2013	394310	Perform Campaign 01_13 CCTV and GPS AUDIT inspect vehicles	Carried out audit		675507
796	02/20/2013	393878		Inspect vehicle as per RSI Checklist		675185
796	02/20/2013	393878		Inspect vehicle as per RSI Checklist		675185
796	02/20/2013	393891	Clunking noise in wiper pivots & linkages	Tightened & lubed wiper pivots		675185
796	02/15/2013	393300	Graffiti on passsenger seat backs	Cleaned graffiti from seat backs		674267
796	02/15/2013	393300	FLURO TUBE 18W			674267
796	02/15/2013	393300	GLOBE WEDGE 24V 1.2W			674267
796	02/15/2013	393300	Switch lights N/W	Replaced switch light globes		674267
796	02/15/2013	393300	Saloon light N/W	Replaced o/s rear fluro tube		674267
796	02/15/2013	393300	O/S hand rail loose at roof	Replaced missing screws		674267
796	02/15/2013	393238	FILTER OIL K124 / L94UAB (H200W02)	Filter Oil		674267
796	02/15/2013	393238	HYDRAULIC TORQUE FLUID 414	Torque fluid		674267
796	02/15/2013	393238	FILTER TRANSMISSION ZF 4139-298-038E39HD119	Filter ZF Trans		674267
796	02/15/2013	393238	FILTER FUEL K124 / LU94A (1411894 / H17WK05)	Fuel Filter		674267
796	02/15/2013	393238	ENGINE OIL DELO 400LE 15W40	Engine Oil		674267
796	02/15/2013	393238		Tension ALL Wheel Nuts to OEM Specs		674267
796	02/15/2013	393238		A - Service & Bus Safety Inspection		674267
796	02/15/2013	393238	O RING FILTER KIT K93	Kit . filter Cent		674267
796	02/15/2013	393238		A - Service & Bus Safety Inspection		674267
796	02/15/2013	393238		A - Service & Bus Safety Inspection		674267
796	02/12/2013	392729	WEAR SENSOR SCANIA DISC BRAKE			673809
796	02/12/2013	392729	Brake lining warning light ON	Checked brakes traced electrical fault replaced broken pad wear sensor		673809
796	01/31/2013	391164	Amber engine light coming on whilst driving up montrose hill	Checked engine fault codes removed & road tested OK		671873
796	01/29/2013	390691	GLOBE WEDGE 24V 1.2W			671270
796	01/29/2013	390691	Switch lights N/W	Replaced globe		671270
796	01/29/2013	390691	Rear vanity panel loose at wall	Secured panel		671270
796	01/29/2013	390691	Rear brake pads low	Checked rear brakes OK till next service		671270
796	01/25/2013	390451		Tension ALL Wheel Nuts to OEM Specs		671270
796	01/25/2013	390451		A - Service & Bus Safety Inspection		671270
796	01/24/2013	390236		CCTV Hard Drive Check		671042
796	01/24/2013	390236		Door Service		671042
796	01/23/2013	390129	Drv entered - Elec & Light Bell Button stunchen buttons no	Checked passenger stop buttons for operation all ok & working		670915
796	01/18/2013	388588	FITTING	Creditor #:MIC050 MICHELIN AUSTRALIA PTY LTD P/O #:V119008 Receiving #:120476 Date :2013-02-05		672702
796	01/18/2013	388588	295/80R22.5 RECAMIC DRIVE PATT	Creditor #:MIC050 MICHELIN AUSTRALIA PTY LTD P/O #:V119008 Receiving #:120476 Date :2013-02-05		672702
796	01/15/2013	388759	O/S/F roof panel broken	Repaired brocken roof panel		669338
796	01/15/2013	388588	Ticket machine stand broken	Repaired broken ticket machine stand		669338
796	01/14/2013	388588	N/S/R tyre treads low	Replaced N/S/R tyres		669338
796	01/14/2013	388588	Bus keeps correcting its own hight when finger is on the kne	Checked operation will stay in kneel position when door is opened & park brake is ON once door is closed suspension resets working ok at this time		669338
796	01/14/2013	388588	Engine warning light keeps flickering on for appox 5 seconds	Road tested checked operation rear door was opening with the wind repositioned door guide rail and checked operation ok		669338
796	01/14/2013	388588	Ticket machine stand broken	Started removing ticket machine to repair stand		669338
796	12/28/2012	385672	AIR CONDITIONING REPAIR	Creditor #:TRA061 TRANSIT REFRIGERATION & AIR CONDITIONING SERVICE P/O #:V118151 Receiving #:120926 Date :2013-02-13 REPLACE HOSE & FITTINGS & REGAS		673996
796	12/19/2012	385672	Drv entered - Air Cond - Poor airflow from drivers air vents	TRAX rectified A/C by replacing hose & charging A/C system		665292
796	12/19/2012	385672	Drv entered - Air Cond - not cooling	Refer to fault # 404280		665292
796	12/19/2012	385672	Drv entered - Air Cond	Refer to fault # 404280		665292
796	12/19/2012	385672	Not cooling	Refer to fault # 404280		665292
796	12/18/2012	385406	Gearbox high temp light light coming on - Kick down not norm	Checked transmission fault codes & removed road tested & checked oil level (overfull) washed transmission & removed 5 litres of oil road tested OK		665172
796	12/17/2012	384285	Both tie rod ends needs replacing	Replaced tie rod checked & adjusted toe in road tested OK		665087
796	12/10/2012	384285	N/S/R/O tyre was low on air pressure when serviced & N/S/R/I	Checked tyre pressure ok and fitted up good s/hand valve extension clamp		663878
796	12/10/2012	384285	TRACK ROD ASSY	Creditor #:MUL001 MULTISPARES LTD P/O #:V117694 Receiving #:118248 Date :2012-12-10		664098
796	12/10/2012	384285	Both tie rod ends need replacing	Ordered new tie rod		663878
796	12/10/2012	384285	FLURO TUBE 18W			663878
796	12/10/2012	384285	Rear door roller arm loose	Replaced door bolt		663878
796	12/10/2012	384285	Switch lights N/W	Replaced globes		663878
796	12/10/2012	384285	GLOBE WEDGE 24V 1.2W			663878
796	12/10/2012	384285	Drivers light dull & O/S saloon light dull	Replaced light tubes		663878
796	12/07/2012	384147	Drivers seat belt not locking	Refitted belt retractor lock cover & tested ok		663458
796	12/07/2012	384082		Tension ALL Wheel Nuts to OEM Specs		663458
796	12/07/2012	384082		A - Service & Bus Safety Inspection		663458
796	12/03/2012	383436	Slow to select gear when button is pressed	Checked gear selector operation working OK		662772
796	11/22/2012	381590	RELAY 24V CHANGE OVER	Creditor #:BUR050 BURSON LILYDALE AUTO PARTS P/O #:V116867 Receiving #:117454 Date :2012-11-22		661066
796	11/20/2012	381650	Amber engine warning light on	Checked engine fault codes & removed tested OK no active codes		660726
796	11/20/2012	381590	No rear brake/tail lights working	Traced fault fitted S/H relay to RP7 stop lights working OK		660726
796	11/09/2012	380250	Drv entered - Air Cond Air Conditioner	Refer to fault # 400239		658892
796	11/09/2012	380250	No power to switches	Replaced fuse working ok		658892
796	11/09/2012	380250	Engine amber warning light coming ON intermittently	Checked fault codes code 14 temp sensor cleaned plugs and checked sensor clear fault code and road tested ok		658892
796	11/09/2012	380250	FLURO TUBE 18W			658892
796	11/09/2012	380250	O/S/R saloon lights N/W	Replaced light tube		658892
796	11/09/2012	379752	FLURO TUBE 18W			658892
796	11/09/2012	379752		Hard drive check		658892
796	11/09/2012	379752		Door Service replaced door light tube		658892
796	10/31/2012	378760	FITTING	Creditor #:MIC050 MICHELIN AUSTRALIA PTY LTD P/O #:V115927 Receiving #:116555 Date :2012-11-01		657744
796	10/31/2012	378760	BALANCE OFF VEHICLE	Creditor #:MIC050 MICHELIN AUSTRALIA PTY LTD P/O #:V115927 Receiving #:116555 Date :2012-11-01		657744
796	10/31/2012	378760	295/80R22.5 XZE2+	Creditor #:MIC050 MICHELIN AUSTRALIA PTY LTD P/O #:V115927 Receiving #:116555 Date :2012-11-01		657744
796	10/29/2012	378760	N/S/F tyre tread low	Replaced both front tyres		657005
796	10/26/2012	378392	Drv entered - Engine Wrning Light	Cleared engine fault codes road tested & rechecked for faults ok at this time		656823
796	10/26/2012	378392	Amber check engine light coming on losing power when light	Refer to fault # 398591		656823
796	10/22/2012	377711	Drv entered - Passenger Bell not working	Checked passenger door bell & light operation checked all passenger stopbuttons no faults found at this time		655908
796	10/18/2012	377120	N/S/R/O tyre pressure needs checking? low on service (inflat	Checked tyre had 86 PSI ok to run		655368
796	10/17/2012	376918		Transmission /check as per Check List		655189
796	10/17/2012	377032	Graffiti on N/S/R interior wall panel	Cleaned graffiti from back of seat and panel		655189
796	10/17/2012	377032	GIVE WAY SIGN (LARGE)			655189
796	10/17/2012	377032	Give way decal faded	Replaced faded decal		655189
796	10/17/2012	376917	O RING FILTER KIT K93	Kit . filter Cent		655189
796	10/17/2012	376917	FILTER OIL K124 / L94UAB (H200W02)	Filter Oil		655189
796	10/17/2012	376917	HYDRAULIC TORQUE FLUID 414	Torque fluid		655189
796	10/17/2012	376917	FILTER TRANSMISSION ZF 4139-298-038E39HD119	Filter ZF Trans		655189
796	10/17/2012	376917	FILTER FUEL K124 / LU94A (1411894 / H17WK05)	Fuel Filter		655189
796	10/17/2012	376917	ENGINE OIL DELO 400LE 15W40	Engine Oil		655189

796	10/17/2012	376917		Tension ALL Wheel Nuts to OEM Specs		655189
796	10/17/2012	376917		A - Service & Bus Safety Inspection		655189
796	10/17/2012	376917		A - Service & Bus Safety Inspection		655189
796	10/09/2012	375902	NEARside headlight blown.	Replaced N/S low beam globe		653300
796	10/09/2012	375902	GLOBE H1 24V 70W			653300
796	10/08/2012	375711	Drv entered - Gearbox Slip	Check trans fluid level OK		653300
796	10/08/2012	375712	Engine light coming on and off generally in conjunction wit	Checked eng fault codes (14 temp sensor fault) Checked coolant & road test OK		653300
796	09/27/2012	374362	N/S/F & N/S/R/R air bags need replacing	Replaced air bags		651159
796	09/27/2012	374362	REAR AIR BAG (DRIVE AXLE) SCANIA L94UAB			651159
796	09/27/2012	374362	FRONT AIR BAG SCANIA L94UAB			651159
796	09/27/2012	374362	Engine oil leaks requires wash & check?	Washed engine road tested & checked for leaks OK at this time		651159
796	09/27/2012	374362	Saloon light N/W	Fitted S/H fluro tube		651159
796	09/27/2012	374362	Switch lights N/W	Replaced switch globes		651159
796	09/27/2012	374362	GLOBE WEDGE 24V 1.2W			651159
796	09/27/2012	374296		Tension ALL Wheel Nuts to OEM Specs		651159
796	09/27/2012	374296		A - Service & Bus Safety Inspection		651159
796	09/24/2012	373758	Drv entered - Elec & Light Headlights	Replaced o/s headlight globe		650330
796	09/24/2012	373758	GLOBE H1 24V 70W			650330
796	09/10/2012	371280	DISPOSAL CHARGE	Creditor #:MIC050 MICHELIN AUSTRALIA PTY LTD P/O #:V113530 Receiving #:113948 Date :2012-09-10		647332
796	09/10/2012	371280	FITTING	Creditor #:MIC050 MICHELIN AUSTRALIA PTY LTD P/O #:V113530 Receiving #:113948 Date :2012-09-10		647332
796	09/10/2012	371280	295/80R22.5 RECAMIC DRIVE PATT	Creditor #:MIC050 MICHELIN AUSTRALIA PTY LTD P/O #:V113530 Receiving #:113948 Date :2012-09-10		647332
796	09/07/2012	371392	N/S/R side window broken	Took bus to Elite windscreens for side window replacement & returned to depot		647067
796	09/06/2012	371280	N/S/R outer tyre flat	Replaced flat tyre using S/H cap		647067
796	09/06/2012	371280	Drv entered - Whls & Tyres Soft	Replaced flat tyre		647067
796	09/06/2012	371280	GAS STAY 350N-565MM			647067
796	09/06/2012	371280	Engine hatch struts need replacing	Replaced both gas struts		647067
796	09/06/2012	371392	Sub-contracted - BODY	Creditor #:ELI001 ELITE WINDSCREENS P/O #:V113504 Receiving #:113902 Date :2012-09-07 S & F NEW GLASS TO N/S/R SIDE WINDOW		647332
796	08/31/2012	370661	Lights at front of bus too bright.	Checked and ok to run		645698
796	08/23/2012	368139	N/S wiper pivot loose at body	Welded wiper pivot bracket & reassembled wiper assembly		643198
796	08/22/2012	368125	Both wiper inserts need replacing	Replaced n/s wiper blade checked washer bottle fluid level		643198
796	08/22/2012	368125	BLADE WIPER 1MTR			643198
796	08/17/2012	368675	Driver complaining that interior lights to bright for night	Checked led and saloon lights no fault found at this time		643382
796	08/17/2012	368672	Driver complaining that Bus rools back on hill starts.	Checked hill hold not fitted to this model road tested & checkedtransmission operation ok at this time		643382
796	08/15/2012	368195	Brakes pull to right	Removed front brake calipers replaced N/S/F brake caliper road tested brake temps: N/S/F 99 deg c O/S/F 95 deg c		643198
796	08/15/2012	368195	Brakes pull to right	Checked for brakes pulling o/s/f brake caliper out of adjustmentremovedboth front calipers replaced o/s/f brake caliper andassisted replacing n/sroadtested ok n/s/f99 and o/s/f95		643198
796	08/15/2012	368195	RATIONALISED CALIPER	Creditor #:MUL001 MULTISPARES LTD P/O #:V112371 Receiving #:112755 Date :2012-08-15		643198
796	08/15/2012	368195	RATIONALISED CALIPER	Creditor #:MUL001 MULTISPARES LTD P/O #:V112371 Receiving #:112755 Date :2012-08-15		643198
796	08/14/2012	368125	BLADE WIPER 1MTR			643198
796	08/14/2012	368139	N/S wiper pivot loose at body	Tryed to tighten wiper pivot no good weld cracked requires further		643198
796	08/14/2012	368125	Both wiper inserts need replacing	Replaced o/s wiper blade n/s blade needs changing no stock		643198
796	08/14/2012	368127	PUMP WIPER-WASHER 24 VOLT			643198
796	08/14/2012	368127	Washer pressure very weak	Replaced washer pump		643198
796	08/14/2012	368142	Metal engine idler pulley bearing noisey	Replaced engine idler pulley		643198
796	08/14/2012	368142	152 FAN HUB BEARING			643198
796	08/14/2012	368140	Saloon lights & switch lights N/W	Replaced saloon fluro tubes and switch light globe		643198
796	08/14/2012	368141	Tacho light N/W	Replaced tacho light globe		643198
796	08/14/2012	368141	GLOBE WEDGE 24V 1.2W			643198
796	08/14/2012	368140	FLURO TUBE 18W			643198
796	08/14/2012	368140	GLOBE WEDGE 24V 1.2W			643198
796	08/14/2012	368106		A - Service & Bus Safety Inspection		643198
796	08/14/2012	368106		Tension ALL Wheel Nuts to OEM Specs		643198
796	08/09/2012	367498	Drv entered - Elec & Light Indicators	Replaced n/s/r indicator lamp faulty terminal		642373
796	08/08/2012	367317	GLOBE 24V 5W BAYONETT			642193
796	08/08/2012	367317	Drv entered - Elec & Light Park Lights	Replaced O/S clearance light globe		642193
796	08/08/2012	367182		CCTV Hard Drive Check		642193
796	08/08/2012	367182		Door Service		642193
796	08/03/2012	366640	Drv entered - Body & Acc Drivers Seat Belt	Checked drivers seat belt condition and operation no faults found at thistime		641614
796	07/26/2012	365421	Accident Damaged # 35707 Repair front bumper-bar. Prepare a	Repaired accident damage # 35797		639538
796	07/26/2012	365421	Accident Damaged # 35707 Repair front bumper-bar. Prepare a	Assisted with repairing accident damage # 35797		639538
796	07/26/2012	365421	DECAL EMERGENCY EXIT BLACK PUSH BUTTON UNDER BUMPER			639538
796	07/26/2012	365421	PAINT SUPPLIES			639538
796	07/26/2012	365421	BODY SHOP SUPPLIES			639538
796	07/17/2012	363910	Filter Air Inner Scania K124EB			638223
796	07/16/2012	363910		Adjust Tappets		638223
796	07/16/2012	363910		Adjust Tappets		638223
796	07/13/2012	363700	Drv entered - Elec & Light Interior Lights	Checked interior lights no fault found at this time		638223
796	07/03/2012	361995	FLURO TUBE 18W			635298
796	07/03/2012	361995	Saloon lights at rear N/W	Replaced 3 saloon light tubes 1 x new and 2 x s/hand		635298
796	07/02/2012	361682	GLOBE 24V 21W SINGLE CONTACT			635298
796	07/02/2012	361682	Drv entered - Elec & Light Indicators	Checked indicators n/s on but not flashing replaced globe and repair loose plug tested working ok		635298
796	07/02/2012	361744	O RING FILTER KIT K93	Kit . filter Cent		635298
796	07/02/2012	361744	FILTER OIL K124 / L94UAB (H200W02)	Filter Oil		635298
796	07/02/2012	361744	HYDRAULIC TORQUE FLUID 414	Torque fluid		635298
796	07/02/2012	361744	FILTER TRANSMISSION ZF 4139-298-038E39HD119	Filter ZF Trans		635298
796	07/02/2012	361744	FILTER FUEL K124 / LU94A (1411894 / H17WK05)	Fuel Filter		635298
796	07/02/2012	361744	ENGINE OIL DELO 400LE 15W40	Engine Oil		635298
796	07/02/2012	361744		Tension ALL Wheel Nuts to OEM Specs		635298
796	07/02/2012	361744		A - Service & Bus Safety Inspection		635298
796	07/02/2012	361744		A - Service & Bus Safety Inspection		635298
796	07/02/2012	361744		A - Service & Bus Safety Inspection		635298
796	06/21/2012	359689	Drv entered - Diff & Hubs Leaking	Replaced diff pinion seal steam cleaned & road tested checked for leaks ok		633704
796	06/19/2012	359689	SEAL DIFF PINION SCANIA L94	Creditor #:MUL001 MULTISPARES LTD P/O #:V109737-1 Receiving #:111828 Date :2012-07-26		640216
796	06/18/2012	359689	Drv entered - Diff & Hubs Leaking	Checked diff pinion seal leak & oil level check for parts & order seal		633486
796	06/13/2012	359019	O/S wiper pivot loose at body	Removed wiper arm tightened pivot & refitted arm		632803
796	06/13/2012	359021	ELC rear control unit leaking from exhaust	Washed rear ELC control valve checked for air leaks none found at this time		632803
796	06/13/2012	359018	Diff pinion seal leaking wash & check?	Washed diff checked & topped up oil ok at this time		632803
796	06/12/2012	358807	Switch lights N/W	Replaced globes		632580
796	06/12/2012	358806	O/S saloon lights N/W	Replaced fluro tubes & shortened invertors		632580
796	06/12/2012	358805	Rear door external light N/W	Replaced fluro tube		632580
796	06/12/2012	358807	GLOBE WEDGE 24V 1.2W			632580
796	06/12/2012	358806	FLURO TUBE 18W			632580
796	06/12/2012	358805	FLURO TUBE 18W			632580
796	06/12/2012	358802	DECAL BREAK GLASS WITH ROCK			632580

796	06/12/2012	358802	DECAL EMERGENCY EXIT LARGE			632580
796	06/12/2012	358802	External rear emergency exit decal faded	Removed decals & fitted new decals		632580
796	06/12/2012	358705		Tension ALL Wheel Nuts to OEM Specs		632580
796	06/12/2012	358705		A - Service & Bus Safety Inspection		632580
796	05/26/2012	356553		CCTV Hard Drive Check		629125
796	05/26/2012	356553		Door Service		629125
796	05/23/2012	356150		Transmission /check as per Check List		628301
796	05/08/2012	353884	FRONT AIR BAG SCANIA L94UAB			624704
796	05/08/2012	353884	N/S/F air bag leaking	Replaced front air bag		624704
796	05/08/2012	353911	Engine oil leaks requires wash & check?	Washed & road tested light leak at bell housing ok for now		624704
796	05/08/2012	353910	Diff oil leaks requires wash & check?	Washed & road tested leak from pinion seal still OK at this stage		624704
796	05/04/2012	353532	FLURO TUBE 18W			624374
796	05/04/2012	353532	Front door external step light N/W	Replaced fluro light tube		624374
796	05/04/2012	353531	GLOBE WEDGE 24V 1.2W			624374
796	05/04/2012	353531	Switch lights N/W	Replaced switch light globes		624374
796	05/04/2012	353440	BODY SHOP SUPPLIES			624371
796	05/04/2012	353440	PAINT SUPPLIES			624371
796	05/04/2012	353440	Accident Damaged # 34865 R/R. rear bumper-bar reflectors r	Repaired accident damage # 34865		624374
796	05/04/2012	353364		A - Service & Bus Safety Inspection		624374
796	05/04/2012	353364		Tension ALL Wheel Nuts to OEM Specs		624374
796	05/02/2012	353118	Drv entered - Elec & Light Headlights	Replaced N/S low beam globe		623902
796	05/02/2012	353118	GLOBE H1 24V 70W			623902
796	04/28/2012	345442	Incorrect type fire extinguisher fitted	Replaced fire extinguisher		623205
796	04/26/2012	351969	Drv entered - Elec & Light Indicators	Replaced O/S/F/T indicator globe		622468
796	04/26/2012	351969	GLOBE 24V 21W SINGLE CONTACT			622468
796	04/20/2012	350495	Annual Inspections	Creditor #:ROA001 Road Safety Inspections P/O #:V106699 Receiving #:107651 Date :2012-04-27 Bus 796		622828
796	04/15/2012	350495		RSI Inspection (RWC 284064)		620138
796	04/03/2012	348266	Power steering reservoir filter hold down clamp broken	Fitted power steering resevoir filter clamp		616428
796	03/30/2012	348266	LOCK P/S FILTER	Creditor #:SCA001 SCANIA AUSTRALIA PTY LTD P/O #:V106149 Receiving #:106861 Date :2012-04-03		617749
796	03/28/2012	348320	OS mirror head requires securing	Secured O/S mirror head		616428
796	03/28/2012	348313	N/S/F vanity panel loose	Secured vanity panel		616428
796	03/28/2012	348310	OS centre seat base needs securing	Secured seat base		616428
796	03/28/2012	348238		Service as per check list		616428
796	03/28/2012	348238	Hydraulic Oil Torque Fluid 414	Hydraulic oil		616428
796	03/28/2012	348238	POWER STEERING FILTER VOLVO	Power steering filter		616428
796	03/28/2012	348238	FILTER K124EB HYD COOLING FAN	Hydraulic filter		616428
796	03/28/2012	348238	FUEL FILTER ELEMENT SCANIA L94UAB (R90T / H7090WK10)	Raycor filter		616428
796	03/28/2012	348238	AIR DRYER CANISTER VOLVO+ NL202	Filter Air Dryer		616428
796	03/28/2012	348238	Diff Oil Borate EP 460			616428
796	03/28/2012	348238		A - Service & Bus Safety Inspection		616428
796	03/28/2012	348238		Tension ALL Wheel Nuts to OEM Specs		616428
796	03/26/2012	347850	ENGINE OIL DELO 400LE 15W40	Engine Oil		616041
796	03/26/2012	347850		Tension ALL Wheel Nuts to OEM Specs		616041
796	03/26/2012	347850		A - Service & Bus Safety Inspection		616041
796	03/26/2012	347850	Hydraulic Oil Torque Fluid 414	Torque fluid		616041
796	03/26/2012	347850	FILTER TRANSMISSION ZF 4139-298-038E39HD119	Filter ZF Trans		616041
796	03/26/2012	347850	O RING FILTER KIT K93	Kit , filter Cent		616041
796	03/26/2012	347850	FILTER OIL K124 / L94UAB (H200W02)	Filter Oil		616041
796	03/26/2012	347850	FILTER FUEL K124 / LU94A (1411894 / H17WK05)	Fuel Filter		616041
796	03/26/2012	347850		A - Service & Bus Safety Inspection		616041
796	03/26/2012	347850		Tension ALL Wheel Nuts to OEM Specs		616041
796	03/26/2012	347850	Service	QAM check after service		616041
796	03/22/2012	347500	ELLAMP LIGHT COVER 3MT			615415
796	03/22/2012	347500	FLURO TUBE 18W			615415
796	03/22/2012	347500	Drv entered - Elec & Light Cab Light	Fitted new fluro saloon light fluro fitted saloon light cover		615415
796	03/20/2012	346897		CCTV Hard Drive Check		615043
796	03/20/2012	346897		Door Service		615043
796	03/19/2012	345390	295/80R22.5 RECAMIC DRIVE PATT	Creditor #:MIC050 MICHELIN AUSTRALIA PTY LTD P/O #:V105643 Receiving #:106922 Date :2012-04-04		618108
796	03/19/2012	345390	FITTING	Creditor #:MIC050 MICHELIN AUSTRALIA PTY LTD P/O #:V105643 Receiving #:106922 Date :2012-04-04		618108
796	03/13/2012	345647	AIR CON REFRIDGERANT			613817
796	03/13/2012	345647	Drv entered - Air Cond Air Conditioner	Replaced faulty low pressure switch charged system with nitrogen tested ok regas 6.5 kg tested operation ok replaced a/c belts with b90		613817
796	03/13/2012	345647	BELT AIR CONDITIONING			613817
796	03/09/2012	345647	Drv entered - Air Cond Air Conditioner	Traced a/c fault no gas in system leak at receiver dryer low pressure switch u/s		613817
796	03/08/2012	345444	Front sway bar bushes need replacing	Replaced N/S/F sway bar bush		613696
796	03/08/2012	345444	STABILIZER BAR BUSH FRONT L94UAB			613696
796	03/08/2012	345440	Switch lights N/W	Replaced switch light globe		613696
796	03/08/2012	345443	Front saloon light very dull	Checked step light OK at this time		613696
796	03/08/2012	345440	GLOBE WEDGE 24V 1.2W			613696
796	03/08/2012	345460	Diff pinion seal leaking requires wash & check?	Washed & checked diff for leaks road tested OK		613696
796	03/08/2012	345442	Incorrect type fire extinguisher fitted	Nill stock		613696
796	03/07/2012	345350		Inspect vehicle as per RSI Checklist		613696
796	03/07/2012	345350		Inspect vehicle as per RSI Checklist		613696
796	03/07/2012	345390	O/S/R/I tyre tread low	Replaced O/S/R tyres using new caps		613696
796	03/05/2012	343299	295/80R22.5 RECAMIC DRIVE PATT	Creditor #:MIC050 MICHELIN AUSTRALIA PTY LTD P/O #:V105109 Receiving #:105866 Date :2012-03-09		613817
796	03/05/2012	343299	DISPOSAL CHARGE	Creditor #:MIC050 MICHELIN AUSTRALIA PTY LTD P/O #:V105109 Receiving #:105866 Date :2012-03-09		613817
796	03/05/2012	343299	FITTING	Creditor #:MIC050 MICHELIN AUSTRALIA PTY LTD P/O #:V105109 Receiving #:105866 Date :2012-03-09		613817
796	03/01/2012	344350	Engine oil leaks requires wash & check?	Washed engine road tested & checked for oil leaks OK at this time		612299
796	03/01/2012	344332	L.E.D SIDE MARKER RED/AMBER			612299
796	03/01/2012	344332	N/S/R side light needs replacing	Replaced N/S/R side lamp		612299
796	03/01/2012	344349	SYMBOL (REAR DOOR) SWF SWITCH			612299
796	03/01/2012	344349	Lens missing from door switch	Replaced missing lens		612299
796	03/01/2012	344348	Switch lights N/W	Replaced switch light globes		612299
796	03/01/2012	344348	GLOBE WEDGE 24V 1.2W			612299
796	03/01/2012	344309		Tension ALL Wheel Nuts to OEM Specs		612299
796	03/01/2012	344309	Service	A - Service & Bus Safety Inspection		612299
796	03/01/2012	344309	Service	A - Service & Bus Safety Inspection		612299
796	02/29/2012	339825	AIR CON REFRIDGERANT			612299
796	02/29/2012	339825	Drv entered - Air Cond	Replaced broken shaft seal hub vaccumed system down & charged with gas (6.5kg R134a) tested a/c operation ok		612299
796	02/24/2012	343299	N/S/R/I tyre side wall blown out	Replaced n/s/r/i tyre		611650
796	02/24/2012	339825	HUB 05G SHAFT SEAL	Creditor #:TRA061 TRANSIT REFRIGERATION & AIR CONDITIONING SERVICE P/O #:V104335 Receiving #:105364 Date :2012-02-28 O5G SHAFT SEAL HUB		612032
796	02/15/2012	339825	Drv entered - Air Cond	Recovered a/c gas fitted shaft seal ordered new shaft hub replaced receiver/dryer changed a/c compressor oil		611650
796	02/15/2012	339825	Drv entered - Cool & AC Sys Poor	Refer to fault # 360184		611650
796	02/15/2012	339825	Drv entered - Cool & AC Sys Poor	Refer to fault # 360184		611336

796	02/15/2012	339825	Drv entered - Air Cond Air Conditioner	Refer to fault # 360184	609634
796	02/08/2012	339825	RECIEVER/DRYER A/C CAPRI 280	Creditor #:TRA061 TRANSIT REFRIGERATION & AIR CONDITIONING SERVICE P/O #:V103696 Receiving #:104753 Date :2012-02-10	609259
796	02/08/2012	339825	SEAL SHAFT 05G A/C COMPRESSOR	Creditor #:TRA061 TRANSIT REFRIGERATION & AIR CONDITIONING SERVICE P/O #:V103696 Receiving #:104753 Date :2012-02-10	609259
796	02/08/2012	339825	REFRIDGERANT OIL CARRIER R134	Creditor #:TRA061 TRANSIT REFRIGERATION & AIR CONDITIONING SERVICE P/O #:V103696 Receiving #:104753 Date :2012-02-10	609259
796	02/01/2012	339825	Drv entered - Air Cond	Checked a/c operation pressures low leaking shaft seal & hand taps fitted brass hand tap covers and ordered new shaft seal & receiver/dryer	607760
796	02/01/2012	339825	CAP SERVICE VALVE O5G		607760
796	02/01/2012	339825	Drv entered - Air Cond Air Conditioner	Refer to fault # 360184	607760
796	02/01/2012	339825	Not cooling	Refer to fault # 360184	606884
796	01/25/2012	339065	Engine oil leaks requires wash & check?	Washed off engine and checked for leaks no leaks found at this time	605537
796	01/25/2012	339047	GLOBE WEDGE 24V 1.2W		605537
796	01/25/2012	339047	Guage lights N/W	Replaced globe	605537
796	01/25/2012	339063	Coolant boost pump hoses need securing	Secured boost pump hoses	605537
796	01/25/2012	339064	Diff leaking oil requires wash & check?	Washed off diff road tested and checked ok	605537
796	01/25/2012	339062	Screws missing from head board	Replaced missing screws	605537
796	01/23/2012	338663	Engine multi V belt needs replacing	Replaced alternator belt	604904
796	01/23/2012	338663	BELT POLY		604904
796	01/20/2012	338349		A - Service & Bus Safety Inspection	604904
796	01/20/2012	338349		Tension ALL Wheel Nuts to OEM Specs	604904
796	01/20/2012	338349	Service	A - Service & Bus Safety Inspection	604904
796	01/12/2012	337060		Door Service	603379
796	01/12/2012	337060		CCTV Hard Drive Check	603379
796	01/05/2012	335927	NUT TORQUE ROD MOUNTING L94	Creditor #:SCA001 SCANIA AUSTRALIA PTY LTD P/O #:V102455 Receiving #:103538 Date :2012-01-10 Bus 796	602828
796	01/05/2012	335927	BOLT TORQUE ROD L94	Creditor #:SCA001 SCANIA AUSTRALIA PTY LTD P/O #:V102455 Receiving #:103538 Date :2012-01-10 Bus 796	602828
796	01/04/2012	335927	OSR lower track rod mounting bolts broken.	Replaced O/S/R track rod mounting bolts	602165
796	12/28/2011	335044		Transmission /check as per Check List	601614
796	12/15/2011	333689	Drv entered - Elec & Light Indicators	Checked all lights and indicator self cancel working ok	599266
796	12/05/2011	331564	FITTING	Creditor #:MIC050 MICHELIN AUSTRALIA PTY LTD P/O #:V101240 Receiving #:102239 Date :2011-12-06	597315
796	12/05/2011	331564	295/80R22.5 RECAMIC DRIVE PATT	Creditor #:MIC050 MICHELIN AUSTRALIA PTY LTD P/O #:V101240 Receiving #:102239 Date :2011-12-06	597315
796	12/01/2011	331831	Washer jets blocked	Bleed washer motor & tested ok	596827
796	12/01/2011	331836	Graffiti on passenger seats	Removed graffitti	596827
796	12/01/2011	331824	GLOBE WEDGE 24V 1.2W		596827
796	12/01/2011	331823	Rear door emergency exit light N/W	Removed panel repaired connection to emergency exit light	596827
796	12/01/2011	331794	Rear door step light N/W	Removed panel fitted new step light & rewired	596827
796	12/01/2011	331794	COURTESY LAMP LED		596827
796	12/01/2011	331832	Guage lights N/W	Checked guage lights ok	596827
796	12/01/2011	331824	Switch lights N/W	Replaced switch light globes	596827
796	11/30/2011	331564	Thump in tyre while driving	Refer to fault # 352083	596650
796	11/30/2011	331564	O/S/R/I tyre tread low	Replaced punctured & flat spotted O/S/R/I tyre	596650
796	11/30/2011	331517	O RING FILTER KIT K93	Kit . filter Cent	596650
796	11/30/2011	331517	FILTER OIL K124 / L94UAB (H200W02)	Filter Oil	596650
796	11/30/2011	331517	Hydraulic Oil Torque Fluid 414	Torque fluid	596650
796	11/30/2011	331517	FILTER TRANSMISSION ZF 4139-298-038E39HD119	Filter ZF Trans	596650
796	11/30/2011	331517	FILTER FUEL K124 / LU94A (1411894 / H17WK05)	Fuel Filter	596650
796	11/30/2011	331517		Tension ALL Wheel Nuts to OEM Specs	596650
796	11/30/2011	331517	ENGINE OIL DELO 400LE 15W40	Engine Oil	596650
796	11/30/2011	331517		A - Service & Bus Safety Inspection	596650
796	11/30/2011	331517		A - Service & Bus Safety Inspection	596650
796	11/28/2011	329546	HEADER TANK SCANIA L94 SIDE FILL		596034
796	11/28/2011	329546	Coolant leak at header tank	Replaced leaking header tank	596034
796	11/23/2011	330646	O/S mirror broken	Drilled & taped mirror mount drilled mirror arm & refited s/h mirror glassrefitted w/screen rubber	595338
796	11/22/2011	330428	Drv entered - Suspension Kneeling System	Checked for fault remove kneeling switch and clean out coffee working ok	595130
796	11/16/2011	329545	A/C filter needs replacing	Replaced filter material for a/c filter	594073
796	11/16/2011	329541	FLURO TUBE 18W		594073
796	11/16/2011	329541	Rear saloon lights N/W	Replaced saloon light fluro tube	594073
796	11/16/2011	329540	GLOBE WEDGE 24V 1.2W		594073
796	11/16/2011	329540	Switch lights N/W	Replaced switch light globes	594073
796	11/16/2011	329546	Coolant leak at header tank	Washed road tested & checked coolant leak order header tank	594073
796	11/16/2011	329543	Wheel chair ramp pull ring U/S	Modified ramp floor & fitted new lift ring	594073
796	11/16/2011	329543	LIFT RING		594073
796	11/16/2011	329539	Rear seat backrest needs securing	Drilled out broken seat bolts tightened other bolts & fitted rivots to secure	594073
796	11/16/2011	329442	Park brake valve not locking ON	Replaced park brake valve assembly & swap fittings tested ok	594073
796	11/15/2011	329442	CONSUMABLE DELIVERY CHARGE	Creditor #:SCA001 SCANIA AUSTRALIA PTY LTD P/O #:V100512 Receiving #:101370 Date :2011-11-16	594073
796	11/15/2011	329442	VALVE PARK BRAKE L94	Creditor #:SCA001 SCANIA AUSTRALIA PTY LTD P/O #:V100512 Receiving #:101370 Date :2011-11-16	594073
796	11/14/2011	329092	GLOBE 24V 2W BA29		593834
796	11/14/2011	329092	N/S/F park light N/W	Replaced N/S/F park light globe	593834
796	11/14/2011	329014		A - Service & Bus Safety Inspection	593834
796	11/14/2011	329014		Tension ALL Wheel Nuts to OEM Specs	593834
796	11/14/2011	329014		QAM check & road test	593834
796	10/18/2011	325117	Drv entered - Whls & Tyres Noisy	Checked for noise stup axle hitting steering stops OK	588611
796	10/18/2011	325116	Drv entered - Elec & Light Indicators	Checked indicators no fault found at this time	588611
796	10/18/2011	325096		CCTV Hard Drive Check	588611
796	10/18/2011	325096		Door Service	588611
796	10/18/2011	325095		Door Service	588611
796	10/18/2011	325095		CCTV Hard Drive Check	588611
796	10/18/2011	325095	SYMBOL (REAR DOOR) SWF SWITCH		588611
796	10/15/2011	324738	Drv entered - Air Cond OtherScrews falling out of air cond	Fitted new screws to A/C ducts	588611
796	10/15/2011	324737	Drv entered - OtherScrews holding dashboard top come out	Replaced dash screws	588611
796	10/05/2011	322561	KIT QUICK RELEASE VALVE		586608
796	10/05/2011	322561	Drv entered - Body & Acc Floor	Fitted new drivers seat quick release valve	586608
796	10/03/2011	322559	2nd from O/S/R seat base ripped	Sewed up tear in seat base	586113
796	10/03/2011	322560	LED FRONT POSITION MARKER LIGHT		586113
796	10/03/2011	322560	N/S number plate light N/W	Replaced number plate light	586113
796	10/03/2011	322558	Reverse buzzer mount broken	Refitted reverse buzzer	586113
796	10/03/2011	322537	Switch lights N/W	Replaced switch light globes	586113
796	10/03/2011	322537	GLOBE WEDGE 24V 1.2W		586113
796	10/03/2011	322561	Drv entered - Body & Acc Floor	Ordered quick release valve switch for drivers seat	586113
796	09/30/2011	322410	TYRE VALVE EXTENSION		586113
796	09/30/2011	322410	N/S/R/I tyre tyre soft	Replaced N/S/R tyre valve extension	586113
796	09/30/2011	322382		A - Service & Bus Safety Inspection	586113
796	09/30/2011	322382		Tension ALL Wheel Nuts to OEM Specs	586113
796	09/30/2011	322382		QAM & road tested	586113
796	09/23/2011	321276	Coolant leak at header tank	Washed header tank road tested light leak ok for now & checkedcoolant level	584638
796	09/22/2011	321083	GLOBE		584400

796	09/21/2011	320983	Drv entered - Steering Pulls Left	Changed n/s/f tyre fitted new clean skin road tested o/k	584226
796	09/21/2011	321083	Dash indicator light N/W	Replaced globe	584400
796	09/21/2011	320982	Grinding noise at lower speeds	Road tested noise from rear tyres OK at this time	584226
796	09/14/2011	319811	Transcal to fit decals	Decals fitted by Transcal	582969
796	09/14/2011	297536	Direct Purchase - BODYWORK	Creditor #:TRA060 TRANSCAL GRAPHICS P/O #:V97357 Receiving #:99271 Date :2011-09-28 Please supply and fit decals to bus 796 as per order sheet	586043
796	09/12/2011	319178	Drv entered - Heat & Demist Heater Cold	Replaced faulty boost pump and heater solinoid relay tested heating ok	582475
796	09/12/2011	319172	Drv entered - Heat & Demist Demisters Cold	Replaced faulty boost pump and heater solinoid relay tested heating ok	582475
796	09/12/2011	319172	RELAY 24V/20AMP		582475
796	08/29/2011	315385	HEADER TANK L94 SIDE FILL	Creditor #:MUL001 MULTISPARES LTD P/O #:V96925R Receiving #:98059 Date :2011-08-29	579220
796	08/24/2011	316062	Drv entered - Vandalism Graffiti	Remove graffiti	578496
796	08/24/2011	316063	Drv entered - Elec & Light Stop lights	check stop lights. (working)	578496
796	08/23/2011	315949	Drv entered - Elec & Light Stop lights	Fit wires correctly to N/S/L brake light	578197
796	08/23/2011	315385	HEADER TANK L94 SIDE FILL	Creditor #:MUL001 MULTISPARES LTD P/O #:V96925 Receiving #:98058 Date :2011-08-29	579220
796	08/19/2011	315401	A/C compressor shaft seal leaking wash & check?	Washed & checked ok	577896
796	08/19/2011	315457	Drv entered - Elec & Light Park Lights	Replaced L.E.D. stop tail lamp	577896
796	08/19/2011	315386	GLOBE WEDGE 24V 1.2W		577896
796	08/19/2011	315386	Guage lights N/W	Replaced guage light globes	577896
796	08/19/2011	315405	FLURO TUBE 18W		577896
796	08/19/2011	315405	Saloon lights N/W	Replaced fluros tubes	577896
796	08/19/2011	315457	L.E.D.STOP+TAIL LIGHT		577896
796	08/19/2011	315385	Header tank split wash & check?	checked ok at this stage	577896
796	08/19/2011	315403	Boost pump leaking	Washed & checked ok	577896
796	08/19/2011	315374	N/S/R passenger seat base loose	Secured rear seat	577896
796	08/18/2011	315110	Doors not working properly half open close back itself wh	Adjusted door operation & checked kneel operation ok	577706
796	08/18/2011	315127	Air leak at front brake chamber	Tightened nsf brake chamber clamp & checked for air leaks OK	577706
796	08/18/2011	314979		Tension ALL Wheel Nuts to OEM Specs	577706
796	08/18/2011	314979		A - Service & Bus Safety Inspection	577706
796	08/18/2011	314979	FILTER OIL K124 / L94UAB (H200W02)	Filter Oil	577706
796	08/18/2011	314979	Hydraulic Oil Torque Fluid 414	Torque fluid	577706
796	08/18/2011	314979	FILTER FUEL K124 / LU94A (1411894 / H17WK05)	Fuel Filter	577706
796	08/18/2011	314979	ENGINE OIL DELO 400LE 15W40	Engine Oil	577706
796	08/18/2011	314979	FILTER TRANSMISSION ZF 4139-298-038E39HD119	Filter ZF Trans	577706
796	08/18/2011	314979	FILTER AIR SCANIA USE AF25066		577706
796	08/18/2011	314979	O RING FILTER KIT K93	Kit . filter Cent	577706
796	08/18/2011	314979		A - Service & Bus Safety Inspection	577706
796	08/08/2011	312850	BALANCE OFF VEHICLE	Creditor #:MIC050 MICHELIN AUSTRALIA PTY LTD P/O #:V96273 Receiving #:97343 Date :2011-08-11	576208
796	08/08/2011	312850	295/80R22.5 XZE2+	Creditor #:MIC050 MICHELIN AUSTRALIA PTY LTD P/O #:V96273 Receiving #:97343 Date :2011-08-11	576208
796	08/08/2011	312850	FITTING	Creditor #:MIC050 MICHELIN AUSTRALIA PTY LTD P/O #:V96273 Receiving #:97343 Date :2011-08-11	576208
796	08/04/2011	312850	N/S/R/O tyre tread low	Replaced N/S/R tyres	574816
796	08/03/2011	311333	Battery hatch struts U/S	Fitted battery hatch struts	574565
796	08/01/2011	311360	BUSH TORQUE ROD KIT		574218
796	08/01/2011	311360	All front upper track rod bushes U/S	Replaced o/s/f track rod bushes	574218
796	08/01/2011	311328	Oil leak around A/C compressor wash & check?	Checked a/c compressor no leak found	574218
796	08/01/2011	312183		Door Service	574218
796	08/01/2011	312183		CCTV Hard Drive Check	574218
796	07/29/2011	311333	GAS STRUT 400NM 330MM	Creditor #:UNI001 UNIVERSAL ENG. SUPPLIES P/L P/O #:V95970 Receiving #:97140 Date :2011-08-08	575495
796	07/28/2011	311337	Park brake leaking out of exhaust	Replaced park brake valve & modify dash to fit	573770
796	07/27/2011	311337	VALVE PARK BRAKE SCANIA L94	Creditor #:MUL001 MULTISPARES LTD P/O #:V95774 Receiving #:96692 Date :2011-07-27	573585
796	07/26/2011	311360	All front upper track rod bushes U/S	Replaced n/s/f track rod bushers	573330
796	07/26/2011	311360	BUSH TORQUE ROD KIT		573330
796	07/26/2011	311328	Oil leak around A/C compressor wash & check?	Washed compressor & road tested ok for now needs to checked in aweeks time.	573330
796	07/26/2011	311317	Both front door guide rollers need to be repositioned	Adjusted rollers so wheel chair ramp does not scrape against door handles.	573330
796	07/26/2011	311322	O/S/R saloon light N/W	Replaced fluro tube	573330
796	07/26/2011	311322	FLURO TUBE 18W		573330
796	07/26/2011	311275	O/S/F saloon light N/W	Replaced fluro tubes	573330
796	07/26/2011	311275	FLURO TUBE 18W		573330
796	07/26/2011	311326	Header tank hose clamps loose	Secure leaking coolant hoses wash up and road test. No leak	573330
796	07/26/2011	311333	Battery hatch struts U/S	Ordered struts	573330
796	07/26/2011	311327	O/S/F wheel arch panel screw missing	Replaced missing screw	573330
796	07/26/2011	311332	N/S/R seat frame needs securing	secured rear seat clamps.	573330
796	07/26/2011	311334	Radiator stone tray missing	Checked ok	573330
796	07/26/2011	311337	Park brake leaking out of exhaust	order new hand brake valve	573330
796	07/26/2011	311362	Moisture ejector N/W	Checked moisture ejector operation could not fault at this time	573330
796	07/25/2011	311091		Transmission /check as per Check List Checked as per list	573330
796	07/25/2011	311161	A/C service & coil clean	Carried out A/C service & coil clean	573330
796	07/25/2011	311034		A - Service & Bus Safety Inspection	573330
796	07/25/2011	311034		Tension ALL Wheel Nuts to OEM Specs	573330
796	06/30/2011	293786	AIR CONDITIONING REPAIR	Creditor #:TRA061 TRANSIT REFRIGERATION & AIR CONDITIONING SERVICE P/O #:V94566 Receiving #:95587 Date :2011-07-01 Retrofit AC controller	568774
796	06/24/2011	293786	Air conditioner flow cold air without heat air?	Take bus to TRAX refer to fault # 306580	568254
796	06/24/2011	293786	Thermostat on climate control reading inaccurate causing A/	Take bus to TRAX refer to fault # 306580	568254
796	06/24/2011	293786	Heater and heater controls not working	Take bus to TRAX refer to fault # 306580	568254
796	06/24/2011	293786	Heaters not working I set temp at 25 degrees it just kept	Take bus to TRAX refer to fault # 306580	568254
796	06/23/2011	306114	CRANK PULLEY BELT B10B 21/32X94		568254
796	06/23/2011	306114	AC Belt jumping off.	Realign A/C compressor fit new belts	568254
796	06/21/2011	306114	AC Belt jumping off.	Checked and AC comp requires repositioning	567963
796	06/09/2011	304453	Graffiti on back seat & walls	Removed graffiti from seat and wall	566043
796	06/09/2011	304453	R clip missing from air bag front of O/S/R	Fitted new R clip	566043
796	06/09/2011	304453	A/C belt has jumped 1 pulley compressor out of alignment	Removed wrong belt and fit right belt	566043
796	06/09/2011	304453	BELT AIR CONDITIONING		566043
796	06/09/2011	304453	Engine hatch micro switch sticking after lube	Cleaned out switch and lube	566043
796	06/09/2011	304453	Body panel screws loose	Tightened body panel screws	566043
796	06/09/2011	304453	Wheel chair decal on front of bus U/S	Checked wheel chair decal OK at this time	566043
796	06/09/2011	304453	Back seat not secure parcel shelf loose	Fitted bolts to rear parcel shelf	566043
796	06/09/2011	304453	No.5 O/S double seat loose at floor	Replaced broken passenger seat bolt	566043
796	06/07/2011	304149		Tension ALL Wheel Nuts to OEM Specs	565892
796	06/07/2011	304149		A - Service & Bus Safety Inspection	565892
796	05/28/2011	302780	FLURO TUBE 18W		563798
796	05/28/2011	302780	Fluro (drivers light) N/W	Replaced drivers & saloon light fluro tubes	563798
796	05/21/2011	289295	Direct Purchase - BODYWORK	Creditor #:TRA060 TRANSCAL GRAPHICS P/O #:V91327 Receiving #:94524 Date :2011-06-08 Please supply and fit decals as per order sheet	565892
796	05/11/2011	296981	FLURO TUBE 18W		558636
796	05/11/2011	296981	N/S saloon fluro light cover missing	Replaced saloon light cover	558636
796	05/11/2011	300022	Accident Damaged # 32966 R/R. o/s. lower body panel No5 Ma	Repaired accident damage # 32966	560938
796	05/11/2011	300022	Accident Damaged # 32966 R/R. o/s. lower body panel No5 Ma	Repaired accident damage # 32966	560938

796	05/11/2011	300120		Door Service	561155
796	05/11/2011	300120		CCTV Hard Drive Check	561155
796	05/08/2011	299629	GLOBE		560687
796	05/08/2011	299629	Service	RSI Inspection RWC583131	560687
796	05/04/2011	298992	O/S king pin has excessive movement	Replaced O/S king pin using bearing type kit	560428
796	05/03/2011	298992	O/S king pin has excessive movement	Dismantle O/S king pin cleaned & inspected	560428
796	04/20/2011	296981	Steering wheel cover loose	Fitted new steering wheel	558636
796	04/20/2011	296981	N/S last folding seat base cover needs securing	Secured loose seat base	558636
796	04/18/2011	296981	Steering wheel adjuster not working	Replaced steering wheel adjuster	558636
796	04/18/2011	297536	PAINT SUPPLIES		558636
796	04/18/2011	297536	BODY SHOP SUPPLIES		558636
796	04/18/2011	297536	ALUMINIUM SUPPLIES		558636
796	04/18/2011	297536	Accident Damaged # 32929 R/R. rear door apeture rubber Rep	Repair accident damage #32929	558636
796	04/15/2011	296981	STEERING WHEEL L94	Creditor #:MUL001 MULTISPARES LTD P/O #:V91145 Receiving #:92554 Date :2011-04-28 BUS 796	559522
796	04/15/2011	297508	Accident damage assessment 10:30 AM appointment	Gary Barney assessed accident damage	558636
796	04/14/2011	296981	HANDLE	Creditor #:SCA001 SCANIA AUSTRALIA PTY LTD P/O #:V91130 Receiving #:92420 Date :2011-04-21	558855
796	04/14/2011	298992	KIT KING PIN L94	Creditor #:MUL001 MULTISPARES LTD P/O #:V91085 Receiving #:92730 Date :2011-05-03	560428
796	04/14/2011	296981	Heater not working	Checked boost pump filter taps & solenoid all OK faulty cab tempprobeTRAX repaired	558636
796	04/14/2011	296981	Brrr! could not get any heating	Refer to fault # 315406	558636
796	04/13/2011	296981	Steering wheel cover loose	Checked steering wheel order steering wheel	558636
796	04/13/2011	296981	Steering wheel adjuster not working	Checked steering wheel adjuster order parts	558636
796	04/13/2011	296981	Air compressor head gasket leaking	Refer to W/O # 288986 replaced air compressor head gasket	558636
796	04/13/2011	296981	GLOBE		558636
796	04/13/2011	296981	N/S/F park light N/W	Replaced N/S/F park light globe	558636
796	04/13/2011	296981	EMERGENCY EXIT DECAL HAMMER SYMBOL		558636
796	04/13/2011	296981	Rear emergency exit decal U/S	Replaced emergency exit decal	558636
796	04/13/2011	296981	FRONT DISC BRAKE ROTORS SCANIA		558636
796	04/13/2011	296981	O/S/F brake rotor undersized 37mm	Replaced front brake rotors & pads road tested	558636
796	04/13/2011	296981	O/S/F brake rotor undersized 37mm	Replaced front brake rotors & pads	558636
796	04/13/2011	296981	BRAKE PADS MERCEDES 0500LE (PLUS SCANIA K124)(A0044206020)		558636
796	04/12/2011	296923		Inspect vehicle as per RSI Checklist	558637
796	04/12/2011	296981	O/S/F brake rotor undersized 37mm	Started front brake reline	558636
796	04/08/2011	296981	DISC PAD SET	Creditor #:MUL001 MULTISPARES LTD P/O #:V90858 Receiving #:92142 Date :2011-04-18	558636
796	04/06/2011	295851	Light cover missing from N/S/R saloon light	Cut fluro light covers to size & fitted	551155
796	04/06/2011	295851	Bell on middle poles not working	Checked bell buttons not fault found at this time	557776
796	04/06/2011	295851	Trans coolant hose U/S	Replaced transmission coolant hose filled with coolant & road tested	557776
796	04/06/2011	295851	HAND PUMP FUEL FEED		557776
796	04/06/2011	295851	Fuel hand primer leaking	Replaced fuel hand primer	557776
796	04/06/2011	295851	Folding seat base torn	Repaired torn seat	557776
796	04/06/2011	296029		A - Service & Bus Safety Inspection	557635
796	04/06/2011	296029	Service	A - Service & Bus Safety Inspection	557635
796	04/05/2011	296029		Tension ALL Wheel Nuts to OEM Specs	557635
796	04/05/2011	296029	Kit Scania Cent Oil filter	Kit . filter Cent	557635
796	04/05/2011	296029	ENGINE OIL DELO 400LE 15W40	Engine Oil	557635
796	04/05/2011	296029	FILTER FUEL K124 / LU94A (1411894 / H17WK05)	Fuel Filter	557635
796	04/05/2011	296029	FILTER TRANSMISSION ZF 4139-298-038E39HD119	Filter ZF Trans	557635
796	04/05/2011	296029	Hydraulic Oil Torque Fluid 414	Torque fluid	557635
796	04/05/2011	296029	FILTER OIL K124 / L94UAB (H200W01)	Filter Oil	557635
796	04/05/2011	296029		A - Service & Bus Safety Inspection	557635
796	04/04/2011	295851	A/C belt needs refitting	Refitted A/C belt	557776
796	04/04/2011	295851	Number plate light N/W	Replaced number plate light globe	557776
796	04/04/2011	295851	GLOBE		557776
796	04/04/2011	295851	Interrior saloon lights N/W	Replaced interrior saloon light fluro tubes	557776
796	04/04/2011	295851	Switch lights N/W	Replace switch light globe	557776
796	04/04/2011	295851	Guage lights N/W	Replaced guage light globes	557776
796	04/04/2011	295851	LED NO PLATE+EXIT LIGHT		557776
796	04/04/2011	295851	25mm BLACK NUMERAL		557776
796	04/04/2011	295851	REFLECTOR ORANGE		557776
796	04/04/2011	295851	RED REFLECTOR NARVA 90x40mm		557776
796	04/04/2011	295851	N/S/R brake chamber U/S	Resealed brake chamber diaphragm	557776
796	04/04/2011	295851	Internal licence to carry decal missing numbers	Replaced internal licence to carry number decals	557776
796	04/04/2011	295851	O/S seat bracket broken on seat behind folding seat	Welded up broken O/S passenger seat frame	557776
796	04/04/2011	295851	Broom handle broken	Replaced broom	557776
796	04/04/2011	295851	N/S/R body panel reflectors missing	Replaced N/S/R body reflectors	557776
796	04/01/2011	295616	Filter Raycor	Raycor filter	557127
796	04/01/2011	295616	Hydraulic Oil Torque Fluid 414	Hydraulic oil	557127
796	04/01/2011	295616	Filter P/S	Power steering filter	557127
796	04/01/2011	295616	Diff Oil Borate EP 460	diff oil	557127
796	04/01/2011	295616		Service as per check list	557127
796	04/01/2011	295616	Service	A - Service & Bus Safety Inspection	557127
796	04/01/2011	295616		Tension ALL Wheel Nuts to OEM Specs	557127
796	04/01/2011	295616		A - Service & Bus Safety Inspection	557127
796	03/25/2011	294509	295/80R22.5 RECAMIC DRIVE PATT	Creditor #:MIC050 MICHELIN AUSTRALIA PTY LTD P/O #:V90177 Receiving #:91257 Date :2011-03-29 XZE Pattern	555652
796	03/25/2011	294509	FITTING	Creditor #:MIC050 MICHELIN AUSTRALIA PTY LTD P/O #:V90177 Receiving #:91257 Date :2011-03-29	555652
796	03/23/2011	294509	Front near side tyre almost bald	Replace N/S/F tyre	555154
796	03/17/2011	293786	A/C return air sensor faulty? swap components with school	Test A/C controller OK check inside temperature sensor faulty TRAX repaired A/C & heater	553509
796	03/08/2011	292476	1MT MULTI FIT WIPER REFILL		550796
796	03/08/2011	292476	1 Wiper insert U/S	Replaced 1 U/S wiper insert	550796
796	02/23/2011	288986	Direct Purchase - BODYWORK	Creditor #:VOL001 VOLGREN AUSTRALIA P/L P/O #:V88459 Receiving #:90789 Date :2011-03-17 Floor insulation for bus 796 2300x450mm	553451
796	02/22/2011	290716		CCTV Hard Drive Check	547494
796	02/22/2011	290716		Door Service	547494
796	02/14/2011	288986	O RING COMPRESSOR MOUNT SCANIA	Creditor #:MUL001 MULTISPARES LTD P/O #:V88362 Receiving #:89510 Date :2011-02-14 Bus 796	546496
796	02/14/2011	288986	LP49-34 COMP H/GASKET KIT (KSK	Creditor #:MUL001 MULTISPARES LTD P/O #:V88362 Receiving #:89510 Date :2011-02-14 Bus 796	546496
796	02/14/2011	289295	Accident Damaged # 32606 R/R.n/s/r. lower engine panel n/s	Repair accident damage #32606	546496
796	02/14/2011	289295	Accident Damaged # 32606 R/R.n/s/r. lower engine panel n/s	Repair accident damage #32606	546496
796	02/11/2011	288986	Isle of floor really soft	Repair damged floor	546324
796	02/11/2011	288986	Isle of floor really soft	Repair damged floor	546324
796	02/10/2011	288986	N/S wiper arm pivot loose	Tighten wiper arm pivot	546324
796	02/10/2011	288986	GLOBE		546324
796	02/10/2011	288986	External door lights N/W	Replace blown globe	546324
796	02/10/2011	288986	Alternator bearings U/S	Check bearings ok	546324
796	02/10/2011	288986	Rear saloon light N/W	Replace blown globe	546324
796	02/10/2011	288986	Isle of floor really soft	Repair damged floor	546324

796	02/10/2011	288986	Isle of floor really soft	Repair damged floor		546324
796	02/10/2011	288986	Isle of floor really soft	Repair damged floor		546324
796	02/10/2011	288986	Isle of floor really soft	Repair damged floor		546324
796	02/10/2011	288986	O/S wheel chair seat base torn	Repair seat		546324
796	02/10/2011	288986	Yellow line at drivers area damaged U/S	Replace decal		546324
796	02/10/2011	288986	O/S 5th from rear seat base loose	Tighten seat base		546324
796	02/10/2011	288986	Isle of floor really soft	Check floor for rot. Rear isle to be replaced by Panel shop		546324
796	02/10/2011	288986	DECAL STAND BEHIND THIS LINE			546324
796	02/10/2011	288986	Air compressor head gasket U/S	Check and order parts for compressor		546324
796	02/09/2011	288928	WIPER WASHER NON-RETURN VALVE			545772
796	02/09/2011	288928	Windscreen washers N/W	Replaced non return valve ok		545772
796	02/09/2011	288928	GLOBE			545772
796	02/09/2011	288928	Door OK light N/W	Replaced door ok light globe		545772
796	02/09/2011	288928	GIVE WAY SIGN (LARGE)			545772
796	02/09/2011	288928	Give way decal U/S	Replaced give way decal		545772
796	02/08/2011	287405	Service	QAM amd road test after service		545596
796	02/07/2011	287405	AIR CON REFRIDGERANT			545596
796	02/07/2011	288526	Air conditioner does not seem to be working properly	Vac and charge AC system (refer W/O #287405)		545772
796	02/07/2011	288526	Air con not cold enough	Vac and charge AC system (refer W/O #287405)		545772
796	02/07/2011	287405	Air conditioning not working properly. Blows warm air	Fit new evaporator fans check over A/C system low on gas recover gas trace leak tighten loose hand tap vac down		545596
796	02/07/2011	287405		A - Service & Bus Safety Inspection		545596
796	02/07/2011	287405	Service	Tension ALL Wheel Nuts to OEM Specs		545596
796	02/01/2011	287405	MOTOR EVAP CARRIER CAPRI 280	Creditor #:TRA TRANIST REFRIGERATION & AIR CONDITIONING SERVICE P/O #:V87873 Receiving #:89030 Date :2011-02-01 Bus 796		545596
796	02/01/2011	287405	CONSUMABLE DELIVERY CHARGE	Creditor #:TRA TRANIST REFRIGERATION & AIR CONDITIONING SERVICE P/O #:V87873 Receiving #:89030 Date :2011-02-01		545596
796	01/31/2011	287406	Service	Transmission /check as per Check List		544845
796	01/31/2011	287405	Air conditioning not working properly. Blows warm air	Check over A/C components. Order evaporator fan motors. Adjust A/C belts and clutch armature clearance		545596
796	01/24/2011	284205	AIR CONDITIONING REPAIR	Creditor #:TRA TRANIST REFRIGERATION & AIR CONDITIONING SERVICE P/O #:V87241 Receiving #:88630 Date :2011-01-24 CHECK A/C OP ON BUS 796		543203
796	01/18/2011	285956	Valve adjustment	Recheck valve adjustment		542956
796	01/13/2011	281475	Air con was on then went off went to 40 degrees it was se			542265
796	01/13/2011	284205	Drv entered - Cool & AC Sys Not Operating	New return air sensor fitted by TRACHS		541299
796	01/12/2011	282965	MOUNT ENGINE SCANIA	Creditor #:MUL001 MULTISPARES LTD P/O #:V86590 Receiving #:88165 Date :2011-01-12 BUS 796		539091
796	01/05/2011	284205	Air conditioner isnt up to standards. Tem reached 33 deg in	Check over system order partNew return air sensor fitted by TRACHS		541299
796	01/05/2011	284205	Climate control not working. Cant cool or heat bus	Order return Air SensorNew return air sensor fitted by TRACHS		541299
796	01/05/2011	284205	Door bell not reliable	Chck no Fault Found		541299
796	12/30/2010	283730	Engine oil leak at rear of engine	Check for oil leak at engine . Secure turbo ooil feed union wash and road test ok		540719
796	12/24/2010	283228	Service	Adjust Tappets		539499
796	12/24/2010	283228	FILTER AIR INNER L94			539499
796	12/22/2010	282965	A/C belt needs adjusting	Adjust AC belts ok		539091
796	12/22/2010	282965	Engine & trans oil leaks wash & check?	Washed and checked. Rear main leaking from bell housing		539091
796	12/22/2010	282965	Alternator idler bearing noisey	Replace alt idler bearing		539091
796	12/22/2010	282965	O/S engine mount rubber split	Order new engine mount		539091
796	12/22/2010	282965	O/S engine mount rubber split	Replace OSF engine mount		539091
796	12/22/2010	282965	BELT POLY			539091
796	12/22/2010	282965	Multi V belt U/S	Replace engine multi belt		539091
796	12/22/2010	282965	Front door exterrior light N/W	Replace fluro tube		539091
796	12/22/2010	282965	O/S number plate light N/W	Check park lights and working ok		539091
796	12/22/2010	282965	Saloon lights N/W	Replace 6 blown fluro tubes		539091
796	12/22/2010	282965	Switch lights N/W	Replace blown switch light globes		539091
796	12/22/2010	282965	Vinyl floor lifted between rear wheels check & report?	Floor checked by Danny H and ok to run at this time		539091
796	12/22/2010	282965	Drivers seat base cover U/S - In stock	Replace drivers seat cushion cover		539091
796	12/22/2010	282965	CUSHION COVER ISRI 6860			539091
796	12/22/2010	282965	Rear brake disc pads low close to end of slides	Replace rear brake pads and road test ok		539091
796	12/22/2010	282965	DISC PAD SET SCANIA			539091
796	12/22/2010	282965	Rear brake disc pads low close to end of slides	Replace rear brake pads and road test ok		539091
796	12/20/2010	282055	CUSHION COVER ISRI 6860	Creditor #:ISR001 ISRINGHAUSEN P/L P/O #:V86317 Receiving #:87457 Date :2010-12-20 BUS 796		538651
796	12/16/2010	282234	Kit Scania Cent Oil filter	Kit . filter Cent		538155
796	12/16/2010	282234	WORKSHOP SUPPLIES			538155
796	12/16/2010	282234	FILTER OIL K124 / L94UAB (H200W01)	Filter Oil		538155
796	12/16/2010	282234	Hydraulic Oil Torque Fluid 414	Torque fluid		538155
796	12/16/2010	282234	FILTER TRANSMISSION ZF 4139-298-038E39HD119	Filter ZF Trans		538155
796	12/16/2010	282234	FILTER FUEL K124 / LU94A (1411894 / H17WK05)	Fuel Filter		538155
796	12/16/2010	282234	ENGINE OIL DELO 400LE 15W40	Engine Oil		538155
796	12/16/2010	282234		Tension ALL Wheel Nuts to OEM Specs		538155
796	12/16/2010	282234	Service	A - Service & Bus Safety Inspection		538155
796	12/16/2010	282234		A - Service & Bus Safety Inspection		538155
796	12/15/2010	282055	Cover on drivers seat need replacing	Fit new seat base		538069
796	12/14/2010	281475	SEAL SHAFT 05G A/C COMPRESSOR	Creditor #:CAR008 CARRIER P/O #:V85989 Receiving #:87252 Date :2010-12-14 BUS796		537502
796	12/10/2010	281475	Air conditioning works but needs gas I think cause it wont	Check over AC system pressures ok and gas level ok 4 out of 6 condensor fans not working order parts		536886
796	12/10/2010	281597	GLOBE			536978
796	12/10/2010	281597	OSF park light not working	Replace park light globe		536978
796	12/03/2010	280324	WASHER PUMP 24VOLT			535073
796	12/03/2010	280324	W/screen washer pump possibly burnt out not pumping water	Replace washer motor and test ok		535073
796	12/01/2010	279448	FITTING	Creditor #:MIC050 MICHELIN AUSTRALIA PTY LTD P/O #:V85290 Receiving #:86646 Date :2010-12-01		534806
796	12/01/2010	279448	295/80R22.5 RECAMIC DRIVE PATT	Creditor #:MIC050 MICHELIN AUSTRALIA PTY LTD P/O #:V85290 Receiving #:86646 Date :2010-12-01		534806
796	12/01/2010	280055		CCTV Hard Drive Check		535036
796	12/01/2010	280055	Service	Door Service		535036
796	11/25/2010	279448	OSR outer tyre U/S	Replace both OSR tyres with new Michelin recaps		534007
796	11/25/2010	279043	TYRE VALVE EXTENSION			533686
796	11/25/2010	279043	Boost pump leaking	Fit new coolant boost pump		533686
796	11/25/2010	279043	PUMP BOOST A/C HEATER			533686
796	11/25/2010	279043	Boost pump leaking	Assist with fitting new coolant boost pump		533686
796	11/23/2010	279043	Boost pump leaking	Wash road test and check for leaks from boost pump. Order new boost pump		533686
796	11/10/2010	276736	Coolant boost pump leaking	Recheck boost pump and ok to run at this time		528953
796	11/08/2010	276736	1MT MULTI FIT WIPER REFILL			528953
796	11/08/2010	276736	GLOBE			528953
796	11/08/2010	276736	REFLECTOR ORANGE			528953
796	11/05/2010	276736	Wiper inserts U/S	Replace wiper inserts		528953
796	11/05/2010	276736	O/S/R seat base slashed	Stitch up torn seats		528953
796	11/05/2010	276736	Graffiti on rear seats	Check graffiti and has already been cleaned off by cleaners		528953
796	11/05/2010	276736	A/C pipe rubbing on alternator cooler pipe	Reposition and secure cooler pipe		528953
796	11/05/2010	276736	Coolant boost pump leaking	Check and requires new boost pump		528953
796	11/05/2010	276736	Switch lights not working	Replace blown switch light globes		528953
796	11/05/2010	276736	N/S/F fluro not working	Replace fluro with second hand ok one nil stosk of new ones		528953

796	11/05/2010	276736	Body reflectors missing	Replace missing reflector		528953
796	11/05/2010	276736	Mirror loose on N/S mirror head	Secure mirror glass		528953
796	11/05/2010	276736	Rear seat base loose	Secure seat base		528953
796	11/03/2010	276431	Service	QAM after service		528552
796	11/03/2010	276431		A - Service & Bus Safety Inspection		528552
796	11/03/2010	276431		Tension ALL Wheel Nuts to OEM Specs		528552
796	10/28/2010	275633	295/80R22.5 RECAMIC DRIVE PATT	Creditor #:MIC050 MICHELIN AUSTRALIA PTY LTD P/O #:V84000 Receiving #:85286 Date :2010-10-28		526340
796	10/28/2010	275633	FITTING	Creditor #:MIC050 MICHELIN AUSTRALIA PTY LTD P/O #:V84000 Receiving #:85286 Date :2010-10-28		526340
796	10/28/2010	275634	CAP SERVICE VALVE O5G COMPRESSOR			526340
796	10/28/2010	275634	BODY SHOP SUPPLIES			526340
796	10/27/2010	275634	Air con not working	Check pressures check for leaks replace comp oil. Replace receiver dryer vac down and cherge with 6.5 kg of gas		527127
796	10/26/2010	275633	OSRO tyre flat	Replace OSRO tyre with good second hand recap		526862
796	10/13/2010	273467	Turbo U/S	Replace turbo road test. Top up oil		524073
796	10/13/2010	273467	Filter Air Inner Scania K124EB			524073
796	10/13/2010	273467	O RING TURBO SCANIA L94UAB	Creditor #:SCA001 SCANIA AUSTRALIA PTY LTD P/O #:V83282 Receiving #:84590 Date :2010-10-13 BUS 796		524073
796	10/13/2010	273467	GASKET EXHAUST MANIFOLD	Creditor #:SCA001 SCANIA AUSTRALIA PTY LTD P/O #:V83282 Receiving #:84590 Date :2010-10-13 BUS 796		524073
796	10/13/2010	273467	TURBO SCANIA L94	Creditor #:SCA001 SCANIA AUSTRALIA PTY LTD P/O #:V83282 Receiving #:84590 Date :2010-10-13 1766750 TURBO FOR BUS 796		524073
796	10/13/2010	273467	GASKETEXHAUST	Creditor #:SCA001 SCANIA AUSTRALIA PTY LTD P/O #:V83282 Receiving #:84590 Date :2010-10-13 BUS 796		524073
796	10/12/2010	273467	Turbo U/S	Remove turbo		524073
796	10/07/2010	272844	A/C belt has jumped pulley on compressor	Refit A/C belt		523210
796	10/04/2010	272400	Drivers seat fraying infront top	Sew up torn seat		522385
796	09/16/2010	269039	Very noisy diff	Refit diff and road test ok		518271
796	09/15/2010	270059	O/S/R tyre flat	Check O/S/R tyre pressures could not fault		518482
796	09/15/2010	269110	SENDER OIL PRESS. L94			518482
796	09/15/2010	269039	Very noisy diff	Assemble diff with all new bearings		518271
796	09/15/2010	249251	Direct Purchase - BODYWORK	Creditor #:TRA060 TRANSCAL GRAPHICS P/O #:V82215 Receiving #:83513 Date :2010-09-15 S&F DECALS TO 796		518482
796	09/14/2010	269110	Engine oil pressure light N/W	Replace engine oil pressure switch		518487
796	09/14/2010	269039	Very noisy diff	Assemble diff with all new bearings		518271
796	09/10/2010	269039	PINION NUT SCANIA R660 DIFF	Creditor #:MUL001 MULTISPARES LTD P/O #:V81911 Receiving #:83297 Date :2010-09-10		518271
796	09/10/2010	269039	DIFF BRG & SEAL KIT SCANIA R66	Creditor #:MUL001 MULTISPARES LTD P/O #:V81911 Receiving #:83296 Date :2010-09-10 DIFF PARTS FOR BUS 796		518271
796	09/10/2010	269039	WASHER THRUST SPIDER GEAR SCAN	Creditor #:MUL001 MULTISPARES LTD P/O #:V81911 Receiving #:83296 Date :2010-09-10		518271
796	09/10/2010	269039	THRUST WASHER SIDE GEAR SCANI	Creditor #:MUL001 MULTISPARES LTD P/O #:V81911 Receiving #:83296 Date :2010-09-10		518271
796	09/09/2010	268721	FITTING	Creditor #:MIC050 MICHELIN AUSTRALIA PTY LTD P/O #:V81781 Receiving #:83233 Date :2010-09-09 Fit Run out tyre to rim EX 796		518482
796	09/09/2010	268721	BALANCE OFF VEHICLE	Creditor #:MIC050 MICHELIN AUSTRALIA PTY LTD P/O #:V81781 Receiving #:83233 Date :2010-09-09 Fit Run out tyre to rim EX 796		518482
796	09/08/2010	269110	Wiper arms require adjustment	Adjust wiper arms		518487
796	09/08/2010	269110	N/S saloon fluro N/W	Replace saloon fluro tubes		518487
796	09/08/2010	269110	Engine oil pressure light N/W	Order engine oil pressure switch		518487
796	09/08/2010	269110	GLOBE			518487
796	09/08/2010	269110	FLURO TUBE 18W			518487
796	09/08/2010	269110	O/S number plate light N/W	Could not fault working ok		518487
796	09/08/2010	269110	Switch lights N/W	Replace switch light globes		518487
796	09/08/2010	269110	Front step light N/W	Replace front step light fluro tube		518487
796	09/08/2010	269110	Globe in passenger stop light N/W	Replace passenger stop globe		518487
796	09/08/2010	269039	Very noisy diff	Dismantle diff		518271
796	09/08/2010	269110	Trim missing from O/S/R seat back	Fit new trim to 4 seat backs		518487
796	09/07/2010	269039	Very noisy diff	Start to remove diff centre		518271
796	09/07/2010	268917	Hydraulic Oil Torque Fluid 414	Torque fluid		518482
796	09/07/2010	268917	FILTER OIL K124 / L94UAB (H200W01)	Filter Oil		518482
796	09/07/2010	268917	Kit Scania Cent Oil filter	Kit . filter Cent		518482
796	09/07/2010	268917	ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL	Engine Oil		518482
796	09/07/2010	268917	FILTER FUEL K124 / LU94A (1411894 / H17WK05)	Fuel Filter		518482
796	09/07/2010	268917	FILTER TRANSMISSION ZF 4139-298-038E39HD119	Filter ZF Trans		518482
796	09/07/2010	268917		A - Service & Bus Safety Inspection		518482
796	09/07/2010	268917	Service	QAM and road test after service		518482
796	09/07/2010	268917	WORKSHOP SUPPLIES			518482
796	09/07/2010	268917		A - Service & Bus Safety Inspection		518482
796	09/07/2010	268917	Service	Tension ALL Wheel Nuts to OEM Specs		518482
796	09/04/2010	268721	OSF tyre worn out	Replace O/S/F tyre repair damaged low pad warning wire		518351
796	09/02/2010	268302		Door Service		517314
796	09/02/2010	268302		CCTV Hard Drive Check		517314
796	08/28/2010	267725	Service	Transmission /check as per Check List		516077
796	08/27/2010	267582	Fit wheel nut squirrels to rear wheel hubs	Fit squirrels to rear wheel nuts		516077
796	08/27/2010	267582	WHEEL NUT SQUIRREL			516077
796	08/11/2010	265392	Refit original 2-way	Refit original two way head		512808
796	08/11/2010	265392	Driver cabin door is broken	Replace both door hinges		512808
796	08/11/2010	265392	BUTT HINGE BLACK			512808
796	08/11/2010	265392	Drivers door hinges broken	Replace both door hinges		512808
796	08/11/2010	265392	BOLT			512808
796	08/06/2010	264725	NS headlight not working	Replace headlight globe		511038
796	08/06/2010	264725	GLOBE HEADLAMP H1			511038
796	08/03/2010	264262	AC coil clean and service	AC coil clean and service		511038
796	07/28/2010	263358	WORKSHOP SUPPLIES			511038
796	07/28/2010	263358	BELT TWIN A/C			511038
796	07/28/2010	263358	Copper AC pipe rubbed through on body work	Complete repairs to rubbed through copper pipe at OS of engine bay		511038
796	07/28/2010	263358	Copper AC pipe rubbed through on body work	Complete repairs to rubbed through copper pipe at OS of engine bay		511038
796	07/27/2010	263358	Copper AC pipe rubbed through on body work	Start repairs to rubbed through copper pipe at OS of engine bay		511038
796	07/26/2010	262959	RECIEVER/DRYER A/C CAPRI 280			510799
796	07/26/2010	262959	AC comp U/S	Finish fitting new AC comp and clutch.		510799
796	07/23/2010	262959	AC comp U/S	Start fitting new AC compressor		510799
796	07/23/2010	262676	Hazard light switch not working	Fit new hazard switch		510701
796	07/23/2010	262676	hazard switch scania L94			510701
796	07/21/2010	262676	Hazard light switch not working	Trace fault in hazard switch circuit and order parts to repair		510701
796	07/19/2010	262304	Air conditioner heater unit not working displays FL	Run bus to operating temp and check heaters ok		509817
796	07/13/2010	261590	Strip and diagnose AC compressor	Strip AC compresor. Thrown 3 conrods and compressor U/s		508562
796	07/12/2010	260322	FLURO TUBE 18W			507321
796	07/12/2010	260322	GAS STAY 350N-565MM			507321
796	07/10/2010	260322	O/S saloon light N/W	Replace fluro rube		507321
796	07/10/2010	260322	Engine hatch struts U/S	Fit new hatch struts		507321
796	07/10/2010	260322	Last N/S double seat base needs securing	Secure seat base		507321
796	07/09/2010	261194		A - Service & Bus Safety Inspection		508562
796	07/09/2010	261194		Tension ALL Wheel Nuts to OEM Specs		508562
796	07/08/2010	261021	Accident Damaged # 31211 R/R. front bumper-bar-fibreglass	Repair accident damage #31211 repaired in the 4th month of 2010		508562
796	07/03/2010	260514	A/C belts U/S - been removed	Check AC comp and remove belts AC comp U/S		507790

796	07/01/2010	260204	Two-way keeps turning off or switching between channels 0-2	Test two way operation and remove for repair fit spare head and test ok	507600
796	07/01/2010	260322	Engine hatch struts U/S	Remove struts and order	507321
796	06/09/2010	257684		CCTV Hard Drive Check	502861
796	06/09/2010	257684		Door Service	502861
796	06/06/2010	257320	RSI Inspection	RSI Inspection (BC 126653)	502399
796	06/05/2010	257177	Wash and check over for RSI	Wash and checkover for RSI	502399
796	06/05/2010	257177	Wash and check over for RSI	Wash and checkover for RSI	502399
796	06/03/2010	257064	Inspect floor put hole in vinyl above rear axle check if	Inspect first layer of timber has separated	502111
796	05/31/2010	256312	Batteries to be replaced	Replace original Scania batteries with 2 power crank N94	501571
796	05/31/2010	256312	BATTERY		501571
796	05/29/2010	256258	Con not remove hard drive	Trace fault with hard drive and repair hard drive unit lock	501571
796	05/29/2010	256258	Service	Assist with repairing hard drive unit	501571
796	05/28/2010	256150	Batteries flat	Jump start	501571
796	05/27/2010	256002	Drivers seat shocker in stock	Fit new shocker to drivers seat and order new batterins for bus	501027
796	05/24/2010	255710	Graffiti on seats	Remove Graffiti	500381
796	05/22/2010	255413	Flat batteries	Jump start and put on charge	500381
796	05/21/2010	254999	Service	Finish replacing 3 rear air bags	499953
796	05/20/2010	254988	Rear OS seat base has hol in it	Stitch seat back together	499953
796	05/20/2010	254993	Rear seat blocks have been ripped off	Refit seat blocks to bases	499953
796	05/20/2010	254998	Do not sit in this area decal missing	Replace decal	499953
796	05/20/2010	254998	DECAL. DO NOT SIT HERE		499953
796	05/20/2010	254999	Service	Assist with removing air bags	499953
796	05/20/2010	254999	Replace 2 OSR air bags and 1 NSF of rear air bags	Start to replace air bags	499953
796	05/20/2010	254999	REAR AIR BAG (DRIVE AXLE) SCANIA L94UAB		499953
796	05/20/2010	254966	Switch lights not working	Replace 3 switch light globes	499953
796	05/20/2010	254966	GLOBE 24V 1.2W SWF SWITCH		499953
796	05/20/2010	254985	Secure wiring under dash	Tie up and secure wiring under dash board	499953
796	05/20/2010	254994	Secure wiring to tray under bus	Secure all wiring under bus along chassis	499953
796	05/20/2010	254996	Saloon light not working	Replace 3 saloon light fluro tubes	499953
796	05/20/2010	254996	FLURO TUBE 18W		499953
796	05/20/2010	254997	HAND PUMP FUEL FEED		499953
796	05/20/2010	254995	Fuel line rubbing on P clamp next to alternator	Insulate P clamp on fuel line	499953
796	05/20/2010	254997	Wash and check fuel leak at primer pump	Replace fuel primer pump and wash and test ok	499953
796	05/20/2010	254986	NS rear bumper chevron missing	Replace chevron decal	499953
796	05/20/2010	254986	REAR MARKER DECAL		499953
796	05/20/2010	254987	Battery hatch struts U/S	Fit 2 second hand battery hatch struts ok	499953
796	05/20/2010	254989	1st NS grab handle cracked	Replace grab handle. No parts charged because we did not pay for them	499953
796	05/20/2010	254991	Wheel chair ramp decal on front of bus U/S	Replace wheel chair ramp decal	499953
796	05/20/2010	254991	STICKER INTERNATIONAL DISABLE LOW FLOOR (BLUE)		499953
796	05/20/2010	254992	OSR wheel arch panel screws loose	Drill tap and secure wheel arch panel screws	499953
796	05/19/2010	254788	Drivers seat controls for seat first and middle control swi	Replace NTS switch on drivers seat	499465
796	05/19/2010	254788	ADJUSTER DRIVERS SEAT		499465
796	05/19/2010	254761	FILTER TRANSMISSION ZF 4139-298-038E39HD119	Filter ZF Trans	499465
796	05/19/2010	254761	FILTER FUEL K124 / LU94A (1411894 / H17WK05)	Fuel Filter	499465
796	05/19/2010	254761	ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL	Engine Oil	499465
796	05/19/2010	254761		Tension ALL Wheel Nuts to OEM Specs	499465
796	05/19/2010	254761		A - Service & Bus Safety Inspection	499465
796	05/19/2010	254761	Hydraulic Oil Torque Fluid 414	Torque fluid	499465
796	05/19/2010	254761	FILTER OIL K124 / L94UAB (H200W01)	Filter Oil	499465
796	05/19/2010	254761	Kit Scania Cent Oil filter	Kit . filter Cent	499465
796	05/19/2010	254761		A - Service & Bus Safety Inspection	499465
796	05/06/2010	253262	When diirs close bell and bus stop come on	check for faulty door bell could not fault	497094
796	05/05/2010	253127	Service	Inspect vehicle as per RSI Checklist	497094
796	04/30/2010	252547	ACCUMULATOR RETARDER VALVE B12BLE		495831
796	04/30/2010	252547	Replace accumulator solenoid valve	Replace accumulator valve and test ok	495831
796	04/28/2010	252245	Bus skidded ABS may not be working	Check ABS sensors and road test could not fault	495831
796	04/23/2010	251258	VALVE FOOT BRAKE		495340
796	04/19/2010	251258	Replace foot valve potentiometer	Replace brake foot valve and adjut potentiometer	495340
796	03/31/2010	249251	Accident Damaged # 30988 (Est. 25.0 Hrs.) R/R. front bumpe		492950
796	03/19/2010	248121	A/C Not cooling	Check A/C operation no fault found	492950
796	03/15/2010	247609		CCTV Hard Drive Check	491906
796	03/15/2010	247609		Door Service	491906
796	03/15/2010	247609		COMPLETED	491906
796	03/01/2010	262959	COMPRESSOR A/C 05G	Creditor #:CAR008 CARRIER P/O #:V79567 Receiving #:81262 Date :2010-07-26 BUS 796 C/O O5G COMPRESSOR	510799
796	03/01/2010	262959	CLUTCH A/C 05G 24V 2B GROOVE	Creditor #:CAR008 CARRIER P/O #:V79567 Receiving #:81262 Date :2010-07-26 BUS 796 2B 24V CLUTCH FOR A/C COMPRESSOR	510799
796	03/01/2010	262959	NUT 05G COMPRESSOR CRANK/CLUT	Creditor #:CAR008 CARRIER P/O #:V79998 Receiving #:81275 Date :2010-07-26 BUS 796	510799
796	03/01/2010	262304	RECIEVER/DRYER A/C CAPRI 280	Creditor #:CAR008 CARRIER P/O #:V79725 Receiving #:81090 Date :2010-07-21 BUS796	510701
796	03/01/2010	262959	AIR CONDITIONING REPAIR	Creditor #:CAR008 CARRIER P/O #:V79567 Receiving #:81262 Date :2010-07-26 CORE DEPOSIT	510799
796	03/01/2010	260204	Direct Purchase - ELECTRICAL	Creditor #:RFE001 RF ELECTROCOM P/O #:I79075 Receiving #:80715 Date :2010-07-09 BUS 796	508562
796	03/26/2009	0	Imported Service History	Imported Service History	416970