

| Veh# | Date       | W/O#    | Description                                                  | Notes                                                                                                                                                     | Odometer |
|------|------------|---------|--------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------|----------|
| 797  | 09/05/2026 | 1367345 |                                                              | COMPLETED BY ATS 12/8/26                                                                                                                                  | 1159100  |
| 797  | 08/21/2026 | 1356808 | DECAL MAX SAFE CARRY BLACK ON WHITE                          |                                                                                                                                                           | 1159100  |
| 797  | 07/29/2026 | 1357824 | Decommission Bus for Auction                                 | Assisting                                                                                                                                                 | 1159100  |
| 797  | 07/29/2026 | 1357824 | Decommission Bus for Auction                                 | Jump started the bus and carried out decom preparation                                                                                                    | 1159100  |
| 797  | 07/24/2026 | 1356743 |                                                              | VEHICLE SAFETY INSPECTION carried out safety inspection.                                                                                                  | 1159100  |
| 797  | 07/24/2026 | 1356743 |                                                              | TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS                                                                                                              | 1159100  |
| 797  | 07/24/2026 | 1356808 | Consumables                                                  |                                                                                                                                                           | 1159100  |
| 797  | 07/24/2026 | 1356808 | Consumables                                                  |                                                                                                                                                           | 1159100  |
| 797  | 07/24/2026 | 1356808 | Mechanic entered - Elec and Light Exterior Lights N/S/R Reve | replaced blown globe checked for operation ok.                                                                                                            | 1159100  |
| 797  | 07/24/2026 | 1356808 | Mechanic entered - Body Other O/S/F Wheel Arch Brush Not sec | re secured osf wheel arch brush.                                                                                                                          | 1159100  |
| 797  | 07/24/2026 | 1356808 | DECAL MAX SAFE CARRY BLACK ON WHITE                          |                                                                                                                                                           | 1159100  |
| 797  | 07/24/2026 | 1356808 | Mechanic entered - Body Other Interior Maximum Capacity deca | removed Wrong decal fitted new decal with capacity.                                                                                                       | 1159100  |
| 797  | 06/12/2026 | 1347445 | AIR CONDITIONING REPAIR                                      | Creditor #;VB-COL004 COLD DRIVE PTY LTD P/O #:O412345 Receiving #:439522 Date :2026-06-19 carry out AC-B service                                          | 1159100  |
| 797  | 06/12/2026 | 1347445 |                                                              | CARRY OUT A/C - B SERVICE AS PER CHECK LIST carried out by Dave Cold Drive O412345                                                                        | 1159100  |
| 797  | 06/12/2026 | 1347445 |                                                              | CARRY OUT A/C - A SERVICE AS PER CHECK LIST                                                                                                               | 1159100  |
| 797  | 05/06/2026 | 1338942 | AIR CONDITIONING REPAIR                                      | Creditor #;VB-COL004 COLD DRIVE PTY LTD P/O #:O409831 Receiving #:436746 Date :2026-05-15 check and rectify ac not cooling                                | 1159100  |
| 797  | 05/06/2026 | 1338942 | A/C Heating Air Conditioning not cooling                     | shaft seal and other gas leak fixed by Ben PO completed by Ben Cold drive PO O409831                                                                      | 1159100  |
| 797  | 05/06/2026 | 1338830 |                                                              | CARRY OUT CCTV - A SERVICE AS PER CHECK LIST carried out as per check list                                                                                | 1159100  |
| 797  | 04/30/2026 | 1337512 |                                                              | ASSISTING                                                                                                                                                 | 1159100  |
| 797  | 04/30/2026 | 1337512 |                                                              | VEHICLE SAFETY INSPECTION                                                                                                                                 | 1159100  |
| 797  | 04/30/2026 | 1337512 |                                                              | TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS                                                                                                              | 1159100  |
| 797  | 04/30/2026 | 1337600 | Mechanic entered - Steering Excessive Play Steering wheel ad | Removed steering covers tightened adjuster pawl checked for movement ok refitted covers.                                                                  | 1159100  |
| 797  | 04/30/2026 | 1337600 | Consumables                                                  |                                                                                                                                                           | 1159100  |
| 797  | 04/30/2026 | 1337600 | Mechanic entered - Elec and Light Next Stop Button 1x Pax Be | removed pax bell found connection not fitted refitted connection checked for operation ok.                                                                | 1159100  |
| 797  | 04/30/2026 | 1337600 | INVERTER 24VDC 15-36W                                        |                                                                                                                                                           | 1159100  |
| 797  | 04/30/2026 | 1337600 | Mechanic entered - Elec and Light Interior Lights N/S/R Salo | Inverter U/S - No power to light replaced inverter checked for operation ok.                                                                              | 1159100  |
| 797  | 04/30/2026 | 1337600 | LIGHT INDICATOR SIDE R/H                                     |                                                                                                                                                           | 1159100  |
| 797  | 04/30/2026 | 1337600 | Mechanic entered - Elec and Light Exterior Lights O/S/F Indi | replaced lens with new item from stock ok.                                                                                                                | 1159100  |
| 797  | 04/30/2026 | 1337600 |                                                              | removed and replaced with new brake light from stock. checked working .                                                                                   | 1159100  |
| 797  | 04/30/2026 | 1337600 | LIGHT LED STOP/TAIL RED 9 LED - 3 LED PARKER                 |                                                                                                                                                           | 1159100  |
| 797  | 04/30/2026 | 1337600 | Consumables                                                  |                                                                                                                                                           | 1159100  |
| 797  | 04/30/2026 | 1337600 | Mechanic entered - Body Other fuse bord hatch nit secured    | removed hatch lock and adjuted .                                                                                                                          | 1159100  |
| 797  | 04/30/2026 | 1337600 | Mechanic entered - Body Other disabel seat top pins center o | knocked and make it center.                                                                                                                               | 1159100  |
| 797  | 04/30/2026 | 1337600 | Mechanic entered - Body Other o/s seat gas strut broken .    | removed seat and strut reinstalled.                                                                                                                       | 1159100  |
| 797  | 04/30/2026 | 1337600 | Mechanic entered - Body Other o/s front air vent screws miss | fitted new screws.                                                                                                                                        | 1159100  |
| 797  | 04/21/2026 | 1335532 | >>>RAIL BUS <<< A/C compressor shaft seal leaking.           | carried out by Ben Cold drive                                                                                                                             | 1159100  |
| 797  | 03/27/2026 | 1326829 | DIRECT PURCHASE - MECHANICAL G                               | Creditor #;VB-ENZED ENZED MOORABBIN P/O #:O407204 Receiving #:433196 Date :2026-03-30 supply fitting and fix the air hose as required                     | 1159100  |
| 797  | 03/26/2026 | 1326829 |                                                              | change fittings to new manifold and fitrun busok. po for Enzed O407204                                                                                    | 1159100  |
| 797  | 03/13/2026 | 1326829 | 1354646 Manifold Fitting                                     | Creditor #;VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:O406321 Receiving #:432023 Date :2026-03-13                                                           | 1159100  |
| 797  | 03/12/2026 | 1326829 | AIR MANIFOLD VALVE U/S                                       | ORDERED VALVE WITH IAN . MANIFOLD VALVE WAS NEEDED FOR A VOR SCHOOL BUS @ ROSEBUD . REMOVED FROM 797 AND SENT TO ROSEBUD . NEW VALVE TO GO TO 797         | 1159100  |
| 797  | 02/26/2026 | 1319345 | Mechanic entered - Elec and Light Flat Batteries Front batte | Modify the same alloy bracket fit back swapped around fit plates and mounting screws fit frame on stands and tight bolts fit strut and new seat end cap   | 1159042  |
| 797  | 02/26/2026 | 1319345 | CAP CENTRA SEAT END MCCONNELL                                |                                                                                                                                                           | 1159042  |
| 797  | 02/26/2026 | 1323420 |                                                              | COMPLETED BY ATS 15/2/26                                                                                                                                  | 1159042  |
| 797  | 02/09/2026 | 1319345 | >>>RAIL BUS <<< NSR HATCH STRUT BRACKET MISSING              | Checked for bracket could not fault                                                                                                                       | 1159042  |
| 797  | 02/07/2026 | 1319048 |                                                              | VEHICLE SAFETY INSPECTION                                                                                                                                 | 1159042  |
| 797  | 02/07/2026 | 1319048 |                                                              | TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS                                                                                                              | 1159042  |
| 797  | 02/07/2026 | 1319089 | Mechanic entered - Wipers and Washers Wipers Noisy N/S wiper | Removed and replaced wiper blade refill tested okay now                                                                                                   | 1159042  |
| 797  | 02/07/2026 | 1319089 | Mechanic entered - Elec and Light Flat Batteries Front batte | Removed and replaced battery with good second hand one removed from decommissioned bus charge the batteries                                               | 1159042  |
| 797  | 02/07/2026 | 1319089 | Mechanic entered - Elec and Light Interior Lights One saloon | Removed and rplaced fluro                                                                                                                                 | 1159042  |
| 797  | 02/07/2026 | 1319089 | Consumables                                                  |                                                                                                                                                           | 1159042  |
| 797  | 01/01/2026 | 1309449 | DIRECT PURCHASE - VANDALISM                                  | Creditor #;VB-GLA010 GLASSPROTECH MELBOURNE P/O #:O401206 Receiving #:427339 Date :2026-01-05 Anti-graffiti audit #1281 - 15/12/25                        | 1159042  |
| 797  | 12/16/2025 | 1309449 | Anti-Graffiti Film Audit # 1281 - 15/12/25                   | PO:O401206 - CARRIED OUT BY GLASS PROTECH                                                                                                                 | 1159042  |
| 797  | 11/17/2025 | 1302901 | DIRECT PURCHASE - BUS INSPECTI                               | Creditor #;VB-ROA002 ROAD SAFETY INSPECTIONS P/O #:O399019 Receiving #:424167 Date :2025-11-18                                                            | 1159042  |
| 797  | 11/14/2025 | 1302901 |                                                              | VEHICLE SAFETY INSPECTION                                                                                                                                 | 1159042  |
| 797  | 11/14/2025 | 1302901 |                                                              | TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS                                                                                                              | 1159042  |
| 797  | 11/14/2025 | 1302901 |                                                              | ANNUAL SAFETY INSPECTION SERIAL # _RSI 074856 PASS___ WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25 | 1159042  |
| 797  | 11/12/2025 | 1302341 |                                                              | CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST carried ou as per check list                                                                           | 1159042  |
| 797  | 11/11/2025 | 1302243 | FUEL / CHECK / FUEL BUS 797 AS REQUIRED                      | COMPLETED                                                                                                                                                 | 1159042  |
| 797  | 11/11/2025 | 1302243 | Consumables                                                  |                                                                                                                                                           | 1159042  |
| 797  | 11/10/2025 | 1301845 | Mechanic entered - Elec and Light Flat Batteries             | Jump started ok.                                                                                                                                          | 1159042  |
| 797  | 10/30/2025 | 1300123 | Mechanic entered - Suspension Other N/S/R rear shock absorbe | Removed shock absorber and replaced with new one                                                                                                          | 1159042  |
| 797  | 10/30/2025 | 1300123 | HANDLE GRAB PLASTIC PASSENGER GREY SE-GH001(29769)           |                                                                                                                                                           | 1159042  |
| 797  | 10/30/2025 | 1300123 | SHOCK ABSORBER REAR SCANIA L94/K124 300 025 1478317          |                                                                                                                                                           | 1159042  |
| 797  | 10/30/2025 | 1300122 | 2ND PRE ASI CHECK                                            | Carried out 2nd check                                                                                                                                     | 1159042  |
| 797  | 10/30/2025 | 1300123 | Mechanic entered - Body Other N/S hand rail grab worn        | Removed and replaced hand rail grab with new one                                                                                                          | 1159042  |
| 797  | 10/30/2025 | 1300123 | Mechanic entered - Body Other Panel above rear door screw mi | Fit missing screws                                                                                                                                        | 1159042  |
| 797  | 10/10/2025 | 1295607 | Mechanic entered - Wheels and Tyres Wheel Nut Retension N/S/ | TOOK FOR A LONG DRIVE AND RETORQUE ALL REAR WHEEL NUTS.                                                                                                   | 1159042  |
| 797  | 10/10/2025 | 1295607 | Consumables                                                  |                                                                                                                                                           | 1159042  |
| 797  | 10/09/2025 | 1295239 | Service                                                      | parked the bus up the top for O'Brien - job completed                                                                                                     | 1159042  |
| 797  | 10/09/2025 | 1295239 | GLASS RESEAL                                                 | Creditor #;VB-OBRO01 O'BRIENS GLASS INDUSTRIES P/O #:O396677 Receiving #:421347 Date :2025-10-10 RESEAL GLASS X 1 AS REQUIRED                             | 1159042  |
| 797  | 10/08/2025 | 1295239 | REAR GLASS TO BE RESEALED - LDM CONFIRMED                    | PO:O396677 - OBRIANS ONLINES BOOKING COMPLETE . WAITING FOR REPAIR DATE                                                                                   | 1159042  |
| 797  | 10/06/2025 | 1294481 |                                                              | PRE ANNUAL SAFETY INSPECTION CHECK Carried out Pre ASI Check                                                                                              | 1159042  |
| 797  | 10/06/2025 | 1294481 |                                                              | Assisting                                                                                                                                                 | 1159042  |
| 797  | 10/06/2025 | 1294561 | BUSH FRONT SWAY BAR SCANIA K230UB 40MM                       |                                                                                                                                                           | 1159042  |
| 797  | 10/06/2025 | 1294561 | Mechanic entered - Suspension Other Front Sway Bar 'D' Bushe | removed worn 'D' Bushes replaced with new items from stock.                                                                                               | 1159042  |
| 797  | 10/06/2025 | 1294561 | Mechanic entered - A/C Heating Other A/C Bracket Cracked in  | grinded along crack welded both cracks made several passes allowed to cool painted area ok.                                                               | 1159042  |
| 797  | 10/06/2025 | 1294561 | Mechanic entered - Engine Other header tank strap bolts loos | secured straps onto header tank. all good.                                                                                                                | 1159042  |
| 797  | 10/06/2025 | 1294561 | Mechanic entered - Elec and Light Next Stop Button 2x Pax be | replaced both pax bells. both working now.                                                                                                                | 1159042  |
| 797  | 10/06/2025 | 1294561 | SWITCH STOP YELLOW (62628)(50V2242) 340085                   |                                                                                                                                                           | 1159042  |
| 797  | 10/06/2025 | 1294561 | SEAT CUSH SINGLE SUPER SLIM CVR - CC                         |                                                                                                                                                           | 1159042  |
| 797  | 10/06/2025 | 1294561 | Consumables                                                  |                                                                                                                                                           | 1159042  |
| 797  | 10/06/2025 | 1294561 | Mechanic entered - Body Passenger Seat Torn n/s seat behind  | removed old seat and replaced with a new one from parts store. seat was found in parts room unsure of where it came from.                                 | 1159042  |
| 797  | 10/06/2025 | 1294561 | SEAT DOUBLE CUSH MET CVR RA                                  |                                                                                                                                                           | 1159042  |
| 797  | 10/06/2025 | 1294561 | Mechanic entered - Body Passenger Seat Torn 2x o/s and 1x ne | replaced all 3 torn seats with new ones from parts room.                                                                                                  | 1159042  |
| 797  | 10/06/2025 | 1294561 | Mechanic entered - Body Other O/S/R Pillar Cracked.          | located crack die grinded area due to limited access welded along crack made several passes allowed to cool painted area ok.                              | 1159042  |
| 797  | 10/06/2025 | 1294561 | Mechanic entered - Body Other Front Desto Cover (inside) Mis | fitted new screws checked for tightness ok.                                                                                                               | 1159042  |
| 797  | 10/06/2025 | 1294561 | Mechanic entered - Body Other Rear Bumper Bar Loose          | adjusted bar location tightened all loose bolts ok.                                                                                                       | 1159042  |
| 797  | 10/06/2025 | 1294561 | Mechanic entered - Body Other Drivers Door Latch Loose - Mis | added screw tightened loose screw ok.                                                                                                                     | 1159042  |
| 797  | 10/06/2025 | 1294549 | Mechanic entered - Brakes Foot_Brakes Leaking Air Rear Brake | removed leaking boosters replaced with new items from stock checked for operation and leaks ok.                                                           | 1159042  |
| 797  | 10/06/2025 | 1294549 | BRAKE CHAMBER REAR 24/30 16MM PORT SCANIA K310 K320 UB       |                                                                                                                                                           | 1159042  |
| 797  | 09/27/2025 | 1292829 |                                                              | CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST caried out fire safe as per check list                                                                 | 1159042  |
| 797  | 09/19/2025 | 1291442 |                                                              | VEHICLE SAFETY INSPECTION                                                                                                                                 | 1159042  |

|     |            |         |                                                              |                                                                                                                                                                                                                                     |  |         |
|-----|------------|---------|--------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|---------|
| 797 | 09/19/2025 | 1291442 |                                                              | TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS                                                                                                                                                                                        |  | 1159042 |
| 797 | 09/19/2025 | 1291534 | Mechanic entered - Steering Other o/s/f draglink hit from ai | repaired o/s/f draglink hit from air hose ok.                                                                                                                                                                                       |  | 1159042 |
| 797 | 09/19/2025 | 1291534 | Mechanic entered - Steering Other Steering wheel play.       | Tightened screw and checked for any more play all ok.                                                                                                                                                                               |  | 1159042 |
| 797 | 09/19/2025 | 1291534 | Mechanic entered - Elec and Light Other both headlight highb | repaired head light highbeam ok.                                                                                                                                                                                                    |  | 1159042 |
| 797 | 09/19/2025 | 1291534 | Mechanic entered - Elec and Light Other o/s/r pax stop switc | repaired o/s/r pax stop switch wires ok.                                                                                                                                                                                            |  | 1159042 |
| 797 | 09/19/2025 | 1291534 | Consumables                                                  |                                                                                                                                                                                                                                     |  | 1159042 |
| 797 | 09/19/2025 | 1291534 | Mechanic entered - Body Other a section of n/s/f wheel arch  | replaced missing section from spare old wheel arch brushes from in the workshop.                                                                                                                                                    |  | 1159042 |
| 797 | 09/19/2025 | 1291534 | Mechanic entered - Body Other n/s/r seat top roll cut.       | repaired n/s/r seat top roll ok.                                                                                                                                                                                                    |  | 1159042 |
| 797 | 09/19/2025 | 1291534 | Mechanic entered - Body Other n/s/middle body panel bolt bro | removed n/s/middle body panel broken bolt and replaced n/s middle body panel bolt ok.                                                                                                                                               |  | 1159042 |
| 797 | 09/19/2025 | 1291534 | Mechanic entered - Body Other o/s and n/s middle seat all lo | repaired o/s and n/s middle all seat ok.                                                                                                                                                                                            |  | 1159042 |
| 797 | 09/02/2025 | 1287726 | Mechanic entered - Body Other O/S/F wheel arch brush loose.  | Refitted wheel arch brush.                                                                                                                                                                                                          |  | 1157227 |
| 797 | 08/28/2025 | 1286247 |                                                              | COMPLETE                                                                                                                                                                                                                            |  | 1157017 |
| 797 | 07/18/2025 | 1277161 | SWITCH SWF 2 POSITION                                        |                                                                                                                                                                                                                                     |  | 1156939 |
| 797 | 07/18/2025 | 1277161 | Mechanic entered - Elec and Light Interior Lights Switch lig | Step light/ driver light flash on/off when switched on. Tested with other switch lights worked. Replaced switch tested ok.                                                                                                          |  | 1156939 |
| 797 | 07/18/2025 | 1277161 | Consumables                                                  |                                                                                                                                                                                                                                     |  | 1156939 |
| 797 | 07/11/2025 | 1275939 |                                                              | CARRY OUT A/C - A SERVICE AS PER CHECK LIST - Done by Cold Drive - Ben - P/O 0391160                                                                                                                                                |  | 1156939 |
| 797 | 07/11/2025 | 1275939 | AIR CONDITIONING REPAIR                                      | Creditor #:-VB-COL004 COLD DRIVE PTY LTD P/O #:-O391160 Receiving #:-415656 Date :2025-07-22 Carry out A service as per check list                                                                                                  |  | 1157017 |
| 797 | 07/07/2025 | 1274897 |                                                              | VEHICLE SAFETY INSPECTION Completed safety inspection as per checklist.                                                                                                                                                             |  | 1156939 |
| 797 | 07/07/2025 | 1274897 |                                                              | TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Tensioned all wheel nuts.                                                                                                                                                              |  | 1156939 |
| 797 | 07/07/2025 | 1274969 | Mechanic entered - Engine Other Engine belt tensioner u/s    | Replaced belt tensioner pulley with new.                                                                                                                                                                                            |  | 1156939 |
| 797 | 07/07/2025 | 1274969 | TENSIONER BELT SCANIA SR4 L94 K230 1859654 1503113 2197002   |                                                                                                                                                                                                                                     |  | 1156939 |
| 797 | 05/29/2025 | 1267179 | Ops Entered - Fault - Body Front_Door Operation Faulty - R   | this defect entered in Keysborough TIMS job was completed at Oakleigh by Satya                                                                                                                                                      |  | 1156939 |
| 797 | 05/29/2025 | 1267179 | Consumables                                                  |                                                                                                                                                                                                                                     |  | 1156939 |
| 797 | 05/29/2025 | 1267179 | Consumables                                                  |                                                                                                                                                                                                                                     |  | 1156939 |
| 797 | 05/26/2025 | 1266525 | Fault#:39620 - Ops Entered - Fault - Breakdown Passenger Do  | Checked and found front door getting stuck while opening adjusted the both door speed and tested several times found working okay . will monitor                                                                                    |  | 1156483 |
| 797 | 05/24/2025 | 1266257 | Elec and Light (None) front doors close and open at times    | replaced sensitive edge sensor at front door and checked ok                                                                                                                                                                         |  | 1156483 |
| 797 | 05/24/2025 | 1266257 | SWITCH SENSITIVE EDGE (RED)                                  |                                                                                                                                                                                                                                     |  | 1156483 |
| 797 | 05/24/2025 | 1266257 | Consumables                                                  |                                                                                                                                                                                                                                     |  | 1156483 |
| 797 | 05/20/2025 | 1265156 | Mechanic entered - Body Front_Door Operation Faulty doors n/ | build up air pressureok.                                                                                                                                                                                                            |  | 1155983 |
| 797 | 05/20/2025 | 1265156 | Consumables                                                  |                                                                                                                                                                                                                                     |  | 1155983 |
| 797 | 05/20/2025 | 1265156 | Consumables                                                  |                                                                                                                                                                                                                                     |  | 1155983 |
| 797 | 05/13/2025 | 1264029 |                                                              | CARRY OUT CCTV - A SERVICE AS PER CHECK LIST complete CCTV A service as per checklist                                                                                                                                               |  | 1155983 |
| 797 | 04/29/2025 | 1261131 | Mechanic entered - Wheels and Tyres Wheel Nut Retention O/S/ | Tensioned O/S/R wheel nut to OEM specs (650nm).                                                                                                                                                                                     |  | 1155983 |
| 797 | 04/29/2025 | 1261131 | Consumables                                                  |                                                                                                                                                                                                                                     |  | 1155983 |
| 797 | 04/15/2025 | 1258974 |                                                              | VEHICLE SAFETY INSPECTION Carried out Safety Inspection as per checklist.                                                                                                                                                           |  | 1155945 |
| 797 | 04/15/2025 | 1258974 |                                                              | TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Tensioned all wheel nuts.                                                                                                                                                              |  | 1155945 |
| 797 | 04/15/2025 | 1258988 | Mechanic entered - Wipers and Washers Other N/S wiper arm wo | Removed and fitted good spare wiper arm.                                                                                                                                                                                            |  | 1155945 |
| 797 | 04/15/2025 | 1258988 | Mechanic entered - Suspension Other O/S/R sway bar link rod  | Removed and fitted new sway bar link rod.                                                                                                                                                                                           |  | 1155945 |
| 797 | 04/15/2025 | 1258988 | LINK RR SWAY BAR DR AXLE SCANIA L94UAB 0488738               |                                                                                                                                                                                                                                     |  | 1155945 |
| 797 | 04/15/2025 | 1258988 | Mechanic entered - Suspension Other O/S/R/R and N/S/R/R airb | Removed and fitted new airbags.                                                                                                                                                                                                     |  | 1155945 |
| 797 | 04/15/2025 | 1258988 | AIRBAG REAR SCANIA K280UB K310 16mm FITTING 6714 NP02        |                                                                                                                                                                                                                                     |  | 1155945 |
| 797 | 04/15/2025 | 1258988 | Mechanic entered - Suspension Other Front sway bar link rods | Removed and fitted new front sway bar link rods.                                                                                                                                                                                    |  | 1155945 |
| 797 | 04/15/2025 | 1258988 | LINK FRT SWAY BAR L94 K360 1766014 0463245 2048601           |                                                                                                                                                                                                                                     |  | 1155945 |
| 797 | 04/15/2025 | 1258988 | Mechanic entered - Engine Other Drive belt idler pulley bear | Removed and fitted new idler pulley.                                                                                                                                                                                                |  | 1155945 |
| 797 | 04/15/2025 | 1258988 | PULLEY IDLER PLASTIC GROOVED SCANIA L94 1514087              |                                                                                                                                                                                                                                     |  | 1155945 |
| 797 | 04/15/2025 | 1258988 | Mechanic entered - Body Other n/s front 2 passenger handle d | removed old handles fitted with new handled                                                                                                                                                                                         |  | 1155945 |
| 797 | 04/15/2025 | 1258988 | HANDLE GRAB PLASTIC PASSENGER GREY SE-GH001(29769)           |                                                                                                                                                                                                                                     |  | 1155945 |
| 797 | 04/15/2025 | 1258988 | Consumables                                                  |                                                                                                                                                                                                                                     |  | 1155945 |
| 797 | 03/18/2025 | 1253051 | AIR CONDITIONING REPAIR                                      | Creditor #:-VB-COL004 COLD DRIVE PTY LTD P/O #:-O383829 Receiving #:-407605 Date :2025-03-28 rectify ac not cooling as required - also degas scrap bus 868. 868 is deactivated in tims . so simon is charging the labour out to 797 |  | 1155945 |
| 797 | 03/18/2025 | 1253051 | >>>RAIL BUS <<< Mechanic entered - A/C Heating Not Cooling   | PO:O383829 - repaired by simon from cold drive                                                                                                                                                                                      |  | 1155945 |
| 797 | 03/18/2025 | 1253051 | Driver Tablet Entered -A/C Heating - Not Cooling             | PO:O383829 - repaired by simon from cold drive                                                                                                                                                                                      |  | 1155945 |
| 797 | 02/27/2025 | 1248900 |                                                              | COMPLETED BY ATS 20-2-25                                                                                                                                                                                                            |  | 1155592 |
| 797 | 02/12/2025 | 1244495 | PERFORM CAMPAIGN 02/25 2025 PTV FARE DECAL REPLACEMENT       | CAMPAIGN DOES NOT APPLY TO RAIL BUSES                                                                                                                                                                                               |  | 1155592 |
| 797 | 02/01/2025 | 1241684 | Service                                                      | checked and confirmed repair complete                                                                                                                                                                                               |  | 1155592 |
| 797 | 02/01/2025 | 1241684 | Consumables                                                  |                                                                                                                                                                                                                                     |  | 1155592 |
| 797 | 01/30/2025 | 1241684 | Bus not starting from front ignition key.                    | diagnosed and found faulty ignition switch as there is no output power from it. replaced switch and tested ok. need to keep monitoring.                                                                                             |  | 1155592 |
| 797 | 01/30/2025 | 1241684 | SWITCH IGNITION SCANIA L94 UAB                               |                                                                                                                                                                                                                                     |  | 1155592 |
| 797 | 01/30/2025 | 1241684 | Consumables                                                  |                                                                                                                                                                                                                                     |  | 1155592 |
| 797 | 01/28/2025 | 1241060 |                                                              | VEHICLE SAFETY INSPECTION Completed safety inspection as per checklist.                                                                                                                                                             |  | 1155592 |
| 797 | 01/28/2025 | 1241060 |                                                              | TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Tensioned all wheel nuts to 650nm.                                                                                                                                                     |  | 1155592 |
| 797 | 01/28/2025 | 1241123 | Mechanic entered - Engine Other Engine idler pulley u/s      | Replaced engine idler pulley with new.                                                                                                                                                                                              |  | 1155592 |
| 797 | 01/28/2025 | 1241123 | PULLEY IDLER SMOOTH PLASTIC SCANIA 1514086 1428940           |                                                                                                                                                                                                                                     |  | 1155592 |
| 797 | 01/28/2025 | 1241123 | Mechanic entered - Body Other 2x interior top panels loose.  | Secured loose panels with screws.                                                                                                                                                                                                   |  | 1155592 |
| 797 | 01/28/2025 | 1241123 | Consumables                                                  |                                                                                                                                                                                                                                     |  | 1155592 |
| 797 | 01/18/2025 | 1239465 | Bus not starting from the front ignition key.                | checked and found hatch switch was not in position and the hatch sitting on the switch when closed. repositioned hatch switch and moved the hatch plate mounting; tested ok                                                         |  | 1155592 |
| 797 | 01/18/2025 | 1239465 | Consumables                                                  |                                                                                                                                                                                                                                     |  | 1155592 |
| 797 | 01/18/2025 | 1239466 | Body (None) driver's door lock not releasing; stuck locke    | removed the lock assy and repaired; re-fitted ok                                                                                                                                                                                    |  | 1155592 |
| 797 | 01/18/2025 | 1239466 | Consumables                                                  |                                                                                                                                                                                                                                     |  | 1155592 |
| 797 | 01/09/2025 | 1237826 | Vandalism Graffiti- GLASS FILM AUDIT # 1143                  | DELETE - WRONGLY ENTERED INTO SYSTEM                                                                                                                                                                                                |  | 1155592 |
| 797 | 12/20/2024 | 1234862 | REMOVE PTV FARE DECALS AS REQUIRED                           | removed                                                                                                                                                                                                                             |  | 1155592 |
| 797 | 11/14/2024 | 1225852 | RSI INSPECTION                                               | Creditor #:-GB-ROA001 ROAD SAFETY INSPECTIONS P/O #:-G375616 Receiving #:-398441 Date :2024-11-15                                                                                                                                   |  | 1154412 |
| 797 | 11/08/2024 | 1226021 | Mechanic entered - Body Other pax. seat plastic end cover mi | replaced.                                                                                                                                                                                                                           |  | 1154412 |
| 797 | 11/08/2024 | 1226021 | CAP CENTRA SEAT END MCCONNELL                                |                                                                                                                                                                                                                                     |  | 1154412 |
| 797 | 11/07/2024 | 1225852 |                                                              | VEHICLE SAFETY INSPECTION                                                                                                                                                                                                           |  | 1154412 |
| 797 | 11/07/2024 | 1225852 |                                                              | TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS                                                                                                                                                                                        |  | 1154412 |
| 797 | 11/07/2024 | 1225852 |                                                              | ANNUAL SAFETY INSPECTION SERIAL #RSI 063468 PASS. 7/11/2024. WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25 RSI completed                                                      |  | 1154412 |
| 797 | 11/06/2024 | 1207283 | Service                                                      | This work order not posted due to date was august. Date change to6/11/2024 for post the work order and it will not effect to VSI because we are doing RSI 7/11/2024 for this bus                                                    |  | 1154412 |
| 797 | 11/06/2024 | 1207283 | Service                                                      | VEHICLE SAFETY INSPECTION completed.                                                                                                                                                                                                |  | 1154412 |
| 797 | 11/06/2024 | 1207283 |                                                              | TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS with Abrahm                                                                                                                                                                            |  | 1154412 |
| 797 | 11/04/2024 | 1225291 | Carry out final inspection fpr RSI                           | completed                                                                                                                                                                                                                           |  | 1154368 |
| 797 | 11/04/2024 | 1225291 | DECAL FIRE EXTINGUISHER DOWN ARROW                           |                                                                                                                                                                                                                                     |  | 1154368 |
| 797 | 10/23/2024 | 1222688 |                                                              | CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST Secured wiring harness around battery with conjure also adjusted door sensitivity. Carry out fire safety inspection as per checklist. Complete                                   |  | 1153997 |
| 797 | 10/18/2024 | 1221222 |                                                              | r/r the shock absorber                                                                                                                                                                                                              |  | 1153997 |
| 797 | 10/17/2024 | 1221222 | SHOCK ABSORBER REAR SCANIA                                   | Creditor #:-GB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:-G374355 Receiving #:-396675 Date :2024-10-17                                                                                                                                  |  | 1153997 |
| 797 | 10/16/2024 | 1221175 |                                                              | PRE ANNUAL SAFETY INSPECTION CHECK Carried pre RSI as per checklist reported / repaired any found defects.                                                                                                                          |  | 1153997 |
| 797 | 10/16/2024 | 1221175 |                                                              | CARRY OUT CCTV - B SERVICE AS PER CHECK LIST CCTV service checks completed by Fed.                                                                                                                                                  |  | 1153997 |
| 797 | 10/16/2024 | 1221222 | Mechanic entered - Suspension Soft N/S/R/R Shock absorber le | ***Parts order form in 8:25AM 16/10/2024***                                                                                                                                                                                         |  | 1153997 |
| 797 | 10/16/2024 | 1221329 | Mechanic entered - Engine Other Steam clean engine / gearbox | Removed floor hatches and steam cleaned engine gearbox and both front and rear axles for RSI. Fit floor hatches back.                                                                                                               |  | 1153997 |
| 797 | 10/16/2024 | 1221231 | Consumables                                                  |                                                                                                                                                                                                                                     |  | 1153997 |
| 797 | 10/16/2024 | 1221269 | Consumables                                                  |                                                                                                                                                                                                                                     |  | 1153997 |
| 797 | 10/16/2024 | 1221273 | Consumables                                                  |                                                                                                                                                                                                                                     |  | 1153997 |
| 797 | 10/16/2024 | 1221281 | Consumables                                                  |                                                                                                                                                                                                                                     |  | 1153997 |
| 797 | 10/16/2024 | 1221231 | Mechanic entered - Elec and Light Electric Mirrors Faulty N/ | passenger side mirror was not working checked for wires and plug tested them all ok.then find faulty switch.re-placed and checke ok.Complete.                                                                                       |  | 1153997 |

|     |            |         |                                                              |                                                                                                                                                                                                                                                                                                                                   |         |
|-----|------------|---------|--------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------|
| 797 | 10/16/2024 | 1221231 | SWITCH MIRROR LH OPTIMUS 5016500                             |                                                                                                                                                                                                                                                                                                                                   | 1153997 |
| 797 | 10/16/2024 | 1221269 | Mechanic entered - Elec and Light Exterior Lights x2 Step li | Assisting Feda with replacing one exterior step light and one interior step light both at the front door.                                                                                                                                                                                                                         | 1153997 |
| 797 | 10/16/2024 | 1221269 |                                                              | Working with Matt replacing step lights. re-placed 1x step light and 1x exterior step light and checked ok.Complete.                                                                                                                                                                                                              | 1153997 |
| 797 | 10/16/2024 | 1221273 | Mechanic entered - Elec and Light Interior Lights x1 Saloon  | Found wire had disconnected from terminal on the light rewired with new terminal and tested light now working good.                                                                                                                                                                                                               | 1153997 |
| 797 | 10/16/2024 | 1221281 | Mechanic entered - Dash Dash_Lights Not Working x3 switch li | Replaced x3 dash switch globes.                                                                                                                                                                                                                                                                                                   | 1153997 |
| 797 | 10/16/2024 | 1221281 |                                                              | re-placed 5x globes for dash then modified the door ok and door alarm signal cover as dont had it.checked all ok.Complete.                                                                                                                                                                                                        | 1153997 |
| 797 | 10/16/2024 | 1221228 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                                   | 1153997 |
| 797 | 10/16/2024 | 1221247 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                                   | 1153997 |
| 797 | 10/16/2024 | 1221279 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                                   | 1153997 |
| 797 | 10/16/2024 | 1221228 | Mechanic entered - Body Other Emergency exit sticker N/S wor | Removed and replaced N/S emergency exit sticker.                                                                                                                                                                                                                                                                                  | 1153997 |
| 797 | 10/16/2024 | 1221228 | DECAL EMERGENCY EXIT ROCK BLACK/WHITE                        |                                                                                                                                                                                                                                                                                                                                   | 1153997 |
| 797 | 10/16/2024 | 1221247 | Mechanic entered - Body Other Wheelchair sticker front missi | Fit new wheelchair sticker to the front of the bus.                                                                                                                                                                                                                                                                               | 1153997 |
| 797 | 10/16/2024 | 1221247 | DECAL DISABLED WHITE ON BLUE S/SIDED 150MM X 150MM           |                                                                                                                                                                                                                                                                                                                                   | 1153997 |
| 797 | 10/16/2024 | 1221279 | Mechanic entered - Body Passenger Seat Torn x2 Torn seat bas | Stitched up two rear seat bases and cleaned up the threads no longer ripped.                                                                                                                                                                                                                                                      | 1153997 |
| 797 | 10/14/2024 | 1220811 | PERFORM CAMPAIGN 11/24 CHECK & ENSURE ALL BUS DRIVE AXLE WH  | Completed                                                                                                                                                                                                                                                                                                                         | 1153997 |
| 797 | 10/02/2024 | 1217851 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                                   | 1153339 |
| 797 | 10/02/2024 | 1217851 | PTI Tablet Entered -Wheels and Tyres - DamagedTyre #6 cracke | check pos 6 tyre. rethred tyre it's not crack juest lift glue layer tyre serviceble                                                                                                                                                                                                                                               | 1153339 |
| 797 | 09/23/2024 | 1215133 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                                   | 1153339 |
| 797 | 09/23/2024 | 1215133 |                                                              | The bus starts up again this morning can not fault it for the moment keep mointering. Complete                                                                                                                                                                                                                                    | 1153339 |
| 797 | 09/18/2024 | 1215133 |                                                              | Bus is starting after few cranks but it won't start sometimes tried to find the issue but everything works normally and the bus starts like normal.                                                                                                                                                                               | 1153339 |
| 797 | 09/18/2024 | 1215133 |                                                              | the bus is still starts normally trying to fault it again it happens only cold starts work is still under progress                                                                                                                                                                                                                | 1153339 |
| 797 | 09/17/2024 | 1215133 | Mechanic entered - Elec and Light Flat Batteries Bus not sta | Stop button at the back was at 0 position we pushed it upwards now the bus starts everytime Job still under progress                                                                                                                                                                                                              | 1153221 |
| 797 | 08/29/2024 | 1210881 |                                                              | COMPLETED BY ATS 20/8/2024                                                                                                                                                                                                                                                                                                        | 1152695 |
| 797 | 08/26/2024 | 1209802 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                                   | 1152598 |
| 797 | 08/26/2024 | 1209802 | Mechanic entered - Elec and Light Other ignition Switch fau  | Repair completed and refr W/O 1207714 15/8/2024                                                                                                                                                                                                                                                                                   | 1152598 |
| 797 | 08/15/2024 | 1207714 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                                   | 1152532 |
| 797 | 08/15/2024 | 1207714 | Workshop Tablet Entered -hard to start turn key hard to tur  | checked for ignition stch and hen checked for starter find not getting signal from there then checked for if have any issue but all ok.then find relay for starter fualty.re-placed and checked ok.Complete.                                                                                                                      | 1152532 |
| 797 | 08/15/2024 | 1207714 | RELAY CHANGE OVER 24V 40AMP 5PIN OPEN E50-0005               |                                                                                                                                                                                                                                                                                                                                   | 1152532 |
| 797 | 08/15/2024 | 1207714 |                                                              | The bus was not cranking due to no signal/trigger to starter motor armature found relay for starter cut off faulty replaced with new one problem resolved. complete                                                                                                                                                               | 1152532 |
| 797 | 08/13/2024 | 1207284 |                                                              | completed safety inspection as per check list and tensioned the wheel nuts with Abraham                                                                                                                                                                                                                                           | 1152270 |
| 797 | 08/13/2024 | 1207284 |                                                              | VEHICLE SAFETY INSPECTION Assisted Guri.                                                                                                                                                                                                                                                                                          | 1152270 |
| 797 | 08/13/2024 | 1207284 |                                                              | TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS                                                                                                                                                                                                                                                                                      | 1152270 |
| 797 | 08/07/2024 | 1205842 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                                   | 1152213 |
| 797 | 08/07/2024 | 1205842 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                                   | 1152213 |
| 797 | 08/07/2024 | 1205842 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                                   | 1152213 |
| 797 | 08/07/2024 | 1205842 | OIL ENGINE ALL FLEET PLUS E900 15W-40                        |                                                                                                                                                                                                                                                                                                                                   | 1152213 |
| 797 | 08/07/2024 | 1205842 | OIL ATF STEERING DEX-3 VALVOLINE                             |                                                                                                                                                                                                                                                                                                                                   | 1152213 |
| 797 | 08/07/2024 | 1205842 | FILTER FUEL SCANIA VARIOUS MODELS H17WK04                    |                                                                                                                                                                                                                                                                                                                                   | 1152213 |
| 797 | 08/07/2024 | 1205842 | FILTER ZF ECOMAT GEARBOX 4139-298-038 3098081                |                                                                                                                                                                                                                                                                                                                                   | 1152213 |
| 797 | 08/07/2024 | 1205842 | OIL SAMPLE TEST KIT                                          |                                                                                                                                                                                                                                                                                                                                   | 1152213 |
| 797 | 08/07/2024 | 1205842 | FILTER OIL SCANIA VARIOUS MODELS                             |                                                                                                                                                                                                                                                                                                                                   | 1152213 |
| 797 | 08/07/2024 | 1205842 | PAPER SPINNER FILTER OIL INSERT SCANIA VARIOUS MODELS        |                                                                                                                                                                                                                                                                                                                                   | 1152213 |
| 797 | 08/07/2024 | 1205842 | O-RING LARGE UPPER SPINNER FILTER SCANIA                     |                                                                                                                                                                                                                                                                                                                                   | 1152213 |
| 797 | 08/07/2024 | 1205842 | O-RING LOWER SPINNER FILTER SCANIA L94 K124                  |                                                                                                                                                                                                                                                                                                                                   | 1152213 |
| 797 | 08/07/2024 | 1205842 |                                                              | CARRY OUT B SERVICE AS PER CHECK LIST completed as per check list and tensioned the wheel nuts with Satheesh.                                                                                                                                                                                                                     | 1152213 |
| 797 | 08/05/2024 | 1205370 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                                   | 1152085 |
| 797 | 08/05/2024 | 1205370 | Workshop Tablet Entered -Elec and Light - Flat Batteriesbus  | checked the relays change one and adjust the engine hach safety swich. starting now                                                                                                                                                                                                                                               | 1152085 |
| 797 | 08/05/2024 | 1205370 | 24V 20/10 HOIST RELAY BRAUN UVL                              |                                                                                                                                                                                                                                                                                                                                   | 1152085 |
| 797 | 08/05/2024 | 1205370 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                                   | 1152085 |
| 797 | 08/05/2024 | 1205370 | Driver Tablet Entered -Body - Front_Door Operation Faultyno  | checked the door operation open ang close lot of time but operating good                                                                                                                                                                                                                                                          | 1152085 |
| 797 | 07/31/2024 | 1204535 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                                   | 1151635 |
| 797 | 07/31/2024 | 1204535 | Workshop Tablet Entered -Elec and Light - Warning Light On D | Checked no warning light on dash.                                                                                                                                                                                                                                                                                                 | 1151635 |
| 797 | 07/25/2024 | 1203214 | PERFORM CAMPAIGN 08/24 CHECK AND REPLACE WHERE REQUIRED ACCR | checked - o.k.                                                                                                                                                                                                                                                                                                                    | 1151472 |
| 797 | 06/29/2024 | 1197349 | BATTERY EXSN94SCMF 1350AAC EMFN150L                          |                                                                                                                                                                                                                                                                                                                                   | 1151225 |
| 797 | 06/29/2024 | 1197349 | Elec and Light battery need to replace                       | After fully charged the battery load testeed and battery life is under 50% and battery also old more than 3.5 years old. Replaced battery                                                                                                                                                                                         | 1151225 |
| 797 | 06/29/2024 | 1197349 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                                   | 1151225 |
| 797 | 06/21/2024 | 1195823 | Fault#:39228 - Ops Entered - Fault - Breakdown Not Starting  | Bus B/D front of dandenong chisholm flat battery and starter motor stuck connect the jumper pack and tap the moter bus started . left from W/S 1025 back 12pm used B/d Van.                                                                                                                                                       | 1151225 |
| 797 | 06/04/2024 | 1192463 | Mechanic entered - Elec and Light Flat Batteries             | jump started.                                                                                                                                                                                                                                                                                                                     | 1150627 |
| 797 | 06/04/2024 | 1192463 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                                   | 1150627 |
| 797 | 06/03/2024 | 1190145 |                                                              |                                                                                                                                                                                                                                                                                                                                   | 1150627 |
| 797 | 06/03/2024 | 1190145 |                                                              | Replaced all condenser fan assembly run up tested ok                                                                                                                                                                                                                                                                              | 1150627 |
| 797 | 05/31/2024 | 1190145 | 16-290075-00 condenser fan                                   | Creditor #:GB-22C001 22 CELSIUS P/O #:G365546 Receiving #:387379 Date :2024-06-03                                                                                                                                                                                                                                                 | 1150627 |
| 797 | 05/28/2024 | 1190145 |                                                              | Replaced all evaporator fan motors removed condenser lid found EM3643 motors will not fit parts ordered                                                                                                                                                                                                                           | 1150469 |
| 797 | 05/24/2024 | 1190145 | fan motor as per bruces reques                               | Creditor #:GB-22C001 22 CELSIUS P/O #:G365248 Receiving #:386690 Date :2024-05-24                                                                                                                                                                                                                                                 | 1150397 |
| 797 | 05/23/2024 | 1190145 | Mechanic entered - A/C Heating Not Cooling All condenser and | Replace all evaporator fan motors will need to replace all condenser fan motors TK fans wont suit the mount set up                                                                                                                                                                                                                | 1150338 |
| 797 | 05/22/2024 | 1189891 |                                                              | CARRY OUT A/C - B SERVICE AS PER CHECK LIST Service as per list no drier in stock will replace oil and drier next service                                                                                                                                                                                                         | 1150338 |
| 797 | 05/22/2024 | 1189891 |                                                              | CARRY OUT A/C - A SERVICE AS PER CHECK LIST Service as per list                                                                                                                                                                                                                                                                   | 1150338 |
| 797 | 05/20/2024 | 1189310 |                                                              | VEHICLE SAFETY INSPECTION completed as per check list.                                                                                                                                                                                                                                                                            | 1150151 |
| 797 | 05/20/2024 | 1189310 |                                                              | TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS done with Zubair                                                                                                                                                                                                                                                                     | 1150151 |
| 797 | 05/20/2024 | 1189316 |                                                              | CARRY OUT CCTV - A SERVICE AS PER CHECK LIST complate CCTV A service as per checklist                                                                                                                                                                                                                                             | 1150151 |
| 797 | 05/14/2024 | 1188136 | FILTER AIR DRY MAN A91 MERC 0500LE OH1830 3090288            |                                                                                                                                                                                                                                                                                                                                   | 1149895 |
| 797 | 05/14/2024 | 1188136 | SILENCER AIR DRYER MERC BENZ 0500LE                          |                                                                                                                                                                                                                                                                                                                                   | 1149895 |
| 797 | 05/14/2024 | 1188136 |                                                              | Assisted Matt                                                                                                                                                                                                                                                                                                                     | 1149895 |
| 797 | 05/14/2024 | 1188136 | Mechanic entered - Brakes Warning Light On Park brake light  | Found the park brake light staying on for to long brakes would release like normal just light would be on a little to long. Dooly reckons air not building up quick enough checked history of the bus has not had an air dryer replaced since early 2021 removed and replaced air dryer as next due service for it was 45000km aw | 1149895 |
| 797 | 05/01/2024 | 1185433 | Body_Door Operation Faulty                                   | check and fixed passanger door power line to switch and adjusted door senseitive edges.doors ok                                                                                                                                                                                                                                   | 1149253 |
| 797 | 05/01/2024 | 1185433 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                                   | 1149253 |
| 797 | 04/30/2024 | 1185183 | Mechanic entered - Elec and Light Flat Batteries             | jump started.                                                                                                                                                                                                                                                                                                                     | 1149253 |
| 797 | 04/30/2024 | 1185183 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                                   | 1149253 |
| 797 | 03/23/2024 | 1178323 | Mechanic entered - Engine Will Not Start in Neutral hard to  | fully close engine hatch.                                                                                                                                                                                                                                                                                                         | 1149253 |
| 797 | 02/29/2024 | 1173500 | PERFORM CAMPAIGN 01/24 REMOVAL OF OLD NO SMOKING DECALS      | completed                                                                                                                                                                                                                                                                                                                         | 1148896 |
| 797 | 02/28/2024 | 1172938 |                                                              | COMPLETED BY ATS                                                                                                                                                                                                                                                                                                                  | 1148896 |
| 797 | 02/27/2024 | 1172396 | GLASS WINDSCREEN CR228L                                      | Creditor #:GB-OBRO10 O'BRIENS GLASS INDUSTRIES P/O #:G360175 Receiving #:380419 Date :2024-02-27                                                                                                                                                                                                                                  | 1148896 |
| 797 | 02/26/2024 | 1172396 | *** PHOTOS TAKEN BY RANJITH ***Accident #56540 FRONT         | Replaced windscreen by O briens                                                                                                                                                                                                                                                                                                   | 1148633 |
| 797 | 02/26/2024 | 1172396 | *** PHOTOS TAKEN BY RANJITH ***Accident #56540 FRONT         | Assisting                                                                                                                                                                                                                                                                                                                         | 1148633 |
| 797 | 02/24/2024 | 1172118 |                                                              | VEHICLE SAFETY INSPECTION carried out safety inspection as per check list and tensioned all wheel nuts with feda/.                                                                                                                                                                                                                | 1148633 |
| 797 | 02/24/2024 | 1172118 |                                                              | TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS                                                                                                                                                                                                                                                                                      | 1148633 |
| 797 | 02/24/2024 | 1172139 | Mechanic entered - Body Other wiper damaged due to crash     | carried out removing and replacing with new wiper arm and wiper blade.                                                                                                                                                                                                                                                            | 1148633 |
| 797 | 02/24/2024 | 1172139 | WIPER ARM OSF M12x16MM SPLINE CUSTOM VOLVO B12BLE            |                                                                                                                                                                                                                                                                                                                                   | 1148633 |
| 797 | 02/24/2024 | 1172139 | WIPER BLADE ASSY 1000MM N102BOSCH                            |                                                                                                                                                                                                                                                                                                                                   | 1148633 |
| 797 | 02/24/2024 | 1172139 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                                   | 1148633 |
| 797 | 01/04/2024 | 1161292 | PERFORM CAMPAIGN 10/23 POSITIONING OF 2024 PTV FARES         | Rail Bus                                                                                                                                                                                                                                                                                                                          | 1148196 |
| 797 | 12/04/2023 | 1155383 | DIRECT PURCHASE - BUS INSPECTI                               | Creditor #:GB-ROA001 ROAD SAFETY INSPECTIONS P/O #:G355443 Receiving #:374911 Date :2023-12-05                                                                                                                                                                                                                                    | 1148196 |
| 797 | 12/01/2023 | 1155383 |                                                              | VEHICLE SAFETY INSPECTION completed                                                                                                                                                                                                                                                                                               | 1148196 |

|     |            |         |                                                                                                                                                                                                                                                                                                                                      |         |
|-----|------------|---------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------|
| 797 | 12/01/2023 | 1155383 | TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS                                                                                                                                                                                                                                                                                         | 1148196 |
| 797 | 12/01/2023 | 1155383 | ANNUAL SAFETY INSPECTION SERIAL #RSI 0508686 PASS 01/12/23 WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25                                                                                                                                                                       | 1148196 |
| 797 | 12/01/2023 | 1155383 | Assisting                                                                                                                                                                                                                                                                                                                            | 1148196 |
| 797 | 11/29/2023 | 1154994 |                                                                                                                                                                                                                                                                                                                                      | 1148196 |
| 797 | 11/29/2023 | 1154994 |                                                                                                                                                                                                                                                                                                                                      | 1148196 |
| 797 | 11/29/2023 | 1154994 | completed                                                                                                                                                                                                                                                                                                                            | 1148196 |
| 797 | 11/29/2023 | 1154994 |                                                                                                                                                                                                                                                                                                                                      | 1148196 |
| 797 | 11/29/2023 | 1154994 |                                                                                                                                                                                                                                                                                                                                      | 1148196 |
| 797 | 11/29/2023 | 1154994 | Carry out final inspection for RSI                                                                                                                                                                                                                                                                                                   | 1148196 |
| 797 | 11/29/2023 | 1154994 | Consumables                                                                                                                                                                                                                                                                                                                          | 1148196 |
| 797 | 11/17/2023 | 1152884 | Mechanic entered - Wipers and Washers Other n/s washer jet n                                                                                                                                                                                                                                                                         | 1148196 |
| 797 | 11/17/2023 | 1152890 | Mechanic entered - Engine Other needs to steam clean the eng                                                                                                                                                                                                                                                                         | 1148196 |
| 797 | 11/17/2023 | 1152882 | Mechanic entered - Body Other behind drivers seat panel need                                                                                                                                                                                                                                                                         | 1148196 |
| 797 | 11/17/2023 | 1152883 | Mechanic entered - Body Windows Front screen got small chip                                                                                                                                                                                                                                                                          | 1148196 |
| 797 | 11/17/2023 | 1152885 | Mechanic entered - Body Other rear door rattling need to fix                                                                                                                                                                                                                                                                         | 1148196 |
| 797 | 11/17/2023 | 1152886 | Mechanic entered - Body Other o/s middle passanger seat base                                                                                                                                                                                                                                                                         | 1148196 |
| 797 | 11/17/2023 | 1152882 | Consumables                                                                                                                                                                                                                                                                                                                          | 1148196 |
| 797 | 11/17/2023 | 1152883 | Consumables                                                                                                                                                                                                                                                                                                                          | 1148196 |
| 797 | 11/17/2023 | 1152885 | Consumables                                                                                                                                                                                                                                                                                                                          | 1148196 |
| 797 | 11/17/2023 | 1152886 | Consumables                                                                                                                                                                                                                                                                                                                          | 1148196 |
| 797 | 11/16/2023 | 1152502 |                                                                                                                                                                                                                                                                                                                                      | 1148196 |
| 797 | 11/16/2023 | 1152502 | PRE ANNUAL SAFETY INSPECTION CHECK Re-tensioned wheel nuts with guri.                                                                                                                                                                                                                                                                | 1148196 |
| 797 | 11/16/2023 | 1152502 | CARRY OUT CCTV - B SERVICE AS PER CHECK LIST                                                                                                                                                                                                                                                                                         | 1148196 |
| 797 | 11/16/2023 | 1152502 | . carried out Pre annual safety inspecion CCTV - B service as per check list and tensioned wheel nut s with Satheesh.                                                                                                                                                                                                                | 1148196 |
| 797 | 11/16/2023 | 1152579 |                                                                                                                                                                                                                                                                                                                                      | 1148196 |
| 797 | 11/16/2023 | 1152579 | fitted new both front mud flap                                                                                                                                                                                                                                                                                                       | 1148196 |
| 797 | 11/16/2023 | 1152579 |                                                                                                                                                                                                                                                                                                                                      | 1148196 |
| 797 | 11/06/2023 | 1150846 | VEHICLE SAFETY INSPECTION Completed safety service.                                                                                                                                                                                                                                                                                  | 1148196 |
| 797 | 11/06/2023 | 1150846 | TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS                                                                                                                                                                                                                                                                                         | 1148196 |
| 797 | 11/06/2023 | 1150849 |                                                                                                                                                                                                                                                                                                                                      | 1148196 |
| 797 | 11/06/2023 | 1150849 | Rplaced a wheel arch brush for O/S/F.                                                                                                                                                                                                                                                                                                | 1148196 |
| 797 | 11/06/2023 | 1150849 |                                                                                                                                                                                                                                                                                                                                      | 1148196 |
| 797 | 11/06/2023 | 1150849 |                                                                                                                                                                                                                                                                                                                                      | 1148196 |
| 797 | 10/26/2023 | 1148865 | CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST assist Lochi to Complete fire safety inspection as per check list. Complete.                                                                                                                                                                                                      | 1148196 |
| 797 | 10/26/2023 | 1148865 | complete fire safety inspection as per check list                                                                                                                                                                                                                                                                                    | 1148196 |
| 797 | 09/16/2023 | 1140807 |                                                                                                                                                                                                                                                                                                                                      | 1148196 |
| 797 | 09/16/2023 | 1140807 | remove and replace panel cut and polish n/s                                                                                                                                                                                                                                                                                          | 1148196 |
| 797 | 09/15/2023 | 1140807 | prep and paint 1 panel                                                                                                                                                                                                                                                                                                               | 1148196 |
| 797 | 09/15/2023 | 1140807 |                                                                                                                                                                                                                                                                                                                                      | 1148196 |
| 797 | 09/15/2023 | 1140807 | fabricated prefit and painted 1 panel white/black                                                                                                                                                                                                                                                                                    | 1148196 |
| 797 | 09/15/2023 | 1140807 |                                                                                                                                                                                                                                                                                                                                      | 1148196 |
| 797 | 09/15/2023 | 1140807 | fabricate panel and prefit. (offcut)                                                                                                                                                                                                                                                                                                 | 1148014 |
| 797 | 09/14/2023 | 1140807 | CARRY OUT FIRE EXTINGUISHER TEST & TAG Completed                                                                                                                                                                                                                                                                                     | 1148014 |
| 797 | 08/18/2023 | 1136445 | CARRY OUT FIRE EXTINGUISHER TEST & TAG Completed by ATS                                                                                                                                                                                                                                                                              | 1148014 |
| 797 | 08/18/2023 | 1138634 | Assisting                                                                                                                                                                                                                                                                                                                            | 1148014 |
| 797 | 08/18/2023 | 1138634 | Done by Refuelers                                                                                                                                                                                                                                                                                                                    | 1148014 |
| 797 | 08/17/2023 | 1134148 | VEHICLE SAFETY INSPECTION                                                                                                                                                                                                                                                                                                            | 1148014 |
| 797 | 08/16/2023 | 1133671 | TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS                                                                                                                                                                                                                                                                                         | 1148014 |
| 797 | 08/16/2023 | 1133671 | completed safety inspection as per check list with neven                                                                                                                                                                                                                                                                             | 1148014 |
| 797 | 08/16/2023 | 1133740 |                                                                                                                                                                                                                                                                                                                                      | 1148014 |
| 797 | 08/16/2023 | 1133740 | Consumables                                                                                                                                                                                                                                                                                                                          | 1148014 |
| 797 | 08/16/2023 | 1133740 | Mechanic entered - Body Other missing please hold on decal o                                                                                                                                                                                                                                                                         | 1148014 |
| 797 | 08/16/2023 | 1133740 | DECAL PLEASE HOLD ON BLACK ON YELLOW                                                                                                                                                                                                                                                                                                 | 1148014 |
| 797 | 07/24/2023 | 1128621 | PERFORM CAMPAIGN 02/23 POSITIONING OF 2023 PTV FARES                                                                                                                                                                                                                                                                                 | 1147722 |
| 797 | 07/20/2023 | 1128028 | Drv entered - Body Front_Door Operation Faulty                                                                                                                                                                                                                                                                                       | 1147722 |
| 797 | 07/20/2023 | 1128028 | Consumables                                                                                                                                                                                                                                                                                                                          | 1147722 |
| 797 | 07/10/2023 | 1125367 |                                                                                                                                                                                                                                                                                                                                      | 1147722 |
| 797 | 06/22/2023 | 1121987 | CARRY OUT A/C - A SERVICE AS PER CHECK LIST Service as per list                                                                                                                                                                                                                                                                      | 1147578 |
| 797 | 06/22/2023 | 1121987 | Replaced globe.                                                                                                                                                                                                                                                                                                                      | 1147578 |
| 797 | 06/22/2023 | 1121987 |                                                                                                                                                                                                                                                                                                                                      | 1147578 |
| 797 | 05/30/2023 | 1117609 |                                                                                                                                                                                                                                                                                                                                      | 1146023 |
| 797 | 05/30/2023 | 1117609 | CARRY OUT CCTV - A SERVICE AS PER CHECK LIST complete cctv service as per check list                                                                                                                                                                                                                                                 | 1146023 |
| 797 | 05/26/2023 | 1116934 | Service Complete as per Check list.                                                                                                                                                                                                                                                                                                  | 1146023 |
| 797 | 05/24/2023 | 1116644 | Incorrect bus number entered                                                                                                                                                                                                                                                                                                         | 1145828 |
| 797 | 05/24/2023 | 1116644 | Assisted Abraham.                                                                                                                                                                                                                                                                                                                    | 1145828 |
| 797 | 05/24/2023 | 1116644 | Tensioned wheel nuts w/ Haysun pos.12.                                                                                                                                                                                                                                                                                               | 1145828 |
| 797 | 05/23/2023 | 1116384 | VEHICLE SAFETY INSPECTION Completed VSI.                                                                                                                                                                                                                                                                                             | 1145828 |
| 797 | 05/23/2023 | 1116384 | Tensioned wheel nutrs w/ Nick.                                                                                                                                                                                                                                                                                                       | 1145828 |
| 797 | 05/23/2023 | 1116384 |                                                                                                                                                                                                                                                                                                                                      | 1145828 |
| 797 | 05/23/2023 | 1116389 | Fitted new orig tyres pos.12 and tensioned wheel nuts w/ Nick.                                                                                                                                                                                                                                                                       | 1145828 |
| 797 | 05/23/2023 | 1116389 |                                                                                                                                                                                                                                                                                                                                      | 1145828 |
| 797 | 05/23/2023 | 1116389 |                                                                                                                                                                                                                                                                                                                                      | 1145828 |
| 797 | 05/23/2023 | 1116389 | Assisted Abraham.                                                                                                                                                                                                                                                                                                                    | 1145828 |
| 797 | 03/29/2023 | 1106287 |                                                                                                                                                                                                                                                                                                                                      | 1145008 |
| 797 | 03/29/2023 | 1106287 | assist feda with start issue                                                                                                                                                                                                                                                                                                         | 1145008 |
| 797 | 03/29/2023 | 1106287 | checked and tried to start bus from engine bay was starting and when tried to start from dash switch not starting checked for fuses and find out engine bay safety switch is not switching when pannel is closed. put some double sided tape still did not worki ok. adjusted the screw and pressed the sit it ok and started workin | 1145008 |
| 797 | 03/02/2023 | 1100383 |                                                                                                                                                                                                                                                                                                                                      | 1142777 |
| 797 | 03/02/2023 | 1100383 | RETORQUE ALL WHEELNUTS TO SPEC                                                                                                                                                                                                                                                                                                       | 1142777 |
| 797 | 03/02/2023 | 1100383 | Assisting                                                                                                                                                                                                                                                                                                                            | 1142777 |
| 797 | 03/02/2023 | 1100383 | RETORQUE ALL WHEELNUTS TO SPEC                                                                                                                                                                                                                                                                                                       | 1142777 |
| 797 | 02/28/2023 | 1099772 | TRANSMISSION CHECK AS PER CHECK LIST                                                                                                                                                                                                                                                                                                 | 1142514 |
| 797 | 02/28/2023 | 1099772 | TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS                                                                                                                                                                                                                                                                                         | 1142514 |
| 797 | 02/28/2023 | 1099772 | VEHICLE SAFETY INSPECTION                                                                                                                                                                                                                                                                                                            | 1142514 |
| 797 | 02/28/2023 | 1099911 |                                                                                                                                                                                                                                                                                                                                      | 1142514 |
| 797 | 02/28/2023 | 1099911 |                                                                                                                                                                                                                                                                                                                                      | 1142514 |
| 797 | 02/28/2023 | 1099911 | REPlace n/s/r tyres                                                                                                                                                                                                                                                                                                                  | 1142514 |
| 797 | 02/28/2023 | 1099812 |                                                                                                                                                                                                                                                                                                                                      | 1142514 |
| 797 | 02/28/2023 | 1099812 |                                                                                                                                                                                                                                                                                                                                      | 1142514 |
| 797 | 02/28/2023 | 1099812 | Replace drive front airbags and steer air bags                                                                                                                                                                                                                                                                                       | 1142514 |
| 797 | 02/28/2023 | 1099781 | Replace idler and tensioner                                                                                                                                                                                                                                                                                                          | 1142514 |
| 797 | 02/28/2023 | 1099781 |                                                                                                                                                                                                                                                                                                                                      | 1142514 |
| 797 | 02/28/2023 | 1099781 |                                                                                                                                                                                                                                                                                                                                      | 1142514 |
| 797 | 02/28/2023 | 1099781 |                                                                                                                                                                                                                                                                                                                                      | 1142514 |
| 797 | 02/27/2023 | 1099553 | Completed by ATS 17.02.2023                                                                                                                                                                                                                                                                                                          | 1142514 |
| 797 | 02/22/2023 | 1098414 | reset desto                                                                                                                                                                                                                                                                                                                          | 1141814 |
| 797 | 02/03/2023 | 1094463 |                                                                                                                                                                                                                                                                                                                                      | 1139469 |
| 797 | 02/03/2023 | 1094463 | Wheels and Tyres (None)O/S/F tyre - wheel arch brush fal                                                                                                                                                                                                                                                                             | 1139469 |
| 797 | 02/03/2023 | 1094126 | Anti Graffiti Film                                                                                                                                                                                                                                                                                                                   | 1139975 |
| 797 | 02/01/2023 | 1094126 | Anti Graffiti Film -                                                                                                                                                                                                                                                                                                                 | 1139299 |

|     |            |         |                                                                   |                                                                                                                                                  |           |
|-----|------------|---------|-------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------|-----------|
| 797 | 01/23/2023 | 1092381 | Workshop Tablet Entered - Elec and Light - Indicators Not Working | Could not fault at time of test                                                                                                                  | 1138251   |
| 797 | 01/18/2023 | 1091798 | Consumables                                                       |                                                                                                                                                  | 1137959   |
| 797 | 01/18/2023 | 1091798 | Workshop Tablet Entered -Body - Mirrors Exterior Passenger        | repaired wiring in n/s mirror                                                                                                                    | 1137959   |
| 797 | 01/11/2023 | 1090344 | Elec and Light Desto Fault The Desto sign outside is fault        | Reset desto sign and check ok                                                                                                                    | 1137295   |
| 797 | 12/08/2022 | 1084929 | DIRECT PURCHASE - BUS INSPECTI                                    | Creditor #:VB-ROA002 ROAD SAFETY INSPECTIONS P/O #:CR333779 Receiving #:351942 Date :2022-12-23                                                  | 1135981   |
| 797 | 12/06/2022 | 1084929 |                                                                   | VEHICLE SAFETY INSPECTION                                                                                                                        | 1133991   |
| 797 | 12/06/2022 | 1084929 |                                                                   | TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS                                                                                                     | 1133991   |
| 797 | 12/06/2022 | 1084929 |                                                                   | ANNUAL SAFETY INSPECTION SERIAL #_RSI 052579 WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25 | 1133991   |
| 797 | 12/06/2022 | 1084929 |                                                                   | Assisting                                                                                                                                        | 1133991   |
| 797 | 11/16/2022 | 1081271 |                                                                   | PRE ANNUAL SAFETY INSPECTION CHECK                                                                                                               | 1131941   |
| 797 | 11/16/2022 | 1081271 |                                                                   | CARRY OUT CCTV - B SERVICE AS PER CHECK LIST                                                                                                     | 1131941   |
| 797 | 11/16/2022 | 1081271 | Consumables                                                       |                                                                                                                                                  | 1131941   |
| 797 | 11/16/2022 | 1081271 | Consumables                                                       |                                                                                                                                                  | 1131941   |
| 797 | 11/16/2022 | 1081271 | Consumables                                                       |                                                                                                                                                  | 1131941   |
| 797 | 11/16/2022 | 1081271 |                                                                   | CARRY OUT B SERVICE AS PER CHECK LIST                                                                                                            | 1131941   |
| 797 | 11/16/2022 | 1081271 | O-RING LARGE SPINNER FILTER SCANIA L94 & K230                     |                                                                                                                                                  | 1131941   |
| 797 | 11/16/2022 | 1081271 | O-RING SPINNER FILTER SCANIA L94                                  |                                                                                                                                                  | 1131941   |
| 797 | 11/16/2022 | 1081271 | FILTER OIL SCANIA K93 L94 1117285 2059778                         |                                                                                                                                                  | 1131941   |
| 797 | 11/16/2022 | 1081271 | FILTER ZF ECOMAT GEARBOX 4139-298-038 1193281                     |                                                                                                                                                  | 1131941   |
| 797 | 11/16/2022 | 1081271 | KIT OIL SAMPLE AMPOL                                              |                                                                                                                                                  | 1131941   |
| 797 | 11/16/2022 | 1081271 | FILTER FUEL SCANIA L94(1372444)                                   |                                                                                                                                                  | 1131941   |
| 797 | 11/16/2022 | 1081271 | PAPER SPINNER FILTER OIL INSERT SCANIA L94                        |                                                                                                                                                  | 1131941   |
| 797 | 11/16/2022 | 1081271 | Consumables                                                       |                                                                                                                                                  | 1131941   |
| 797 | 11/16/2022 | 1081271 | Consumables                                                       |                                                                                                                                                  | 1131941   |
| 797 | 11/16/2022 | 1081271 | Consumables                                                       |                                                                                                                                                  | 1131941   |
| 797 | 11/14/2022 | 1080671 | Consumables                                                       |                                                                                                                                                  | 1131671   |
| 797 | 11/14/2022 | 1080671 | Wheels and Tyres Wheel Nut RetensionPlease check whee             | RETORQUE OSR WHEELNUTS AND FIT WHEEL NUT POINTERS                                                                                                | 1131671   |
| 797 | 11/14/2022 | 1080671 | Wheels and Tyres Wheel Nut RetensionPlease check whee             | Assisting                                                                                                                                        | 1131671   |
| 797 | 11/14/2022 | 1080671 | Consumables                                                       |                                                                                                                                                  | 1131671   |
| 797 | 11/03/2022 | 1077883 | DIRECT PURCHASE - BRAKES                                          | Creditor #:VB-BUR001 BURSON AUTOMOTIVE PTY LTD P/O #:CR331490RET Receiving #:348686 Date :2022-11-04 bearings as per sample                      | 1130776   |
| 797 | 11/03/2022 | 1078946 | CCTV CCTV not recordingRT 24/10/22: Hard Drive not con            | replaced HDD due to hard drive being replaced before service handed old HDD to Chris incase footage is needed in the future                      | 1130664   |
| 797 | 11/03/2022 | 1078946 | HARD DRIVE HDD 1TB CCTV                                           |                                                                                                                                                  | 1130664   |
| 797 | 11/03/2022 | 1078947 |                                                                   | CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST completed FSI secured wiring under bus and covered exposed fuse block in hatch o/s            | 1130664   |
| 797 | 10/27/2022 | 1077883 | DECAL EMERGENCY EXIT (HAMMER)                                     |                                                                                                                                                  | 1129895   |
| 797 | 10/27/2022 | 1077883 |                                                                   | VEHICLE SAFETY INSPECTION                                                                                                                        | 1129895   |
| 797 | 10/27/2022 | 1077883 |                                                                   | TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS                                                                                                     | 1129895   |
| 797 | 10/27/2022 | 1077883 | CATCH DRIVERS WINDOW                                              |                                                                                                                                                  | 1129895   |
| 797 | 10/27/2022 | 1077961 | Elec and Light Horn                                               | REMOVE AND REPLACE HORN ASSEMBLY                                                                                                                 | 1129895   |
| 797 | 10/27/2022 | 1077961 | HORN 24V 112MM                                                    |                                                                                                                                                  | 1129895   |
| 797 | 10/27/2022 | 1077961 | Consumables                                                       |                                                                                                                                                  | 1129895   |
| 797 | 10/27/2022 | 1077883 | Body (None)- internal panel fallen down                           | SECURE PANEL                                                                                                                                     | 1129895   |
| 797 | 10/27/2022 | 1077883 | DIRECT PURCHASE - BRAKES                                          | Creditor #:VB-BEA001 BEARING WHOLESALERS P/O #:CR331490 Receiving #:348314 Date :2022-10-28 Supply wheel bearings as per sample                  | 1130154   |
| 797 | 10/27/2022 | 1077883 | Consumables                                                       |                                                                                                                                                  | 1130154   |
| 797 | 10/26/2022 | 1077752 | Drv entered - Elec and Light Interior Lights                      | refit rear lights and light covers - OK                                                                                                          | 1129895   |
| 797 | 10/26/2022 | 1077752 | Consumables                                                       |                                                                                                                                                  | 1129895   |
| 797 | 10/15/2022 | 1075589 | PERFORM CAMPAIGN 10/22 WEAR A FACE MASK WHILE TRAVELLING          | Carried out campaign 10/22                                                                                                                       | 1128488   |
| 797 | 09/30/2022 | 1072213 | Workshop Tablet Entered -Body - Mirrors Exterior Electrics        | checked found wiring damaged repaired wire checked tested ok                                                                                     | 1126769   |
| 797 | 09/30/2022 | 1072213 | Consumables                                                       |                                                                                                                                                  | 1126769   |
| 797 | 09/09/2022 | 1068529 | Mechanic entered - A/C Heating Belt Loose or_Missing A/c bel      | Replace a/c belts                                                                                                                                | 1124750   |
| 797 | 09/08/2022 | 1068529 | Mechanic entered - A/C Heating Belt Loose or_Missing A/c bel      |                                                                                                                                                  | 1124750   |
| 797 | 09/08/2022 | 1068529 | BELT V HI-POWER 17x2235mm VOLV                                    | Creditor #:VB-MUL002 MULTISPARES CROYDON P/O #:CR328681 Receiving #:345282 Date :2022-09-09                                                      | 1124800   |
| 797 | 09/08/2022 | 1068528 | Mechanic entered - Fluid Leaks Rear of bus                        | Drian coolant remove split hose from trans cooler and replace. Refill with coolant                                                               | 1124750   |
| 797 | 09/08/2022 | 1068528 | HOSE G/BOX COOLING 160 DEG 1 7/8 X 2 1/4 1451072 461674           |                                                                                                                                                  | 1124750</ |

|     |            |         |                                                             |                                                                                                                                                   |                                                                                                |         |
|-----|------------|---------|-------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------|---------|
| 797 | 06/14/2022 | 1051792 | Consumables                                                 |                                                                                                                                                   |                                                                                                | 1114811 |
| 797 | 06/02/2022 | 1049695 | CCTV                                                        | CCTV not recording                                                                                                                                |                                                                                                | 1113531 |
| 797 | 06/02/2022 | 1049695 |                                                             | CARRY OUT CCTV - A SERVICE AS PER CHECK LIST complete CCTV A service checked for recording - OK                                                   |                                                                                                | 1113531 |
| 797 | 06/01/2022 | 1049550 |                                                             | CARRY OUT A/C - B SERVICE AS PER CHECK LIST                                                                                                       |                                                                                                | 1113531 |
| 797 | 06/01/2022 | 1049550 |                                                             | Assisting                                                                                                                                         |                                                                                                | 1113531 |
| 797 | 06/01/2022 | 1049550 | AIR CONDITIONING REPAIR                                     | Creditor #-VB-COL004 COLD DRIVE PTY LTD P/O #:CR322600 Receiving #:338910 Date :2022-06-08 carry out a/c b service                                |                                                                                                | 1114310 |
| 797 | 06/01/2022 | 1049550 |                                                             | CARRY OUT A/C - A SERVICE AS PER CHECK LIST                                                                                                       |                                                                                                | 1113531 |
| 797 | 05/25/2022 | 1048140 | Consumables                                                 |                                                                                                                                                   |                                                                                                | 1112291 |
| 797 | 05/25/2022 | 1048140 | Mechanic entered -                                          | Wheels and Tyres Wheel Nut Retension O/S                                                                                                          |                                                                                                | 1112291 |
| 797 | 05/25/2022 | 1048140 | Mechanic entered -                                          | Wheels and Tyres Wheel Nut Retension O/S                                                                                                          |                                                                                                | 1112291 |
| 797 | 05/24/2022 | 1047881 |                                                             | VEHICLE SAFETY INSPECTION                                                                                                                         |                                                                                                | 1112291 |
| 797 | 05/24/2022 | 1047881 |                                                             | TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS                                                                                                      |                                                                                                | 1112291 |
| 797 | 05/24/2022 | 1048033 | Consumables                                                 |                                                                                                                                                   |                                                                                                | 1112291 |
| 797 | 05/24/2022 | 1048033 | Mechanic entered -                                          | Wheels and Tyres Worn O/S/R tyres worn                                                                                                            |                                                                                                | 1112291 |
| 797 | 05/24/2022 | 1048033 | TYRE 295/80R22.5 RECAP                                      |                                                                                                                                                   |                                                                                                | 1112291 |
| 797 | 05/24/2022 | 1048033 | TYRE 295/80R22.5 RECAP                                      |                                                                                                                                                   |                                                                                                | 1112291 |
| 797 | 05/24/2022 | 1047881 | Consumables                                                 |                                                                                                                                                   |                                                                                                | 1112291 |
| 797 | 05/24/2022 | 1047881 | Consumables                                                 |                                                                                                                                                   |                                                                                                | 1112291 |
| 797 | 05/24/2022 | 1047881 | Consumables                                                 |                                                                                                                                                   |                                                                                                | 1112291 |
| 797 | 05/24/2022 | 1047881 | Consumables                                                 |                                                                                                                                                   |                                                                                                | 1112291 |
| 797 | 05/24/2022 | 1047881 |                                                             | CARRY OUT B SERVICE AS PER CHECK LIST                                                                                                             |                                                                                                | 1112291 |
| 797 | 05/24/2022 | 1047881 | O-RING SPINNER FILTER SCANIA L94                            |                                                                                                                                                   |                                                                                                | 1112291 |
| 797 | 05/24/2022 | 1047881 | O-RING LARGE SPINNER FILTER SCANIA L94 & K230               |                                                                                                                                                   |                                                                                                | 1112291 |
| 797 | 05/24/2022 | 1047881 | PAPER SPINNER FILTER OIL INSERT SCANIA L94                  |                                                                                                                                                   |                                                                                                | 1112291 |
| 797 | 05/24/2022 | 1047881 | FILTER FUEL SCANIA L94 1372444                              |                                                                                                                                                   |                                                                                                | 1112291 |
| 797 | 05/24/2022 | 1047881 | FILTER OIL SCANIA K93 L94 1117285 2059778                   |                                                                                                                                                   |                                                                                                | 1112291 |
| 797 | 05/24/2022 | 1047881 | FILTER ZF ECOMAT GEARBOX(4139-298-038)(1193281)             |                                                                                                                                                   |                                                                                                | 1112291 |
| 797 | 05/24/2022 | 1047881 | BRUSH WHEELARCH 75mm 2.5M PER METRE                         |                                                                                                                                                   |                                                                                                | 1112291 |
| 797 | 05/24/2022 | 1047881 | TENSIONER ALT BELT SCANIA N310UA 2197005 1859657            |                                                                                                                                                   |                                                                                                | 1112291 |
| 797 | 05/24/2022 | 1047881 | PULLEY IDLER PLASTIC GROOVED SCANIA L94 1514087             |                                                                                                                                                   |                                                                                                | 1112291 |
| 797 | 05/24/2022 | 1047881 | PULLEY IDLER (SMOOTH PLASTIC) SCANIA 1514086 1428940        |                                                                                                                                                   |                                                                                                | 1112291 |
| 797 | 05/24/2022 | 1047881 | INVERTER 24 VOLT 36 WATT MAN                                |                                                                                                                                                   |                                                                                                | 1112291 |
| 797 | 05/18/2022 | 1047051 | Drv entered -                                               | A/C Heating Not Heating                                                                                                                           |                                                                                                | 1111655 |
| 797 | 05/18/2022 | 1047057 | Consumables                                                 |                                                                                                                                                   |                                                                                                | 1111655 |
| 797 | 05/18/2022 | 1047057 | Drv entered -                                               | Dash Dash_Lights Not Working                                                                                                                      |                                                                                                | 1111655 |
| 797 | 05/17/2022 | 1046576 | CCTV Not downloading                                        | hard drive failed to read on computer                                                                                                             |                                                                                                | 1111332 |
| 797 | 05/13/2022 | 1045975 |                                                             | TRANSMISSION CHECK AS PER CHECK LIST Carried out trans check as per checklist.                                                                    |                                                                                                | 1110954 |
| 797 | 05/12/2022 | 1045571 | GLASS WINDSCREEN CR228L BODY                                | Creditor #-VB-OBRO01 O'BRIENS GLASS INDUSTRIES P/O #:CR321259 Receiving #:337902 Date :2022-05-25 replace windscreen (817594)                     |                                                                                                | 1112644 |
| 797 | 05/11/2022 | 1045571 | Accident                                                    | WINDOWS - Windscreen ACCIDENT #53550                                                                                                              |                                                                                                | 1110889 |
| 797 | 05/10/2022 | 1045164 | HOSE HEADER TANK(483182)                                    | Creditor #-VB-MUL002 MULTISPARES CROYDON P/O #:CR321129 Receiving #:336956 Date :2022-05-11 transer from knox                                     |                                                                                                | 1110889 |
| 797 | 05/09/2022 | 1045164 | Fault#:38343 -                                              | Ops Entered - Fault - Breakdown Overheating/                                                                                                      |                                                                                                | 1110649 |
| 797 | 04/27/2022 | 1042564 | Elec and Light                                              | Indicators Not Working                                                                                                                            |                                                                                                | 1109272 |
| 797 | 04/27/2022 | 1042564 | Consumables                                                 |                                                                                                                                                   |                                                                                                | 1109272 |
| 797 | 04/27/2022 | 1042432 | PERFORM CAMPAIGN 03/22 QR CODE & SELECTED COVID19 DECAL REM |                                                                                                                                                   |                                                                                                | 1109272 |
| 797 | 03/15/2022 | 1035187 | Consumables                                                 |                                                                                                                                                   |                                                                                                | 1104968 |
| 797 | 03/15/2022 | 1035187 | Mechanic entered -                                          | Elec and Light Exterior Lights N/S & O/S                                                                                                          |                                                                                                | 1104968 |
| 797 | 03/15/2022 | 1035187 | LIGHT STOP/TAIL 9-33V LED KIT C/W GROMMET                   |                                                                                                                                                   |                                                                                                | 1104968 |
| 797 | 03/15/2022 | 1035187 | LAMP INDICATOR LED WITH GROMMET                             |                                                                                                                                                   |                                                                                                | 1104968 |
| 797 | 03/03/2022 | 1032904 | RETORQUE NSF WHEELNUTS TO SPEC                              |                                                                                                                                                   |                                                                                                | 1103412 |
| 797 | 03/03/2022 | 1032904 |                                                             | Assisting                                                                                                                                         |                                                                                                | 1103412 |
| 797 | 03/02/2022 | 1032646 | TENSIONER BELT SCANIA N310UA(2197005)(1859657)              |                                                                                                                                                   |                                                                                                | 1103412 |
| 797 | 03/02/2022 | 1032646 | BUSH FRONT SWAY BAR SCANIA K230UB 40MM 1919010 0469081      |                                                                                                                                                   |                                                                                                | 1103412 |
| 797 | 03/02/2022 | 1032646 |                                                             | VEHICLE SAFETY INSPECTION                                                                                                                         |                                                                                                | 1103412 |
| 797 | 03/02/2022 | 1032646 |                                                             | TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS                                                                                                      |                                                                                                | 1103412 |
| 797 | 02/23/2022 | 1031128 |                                                             | CARRY OUT FIRE EXTINGUISHER TEST & TAG Completed By ATS Fire                                                                                      |                                                                                                | 1102725 |
| 797 | 02/16/2022 | 1029429 | Ops Entered -                                               | Fault - Gearbox Driveline Warning Light On Da                                                                                                     |                                                                                                | 1101850 |
| 797 | 02/16/2022 | 1029429 | Ops Entered -                                               | Fault - Gearbox Driveline Warning Light On Da                                                                                                     |                                                                                                | 1101850 |
| 797 | 02/08/2022 | 1027348 | Drv entered -                                               | ERROR - Fault type not set ERROR - Fault type                                                                                                     |                                                                                                | 1100680 |
| 797 | 02/02/2022 | 1026076 | Fault#:38236 -                                              | Ops Entered - Fault - Breakdown Electrical -                                                                                                      |                                                                                                | 1100232 |
| 797 | 01/24/2022 | 1024516 | Ops Entered -                                               | Fault - Body Drivers Seat Controls - Route:                                                                                                       |                                                                                                | 1099336 |
| 797 | 01/21/2022 | 1024167 | REMOVE OLD 2020 DECAL AND FIT NEW 2022 DECAL POSITION AS S  | Campaign Complete                                                                                                                                 |                                                                                                | 1099205 |
| 797 | 12/17/2021 | 1018488 |                                                             | CARRY OUT TUNE-UP SERVICE AS PER CHECK LIST                                                                                                       |                                                                                                | 1096255 |
| 797 | 12/17/2021 | 1018488 |                                                             | SERVICE MOISTURE EJECTOR                                                                                                                          |                                                                                                | 1096255 |
| 797 | 12/17/2021 | 1018488 |                                                             |                                                                                                                                                   |                                                                                                | 1096255 |
| 797 | 12/17/2021 | 1018488 | GASKET ROCKER CVR DC903 B01 SCANIA L94UAB 1425921           |                                                                                                                                                   |                                                                                                | 1096255 |
| 797 | 12/17/2021 | 1018488 | VALVE CONDENSOR KIT CYCLONE LOWER SECTION                   |                                                                                                                                                   |                                                                                                | 1096255 |
| 797 | 12/08/2021 | 1016655 |                                                             | VEHICLE SAFETY INSPECTION                                                                                                                         |                                                                                                | 1095213 |
| 797 | 12/08/2021 | 1016655 |                                                             | TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS                                                                                                      |                                                                                                | 1095213 |
| 797 | 12/08/2021 | 1016655 | DIRECT PURCHASE -                                           | BUS INSPECTI                                                                                                                                      | Creditor #-VB-FLE001 FLEETCHECK BUS PTY LTD P/O #:CR312406 Receiving #:328491 Date :2021-12-22 | 1097225 |
| 797 | 12/08/2021 | 1016655 |                                                             | Assisting                                                                                                                                         |                                                                                                | 1095213 |
| 797 | 12/08/2021 | 1016655 |                                                             | ANNUAL SAFETY INSPECTION SERIAL #L630924_____ WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25 |                                                                                                | 1095213 |
| 797 | 12/08/2021 | 1016699 | Mechanic entered -                                          | Body Other n/s reflectors missing either                                                                                                          |                                                                                                | 1095213 |
| 797 | 12/08/2021 | 1016699 | REFLECTOR AMBER SMALL 70x28mm                               |                                                                                                                                                   |                                                                                                | 1095213 |
| 797 | 11/22/2021 | 1013208 | Elec and Light                                              | Interior Lights 2x saloon lightys N/W wait                                                                                                        |                                                                                                | 1093432 |
| 797 | 11/19/2021 | 1012834 | Mechanic entered -                                          | Body Drivers Seat Cover Seat base flat                                                                                                            |                                                                                                | 1093353 |
| 797 | 11/19/2021 | 1012834 | SEAT CUSH 6008 DRIVER COMPLETE                              |                                                                                                                                                   |                                                                                                | 1093353 |
| 797 | 11/19/2021 | 1012833 | Mechanic entered -                                          | Body Passenger Seat Torn Folding seat bas                                                                                                         |                                                                                                | 1093353 |
| 797 | 11/19/2021 | 1012833 | SEAT SINGLE SUPER SLIM CVR CA                               |                                                                                                                                                   |                                                                                                | 1093353 |
| 797 | 11/19/2021 | 1012833 | SEAT COVER SINGLE SUPER SLIM PLASTIC                        |                                                                                                                                                   |                                                                                                | 1093353 |
| 797 | 11/18/2021 | 1012557 |                                                             | VEHICLE SAFETY INSPECTION                                                                                                                         |                                                                                                | 1093195 |
| 797 | 11/18/2021 | 1012557 |                                                             | TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS                                                                                                      |                                                                                                | 1093195 |
| 797 | 11/18/2021 | 1012557 |                                                             | Assisting Carried out VSI on vehicle                                                                                                              |                                                                                                | 1093195 |
| 797 | 11/18/2021 | 1012557 |                                                             | PRE ANNUAL SAFETY INSPECTION CHECK                                                                                                                |                                                                                                | 1093195 |
| 797 | 11/18/2021 | 1012557 |                                                             | CARRY OUT CCTV - B SERVICE AS PER CHECK LIST                                                                                                      |                                                                                                | 1093195 |
| 797 | 11/17/2021 | 1011576 | DIRECT PURCHASE ACCIDENT                                    | Creditor #-VB-ECOAST EASTCOAST TRUCK & BUS SERVICE P/O #:CR310863 Receiving #:326602 Date :2021-11-25 CARRY OUT REPAIRS AS PER #52624             |                                                                                                | 1093967 |
| 797 | 11/15/2021 | 1011576 | Accident #52624 -                                           | The panel that surrounds the front passen                                                                                                         |                                                                                                | 1092757 |
| 797 | 11/15/2021 | 1011576 | Accident #52624 -                                           | The panel that surrounds the front passen                                                                                                         |                                                                                                | 1092757 |
| 797 | 11/12/2021 | 1011214 | PERFORM CAMPAIGN 20/20 PRE SUMMER PREVENTATIVE MAINTENANCE  |                                                                                                                                                   |                                                                                                | 1092676 |
| 797 | 11/12/2021 | 1011214 | FILTER FUEL SCANIA SR4(1372444 )                            |                                                                                                                                                   |                                                                                                | 1092676 |
| 797 | 11/12/2021 | 1011214 |                                                             | CARRY OUT C SERVICE AS PER CHECK LIST                                                                                                             |                                                                                                | 1092676 |
| 797 | 11/12/2021 | 1011214 |                                                             | Assisting Carry out C-Service on vehicle as per checklist                                                                                         |                                                                                                | 1092676 |
| 797 | 11/12/2021 | 1011214 | FILTER HYD COOLING FAN SCANIA L94UAB(1354074)               |                                                                                                                                                   |                                                                                                | 1092676 |
| 797 | 11/12/2021 | 1011214 | FILTER ZF ECOMAT GEARBOX(4139-298-038)(1193281)             |                                                                                                                                                   |                                                                                                | 1092676 |

|     |            |         |                                                              |                                                                                                                                                                                                                                                                                 |         |
|-----|------------|---------|--------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------|
| 797 | 11/12/2021 | 1011214 | FILTER OIL SCANIA S4 & K                                     |                                                                                                                                                                                                                                                                                 | 1092676 |
| 797 | 11/12/2021 | 1011214 | FILTER STEERING(153468)(0153468)(349619)                     |                                                                                                                                                                                                                                                                                 | 1092676 |
| 797 | 11/12/2021 | 1011214 | FILTER FUEL SCANIA SR4(1393640)                              |                                                                                                                                                                                                                                                                                 | 1092676 |
| 797 | 11/12/2021 | 1011214 | FILTER DRYER SCANIA/VOLVO(1375997)(3090288-6)(49G8704W)      |                                                                                                                                                                                                                                                                                 | 1092676 |
| 797 | 11/12/2021 | 1011214 | OIL SAMPLE KIT AMPOL                                         |                                                                                                                                                                                                                                                                                 | 1092676 |
| 797 | 11/12/2021 | 1011214 | O-RING LARGE SPINNER FILTER SCANIA 40A7703                   |                                                                                                                                                                                                                                                                                 | 1092676 |
| 797 | 11/12/2021 | 1011214 | O-RING SPINNER FILTER SCANIA ->  ENG#6203049 40A7701         |                                                                                                                                                                                                                                                                                 | 1092676 |
| 797 | 11/12/2021 | 1011214 | PAPER SPINNER FILTER OIL INSERT SCANIA L94                   |                                                                                                                                                                                                                                                                                 | 1092676 |
| 797 | 11/12/2021 | 1011214 | Consumables                                                  |                                                                                                                                                                                                                                                                                 | 1092676 |
| 797 | 11/12/2021 | 1011214 | Consumables                                                  |                                                                                                                                                                                                                                                                                 | 1092676 |
| 797 | 11/12/2021 | 1011214 |                                                              | CARRY OUT B SERVICE AS PER CHECK LIST                                                                                                                                                                                                                                           | 1092676 |
| 797 | 11/12/2021 | 1011214 |                                                              |                                                                                                                                                                                                                                                                                 | 1092676 |
| 797 | 11/12/2021 | 1011214 | Consumables                                                  |                                                                                                                                                                                                                                                                                 | 1092676 |
| 797 | 11/12/2021 | 1011214 | Consumables                                                  |                                                                                                                                                                                                                                                                                 | 1092676 |
| 797 | 11/09/2021 | 1010404 | Mechanic entered - Body Drivers Seat Belt Buckle Broken      | Removed and replaced buckle                                                                                                                                                                                                                                                     | 1092145 |
| 797 | 11/09/2021 | 1010404 | BUCKLE SEAT BELT NTS                                         |                                                                                                                                                                                                                                                                                 | 1092145 |
| 797 | 10/28/2021 | 1008140 | Mechanic entered - Elec and Light Other fit new battery brac | part ordered on 28-10-21                                                                                                                                                                                                                                                        | 1090911 |
| 797 | 10/28/2021 | 1008140 | BRACKET                                                      | Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:CR309866 Receiving #:324817 Date :2021-10-28                                                                                                                                                                                | 1090911 |
| 797 | 10/28/2021 | 1008140 | REINFORCEMENT                                                | Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:CR309866 Receiving #:324817 Date :2021-10-28                                                                                                                                                                                | 1090911 |
| 797 | 10/28/2021 | 1008140 | Service                                                      | replace battery hold down                                                                                                                                                                                                                                                       | 1090911 |
| 797 | 10/28/2021 | 1008139 |                                                              | CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST completed FSI defect raised on new w/o                                                                                                                                                                                       | 1090702 |
| 797 | 10/26/2021 | 1007537 | O-RING SPINNER FILTER SCANIA ->  ENG#6203049 40A7701         |                                                                                                                                                                                                                                                                                 | 1090533 |
| 797 | 10/26/2021 | 1007537 |                                                              | CARRY OUT B SERVICE AS PER CHECK LIST complete B service and repairs as per checklist                                                                                                                                                                                           | 1090533 |
| 797 | 10/26/2021 | 1007537 | PAPER SPINNER FILTER OIL INSERT SCANIA L94                   |                                                                                                                                                                                                                                                                                 | 1090533 |
| 797 | 10/26/2021 | 1007537 | OIL SAMPLE KIT AMPOL                                         |                                                                                                                                                                                                                                                                                 | 1090533 |
| 797 | 10/26/2021 | 1007537 | FILTER AIR OUTER SCANIA SR 3 & 4(395773)(AF25066)            |                                                                                                                                                                                                                                                                                 | 1090533 |
| 797 | 10/26/2021 | 1007537 | FILTER OIL SCANIA S4 & K                                     |                                                                                                                                                                                                                                                                                 | 1090533 |
| 797 | 10/26/2021 | 1007537 | FILTER FUEL FILTER SCANIA SR4 (1372444 )                     |                                                                                                                                                                                                                                                                                 | 1090533 |
| 797 | 10/26/2021 | 1007537 | FILTER ZF ECOMAT GEARBOX 4139-298-038 1193281                |                                                                                                                                                                                                                                                                                 | 1090533 |
| 797 | 10/26/2021 | 1007537 | O-RING LARGE SPINNER FILTER SCANIA 40A7703                   |                                                                                                                                                                                                                                                                                 | 1090533 |
| 797 | 10/26/2021 | 1007537 | DIRECT PURCHASE - ENGINE                                     | Creditor #:VB-ENZ001 ENZED BAYSWATER P/O #:CR309642 Receiving #:324808 Date :2021-10-28 FABRICATE TURBO LUBRICATION PIPE AS PER SAMPLE                                                                                                                                          | 1090911 |
| 797 | 10/26/2021 | 1007537 | Consumables                                                  |                                                                                                                                                                                                                                                                                 | 1090911 |
| 797 | 10/26/2021 | 1007537 | Consumables                                                  |                                                                                                                                                                                                                                                                                 | 1090911 |
| 797 | 10/21/2021 | 1006822 | Mechanic entered - Fluid Leaks Rear of bus                   | spin filter cap had come loose. tightened washed engine and brought into workshop. removed spint filter and removed shaft cleaned and used thread locker torqued to spec refit spin filter. refitted filter cap with new o-ring and torqued to spec. topped up 7 litres of oil. | 1090173 |
| 797 | 10/21/2021 | 1006822 | O-RING LARGE SPINNER FILTER SCANIA 40A7703                   |                                                                                                                                                                                                                                                                                 | 1090173 |
| 797 | 10/08/2021 | 1004478 | Mechanic entered - Elec and Light Exterior Lights N/S lower  | replace LED stop light                                                                                                                                                                                                                                                          | 1088554 |
| 797 | 10/08/2021 | 1004478 | LED RED STOP/ TAIL LAMP (41197)                              |                                                                                                                                                                                                                                                                                 | 1088554 |
| 797 | 09/16/2021 | 1000135 | LHS Electric Mirrors control not working                     | Unplugged and re set plug to electric mirror working ok now.                                                                                                                                                                                                                    | 1087144 |
| 797 | 09/09/2021 | 998274  | Consumables                                                  |                                                                                                                                                                                                                                                                                 | 1086127 |
| 797 | 09/09/2021 | 998274  | Mechanic entered - Wheels and Tyres Wheel Nut Retension N/S  | RETORQUE NSR WHEELNUTS TO SPEC                                                                                                                                                                                                                                                  | 1086127 |
| 797 | 09/09/2021 | 998274  | Mechanic entered - Wheels and Tyres Wheel Nut Retension N/S  | Assisting                                                                                                                                                                                                                                                                       | 1086127 |
| 797 | 09/08/2021 | 998018  | Consumables                                                  |                                                                                                                                                                                                                                                                                 | 1086127 |
| 797 | 09/08/2021 | 998018  | Wheels and Tyres N/S/R Worn need to recheck                  | R&R both N/S/R tyres with new put X1 old tyre into runout rack                                                                                                                                                                                                                  | 1086127 |
| 797 | 09/08/2021 | 998018  | TYRE 295/80R22.5 RECAP                                       |                                                                                                                                                                                                                                                                                 | 1086127 |
| 797 | 09/08/2021 | 998018  | TYRE 295/80R22.5 RECAP                                       |                                                                                                                                                                                                                                                                                 | 1086127 |
| 797 | 09/08/2021 | 998017  | Fluid Leaks Rear of busdiff pinion leakingneed to rech       | found no trans leak fit plug onto diff flange                                                                                                                                                                                                                                   | 1086127 |
| 797 | 09/06/2021 | 997460  | Ops Entered - Fault - Elec and Light Indicators Not Working  | CHECKED INDICATOR OPERATION ALL WORKING O.K.                                                                                                                                                                                                                                    | 1085922 |
| 797 | 09/03/2021 | 997047  | PERFORM CAMPAIGN 17/21 QR CODE DECAL FITMENT TO ALL BUSES    | Campaign Completed                                                                                                                                                                                                                                                              | 1085801 |
| 797 | 09/01/2021 | 995367  | Service                                                      | resecure rear parcel shelf & replace seat roll top.                                                                                                                                                                                                                             | 1085551 |
| 797 | 09/01/2021 | 986136  | DIRECT PURCHASE GLASS                                        | Creditor #:VB-ALP003 ALPHA BUS GLASS PTY LTD P/O #:CR302998 Receiving #:321140 Date :2021-09-09 REPLACE WINDSCREEN                                                                                                                                                              | 1086372 |
| 797 | 08/27/2021 | 995367  | Body (None)shelf behind rear seats loose.N/S 2nd from        |                                                                                                                                                                                                                                                                                 | 1085098 |
| 797 | 08/27/2021 | 995367  | Consumables                                                  |                                                                                                                                                                                                                                                                                 | 1085551 |
| 797 | 08/25/2021 | 994664  |                                                              | VEHICLE SAFETY INSPECTION                                                                                                                                                                                                                                                       | 1084871 |
| 797 | 08/25/2021 | 994664  |                                                              | TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS                                                                                                                                                                                                                                    | 1084871 |
| 797 | 08/25/2021 | 994664  |                                                              |                                                                                                                                                                                                                                                                                 | 1084871 |
| 797 | 08/25/2021 | 994683  | PULLEY IDLER (SMOOTH PLASTIC) SCANIA 1514086 1428940         |                                                                                                                                                                                                                                                                                 | 1084871 |
| 797 | 08/25/2021 | 994683  | BELT MICRO V SERPENTINE BELT 8 RIB 2135mm LONG(1389048)      |                                                                                                                                                                                                                                                                                 | 1084871 |
| 797 | 08/25/2021 | 994683  | PULLEY IDLER SCANIA L94 1514087                              |                                                                                                                                                                                                                                                                                 | 1084871 |
| 797 | 08/25/2021 | 994683  | Mechanic entered - Engine Belts_Loose Noisy Missing engine d | removed and replaced engine belt and idlers.                                                                                                                                                                                                                                    | 1084871 |
| 797 | 08/25/2021 | 994683  | Mechanic entered - Engine Belts_Loose Noisy Missing engine d | assist                                                                                                                                                                                                                                                                          | 1084871 |
| 797 | 08/24/2021 | 994318  |                                                              | CARRY OUT FIRE EXTINGUISHER TEST & TAG                                                                                                                                                                                                                                          | 1084732 |
| 797 | 08/24/2021 | 994318  |                                                              | Assisting - Completed by ATS                                                                                                                                                                                                                                                    | 1084732 |
| 797 | 08/24/2021 | 994318  |                                                              | Completed by ATS                                                                                                                                                                                                                                                                | 1084732 |
| 797 | 08/18/2021 | 992998  | Mechanic entered - Elec and Light Exterior Lights N/S top pa | found light U/S. replace both parker lights with LED.                                                                                                                                                                                                                           | 1084008 |
| 797 | 08/18/2021 | 992998  | LAMP LED WHITE FRONT PARK                                    |                                                                                                                                                                                                                                                                                 | 1084008 |
| 797 | 08/18/2021 | 992998  | LAMP LED WHITE FRONT PARK                                    |                                                                                                                                                                                                                                                                                 | 1084008 |
| 797 | 08/18/2021 | 992998  | Consumables                                                  |                                                                                                                                                                                                                                                                                 | 1084008 |
| 797 | 08/12/2021 | 991731  | Ops Entered - Fault - Body Front_Door Operation Faulty - R   | Reset rpd                                                                                                                                                                                                                                                                       | 1083469 |
| 797 | 08/12/2021 | 991731  | Consumables                                                  |                                                                                                                                                                                                                                                                                 | 1083469 |
| 797 | 07/27/2021 | 988189  |                                                              | TRANSMISSION CHECK AS PER CHECK LIST                                                                                                                                                                                                                                            | 1081345 |
| 797 | 07/27/2021 | 988189  |                                                              | complete TRANS CHECK as per checklist                                                                                                                                                                                                                                           | 1081345 |
| 797 | 07/16/2021 | 986136  | Ops Entered - Fault - Body Windows Front - Route: - Arriv    | FRONT WINDSCREEN REPLACED BY ALPHA GLASS                                                                                                                                                                                                                                        | 1080324 |
| 797 | 07/16/2021 | 986136  | Ops Entered - Fault - Body Windows Front - Route: - Arriv    | Assisting                                                                                                                                                                                                                                                                       | 1080324 |
| 797 | 07/06/2021 | 982137  | Diff Repair                                                  | Creditor #:VB-BAY002 BAYSWATER DIFF SERVICE PTY LTD P/O #:K302017 Receiving #:318129 Date :2021-07-30                                                                                                                                                                           | 1081890 |
| 797 | 07/01/2021 | 980477  | AIR CONDITIONING REPAIR                                      | Creditor #:VB-COL004 COLD DRIVE PTY LTD P/O #:CR301119 Receiving #:317754 Date :2021-07-27 CARRY OUT A/C A SERVICE                                                                                                                                                              | 1081533 |
| 797 | 06/25/2021 | 982137  | Ops Entered - Fault - Brakes Foot_Brakes Noisy - Route: -    | removed tailshaft removed old diff and replaced with new diff and then refitted tailshaft bundy road tested bus check for leaks no leaks                                                                                                                                        | 1077965 |
| 797 | 06/25/2021 | 982137  | Ops Entered - Fault - Brakes Foot_Brakes Noisy - Route: -    | remove and refit diff with reivan                                                                                                                                                                                                                                               | 1077965 |
| 797 | 06/17/2021 | 980477  |                                                              | CARRY OUT A/C - A SERVICE AS PER CHECK LIST                                                                                                                                                                                                                                     | 1077275 |
| 797 | 06/17/2021 | 980477  |                                                              | Assisting                                                                                                                                                                                                                                                                       | 1077275 |
| 797 | 06/08/2021 | 978399  | WHEEL ARCH RUBBER 41294                                      | incorrect PN booked. correcting neg stock                                                                                                                                                                                                                                       | 1076278 |
| 797 | 06/08/2021 | 978399  | W/ARCH RUBBER EXTRUSION 040021                               | correcting PN booked to WO                                                                                                                                                                                                                                                      | 1076278 |
| 797 | 06/04/2021 | 978329  |                                                              | VEHICLE SAFETY INSPECTION                                                                                                                                                                                                                                                       | 1075914 |
| 797 | 06/04/2021 | 978329  |                                                              | TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS                                                                                                                                                                                                                                    | 1075914 |
| 797 | 06/04/2021 | 978329  |                                                              | Assisting                                                                                                                                                                                                                                                                       | 1075914 |
| 797 | 06/04/2021 | 978412  | AIRBAG DRIVE & TAG AXLE                                      |                                                                                                                                                                                                                                                                                 | 1075914 |
| 797 | 06/04/2021 | 978412  | Mechanic entered - Suspension Other rear axle rear airbags l | removed and replaced rear rear airbags                                                                                                                                                                                                                                          | 1075914 |
| 797 | 06/04/2021 | 978329  | Drv entered - A/C Heating Not Heating. needs thermostat      | drain and saved coolant. removed thermostat housing removed thermostat. cleaned mating surfaces. fitted new thermostat. refitting housing to vehicle. refitted top hose. refilled with dsaved coolant road test and check for leaks. all okay.                                  | 1075914 |
| 797 | 06/04/2021 | 978329  | THERMOSTAT SCANIA K230 1404925 1849060                       |                                                                                                                                                                                                                                                                                 | 1075914 |
| 797 | 06/04/2021 | 978399  | Mechanic entered - Body Other OSF wheel arch rubber          | Fitted new wheel arch rubber to OSF                                                                                                                                                                                                                                             | 1075914 |
| 797 | 06/04/2021 | 978399  | 75MM WHEELARCH BRUSH 2.5M PER WHEEL SOLD BY METRE            |                                                                                                                                                                                                                                                                                 | 1075914 |
| 797 | 06/04/2021 | 978399  | WHEEL ARCH RUBBER 41294                                      |                                                                                                                                                                                                                                                                                 | 1075914 |
| 797 | 06/04/2021 | 978329  |                                                              | carry out CCTV A service as per checklist                                                                                                                                                                                                                                       | 1075914 |
| 797 | 05/19/2021 | 975262  | Mechanic entered - Elec and Light Exterior Lights            | Fitted new light lens and globe                                                                                                                                                                                                                                                 | 1074007 |
| 797 | 05/19/2021 | 975262  | HEAD LAMP INSERT HELLA 100MM L/FLOOR 0500 29204              |                                                                                                                                                                                                                                                                                 | 1074007 |

|     |            |        |                                                              |                                                                                                                                                                                                                                                                                                                                     |  |         |
|-----|------------|--------|--------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|---------|
| 797 | 05/19/2021 | 975262 | GLOBE 24V 70W HALOGEN H1                                     |                                                                                                                                                                                                                                                                                                                                     |  | 1074007 |
| 797 | 05/19/2021 | 975262 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                                     |  | 1074007 |
| 797 | 05/10/2021 | 973355 | Elec and Light Indicators Not Working                        | replace indicator stalk                                                                                                                                                                                                                                                                                                             |  | 1072635 |
| 797 | 05/10/2021 | 973355 | SWITCH INDICATOR SCANIA L94 1402448                          |                                                                                                                                                                                                                                                                                                                                     |  | 1072635 |
| 797 | 05/10/2021 | 973355 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                                     |  | 1072635 |
| 797 | 05/07/2021 | 973028 | GLOBE & HOLDER INSTRUMENT PANEL GREY                         |                                                                                                                                                                                                                                                                                                                                     |  | 1072635 |
| 797 | 05/07/2021 | 973028 | Ops Entered - Fault - Elec and Light Next Stop Button - -ne  | R&R Dash stop light with new tested okay                                                                                                                                                                                                                                                                                            |  | 1072635 |
| 797 | 05/07/2021 | 973028 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                                     |  | 1072635 |
| 797 | 05/04/2021 | 972216 | Ops Entered - Fault - BusMinder No Power - Route: - Arriv    | replace cable. test ok                                                                                                                                                                                                                                                                                                              |  | 1072154 |
| 797 | 05/04/2021 | 972216 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                                     |  | 1072154 |
| 797 | 04/27/2021 | 970840 | on occasion when the wheel is turned the horn will sound     | checked wiring & horn operation. could not fault at time of test                                                                                                                                                                                                                                                                    |  | 1071293 |
| 797 | 04/22/2021 | 969746 | PERFORM CAMPAIGN 12/21 ROUTE BUS DESTINATION FILE UPDATE     | uploaded files                                                                                                                                                                                                                                                                                                                      |  | 1070737 |
| 797 | 04/21/2021 | 969574 | Mechanic entered - Suspension Other D-Rubbers on front Sway  | Fitted two new sway bar rubbers                                                                                                                                                                                                                                                                                                     |  | 1070737 |
| 797 | 04/21/2021 | 969574 | BUSH FRT SWAY BAR SCANIA K230UB 0469081 1919010 40MM         |                                                                                                                                                                                                                                                                                                                                     |  | 1070737 |
| 797 | 04/21/2021 | 969580 | Mechanic entered - Engine Belts_Loose Noisy Missing          | Remove and replace belt tensioner                                                                                                                                                                                                                                                                                                   |  | 1070737 |
| 797 | 04/21/2021 | 969580 | BELT TENSIONER SCANIA N310UA 2197005 1859657                 |                                                                                                                                                                                                                                                                                                                                     |  | 1070737 |
| 797 | 04/21/2021 | 969529 |                                                              | CARRY OUT B SERVICE AS PER CHECK LIST                                                                                                                                                                                                                                                                                               |  | 1070737 |
| 797 | 04/21/2021 | 969529 | FILTER OIL SCANIA S4 & K                                     |                                                                                                                                                                                                                                                                                                                                     |  | 1070737 |
| 797 | 04/21/2021 | 969529 | FILTER ZF ECOMAT GEARBOX 4139-298-038 1193281                |                                                                                                                                                                                                                                                                                                                                     |  | 1070737 |
| 797 | 04/21/2021 | 969529 | SPINNER FILTER KIT ALL SCANIA                                |                                                                                                                                                                                                                                                                                                                                     |  | 1070737 |
| 797 | 04/21/2021 | 969529 | FILTER FUEL FILTER SCANIA SR4 (1372444 )                     |                                                                                                                                                                                                                                                                                                                                     |  | 1070737 |
| 797 | 04/21/2021 | 969529 | OIL SAMPLE KIT CALTEX                                        |                                                                                                                                                                                                                                                                                                                                     |  | 1070737 |
| 797 | 04/21/2021 | 969529 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                                     |  | 1070737 |
| 797 | 04/21/2021 | 969529 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                                     |  | 1070737 |
| 797 | 04/21/2021 | 969529 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                                     |  | 1070737 |
| 797 | 04/08/2021 | 966954 | Ops Entered - Fault - Elec and Light - fuel gauge not work   | check front & rear gauges operation. all ok. check wiring found broken wire. repaire wire. test all ok                                                                                                                                                                                                                              |  | 1069299 |
| 797 | 03/30/2021 | 965147 | Place new poster over the top attach hangers to hand rails   | Campaign Complete                                                                                                                                                                                                                                                                                                                   |  | 1068568 |
| 797 | 03/30/2021 | 965148 | PERFORM CAMPAIGN 10/21 FITMENT OF AUTHORISED OPERATOR DECAL  | Campaign Complete                                                                                                                                                                                                                                                                                                                   |  | 1068568 |
| 797 | 03/24/2021 | 962987 | Near side indicator stays on.                                | repaired wiring                                                                                                                                                                                                                                                                                                                     |  | 1068000 |
| 797 | 03/24/2021 | 962987 | Near side indicator stays on.                                |                                                                                                                                                                                                                                                                                                                                     |  | 1068000 |
| 797 | 03/24/2021 | 962036 | Ops Entered - Fault - Elec and Light - Route: - Arrive Cro   | check operation of indicators not able to turn indicators on in straight ahead position. attempt to remove and fit another steering wheel could not remove. on closer inspection found stork to be too close to steering wheel as steering wheel has been repaired previously. spaced stork out and test indicator work as per norm |  | 1068000 |
| 797 | 03/24/2021 | 962036 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                                     |  | 1068000 |
| 797 | 03/24/2021 | 962987 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                                     |  | 1068000 |
| 797 | 03/22/2021 | 962036 | STEERING WHEEL SCANIA                                        | Creditor #::VB-MUL002 MULTISPARES CROYDON P/O #::CR295455 Receiving #:308895 Date :2021-03-24                                                                                                                                                                                                                                       |  | 1068000 |
| 797 | 03/19/2021 | 962036 | Ops Entered - Fault - Elec and Light - Route: - Arrive Cr    |                                                                                                                                                                                                                                                                                                                                     |  | 1067575 |
| 797 | 03/19/2021 | 961927 | PERFORM CAMPAIGN 09/21 POSITIONING OF 2021 PTV FARES & COVI  | Campaign Completed                                                                                                                                                                                                                                                                                                                  |  | 1067575 |
| 797 | 03/18/2021 | 961711 | Mechanic entered - Elec and Light Indicators Not Working     | replace indicator stalk                                                                                                                                                                                                                                                                                                             |  | 1067456 |
| 797 | 03/18/2021 | 961711 | SWITCH INDICATOR SCANIA L94 1402448                          |                                                                                                                                                                                                                                                                                                                                     |  | 1067456 |
| 797 | 03/18/2021 | 961711 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                                     |  | 1067456 |
| 797 | 03/10/2021 | 959397 | Elec and Light Indicator stalk doesn't stay in the turn p    | genuine unit on order wop                                                                                                                                                                                                                                                                                                           |  | 1066495 |
| 797 | 03/10/2021 | 959397 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                                     |  | 1066495 |
| 797 | 03/09/2021 | 959025 |                                                              | VEHICLE SAFETY INSPECTION carry out safety inpection as per checklist                                                                                                                                                                                                                                                               |  | 1066297 |
| 797 | 03/09/2021 | 959025 |                                                              | Assisting                                                                                                                                                                                                                                                                                                                           |  | 1066297 |
| 797 | 03/09/2021 | 959025 |                                                              | TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS                                                                                                                                                                                                                                                                                        |  | 1066297 |
| 797 | 03/09/2021 | 959150 | Mechanic entered - Suspension Other n/s fronty airbag leakin | removed and replaced leaking front airbag                                                                                                                                                                                                                                                                                           |  | 1066297 |
| 797 | 03/09/2021 | 959150 | AIRBAG FRT 14MM SCANIA K230UB 1726239 2809671                |                                                                                                                                                                                                                                                                                                                                     |  | 1066297 |
| 797 | 03/09/2021 | 959150 | FITTING ELBOW                                                |                                                                                                                                                                                                                                                                                                                                     |  | 1066297 |
| 797 | 03/09/2021 | 959150 | FITTING. RR AIRBAG SCANIA                                    |                                                                                                                                                                                                                                                                                                                                     |  | 1066297 |
| 797 | 03/09/2021 | 959231 | Mechanic entered - Steering Steering Wheel Faulty steering w | removed and replaced steering wheel                                                                                                                                                                                                                                                                                                 |  | 1066297 |
| 797 | 03/09/2021 | 959231 | STEERING WHEEL SCANIA                                        |                                                                                                                                                                                                                                                                                                                                     |  | 1066297 |
| 797 | 03/02/2021 | 958184 | Mechanic entered - Body Other O/S/F wheel arch brush missing | replace wheel arch brush                                                                                                                                                                                                                                                                                                            |  | 1065868 |
| 797 | 03/02/2021 | 958184 | 75MM WHEELARCH BRUSH 2.5M PER WHEEL SOLD BY METRE            |                                                                                                                                                                                                                                                                                                                                     |  | 1065868 |
| 797 | 03/02/2021 | 958184 | WHEEL ARCH RUBBER 41294                                      |                                                                                                                                                                                                                                                                                                                                     |  | 1065868 |
| 797 | 03/01/2021 | 956697 | Vandalism: Replace Anti Graffi                               | Creditor #::VB-GLA010 GLASSPROTECH MELBOURNE P/O #::CR293893 Receiving #:307833 Date :2021-03-09                                                                                                                                                                                                                                    |  | 1066473 |
| 797 | 02/25/2021 | 957195 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                                     |  | 1065656 |
| 797 | 02/25/2021 | 957195 | Ops Entered - Fault - Elec and Light Exterior Lights - indi  | Inspect indicators no fault found at time of test                                                                                                                                                                                                                                                                                   |  | 1065481 |
| 797 | 02/24/2021 | 956697 | Vandalism: Replace Anti Graffiti Film - L1 L2                | Assisting - Completed by Glassprotech                                                                                                                                                                                                                                                                                               |  | 1065263 |
| 797 | 02/24/2021 | 956697 | Vandalism: Replace Anti Graffiti Film - L1 L2                | Completed by Glassprotech                                                                                                                                                                                                                                                                                                           |  | 1065263 |
| 797 | 02/17/2021 | 955017 | Leave old poster in and fit you must wear a maskover the     | Campaign Completed                                                                                                                                                                                                                                                                                                                  |  | 1064528 |
| 797 | 02/16/2021 | 954287 |                                                              | Completed By ATS                                                                                                                                                                                                                                                                                                                    |  | 1064325 |
| 797 | 02/16/2021 | 954287 |                                                              | CARRY OUT FIRE EXTINGUISHER TEST & TAG                                                                                                                                                                                                                                                                                              |  | 1064325 |
| 797 | 02/10/2021 | 952741 | Ops Entered - Fault - A/C Heating Not Cooling - Route: 690   | Checked A/C compressor clutch and high pressure line. Checked blower motors. A/C seems to be functioning.                                                                                                                                                                                                                           |  | 1063766 |
| 797 | 02/10/2021 | 952565 | Keep ol poster in holder and place Travel off Peak and Sav   | Campaign Completed                                                                                                                                                                                                                                                                                                                  |  | 1063766 |
| 797 | 02/03/2021 | 950720 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                                     |  | 1063112 |
| 797 | 02/03/2021 | 950720 | Ops Entered - Fault - Elec and Light Warning Light On Dash   | Job completed ref w/o 949778                                                                                                                                                                                                                                                                                                        |  | 1062622 |
| 797 | 02/02/2021 | 950483 | Removed N/S/F window COVID-19 & MYKI decals and reposition   | Campaign Completed                                                                                                                                                                                                                                                                                                                  |  | 1062622 |
| 797 | 02/01/2021 | 941815 | Direct Purchase - BODYWORK                                   | Creditor #::VB-ECOAST EASTCOAST TRUCK & BUS SERVICE P/O #::CR289878 Receiving #:305271 Date :2021-02-04 SECURE A/C MOUNTING ON ROOF POD                                                                                                                                                                                             |  | 1063290 |
| 797 | 02/01/2021 | 941815 | AIR CONDITIONING REPAIR                                      | Creditor #::VB-COL004 COLD DRIVE PTY LTD P/O #::CR290855 Receiving #:306235 Date :2021-02-17 SUPPLY A/C ROOF FANS                                                                                                                                                                                                                   |  | 1064528 |
| 797 | 01/29/2021 | 949778 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                                     |  | 1062444 |
| 797 | 01/29/2021 | 949778 | Ops Entered - Fault - Elec and Light Warning Light On Dash - | Checked fuse and alternator wiring okay. Checked voltage regulator okay. Fault found faulty alternator rotor. Removed and replaced alternator. Checked and tested alternator charge ikay.                                                                                                                                           |  | 1062224 |
| 797 | 01/29/2021 | 949778 | ALTERNATOR 24V 140A SCANIA L94UAB 0571419                    |                                                                                                                                                                                                                                                                                                                                     |  | 1062224 |
| 797 | 01/15/2021 | 946916 | Service                                                      | replace solinoid & fuse                                                                                                                                                                                                                                                                                                             |  | 1061191 |
| 797 | 01/15/2021 | 946916 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                                     |  | 1061191 |
| 797 | 01/15/2021 | 946916 | SOLENOID 24V CONT SILVER CONT                                |                                                                                                                                                                                                                                                                                                                                     |  | 1061191 |
| 797 | 01/14/2021 | 946916 | Elec and Light Exterior Lights all lights n/w. Soildnoid     | Creditor #::VB-MUL002 MULTISPARES CROYDON P/O #::CR291226 Receiving #:304130 Date :2021-01-18                                                                                                                                                                                                                                       |  | 1061015 |
| 797 | 01/13/2021 | 944452 | Check and repair fan motor mounts                            | Remved all 5 fans made up stiffeners mounted new motors tested there is still a little noise caused by harmonics from motors                                                                                                                                                                                                        |  | 1061015 |
| 797 | 01/07/2021 | 945136 | Accident #50757. Damage to NS Front. DAF                     | Phil advised to close job                                                                                                                                                                                                                                                                                                           |  | 1061015 |
| 797 | 01/07/2021 | 945142 | Accident #51107 - N/s mirror. DAF                            | Phil advised to close                                                                                                                                                                                                                                                                                                               |  | 1061015 |
| 797 | 01/06/2021 | 944452 | Check and repair fan motor mounts                            | Replaced all failed mount points to condenser fan motors reinforce front motor mount number 3 and 4 condenser fan assembly are out of ballance new motors have been ordered carry over job not completed                                                                                                                            |  | 1061015 |
| 797 | 01/05/2021 | 944452 | Check and repair fan motor mounts                            | Started on securing loose condenser fan motors job not completed carry over                                                                                                                                                                                                                                                         |  | 1061015 |
| 797 | 12/18/2020 | 941815 | SECURE A/C FAN MOUNTING ON ROOF POD                          | REPAIRED EASTCOAST DANDENONG                                                                                                                                                                                                                                                                                                        |  | 1059323 |
| 797 | 12/18/2020 | 941815 | SECURE A/C FAN MOUNTING ON ROOF POD                          | Assisting                                                                                                                                                                                                                                                                                                                           |  | 1059323 |
| 797 | 12/07/2020 | 939652 |                                                              | VEHICLE SAFETY INSPECTION                                                                                                                                                                                                                                                                                                           |  | 1057954 |
| 797 | 12/07/2020 | 939652 |                                                              | TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS                                                                                                                                                                                                                                                                                        |  | 1057954 |
| 797 | 12/07/2020 | 939652 |                                                              | ANNUAL SAFETY INSPECTION SERIAL #_L157558_____WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLESAFETY INSPECTION LINE TIME ON THE W/O TO 0.25                                                                                                                                                                                    |  | 1057954 |
| 797 | 12/07/2020 | 939652 |                                                              | Assisting                                                                                                                                                                                                                                                                                                                           |  | 1057954 |
| 797 | 12/07/2020 | 939652 | DIRECT PURCHASE - BUS INSPECTI                               | Creditor #::VB-FLE001 FLEETCHECK BUS PTY LTD P/O #::CR289103 Receiving #:301621 Date :2020-12-07                                                                                                                                                                                                                                    |  | 1058320 |
| 797 | 12/04/2020 | 939293 | RETORQUE OSR WHEELNUTS                                       | RETORQUE OSR WHEELNUTS TO SPEC                                                                                                                                                                                                                                                                                                      |  | 1057954 |
| 797 | 12/04/2020 | 939293 |                                                              | Assisting                                                                                                                                                                                                                                                                                                                           |  | 1057954 |
| 797 | 12/03/2020 | 939012 | REPLACE OSR REAR TYRES                                       | REMOVE AND REPLACE OSR TYRES TORQUE WHEELNUTS TO SPEC                                                                                                                                                                                                                                                                               |  | 1057954 |
| 797 | 12/03/2020 | 939012 | REPLACE OSR REAR TYRES                                       | Assisting                                                                                                                                                                                                                                                                                                                           |  | 1057954 |
| 797 | 12/03/2020 | 939012 | TYRE 295/80R22.5 RECAP                                       |                                                                                                                                                                                                                                                                                                                                     |  | 1057954 |
| 797 | 12/03/2020 | 939012 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                                     |  | 1058223 |

|     |            |        |                                                              |                                                                                                                          |         |
|-----|------------|--------|--------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------|---------|
| 797 | 12/03/2020 | 939257 | Mechanic entered - Elec and Light Flat Batteries Main batter | R/R main batteries and checked charge rate.                                                                              | 1057954 |
| 797 | 12/03/2020 | 939257 | BATTERY 1030CCA POS ON LHS EMFN150L                          |                                                                                                                          | 1057954 |
| 797 | 12/03/2020 | 939257 | Consumables                                                  |                                                                                                                          | 1058223 |
| 797 | 11/30/2020 | 938105 | PERFORM CAMPAIGN 27/20 UPDATED INTERNAL BUS NUMBER DECALS    | Campaign Completed                                                                                                       | 1057675 |
| 797 | 11/26/2020 | 932441 | Consumables                                                  |                                                                                                                          | 1057500 |
| 797 | 11/26/2020 | 932441 | GAS STRUT 700N-502MM                                         | Non-Stock Item. Correcting Negative Stock                                                                                | 1057375 |
| 797 | 11/21/2020 | 935535 | AIR CONDITIONING REPAIR                                      | Creditor #:-VB-COL004 COLD DRIVE PTY LTD P/O #:CR288083 Receiving #:301093 Date :2020-11-30 rectify roof fans noisy      | 1057675 |
| 797 | 11/20/2020 | 935535 | Ops Entered - Fault - A/C Heating Noisy - when first turn    | A/C ROOF POD MOUNTING REPAIRED EASTCOAST DANDENONG                                                                       | 1057067 |
| 797 | 11/20/2020 | 935535 | Ops Entered - Fault - A/C Heating Noisy - when first turn    | Assisting                                                                                                                | 1057067 |
| 797 | 11/20/2020 | 935535 | A/C Heating (None) roof fans noisy                           |                                                                                                                          | 1057067 |
| 797 | 11/20/2020 | 935379 | Remove old poster and fit you must wear a face mask when t   | Campaign Completed                                                                                                       | 1057067 |
| 797 | 11/20/2020 | 935509 | PERFORM CAMPAIGN 26/20 REAR EXIT DECAL MAKE YOUR MARK & SE   | Campaign Completed                                                                                                       | 1057067 |
| 797 | 11/17/2020 | 933851 |                                                              | VEHICLE SAFETY INSPECTION                                                                                                | 1056660 |
| 797 | 11/17/2020 | 933851 |                                                              | TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS                                                                             | 1056660 |
| 797 | 11/17/2020 | 933851 |                                                              | Assisting                                                                                                                | 1056660 |
| 797 | 11/16/2020 | 933553 | Panel above driver's head loose                              | secure desto panel                                                                                                       | 1056468 |
| 797 | 11/11/2020 | 932417 |                                                              | PRE ANNUAL SAFETY INSPECTION CHECK complete as per W/O                                                                   | 1056163 |
| 797 | 11/11/2020 | 932417 |                                                              | CARRY OUT CCTV - B SERVICE AS PER CHECK LIST complete as per W/O                                                         | 1056163 |
| 797 | 11/11/2020 | 932417 |                                                              | Assisting                                                                                                                | 1056163 |
| 797 | 11/11/2020 | 932467 | Mechanic entered - Suspension Other OSR/Front airbag perishe | R/R airbag and check for air leaks.                                                                                      | 1056163 |
| 797 | 11/11/2020 | 932467 | AIRBAG REAR 16MM SCANIA K230 / K270 2024287 2024290          |                                                                                                                          | 1056163 |
| 797 | 11/11/2020 | 932439 | Mechanic entered - Engine Other X2 engine idler pullers worn | R&R both with new                                                                                                        | 1056163 |
| 797 | 11/11/2020 | 932439 | PULLEY IDLER (SMOOTH PLASTIC) SCANIA 1514086 1428940         |                                                                                                                          | 1056163 |
| 797 | 11/11/2020 | 932439 | PULLEY IDLER SCANIA (1514087)                                |                                                                                                                          | 1056163 |
| 797 | 11/11/2020 | 932480 | Mechanic entered - Elec and Light Next Stop Button NSF and O |                                                                                                                          | 1056163 |
| 797 | 11/11/2020 | 932480 | SWITCH STOP RED/GREY                                         |                                                                                                                          | 1056163 |
| 797 | 11/11/2020 | 932480 | Consumables                                                  |                                                                                                                          | 1056163 |
| 797 | 11/11/2020 | 932441 | GAS STRUT 700N-502MM                                         |                                                                                                                          | 1056163 |
| 797 | 11/11/2020 | 932441 | GAS STRUT 700N-502MM                                         |                                                                                                                          | 1056163 |
| 797 | 11/11/2020 | 932441 | Mechanic entered - Body Other Rear hatch and O/S/R engine ha | R&R 4 gas struts with new                                                                                                | 1056163 |
| 797 | 11/11/2020 | 932441 | STRUT GAS STAY 350NM 425MM LONG                              |                                                                                                                          | 1056163 |
| 797 | 11/11/2020 | 932441 | STRUT GAS STAY 350NM 425MM LONG                              |                                                                                                                          | 1056163 |
| 797 | 11/09/2020 | 931664 | Fit new Myki Decals & refit COVID-19 decals new position f   | Campaign Completed                                                                                                       | 1055895 |
| 797 | 11/05/2020 | 930881 |                                                              | CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST completed FSI covered battery cables and wiring under bus and secured | 1055368 |
| 797 | 10/07/2020 | 924763 | PERFORM CAMPAIGN 20/20 VEHICLE TOLLWAY ETAG FITMENT          | Etag fitted                                                                                                              | 1052420 |
| 797 | 10/02/2020 | 923466 | Vandalism/ Graffiti Interior. rear seat base to              | Check bus no faults found                                                                                                | 1051708 |
| 797 | 09/29/2020 | 921798 |                                                              | TRANSMISSION CHECK AS PER CHECK LIST                                                                                     | 1051435 |
| 797 | 09/29/2020 | 921798 | Service                                                      | REMOVE AND REPLACE FRONT DOOR INTERIOR ACCESS PANEL                                                                      | 1051435 |
| 797 | 09/29/2020 | 921798 | Consumables                                                  |                                                                                                                          | 1051531 |
| 797 | 09/29/2020 | 921798 |                                                              | CARRY OUT B SERVICE AS PER CHECK LIST                                                                                    | 1051435 |
| 797 | 09/29/2020 | 921798 | FILTER FUEL FILTER SCANIA SR4 (1372444 )                     |                                                                                                                          | 1051435 |
| 797 | 09/29/2020 | 921798 | Oil Filter SCANIA S4 & K                                     |                                                                                                                          | 1051435 |
| 797 | 09/29/2020 | 921798 | FILTER ZF ECOMAT GEARBOX 4139-298-038 1193281                |                                                                                                                          | 1051435 |
| 797 | 09/29/2020 | 921798 | KIT O-RING OIL SPINNER FILTER SCANIA ABOVE ENG #6203050      |                                                                                                                          | 1051435 |
| 797 | 09/29/2020 | 921798 | OIL SAMPLE KIT CALTEX                                        |                                                                                                                          | 1051435 |
| 797 | 09/29/2020 | 921798 | Consumables                                                  |                                                                                                                          | 1051531 |
| 797 | 09/29/2020 | 921798 | Consumables                                                  |                                                                                                                          | 1051531 |
| 797 | 09/29/2020 | 921798 | Consumables                                                  |                                                                                                                          | 1051531 |
| 797 | 09/24/2020 | 921798 | DUCT PIECE 1800MM ELLAMP                                     | Creditor #:-VB-VOLGREN VOLGREN AUSTRALIA PTY LTD P/O #:CR284360 Receiving #:296862 Date :2020-09-28                      | 1051435 |
| 797 | 09/24/2020 | 921798 | FINISHING MOLD R/H ELLAMP                                    | Creditor #:-VB-VOLGREN VOLGREN AUSTRALIA PTY LTD P/O #:CR284360 Receiving #:296862 Date :2020-09-28                      | 1051435 |
| 797 | 09/24/2020 | 921798 | FINISHING MOLD L/H ELLAMP                                    | Creditor #:-VB-VOLGREN VOLGREN AUSTRALIA PTY LTD P/O #:CR284360 Receiving #:296862 Date :2020-09-28                      | 1051435 |
| 797 | 09/23/2020 | 921797 | GLOBE 24V 70W HALOGEN H1                                     |                                                                                                                          | 1051122 |
| 797 | 09/23/2020 | 921797 | Mechanic entered - Elec and Light Exterior Lights O/S head l | replace head light globe                                                                                                 | 1051122 |
| 797 | 09/23/2020 | 921797 | Consumables                                                  |                                                                                                                          | 1051398 |
| 797 | 09/23/2020 | 921798 | Body Panel above front door has broken off                   | remove & temp repair panel. oorder new panel                                                                             | 1051122 |
| 797 | 09/18/2020 | 920871 | Mechanic entered - Elec and Light Other Hard to start        | Check battery charge rate load test batteries. Check start all ok                                                        | 1050729 |
| 797 | 09/18/2020 | 920865 | Ops Entered - Fault - Elec and Light Flat Batteries - Rout   | CHECK BATTERY CHARGE RATE LOAD TEST CHECKED OK NO FAULT FOUND AND JUMP STARTING NOT REQUIRED                             | 1050729 |
| 797 | 09/18/2020 | 920871 | Consumables                                                  |                                                                                                                          | 1050803 |
| 797 | 09/18/2020 | 920865 | Consumables                                                  |                                                                                                                          | 1050803 |
| 797 | 09/01/2020 | 917408 | Accident - FRONT                                             | FIT NEW NS ELECTRIC MIRROR ASSEMBLY ACCIDENT 51107                                                                       | 1048782 |
| 797 | 09/01/2020 | 917408 | Mirror Electric Heated suit Volgren (17498/SER)              |                                                                                                                          | 1048782 |
| 797 | 08/26/2020 | 916418 | HORN 24V 112MM                                               |                                                                                                                          | 1048168 |
| 797 | 08/26/2020 | 916418 | Body (None) repairs as per listdash lightssteering           | complete all repairs                                                                                                     | 1048168 |
| 797 | 08/25/2020 | 916134 | Mechanic entered - Dash Other trans seletor D button broken  | replace D button                                                                                                         | 1048075 |
| 797 | 08/25/2020 | 916134 | BUTTON GEAR SHIFT D HORIZONTAL SERIES 3                      |                                                                                                                          | 1048075 |
| 797 | 08/25/2020 | 916134 | Consumables                                                  |                                                                                                                          | 1048168 |
| 797 | 08/24/2020 | 915695 | Ops Entered - Fault - Elec and Light Flat Batteries - Rout   | jump start bus -a/c and battery master left on                                                                           | 1047929 |
| 797 | 08/24/2020 | 915695 | Consumables                                                  |                                                                                                                          | 1048075 |
| 797 | 08/18/2020 | 914707 |                                                              | VEHICLE SAFETY INSPECTION                                                                                                | 1047264 |
| 797 | 08/18/2020 | 914707 |                                                              | TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS                                                                             | 1047264 |
| 797 | 08/18/2020 | 914778 | Mechanic entered - Engine Belts_Loose Noisy Missing engine b | R&R with new                                                                                                             | 1047264 |
| 797 | 08/18/2020 | 914778 | BELT MICRO V SERPENTINE BELT 8 RIB 2135mm LONG (1389048)     |                                                                                                                          | 1047264 |
| 797 | 08/18/2020 | 914779 | PLASTIC DOOR ROLLER BOTTOM                                   |                                                                                                                          | 1047264 |
| 797 | 08/18/2020 | 914779 | PLASTIC DOOR ROLLER BOTTOM                                   |                                                                                                                          | 1047264 |
| 797 | 08/18/2020 | 914779 | PLASTIC DOOR ROLLER BOTTOM                                   |                                                                                                                          | 1047264 |
| 797 | 08/18/2020 | 914779 | Mechanic entered - Body Front_Door Operation Faulty front +  | R&R all floor pivot and rear door pivot bushes with new                                                                  | 1047264 |
| 797 | 08/17/2020 | 914116 |                                                              | Completed                                                                                                                | 1047171 |
| 797 | 08/17/2020 | 914116 |                                                              | CARRY OUT FIRE EXTINGUISHER TEST & TAG                                                                                   | 1047171 |
| 797 | 08/10/2020 | 912376 | Near side mirror rotates to inside of bus when going over t  | SECURED INTERIOR MIRROR                                                                                                  | 1046223 |
| 797 | 08/06/2020 | 911515 | Remove old A3 Poster and fit with You can no longer top up   | Completed                                                                                                                | 1046031 |
| 797 | 08/01/2020 | 910403 | Vandalism/ Graffiti Interior                                 | Remove graffiti from interior                                                                                            | 1045413 |
| 797 | 07/28/2020 | 909540 | Consumables                                                  |                                                                                                                          | 1045010 |
| 797 | 07/28/2020 | 909540 | Ops Entered - Fault - Elec and Light Flat Batteries - Route  | found alt not putting out charge replaced with second hand one from 730 checked ok                                       | 1044906 |
| 797 | 07/15/2020 | 906996 | Ops Entered - Fault - Body Drivers Seat Belt - Route: - Ar   | replace O/S/F wheel brush with secondhand                                                                                | 1043826 |
| 797 | 07/01/2020 | 896183 | TEST NIPPLE 16MM SCANIA 30G4500WABCO                         | incorrect quantity added to work order. correcting stock levels                                                          | 1042176 |
| 797 | 06/29/2020 | 898053 | REPAIR CRACKED OSR PASSENGER S                               | Creditor #:-VB-VOLGREN VOLGREN AUSTRALIA PTY LTD P/O #:CR276707 Receiving #:290519 Date :2020-07-02                      | 1042549 |
| 797 | 06/25/2020 | 903273 | Mechanic entered - Elec and Light Exterior Lights Rear top i | Replace rear upper indicators                                                                                            | 1041545 |
| 797 | 06/25/2020 | 903273 | LAMP INDICATOR LED WITH GROMMET                              |                                                                                                                          | 1041545 |
| 797 | 06/25/2020 | 903273 | Consumables                                                  |                                                                                                                          | 1041738 |
| 797 | 06/12/2020 | 900378 |                                                              | CARRY OUT A/C - B SERVICE AS PER CHECK LIST                                                                              | 1040096 |
| 797 | 06/12/2020 | 900378 | AIR CONDITIONING REPAIR                                      | Creditor #:-VB-COL004 COLD DRIVE PTY LTD P/O #:CR277329 Receiving #:289355 Date :2020-06-18 CARRY OUT A/C B SERVICE      | 1041029 |
| 797 | 06/12/2020 | 900378 |                                                              | CARRY OUT A/C - A SERVICE AS PER CHECK LIST - COLDDRIVE                                                                  | 1040096 |
| 797 | 06/10/2020 | 896281 | Body (None) rear number plate fadded                         |                                                                                                                          | 1040096 |

|     |            |        |                                                               |                                                                                                                                                                                                                                                                                                |         |
|-----|------------|--------|---------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------|
| 797 | 06/10/2020 | 896281 | Body (None) rear number plate fadded                          | R/R front and rear license plates replaced reverse buzzer                                                                                                                                                                                                                                      | 1040013 |
| 797 | 06/10/2020 | 896281 | BUZZER REVERSING 24V 102DB NR72602                            |                                                                                                                                                                                                                                                                                                | 1040013 |
| 797 | 06/10/2020 | 899571 | Fit A3 Poster in poster frame and fit decals as requested i   | Completed                                                                                                                                                                                                                                                                                      | 1040013 |
| 797 | 06/02/2020 | 898053 | Body (None) O/S/R seat post cracked                           | repaired by Volgren                                                                                                                                                                                                                                                                            | 1039917 |
| 797 | 06/02/2020 | 898074 | PERFORM CAMPAIGN 06/19 DRIVERS SECURITY SCREEN UPGRADE        | campaign done by Volgren                                                                                                                                                                                                                                                                       | 1039917 |
| 797 | 06/02/2020 | 898074 | PERFORM CAMPAIGN 06/19 DRIVERS SECURITY SCREEN UPGRADE        | Assisting                                                                                                                                                                                                                                                                                      | 1039917 |
| 797 | 06/01/2020 | 896183 | SWAY ( ANTI ROLL) BAR FRT SCA                                 | Creditor #.:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:CR276119 Receiving #:289677 Date :2020-06-23                                                                                                                                                                                              | 1041384 |
| 797 | 06/01/2020 | 896183 | TEST NIPPLE 16MM SCANIA 30G4                                  | Creditor #.:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:CR276119 Receiving #:289677 Date :2020-06-23                                                                                                                                                                                              | 1041384 |
| 797 | 06/01/2020 | 897903 | Elec and Light Exterior Lights O/S/R clearance light N/W      | replace LED clearance light                                                                                                                                                                                                                                                                    | 1039734 |
| 797 | 06/01/2020 | 897903 | LAMP LED SIDE MARKER RED/AMBER                                |                                                                                                                                                                                                                                                                                                | 1039734 |
| 797 | 06/01/2020 | 897903 | Consumables                                                   |                                                                                                                                                                                                                                                                                                | 1039917 |
| 797 | 05/28/2020 | 896183 | Suspension (None) front swaybar worn                          | replace front swaybar. bushes where good                                                                                                                                                                                                                                                       | 1039469 |
| 797 | 05/28/2020 | 896184 | Air System (None) test port at front of bus leaking           | replace test port                                                                                                                                                                                                                                                                              | 1039469 |
| 797 | 05/28/2020 | 896184 | VALVE TEST M16                                                |                                                                                                                                                                                                                                                                                                | 1039469 |
| 797 | 05/26/2020 | 896744 |                                                               | CARRY OUT CCTV - A SERVICE AS PER CHECK LIST Carried out CCTV service                                                                                                                                                                                                                          | 1039244 |
| 797 | 05/22/2020 | 895971 | Mechanic entered - Wheels and Tyres Wheel Nut Retension Ste   | RETORQUE STEER WHEELNUTS TO SPEC                                                                                                                                                                                                                                                               | 1039021 |
| 797 | 05/22/2020 | 896183 | Suspension (None) front swaybar worn                          |                                                                                                                                                                                                                                                                                                | 1039021 |
| 797 | 05/22/2020 | 896184 | Air System (None) test port at front of bus leaking           |                                                                                                                                                                                                                                                                                                | 1039021 |
| 797 | 05/20/2020 | 895570 |                                                               | VEHICLE SAFETY INSPECTION                                                                                                                                                                                                                                                                      | 1038924 |
| 797 | 05/20/2020 | 895570 |                                                               | TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS                                                                                                                                                                                                                                                   | 1038924 |
| 797 | 05/20/2020 | 895646 | Mechanic entered - Suspension Other o/s drive lowerwer torque | Remove and replace torque rod and airbag                                                                                                                                                                                                                                                       | 1038924 |
| 797 | 05/20/2020 | 895646 | AIRBAG DRIVE & TAG AXLE                                       |                                                                                                                                                                                                                                                                                                | 1038924 |
| 797 | 05/20/2020 | 895646 | TORQUE ROD RR LWR D/AXLE SCANIA 0489987                       |                                                                                                                                                                                                                                                                                                | 1038924 |
| 797 | 05/14/2020 | 894416 | Ops Entered - Fault - Body Front_Door Operation Faulty - I    | check and adjust front door                                                                                                                                                                                                                                                                    | 1038285 |
| 797 | 05/11/2020 | 893684 | Accident - MIRROR N/S broken off accident No: 50757           | replace N/S mirror arm & repair wiring. test all ok                                                                                                                                                                                                                                            | 1037902 |
| 797 | 05/11/2020 | 893684 | MIRROR ARM LONG LH 19mm                                       |                                                                                                                                                                                                                                                                                                | 1037902 |
| 797 | 05/05/2020 | 892410 | Body Front_Door Operation Faulty doesn't open unless butt     | CHECKED FRONT AND REAR DOOR OPERATION DID NOT FAULT                                                                                                                                                                                                                                            | 1037217 |
| 797 | 04/15/2020 | 888543 | A4 notification to be printed off in colour laminated and     | campaign complete                                                                                                                                                                                                                                                                              | 1035221 |
| 797 | 03/27/2020 | 884628 |                                                               | Completed in Feb                                                                                                                                                                                                                                                                               | 1033079 |
| 797 | 03/27/2020 | 884628 |                                                               | CARRY OUT FIRE EXTINGUISHER TEST & TAG                                                                                                                                                                                                                                                         | 1033079 |
| 797 | 03/24/2020 | 882943 | Remove old poster and fit Reduce Your Risk of Coronavirus     | Campaign Completed                                                                                                                                                                                                                                                                             | 1032585 |
| 797 | 03/24/2020 | 883080 | Tape off front Seats of All Route and Rail Buses with spec    | carried out                                                                                                                                                                                                                                                                                    | 1032585 |
| 797 | 03/19/2020 | 881611 | adjusting knob/handle on steering wheel underside is loose    | refitted steering column adjuster in correct position                                                                                                                                                                                                                                          | 1032185 |
| 797 | 03/19/2020 | 879350 | Elec and Light Exterior Lights. rear step light N/W           | replace rear door exterior step light                                                                                                                                                                                                                                                          | 1032185 |
| 797 | 03/19/2020 | 879350 | Consumables                                                   |                                                                                                                                                                                                                                                                                                | 1032373 |
| 797 | 03/19/2020 | 879350 | Consumables                                                   |                                                                                                                                                                                                                                                                                                | 1032373 |
| 797 | 03/18/2020 | 879350 | LIGHT FLUORESCENT TUBE EXTER                                  | Creditor #.:VB-VOLGREN VOLGREN AUSTRALIA PTY LTD P/O #:CR270642 Receiving #:282253 Date :2020-03-19 Bus 797                                                                                                                                                                                    | 1032185 |
| 797 | 03/17/2020 | 880871 | Mechanic entered - Wipers and Washers Washers Not Working     | replaced washer bottle pump                                                                                                                                                                                                                                                                    | 1031681 |
| 797 | 03/17/2020 | 880871 | PUMP WASHER PUMP 24 VOLT                                      |                                                                                                                                                                                                                                                                                                | 1031681 |
| 797 | 03/17/2020 | 880872 | Mechanic entered - Engine Other fuel leak from primer pump    | replaced primer pump                                                                                                                                                                                                                                                                           | 1031681 |
| 797 | 03/17/2020 | 880872 | PUMP. FUEL PRIMER VOLVO B10BLE 3826073 A0000908850            |                                                                                                                                                                                                                                                                                                | 1031681 |
| 797 | 03/17/2020 | 880838 | Body Passenger Seat Torn. wheel chair seat                    | checked all wheelcahir ramp seats o.k at time of inspection                                                                                                                                                                                                                                    | 1031681 |
| 797 | 03/17/2020 | 880822 |                                                               | CARRY OUT B SERVICE AS PER CHECK LIST                                                                                                                                                                                                                                                          | 1031681 |
| 797 | 03/17/2020 | 880822 |                                                               | Assisting B Service completed                                                                                                                                                                                                                                                                  | 1031681 |
| 797 | 03/17/2020 | 880822 | KIT O-RING OIL SPINNER FILTER SCANIA ABOVE ENG #6203050       |                                                                                                                                                                                                                                                                                                | 1031681 |
| 797 | 03/17/2020 | 880822 | FILTER ZF TRANS ECOMAT (1193281-1)(4139 298 038 01)           |                                                                                                                                                                                                                                                                                                | 1031681 |
| 797 | 03/17/2020 | 880822 | FILTER FUEL FILTER SCANIA SR4 (1372444 )                      |                                                                                                                                                                                                                                                                                                | 1031681 |
| 797 | 03/17/2020 | 880822 | Oil Filter SCANIA S4 & K                                      |                                                                                                                                                                                                                                                                                                | 1031681 |
| 797 | 03/17/2020 | 880822 | Consumables                                                   |                                                                                                                                                                                                                                                                                                | 1031920 |
| 797 | 03/17/2020 | 880822 | Consumables                                                   |                                                                                                                                                                                                                                                                                                | 1031920 |
| 797 | 03/17/2020 | 880822 | Consumables                                                   |                                                                                                                                                                                                                                                                                                | 1031920 |
| 797 | 03/17/2020 | 880822 | Consumables                                                   |                                                                                                                                                                                                                                                                                                | 1031920 |
| 797 | 03/17/2020 | 880822 | Consumables                                                   |                                                                                                                                                                                                                                                                                                | 1031920 |
| 797 | 03/17/2020 | 880822 | Consumables                                                   |                                                                                                                                                                                                                                                                                                | 1031920 |
| 797 | 03/17/2020 | 880822 | Consumables                                                   |                                                                                                                                                                                                                                                                                                | 1031920 |
| 797 | 03/17/2020 | 880822 | Consumables                                                   |                                                                                                                                                                                                                                                                                                | 1031920 |
| 797 | 03/10/2020 | 879350 | Elec and Light Exterior Lights. rear step light N/W           |                                                                                                                                                                                                                                                                                                | 1030922 |
| 797 | 02/22/2020 | 875987 | Body (None). smoking stickers missing                         | rit new stickers                                                                                                                                                                                                                                                                               | 1029206 |
| 797 | 02/22/2020 | 875987 | Consumables                                                   |                                                                                                                                                                                                                                                                                                | 1029418 |
| 797 | 02/22/2020 | 875987 | Consumables                                                   |                                                                                                                                                                                                                                                                                                | 1029418 |
| 797 | 02/21/2020 | 875157 | TYRE 275/70R22.5 RECAP                                        |                                                                                                                                                                                                                                                                                                | 1029206 |
| 797 | 02/21/2020 | 875157 | TYRE 295/80R22.5 NEW                                          |                                                                                                                                                                                                                                                                                                | 1029206 |
| 797 | 02/21/2020 | 875157 | Consumables                                                   |                                                                                                                                                                                                                                                                                                | 1029418 |
| 797 | 02/21/2020 | 875424 | EDGE SENSITIVE EDGE DOOR SWITCH DW40                          | INCORRECT PART NUMBER                                                                                                                                                                                                                                                                          | 1029206 |
| 797 | 02/21/2020 | 875424 | SWITCH BISCHER DOOR SWITCH                                    | FIX ABOVE LINE                                                                                                                                                                                                                                                                                 | 1029206 |
| 797 | 02/21/2020 | 875424 | Consumables                                                   |                                                                                                                                                                                                                                                                                                | 1029418 |
| 797 | 02/21/2020 | 875424 | Consumables                                                   |                                                                                                                                                                                                                                                                                                | 1029418 |
| 797 | 02/20/2020 | 874856 | MOUNT ENGINE SCANIA 1475868                                   | Creditor #.:VB-MUL002 MULTISPARES CROYDON P/O #:CR269110 Receiving #:280212 Date :2020-02-21 SUPPLY ENGINE MOUNTS                                                                                                                                                                              | 1029206 |
| 797 | 02/20/2020 | 875440 | Mechanic entered - Wheels and Tyres Wheel Nut Retension Ret   | RETORQUE REAR WHEELNUTS TO SPEC                                                                                                                                                                                                                                                                | 1029019 |
| 797 | 02/20/2020 | 875440 | Mechanic entered - Wheels and Tyres Wheel Nut Retension Ret   | Assisting                                                                                                                                                                                                                                                                                      | 1029019 |
| 797 | 02/20/2020 | 875440 | Consumables                                                   |                                                                                                                                                                                                                                                                                                | 1029206 |
| 797 | 02/20/2020 | 875716 | Body Windows Side rear emergency exit window etched           | wrong bus                                                                                                                                                                                                                                                                                      | 1029019 |
| 797 | 02/20/2020 | 875716 | Consumables                                                   |                                                                                                                                                                                                                                                                                                | 1029206 |
| 797 | 02/20/2020 | 875716 | Consumables                                                   |                                                                                                                                                                                                                                                                                                | 1029206 |
| 797 | 02/19/2020 | 875422 | Mechanic entered - Body Other emergency exit hammer broken    | replace hammer                                                                                                                                                                                                                                                                                 | 1029019 |
| 797 | 02/19/2020 | 875422 | EMERGENCY HAMMER KIT W/WIRE                                   |                                                                                                                                                                                                                                                                                                | 1029019 |
| 797 | 02/19/2020 | 875424 | Mechanic entered - Body Front_Door Operation Faulty Front do  | pop rivets holding door ram all loose or broken removed door ram plates and hardware drilled out all old pop rivets get new steel rivets and secured plates in place put ram and hardware back in and test adjust as nessary rear leaf sensitive edge not working so fit new unit adjusted ok. | 1029019 |
| 797 | 02/19/2020 | 875424 | EDGE SENSITIVE EDGE DOOR SWITCH DW40                          |                                                                                                                                                                                                                                                                                                | 1029019 |
| 797 | 02/19/2020 | 875422 | Consumables                                                   |                                                                                                                                                                                                                                                                                                | 1029019 |
| 797 | 02/19/2020 | 875422 | Consumables                                                   |                                                                                                                                                                                                                                                                                                | 1029019 |
| 797 | 02/19/2020 | 875075 | SEAL REAR AXLE CAP SCANIA 1                                   | Creditor #.:VB-MUL002 MULTISPARES CROYDON P/O #:CR269190 Receiving #:279968 Date :2020-02-19 hub cap seal                                                                                                                                                                                      | 1029019 |
| 797 | 02/18/2020 | 874856 |                                                               | VEHICLE SAFETY INSPECTION                                                                                                                                                                                                                                                                      | 1028850 |
| 797 | 02/18/2020 | 874856 |                                                               | TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS                                                                                                                                                                                                                                                   | 1028850 |
| 797 | 02/18/2020 | 875157 | Mechanic entered - Wheels and Tyres Worn Pos 1 3 4 worn       | fitted replacement tyres and tensioned wheel nuts                                                                                                                                                                                                                                              | 1028850 |
| 797 | 02/18/2020 | 875157 | VALVE EXTENSION-130mm Metal type                              |                                                                                                                                                                                                                                                                                                | 1028850 |
| 797 | 02/18/2020 | 875157 | TYRE 295/80R22.5 RECAP                                        |                                                                                                                                                                                                                                                                                                | 1028850 |
| 797 | 02/18/2020 | 875157 | TYRE 275/70R22.5 RECAP                                        |                                                                                                                                                                                                                                                                                                | 1028850 |
| 797 | 02/18/2020 | 874928 | Mechanic entered - Suspension Soft front sway bar mount bush  | replaced front sway bar bushes                                                                                                                                                                                                                                                                 | 1028850 |
| 797 | 02/18/2020 | 874928 | BUSH FRT SWAY BAR SCANIA K230UB 0469081 1919010 40MM          |                                                                                                                                                                                                                                                                                                | 1028850 |
| 797 | 02/18/2020 | 875135 | Mechanic entered - Brakes Other Rear brake rotors worn        | Fitted new rotors and brake linings tensioned new wheel nuts                                                                                                                                                                                                                                   | 1028850 |
| 797 | 02/18/2020 | 875075 | Mechanic entered - Brakes Other Front brake discs and pads u  |                                                                                                                                                                                                                                                                                                | 1028850 |
| 797 | 02/18/2020 | 875075 | BRAKE DISC FRT SCANIA K230UB 1858351 1402272                  |                                                                                                                                                                                                                                                                                                | 1028850 |
| 797 | 02/18/2020 | 875135 | SEAL REAR AXLE CAP SCANIA 1765061 120310                      |                                                                                                                                                                                                                                                                                                | 1028850 |

|     |            |        |                                                              |                                                                                                                                                                             |  |         |
|-----|------------|--------|--------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|---------|
| 797 | 02/18/2020 | 875135 | DISC PAD SET SCANIA                                          |                                                                                                                                                                             |  | 1028850 |
| 797 | 02/18/2020 | 875135 | SEAL RR HUB OUTER SCANIA K230UB 1409890                      |                                                                                                                                                                             |  | 1028850 |
| 797 | 02/18/2020 | 875135 | SEAL RR HUB INNER SCANIA K230UB 1740992                      |                                                                                                                                                                             |  | 1028850 |
| 797 | 02/18/2020 | 875075 | DISC PAD SET SCANIA                                          |                                                                                                                                                                             |  | 1028850 |
| 797 | 02/18/2020 | 875075 | SENSOR WEAR SENSOR KIT BLOCK TYPE-AXLE SET L94UB (1794440)   | refitted calipers and wheels tensioned wheel nuts                                                                                                                           |  | 1028850 |
| 797 | 02/18/2020 | 875075 | Mechanic entered - Brakes Other Front brake discs and pads u |                                                                                                                                                                             |  | 1028850 |
| 797 | 02/18/2020 | 875135 | BRAKE DISC FRT SCANIA K230UB 1858351 1402272                 |                                                                                                                                                                             |  | 1028850 |
| 797 | 02/18/2020 | 875135 | SENSOR WEAR SENSOR KIT BLOCK TYPE-AXLE SET L94UB (1794440)   |                                                                                                                                                                             |  | 1028850 |
| 797 | 02/18/2020 | 875075 | Mechanic entered - Brakes Other Front brake discs and pads u | fit front caliper booster new pads and wheel all tentioned to spec                                                                                                          |  | 1028850 |
| 797 | 02/18/2020 | 875135 | Mechanic entered - Brakes Other Rear brake rotors worn       | remove booster pads caliper hub and rotor clean all parts and pack new grease in bearings and hubs fit hub and rotor caliper pads booster and wheels. all tentioned to spec |  | 1028850 |
| 797 | 02/18/2020 | 872274 | CARRY OUT ACCIDENT REPAIRS AS                                | Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS SERVICE P/O #:CR268298 Receiving #:279879 Date :2020-02-19                                                                       |  | 1029019 |
| 797 | 02/07/2020 | 872392 | Mechanic entered - Wheels and Tyres Wheel Nut Retension ODO  | RETORQUE NSR WHEELNUTS                                                                                                                                                      |  | 1027485 |
| 797 | 02/07/2020 | 872392 | Mechanic entered - Wheels and Tyres Wheel Nut Retension ODO  | Assisting                                                                                                                                                                   |  | 1027485 |
| 797 | 02/07/2020 | 872392 | Consumables                                                  |                                                                                                                                                                             |  | 1027754 |
| 797 | 02/06/2020 | 872274 | REPLACE REAR BUMPER ASSEMBLY AS PER ACCIDENT #50105          | REPAIRED ONSITE MICHAEL VALKRANOFF                                                                                                                                          |  | 1027485 |
| 797 | 02/06/2020 | 872274 | REPLACE REAR BUMPER ASSEMBLY AS PER ACCIDENT #50105          | Assisting                                                                                                                                                                   |  | 1027485 |
| 797 | 02/01/2020 | 871005 | Drv entered - A/C Heating Not Cooling                        | check a/c all ok. no driver boost function in bus                                                                                                                           |  | 1026820 |
| 797 | 02/01/2020 | 870499 | Accident #50105 - Rear N/s bumper bar corner. UNREPORTED AC  |                                                                                                                                                                             |  | 1026820 |
| 797 | 02/01/2020 | 870499 | Accident #50105 - Rear N/s bumper bar corner. UNREPORTED AC  | Assisting                                                                                                                                                                   |  | 1026820 |
| 797 | 01/31/2020 | 870698 | PERFORM CAMPAIGN 01/20 POSITIONING OF 2020 PTV FARES & PRIO  | campaign completed                                                                                                                                                          |  | 1026820 |
| 797 | 01/01/2020 | 859708 | DIFFUSER LIGHT COVER ELLAMP                                  | Creditor #:VB-VOLGREN VOLGREN AUSTRALIA PTY LTD P/O #:CR264194 Receiving #:277969 Date :2020-01-24 supply light diffuser cover                                              |  | 1026025 |
| 797 | 01/01/2020 | 859708 | Consumables                                                  |                                                                                                                                                                             |  | 1023213 |
| 797 | 12/13/2019 | 861667 |                                                              | TRANSMISSION CHECK AS PER CHECK LIST comleted as per checklist                                                                                                              |  | 1021273 |
| 797 | 12/10/2019 | 860817 | Ops Entered - Fault - Desto Signs - part of display numbers  | checked dest controller and dest signs both seem to be working fine                                                                                                         |  | 1020791 |
| 797 | 12/09/2019 | 860774 | Ops Entered - Fault - A/C Heating Not Cooling - there is no  | no boost fan fitted. A/C is cold just has small air vents.                                                                                                                  |  | 1020791 |
| 797 | 12/06/2019 | 859708 | Body- internal light cover is missing exposing wires         |                                                                                                                                                                             |  | 1020445 |
| 797 | 12/06/2019 | 859708 | Service                                                      | replace saloon light cover                                                                                                                                                  |  | 1020445 |
| 797 | 12/02/2019 | 858167 |                                                              | CHECK ENGINE FOR LEAKS NONE VISABLE O.K                                                                                                                                     |  | 1019878 |
| 797 | 12/02/2019 | 858485 | A3 Poster Frame Adhesive Decal Campaign please remove old    |                                                                                                                                                                             |  | 1019878 |
| 797 | 12/01/2019 | 849349 | DIRECT PURCHASE - ENGINE                                     | Creditor #:VB-BEA001 BEARING WHOLESALERS P/O #:CR260722 Receiving #:275318 Date :2019-12-18 b85 belts                                                                       |  | 1021897 |
| 797 | 12/01/2019 | 857964 | DIRECT PURCHASE - ELECTRICAL                                 | Creditor #:VB-BWE001 BWERE ELECTRICS PTY LTD P/O #:CR263686 Receiving #:274428 Date :2019-12-09 6 MONTH SERVICE                                                             |  | 1020791 |
| 797 | 11/29/2019 | 857964 | CCTV: 6 month service                                        | Assisting - completed by bwere 28.11.19                                                                                                                                     |  | 1019878 |
| 797 | 11/29/2019 | 857964 | CCTV: 6 month service                                        | completed by bwere 28.11.19                                                                                                                                                 |  | 1019878 |
| 797 | 11/26/2019 | 857131 |                                                              | VEHICLE SAFETY INSPECTION                                                                                                                                                   |  | 1019357 |
| 797 | 11/26/2019 | 857131 |                                                              | TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS                                                                                                                                |  | 1019357 |
| 797 | 11/26/2019 | 857131 |                                                              | ANNUAL SAFETY INSPECTION SERIAL # ____K199892____WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLESAFETY INSPECTION LINE TIME ON THE W/O TO 0.25                         |  | 1019357 |
| 797 | 11/26/2019 | 857131 | DIRECT PURCHASE - BUS INSPECTI                               | Creditor #:VB-FLE001 FLEETCHECK BUS PTY LTD P/O #:CR263379 Receiving #:273391 Date :2019-11-27 carry out A.S.I                                                              |  | 1019563 |
| 797 | 11/25/2019 | 856795 | Wheels and Tyres Wheel Nut Retension N/S/R                   | retension N/S/R tyre                                                                                                                                                        |  | 1019294 |
| 797 | 11/25/2019 | 856795 | Consumables                                                  |                                                                                                                                                                             |  | 1019357 |
| 797 | 11/22/2019 | 856330 | Mechanic entered - Wheels and Tyres Wheel Nut Retension NSR  | RETORQUE NSR WHEEL NUTS TO SPEC                                                                                                                                             |  | 1018990 |
| 797 | 11/22/2019 | 856330 | Mechanic entered - Wheels and Tyres Wheel Nut Retension NSR  | Assisting                                                                                                                                                                   |  | 1018990 |
| 797 | 11/22/2019 | 856330 | Consumables                                                  |                                                                                                                                                                             |  | 1019294 |
| 797 | 11/21/2019 | 856155 | Mechanic entered - Wheels and Tyres Flat or Leaking NSRO tyr | R/R NSRO with runout tensioned wheel nuts                                                                                                                                   |  | 1018990 |
| 797 | 11/21/2019 | 856155 | Consumables                                                  |                                                                                                                                                                             |  | 1019082 |
| 797 | 11/13/2019 | 854304 | Body Windows Rear                                            | secured rear window                                                                                                                                                         |  | 1017864 |
| 797 | 11/08/2019 | 853408 | Ops Entered - Fault - Suspension Soft - Route: 679 - Baysw   | secure front level valve sensor rod                                                                                                                                         |  | 1017301 |
| 797 | 11/01/2019 | 851093 | DIRECT PURCHASE - ELECTRICAL                                 | Creditor #:VB-LONSDALE LONSDALE ST AUTO ELECTRICS P/O #:CR261367 Receiving #:272176 Date :2019-11-13 CARRY OUT FIRE SAFETY INSPECTION                                       |  | 1017864 |
| 797 | 11/01/2019 | 852012 |                                                              | CARRY OUT CCTV - A SERVICE AS PER CHECK LIST                                                                                                                                |  | 1016529 |
| 797 | 11/01/2019 | 852012 |                                                              | not required                                                                                                                                                                |  | 1016529 |
| 797 | 10/31/2019 | 851573 | Consumables                                                  |                                                                                                                                                                             |  | 1016529 |
| 797 | 10/31/2019 | 851573 | Drv entered - Body Windows Front                             | check destination operation working ok                                                                                                                                      |  | 1016016 |
| 797 | 10/30/2019 | 851564 | Consumables                                                  |                                                                                                                                                                             |  | 1016344 |
| 797 | 10/30/2019 | 851564 | Drv entered - Elec and Light Electric Mirrors Faulty         | adjust & test all ok                                                                                                                                                        |  | 1016016 |
| 797 | 10/29/2019 | 851093 |                                                              | CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST                                                                                                                          |  | 1015801 |
| 797 | 10/28/2019 | 849328 | V STAY ASSEMBLY SCANIA L94UAB                                |                                                                                                                                                                             |  | 1015623 |
| 797 | 10/28/2019 | 849328 | REPLACE V ROD ASSEMBLY                                       | REPLACED                                                                                                                                                                    |  | 1015623 |
| 797 | 10/25/2019 | 850397 | Consumables                                                  |                                                                                                                                                                             |  | 1015623 |
| 797 | 10/25/2019 | 850397 | Mechanic entered - Elec and Light Exterior Lights O/S head I | replace head light globe                                                                                                                                                    |  | 1015250 |
| 797 | 10/23/2019 | 847533 | DIRECT PURCHASE - VANDALISM                                  | Creditor #:VB-GLA010 GLASSPROTECH MELBOURNE P/O #:CR259971 Receiving #:271002 Date :2019-10-25 Replace Anti Graffiti Film                                                   |  | 1015466 |
| 797 | 10/23/2019 | 849977 | Consumables                                                  |                                                                                                                                                                             |  | 1015250 |
| 797 | 10/23/2019 | 849977 | Mechanic entered - Body Other N/S 4th row seat base cracked  | remove seat disconnect battery and clean area with grinder ready for welding welded crack put seat back on cleaned work area                                                |  | 1015250 |
| 797 | 10/23/2019 | 849841 | LED RED STOP/ TAIL LAMP (41197)                              |                                                                                                                                                                             |  | 1015250 |
| 797 | 10/23/2019 | 849841 | VALVE CLIPPARD DOOR OPEN/CLOSE (11916-2) BUTTON              |                                                                                                                                                                             |  | 1015250 |
| 797 | 10/23/2019 | 849841 | Mechanic entered - Air System Air_Leak Front Front external  |                                                                                                                                                                             |  | 1015250 |
| 797 | 10/21/2019 | 849328 |                                                              | PRE ANNUAL SAFETY INSPECTION CHECK carry out pre annual inspection as per service sheet                                                                                     |  | 1014799 |
| 797 | 10/21/2019 | 849328 |                                                              | Asist mick to complete pre rsi replairs and wash roadtest                                                                                                                   |  | 1014799 |
| 797 | 10/21/2019 | 849328 |                                                              | CARRY OUT CCTV - B SERVICE AS PER CHECK LIST                                                                                                                                |  | 1014799 |
| 797 | 10/21/2019 | 849439 | BUSH FRT SWAY BAR SCANIA K230UB 0469081 1919010 40MM         |                                                                                                                                                                             |  | 1014799 |
| 797 | 10/21/2019 | 849439 | Mechanic entered - Suspension Noisy front d bushes worn      | remove and replace front d bushes                                                                                                                                           |  | 1014799 |
| 797 | 10/21/2019 | 849349 | Engine Belts_Loose Noisy Missing                             | replace A/C belts                                                                                                                                                           |  | 1014799 |
| 797 | 10/11/2019 | 847533 | Vandalism: Replace Anti Graffiti Film - R2                   | Completed                                                                                                                                                                   |  | 1013381 |
| 797 | 10/02/2019 | 845445 | Service                                                      | remove trans & bell housing from engine. reseal & refit bell housing. fit new rear main seal. refit trans                                                                   |  | 1012295 |
| 797 | 10/02/2019 | 845445 | RECTIFY ENGINE OIL LEAK                                      | Replaced trans from day shift. R/R front timing cover diaphragm and baffle plate. R/R turbo oil drain gasket                                                                |  | 1012295 |
| 797 | 10/02/2019 | 845445 | DIRECT PURCHASE - ENGINE                                     | Creditor #:VB-MUL002 MULTISPARES CROYDON P/O #:CR259157 Receiving #:268750 Date :2019-10-02 SUPPLY REAR MAIN SEAL                                                           |  | 1012295 |
| 797 | 10/02/2019 | 845445 | RECTIFY ENGINE OIL LEAK                                      |                                                                                                                                                                             |  | 1012295 |
| 797 | 10/01/2019 | 845277 | Consumables                                                  |                                                                                                                                                                             |  | 1012295 |
| 797 | 10/01/2019 | 845277 | Consumables                                                  |                                                                                                                                                                             |  | 1012295 |
| 797 | 10/01/2019 | 845277 | Oil Filter SCANIA S4 & K                                     |                                                                                                                                                                             |  | 1012219 |
| 797 | 10/01/2019 | 845277 | TENSIONER SR4 FLATBACK BELT 1859654 knx 1503113              |                                                                                                                                                                             |  | 1012219 |
| 797 | 10/01/2019 | 845277 | IDLER PULLEY SCANIA ARTIC (No Groove Plastic) (1428940)      |                                                                                                                                                                             |  | 1012219 |
| 797 | 10/01/2019 | 845277 | FILTER FUEL FILTER SCANIA SR4 (1372444 )                     |                                                                                                                                                                             |  | 1012219 |
| 797 | 10/01/2019 | 845277 | FILTER ZF TRANS ECOMAT (1193281-1)(4139 298 038 01)          |                                                                                                                                                                             |  | 1012219 |
| 797 | 10/01/2019 | 845277 | KIT O-RING OIL SPINNER FILTER SCANIA ABOVE ENG #6203050      |                                                                                                                                                                             |  | 1012219 |
| 797 | 10/01/2019 | 845277 |                                                              | CARRY OUT B SERVICE AS PER CHECK LIST complete                                                                                                                              |  | 1012219 |
| 797 | 09/07/2019 | 840997 | Consumables                                                  |                                                                                                                                                                             |  | 1009271 |
| 797 | 09/07/2019 | 840997 | Mechanic entered - Wheels and Tyres Wheel Nut Retension O/S/ | Asist darren to complete retention                                                                                                                                          |  | 1009104 |
| 797 | 09/06/2019 | 840704 | DIRECT PURCHASE - VANDALISM                                  | Creditor #:VB-RP RP AUTO UPHOLSTERY PTY LTD P/O #:CR257398 Receiving #:266848 Date :2019-09-09 3x seat bases repair                                                         |  | 1009271 |
| 797 | 09/06/2019 | 840704 | Vandalism (None) 3x seats torn                               | removed & refit repaired seat bases x3                                                                                                                                      |  | 1009104 |
| 797 | 09/06/2019 | 840804 | CONSUMABLE - BODYWORK                                        | Creditor #:VB-BAYBOL BAYSWATER BOLTS P/O #:CR257452 Receiving #:266843 Date :2019-09-09 nut                                                                                 |  | 1009271 |
| 797 | 09/06/2019 | 840804 | CONSUMABLE - BODYWORK                                        | Creditor #:VB-BAYBOL BAYSWATER BOLTS P/O #:CR257452 Receiving #:266843 Date :2019-09-09 bolt                                                                                |  | 1009271 |
| 797 | 09/06/2019 | 840804 | FITTING                                                      |                                                                                                                                                                             |  | 1009104 |
| 797 | 09/06/2019 | 840804 | FITTING ELBOW                                                |                                                                                                                                                                             |  | 1009104 |
| 797 | 09/06/2019 | 840804 | AIRBAG REAR SCANIA K230 / K270 2024287 2024290               |                                                                                                                                                                             |  | 1009104 |

|     |            |        |                                                              |                                                                                                                                                              |         |
|-----|------------|--------|--------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------|---------|
| 797 | 09/06/2019 | 840804 | AIRBAG REAR SCANIA K230 / K270 2024287 2024290               |                                                                                                                                                              | 1009104 |
| 797 | 09/06/2019 | 840804 | TORQUE ROD FRONT UPPER SCANIA K230 (1438475)                 |                                                                                                                                                              | 1009104 |
| 797 | 09/06/2019 | 840804 | TORQUE ROD FRONT UPPER SCANIA K230 (1438475)                 |                                                                                                                                                              | 1009104 |
| 797 | 09/06/2019 | 840804 | Service                                                      | replace front upper torque rods & steering drag link                                                                                                         | 1009104 |
| 797 | 09/06/2019 | 840804 | Service                                                      | fitted 2 x rear air bags & repair air leak                                                                                                                   | 1009104 |
| 797 | 09/06/2019 | 840804 | Suspension (None) upper front torque rod bushes worn. Wron   | Fitted drag link and 2x upper torque rods. Fitted 2x Airbags.                                                                                                | 1009104 |
| 797 | 09/06/2019 | 840804 | Suspension (None) upper front torque rod bushes worn. Wro    |                                                                                                                                                              | 1009104 |
| 797 | 09/05/2019 | 840107 | DIRECT PURCHASE - STEERING                                   | Creditor #:VB-MUL002 MULTISPARES CROYDON P/O #:CR257307 Receiving #:266638 Date :2019-09-05 supply draglink 40L2227ZF                                        | 1009104 |
| 797 | 09/05/2019 | 840107 |                                                              | Finished safety. *Faults noted on work order*                                                                                                                | 1008909 |
| 797 | 09/04/2019 | 840107 | TYRE 295/80R22.5 RECAP                                       |                                                                                                                                                              | 1008909 |
| 797 | 09/04/2019 | 840107 |                                                              | Assisting                                                                                                                                                    | 1008909 |
| 797 | 09/04/2019 | 840107 |                                                              | VEHICLE SAFETY INSPECTION                                                                                                                                    | 1008909 |
| 797 | 09/04/2019 | 840107 |                                                              | TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS                                                                                                                 | 1008909 |
| 797 | 09/04/2019 | 840192 | PULLEY IDLER SCANIA (1514087)                                |                                                                                                                                                              | 1008909 |
| 797 | 09/04/2019 | 840192 | Mechanic entered - Engine Noisy or Rattling                  | Fitted new idler pulley                                                                                                                                      | 1008909 |
| 797 | 08/29/2019 | 838972 | Consumables                                                  |                                                                                                                                                              | 1008749 |
| 797 | 08/29/2019 | 838972 | LIGHT SIDE INDICATOR L/H                                     |                                                                                                                                                              | 1008353 |
| 797 | 08/29/2019 | 838972 | Drv entered - Elec and Light Indicators Not Working          | replace N/S indicator assy                                                                                                                                   | 1008353 |
| 797 | 08/28/2019 | 838648 |                                                              | CARRY OUT FIRE EXTINGUISHER TEST & TAG                                                                                                                       | 1008113 |
| 797 | 08/28/2019 | 838648 |                                                              | Completed                                                                                                                                                    | 1008113 |
| 797 | 08/15/2019 | 835636 | Consumables                                                  |                                                                                                                                                              | 1008749 |
| 797 | 08/15/2019 | 835636 | Ops Entered - Fault - Body Windows Front - Route: 755a - Kn  | Can't replicate fault. Mirror is tight                                                                                                                       | 1006499 |
| 797 | 07/31/2019 | 832337 | Vandalism: Replace Anti Graffiti Film - R2                   | Completed By Glass Protect                                                                                                                                   | 1004340 |
| 797 | 07/25/2019 | 831203 | Consumables                                                  |                                                                                                                                                              | 1003714 |
| 797 | 07/25/2019 | 831203 | Drv entered - Elec and Light Next Stop Button                | repair wire to n/s next stop button                                                                                                                          | 1003453 |
| 797 | 07/23/2019 | 830397 | Consumables                                                  |                                                                                                                                                              | 1003453 |
| 797 | 07/23/2019 | 830397 | Light for speedo not working. Cant see at night. Back in dep | replaced dash lights                                                                                                                                         | 1003030 |
| 797 | 07/09/2019 | 827757 | A/C Heating Noisy roof fans noisy                            | test heater. found to be working ok                                                                                                                          | 1001327 |
| 797 | 07/05/2019 | 826747 | AIR CONDITIONING REPAIR                                      | Creditor #:VB-COL004 COLD DRIVE PTY LTD P/O #:CR252190 Receiving #:261486 Date :2019-07-11 FIT NEW A.C CONTROL PANEL AND CHECK HEATER AND DEMISTER OPERATION | 1001698 |
| 797 | 07/05/2019 | 826747 | Ops Entered - Fault - Heat & Demist - Route: 677 - Lilydal   | REPAIRED BY COLDRIIVE                                                                                                                                        | 1000854 |
| 797 | 07/04/2019 | 826747 | Direct Purchase - ELECTRICAL                                 | Creditor #:VB-VOLGREN VOLGREN AUSTRALIA PTY LTD P/O #:CR252107 Receiving #:261001 Date :2019-07-04 P/N 11648 (under seat heater assy Aurora)                 | 1000854 |
| 797 | 07/04/2019 | 826747 | A/C Heating Demister Not Heating                             | REPAIRED BY COLDRIIVE                                                                                                                                        | 1000854 |
| 797 | 07/01/2019 | 822631 | AIR CONDITIONING REPAIR                                      | Creditor #:VB-COL004 COLD DRIVE PTY LTD P/O #:CR250241 Receiving #:261869 Date :2019-07-15 CARRY OUT A/C A SERVICE. FIT NEW A/C OMPRESSOR CLUTCH             | 1002322 |
| 797 | 06/26/2019 | 825272 | AIR CONDITIONING REPAIR                                      | Creditor #:VB-COL004 COLD DRIVE PTY LTD P/O #:CR251360 Receiving #:260622 Date :2019-06-30 RECTIFY DEMISTER NOT HEATING                                      | 1000504 |
| 797 | 06/26/2019 | 825272 | Demister is Not Heating.                                     |                                                                                                                                                              | 1000126 |
| 797 | 06/21/2019 | 824278 |                                                              | TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS                                                                                                                 | 999456  |
| 797 | 06/21/2019 | 824278 |                                                              | VEHICLE SAFETY INSPECTION completed all ok                                                                                                                   | 999456  |
| 797 | 06/21/2019 | 824385 | Consumables                                                  |                                                                                                                                                              | 999844  |
| 797 | 06/21/2019 | 824385 | Mechanic entered - Body Other lights n/w doors loose repl    | Fitted new air regulator for door/s.                                                                                                                         | 999748  |
| 797 | 06/21/2019 | 824385 | OIL COLLECTOR AIR DRIER -SCANIA 40G0006                      |                                                                                                                                                              | 999748  |
| 797 | 06/21/2019 | 824385 | Mirror Electric Heated suit Volgren (17498/SER)              |                                                                                                                                                              | 999456  |
| 797 | 06/21/2019 | 824385 | Mechanic entered - Body Other lights n/w doors loose repl    | REPLACED STEP LIGHT AND 2 INSIDE LIGHTS AND ALSO REPLACED O/S MIRROR PLUS DOOR REGULATOR NEEDS REPLACING COMPLETE ALL DEFECTS ALSO REPLACED AIR DRYER        | 999456  |
| 797 | 06/21/2019 | 824385 | Direct Purchase - BODYWORK                                   | Creditor #:VB-VOLGREN VOLGREN AUSTRALIA PTY LTD P/O #:CR250982 Receiving #:259771 Date :2019-06-21 P/N 42151 (air regulator)                                 | 999748  |
| 797 | 06/21/2019 | 824385 | Direct Purchase - BODYWORK                                   | Creditor #:VB-VOLGREN VOLGREN AUSTRALIA PTY LTD P/O #:CR250982 Receiving #:259771 Date :2019-06-21 P/N 11368 (plunger valve)                                 | 999748  |
| 797 | 06/21/2019 | 824385 | LAMP CLEAR FRT INDICATOR WRAP-AROUND                         |                                                                                                                                                              | 999456  |
| 797 | 06/21/2019 | 824385 | Mechanic entered - Body Other lights n/w doors loose repl    |                                                                                                                                                              | 999456  |
| 797 | 06/17/2019 | 823312 | Consumables                                                  |                                                                                                                                                              | 999057  |
| 797 | 06/17/2019 | 823312 | Ops Entered - Fault - Desto Signs - Route: - Arrive Croyd    | reboot system test all ok                                                                                                                                    | 998895  |
| 797 | 06/14/2019 | 823050 | Consumables                                                  |                                                                                                                                                              | 998895  |
| 797 | 06/14/2019 | 823050 | MIRROR ARM LONG LH 19mm                                      |                                                                                                                                                              | 998673  |
| 797 | 06/14/2019 | 823050 | Mirror Electric Heated suit Volgren (17498/SER)              | replace mirror arm & head                                                                                                                                    | 998673  |
| 797 | 06/14/2019 | 823050 | Body (None). broken N/S mirror                               | replace mirror arm & head                                                                                                                                    | 998673  |
| 797 | 06/13/2019 | 822631 | Drv entered - A/C Heating Not Heating                        | repaired by colddrive                                                                                                                                        | 998370  |
| 797 | 06/13/2019 | 822631 |                                                              | CARRY OUT A/C - A SERVICE AS PER CHECK LIST. done by colddrive                                                                                               | 998370  |
| 797 | 06/01/2019 | 819785 | DIRECT PURCHASE - ENGINE                                     | Creditor #:VB-ECOAST EASTCOAST TRUCK & BUS SERVICE P/O #:CR249203R Receiving #:259821 Date :2019-06-24 Part Number: 40A8509 Gasket Rocket Cover              | 999844  |
| 797 | 05/30/2019 | 820165 | dash lights m/w                                              | replace 4x dash lights                                                                                                                                       | 996865  |
| 797 | 05/30/2019 | 820165 | Air leaking and not building                                 | fit new air compressor                                                                                                                                       | 996865  |
| 797 | 05/30/2019 | 820165 | Air leaking and not building                                 | remove air compressor                                                                                                                                        | 996865  |
| 797 | 05/30/2019 | 820165 | DIRECT PURCHASE - BRAKES                                     | Creditor #:VB-MUL002 MULTISPARES CROYDON P/O #:CR249345 Receiving #:257908 Date :2019-05-30 P/N 40A9405 (bolt compressor crank gear)                         | 996865  |
| 797 | 05/30/2019 | 820165 | DIRECT PURCHASE - BRAKES                                     | Creditor #:VB-MUL002 MULTISPARES CROYDON P/O #:CR249345 Receiving #:257908 Date :2019-05-30 P/N 40A5709 (o-ring flywheel insp plate)                         | 996865  |
| 797 | 05/30/2019 | 820165 | DIRECT PURCHASE - BRAKES                                     | Creditor #:VB-MUL002 MULTISPARES CROYDON P/O #:CR249345 Receiving #:257908 Date :2019-05-30 P/N 40A9403 (o-ring 11mm ID)                                     | 996865  |
| 797 | 05/30/2019 | 820165 | DIRECT PURCHASE - BRAKES                                     | Creditor #:VB-MUL002 MULTISPARES CROYDON P/O #:CR249345 Receiving #:257908 Date :2019-05-30 P/N 40A9106KNORR (air compressor)                                | 996865  |
| 797 | 05/29/2019 | 819785 | DIRECT PURCHASE - ENGINE                                     | Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:CR249225 Receiving #:257873 Date :2019-05-30 P/N 1493179 (hose)                                          | 996865  |
| 797 | 05/29/2019 | 819785 | DIRECT PURCHASE - ENGINE                                     | Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:CR249225 Receiving #:257873 Date :2019-05-30 P/N 1496295 (hose)                                          | 996865  |
| 797 | 05/29/2019 | 819785 | DIRECT PURCHASE - ENGINE                                     | Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:CR249225 Receiving #:257873 Date :2019-05-30 P/N 1358837 (pressure monitor)                              | 996865  |
| 797 | 05/29/2019 | 819785 | DIRECT PURCHASE - ENGINE                                     | Creditor #:VB-SCANIA SCANIA AUSTRALIA PTY LTD P/O #:CR249225 Receiving #:257873 Date :2019-05-30 P/N 1343144 (union assy)                                    | 996865  |
| 797 | 05/29/2019 | 819785 | DIRECT PURCHASE - ENGINE                                     | Creditor #:VB-MUL002 MULTISPARES CROYDON P/O #:CR249203 Receiving #:257752 Date :2019-05-29 P/N 40N1590X140 (hose intercooler)                               | 996865  |
| 797 | 05/29/2019 | 819785 | DIRECT PURCHASE - ENGINE                                     | Creditor #:VB-MUL002 MULTISPARES CROYDON P/O #:CR249203 Receiving #:257752 Date :2019-05-29 P/N 40A8509 (gasket rocker cover)                                | 996865  |
| 797 | 05/29/2019 | 819785 | LAMP CLEAR FRT INDICATOR WRAP-AROUND                         |                                                                                                                                                              | 996743  |
| 797 | 05/29/2019 | 819785 |                                                              | SERVICE MOISTURE EJECTOR also replaced front indicator                                                                                                       | 996743  |
| 797 | 05/29/2019 | 819842 | DIRECT PURCHASE - ELECTRICAL                                 | CARRY OUT TUNE-UP SERVICE AS PER CHECK LIST                                                                                                                  | 996743  |
| 797 | 05/29/2019 | 819842 | Fault#:36582 - Ops Entered - Fault - Breakdown Warning Ligh  | Creditor #:VB-MUL002 MULTISPARES CROYDON P/O #:CR249205 Receiving #:257750 Date :2019-05-29 P/N 94V0003 (regulator Bosch)                                    | 996865  |
| 797 | 05/29/2019 | 819794 | Consumables                                                  | remove and replace alternator regulator                                                                                                                      | 996743  |
| 797 | 05/29/2019 | 819794 | Mechanic entered - Body Front_Door Operation Faulty buttons  | replaced                                                                                                                                                     | 996865  |
| 797 | 05/29/2019 | 819794 | Direct Purchase - ELECTRICAL                                 | Creditor #:VB-VOLGREN VOLGREN AUSTRALIA PTY LTD P/O #:CR249213 Receiving #:257878 Date :2019-05-30 P/N 33895 (button brass door valve Clippard)              | 996865  |
| 797 | 05/28/2019 | 819608 | Consumables                                                  |                                                                                                                                                              | 996865  |
| 797 | 05/28/2019 | 819608 | Ops Entered - Fault - Elec and Light Warning Light On Dash   | reset test o.k                                                                                                                                               | 996743  |
| 797 | 05/17/2019 | 817479 | CCTV 6 MONTH SERVICE                                         | DELETE DOUBLE ENTRY                                                                                                                                          | 994871  |
| 797 | 05/16/2019 | 817416 | CCTV (None) 6 mths service                                   | done                                                                                                                                                         | 994871  |
| 797 | 05/16/2019 | 817416 | DIRECT PURCHASE - ELECTRICAL                                 | Creditor #:VB-BWE001 BWERE ELECTRICS PTY LTD P/O #:CR248254 Receiving #:257175 Date :2019-05-22 6 mths service                                               | 995989  |
| 797 | 05/13/2019 | 816114 | Direct Purchase - ELECTRICAL                                 | Creditor #:VB-VOLGREN VOLGREN AUSTRALIA PTY LTD P/O #:CR247957 Receiving #:257182 Date :2019-05-22 P/N 11468 lamp door fluorescent                           | 995989  |
| 797 | 05/10/2019 | 816114 | MIRROR HEAD LH 200X430 2 PCE FLAT/CONVEX                     |                                                                                                                                                              | 993999  |
| 797 | 05/10/2019 | 816114 | Mechanic entered - Accident - MIRROR                         | replace ns mirror                                                                                                                                            | 993999  |
| 797 | 05/07/2019 | 814984 | Please remove all old poster and fit MYKI has gone mobil     | done                                                                                                                                                         | 993430  |
| 797 | 05/02/2019 | 813704 | 12.11.18 BWERE - CCTV 6 MONTH SERVICE @ LILYDALE             |                                                                                                                                                              | 992905  |
| 797 | 05/01/2019 | 806797 | Consumables                                                  |                                                                                                                                                              | 992905  |
| 797 | 05/01/2019 | 806797 | DIRECT PURCHASE - ELECTRICAL                                 | Creditor #:VB-TOTAUT TOTAL AUTO ELECTRICAL & MECHANICAL P/O #:CR244530 Receiving #:256540 Date :2019-05-15 rectify short in transmission wiring as required  | 994871  |
| 797 | 05/01/2019 | 813704 | CCTV 6 MONTH SERVICE - 12.11.1                               | Creditor #:JB-BWE001 BWERE ELECTRICS PTY LTD P/O #:V246974 Receiving #:255494 Date :2019-05-06                                                               | 993247  |
| 797 | 04/30/2019 | 812759 | Consumables                                                  |                                                                                                                                                              | 992730  |
| 797 | 04/30/2019 | 812759 | Consumables                                                  |                                                                                                                                                              | 992730  |
| 797 | 04/30/2019 | 812759 | FILTER P/STEER SCANIA VOLVO MERCEDES (349619-7) (2192404)    |                                                                                                                                                              | 992720  |
| 797 | 04/30/2019 | 812759 | FILTER FUEL FILTER SCANIA SR4 (1393640)                      |                                                                                                                                                              | 992720  |

|     |            |        |                                                              |        |
|-----|------------|--------|--------------------------------------------------------------|--------|
| 797 | 04/30/2019 | 812759 | FILTER DRYER SCANIA/VOLVO (1375997) (3090288-6) (49G8704W)   | 992720 |
| 797 | 04/30/2019 | 812759 | FILTER FUEL FILTER SCANIA SR4 (1393640)                      | 992720 |
| 797 | 04/30/2019 | 812759 | KIT O-RING OIL SPINNER FILTER SCANIA ABOVE ENG #6203050      | 992720 |
| 797 | 04/30/2019 | 812759 | FILTER ZF TRANS ECOMAT (1193281-1)(4139 298 038 01)          | 992720 |
| 797 | 04/30/2019 | 812759 | Oil Filter SC S4 & K                                         | 992720 |
| 797 | 04/30/2019 | 812759 |                                                              | 992720 |
| 797 | 04/30/2019 | 812759 | Consumables                                                  | 992730 |
| 797 | 04/30/2019 | 812759 | Consumables                                                  | 992730 |
| 797 | 04/30/2019 | 812759 |                                                              | 992720 |
| 797 | 04/16/2019 | 810505 |                                                              | 991406 |
| 797 | 04/16/2019 | 810793 | Consumables                                                  | 991625 |
| 797 | 04/16/2019 | 810793 | Drv entered - Elec and Light Horn                            | 991406 |
| 797 | 04/16/2019 | 810720 |                                                              | 991406 |
| 797 | 04/05/2019 | 808670 | Disregard it was entered by mistake.                         | 990270 |
| 797 | 04/04/2019 | 808205 | DIRECT PURCHASE - CHASSIS                                    | 990166 |
| 797 | 04/04/2019 | 808205 | ASSY WIPER BLADE ASSY 1000mm (TRP1000 is Refill)             | 989984 |
| 797 | 04/04/2019 | 808205 | BUSH SWAY BAR FRONT SCANIA SR4(0469081) 1919010(40mm ID)     | 989984 |
| 797 | 04/04/2019 | 808205 |                                                              | 989984 |
| 797 | 04/04/2019 | 808205 |                                                              | 989984 |
| 797 | 04/01/2019 | 804033 | Direct Purchase - ELECTRICAL                                 | 990166 |
| 797 | 03/28/2019 | 806797 | Fault#:36414 - Ops Entered - Fault - Breakdown Not Starting  | 989551 |
| 797 | 03/28/2019 | 806813 | Mechanic entered - Breakdown Gearbox Fault                   | 989551 |
| 797 | 03/28/2019 | 806797 | Consumables                                                  | 989551 |
| 797 | 03/28/2019 | 806797 | DIRECT PURCHASE - TOWING                                     | 989551 |
| 797 | 03/28/2019 | 806797 | BUS BLOWING FUSE WHEN PUT GEAR                               | 989551 |
| 797 | 03/15/2019 | 804033 | Breakdown#:36359 - Ops Entered - Breakdown - Breakdown Low E | 988792 |
| 797 | 03/15/2019 | 803437 | Mechanic entered - Breakdown Other anderson street lilydale  | 988792 |
| 797 | 03/14/2019 | 803437 | Mechanic entered - Breakdown Other anderson street lilydale  | 988792 |
| 797 | 03/13/2019 | 804033 | DIRECT PURCHASE - TOWING                                     | 989031 |
| 797 | 03/13/2019 | 803437 | Mechanic entered - Breakdown Other anderson street lilydale  | 988792 |
| 797 | 03/12/2019 | 803043 | Consumables                                                  | 988792 |
| 797 | 03/12/2019 | 803043 | Wheels and Tyres Wheel Nut Retension N/S/F @ 988252          | 988596 |
| 797 | 03/12/2019 | 803043 | Wheels and Tyres Wheel Nut Retension N/S/F @ 988252          | 988596 |
| 797 | 03/09/2019 | 802865 | Consumables                                                  | 988252 |
| 797 | 03/09/2019 | 802865 | Mechanic entered - Wheels and Tyres Worn N/s/f 2mm on outer  | 988252 |
| 797 | 03/09/2019 | 802865 | TYRE 295/80R22.5 NEW                                         | 988252 |
| 797 | 03/02/2019 | 801356 | Consumables                                                  | 986839 |
| 797 | 03/02/2019 | 801356 | Body (None) fire extingsher needs replacing                  | 986516 |
| 797 | 02/21/2019 | 794581 | DIRECT PURCHASE - MECHANICAL G                               | 985909 |
| 797 | 02/20/2019 | 799233 | Direct Purchase - BODYWORK                                   | 984953 |
| 797 | 02/20/2019 | 799233 | Accident # 485443 - NEAR SIDE MID                            | 984953 |
| 797 | 02/20/2019 | 799233 | Accident # 485443 - NEAR SIDE MID                            | 984953 |
| 797 | 02/08/2019 | 794581 | Service                                                      | 983018 |
| 797 | 02/07/2019 | 796321 | Consumables                                                  | 983018 |
| 797 | 02/07/2019 | 796321 | Elec and Light Horn                                          | 982804 |
| 797 | 02/06/2019 | 794581 | Consumables                                                  | 982804 |
| 797 | 02/06/2019 | 794581 | Direct Purchase - MECHANICAL                                 | 982528 |
| 797 | 02/02/2019 | 794577 | Consumables                                                  | 981931 |
| 797 | 02/02/2019 | 794577 | Drv entered - Elec and Light Flat Batteries                  | 981931 |
| 797 | 02/02/2019 | 794577 | BATTERY 800CCAPOS ON LHS                                     | 981931 |
| 797 | 02/02/2019 | 794577 | Mechanic entered - Elec and Light Flat Batteries             | 981931 |
| 797 | 02/01/2019 | 794581 | BUSH SWAY BAR                                                | 981673 |
| 797 | 02/01/2019 | 794581 | Suspension (None) REAR S/WAY BAR D BUSHES WORN REFER TO      | 981931 |
| 797 | 02/01/2019 | 795050 | Breakdown#:36176 - Ops Entered - Breakdown - Breakdown Not S | 981673 |
| 797 | 02/01/2019 | 794581 | Air System Air_Leak Rear RECTIFY AIR AT DRYER REFER TO RS    | 981931 |
| 797 | 01/31/2019 | 794577 | Consumables                                                  | 981673 |
| 797 | 01/31/2019 | 794577 | Mechanic entered - Elec and Light Flat Batteries             | 981142 |
| 797 | 01/30/2019 | 792925 | Breakdown#:36171 - Ops Entered - Breakdown - Breakdown Not S | 981142 |
| 797 | 01/25/2019 | 793666 | STARTER SCANIA 0571420 IM038                                 | 980880 |
| 797 | 01/25/2019 | 793666 | Ops Entered - Fault - Engine Low Power - Route: 677 - Chirn  | 980880 |
| 797 | 01/25/2019 | 793742 | Consumables                                                  | 980880 |
| 797 | 01/25/2019 | 793742 | Mechanic entered - Elec and Light Flat Batteries starter mot | 980880 |
| 797 | 01/24/2019 | 793399 | Consumables                                                  | 980880 |
| 797 | 01/24/2019 | 793399 | Mechanic entered - Elec and Light Flat Batteries             | 980567 |
| 797 | 01/23/2019 | 792878 | DIRECT PURCHASE - BUS INSPECTI                               | 981142 |
| 797 | 01/23/2019 | 793299 | Please remove old 2018 fare decals and fit new 2019 fare de  | 980567 |
| 797 | 01/22/2019 | 792878 |                                                              | 980567 |
| 797 | 01/22/2019 | 792878 |                                                              | 980567 |
| 797 | 01/22/2019 | 792878 |                                                              | 980567 |
| 797 | 01/22/2019 | 792923 | Consumables                                                  | 980567 |
| 797 | 01/22/2019 | 792925 | Consumables                                                  | 980567 |
| 797 | 01/22/2019 | 792925 | Mechanic entered - Body Other LIST OF BODY FAULTS            | 980567 |
| 797 | 01/22/2019 | 792923 | Body wash and check over whole engine for leaks for RSI.     | 980567 |
| 797 | 01/18/2019 | 791947 | Consumables                                                  | 980336 |
| 797 | 01/18/2019 | 791947 | Elec and Light led lights playing up on o/s/r and saloon     | 980192 |
| 797 | 01/18/2019 | 791947 | LIGHT INDICATOR LIGHT LED (NARVA)                            | 980192 |
| 797 | 01/18/2019 | 791947 | LAMP FLUORESCENT TUBE 36 Watt                                | 980192 |
| 797 | 01/17/2019 | 791850 | IDLER PULLEY SCANIA ARTIC (No Groove Plastic) (1428940)      | 979996 |
| 797 | 01/17/2019 | 791850 | Mechanic entered - Engine Belts_Loose Noisy Missing o/s idle | 979996 |
| 797 | 01/17/2019 | 791866 | Consumables                                                  | 980192 |
| 797 | 01/17/2019 | 791947 | Elec and Light led lights playing up on o/s/r and saloon     | 979996 |
| 797 | 01/17/2019 | 791947 | LED FRONT POSITION MARKER LIGHT                              | 979996 |
| 797 | 01/17/2019 | 791866 | Mechanic entered - Elec and Light Other engine hatch micro s | 979996 |
| 797 | 01/17/2019 | 789204 | Consumables                                                  | 980192 |
| 797 | 01/17/2019 | 789203 | Consumables                                                  | 980192 |
| 797 | 01/17/2019 | 789204 | Acc# 47017                                                   | 980192 |
| 797 | 01/17/2019 | 789204 | Accident number 46315                                        | 980192 |
| 797 | 01/17/2019 | 789204 | Repair drivers blind                                         | 980192 |
| 797 | 01/17/2019 | 789204 | Repair wheel chair ramp as req                               | 980192 |
| 797 | 01/17/2019 | 789203 | Rust in rear step leading to s                               | 980192 |
| 797 | 01/17/2019 | 791734 | Consumables                                                  | 980192 |
| 797 | 01/17/2019 | 791734 | Consumables                                                  | 980192 |
| 797 | 01/17/2019 | 791734 | FILTER ZF TRANS ECOMAT (1193281-1)(4139 298 038 01)          | 979996 |

|     |            |        |                                                              |                                                                                                                                                          |                                                          |        |
|-----|------------|--------|--------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------|--------|
| 797 | 01/17/2019 | 791734 | FILTER KIT K230 MINOR                                        |                                                                                                                                                          |                                                          | 979996 |
| 797 | 01/17/2019 | 791734 |                                                              | CARRY OUT B SERVICE AS PER CHECK LIST                                                                                                                    | move buses in yard to access bus carryout B service      | 979996 |
| 797 | 01/04/2019 | 789005 |                                                              |                                                                                                                                                          | took over from phil and finished job finished pre annual | 979772 |
| 797 | 01/04/2019 | 789216 | Consumables                                                  |                                                                                                                                                          |                                                          | 979772 |
| 797 | 01/04/2019 | 789204 | Body drivers sun blind faulty doesnt open close smoothly.    | ECTB CARRY OUT REPAIRS                                                                                                                                   | 17/01/19                                                 | 979772 |
| 797 | 01/04/2019 | 789204 | Mechanic entered - Body Other                                | send to ectb                                                                                                                                             | 4/01/19                                                  | 979772 |
| 797 | 01/04/2019 | 789204 | Body n/s/r seat and n/s/f seat damage require repair.        | ECTB CARRY OUT REPAIRS                                                                                                                                   | 17/01/19                                                 | 979772 |
| 797 | 01/04/2019 | 789203 | Body rust in rear step leading to back seats requires urgent | send to ectb                                                                                                                                             | ECTB CARRY OUT REPAIRS 17/01/19                          | 979772 |
| 797 | 01/04/2019 | 789216 | Body (None) REAR STEP VINYL COVER SPLIT                      | double up defect has been sent to ectb for repair                                                                                                        |                                                          | 979772 |
| 797 | 01/04/2019 | 789204 | Accident#:46315 - Ops Entered - Accident - To Be Advised (a  | ECTB CARRY OUT REPAIRS                                                                                                                                   | 17/01/19                                                 | 979772 |
| 797 | 01/04/2019 | 789204 | Accident#:47017 - Ops Entered - Accident - Bus is hit by 3r  | ECTB CARRY OUT REPAIRS                                                                                                                                   | 17/01/19                                                 | 979772 |
| 797 | 01/03/2019 | 789005 |                                                              |                                                                                                                                                          |                                                          | 979772 |
| 797 | 01/03/2019 | 789005 |                                                              | TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS                                                                                                             |                                                          | 979772 |
| 797 | 01/03/2019 | 789005 |                                                              | VEHICLE SAFETY INSPECTION                                                                                                                                |                                                          | 979772 |
| 797 | 01/03/2019 | 789005 |                                                              | PRE ANNUAL SAFETY INSPECTION CHECK                                                                                                                       |                                                          | 979772 |
| 797 | 01/03/2019 | 788970 | Drv entered - A/C Heating Not Cooling                        | checked all ok by gary                                                                                                                                   |                                                          | 979772 |
| 797 | 12/21/2018 | 787319 | Mechanic entered - Elec and Light Exterior Lights top left f | replace both parker globes                                                                                                                               |                                                          | 977844 |
| 797 | 12/14/2018 | 786004 | Mechanic entered - Elec and Light Flat Batteries             | jump start. check charge rate. all ok                                                                                                                    |                                                          | 976473 |
| 797 | 12/14/2018 | 786004 | Consumables                                                  |                                                                                                                                                          |                                                          | 976779 |
| 797 | 12/14/2018 | 786004 | MIRROR L/H 440mm LONG SPLIT BM04                             |                                                                                                                                                          |                                                          | 976473 |
| 797 | 12/14/2018 | 785792 | Direct Purchase - ELECTRICAL                                 | Creditor #:#B-LON002 LONSDALE ST AUTO ELECTRICS P/O #:#V236876 Receiving #:#245655 Date :2018-12-27                                                      | CARRY OUT FIRE SAFETY                                    | 978666 |
| 797 | 12/13/2018 | 785792 |                                                              | LONSDALE ELEC CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST                                                                                         |                                                          | 976257 |
| 797 | 12/11/2018 | 785109 | GLOBE 24V 70W H1                                             |                                                                                                                                                          |                                                          | 975740 |
| 797 | 12/11/2018 | 785109 | Mechanic entered - Elec and Light Exterior Lights N/S/F head | Replaced globe all good                                                                                                                                  |                                                          | 975740 |
| 797 | 12/07/2018 | 784582 | AIR CONDITIONING REPAIR                                      | Creditor #:#B-COL004 COLD DRIVE PTY LTD P/O #:#V237114 Receiving #:#245607 Date :2018-12-24                                                              | 797 Air Conditioner Repair                               | 978316 |
| 797 | 12/07/2018 | 784582 | A/C Heating Not Cooling                                      | GARY FROM FROM COLD DRIVE CARRY OUT REPAIRS                                                                                                              |                                                          | 975245 |
| 797 | 12/07/2018 | 784599 | LED DOWNLIGHT ROUND ENT DOOR                                 |                                                                                                                                                          |                                                          | 975245 |
| 797 | 12/07/2018 | 784599 | Mechanic entered - A/C Heating Other A/c duct above rear doo | Ducting removed and repaired. New LED light installed to replace broken existing. Ducting refitted and lights and emergency door open button checked ok. |                                                          | 975245 |
| 797 | 11/12/2018 | 739044 | Direct Purchase - ELECTRICAL                                 | Creditor #:#B-LON002 LONSDALE ST AUTO ELECTRICS P/O #:#V234171 Receiving #:#243180 Date :2018-11-27                                                      | Wire up USB                                              | 973097 |
| 797 | 11/09/2018 | 778485 | Consumables                                                  |                                                                                                                                                          |                                                          | 970320 |
| 797 | 11/09/2018 | 778485 | Consumables                                                  |                                                                                                                                                          |                                                          | 970320 |
| 797 | 11/09/2018 | 778485 | DIRECT PURCHASE - GLASS                                      | Creditor #:#B-ALP003 ALPHA BUS GLASS PTY LTD P/O #:#V233997 Receiving #:#241786 Date :2018-11-12                                                         | SUPPPPLY AND REPLACE SCREEN                              | 970320 |
| 797 | 11/09/2018 | 778485 | Mechanic entered - Body Windows Front                        | GARY FROM ALPHA GLASS CARRY OUT REPAIRS                                                                                                                  | cracked window n/s/f                                     | 969763 |
| 797 | 11/08/2018 | 778136 | Consumables                                                  |                                                                                                                                                          |                                                          | 969958 |
| 797 | 11/08/2018 | 778136 | Mechanic entered - Wheels and Tyres Wheel Nut Retension rete | carry out N/S/R wheel retension.                                                                                                                         | 969763km                                                 | 969763 |
| 797 | 11/07/2018 | 778012 | Service                                                      | VEHICLE SAFETY INSPECTION assist                                                                                                                         |                                                          | 969500 |
| 797 | 11/07/2018 | 778012 |                                                              | TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS                                                                                                             |                                                          | 969500 |
| 797 | 11/07/2018 | 778012 |                                                              | VEHICLE SAFETY INSPECTION completed safety and defects                                                                                                   |                                                          | 969500 |
| 797 | 11/07/2018 | 778079 | Consumables                                                  |                                                                                                                                                          |                                                          | 969763 |
| 797 | 11/07/2018 | 778079 | TYRE 295/80R22.5 NEW                                         |                                                                                                                                                          |                                                          | 969500 |
| 797 | 11/07/2018 | 778079 | Mechanic entered - Wheels and Tyres Worn n/s/r inner 3.5mm   | fitted new tyres on n/s/r/                                                                                                                               |                                                          | 969500 |
| 797 | 11/07/2018 | 778042 | Drv entered - A/C Heating Not Cooling                        |                                                                                                                                                          |                                                          | 969500 |
| 797 | 11/07/2018 | 778042 | Drv entered - A/C Heating Not Cooling                        | GARY FROM COLD DRIVE CARRY OUT REPAIRS                                                                                                                   |                                                          | 969500 |
| 797 | 11/07/2018 | 739044 | PERFORM CAMPAIGN 11/18 VENTURA BUS MINDER INSTALLATION       | LONSDALE ELEC CARRY OUT REWIRE                                                                                                                           |                                                          | 969763 |
| 797 | 10/16/2018 | 773577 | VALVE FOOTBRAKE SR3 & SR4 SC 0469052                         |                                                                                                                                                          |                                                          | 965206 |
| 797 | 10/16/2018 | 773577 | Drv entered - Brakes Foot_Brakes Pulling                     | remove and replace foot valve. remove and replace air line and hardware. Drill out plate and refit. to get to ajustment srew. and test drive bus .       |                                                          | 965206 |
| 797 | 10/16/2018 | 773577 | Mechanic entered - Brakes Foot_Brakes Leaking Air Foot valve | Checked ok                                                                                                                                               |                                                          | 965206 |
| 797 | 10/15/2018 | 773342 | REMOVE AND REPLACE A3 POSTER TO ALL ROUTE VEHICLES           | COMPLETED                                                                                                                                                |                                                          | 965012 |
| 797 | 10/08/2018 | 771510 | Consumables                                                  |                                                                                                                                                          |                                                          | 963684 |
| 797 | 10/08/2018 | 771510 | Mechanic entered - Elec and Light Flat Batteries             | jump start & check charge rate. all ok                                                                                                                   |                                                          | 963014 |
| 797 | 10/07/2018 | 713850 | Air System Air leaks infront of diff RSI 011886              | Checked for air leaks infront of diff and checked for leaks after wash and oradtest- no leaks found                                                      |                                                          | 963014 |
| 797 | 10/06/2018 | 713850 | Consumables                                                  |                                                                                                                                                          |                                                          | 963298 |
| 797 | 10/06/2018 | 713850 | Body Wheel chair ramp soft                                   | Remove ramp and fit new ramp to bus and secure                                                                                                           |                                                          | 963014 |
| 797 | 10/04/2018 | 770389 | Consumables                                                  |                                                                                                                                                          |                                                          | 963014 |
| 797 | 10/04/2018 | 770389 | Consumables                                                  |                                                                                                                                                          |                                                          | 963014 |
| 797 | 10/04/2018 | 770389 | Body Wheel Chair Ramp soft - needs to go to ECTB             | finished fitting ramp                                                                                                                                    |                                                          | 963014 |
| 797 | 10/02/2018 | 770389 | Body Wheel Chair Ramp soft - needs to go to ECTB             | removed old ramp and fitted new ramp                                                                                                                     |                                                          | 963014 |
| 797 | 09/27/2018 | 713850 | Engine Oil leaks RSI 011886                                  | Wash engine and trans roadtest and check for leaks- no leaks present                                                                                     |                                                          | 963014 |
| 797 | 09/27/2018 | 713850 | Consumables                                                  |                                                                                                                                                          |                                                          | 963014 |
| 797 | 09/27/2018 | 713850 | Consumables                                                  |                                                                                                                                                          |                                                          | 963014 |
| 797 | 09/27/2018 | 713850 | Body Wheel Chair Ramp soft                                   |                                                                                                                                                          |                                                          | 963014 |
| 797 | 09/20/2018 | 767915 | Service                                                      | TRANSMISSION CHECK AS PER CHECK LIST                                                                                                                     |                                                          | 961693 |
| 797 | 09/20/2018 | 768007 | Mechanic entered - Engine Other full under wash              | full under body wash done to this bus                                                                                                                    |                                                          | 961693 |
| 797 | 09/20/2018 | 767915 | PERFORM CAMPAIGN 26/18 CHASSIS WASH & UNDER CARRIAGE CHECK   |                                                                                                                                                          |                                                          | 961693 |
| 797 | 09/20/2018 | 767625 | Consumables                                                  |                                                                                                                                                          |                                                          | 962004 |
| 797 | 09/20/2018 | 767625 | Consumables                                                  |                                                                                                                                                          |                                                          | 962004 |
| 797 | 09/20/2018 | 767625 | Consumables                                                  |                                                                                                                                                          |                                                          | 962004 |
| 797 | 09/20/2018 | 767625 | Consumables                                                  |                                                                                                                                                          |                                                          | 962004 |
| 797 | 09/20/2018 | 767625 |                                                              | carried out b service                                                                                                                                    |                                                          | 961693 |
| 797 | 09/20/2018 | 767625 | FILTER AIR FILTER OUTER VOLVO B7R (8149064 21834199          |                                                                                                                                                          |                                                          | 961693 |
| 797 | 09/20/2018 | 767625 | FILTER ZF TRANS ECOMAT (1193281-1)(4139 298 038 01)          |                                                                                                                                                          |                                                          | 961693 |
| 797 | 09/20/2018 | 767625 | FILTER FUEL FILTER SCANIA SR4 (1372444 )                     |                                                                                                                                                          |                                                          | 961693 |
| 797 | 09/20/2018 | 767625 | Oil Filter SC S4 & K                                         |                                                                                                                                                          |                                                          | 961693 |
| 797 | 09/19/2018 | 767625 |                                                              |                                                                                                                                                          |                                                          | 961693 |
| 797 | 09/19/2018 | 767625 |                                                              | CARRY OUT B SERVICE AS PER CHECK LIST                                                                                                                    | finish off sevice and clean up mess. See scope of work.  | 961693 |
| 797 | 09/19/2018 | 767625 | FILTER AIR FILTER (395773) AF25066                           |                                                                                                                                                          |                                                          | 961693 |
| 797 | 09/19/2018 | 767625 | Oil Filter SC S4 & K                                         |                                                                                                                                                          |                                                          | 961693 |
| 797 | 09/19/2018 | 767625 | FILTER FUEL FILTER SCANIA SR4 (1372444 )                     |                                                                                                                                                          |                                                          | 961693 |
| 797 | 09/19/2018 | 767625 | KIT O-RING OIL SPINNER FILTER SCANIA ABOVE ENG #6203050      |                                                                                                                                                          |                                                          | 961693 |
| 797 | 09/19/2018 | 767625 | FILTER ZF TRANS ECOMAT (1193281-1)(4139 298 038 01)          |                                                                                                                                                          |                                                          | 961693 |
| 797 | 09/12/2018 | 765750 | CARRY OUT FIRE EXTINGUISHER TEST & TAG BY ATS                | CARRY OUT FIRE EXTINGUISHER TEST & TAG                                                                                                                   |                                                          | 960498 |
| 797 | 09/01/2018 | 763407 |                                                              | TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS                                                                                                             |                                                          | 958847 |
| 797 | 09/01/2018 | 763407 |                                                              | VEHICLE SAFETY INSPECTION                                                                                                                                |                                                          | 958847 |
| 797 | 09/01/2018 | 763423 | PERFORM CAMPAIGN 17/18 INTERNAL BUS NUMBERS                  | Decals fitted                                                                                                                                            |                                                          | 958847 |
| 797 | 08/25/2018 | 761796 | Consumables                                                  |                                                                                                                                                          |                                                          | 957572 |
| 797 | 08/25/2018 | 761796 | INDICATOR STALK SCANIA SERIES 4 (1402448)                    |                                                                                                                                                          |                                                          | 957306 |
| 797 | 08/25/2018 | 761796 | Drv entered - Elec and Light Indicators Not Working          | Checked indicator operation. Does not self cance. Fitted new switch                                                                                      |                                                          | 957306 |
| 797 | 08/23/2018 | 761115 | Consumables                                                  |                                                                                                                                                          |                                                          | 957306 |
| 797 | 08/23/2018 | 761115 | Service                                                      | Replaced ignistion swtch                                                                                                                                 |                                                          | 957024 |
| 797 | 08/22/2018 | 761115 | Mechanic entered - Elec and Light Exterior Lights ignition   | WOP                                                                                                                                                      |                                                          | 956670 |
| 797 | 08/16/2018 | 759614 | Consumables                                                  |                                                                                                                                                          |                                                          | 955791 |
| 797 | 08/16/2018 | 759614 | Drv entered - Elec and Light Indicators Not Working indicat  | Checked stalk. Staying on by itself. Self cancelling working also.                                                                                       |                                                          | 955457 |
| 797 | 08/16/2018 | 759425 | Direct Purchase - BODYWORK                                   | Creditor #:#B-EAS003 EASTCOAST TRUCK & BUS SERVICE P/O #:#V227150 Receiving #:#234810 Date :2018-08-17                                                   | weld repair & refit rear bar (accident #47697)           | 955457 |

|     |            |        |                                                              |                                                                                                                                                                                                                                                                                                                     |  |        |
|-----|------------|--------|--------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|--------|
| 797 | 08/15/2018 | 759317 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                     |  | 955457 |
| 797 | 08/15/2018 | 759317 | Mechanic entered - Elec and Light Exterior Lights right hea  | Secured wiring for head light.                                                                                                                                                                                                                                                                                      |  | 955296 |
| 797 | 08/15/2018 | 759425 | Accident#:47697 - Ops Entered - Accident - Bus Hitting Objec | removed rear bar repaired broken bus frame and refitted bar                                                                                                                                                                                                                                                         |  | 955296 |
| 797 | 08/15/2018 | 759425 | Accident#:47697 - Ops Entered - Accident - Bus Hitting Obj   | bus sent Knox to carry out repairs                                                                                                                                                                                                                                                                                  |  | 955296 |
| 797 | 08/13/2018 | 758796 | Wheels and Tyres Wheel Nut Retension O/S/R @ 954464          | Retension Wheel Nuts OSR                                                                                                                                                                                                                                                                                            |  | 954464 |
| 797 | 08/13/2018 | 758796 | Wheels and Tyres Wheel Nut Retension O/S/R @ 954464          | Retension Wheel Nuts OSR                                                                                                                                                                                                                                                                                            |  | 954464 |
| 797 | 08/11/2018 | 758766 | VALVE FLEXIBLE TYRE EXTENSION VALVE 180mm LONG               |                                                                                                                                                                                                                                                                                                                     |  | 954464 |
| 797 | 08/11/2018 | 758766 | TYRE 295/80R22.5 RECAP                                       |                                                                                                                                                                                                                                                                                                                     |  | 954464 |
| 797 | 08/11/2018 | 758766 | Mechanic entered - Wheels and Tyres Worn o/s/r outer 3mm     | Replaced O/S/R tyres using new caps replaced valve extension & sanded rim matting surfaces                                                                                                                                                                                                                          |  | 954464 |
| 797 | 08/03/2018 | 756943 | Mechanic entered - Wheels and Tyres Wheel Nut Retension ret  | Retensioned N/S/R wheel nuts.                                                                                                                                                                                                                                                                                       |  | 951909 |
| 797 | 08/03/2018 | 756943 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                     |  | 952756 |
| 797 | 08/03/2018 | 756943 | Elec and Light Interior Lights only 2 lights work            | Replaced blown saloon lights.                                                                                                                                                                                                                                                                                       |  | 951909 |
| 797 | 08/02/2018 | 756814 | Wheels and Tyres Worn n/s/r                                  | replaced n/s/r/o tyre - sidewall scuffed to wire fit 2nd hand cap                                                                                                                                                                                                                                                   |  | 951909 |
| 797 | 08/02/2018 | 756666 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                     |  | 952470 |
| 797 | 08/02/2018 | 756666 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                     |  | 952470 |
| 797 | 08/02/2018 | 756666 | Body Needsfluro removed from inside front of bus as it shine |                                                                                                                                                                                                                                                                                                                     |  | 951909 |
| 797 | 07/19/2018 | 751898 | Consumables                                                  | Checked ok                                                                                                                                                                                                                                                                                                          |  | 949484 |
| 797 | 07/19/2018 | 751898 | VALVE CLIPPARD DOOR OPEN/CLOSE (11916-2) BUTTON              |                                                                                                                                                                                                                                                                                                                     |  | 949288 |
| 797 | 07/19/2018 | 751898 | Elec and Light Two Way Radio mic wire pulled out             | checked ok.                                                                                                                                                                                                                                                                                                         |  | 949288 |
| 797 | 07/19/2018 | 751898 | Air Tank drain cock leaking                                  |                                                                                                                                                                                                                                                                                                                     |  | 949288 |
| 797 | 07/19/2018 | 751898 | Direct Purchase - MECHANICAL                                 | Creditor #:#IB-MUL001 MULTISPARES LTD P/O #:#V224877 Receiving #:#232362 Date :2018-07-19 49G7901 drain valve                                                                                                                                                                                                       |  | 949288 |
| 797 | 07/19/2018 | 751898 | Air System Air_Leak Rear                                     | removed and replaced 4way valve. replaced front door penumatic switch.replaced test port on 4 way valve.test drive and checked for leaks.ok.                                                                                                                                                                        |  | 949288 |
| 797 | 07/17/2018 | 752659 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                     |  | 949017 |
| 797 | 07/17/2018 | 752659 | Mechanic entered - Elec and Light Exterior Lights n/s headli | removed and repositioned head light assembly.                                                                                                                                                                                                                                                                       |  | 948725 |
| 797 | 07/16/2018 | 751898 | Service                                                      | repaired at knox                                                                                                                                                                                                                                                                                                    |  | 948446 |
| 797 | 07/13/2018 | 752209 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                     |  | 948446 |
| 797 | 07/13/2018 | 752209 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                     |  | 948446 |
| 797 | 07/13/2018 | 752209 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                     |  | 948446 |
| 797 | 07/13/2018 | 752209 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                     |  | 948446 |
| 797 | 07/13/2018 | 752209 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                     |  | 948446 |
| 797 | 07/13/2018 | 752209 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                     |  | 948268 |
| 797 | 07/12/2018 | 751898 | Mechanic entered - Air System Air_Leak Rear Air protection   | CARRY OUT A SERVICE AS PER CHECK LIST                                                                                                                                                                                                                                                                               |  | 948268 |
| 797 | 07/09/2018 | 751289 |                                                              | found air no building up in front circuit suspect protection valve bus sent Knox                                                                                                                                                                                                                                    |  | 948268 |
| 797 | 07/09/2018 | 751289 |                                                              | VEHICLE SAFETY INSPECTION                                                                                                                                                                                                                                                                                           |  | 948268 |
| 797 | 07/03/2018 | 749838 | Air System Air Not Building_Up - LOOSING AIR ALOT AND CONS   | TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS                                                                                                                                                                                                                                                                        |  | 946840 |
| 797 | 07/02/2018 | 749701 | Consumables                                                  | checked air system for any leaks and could not find. drained air system and build up quick. small roadtest and ok.                                                                                                                                                                                                  |  | 946840 |
| 797 | 07/02/2018 | 749701 | GLOBE 24V 70W H1                                             |                                                                                                                                                                                                                                                                                                                     |  | 946523 |
| 797 | 07/02/2018 | 749701 | Mechanic entered - Elec and Light Exterior Lights            | R/R Light globe                                                                                                                                                                                                                                                                                                     |  | 946523 |
| 797 | 06/27/2018 | 748580 | PERFORM CAMPAIGN 13/18 VENTURA ROUTE BUS DECAL UPDATE        | COMPLETED                                                                                                                                                                                                                                                                                                           |  | 945168 |
| 797 | 06/27/2018 | 748515 | PERFORM CAMPAIGN 16/18 2019 REGISTRATION LABEL REPLACEMENT   | COMPLETED                                                                                                                                                                                                                                                                                                           |  | 945168 |
| 797 | 06/19/2018 | 746281 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                     |  | 944000 |
| 797 | 06/19/2018 | 746281 | Drv entered - Elec and Light Next Stop Button                | Checked all next stop buttons ok. Removed rag from bell.                                                                                                                                                                                                                                                            |  | 943951 |
| 797 | 06/12/2018 | 744900 | AIR CONDITIONING REPAIR                                      | Creditor #:#IB-COL004 COLD DRIVE PTY LTD P/O #:#V222354 Receiving #:#229826 Date :2018-06-18 B Service. replace dryer replace compressor oil new filter medium replace condensor motor                                                                                                                              |  | 943310 |
| 797 | 06/12/2018 | 744900 |                                                              | COLD DRIVE CARRY OUT A/C - B SERVICE AS PER CHECK LIST                                                                                                                                                                                                                                                              |  | 942233 |
| 797 | 06/12/2018 | 744900 |                                                              | CARRY OUT A/C - A SERVICE AS PER CHECK LIST                                                                                                                                                                                                                                                                         |  | 942233 |
| 797 | 06/02/2018 | 742956 | Mechanic entered - Suspension Kneel/ Raise Both amber warnin | cleaned the leveling valve.                                                                                                                                                                                                                                                                                         |  | 940697 |
| 797 | 05/30/2018 | 742308 | STRAIGHT UNION                                               |                                                                                                                                                                                                                                                                                                                     |  | 939981 |
| 797 | 05/30/2018 | 742308 | Mechanic entered - Suspension Soft Front suspension losing a | Raise vehicle and place onto stands. Remove corresponding interior panels to access top of the airbag. Remove old air bag and fit new. Found that male fitting into airbag 90degree damaged. Removed and replaced. Start and check for leaks. All good. Remove vehicle from stands.                                 |  | 939981 |
| 797 | 05/30/2018 | 742308 | AIRBAG FRONT SCANIA L94 SERIES 4                             |                                                                                                                                                                                                                                                                                                                     |  | 939981 |
| 797 | 05/30/2018 | 742308 | Mechanic entered - Suspension Soft Front suspension losing a | Raise vehicle and place onto stands. Remove corresponding interior panels to access top of the airbag. Remove old air bag and fit new. Found that male fitting into airbag 90degree damaged. Removed and replaced. Start and check for leaks. All good. Remove vehicle from stands.                                 |  | 939981 |
| 797 | 05/29/2018 | 741905 | PERFORM CAMPAIGN 15/18 A3 POSTER CHANGE - MYKI AUTO TOP UP   | COMPLETE                                                                                                                                                                                                                                                                                                            |  | 939981 |
| 797 | 05/18/2018 | 738942 | Mechanic entered - Suspension Leaning N/s front air bag leak | sent over to knox for repairs.                                                                                                                                                                                                                                                                                      |  | 937933 |
| 797 | 05/17/2018 | 739217 |                                                              | VEHICLE SAFETY INSPECTION                                                                                                                                                                                                                                                                                           |  | 937742 |
| 797 | 05/17/2018 | 739217 |                                                              | TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS                                                                                                                                                                                                                                                                        |  | 937742 |
| 797 | 05/17/2018 | 739278 | Mechanic entered - Vandalism Vandalism/ Graffiti Interior on | removed grafity                                                                                                                                                                                                                                                                                                     |  | 937742 |
| 797 | 05/17/2018 | 739321 | Install anti-graffiti film to bus                            |                                                                                                                                                                                                                                                                                                                     |  | 937742 |
| 797 | 05/17/2018 | 738942 | Mechanic entered - Suspension Leaning N/s front air bag leak |                                                                                                                                                                                                                                                                                                                     |  | 937742 |
| 797 | 05/17/2018 | 738942 | Mechanic entered - Suspension Leaning N/s front air bag leak | Empty all bins into skip and put back into their respective locations. A + B service and safety done.                                                                                                                                                                                                               |  | 937742 |
| 797 | 05/17/2018 | 739220 | Consumables                                                  | safety done a and b service done                                                                                                                                                                                                                                                                                    |  | 937933 |
| 797 | 05/17/2018 | 739220 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                     |  | 937933 |
| 797 | 05/17/2018 | 739220 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                     |  | 937933 |
| 797 | 05/17/2018 | 739220 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                     |  | 937933 |
| 797 | 05/17/2018 | 739220 | FILTER OIL SCANIA SR4 [EARLY] K320 (LF3730) (H200W20)        |                                                                                                                                                                                                                                                                                                                     |  | 937742 |
| 797 | 05/17/2018 | 739220 | KIT O-RING OIL SPINNER FILTER SCANIA ABOVE ENG #6203050      |                                                                                                                                                                                                                                                                                                                     |  | 937742 |
| 797 | 05/17/2018 | 739220 |                                                              | CARRY OUT B SERVICE AS PER CHECK LIST                                                                                                                                                                                                                                                                               |  | 937742 |
| 797 | 05/17/2018 | 739220 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                     |  | 937933 |
| 797 | 05/17/2018 | 739220 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                     |  | 937933 |
| 797 | 05/17/2018 | 739220 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                     |  | 937933 |
| 797 | 05/17/2018 | 739220 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                     |  | 937742 |
| 797 | 05/17/2018 | 739220 |                                                              | CARRY OUT A SERVICE AS PER CHECK LIST                                                                                                                                                                                                                                                                               |  | 937742 |
| 797 | 05/16/2018 | 739321 | DIRECT PURCHASE - VANDALISM                                  | CARRY OUT A SERVICE AS PER CHECK LIST                                                                                                                                                                                                                                                                               |  | 937742 |
| 797 | 05/16/2018 | 738942 | Mechanic entered - Suspension Leaning N/s front air bag leak | Creditor #:#VB-GLA010 GLASSPROTECH MELBOURNE P/O #:#K219933 Receiving #:#227578 Date :2018-05-17 Install anti-graffiti film to bus. window L1L2L3L3aR1R2R3R3aR4 & modesty                                                                                                                                           |  | 937742 |
| 797 | 05/16/2018 | 739043 | PERFORM CAMPAIGN 07/18 RPD DASH MOUNTED OVERRIDE SWITCH INS  | checked over faulty suspension and 4way valve.sent over to knox for repair.                                                                                                                                                                                                                                         |  | 937742 |
| 797 | 05/16/2018 | 739043 | KIT SWITCH OVERRIDE RPD                                      | Fitted and tested dash override switch campaign install. Working as should apart from: Ignition does NOT come on after bus has been completely shut down. Need to fit the RPD label on switch that is inside electrical panel. Had to repair wiring on RPD plugs crimping was not done correctly by a previous job. |  | 937742 |
| 797 | 04/06/2018 | 729484 | Ops Entered - Fault - Suspension Leaning - Route: 693 - Sc   | bus checked over at Knox ok no fault                                                                                                                                                                                                                                                                                |  | 930564 |
| 797 | 04/06/2018 | 731186 | Drv entered - A/C Heating Not Cooling                        | Completed by COLD DRIVE                                                                                                                                                                                                                                                                                             |  | 929680 |
| 797 | 04/04/2018 | 730695 | PERFORM CAMPAIGN 06/18 REPLACEMENT OF NO ACCESS / PARK BRAK  | CAMPAIGN CARRIED OUT                                                                                                                                                                                                                                                                                                |  | 929680 |
| 797 | 04/03/2018 | 729484 | SWITCH DOOR BUTTON NORMALLY OPEN                             |                                                                                                                                                                                                                                                                                                                     |  | 929432 |
| 797 | 04/03/2018 | 729484 | VALVE DOOR SOLENOID VALVE WITH VOLTAGE SUPPRESSOR            |                                                                                                                                                                                                                                                                                                                     |  | 929432 |
| 797 | 04/03/2018 | 730467 | Breakdown#:34712 - Ops Entered - Breakdown - Breakdown Acci  | Driver error                                                                                                                                                                                                                                                                                                        |  | 929432 |
| 797 | 03/29/2018 | 729877 | Mechanic entered - Suspension Kneel/ Raise suspension wont r | fixed wiring on kneel switch.                                                                                                                                                                                                                                                                                       |  | 929143 |
| 797 | 03/27/2018 | 729415 |                                                              | TRANSMISSION CHECK AS PER CHECK LIST complete.                                                                                                                                                                                                                                                                      |  | 928366 |
| 797 | 03/27/2018 | 729415 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                     |  | 928809 |
| 797 | 03/27/2018 | 729415 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                     |  | 928809 |
| 797 | 03/27/2018 | 729415 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                     |  | 928809 |
| 797 | 03/27/2018 | 729415 |                                                              | Assit damo                                                                                                                                                                                                                                                                                                          |  | 928366 |
| 797 | 03/27/2018 | 729415 |                                                              | CARRY OUT A SERVICE AS PER CHECK LIST complete.                                                                                                                                                                                                                                                                     |  | 928366 |
| 797 | 03/22/2018 | 728510 | Drv entered - A/C Heating Not Cooling                        | DUPLICATE DEFECT                                                                                                                                                                                                                                                                                                    |  | 927915 |
| 797 | 03/21/2018 | 728082 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                     |  | 927915 |
| 797 | 03/21/2018 | 728082 | Wheels and Tyres Wheel Nut Retension Front Axle 926889       | complete retension                                                                                                                                                                                                                                                                                                  |  | 927650 |
| 797 | 03/17/2018 | 727436 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                     |  | 927103 |
| 797 | 03/17/2018 | 727436 | TYRE 295/80R22.5 NEW                                         |                                                                                                                                                                                                                                                                                                                     |  | 926889 |

|     |            |        |                                                              |                                                                                                                                                                                |        |
|-----|------------|--------|--------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|
| 797 | 03/17/2018 | 727436 | Mechanic entered - Wheels and Tyres Other front tyres 4mm m  | Replaced both front tyres using new steer tyres & sanded matting surfaces                                                                                                      | 926889 |
| 797 | 03/15/2018 | 726977 |                                                              | TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS                                                                                                                                   | 926737 |
| 797 | 03/15/2018 | 726977 |                                                              | VEHICLE SAFETY INSPECTION finished service and safety and road tested all ok at time of test safety done all ok at time of test safety done                                    | 926737 |
| 797 | 03/08/2018 | 725470 | Drv entered - Wipers and Washers Washers Not Working         | toped up washer and bleed the system.                                                                                                                                          | 925785 |
| 797 | 03/08/2018 | 725471 | Drv entered - Vandalism Vandalism/ Graffiti Interior         | cleaned graffiti.                                                                                                                                                              | 925785 |
| 797 | 03/07/2018 | 725302 | Please remove any old poster and fit new ones multi choice   | COMPLETE                                                                                                                                                                       | 925465 |
| 797 | 03/01/2018 | 723649 | Mechanic entered - A/C Heating Other A/c ducting on o/s behi | repaired ac ducting.                                                                                                                                                           | 924480 |
| 797 | 03/01/2018 | 723629 | Mechanic entered - Body Front_Door Operation Faulty Front do | wheel chair switch wiring faulty.fixed wiring.                                                                                                                                 | 924480 |
| 797 | 02/28/2018 | 723256 | Consumables                                                  |                                                                                                                                                                                | 924480 |
| 797 | 02/28/2018 | 723256 | Ops Entered - Fault - Elec and Light Warning Light On Dash   | Checked ok.                                                                                                                                                                    | 924258 |
| 797 | 02/17/2018 | 720724 | Consumables                                                  |                                                                                                                                                                                | 922167 |
| 797 | 02/17/2018 | 720724 | Mechanic entered - Wheels and Tyres Worn o/s/f 4mm           |                                                                                                                                                                                | 921853 |
| 797 | 02/17/2018 | 720724 | Mechanic entered - Wheels and Tyres Worn o/s/f 4mm           | Checked ok 4mm                                                                                                                                                                 | 921853 |
| 797 | 02/17/2018 | 677984 | Consumables                                                  |                                                                                                                                                                                | 922167 |
| 797 | 02/17/2018 | 677984 | LAMP LED SIDE MARKER RED/AMBER                               |                                                                                                                                                                                | 921853 |
| 797 | 02/17/2018 | 719666 | Service                                                      | Seat replaced all ok.                                                                                                                                                          | 921853 |
| 797 | 02/16/2018 | 720525 | Vandalism Vandalism/ Graffiti Interior rear seats back wi    | completed                                                                                                                                                                      | 921853 |
| 797 | 02/15/2018 | 712863 | Consumables                                                  |                                                                                                                                                                                | 921853 |
| 797 | 02/15/2018 | 712863 | Elec and Light Horn n/w                                      | Ordered new horn.                                                                                                                                                              | 921570 |
| 797 | 02/15/2018 | 711895 | CCTV CCTV not recording - appears Thoreb not working since   | checked ok                                                                                                                                                                     | 921570 |
| 797 | 02/14/2018 | 719666 | Body- driver seat Lowering by it self (Driver Refused Bus)   | Ordered new seat. Plenty of air going to the seat.                                                                                                                             | 921273 |
| 797 | 02/12/2018 | 711894 | Body Drivers Seat Controls Rasing & lowering by it self.     | checked ok.                                                                                                                                                                    | 920868 |
| 797 | 02/12/2018 | 711894 | Desto Signs - first digit on screen                          | checked ok.                                                                                                                                                                    | 920868 |
| 797 | 02/12/2018 | 711894 | Ops Entered - Fault - Body Drivers Seat Controls - losing a  | checked ok.                                                                                                                                                                    | 920868 |
| 797 | 02/05/2018 | 711894 | Consumables                                                  |                                                                                                                                                                                | 919748 |
| 797 | 02/05/2018 | 711894 | Drv entered - desto 670 looks like G70                       | checked desto and orderd new one                                                                                                                                               | 919748 |
| 797 | 02/02/2018 | 716864 | Consumables                                                  |                                                                                                                                                                                | 919488 |
| 797 | 02/02/2018 | 716864 | Mechanic entered - Wheels and Tyres Worn o/s/f 4mm           | tyre ok                                                                                                                                                                        | 919257 |
| 797 | 02/02/2018 | 716809 | Mechanic entered - Brakes Park_Brake Not Holding Door interl | inspected rpd fuse blown.replaced fuse.ok.                                                                                                                                     | 919257 |
| 797 | 01/29/2018 | 715955 | CCTV locker door faulty                                      | secured                                                                                                                                                                        | 918279 |
| 797 | 01/24/2018 | 715187 | Consumables                                                  |                                                                                                                                                                                | 918006 |
| 797 | 01/24/2018 | 715187 | Elec and Light Horn n/w                                      | adjusted horn.                                                                                                                                                                 | 917405 |
| 797 | 01/24/2018 | 704418 | Consumables                                                  |                                                                                                                                                                                | 918006 |
| 797 | 01/24/2018 | 704418 | SEAT DRIVERS ISRI FAT BOY A686                               |                                                                                                                                                                                | 917405 |
| 797 | 01/23/2018 | 715104 | Perform Campaign 27/17 Positioning of 2018 PTV Fares Decals  | Creditor #;IB-ISR002 ISRI SEATS SUNSHINE P/O #;V205098 Receiving #;219335 Date :2018-01-24                                                                                     | 917405 |
| 797 | 01/19/2018 | 714423 | Consumables                                                  | complete                                                                                                                                                                       | 917060 |
| 797 | 01/19/2018 | 714423 | Body- missing numbers on rear 797                            | have fitted 3 small temporary numbers                                                                                                                                          | 916838 |
| 797 | 01/18/2018 | 713768 | DIRECT PURCHASE - BUS INSPECTI                               | Creditor #;IB-ROA003 ROAD SAFETY INSPECTIONS P/O #;V211565 Receiving #;219534 Date :2018-01-29 Carry out ASI on 797                                                            | 918279 |
| 797 | 01/16/2018 | 713768 |                                                              | TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS                                                                                                                                   | 916329 |
| 797 | 01/16/2018 | 713768 |                                                              | VEHICLE SAFETY INSPECTION                                                                                                                                                      | 916329 |
| 797 | 01/16/2018 | 713768 |                                                              | CARRY OUT ASI/VSİ AS PER RELEVANT CHECK LIST                                                                                                                                   | 916329 |
| 797 | 01/16/2018 | 713768 |                                                              | ANNUAL SAFETY INSPECTION SERIAL #RSI 011886                                                                                                                                    | 916329 |
| 797 | 01/16/2018 | 713850 | Engine Oil leaks RSI 011886                                  |                                                                                                                                                                                | 916329 |
| 797 | 01/16/2018 | 713850 | Consumables                                                  |                                                                                                                                                                                | 916329 |
| 797 | 01/16/2018 | 713850 | Body Rectify all loose or damaged seat frames RSI 011886     | replaced bolts and welded seat frames                                                                                                                                          | 916329 |
| 797 | 01/16/2018 | 713850 | Body Drivers sun blind not retracting RSI 011886             | lubricated runers                                                                                                                                                              | 916329 |
| 797 | 01/16/2018 | 713850 | Body Wheel Chair Ramp soft                                   |                                                                                                                                                                                | 916329 |
| 797 | 01/16/2018 | 713850 | Air System Air leaks infront of diff RSI 011886              |                                                                                                                                                                                | 916329 |
| 797 | 01/12/2018 | 713269 | Mechanic entered - Air System Air Not Building_Up Air leak a | tigten air lines and adjusted regulating pressure.                                                                                                                             | 915845 |
| 797 | 01/05/2018 | 711867 |                                                              | completed ok COMPLETE SERVICE AND DEFECTS                                                                                                                                      | 915009 |
| 797 | 01/05/2018 | 711867 |                                                              | PRE ANNUAL SAFETY INSPECTION CHECK                                                                                                                                             | 915009 |
| 797 | 01/05/2018 | 711898 | Drv entered - Wipers and Washers Washers Not Working         |                                                                                                                                                                                | 915009 |
| 797 | 01/05/2018 | 711898 | Drv entered - Wipers and Washers Washers Not Working         | FIXED WASHERS AND MADE WORKING                                                                                                                                                 | 915009 |
| 797 | 01/05/2018 | 711897 | Consumables                                                  |                                                                                                                                                                                | 915009 |
| 797 | 01/05/2018 | 711896 | Consumables                                                  |                                                                                                                                                                                | 915009 |
| 797 | 01/05/2018 | 711896 | Elec and Light - Desto sign displays the 6 as a 3 in 693     | WOP refer to W/o # 711894                                                                                                                                                      | 915009 |
| 797 | 01/05/2018 | 711897 | Ops Entered - Fault - Desto Signs - not readable             | parts orderd Refe to W/O # 711894                                                                                                                                              | 915009 |
| 797 | 01/05/2018 | 711886 | LED DOWNLIGHT ROUND ENT DOOR                                 |                                                                                                                                                                                | 915009 |
| 797 | 01/05/2018 | 711886 | LED NO PLATE+EXIT LIGHT (26674)                              |                                                                                                                                                                                | 915009 |
| 797 | 01/05/2018 | 711886 |                                                              | CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST FIRE SAFETY INSPECTION changed 6 saloon lightsand step light emergency exit hammer light                                    | 915009 |
| 797 | 01/05/2018 | 711867 |                                                              | Assisting                                                                                                                                                                      | 915009 |
| 797 | 01/05/2018 | 711867 | Consumables                                                  |                                                                                                                                                                                | 915009 |
| 797 | 01/05/2018 | 711867 | Consumables                                                  |                                                                                                                                                                                | 915009 |
| 797 | 01/05/2018 | 711867 | Consumables                                                  |                                                                                                                                                                                | 915009 |
| 797 | 01/05/2018 | 711867 | Direct Purchase - MECHANICAL                                 | Creditor #;IB-MUL001 MULTISPARES LTD P/O #;V210864 Receiving #;218134 Date :2018-01-09 Filter Kit                                                                              | 915288 |
| 797 | 01/05/2018 | 711867 | FILTER FUEL FILTER SCANIA L94UAB (H7090WK30)                 |                                                                                                                                                                                | 915009 |
| 797 | 01/05/2018 | 711867 | FILTER OIL SCANIA SR4 [EARLY] K320 (LF3730) (H200W20)        |                                                                                                                                                                                | 915009 |
| 797 | 01/05/2018 | 711867 | KIT O-RING OIL SPINNER FILTER SCANIA ABOVE ENG #6203050      |                                                                                                                                                                                | 915009 |
| 797 | 01/05/2018 | 711867 | FILTER FUEL FILTER ETHANOL SCANIA SR4 (H17WK04)              |                                                                                                                                                                                | 915009 |
| 797 | 01/05/2018 | 711867 |                                                              | CARRY OUT B SERVICE AS PER CHECK LIST                                                                                                                                          | 915009 |
| 797 | 01/05/2018 | 711867 | Consumables                                                  |                                                                                                                                                                                | 915009 |
| 797 | 01/05/2018 | 711867 | Consumables                                                  |                                                                                                                                                                                | 915009 |
| 797 | 01/05/2018 | 711867 | Consumables                                                  |                                                                                                                                                                                | 915009 |
| 797 | 01/05/2018 | 711867 | FILTER ZF ECOMAT TRANS 124 (E39HD119) (1193281-1)            |                                                                                                                                                                                | 915009 |
| 797 | 01/05/2018 | 711867 |                                                              | CARRY OUT A SERVICE AS PER CHECK LIST                                                                                                                                          | 915009 |
| 797 | 01/03/2018 | 709044 | AIR CONDITIONING REPAIR                                      | Creditor #;IB-COL004 COLD DRIVE PTY LTD P/O #;V211102 Receiving #;218421 Date :2018-01-12 REPLACED BOOST PUMP SULLPIED BY INVICT                                               | 915845 |
| 797 | 01/01/2018 | 709586 | Consumables                                                  |                                                                                                                                                                                | 913982 |
| 797 | 01/01/2018 | 709586 | DIRECT PURCHASE - GLASS                                      | Creditor #;VB-ALP003 ALPHA BUS GLASS PTY LTD P/O #;K212087 Receiving #;219283 Date :2018-01-24 Supply and fit rear emergency exit glass and O/S windscreen                     | 917405 |
| 797 | 12/21/2017 | 709586 | Consumables                                                  |                                                                                                                                                                                | 913061 |
| 797 | 12/21/2017 | 709586 | Body Windows Side                                            | ALPHA GLASS SUPPLY AND FIT REAR WINDOW                                                                                                                                         | 911614 |
| 797 | 12/20/2017 | 709044 | Drv entered - A/C Heating Not Cooling                        | work carried outr by Garry.fitted belts.a/c ok.                                                                                                                                | 911614 |
| 797 | 12/20/2017 | 709044 | Drv entered - A/C Heating Not Cooling                        | work carried outr by Garry.fitted belts.a/c ok.                                                                                                                                | 911614 |
| 797 | 12/19/2017 | 709044 | Drv entered - A/C Heating Not Cooling                        | work carried outr by Garry.fitted belts.a/c ok.                                                                                                                                | 911614 |
| 797 | 12/19/2017 | 709003 | BELT V-BELT HI-POWER 17x2235mm VOLVO B7L                     |                                                                                                                                                                                | 911614 |
| 797 | 12/19/2017 | 709003 | A/C Heating Not Cooling                                      | work carried outr by Garry.fitted belts.a/c ok.                                                                                                                                | 911614 |
| 797 | 12/16/2017 | 708539 | Consumables                                                  |                                                                                                                                                                                | 912070 |
| 797 | 12/16/2017 | 708539 | Ops Entered - Fault - Desto Signs - Route: - Off Service t   | checked ok.                                                                                                                                                                    | 911614 |
| 797 | 12/16/2017 | 708523 | Consumables                                                  |                                                                                                                                                                                | 912070 |
| 797 | 12/16/2017 | 708521 | Consumables                                                  |                                                                                                                                                                                | 912070 |
| 797 | 12/16/2017 | 708523 | Body Drivers Seat Controls - Seat won't raise                | fixed kinked air line.                                                                                                                                                         | 911614 |
| 797 | 12/16/2017 | 708521 | Ops Entered - Fault - Body Drivers Seat Controls - Route:    | checked over drivers seat .ok.                                                                                                                                                 | 911614 |
| 797 | 12/09/2017 | 707061 | Breakdown#:34176 - Ops Entered - Breakdown - Breakdown Road  | BUS C/O Sent Knox for repairs                                                                                                                                                  | 910737 |
| 797 | 12/08/2017 | 706944 | Mechanic entered - Steering Other steering noisy             | Traced fault. Resevior broken (bits blocking pump feed) Remove res & flush system. Swap res with 797 & fitted new oil & filter. Road test OK Order new res to be fitted to 786 | 910737 |

|     |            |        |                                                              |                                                                                                                                                                                               |  |        |
|-----|------------|--------|--------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|--------|
| 797 | 12/08/2017 | 706944 | FILTER P/STEER SCANIA VOLVO MERCEDES (349619-7) (2192404)    |                                                                                                                                                                                               |  | 910737 |
| 797 | 12/01/2017 | 704905 | AIR CONDITIONING REPAIR                                      | Creditor #:IB-COL004 COLD DRIVE PTY LTD P/O #:V208808 Receiving #:216384 Date :2017-12-12 check a/c system traced wiring fault to broken wire in loom                                         |  | 911001 |
| 797 | 11/29/2017 | 704905 | A/C Heating Not Cooling                                      |                                                                                                                                                                                               |  | 909100 |
| 797 | 11/29/2017 | 704905 | Drv entered - A/C Heating Not Cooling                        |                                                                                                                                                                                               |  | 909100 |
| 797 | 11/29/2017 | 704905 | A/C Heating Not Cooling                                      |                                                                                                                                                                                               |  | 909100 |
| 797 | 11/29/2017 | 704905 | Drv entered - A/C Heating Not Cooling                        |                                                                                                                                                                                               |  | 909100 |
| 797 | 11/29/2017 | 704905 | Drv entered - A/C Heating Not Cooling                        |                                                                                                                                                                                               |  | 909100 |
| 797 | 11/29/2017 | 704905 | Drv entered - A/C Heating Not Cooling                        |                                                                                                                                                                                               |  | 909100 |
| 797 | 11/27/2017 | 704418 | steering wheel cracking up                                   | Gary cold drive repaired compressor wiring loom.                                                                                                                                              |  | 908913 |
| 797 | 11/27/2017 | 704418 | Body Drivers Seat Controls not raising fully                 | Checked ok.                                                                                                                                                                                   |  | 908913 |
| 797 | 11/17/2017 | 700657 | Mechanic entered - Elec and Light Interior Lights switch lig | Replaced drivers seat                                                                                                                                                                         |  | 907416 |
| 797 | 11/14/2017 | 700657 | Ops Entered - Fault - desto signs faulty lines making a 6 lo |                                                                                                                                                                                               |  | 906692 |
| 797 | 11/14/2017 | 701414 | Consumables                                                  |                                                                                                                                                                                               |  | 906923 |
| 797 | 11/14/2017 | 701414 | Consumables                                                  |                                                                                                                                                                                               |  | 906923 |
| 797 | 11/14/2017 | 701414 | Body N/S/F wheel arch panel loose (seat moves)               | made bolt to clamp seat tighter to wheelarch                                                                                                                                                  |  | 906692 |
| 797 | 11/14/2017 | 701414 | Body Windows Rear window loose                               | striped out old sika and re sikaed bottom half of window where loose                                                                                                                          |  | 906692 |
| 797 | 11/14/2017 | 701414 | Body Wheel chair ramp decal wrong.                           |                                                                                                                                                                                               |  | 906692 |
| 797 | 11/13/2017 | 701290 |                                                              | VEHICLE SAFETY INSPECTION                                                                                                                                                                     |  | 906692 |
| 797 | 11/13/2017 | 701290 |                                                              | TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS                                                                                                                                                  |  | 906692 |
| 797 | 11/13/2017 | 700657 | Mechanic entered - A/C Heating Belt Loose or_Missing         | Refit A/C belt to proper postion                                                                                                                                                              |  | 906692 |
| 797 | 11/13/2017 | 700657 | Mechanic entered - Elec and Light Interior Lights switch li  | changed globes                                                                                                                                                                                |  | 906692 |
| 797 | 11/13/2017 | 700657 | Ops Entered - Fault - desto signs faulty lines making a 6 lo |                                                                                                                                                                                               |  | 906692 |
| 797 | 11/13/2017 | 701290 | Consumables                                                  |                                                                                                                                                                                               |  | 906692 |
| 797 | 11/13/2017 | 701290 | Consumables                                                  |                                                                                                                                                                                               |  | 906692 |
| 797 | 11/13/2017 | 701290 |                                                              | CARRY OUT A SERVICE AS PER CHECK LIST                                                                                                                                                         |  | 906692 |
| 797 | 11/09/2017 | 700657 | Ops Entered - Fault - desto signs faulty lines making a 6 lo | Module number 5 not working correctly. Tried a control module and also another sign segment and still no change. May be controller wiring or controller. Needs help from Lonsdale auto elecs. |  | 906441 |
| 797 | 11/02/2017 | 699111 | Consumables                                                  |                                                                                                                                                                                               |  | 905018 |
| 797 | 11/02/2017 | 699111 | Wheels and Tyres Wheel Nut Retension all rear tyres.         | Retensioned both rear wheels.                                                                                                                                                                 |  | 904810 |
| 797 | 11/02/2017 | 699307 | Please remove the 2 x Do Not Enter decals at the exterior    | completed                                                                                                                                                                                     |  | 904810 |
| 797 | 11/02/2017 | 699136 | Remove old poster and fit new A3 Posters and hangers         | completed                                                                                                                                                                                     |  | 904810 |
| 797 | 11/01/2017 | 698734 | Consumables                                                  |                                                                                                                                                                                               |  | 904810 |
| 797 | 11/01/2017 | 698734 | VALVE FLEXIBLE TYRE EXTENSION VALVE 210mm LONG               |                                                                                                                                                                                               |  | 904621 |
| 797 | 11/01/2017 | 698734 | TYRE 295/80R22.5 RECAP                                       |                                                                                                                                                                                               |  | 904621 |
| 797 | 11/01/2017 | 698734 | Mechanic entered - Wheels and Tyres Worn Both n/s/r tyres an | Replaced all rear tyres and created book back.                                                                                                                                                |  | 904621 |
| 797 | 11/01/2017 | 698802 | PERFORM 19/17 DOOR BRAKE INTERLOCK FITMENT AUDIT             | COMPLETED                                                                                                                                                                                     |  | 904621 |
| 797 | 10/30/2017 | 698170 | A/C Heating (None) evap fans roof pod loose on roof no mid   | Checked ok garry cold drive.                                                                                                                                                                  |  | 904081 |
| 797 | 10/30/2017 | 698223 | INDICATOR SIDE INDICATOR R/H                                 |                                                                                                                                                                                               |  | 904081 |
| 797 | 10/30/2017 | 698223 | Mechanic entered - Elec and Light Exterior Lights O/s indica | Replaced o/s indicator unit. All terminals corroded off. Not sure who installed light originally but was mounted pointing to the front. Re-installed correct way round.                       |  | 904081 |
| 797 | 10/25/2017 | 696811 | Consumables                                                  |                                                                                                                                                                                               |  | 903474 |
| 797 | 10/25/2017 | 696811 | Body - Drivers door hard to close                            | Secured drivers door latch to body - lilydale depot.                                                                                                                                          |  | 903172 |
| 797 | 10/19/2017 | 695711 | AIR CONDITIONING REPAIR                                      | Creditor #:IB-COL004 COLD DRIVE PTY LTD P/O #:V205871 Receiving #:213400 Date :2017-11-01 REPLACED LEAKING SHAFT SEAL REPLACED PULLEY BEARING NEW COMPRESSOR OIL                              |  | 904621 |
| 797 | 10/19/2017 | 695711 | Drv entered - A/C Heating Not Cooling                        |                                                                                                                                                                                               |  | 902036 |
| 797 | 10/19/2017 | 695711 | Drv entered - A/C Heating Not Heating                        |                                                                                                                                                                                               |  | 902036 |
| 797 | 10/19/2017 | 695711 | Mechanic entered - A/C Heating Noisy Evap fan on roof is ve  | garry cold drive replaced shaft seal and compressor pully bearing.regased bus.                                                                                                                |  | 902036 |
| 797 | 10/18/2017 | 695448 | Accident#:46183 - Ops Entered - Accident - To Be Advised (a  | ECTB CARRY OUT ACCIDENT REPAIRS                                                                                                                                                               |  | 901747 |
| 797 | 09/30/2017 | 690686 |                                                              | APPLIANCE TAGGING CARRY OUT INSPECTION                                                                                                                                                        |  | 899507 |
| 797 | 09/30/2017 | 690686 |                                                              | CARRY OUT FIRE EXTINGUISHER TEST & TAG                                                                                                                                                        |  | 899507 |
| 797 | 09/25/2017 | 689029 | PERFORM CAMPAIGN 09/17 REAR DOOR WARNING SIGNS               | COMPLETE                                                                                                                                                                                      |  | 898299 |
| 797 | 09/25/2017 | 689045 | Remove old A3 Posters with Seniors Festival please leave     | COMPLETE                                                                                                                                                                                      |  | 898299 |
| 797 | 09/22/2017 | 688248 | Consumables                                                  |                                                                                                                                                                                               |  | 897832 |
| 797 | 09/22/2017 | 688248 | Consumables                                                  |                                                                                                                                                                                               |  | 897832 |
| 797 | 09/22/2017 | 688248 | Mechanic entered - Elec and Light Exterior Lights offside he | Replaced blown head light globe.                                                                                                                                                              |  | 897311 |
| 797 | 09/19/2017 | 687205 |                                                              | Carried out a tune up service as per check list                                                                                                                                               |  | 897055 |
| 797 | 09/19/2017 | 686759 |                                                              | repair scope of work                                                                                                                                                                          |  | 897055 |
| 797 | 09/19/2017 | 687431 | Consumables                                                  |                                                                                                                                                                                               |  | 897055 |
| 797 | 09/19/2017 | 687431 | Consumables                                                  |                                                                                                                                                                                               |  | 897055 |
| 797 | 09/19/2017 | 687431 | Mechanic entered - Elec and Light Exterior Lights top right  | repair wireing                                                                                                                                                                                |  | 897055 |
| 797 | 09/18/2017 | 687205 |                                                              | SERVICE MOISTURE EJECTOR fit new moisture ejector.                                                                                                                                            |  | 897055 |
| 797 | 09/18/2017 | 687205 |                                                              | CARRY OUT TUNE-UP SERVICE AS PER CHECK LIST                                                                                                                                                   |  | 897055 |
| 797 | 09/18/2017 | 683168 | Consumables                                                  |                                                                                                                                                                                               |  | 897055 |
| 797 | 09/18/2017 | 683168 | Consumables                                                  |                                                                                                                                                                                               |  | 897055 |
| 797 | 09/18/2017 | 683168 | Consumables                                                  |                                                                                                                                                                                               |  | 897055 |
| 797 | 09/18/2017 | 683168 | Consumables                                                  |                                                                                                                                                                                               |  | 897055 |
| 797 | 09/18/2017 | 683168 | Consumables                                                  |                                                                                                                                                                                               |  | 897055 |
| 797 | 09/18/2017 | 683168 | Consumables                                                  |                                                                                                                                                                                               |  | 897055 |
| 797 | 09/18/2017 | 683168 | Consumables                                                  |                                                                                                                                                                                               |  | 897055 |
| 797 | 09/18/2017 | 683168 | Consumables                                                  |                                                                                                                                                                                               |  | 897055 |
| 797 | 09/18/2017 | 683168 | FILTER AIR FILTER OUTER SCANIA SR3 SR4 AF25066 (E218L)       | TRANSMISSION CHECK AS PER CHECK LIST                                                                                                                                                          |  | 897055 |
| 797 | 09/15/2017 | 686759 |                                                              | VEHICLE SAFETY INSPECTION                                                                                                                                                                     |  | 897055 |
| 797 | 09/15/2017 | 686759 |                                                              | TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS                                                                                                                                                  |  | 897055 |
| 797 | 09/07/2017 | 685012 | Consumables                                                  |                                                                                                                                                                                               |  | 895606 |
| 797 | 09/07/2017 | 685012 | Consumables                                                  |                                                                                                                                                                                               |  | 895606 |
| 797 | 09/07/2017 | 685012 | Elec and Light Exterior Lights - O/S/F clearance light n/w   | fix broken wire                                                                                                                                                                               |  | 894918 |
| 797 | 09/05/2017 | 684078 | TYRE 295/80R22.5 NEW                                         | Creditor #:IB-TYR002 TYRES4U P/O #:V201897 Receiving #:209360 Date :2017-09-07 Scania Steel                                                                                                   |  | 894918 |
| 797 | 09/04/2017 | 684126 | Wheels and Tyres Wheel Nut Retension N/S/F                   | wheel nut tention                                                                                                                                                                             |  | 894211 |
| 797 | 09/02/2017 | 684078 | Wheels and Tyres Worn tread low 3 mm n/s/f                   | Replaced N/S/F tyre using S/H steer tyre                                                                                                                                                      |  | 894211 |
| 797 | 08/31/2017 | 683811 | Consumables                                                  |                                                                                                                                                                                               |  | 894027 |
| 797 | 08/31/2017 | 683811 | Mechanic entered - Body Passenger Seat Torn rear seat base b | fitted missing seat base cover                                                                                                                                                                |  | 893730 |
| 797 | 08/30/2017 | 683428 | Consumables                                                  |                                                                                                                                                                                               |  | 893730 |
| 797 | 08/30/2017 | 683428 | Drv entered - Elec and Light Reverse Buzzer                  | checked reverse buzzer all ok                                                                                                                                                                 |  | 893561 |
| 797 | 08/30/2017 | 683429 | Body 2nd folding seat base back cover missing.               |                                                                                                                                                                                               |  | 893561 |
| 797 | 08/30/2017 | 683429 | Consumables                                                  |                                                                                                                                                                                               |  | 893730 |
| 797 | 08/30/2017 | 683429 | SUPERSLIM PLASTIC BASE Black C                               | Creditor #:IB-MCC010 MCCONNELL SEATS AUSTRALIA P/O #:V201615 Receiving #:209081 Date :2017-09-04                                                                                              |  | 894211 |
| 797 | 08/30/2017 | 683168 | Consumables                                                  |                                                                                                                                                                                               |  | 893730 |
| 797 | 08/30/2017 | 683168 | Consumables                                                  |                                                                                                                                                                                               |  | 893730 |
| 797 | 08/30/2017 | 683168 | Consumables                                                  |                                                                                                                                                                                               |  | 893730 |
| 797 | 08/30/2017 | 683168 | Consumables                                                  | carried out service as rwequireds a service and b service                                                                                                                                     |  | 893561 |
| 797 | 08/29/2017 | 683166 | Consumables                                                  |                                                                                                                                                                                               |  | 893561 |
| 797 | 08/29/2017 | 683166 | Drv entered - Gear Change hard to get into reverse           | Dismantle & clean gear selector. Test . OK.                                                                                                                                                   |  | 892578 |
| 797 | 08/29/2017 | 683168 | FILTER KIT K230 MINOR                                        |                                                                                                                                                                                               |  | 892578 |
| 797 | 08/29/2017 | 683168 |                                                              | helped with service and requires finishing as havin g to go out                                                                                                                               |  | 892578 |
| 797 | 08/29/2017 | 683168 |                                                              |                                                                                                                                                                                               |  | 892578 |
| 797 | 08/29/2017 | 683168 | FILTER AIR FILTER OUTER SCANIA SR3 SR4 AF25066 (E218L)       |                                                                                                                                                                                               |  | 892578 |
| 797 | 08/29/2017 | 683168 | FILTER DRYER SCANIA / VOLVO (1375997) (49G8704W)             |                                                                                                                                                                                               |  | 892578 |

|     |            |        |                                                              |                                                                                                                                                                                                                   |        |
|-----|------------|--------|--------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|
| 797 | 08/29/2017 | 683168 | FILTER HYDRAULIC COOLING FAN SCANIA SR3 (E90HD149)           |                                                                                                                                                                                                                   | 892578 |
| 797 | 08/29/2017 | 683168 | FILTER P/STEER SCANIA VOLVO M/BENZ 0153468_1585618-0_153468  |                                                                                                                                                                                                                   | 892578 |
| 797 | 08/29/2017 | 683168 | FILTER FUEL RAYCOR VOLVO B7R D7E (H7062WK30) (21380408)      |                                                                                                                                                                                                                   | 892578 |
| 797 | 08/29/2017 | 683168 | FILTER TRANSMISSION ZF (4139-298-038) (4139 298 038 01)      |                                                                                                                                                                                                                   | 892578 |
| 797 | 08/29/2017 | 683168 |                                                              | CARRY OUT C SERVICE AS PER CHECK LIST                                                                                                                                                                             | 892578 |
| 797 | 08/29/2017 | 683168 | Consumables                                                  |                                                                                                                                                                                                                   | 893561 |
| 797 | 08/29/2017 | 683168 | Consumables                                                  |                                                                                                                                                                                                                   | 893561 |
| 797 | 08/29/2017 | 683168 | Consumables                                                  |                                                                                                                                                                                                                   | 893561 |
| 797 | 08/29/2017 | 683168 |                                                              | CARRY OUT B SERVICE AS PER CHECK LIST                                                                                                                                                                             | 892578 |
| 797 | 08/29/2017 | 683168 | Consumables                                                  |                                                                                                                                                                                                                   | 893561 |
| 797 | 08/29/2017 | 683168 | Consumables                                                  |                                                                                                                                                                                                                   | 893561 |
| 797 | 08/29/2017 | 683168 | Consumables                                                  |                                                                                                                                                                                                                   | 893561 |
| 797 | 08/29/2017 | 683168 | Consumables                                                  |                                                                                                                                                                                                                   | 892578 |
| 797 | 08/23/2017 | 661246 | ELECTRICAL REPAIR                                            | Creditor #:IB-BWE001 BWERE ELECTRICS PTY LTD P/O #:V200835 Receiving #:207967 Date :2017-08-23                                                                                                                    | 891757 |
| 797 | 08/23/2017 | 661246 | Consumables                                                  |                                                                                                                                                                                                                   | 892064 |
| 797 | 08/16/2017 | 680338 | WIPER REFILL 1000mm MULTI FIT                                |                                                                                                                                                                                                                   | 890370 |
| 797 | 08/16/2017 | 680338 | Wipers and Washers Wipers Noisy                              | replaced blades and lubed all ok                                                                                                                                                                                  | 890370 |
| 797 | 08/15/2017 | 680290 | Consumables                                                  |                                                                                                                                                                                                                   | 890370 |
| 797 | 08/15/2017 | 680290 | Mechanic entered - Elec and Light Exterior Lights N/s/r lowe | N/s/r lower indicator replaced.                                                                                                                                                                                   | 890122 |
| 797 | 08/15/2017 | 680290 | LAMP LED AMBER FLASHER ELRLRA                                |                                                                                                                                                                                                                   | 890122 |
| 797 | 08/10/2017 | 679013 | Consumables                                                  |                                                                                                                                                                                                                   | 889562 |
| 797 | 08/10/2017 | 679013 | Mechanic entered - Elec and Light Exterior Lights n/s/r lowe | Checked light operation OK                                                                                                                                                                                        | 889390 |
| 797 | 08/10/2017 | 679382 | Please remove old posters and fit new one along with hangers | Remove replace                                                                                                                                                                                                    | 889390 |
| 797 | 08/09/2017 | 679013 | Mechanic entered - Elec and Light Exterior Lights N/S/R LOW  |                                                                                                                                                                                                                   | 889093 |
| 797 | 08/09/2017 | 679013 | Mechanic entered - Elec and Light Exterior Lights N/s/r lowe | checked and test ok needs replaceing.                                                                                                                                                                             | 889093 |
| 797 | 08/08/2017 | 678766 | Consumables                                                  |                                                                                                                                                                                                                   | 889093 |
| 797 | 08/08/2017 | 678766 | Mechanic entered - Elec and Light Exterior Lights Lower n/s/ | working ok.                                                                                                                                                                                                       | 888789 |
| 797 | 08/03/2017 | 677761 |                                                              | TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS wheel nut retension done                                                                                                                                             | 888051 |
| 797 | 08/03/2017 | 677761 |                                                              | VEHICLE SAFETY INSPECTION safety done                                                                                                                                                                             | 888051 |
| 797 | 08/03/2017 | 677984 | LAMP LED SIDE MARKER RED/AMBER                               |                                                                                                                                                                                                                   | 888051 |
| 797 | 08/03/2017 | 677984 | Consumables                                                  |                                                                                                                                                                                                                   | 888242 |
| 797 | 08/03/2017 | 677984 | Elec and Light Exterior LightsBoth Front and rear exteri     | lights fixed new globes                                                                                                                                                                                           | 888051 |
| 797 | 08/03/2017 | 677761 | Consumables                                                  |                                                                                                                                                                                                                   | 888242 |
| 797 | 08/03/2017 | 677761 | Consumables                                                  |                                                                                                                                                                                                                   | 888242 |
| 797 | 08/03/2017 | 677761 | Consumables                                                  |                                                                                                                                                                                                                   | 888242 |
| 797 | 08/03/2017 | 677761 |                                                              | CARRY OUT A SERVICE AS PER CHECK LIST a service done                                                                                                                                                              | 888051 |
| 797 | 08/01/2017 | 656893 | Direct Purchase - MECHANICAL                                 | Creditor #:IB-BUR001 BURSON AUTOMOTIVE PTY LTD P/O #:V191884A Receiving #:207622 Date :2017-08-18 A937 Bush                                                                                                       | 890878 |
| 797 | 08/01/2017 | 640211 | ELECTRICAL REPAIR                                            | Creditor #:IB-BWE001 BWERE ELECTRICS PTY LTD P/O #:V199648 Receiving #:206976 Date :2017-08-09                                                                                                                    | 889093 |
| 797 | 08/01/2017 | 656893 | Consumables                                                  |                                                                                                                                                                                                                   | 887813 |
| 797 | 08/01/2017 | 640211 | Consumables                                                  |                                                                                                                                                                                                                   | 887813 |
| 797 | 07/28/2017 | 676883 | PERFORM CAMPAIGN 17/16 DASH SWITCH LABELLING                 | Labels and switch inserts installed as required.                                                                                                                                                                  | 887050 |
| 797 | 07/22/2017 | 675569 | Consumables                                                  |                                                                                                                                                                                                                   | 886000 |
| 797 | 07/22/2017 | 675569 | Mechanic entered - Elec and Light Exterior Lights front and  | Replaced blown step lights.                                                                                                                                                                                       | 886000 |
| 797 | 07/14/2017 | 673837 | Consumables                                                  |                                                                                                                                                                                                                   | 884581 |
| 797 | 07/14/2017 | 673837 | Consumables                                                  |                                                                                                                                                                                                                   | 884581 |
| 797 | 07/14/2017 | 673837 | Remove old Green 2016/17 registration Label and/ or Blue EF  | ok                                                                                                                                                                                                                | 884037 |
| 797 | 07/14/2017 | 673728 | PERFORM CAMPAIGN 05/17 BUS DESTINATION PROGRAM UPDATE        | ok                                                                                                                                                                                                                | 884037 |
| 797 | 07/11/2017 | 672944 | Consumables                                                  |                                                                                                                                                                                                                   | 883741 |
| 797 | 07/11/2017 | 672944 | Consumables                                                  |                                                                                                                                                                                                                   | 883741 |
| 797 | 07/11/2017 | 672944 | Drv entered - Body Windows Front - drivers front blind n.w   | secured blind and checked ok                                                                                                                                                                                      | 883443 |
| 797 | 07/05/2017 | 671884 | Consumables                                                  |                                                                                                                                                                                                                   | 882541 |
| 797 | 07/05/2017 | 671884 | Ops Entered - Fault - Elec and Light Interior Lights - inter | checked all ok at time of testing                                                                                                                                                                                 | 882284 |
| 797 | 06/28/2017 | 670359 | Consumables                                                  |                                                                                                                                                                                                                   | 881052 |
| 797 | 06/28/2017 | 670359 | Consumables                                                  |                                                                                                                                                                                                                   | 881052 |
| 797 | 06/28/2017 | 670359 | Ops Entered - Fault - Body Drivers Seat Belt - no retracting | Checked & untwisted seat belt in seat back. Checked operation OK                                                                                                                                                  | 880802 |
| 797 | 06/23/2017 | 667220 | AIRBAG REAR SCANIA K SERIES (2024287) (35CMG0252HD)          |                                                                                                                                                                                                                   | 879258 |
| 797 | 06/22/2017 | 667220 | Suspension O/S/F & N/S/F/R air bags leaking.                 | ReplacedRear air bag & modify air fittings to suit                                                                                                                                                                | 879258 |
| 797 | 06/21/2017 | 668463 | Wipers and Washers Washers Not Working no water              | filled and primed checked ok                                                                                                                                                                                      | 879258 |
| 797 | 06/16/2017 | 667222 | Consumables                                                  |                                                                                                                                                                                                                   | 878591 |
| 797 | 06/16/2017 | 667222 | Wheels and Tyres Wheel Nut Retension O/S/F                   | Retensioned O/S/F wheel nuts.                                                                                                                                                                                     | 877564 |
| 797 | 06/16/2017 | 667835 | Consumables                                                  |                                                                                                                                                                                                                   | 878591 |
| 797 | 06/16/2017 | 667835 | Drv entered - Elec and Light AM-FM Radio                     | Checked ok.                                                                                                                                                                                                       | 877564 |
| 797 | 06/15/2017 | 667160 | TIE ROD ASSY K230                                            | Creditor #:IB-MUL001 MULTISPARES LIMITED P/O #:V195666 Receiving #:202734 Date :2017-06-16                                                                                                                        | 877816 |
| 797 | 06/14/2017 | 667150 |                                                              | TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS                                                                                                                                                                      | 877564 |
| 797 | 06/14/2017 | 667150 |                                                              | VEHICLE SAFETY INSPECTION                                                                                                                                                                                         | 877564 |
| 797 | 06/14/2017 | 667221 | Vandalism Graffiti on seats & floor.                         | Cleaned as best i can                                                                                                                                                                                             | 877564 |
| 797 | 06/14/2017 | 667220 | AIRBAG FRONT SCANIA K230 (40Y2223)                           |                                                                                                                                                                                                                   | 877564 |
| 797 | 06/14/2017 | 667220 | Suspension N/S/F/R air bag leaking.                          | ordered parts                                                                                                                                                                                                     | 877564 |
| 797 | 06/14/2017 | 667220 | Suspension Leaning front air bag leaking                     | Replaced O/S/F air bag only                                                                                                                                                                                       | 877564 |
| 797 | 06/14/2017 | 667223 | Steering Drag link & tie rod need replacing.                 | Replaced tie rod assemblaley                                                                                                                                                                                      | 877564 |
| 797 | 06/14/2017 | 667160 | Direct Purchase - MECHANICAL                                 | Creditor #:IB-MUL001 MULTISPARES LIMITED P/O #:V195666 Receiving #:202551 Date :2017-06-14 40L221ZF                                                                                                               | 877564 |
| 797 | 06/14/2017 | 667160 | Mechanic entered - Steering Excessive Play                   | Replaced Drag link and tie rod                                                                                                                                                                                    | 877564 |
| 797 | 06/14/2017 | 667160 | TIE ROD ASSY K230                                            | Creditor #:IB-MUL001 MULTISPARES LIMITED P/O #:V195682 Receiving #:202727 Date :2017-06-16 TRACK ROD ASSY                                                                                                         | 877816 |
| 797 | 06/14/2017 | 667222 | Consumables                                                  |                                                                                                                                                                                                                   | 878006 |
| 797 | 06/14/2017 | 667222 | Elec and Light Rear step light n/w                           | replaced globe                                                                                                                                                                                                    | 877564 |
| 797 | 06/14/2017 | 667312 | Consumables                                                  |                                                                                                                                                                                                                   | 878006 |
| 797 | 06/14/2017 | 667312 | Consumables                                                  |                                                                                                                                                                                                                   | 878006 |
| 797 | 06/14/2017 | 667312 | Body 1 safety triangle missing.                              | Bus fitted with older style triangles not compatible with new ones so installed a new set.                                                                                                                        | 877564 |
| 797 | 06/09/2017 | 666606 | Engine - fumes in drivers cabin                              | check no fault found                                                                                                                                                                                              | 877012 |
| 797 | 06/06/2017 | 665987 | Direct Purchase - MECHANICAL                                 | Creditor #:IB-MUL001 MULTISPARES LIMITED P/O #:V195278 Receiving #:202773 Date :2017-06-16 Hose                                                                                                                   | 877816 |
| 797 | 06/06/2017 | 665987 | Mechanic entered - Fluid Leaks Rear of bus                   | check out coolant leak. And found hose at back of engine leaking. drain coolant and remove floor to get to hose. remove and replace hose. refill all parts and refill coolant .And check.                         | 876701 |
| 797 | 06/01/2017 | 665434 | Consumables                                                  |                                                                                                                                                                                                                   | 875792 |
| 797 | 06/01/2017 | 665434 | Consumables                                                  |                                                                                                                                                                                                                   | 875792 |
| 797 | 06/01/2017 | 665434 | Body Wheel Chair Ramp soft and load rating decal wrong       | NFF                                                                                                                                                                                                               | 875792 |
| 797 | 06/01/2017 | 664185 | AIR CONDITIONING REPAIR                                      | Creditor #:IB-COL004 COLD DRIVE PTY LTD P/O #:V195394 Receiving #:202719 Date :2017-06-16 A SERVICE REPLACED 2X UNLOADER COILS                                                                                    | 877816 |
| 797 | 05/31/2017 | 664287 | Mechanic entered - Warning Lights Coolant low coolant warnin | top coolant level and r/test after water pump replaced check low coolant sensor wiring & repair connection remove & clean low coolant probe & correctly fit relay r/test & check coolant leaks & warning light ok | 873702 |
| 797 | 05/30/2017 | 664287 | Mechanic entered - Engine Other Coolant leak at water pump.  | refit water pump on. with new orings and gaskets. refill coolant and test drive.                                                                                                                                  | 873702 |
| 797 | 05/30/2017 | 664287 | Mechanic entered - Engine Other Coolant leak at water pump.  | checked and replaced both front engine mounts remove water pump and cooler end housing inspect and order new housing - cavitation damage clean parts and assemble new pump & housing search for o'rings .         | 873702 |
| 797 | 05/30/2017 | 664287 | MOUNT ENGINE SCANIA 40Y3105                                  |                                                                                                                                                                                                                   | 873702 |
| 797 | 05/30/2017 | 664185 | Direct Purchase - MECHANICAL                                 | Creditor #:IB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:V194761 Receiving #:201726 Date :2017-05-31 2279228 seal                                                                                                      | 875575 |
| 797 | 05/30/2017 | 664185 | WATER PUMP HOUSING S4                                        | Creditor #:IB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:V194761 Receiving #:201726 Date :2017-05-31                                                                                                                   | 875575 |
| 797 | 05/30/2017 | 664185 | O-RING COL                                                   | Creditor #:IB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:V194761 Receiving #:201726 Date :2017-05-31                                                                                                                   | 875575 |
| 797 | 05/30/2017 | 664185 |                                                              | GARY COLD DRIVE CARRY OUT A/C - A SERVICE AS PER CHECK LIST                                                                                                                                                       | 873702 |

|     |            |        |                                                              |                                                                                                                                                                                                                                                                                                                         |        |
|-----|------------|--------|--------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|
| 797 | 05/27/2017 | 663873 | Mechanic entered - Wheels and Tyres Wheel Nut Retension Fron | Retension wheel nuts Both front                                                                                                                                                                                                                                                                                         | 873702 |
| 797 | 05/27/2017 | 663873 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                         | 875332 |
| 797 | 05/26/2017 | 660903 | TYRE 295/80R22.5 RECAP                                       | Creditor #:#B-TYR002 TYRES4U P/O #:#V194520 Receiving #:#201364 Date :2017-05-26                                                                                                                                                                                                                                        | 873702 |
| 797 | 05/26/2017 | 660903 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                         | 875332 |
| 797 | 05/25/2017 | 663404 | Mechanic entered - Fluid Leaks Rear of bus Water pump leakin | Checked ok.                                                                                                                                                                                                                                                                                                             | 873702 |
| 797 | 05/25/2017 | 663402 | WEAR SENSOR SCANIA DISC BRAKE 49G8410                        |                                                                                                                                                                                                                                                                                                                         | 873702 |
| 797 | 05/25/2017 | 663402 | Mechanic entered - Elec and Light Warning Light On Dash Pad  | Traced wiring fault to pad sensor on N/S/F. Also replaced tyre on O/S/F                                                                                                                                                                                                                                                 | 873702 |
| 797 | 05/25/2017 | 663402 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                         | 875065 |
| 797 | 05/23/2017 | 663070 | Elec and Light Exterior Lights - O/S side indicator light    | Replaced globe                                                                                                                                                                                                                                                                                                          | 873702 |
| 797 | 05/23/2017 | 663070 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                         | 874582 |
| 797 | 05/19/2017 | 661965 | DIRECT PURCHASE ACCIDENT                                     | Creditor #:#B-EAS003 EASTCOAST TRUCK & BUS SERVICE P/O #:#V193867 Receiving #:#201076 Date :2017-05-23 ACC # 45254                                                                                                                                                                                                      | 873702 |
| 797 | 05/17/2017 | 661965 | Accident - REAR ACC # 45254                                  |                                                                                                                                                                                                                                                                                                                         | 870712 |
| 797 | 05/16/2017 | 660968 | DIRECT PURCHASE - ELECTRICAL                                 | Creditor #:#B-TOTAUT Total Auto Electrical & Mechanic P/O #:#V193577 Receiving #:#201265 Date :2017-05-25                                                                                                                                                                                                               | 873702 |
| 797 | 05/16/2017 | 661574 | Fit A3 Poster/Hangers                                        | Completed                                                                                                                                                                                                                                                                                                               | 870712 |
| 797 | 05/16/2017 | 661574 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                         | 873140 |
| 797 | 05/16/2017 | 661702 | PERFORM CAMPAIGN 01/17 SMARTRAK DRIVER CONTROL CONSOLE AUDIT | done                                                                                                                                                                                                                                                                                                                    | 870712 |
| 797 | 05/15/2017 | 661246 | PERFORM CAMPAIGN 08/16 BUS ROLLAWAY PREVENTION DEVICE (RPD)  | completed 06.01.17 bradman                                                                                                                                                                                                                                                                                              | 870712 |
| 797 | 05/15/2017 | 661246 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                         | 872917 |
| 797 | 05/12/2017 | 660968 | Engine no starting                                           | TOTAL AUTO ELEC CARRY CHECK OVER FAULT NO FAULT FOUND                                                                                                                                                                                                                                                                   | 870712 |
| 797 | 05/12/2017 | 660903 | KIT O-RING OIL SPINNER FILTER SCANIA ABOVE ENG #6203050      |                                                                                                                                                                                                                                                                                                                         | 870712 |
| 797 | 05/12/2017 | 660903 | FILTER OIL SCANIA SR4 [EARLY] K320 (LF3730) (H200W20)        |                                                                                                                                                                                                                                                                                                                         | 870712 |
| 797 | 05/12/2017 | 660903 | FILTER FUEL FILTER SCANIA SR4 (H17WK04)                      |                                                                                                                                                                                                                                                                                                                         | 870712 |
| 797 | 05/12/2017 | 660903 |                                                              | CARRY OUT B SERVICE AS PER CHECK LIST carried out b service as required                                                                                                                                                                                                                                                 | 870712 |
| 797 | 05/12/2017 | 660903 | FILTER TRANSMISSION ZF (4139-298-038) (4139 298 038 01)      |                                                                                                                                                                                                                                                                                                                         | 870712 |
| 797 | 05/12/2017 | 660903 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                         | 872194 |
| 797 | 05/12/2017 | 660903 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                         | 872194 |
| 797 | 05/12/2017 | 660903 | Consumables                                                  | CARRY OUT A SERVICE AS PER CHECK LIST                                                                                                                                                                                                                                                                                   | 870712 |
| 797 | 05/12/2017 | 660903 |                                                              | CARRY OUT A SERVICE AS PER CHECK LIST                                                                                                                                                                                                                                                                                   | 870712 |
| 797 | 05/12/2017 | 660903 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                         | 872194 |
| 797 | 05/12/2017 | 660903 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                         | 872194 |
| 797 | 05/11/2017 | 660676 | Body screw missing in roof hand rails                        | Secured hand rail.                                                                                                                                                                                                                                                                                                      | 870712 |
| 797 | 05/11/2017 | 660676 | Body (None) front passanger seat stitch LHS                  | Repaired seat base.                                                                                                                                                                                                                                                                                                     | 870712 |
| 797 | 05/11/2017 | 660676 | Body o/s/r bumper loose and holding eng hatch switch open c  | Bumper secured.                                                                                                                                                                                                                                                                                                         | 870712 |
| 797 | 05/11/2017 | 660676 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                         | 872194 |
| 797 | 05/11/2017 | 660676 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                         | 872194 |
| 797 | 05/08/2017 | 659859 | Elec and Light Interior Lights to bright.                    | Head lights as bright as bright can be.                                                                                                                                                                                                                                                                                 | 870712 |
| 797 | 05/08/2017 | 659859 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                         | 871270 |
| 797 | 05/06/2017 | 659769 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                         | 871008 |
| 797 | 05/06/2017 | 659768 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                         | 871008 |
| 797 | 05/06/2017 | 659768 | Elec and Light Flat Batteries                                | started ok                                                                                                                                                                                                                                                                                                              | 870712 |
| 797 | 05/06/2017 | 659769 | Elec and Light Exterior Lights - O/S side indicator n/w      | replace globe                                                                                                                                                                                                                                                                                                           | 870712 |
| 797 | 05/01/2017 | 661246 | ELECTRICAL REPAIR                                            | Creditor #:#B-BWE001 BWERE ELECTRICS PTY LTD P/O #:#V193652 Receiving #:#200504 Date :2017-05-16 Supply and fit RPD                                                                                                                                                                                                     | 872649 |
| 797 | 04/27/2017 | 656893 | AIR CONDITIONING REPAIR                                      | Creditor #:#B-COL004 COLD DRIVE PTY LTD P/O #:#V192597 Receiving #:#199467 Date :2017-05-02 removed spring tensioner rubber bushing and spacer missing fitted new rubber mounts from Bursons replaced 2x consendor motor replaced 3x evap motors                                                                        | 869617 |
| 797 | 04/21/2017 | 656893 | Ops Entered - Fault - Elec and Light Exterior Lights - Rout  | check fuses and power to n/s lower indicator light trace wiring and repair fault at wiring connector test ok refit lights used as test from other bus                                                                                                                                                                   | 868069 |
| 797 | 04/19/2017 | 656893 | Direct Purchase - MECHANICAL                                 | Creditor #:#B-BUR001 BURSON AUTO PARTS P/O #:#V191884 Receiving #:#198733 Date :2017-04-20 bushes for a/c compressor                                                                                                                                                                                                    | 868069 |
| 797 | 04/19/2017 | 656893 | Engine Belts_Loose Noisy Missing a/c Belt                    | GARY FROM COLD DRIVE CARRY OUT REPAIRS                                                                                                                                                                                                                                                                                  | 867807 |
| 797 | 04/12/2017 | 655978 | Vandalism Vandalism/ Graffiti Interior                       | all clean no graffiti found                                                                                                                                                                                                                                                                                             | 867807 |
| 797 | 04/10/2017 | 655552 |                                                              | TRANSMISSION CHECK AS PER CHECK LIST                                                                                                                                                                                                                                                                                    | 867807 |
| 797 | 04/10/2017 | 655552 |                                                              | VEHICLE SAFETY INSPECTION                                                                                                                                                                                                                                                                                               | 867807 |
| 797 | 04/10/2017 | 655552 |                                                              | TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS                                                                                                                                                                                                                                                                            | 867807 |
| 797 | 04/10/2017 | 655628 | GLOBE 24V SW BAYONET (17181)                                 |                                                                                                                                                                                                                                                                                                                         | 867807 |
| 797 | 04/10/2017 | 655628 | Elec and Light Exterior Lights - Desto light n/w             | Replaced bus stopping glovbe. Checked desto light ok.                                                                                                                                                                                                                                                                   | 867807 |
| 797 | 04/03/2017 | 653377 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                         | 866891 |
| 797 | 04/03/2017 | 653377 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                         | 866891 |
| 797 | 04/03/2017 | 653377 | Direct Purchase - BODYWORK                                   | Creditor #:#B-SMC001 SMC PNEUMATICS AUST P/L P/O #:#V190453 Receiving #:#197554 Date :2017-04-04 CARRY OUT DOOR REPAIRS                                                                                                                                                                                                 | 866634 |
| 797 | 03/28/2017 | 653377 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                         | 865731 |
| 797 | 03/28/2017 | 653377 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                         | 865731 |
| 797 | 03/28/2017 | 653377 | Body Rear_Door Operation Faulty only opens 50% of the time   | GLEN FROM SMC CARRY OUT REPAIRS                                                                                                                                                                                                                                                                                         | 865731 |
| 797 | 03/27/2017 | 651990 | INDICATOR STALK SCANIA SERIES 4 (1402448)                    |                                                                                                                                                                                                                                                                                                                         | 864316 |
| 797 | 03/24/2017 | 651990 | INDICATOR STALK SCANIA SERIES 4 (1402448)                    |                                                                                                                                                                                                                                                                                                                         | 864316 |
| 797 | 03/24/2017 | 651990 | SYMBOL (REAR DOOR) SWF SWITCH                                |                                                                                                                                                                                                                                                                                                                         | 864316 |
| 797 | 03/21/2017 | 651990 | Drv entered - A/C Heating Not Cooling                        | GARY FROM COLD DRIVE CHECKED OK                                                                                                                                                                                                                                                                                         | 864316 |
| 797 | 03/21/2017 | 651990 | SYMBOL (REAR DOOR) SWF SWITCH                                |                                                                                                                                                                                                                                                                                                                         | 864316 |
| 797 | 03/21/2017 | 651990 | GLOBE 24V1.2WWEDGE (HLW241.20)(47706)(SWFLED)(E-596FWLED)    |                                                                                                                                                                                                                                                                                                                         | 864316 |
| 797 | 03/21/2017 | 651990 | LAMP FLUORESCENT TUBE 36 Watt                                |                                                                                                                                                                                                                                                                                                                         | 864316 |
| 797 | 03/21/2017 | 651990 | Elec and Light Interior Lights saloon light and passenger    | Replaced blownlighting globes in bus                                                                                                                                                                                                                                                                                    | 864316 |
| 797 | 03/16/2017 | 650539 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                         | 864065 |
| 797 | 03/16/2017 | 650539 | TYRE 295/80R22.5 NEW                                         | Creditor #:#B-TYR002 TYRES4U P/O #:#V189448 Receiving #:#196457 Date :2017-03-21                                                                                                                                                                                                                                        | 864316 |
| 797 | 03/15/2017 | 650941 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                         | 863824 |
| 797 | 03/15/2017 | 650860 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                         | 863824 |
| 797 | 03/15/2017 | 650941 | Wheels and Tyres Wheel Nut Retension N/S/F REBOOK            | Refer to w/o # 650860                                                                                                                                                                                                                                                                                                   | 863148 |
| 797 | 03/15/2017 | 650860 | Wheels and Tyres Wheel Nut Retension O/S/F & N/S/R REBOOK    | Retension wheel nuts Both front & NSR                                                                                                                                                                                                                                                                                   | 863148 |
| 797 | 03/11/2017 | 650539 | Mechanic entered - Wheels and Tyres Flat or Leaking n/s/f p  | Replaced N/S/F tyre using S/H steer tyre                                                                                                                                                                                                                                                                                | 863148 |
| 797 | 03/09/2017 | 650207 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                         | 863148 |
| 797 | 03/09/2017 | 650207 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                         | 863148 |
| 797 | 03/09/2017 | 650207 | Consumables                                                  |                                                                                                                                                                                                                                                                                                                         | 863148 |
| 797 | 03/09/2017 | 650207 | Service                                                      | CARRY OUT A SERVICE AS PER CHECK LIST Finished A service                                                                                                                                                                                                                                                                | 862923 |
| 797 | 03/09/2017 | 650207 |                                                              | CARRY OUT A SERVICE AS PER CHECK LIST start A service                                                                                                                                                                                                                                                                   | 862923 |
| 797 | 02/24/2017 | 647564 | A/C Heating Not Cooling                                      | Checked ok                                                                                                                                                                                                                                                                                                              | 859626 |
| 797 | 02/23/2017 | 647007 | Vandalism Vandalism/ Graffiti Interior slashed seats         | little tear no major problem checked ok                                                                                                                                                                                                                                                                                 | 859626 |
| 797 | 02/22/2017 | 646825 | Please remove any old poster and fit either Good News for T  | Completed Campaign                                                                                                                                                                                                                                                                                                      | 859626 |
| 797 | 02/13/2017 | 644338 |                                                              | TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS                                                                                                                                                                                                                                                                            | 857906 |
| 797 | 02/13/2017 | 644338 |                                                              | VEHICLE SAFETY INSPECTION                                                                                                                                                                                                                                                                                               | 857906 |
| 797 | 02/09/2017 | 638245 | Direct Purchase - MECHANICAL                                 | Creditor #:#B-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:#V185108 Receiving #:#193507 Date :2017-02-10 0481831 Front Solinoid Valve                                                                                                                                                                                          | 857679 |
| 797 | 02/07/2017 | 643221 | Fit New 2107 Large and Small Fares Small Concessionand AO    | Fit new decals                                                                                                                                                                                                                                                                                                          | 856824 |
| 797 | 02/01/2017 | 638898 | DIRECT PURCHASE - BUS INSPECTI                               | Creditor #:#B-FLE010 FLEETCHECK BUS PTY LTD P/O #:#V185410 Receiving #:#193223 Date :2017-02-07                                                                                                                                                                                                                         | 856824 |
| 797 | 02/01/2017 | 640211 | FILTER AIR DRYER SCANIA K230 (2081360) (1774598)             |                                                                                                                                                                                                                                                                                                                         | 855881 |
| 797 | 02/01/2017 | 640211 | FILTER AIR DRYER SCANIA K230 (2081360) (1774598)             |                                                                                                                                                                                                                                                                                                                         | 855881 |
| 797 | 02/01/2017 | 640211 | Mechanic entered - Fluid Leaks Rear of bus                   | drain air tanks and clean air system. check for leaks. and test drive.top up levels and change air dyer fitler.                                                                                                                                                                                                         | 855881 |
| 797 | 02/01/2017 | 640190 | DIRECT PURCHASE - TOWING                                     | Creditor #:#B-EAG001 EAGLE TOWING AND SALVAGE P/O #:#V186978 Receiving #:#193361 Date :2017-02-08 tow bayswater to lilydale                                                                                                                                                                                             | 856824 |
| 797 | 01/31/2017 | 640211 | Mechanic entered - Fluid Leaks Rear of bus                   | Refitted intercooler all radiator hoses changed oil filter topped up hydraulic oil and refilled engine with oil. Refitted all aluminium shrouds on radiator cavity and underbody tray holders. Drained coolant from air tanks and inspected air dryer.. Recommend new air dryer filter and to inspect moisture ejector. | 855881 |

|     |            |        |                                                              |                                                                                                                                                                                                                                     |        |
|-----|------------|--------|--------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|
| 797 | 01/31/2017 | 640211 | O RING INTERCOOLER L94                                       | Creditor #:IB-MUL001 MULTISPARES LIMITED P/O #:V186464RET Receiving #:192799 Date :2017-01-31 o ring intercooler                                                                                                                    | 855881 |
| 797 | 01/31/2017 | 640211 | FILTER OIL SCANIA SR4 [EARLY] K320 (LF3730) (H200W20)        |                                                                                                                                                                                                                                     | 855881 |
| 797 | 01/31/2017 | 640211 | SEAL O-RING INTERCOOLER                                      | Creditor #:IB-MUL001 MULTISPARES LIMITED P/O #:V186464 Receiving #:192798 Date :2017-01-31                                                                                                                                          | 855881 |
| 797 | 01/31/2017 | 640211 | Consumables                                                  |                                                                                                                                                                                                                                     | 855881 |
| 797 | 01/31/2017 | 640211 | Consumables                                                  |                                                                                                                                                                                                                                     | 855881 |
| 797 | 01/31/2017 | 640211 | HINGE                                                        |                                                                                                                                                                                                                                     | 855881 |
| 797 | 01/30/2017 | 640211 | Mechanic entered - Fluid Leaks Rear of bus                   | Remove radiator wash down hydraulic fan and parts and associated brackets and replace with new radiator and cleaned internal of intercoolaer and pipes. Clean and reinstall fuel cooler and oil cooler.                             | 855881 |
| 797 | 01/30/2017 | 641715 | A3 POSTER CHANGE X 4 ENDING JAN 2017 PLEASE SEE CAMPAIGN A   | Replaced posters                                                                                                                                                                                                                    | 855881 |
| 797 | 01/24/2017 | 640630 | Vandalism Vandalism/ Graffiti Interior needs paint over      | Ian Bristow carry out paint over                                                                                                                                                                                                    | 855566 |
| 797 | 01/24/2017 | 640211 | Direct Purchase - MECHANICAL                                 | Creditor #:IB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:V185989 Receiving #:192530 Date :2017-01-30 1516491 Radiator                                                                                                                    | 855881 |
| 797 | 01/24/2017 | 640211 | Direct Purchase - MECHANICAL                                 | Creditor #:IB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:V185989 Receiving #:192530 Date :2017-01-30 1796663 Compressor                                                                                                                  | 855881 |
| 797 | 01/24/2017 | 640211 | Consumables                                                  |                                                                                                                                                                                                                                     | 855881 |
| 797 | 01/24/2017 | 640211 | Elec and Light AM-FM Radio fallen into dash                  | Put radio back into place and replaced faulty drivers spealer. Tests ok                                                                                                                                                             | 855566 |
| 797 | 01/24/2017 | 640211 | Direct Purchase - MECHANICAL                                 | Creditor #:IB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:V185989 Receiving #:192530 Date :2017-01-30 0205118 Hose                                                                                                                        | 855881 |
| 797 | 01/24/2017 | 640211 | Direct Purchase - MECHANICAL                                 | Creditor #:IB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:V185989 Receiving #:192530 Date :2017-01-30 0804658 O-Ring                                                                                                                      | 855881 |
| 797 | 01/24/2017 | 640211 | Direct Purchase - MECHANICAL                                 | Creditor #:IB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:V185989 Receiving #:192530 Date :2017-01-30 1413934 O-Ring                                                                                                                      | 855881 |
| 797 | 01/24/2017 | 640211 | Direct Purchase - MECHANICAL                                 | Creditor #:IB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:V185989 Receiving #:192530 Date :2017-01-30 0812515 Bolts                                                                                                                       | 855881 |
| 797 | 01/24/2017 | 640211 | Direct Purchase - MECHANICAL                                 | Creditor #:IB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:V185989 Receiving #:192530 Date :2017-01-30 1385563 washer                                                                                                                      | 855881 |
| 797 | 01/24/2017 | 640211 | Direct Purchase - MECHANICAL                                 | Creditor #:IB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:V185989 Receiving #:192530 Date :2017-01-30 0812612 Bracket                                                                                                                     | 855881 |
| 797 | 01/24/2017 | 640211 | Direct Purchase - MECHANICAL                                 | Creditor #:IB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:V185989 Receiving #:192530 Date :2017-01-30 1871043 Seal                                                                                                                        | 855881 |
| 797 | 01/24/2017 | 640211 | Direct Purchase - MECHANICAL                                 | Creditor #:IB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:V185989 Receiving #:192530 Date :2017-01-30 1437486 Screw                                                                                                                       | 855881 |
| 797 | 01/24/2017 | 640211 | Direct Purchase - MECHANICAL                                 | Creditor #:IB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:V185989 Receiving #:192530 Date :2017-01-30 0323970 O-Ring                                                                                                                      | 855881 |
| 797 | 01/24/2017 | 640211 | Direct Purchase - MECHANICAL                                 | Creditor #:IB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:V185989 Receiving #:192530 Date :2017-01-30 1427426 Plug                                                                                                                        | 855881 |
| 797 | 01/23/2017 | 640211 | Engine (None) Only able to Start Bus from Rear               |                                                                                                                                                                                                                                     | 855566 |
| 797 | 01/23/2017 | 640211 | Mechanic entered - Fluid Leaks Rear of bus                   | Checked for coolant leaks & order new compressor. Radiator & coolant sight glass.                                                                                                                                                   | 855566 |
| 797 | 01/23/2017 | 640211 | Drv entered - Elec and Light AM-FM Radio                     | Put radio back into place and replaced faulty drivers spealer. Tests ok                                                                                                                                                             | 855566 |
| 797 | 01/23/2017 | 640211 | Elec and Light AM-FM Radio fallen into dash                  | Put radio back into place and replaced faulty drivers spealer. Tests ok                                                                                                                                                             | 855566 |
| 797 | 01/23/2017 | 640211 | Drv entered - Comm Equip                                     | Put radio back into place and replaced faulty drivers spealer. Tests ok                                                                                                                                                             | 855566 |
| 797 | 01/21/2017 | 640190 | Breakdown#:33158 - Ops Entered - Breakdown - Breakdown Road  | Take bus to Bayswater swap over traced coolant leak filled with coolant many leaks cooling system pressurising prepare and assist for tow back to Lilydale                                                                          | 855566 |
| 797 | 01/21/2017 | 640190 | Breakdown#:33157 - Ops Entered - Breakdown - Breakdown Road  | Refer to fault # 626925                                                                                                                                                                                                             | 855566 |
| 797 | 01/14/2017 | 638898 |                                                              | ANNUAL SAFETY INSPECTION SERIAL I 098231                                                                                                                                                                                            | 851334 |
| 797 | 01/14/2017 | 638938 | Consumables                                                  |                                                                                                                                                                                                                                     | 854349 |
| 797 | 01/14/2017 | 638938 | Consumables                                                  |                                                                                                                                                                                                                                     | 854349 |
| 797 | 01/14/2017 | 638938 | Mechanic entered - Body Other top door cover broken          | top cover repaired and refitted and checked now operatinal                                                                                                                                                                          | 851334 |
| 797 | 01/12/2017 | 638245 | LEVEL SENSOR                                                 |                                                                                                                                                                                                                                     | 851334 |
| 797 | 01/11/2017 | 638245 | Ops Entered - Fault - Suspension Kneel/ Raise - Route: 670   | Attended breakdown followed back to depot ordered front solenoid valve Fitted multispares solenoid still playing up performed various tests traced fault to front level sensor got new sensor couriered over and fitted tests ok    | 851334 |
| 797 | 01/11/2017 | 638245 | SOLENOID VALVE FRONT                                         |                                                                                                                                                                                                                                     | 851334 |
| 797 | 01/10/2017 | 637810 | BUSH SWAY BAR BUSH D-SHAPE MID AXLE SCANIA L94               |                                                                                                                                                                                                                                     | 851334 |
| 797 | 01/10/2017 | 637810 | TORQUE ROD FRONT UPPER SCANIA K230 1438475                   |                                                                                                                                                                                                                                     | 851334 |
| 797 | 01/10/2017 | 637810 | Suspension (None) n/s/f upper tourqe rod needs replacing     | checked air bags all ok at time of test so replaced upper tourque rod and reposiioned air bag sensor                                                                                                                                | 851334 |
| 797 | 01/10/2017 | 637810 | Suspension upper n/s/f torque rod bush worn                  | checked air bags all ok at time of test so replaced upper tourque rod and reposiioned air bag sensor                                                                                                                                | 851334 |
| 797 | 01/10/2017 | 637810 | Ops Entered - Fault - Suspension Leaning - front suspension  | checked air bags all ok at time of test so replaced upper tourque rod andrepositioned air bag sensor                                                                                                                                | 851334 |
| 797 | 01/10/2017 | 635360 | Fluid Leaks Rear of bus - Coolant level low                  | Refit sight glass                                                                                                                                                                                                                   | 851334 |
| 797 | 01/10/2017 | 637810 | Consumables                                                  |                                                                                                                                                                                                                                     | 853672 |
| 797 | 01/10/2017 | 637810 | Consumables                                                  |                                                                                                                                                                                                                                     | 853672 |
| 797 | 01/10/2017 | 637810 | Mechanic entered - Body Other body panels loose              | secured loose panel screws                                                                                                                                                                                                          | 851334 |
| 797 | 01/10/2017 | 637810 | Body (None) rear door ram mounts loose                       | checked ok                                                                                                                                                                                                                          | 851334 |
| 797 | 01/10/2017 | 637810 | Body (None) rear door ram pivot pole mount loose rivots      |                                                                                                                                                                                                                                     | 851334 |
| 797 | 01/10/2017 | 637810 | Air System (None) wash and check moisture ejector for air    | checked moisture ejectior fixed pipeing and ok at time of testing                                                                                                                                                                   | 851334 |
| 797 | 01/09/2017 | 637591 |                                                              | PRE ANNUAL SAFETY INSPECTION CHECK pre safty done                                                                                                                                                                                   | 851334 |
| 797 | 01/09/2017 | 637602 | Consumables                                                  |                                                                                                                                                                                                                                     | 853672 |
| 797 | 01/09/2017 | 637602 | Consumables                                                  |                                                                                                                                                                                                                                     | 853672 |
| 797 | 01/09/2017 | 637602 | Consumables                                                  |                                                                                                                                                                                                                                     | 853672 |
| 797 | 01/09/2017 | 637602 | FILTER TRANSMISSION ZF (4139-298-038) (4139 298 038 01)      |                                                                                                                                                                                                                                     | 851334 |
| 797 | 01/09/2017 | 637602 | KIT O-RING OIL SPINNER FILTER SCANIA ABOVE ENG #6203050      |                                                                                                                                                                                                                                     | 851334 |
| 797 | 01/09/2017 | 637602 | FILTER OIL SCANIA SR4 [EARLY] K320 (LF3730) (H200W20)        |                                                                                                                                                                                                                                     | 851334 |
| 797 | 01/09/2017 | 637602 | FILTER FUEL FILTER SCANIA SR4 (H17WK04)                      |                                                                                                                                                                                                                                     | 851334 |
| 797 | 01/09/2017 | 637602 |                                                              | CARRY OUT B SERVICE AS PER CHECK LIST service done                                                                                                                                                                                  | 851334 |
| 797 | 01/09/2017 | 637602 | Consumables                                                  |                                                                                                                                                                                                                                     | 853672 |
| 797 | 01/09/2017 | 637602 | Consumables                                                  |                                                                                                                                                                                                                                     | 853672 |
| 797 | 01/09/2017 | 637602 | Consumables                                                  |                                                                                                                                                                                                                                     | 853672 |
| 797 | 01/09/2017 | 637602 |                                                              | CARRY OUT A SERVICE AS PER CHECK LIST                                                                                                                                                                                               | 851334 |
| 797 | 01/06/2017 | 633742 | Consumables                                                  |                                                                                                                                                                                                                                     | 853237 |
| 797 | 01/06/2017 | 633742 | Elec and Light Exterior Lights - front left p/light n/w      | Could not fault. Unless Phil fixed it last night                                                                                                                                                                                    | 851334 |
| 797 | 01/05/2017 | 633742 | GLOBE 24V SW BAYONET                                         |                                                                                                                                                                                                                                     | 851334 |
| 797 | 01/05/2017 | 633742 | Mechanic entered - Elec and Light Exterior Lights            | remove and replace o/s/f globe.                                                                                                                                                                                                     | 851334 |
| 797 | 01/05/2017 | 636585 | Direct Purchase - MECHANICAL                                 | Creditor #:IB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:V184702 Receiving #:190810 Date :2017-01-05 hose                                                                                                                                | 851334 |
| 797 | 01/04/2017 | 633742 | Mechanic entered - Fluid Leaks Rear of bus                   | drain coolant remove hose and checkfit new clamps and refill cooling system                                                                                                                                                         | 851334 |
| 797 | 01/04/2017 | 636585 | Ops Entered - Fault - Fluid Leaks Rear of bus - Route: 670   | Replaced header tank                                                                                                                                                                                                                | 851334 |
| 797 | 01/04/2017 | 636585 | Breakdown#:33115 - Ops Entered - Breakdown - Breakdown Road  | Attended breakdown topped up water followed back to depot                                                                                                                                                                           | 851334 |
| 797 | 01/03/2017 | 633742 | Mechanic entered - Elec and Light Other                      | check out none start found start moter ok check volt to switch and starter                                                                                                                                                          | 851334 |
| 797 | 12/28/2016 | 635360 | Fluid Leaks Rear of bus - Coolant level low                  | OK. Sight glass by passed                                                                                                                                                                                                           | 851334 |
| 797 | 12/19/2016 | 634086 | A/C Heating Noisy                                            | Work carried out by garry colddrive. WO# 634084                                                                                                                                                                                     | 849585 |
| 797 | 12/19/2016 | 634084 | A/C Heating (None) a/c compressor adjuster needs bushers     | Work carried out by colddrive Garry. Unloaders missing and medium pressure switch missing. Evapourator fan requires replacing. Vibration on roof pod caused by body of AC unit. Further work required to be carried out on service. | 849585 |
| 797 | 12/19/2016 | 633989 | Consumables                                                  |                                                                                                                                                                                                                                     | 850315 |
| 797 | 12/19/2016 | 633989 | Mechanic entered - Elec and Light Exterior Lights O/S side i | Replaced globe                                                                                                                                                                                                                      | 849585 |
| 797 | 12/19/2016 | 633989 | GLOBE 24V 21W SINGLE CONTACT (HLR2421)                       |                                                                                                                                                                                                                                     | 849585 |
| 797 | 12/16/2016 | 633742 | Fluid Leaks Rear of bus - Coolant leak right hand rear cor   | Bypassed sight glass and replaced coolant cap. Ordered parts. rebook                                                                                                                                                                | 849585 |
| 797 | 12/14/2016 | 633373 | Consumables                                                  |                                                                                                                                                                                                                                     | 849585 |
| 797 | 12/14/2016 | 633373 | Elec and Light (None) external door step light wiper wa      | Repaired all elec faults                                                                                                                                                                                                            | 848799 |
| 797 | 12/14/2016 | 633373 | GLOBE 24V 5W (HLG245) (2627)                                 |                                                                                                                                                                                                                                     | 848799 |
| 797 | 12/14/2016 | 633373 | LAMP FLUORESCENT TUBE 18W                                    |                                                                                                                                                                                                                                     | 848799 |
| 797 | 12/14/2016 | 633373 | GLOBE 24V1.2WWEDGE (HLW241.20)(47706)(SWFLED)(E-596FWLED)    |                                                                                                                                                                                                                                     | 848799 |
| 797 | 12/14/2016 | 633373 | LENS AMBER TO SUIT 2149                                      |                                                                                                                                                                                                                                     | 848799 |
| 797 | 12/14/2016 | 633372 | Consumables                                                  |                                                                                                                                                                                                                                     | 849585 |
| 797 | 12/14/2016 | 633372 | Consumables                                                  |                                                                                                                                                                                                                                     | 849585 |
| 797 | 12/14/2016 | 633372 | Body (None) bolt missing from upright pole n/s at roof       | Fit new bolts from missing uprights                                                                                                                                                                                                 | 848799 |
| 797 | 12/14/2016 | 633361 |                                                              | CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST Carried out fire safety inspection. Passed                                                                                                                                       | 848799 |
| 797 | 12/09/2016 | 632486 | Consumables                                                  |                                                                                                                                                                                                                                     | 848799 |
| 797 | 12/09/2016 | 632486 | Consumables                                                  |                                                                                                                                                                                                                                     | 848799 |
| 797 | 12/09/2016 | 632486 | DIRECT PURCHASE - GLASS                                      | Creditor #:IB-A1W001 A-1 Windscreens P/O #:V183298 Receiving #:189848 Date :2016-12-15 SUPPLY AND FIT RESEAL FRONT SCREEN                                                                                                           | 849585 |
| 797 | 12/09/2016 | 632486 | Body Windows Front cracked                                   | A1 REPLACED WINDSCREEN                                                                                                                                                                                                              | 848278 |
| 797 | 12/09/2016 | 632486 | Body Water Leaks Roof over driver                            | A1 RESEAL WINDSCREEN                                                                                                                                                                                                                | 848278 |

|     |            |        |                                     |                                                                    |                                                                                                                                                                                                |        |
|-----|------------|--------|-------------------------------------|--------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|
| 797 | 12/08/2016 | 632384 | Service                             |                                                                    |                                                                                                                                                                                                | 848278 |
| 797 | 12/08/2016 | 632384 | Service                             | TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS carried out wheel nut | tension                                                                                                                                                                                        | 848278 |
| 797 | 12/08/2016 | 632384 |                                     | VEHICLE SAFETY INSPECTION Carried out safety inspection            |                                                                                                                                                                                                | 848278 |
| 797 | 12/08/2016 | 632249 | Consumables                         |                                                                    |                                                                                                                                                                                                | 848517 |
| 797 | 12/08/2016 | 632249 | Mechanic entered - Elec and Light   | Flat Batteries not startin                                         | was ignition had to reset and then started all ok now                                                                                                                                          | 848278 |
| 797 | 12/06/2016 | 631728 | Mechanic entered - Engine           | Other bus not starting                                             | bus not starting played with ignition got started operatinal to go                                                                                                                             | 845532 |
| 797 | 12/01/2016 | 630929 | coolant leak from cap               |                                                                    | Checked. OK. System slightly over full.                                                                                                                                                        | 845532 |
| 797 | 11/30/2016 | 630728 | Consumables                         |                                                                    |                                                                                                                                                                                                | 847171 |
| 797 | 11/30/2016 | 630728 | LAMP FLUORESCENT TUBE               | 36 Watt                                                            |                                                                                                                                                                                                | 845532 |
| 797 | 11/30/2016 | 630728 | Dash Dash_Lights                    | Not Working for speedo                                             | fit new dash light globes                                                                                                                                                                      | 845532 |
| 797 | 11/30/2016 | 630728 | Elec and Light                      | Interior Lights front fluro to bright when                         | Repaired all saloon lights                                                                                                                                                                     | 845532 |
| 797 | 11/30/2016 | 630728 | Dash Dash_Lights                    | Not Working speedo light                                           | fit new dash light globes                                                                                                                                                                      | 845532 |
| 797 | 11/30/2016 | 630728 | Elec and Light                      | Interior Lights saloon light above rear do                         | Repaired all saloon lights                                                                                                                                                                     | 845532 |
| 797 | 11/30/2016 | 630728 | Elec and Light                      | Interior Lights - speedo lights n/w                                | new dash light globes fitted                                                                                                                                                                   | 845532 |
| 797 | 11/30/2016 | 630728 | Consumables                         |                                                                    |                                                                                                                                                                                                | 847171 |
| 797 | 11/30/2016 | 630728 | Consumables                         |                                                                    |                                                                                                                                                                                                | 847171 |
| 797 | 11/30/2016 | 630728 | GLOBE 24V SW (HLG245)               | (2627)                                                             |                                                                                                                                                                                                | 845532 |
| 797 | 11/30/2016 | 630728 | INVERTER 24 Volt                    | 36 Watt MAN                                                        |                                                                                                                                                                                                | 845532 |
| 797 | 11/30/2016 | 630728 | GLOBE 24V1.2WWEDGE (HLW241.20)      | (47706)(SWFLED)(E-596FWLED)                                        |                                                                                                                                                                                                | 845532 |
| 797 | 11/30/2016 | 630728 | Body (None)                         | front door sesitive door edge not working                          | repaired sensitive edge. Tests ok                                                                                                                                                              | 845532 |
| 797 | 11/30/2016 | 630728 | Body (None)                         | vent missing from ducting above rear door d                        | re-fit ducting above front door                                                                                                                                                                | 845532 |
| 797 | 11/25/2016 | 628603 | DIRECT PURCHASE                     | ACCIDENT                                                           | Creditor #:IB-EAS003 EASTCOAST TRUCK & BUS SERVICE P/O #:V181774 Receiving #:189050 Date :2016-12-02 Accident#:43146 - NEAR SIDE MID -                                                         | 847171 |
| 797 | 11/18/2016 | 628603 | Accident#:                          | 43146 - Ops Entered - Accident - - NEAR SIDE MID                   | ECTB MOBILE MICK CARRY OUT REPAIRS                                                                                                                                                             | 844809 |
| 797 | 11/17/2016 | 628294 | Consumables                         |                                                                    |                                                                                                                                                                                                | 844809 |
| 797 | 11/17/2016 | 628294 | Campaign 14/16                      | Destination signs Setting and loadig Files.                        | Completed                                                                                                                                                                                      | 843912 |
| 797 | 11/09/2016 | 626851 | Fit A3 poster to holder             | either Explore Melbourne or PTV Ap                                 | Replaced                                                                                                                                                                                       | 842546 |
| 797 | 11/03/2016 | 618201 | AIR CONDITIONING                    | REPAIR                                                             | Creditor #:IB-COL004 COLD DRIVE PTY LTD P/O #:V180491 Receiving #:186790 Date :2016-11-03                                                                                                      | 841461 |
| 797 | 11/03/2016 | 625424 | Mechanic entered - Fluid Leaks      | Rear of bus radiator sight gl                                      | minor leak coolent sight glass                                                                                                                                                                 | 841461 |
| 797 | 11/02/2016 | 625400 | Consumables                         |                                                                    |                                                                                                                                                                                                | 841755 |
| 797 | 11/02/2016 | 625400 | GLOBE 24V 70W                       | H1                                                                 |                                                                                                                                                                                                | 841461 |
| 797 | 11/02/2016 | 625400 | Mechanic entered - Elec and Light   | Exterior Lights o/s headli                                         | Replaced H1 globe.                                                                                                                                                                             | 841461 |
| 797 | 10/20/2016 | 623041 | Consumables                         |                                                                    |                                                                                                                                                                                                | 839586 |
| 797 | 10/20/2016 | 623040 | Consumables                         |                                                                    |                                                                                                                                                                                                | 839586 |
| 797 | 10/20/2016 | 623041 | Mechanic entered - Elec and Light   | Interior Lights                                                    | try fitting new fluro globes to faulty lights still not working suspect faulty inverters further work required                                                                                 | 839228 |
| 797 | 10/20/2016 | 623040 | DIFFUSER LIGHT COVER                | ELLAMP 3mtr LONG                                                   |                                                                                                                                                                                                | 839228 |
| 797 | 10/20/2016 | 623040 | Mechanic entered - Elec and Light   | Interior Lights                                                    | cut to size & fit new saloon light lense                                                                                                                                                       | 839228 |
| 797 | 10/20/2016 | 623041 | Consumables                         |                                                                    |                                                                                                                                                                                                | 839586 |
| 797 | 10/20/2016 | 623041 | CONSUMABLE - BODYWORK               |                                                                    |                                                                                                                                                                                                | 839228 |
| 797 | 10/20/2016 | 623041 | Mechanic entered - Body             | Other                                                              | clean step edge trim cut to size & glue in new step edge strip                                                                                                                                 | 839228 |
| 797 | 10/18/2016 | 622444 | Fluid Leaks                         | Rear of bus header tank has a pin hole at the                      | check coolant level & r/test check for coolant leak no obvious sign of leak bus required for run recheck on return rechecked header tank for leak on return fluid level ok no leaks evident ok | 838082 |
| 797 | 10/15/2016 | 622130 | Mechanic entered - Vandalism        | Vandalism/ Graffiti Interior                                       | removed fresh grafitti from rear seat bases & backs                                                                                                                                            | 838082 |
| 797 | 10/15/2016 | 622062 | Mechanic entered - Suspension       | Soft                                                               | finish replacing n/s/r/r airbag                                                                                                                                                                | 838082 |
| 797 | 10/15/2016 | 622127 | SCANIA ALT BELT TENSIONER           | K1241B (40N0903)                                                   |                                                                                                                                                                                                | 838082 |
| 797 | 10/15/2016 | 622127 | Mechanic entered - Engine           | Belts_Loose Noisy Missing                                          | replaced engine belt tensioner & pulley                                                                                                                                                        | 838082 |
| 797 | 10/15/2016 | 622128 | Consumables                         |                                                                    |                                                                                                                                                                                                | 838343 |
| 797 | 10/15/2016 | 622128 | GLOBE 24V1.2WWEDGE (HLW241.20)      | (47706)(SWFLED)(E-596FWLED)                                        |                                                                                                                                                                                                | 838082 |
| 797 | 10/15/2016 | 622128 | Mechanic entered - Dash Dash_Lights | Not Working                                                        | replaced switch light globes & clean contacts                                                                                                                                                  | 838082 |
| 797 | 10/15/2016 | 622129 | Consumables                         |                                                                    |                                                                                                                                                                                                | 838343 |
| 797 | 10/15/2016 | 622129 | Mechanic entered - Body             | Other                                                              | secure n/s handrail at roof                                                                                                                                                                    | 838082 |
| 797 | 10/14/2016 | 621873 |                                     |                                                                    | TRANSMISSION CHECK AS PER CHECK LIST carryout trans service                                                                                                                                    | 838082 |
| 797 | 10/14/2016 | 621873 |                                     |                                                                    | TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS                                                                                                                                                   | 838082 |
| 797 | 10/14/2016 | 621873 |                                     |                                                                    | VEHICLE SAFETY INSPECTION carryout safety inspection                                                                                                                                           | 838082 |
| 797 | 10/14/2016 | 622062 | AIRBAG REAR DRIVE AXLE              | SCANIA L94UAB (2024287)                                            |                                                                                                                                                                                                | 838082 |
| 797 | 10/14/2016 | 622062 | Mechanic entered - Suspension       | Soft                                                               | start to replace n/s/r/r airbag                                                                                                                                                                | 838082 |
| 797 | 10/14/2016 | 621873 | Mechanic entered - Fluid Leaks      | Rear of bus                                                        | replaced 2 hose clamps on heater hose joiner r/test & check leaks ok                                                                                                                           | 838082 |
| 797 | 10/14/2016 | 621873 | Consumables                         |                                                                    |                                                                                                                                                                                                | 838343 |
| 797 | 10/14/2016 | 621873 | Consumables                         |                                                                    |                                                                                                                                                                                                | 838343 |
| 797 | 10/14/2016 | 621873 | Consumables                         |                                                                    |                                                                                                                                                                                                | 838343 |
| 797 | 10/14/2016 | 621873 |                                     |                                                                    | CARRY OUT A SERVICE AS PER CHECK LIST carryout A service                                                                                                                                       | 838082 |
| 797 | 10/05/2016 | 620043 | Consumables                         |                                                                    |                                                                                                                                                                                                | 836550 |
| 797 | 10/05/2016 | 620043 | Elec and Light                      | Flat Batteries not starting elec fault                             | Traced fault for not starting. Replaced faulty engine hatch switch Tested OK                                                                                                                   | 836392 |
| 797 | 10/05/2016 | 620043 | SWITCH REAR HATCH                   | LIMIT                                                              |                                                                                                                                                                                                | 836392 |
| 797 | 09/26/2016 | 617632 | Suspension                          | Noisy check v rod bush                                             | RandR V-ROD bushspress in and out refit to bus.                                                                                                                                                | 833838 |
| 797 | 09/26/2016 | 618201 | AIR CONDITIONING                    | REPAIR                                                             | Creditor #:IB-COL004 COLD DRIVE PTY LTD P/O #:V178254 Receiving #:184622 Date :2016-10-04                                                                                                      | 835722 |
| 797 | 09/26/2016 | 618201 | Ops Entered - Fault - A/C           | Heating Warning Light On - Smoke                                   | GARRY FROM COLDDRIVE CARRY OUT REPAIRS                                                                                                                                                         | 833838 |
| 797 | 09/26/2016 | 618273 | Consumables                         |                                                                    |                                                                                                                                                                                                | 834416 |
| 797 | 09/26/2016 | 618273 | Consumables                         |                                                                    |                                                                                                                                                                                                | 834416 |
| 797 | 09/26/2016 | 618273 | A3 Poster Change please             | remove old poster and fit Vitorian                                 | Replaced A3 Poster                                                                                                                                                                             | 833838 |
| 797 | 09/23/2016 | 617632 | Direct Purchase - MECHANICAL        |                                                                    | Creditor #:IB-MUL001 MULTISPARES LIMITED P/O #:V177753 Receiving #:184140 Date :2016-09-27 Bus 797---On parts shelf                                                                            | 834416 |
| 797 | 09/23/2016 | 617632 | Suspension                          | Noisy check v rod bush                                             | take over jobremove v rod bush and pack up area                                                                                                                                                | 833838 |
| 797 | 09/23/2016 | 617632 | REAR V BAR+ REACTION                | ROD BUSH 85MM SCANIA L113+L94UAB                                   |                                                                                                                                                                                                | 833838 |
| 797 | 09/23/2016 | 617632 | Suspension                          | Noisy check v rod bush                                             | replaced rear v rod bushes                                                                                                                                                                     | 833838 |
| 797 | 09/23/2016 | 617632 | Steering (None)                     | PS line damage                                                     | checked ok                                                                                                                                                                                     | 833838 |
| 797 | 09/23/2016 | 617632 | Steering - Rubbing                  | noise heard when at full right hand lock                           | No fault found                                                                                                                                                                                 | 833838 |
| 797 | 09/23/2016 | 617791 | Breakdown#:                         | 32838 - Ops Entered - Breakdown - Breakdown Road                   | BUS RETURN TO DEPOT OK                                                                                                                                                                         | 833838 |
| 797 | 09/16/2016 | 614873 | Consumables                         |                                                                    |                                                                                                                                                                                                | 833265 |
| 797 | 09/16/2016 | 614873 | Consumables                         |                                                                    |                                                                                                                                                                                                | 833265 |
| 797 | 09/16/2016 | 614873 | BUTT HINGE                          | BLACK (49080)                                                      |                                                                                                                                                                                                | 831233 |
| 797 | 09/16/2016 | 614873 | HINGE DRIVERS COMPARTMENT           | 12205 49080                                                        |                                                                                                                                                                                                | 831233 |
| 797 | 09/08/2016 | 614873 | HINGE DRIVERS COMPARTMENT           | 12205 49080                                                        |                                                                                                                                                                                                | 831233 |
| 797 | 09/08/2016 | 614873 | Body - A/C                          | vents at front door loose                                          | removed replaced doorhing as broken                                                                                                                                                            | 831233 |
| 797 | 09/08/2016 | 614873 | Ops Entered - Fault - drivers       | security door top hinge broke                                      | Replace door hinge                                                                                                                                                                             | 831233 |
| 797 | 09/06/2016 | 614307 | Elec and Light                      | AM-FM Radio stops working after 10 mins                            | had radio going for 30 minutes checked ok                                                                                                                                                      | 830761 |
| 797 | 09/06/2016 | 614305 | Elec and Light                      | AM-FM Radio Intermittant fault.                                    | checked ok                                                                                                                                                                                     | 830761 |
| 797 | 09/06/2016 | 613903 | Brakes - Park                       | brake valve hard to operate                                        | replaced hand brake                                                                                                                                                                            | 830761 |
| 797 | 09/05/2016 | 613213 | Elec - Wont                         | start from front needs to be started from rear                     | looked at no start from front found no fault. test ok .                                                                                                                                        | 830761 |
| 797 | 09/05/2016 | 613903 | VALVE PARK BRAKE                    | SCANIA SR3 4 0469271 0570866 40G2702W                              |                                                                                                                                                                                                | 830761 |
| 797 | 09/03/2016 | 613903 | Brakes - Park                       | brake valve hard to operate                                        | Park brake valve hard to operate. Ordered new park brake valve.                                                                                                                                | 830761 |
| 797 | 08/31/2016 | 613213 | Consumables                         |                                                                    |                                                                                                                                                                                                | 830408 |
| 797 | 08/31/2016 | 613213 | Elec - Wont                         | start from front needs to be started from rear                     |                                                                                                                                                                                                | 829688 |
| 797 | 08/26/2016 | 612248 | Please                              | remove old poster and fit new Legacy poster                        | Replaced Poster                                                                                                                                                                                | 829339 |
| 797 | 08/26/2016 | 612248 | Consumables                         |                                                                    |                                                                                                                                                                                                | 829465 |
| 797 | 08/22/2016 | 611188 | Dash Switches                       | Not Working Headlight switch not able to tur                       | Replaced switch knob                                                                                                                                                                           | 827445 |

|                       |                                                              |                                                                                                                                              |        |
|-----------------------|--------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------|--------|
| 797 08/22/2016 611023 | Ops Entered - Fault - Elec and Light - light switch broken   | parts ordered                                                                                                                                | 827445 |
| 797 08/22/2016 611188 | Consumables                                                  |                                                                                                                                              | 828446 |
| 797 08/22/2016 611023 | Consumables                                                  |                                                                                                                                              | 828446 |
| 797 08/22/2016 611304 | PLEASE REMOVE ANY OLD POSTERS & FIT NEW A3 POSTER            | Replace poster                                                                                                                               | 827445 |
| 797 08/22/2016 611304 | Consumables                                                  |                                                                                                                                              | 828446 |
| 797 08/19/2016 610780 | Service                                                      | TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS                                                                                                 | 827445 |
| 797 08/19/2016 610780 | Service                                                      | VEHICLE SAFETY INSPECTION                                                                                                                    | 827445 |
| 797 08/19/2016 610843 | FILTER ZF TRANS ECOMAT 124 4139-298-038 E39HD119 1193281-1   |                                                                                                                                              | 827445 |
| 797 08/19/2016 610843 | Service                                                      | CARRY OUT B SERVICE AS PER CHECK LIST                                                                                                        | 827445 |
| 797 08/19/2016 610843 | Consumables                                                  |                                                                                                                                              | 828183 |
| 797 08/19/2016 610843 | Consumables                                                  |                                                                                                                                              | 828183 |
| 797 08/19/2016 610843 | FILTER FUEL SCANIA SR4( H17WK04)                             |                                                                                                                                              | 827445 |
| 797 08/19/2016 610843 | O-RING KIT OIL SPINNER FILTER SCANIA ABOVE ENG #6203050      |                                                                                                                                              | 827445 |
| 797 08/19/2016 610843 | FILTER OIL SCANIA SR4 EARLY K320 (LF3730)(2059778)(H200W20)  |                                                                                                                                              | 827445 |
| 797 08/19/2016 610843 | Consumables                                                  |                                                                                                                                              | 828183 |
| 797 08/19/2016 610780 | Consumables                                                  |                                                                                                                                              | 828183 |
| 797 08/19/2016 610780 | Consumables                                                  |                                                                                                                                              | 828183 |
| 797 08/19/2016 610843 | Service                                                      | CARRY OUT A SERVICE AS PER CHECK LIST                                                                                                        | 827445 |
| 797 08/19/2016 610780 | Service                                                      | CARRY OUT A SERVICE AS PER CHECK LIST                                                                                                        | 827445 |
| 797 08/19/2016 610843 | Consumables                                                  |                                                                                                                                              | 828183 |
| 797 08/16/2016 610115 | Consumables                                                  |                                                                                                                                              | 827445 |
| 797 08/16/2016 610164 | Consumables                                                  |                                                                                                                                              | 827445 |
| 797 08/16/2016 610115 | Drv entered - Elec and Light Exterior Lights                 | broken wire to desto repaired                                                                                                                | 826941 |
| 797 08/16/2016 610115 | Elec and Light desto lights exterior n/w                     | broken wire to desto repaired                                                                                                                | 826941 |
| 797 08/16/2016 610164 | Elec and Light (None) not starting from key but starting     | Found engine hatch switch not closing circuit. Adjusted engine hatch mount. Test ok                                                          | 826941 |
| 797 08/16/2016 610166 | In line with Campaign:1. Identify CCTV DVR type fitted to    | CCTV settings checked and upgraded. Talking to network                                                                                       | 826941 |
| 797 08/16/2016 610166 | -Replace Drivers Camera with a 2.1mm Thoreb unit-Place a b   | New 2.1mm camera fitted and aimed. Tests ok                                                                                                  | 826941 |
| 797 08/04/2016 608137 | Consumables                                                  |                                                                                                                                              | 825388 |
| 797 08/04/2016 608137 | Body Drivers Seat Controls Drivers seat not raising          | remove and replace seat run new air line to drivers seat                                                                                     | 825176 |
| 797 08/04/2016 608137 | SEAT DRIVERS ISRI FAT BOY A6860 SERIES New Assy              |                                                                                                                                              | 825176 |
| 797 08/04/2016 608137 | Body Drivers Seat Controls - Will not lift high enough       | remove and replace seat run new air line to drivers seat                                                                                     | 825176 |
| 797 08/03/2016 607941 | A/C Heating Not Heating                                      | GARY FROM COLD DRIVE CARRY OUT REPAIRS                                                                                                       | 825176 |
| 797 08/03/2016 607982 | Consumables                                                  |                                                                                                                                              | 825176 |
| 797 08/03/2016 607982 | GAS STAY 500N X 330MM (17201 Volgren)                        |                                                                                                                                              | 825176 |
| 797 08/03/2016 607982 | Body (None) battery hatch struts needs replcing              | Replaced battery hatch struts                                                                                                                | 825176 |
| 797 07/28/2016 606768 | Consumables                                                  |                                                                                                                                              | 824321 |
| 797 07/28/2016 606768 | Consumables                                                  |                                                                                                                                              | 824321 |
| 797 07/28/2016 606768 | PERFORM CAMPAIGN 04/16 DRIVERS WALLETS AND MAP POCKET INSTA  | completed                                                                                                                                    | 824056 |
| 797 07/19/2016 604639 | Starter Safety Relay (03318013                               | Creditor #:IB-MUL001 MULTISPARES LIMITED P/O #:V172773 Receiving #:179426 Date :2016-07-28                                                   | 823847 |
| 797 07/19/2016 604639 | Mechanic entered - Engine Other Starter motor not engaging.  | Trace fault and Fit new start safety relay. Tests ok                                                                                         | 822100 |
| 797 07/19/2016 604639 | Ops Entered - Fault - coolant leaking from cap               | check coolant cap and coolant level r/test to operating temp & check for system pressurizing ok                                              | 822100 |
| 797 07/18/2016 604639 | Mechanic entered - Engine Other Starter motor not engaging.  | Checked for not cranking. Solenoid in front electrical center is geting extremly hot. Jump start bus at starter motor to get off pit Put O/R | 822100 |
| 797 07/18/2016 604639 | Ops Entered - Fault - coolant leaking from cap               | Checked for coolant leaks Only leaking from cap Header tank over full. Drain some coolant out to high level mark                             | 822100 |
| 797 07/18/2016 604639 | Consumables                                                  |                                                                                                                                              | 822358 |
| 797 07/18/2016 604639 | Mechanic entered - Elec and Light Other                      | Refer to engine starting fault                                                                                                               | 822100 |
| 797 07/15/2016 604177 | Consumables                                                  |                                                                                                                                              | 822100 |
| 797 07/15/2016 604177 | Mechanic entered - Elec and Light Other                      | Bus will not crank from front or rear Bus started after working through the gears                                                            | 821428 |
| 797 07/07/2016 602422 | Consumables                                                  |                                                                                                                                              | 819784 |
| 797 07/07/2016 602422 | Consumables                                                  |                                                                                                                                              | 819784 |
| 797 07/07/2016 602422 | Body large stone chip front window                           | Windscreen needs replacing. OK AT THIS STAGE                                                                                                 | 818791 |
| 797 07/06/2016 602285 | Mechanic entered - Vandalism Vandalism/ Graffiti Interior Gr | Cleaned graffiti secured seats and checked rotor ok.                                                                                         | 818791 |
| 797 07/05/2016 598661 | FRANCHISEE CASE                                              | Creditor #:IB-MIC002 MICHELIN AUSTRALIA P/O #:V171630 Receiving #:178942 Date :2016-07-21                                                    | 822100 |
| 797 07/05/2016 598661 | DISPOSAL CHARGE                                              | Creditor #:IB-MIC002 MICHELIN AUSTRALIA P/O #:V171630 Receiving #:178942 Date :2016-07-21                                                    | 822100 |
| 797 07/05/2016 598661 | FITTING                                                      | Creditor #:IB-MIC002 MICHELIN AUSTRALIA P/O #:V171630 Receiving #:178942 Date :2016-07-21                                                    | 822100 |
| 797 07/05/2016 598661 | 295/80R22.5 RECAMIC DRIVE PATT                               | Creditor #:IB-MIC002 MICHELIN AUSTRALIA P/O #:V171630 Receiving #:178942 Date :2016-07-21                                                    | 822100 |
| 797 06/30/2016 601094 | Service                                                      | complete wheel re-tension                                                                                                                    | 818030 |
| 797 06/30/2016 601078 | Service                                                      | TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS                                                                                                 | 818030 |
| 797 06/30/2016 601092 | Consumables                                                  | VEHICLE SAFETY INSPECTION                                                                                                                    | 818030 |
| 797 06/30/2016 601092 | GLOBE 24V 70W H1                                             |                                                                                                                                              | 818221 |
| 797 06/30/2016 601092 | Mechanic entered - Elec and Light Exterior Lights headlight  | replace headlight globe pull apart and clean headlight lens                                                                                  | 818030 |
| 797 06/30/2016 601093 | Consumables                                                  |                                                                                                                                              | 818221 |
| 797 06/30/2016 601093 | Mechanic entered - Body Other corner bumper coming off       | repair and secure corner bumper from coming off                                                                                              | 818030 |
| 797 06/30/2016 601077 | Consumables                                                  |                                                                                                                                              | 818221 |
| 797 06/30/2016 601077 | Consumables                                                  |                                                                                                                                              | 818221 |
| 797 06/30/2016 601077 | Consumables                                                  |                                                                                                                                              | 818221 |
| 797 06/30/2016 601077 | GLOBE 24V 1.2W WEDGE HLW241.2 (47706)(SWFLED)(E-596FWLED)    |                                                                                                                                              | 818030 |
| 797 06/30/2016 601077 |                                                              | CARRY OUT A SERVICE AS PER CHECK LIST Carried out A Service                                                                                  | 818030 |
| 797 06/30/2016 601077 |                                                              | CARRY OUT A SERVICE AS PER CHECK LIST Carried out A Service                                                                                  | 818030 |
| 797 06/28/2016 594929 | AIR CONDITIONING REPAIR                                      | Creditor #:IB-TRA012 TRACS (WA) PTY LTD P/O #:V171526 Receiving #:177536 Date :2016-06-30 REFER TO INVOICE FOR REPAIRS                       | 817757 |
| 797 06/24/2016 598661 | Fornt sway bar d-rubbers worn                                | Checked ok at this time.                                                                                                                     | 817073 |
| 797 06/24/2016 598661 | Steering Excessive Play front sway bar links and tie rod e   | Checked ok at this time.                                                                                                                     | 817073 |
| 797 06/24/2016 598661 | A/C Heating (None) heater hose in engine bay needs scuring   | Checked heater hoses ok at this time.                                                                                                        | 817073 |
| 797 06/24/2016 598661 | Consumables                                                  |                                                                                                                                              | 817205 |
| 797 06/24/2016 598661 | rear door lower pivot bush needs replacing                   | Checked not excessive                                                                                                                        | 817073 |
| 797 06/24/2016 598661 | Body APN advert sticker glue on interior side walls.         | Clean by Fleet support                                                                                                                       | 817073 |
| 797 06/24/2016 598661 | TYRE NEW 295/80R22.5                                         |                                                                                                                                              | 817073 |
| 797 06/24/2016 598661 | Brakes (None) Brakes smoking at rear o/side                  | Replaced rear calipers. N/S/R 97°C & O/S/R 78°C Repaired air leak at rear of bus.                                                            | 817073 |
| 797 06/24/2016 598661 | BRAKE CALIPER L94 RHR/LHF                                    | Creditor #:IB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:V170857 Receiving #:176728 Date :2016-06-24                                              | 817073 |
| 797 06/24/2016 598661 | BRAKE CALIPER L94 LHR/RHF                                    | Creditor #:IB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:V170857 Receiving #:176728 Date :2016-06-24                                              | 817073 |
| 797 06/23/2016 598661 | AIR DRYER WABCO                                              |                                                                                                                                              | 817073 |
| 797 06/23/2016 598661 | Brakes (None) Brakes smoking at rear o/side                  | Stripped rear brakes and replaced air dryer unit.                                                                                            | 817073 |
| 797 06/18/2016 598661 | Brakes (None) Brakes smoking at rear o/side                  | Road tested. N/S/R 127°C & O/S/R 97°C. Bus air not building up enough for general bus duties. Air dryer not adjustable and needs replacing.  | 816028 |
| 797 06/15/2016 583063 | Consumables                                                  |                                                                                                                                              | 816028 |
| 797 06/15/2016 583063 | desto light not working                                      | Refitted light in correct postion                                                                                                            | 802501 |
| 797 06/15/2016 583063 | Elec and Light o/s side indicator aimed toward front of bu   | Refitted light in correct postion                                                                                                            | 807457 |
| 797 06/15/2016 583063 | Elec and Light Exterior Lights - desto board lights not w    | Refitted light in correct postion                                                                                                            | 802501 |
| 797 06/11/2016 597174 | WHEEL NUTS RE-TENSION Bookback from W/O-596035 Brakes (Non   | WHEEL NUTS RE-TENSIONED                                                                                                                      | 815082 |
| 797 06/10/2016 588986 | DIRECT PURCHASE - TYRES                                      | Creditor #:IB-MIC002 MICHELIN AUSTRALIA P/O #:V170040 Receiving #:175960 Date :2016-06-14 295/80r22.5 recamic                                | 815372 |
| 797 06/10/2016 588986 | DIRECT PURCHASE - TYRES                                      | Creditor #:IB-MIC002 MICHELIN AUSTRALIA P/O #:V170040 Receiving #:175960 Date :2016-06-14 fitting                                            | 815372 |
| 797 06/08/2016 596518 | Suspension Leaning o/s/r/r and o/s/r/f air bags needs repl   | Replaced airbags                                                                                                                             | 814757 |
| 797 06/08/2016 596518 | REAR AIR BAG (DRIVE AXLE) SCANIA L94UAB 2024287              |                                                                                                                                              | 814757 |
| 797 06/08/2016 596035 | Brakes (None) front brake pads needs replacing               | Replaced front rotors calipers and pads road tested brake temps N/S/F 133°C O/S/F 130°C N/S/R 129°C O/S/R 128°C                              | 814757 |

|                |        |                                                              |                                                                                                                                                                       |        |
|----------------|--------|--------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|
| 797 06/08/2016 | 595766 | rear o/s break stuck on.                                     | Fitted chambers and road tested refer front brake job for temps                                                                                                       | 814757 |
| 797 06/07/2016 | 596035 | BRAKE PADS SCANIA HIGH SPEED                                 | Creditor #:IB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:V169749 Receiving #:175785 Date :2016-06-09                                                                       | 814757 |
| 797 06/07/2016 | 596035 | BRAKE CALIPER L94 RHR/LHF                                    | Creditor #:IB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:V169749 Receiving #:175785 Date :2016-06-09                                                                       | 814757 |
| 797 06/07/2016 | 596035 | BRAKE CALIPER L94 LHR/RHF                                    | Creditor #:IB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:V169749 Receiving #:175785 Date :2016-06-09                                                                       | 814757 |
| 797 06/07/2016 | 596035 | BRAKE DISC SCANIA SR4 AND K SR                               | Creditor #:IB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:V169749 Receiving #:175785 Date :2016-06-09                                                                       | 814757 |
| 797 06/06/2016 | 596035 | Brakes (None) front brake pads needs replacing               | Ordered parts                                                                                                                                                         | 814757 |
| 797 06/04/2016 | 599817 | Consumables                                                  |                                                                                                                                                                       | 814757 |
| 797 06/04/2016 | 599817 | Please remove any old poster and fit new A3 poster and add   | complete                                                                                                                                                              | 804115 |
| 797 06/04/2016 | 595766 | WEAR SENSOR SCANIA DISC BRAKE 40G8401                        |                                                                                                                                                                       | 814757 |
| 797 06/04/2016 | 595766 | DISC PAD SET SCANIA MB0500                                   |                                                                                                                                                                       | 814757 |
| 797 06/04/2016 | 595766 | rear o/s break stuck on.                                     | inspect rear brakes found fault with rear o/s b.chamber remove brake chambers awaiting parts remove pads inspect calipers for ware install pads and adjust clearance. | 814757 |
| 797 06/04/2016 | 595766 | Spring Brake Chamber Scania Re                               | Creditor #:IB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:V169632 Receiving #:175461 Date :2016-06-06                                                                       | 814757 |
| 797 05/31/2016 | 594929 |                                                              | A/C - B SERVICE                                                                                                                                                       | 814245 |
| 797 05/31/2016 | 594929 |                                                              | TRACS CARRY OUT A/C - B SERVICE AS PER CHECK LIST                                                                                                                     | 814245 |
| 797 05/31/2016 | 594929 |                                                              | TRACS CARRY OUT A/C - A SERVICE AS PER CHECK LIST                                                                                                                     | 814245 |
| 797 05/24/2016 | 593360 | Consumables                                                  |                                                                                                                                                                       | 813124 |
| 797 05/24/2016 | 593360 | Elec and Light Interior Lights rear most saloon light not    | Saloon Ligth fluro's replaced. All ok                                                                                                                                 | 812638 |
| 797 05/24/2016 | 593360 | Elec and Light AM-FM Radio cutting in and out                | AM/FM stereo swapped out with spare. Tests ok                                                                                                                         | 812638 |
| 797 05/24/2016 | 593360 | Saloon lights n/w front emergency exit light n/w rear door   | front door e/exit light replaced All others checked ok                                                                                                                | 812638 |
| 797 05/24/2016 | 593360 | TUBES FLUORESCENT 18W                                        |                                                                                                                                                                       | 812638 |
| 797 05/24/2016 | 593360 | Consumables                                                  |                                                                                                                                                                       | 813124 |
| 797 05/24/2016 | 593360 | Consumables                                                  |                                                                                                                                                                       | 813124 |
| 797 05/24/2016 | 593360 | hand rail mounting plates missing bolts rear door vanity pa  | Secured hand rail.                                                                                                                                                    | 812638 |
| 797 05/24/2016 | 593360 | Body - Accelerator pedal squeaky                             | lubed up accelerator pedal                                                                                                                                            | 812638 |
| 797 05/24/2016 | 593360 | FLURO TUBE 36W                                               |                                                                                                                                                                       | 812638 |
| 797 05/24/2016 | 593360 | LED FRONT POSITION MARKER LIGHT                              |                                                                                                                                                                       | 812638 |
| 797 05/18/2016 | 592194 | Service                                                      | TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS                                                                                                                          | 807457 |
| 797 05/18/2016 | 592194 | Service                                                      | VEHICLE SAFETY INSPECTION                                                                                                                                             | 807457 |
| 797 05/18/2016 | 592193 | Consumables                                                  |                                                                                                                                                                       | 812356 |
| 797 05/18/2016 | 592193 | Consumables                                                  |                                                                                                                                                                       | 812356 |
| 797 05/18/2016 | 592193 | Consumables                                                  |                                                                                                                                                                       | 812356 |
| 797 05/18/2016 | 592193 | CONSUMABLES                                                  |                                                                                                                                                                       | 812356 |
| 797 05/18/2016 | 592193 | FILTER TRANSMISSION ZF 4139-298-038/4139 298 038 01          |                                                                                                                                                                       | 807457 |
| 797 05/18/2016 | 592193 | FILTER FUEL SCANIA SR4( H17WK04)                             |                                                                                                                                                                       | 807457 |
| 797 05/18/2016 | 592193 | O-RING KIT OIL SPINNER FILTER SCANIA ABOVE ENG #6203050      |                                                                                                                                                                       | 807457 |
| 797 05/18/2016 | 592193 | FILTER OIL SCANIA SR4 EARLY K320 (LF3730)(2059778)(H200W20)  |                                                                                                                                                                       | 807457 |
| 797 05/18/2016 | 592193 | Service                                                      | CARRY OUT B SERVICE AS PER CHECK LIST                                                                                                                                 | 807457 |
| 797 05/18/2016 | 592193 | Consumables                                                  |                                                                                                                                                                       | 812356 |
| 797 05/18/2016 | 592193 | Consumables                                                  |                                                                                                                                                                       | 812356 |
| 797 05/18/2016 | 592193 | Consumables                                                  |                                                                                                                                                                       | 812356 |
| 797 05/18/2016 | 592193 | Consumables                                                  |                                                                                                                                                                       | 812356 |
| 797 05/18/2016 | 592193 | Service                                                      | CARRY OUT A SERVICE AS PER CHECK LIST                                                                                                                                 | 807457 |
| 797 05/18/2016 | 592193 | Service                                                      | CARRY OUT A SERVICE AS PER CHECK LIST                                                                                                                                 | 807457 |
| 797 05/17/2016 | 587887 | Consumables                                                  |                                                                                                                                                                       | 812122 |
| 797 05/17/2016 | 587887 | COURTESY LAMP LED                                            |                                                                                                                                                                       | 807457 |
| 797 05/17/2016 | 587887 | IDLER PULLEY SCANIA ARTIC(No Groove Plastic)                 |                                                                                                                                                                       | 807457 |
| 797 05/12/2016 | 591316 | Consumables                                                  |                                                                                                                                                                       | 811159 |
| 797 05/12/2016 | 591316 | desto back light n/w                                         | Re-wired desto backlight. Tests ok                                                                                                                                    | 810862 |
| 797 05/11/2016 | 591316 | Ops Entered - Fault - Desto Sign not lighting up.            |                                                                                                                                                                       | 810862 |
| 797 04/30/2016 | 588986 | WHEEL NUTS RE-TENSION Bookback from W/O:588986 rear brakes l | WHEEL NUTS RE-TENSIONED                                                                                                                                               | 807457 |
| 797 04/29/2016 | 588986 | Tyre tread low N/S/R/l - 29/2/16                             | Tyres lowest point 4mm. OK.                                                                                                                                           | 807457 |
| 797 04/29/2016 | 588986 | SENSOR BRAKE PAD (49G8411)                                   |                                                                                                                                                                       | 807457 |
| 797 04/29/2016 | 588986 | DISC PAD SET SCANIA MB0500                                   |                                                                                                                                                                       | 807457 |
| 797 04/29/2016 | 588986 | rear brakes low - N/S worse - 23/3/16                        | Replaced rear brake pads.                                                                                                                                             | 807457 |
| 797 04/28/2016 | 587887 | Fit/secure vents in ducting above front door                 | Checked ok.                                                                                                                                                           | 807457 |
| 797 04/28/2016 | 587887 | Replace engine dipstick                                      | Replaced                                                                                                                                                              | 807457 |
| 797 04/28/2016 | 587887 | Replace engine dipstick                                      | Replaced                                                                                                                                                              | 807457 |
| 797 04/28/2016 | 587887 | O/S engine idler pulley bearing noisy                        | Checked ok.                                                                                                                                                           | 807457 |
| 797 04/28/2016 | 587887 | Ops Entered - Fault - failing to start after 10+ tries. then | Checked starting ok.                                                                                                                                                  | 807457 |
| 797 04/28/2016 | 587887 | Engine belt tensioner idler pulley bearing noisy             | Replaced pully bearing.                                                                                                                                               | 807457 |
| 797 04/28/2016 | 587887 | IDLER PULLEY SCANIA ARTIC(No Groove Plastic)                 |                                                                                                                                                                       | 807457 |
| 797 04/28/2016 | 587887 | Ops Entered - Fault - Indicators not self cancelling         | Replaced indicator stalk.                                                                                                                                             | 807457 |
| 797 04/28/2016 | 587887 | TUBES FLUORESCENT 18W                                        |                                                                                                                                                                       | 807457 |
| 797 04/28/2016 | 587887 | Ops Entered - Fault - Elec and Light Indicators Not Working  | Replaced indicator stalk.                                                                                                                                             | 807457 |
| 797 04/28/2016 | 587887 | Ops Entered - Fault - rear door exit light n/w               | Replaced blown globe.                                                                                                                                                 | 807457 |
| 797 04/28/2016 | 587887 | Elec and Light - Indicator self cancel n/w                   | Replaced indicator stalk.                                                                                                                                             | 807457 |
| 797 04/23/2016 | 588119 | Service                                                      | TRANSMISSION CHECK AS PER CHECK LIST                                                                                                                                  | 807457 |
| 797 04/23/2016 | 587887 | SCANIA DIP STICK L94UAB                                      |                                                                                                                                                                       | 807457 |
| 797 04/23/2016 | 587887 | Engine dipstick needs replacing                              | Replaced                                                                                                                                                              | 807457 |
| 797 04/22/2016 | 587887 | Elec and Light - Indicator self cancel n/w                   | Ordered parts                                                                                                                                                         | 807457 |
| 797 04/22/2016 | 587887 | INDICATOR STALK SCANIA SERIES                                | Creditor #:IB-MUL001 MULTISPARES LIMITED P/O #:V166691 Receiving #:172641 Date :2016-04-27                                                                            | 808165 |
| 797 04/22/2016 | 587887 | Ops Entered - Fault - Elec and Light Indicators Not Working  | replaced                                                                                                                                                              | 807457 |
| 797 04/13/2016 | 586232 | Graffiti on O/S/R seat and flooring                          | Graffiti shadows painted over on floor and side columns.                                                                                                              | 806006 |
| 797 03/31/2016 | 578966 | AIR CONDITIONING REPAIR                                      | Creditor #:IB-TRA012 TRACS (WA) PTY LTD P/O #:V163394 Receiving #:171299 Date :2016-04-07                                                                             | 804693 |
| 797 03/24/2016 | 582755 | Service                                                      | finish safety inspection                                                                                                                                              | 802501 |
| 797 03/23/2016 | 582755 | Service                                                      | TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS                                                                                                                          | 802377 |
| 797 03/23/2016 | 582755 | Service                                                      | VEHICLE SAFETY INSPECTION start safety inspection                                                                                                                     | 802377 |
| 797 03/23/2016 | 582755 | Consumables                                                  |                                                                                                                                                                       | 802501 |
| 797 03/23/2016 | 582755 | Consumables                                                  |                                                                                                                                                                       | 802501 |
| 797 03/23/2016 | 582755 | Consumables                                                  |                                                                                                                                                                       | 802501 |
| 797 03/23/2016 | 582755 | Consumables                                                  |                                                                                                                                                                       | 802377 |
| 797 03/16/2016 | 581643 | Consumables                                                  | CARRY OUT A SERVICE AS PER CHECK LIST carryout A service                                                                                                              | 801436 |
| 797 03/16/2016 | 581643 | Ops Entered - Fault - Elec and Light Warning Light On Dash - | Checked trans for over heating light on. Checked fault codes & tested trans. No fault found at this time.OK.                                                          | 801208 |
| 797 03/01/2016 | 578966 | Ops Entered - Fault - A/C Heating Not Cooling blowing hot a  | Refer to Fault # 576386                                                                                                                                               | 798141 |
| 797 03/01/2016 | 578966 | A/C Heating Not Cooling                                      | Refer to Fault # 576386                                                                                                                                               | 798141 |
| 797 03/01/2016 | 578966 | A/C Heating Not Cooling - Fan n/w                            | GARY FROM TRACS CARRY OUT REPAIRS AS REQUIRED                                                                                                                         | 798141 |
| 797 03/01/2016 | 577463 | Hose trans cooling                                           | Creditor #:IB-MUL001 MULTISPARES LIMITED P/O #:V162826 Receiving #:170112 Date :2016-03-18                                                                            | 801208 |
| 797 02/27/2016 | 577816 | Consumables                                                  |                                                                                                                                                                       | 797900 |
| 797 02/27/2016 | 577816 | FOAM BASE D/SEAT ISRI A8008-5115                             |                                                                                                                                                                       | 797608 |
| 797 02/27/2016 | 577816 | Body - Drivers seat back foam worn - Seat frame can be felt  | Replaced seat base foam.                                                                                                                                              | 797608 |
| 797 02/26/2016 | 578430 | Consumables                                                  |                                                                                                                                                                       | 797900 |
| 797 02/26/2016 | 578430 | The Campaign requires all Bus destinations systems to be in  | completed                                                                                                                                                             | 797608 |
| 797 02/25/2016 | 577816 | Front O/S air bag split                                      | Not leaking at this time.                                                                                                                                             | 796506 |
| 797 02/25/2016 | 577816 | Consumables                                                  |                                                                                                                                                                       | 797608 |
| 797 02/25/2016 | 577816 | Batteries loose in cradle                                    | Secured batteries.                                                                                                                                                    | 796506 |

|     |            |        |                                                             |                                                                                                                                                                                                                                                                                                                              |        |
|-----|------------|--------|-------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|
| 797 | 02/25/2016 | 577816 | Wheelchair ramp lip loose                                   | Secured wheel chair ramp lip.                                                                                                                                                                                                                                                                                                | 796506 |
| 797 | 02/25/2016 | 577816 | Body - Windscreen sun blind guide rail loose                | Secured sun blind rail.                                                                                                                                                                                                                                                                                                      | 796506 |
| 797 | 02/25/2016 | 577816 | 1st N/S seat to body loose                                  | Needs repair at knox bodyshop.                                                                                                                                                                                                                                                                                               | 796506 |
| 797 | 02/25/2016 | 577816 | Body panels loose                                           | Tightened screws.                                                                                                                                                                                                                                                                                                            | 796506 |
| 797 | 02/25/2016 | 577816 | Drivers blind loose                                         | Secured drivers blind.                                                                                                                                                                                                                                                                                                       | 796506 |
| 797 | 02/25/2016 | 577816 | Body - Drivers seat back foam worn - Seat frame can be felt | Checked ok.                                                                                                                                                                                                                                                                                                                  | 796506 |
| 797 | 02/25/2016 | 577816 | Body Drivers Seat Controls - Drivers seat bottoms out reg   | Repaired weight adjuster.                                                                                                                                                                                                                                                                                                    | 796506 |
| 797 | 02/25/2016 | 577816 | Fire extinguisher test date                                 | Checked date ok.                                                                                                                                                                                                                                                                                                             | 796506 |
| 797 | 02/25/2016 | 577816 | Air leak at front bumper                                    | No leak found at this time.                                                                                                                                                                                                                                                                                                  | 796506 |
| 797 | 02/24/2016 | 577733 | Consumables                                                 |                                                                                                                                                                                                                                                                                                                              | 797486 |
| 797 | 02/24/2016 | 577733 | Elec and Light loud beeping noise when indicator on.        | Checked buzzing is indicator tell tale alarm                                                                                                                                                                                                                                                                                 | 796506 |
| 797 | 02/24/2016 | 577816 | Ops Entered - Fault - Body Drivers Seat Leaning to left bad | Ordered parts                                                                                                                                                                                                                                                                                                                | 796506 |
| 797 | 02/23/2016 | 577463 | Ops Entered - Fault - coolant leaks                         | Fit new coolant hose fill with coolant and check for leaks. roadtest and recheck for leaks ok                                                                                                                                                                                                                                | 796506 |
| 797 | 02/22/2016 | 577463 | Ops Entered - Fault - coolant leaks                         | Found split hose at top of engine going to trans cooler. removed damaged hose.                                                                                                                                                                                                                                               | 796506 |
| 797 | 02/17/2016 | 573040 | Engine (None) engine oil filter spinner needs replacing     | Replaced spin filter rotor                                                                                                                                                                                                                                                                                                   | 795859 |
| 797 | 02/16/2016 | 576165 | Smokey smell comming out of A/C vents.                      | Refer to fault 568515                                                                                                                                                                                                                                                                                                        | 795859 |
| 797 | 02/16/2016 | 576165 | A/C Heating Not Cooling                                     | GARY FROM TRACS CARRY OUT REPAIRS AS REQUIRED evap fans needs replacing and gas leak                                                                                                                                                                                                                                         | 795859 |
| 797 | 02/16/2016 | 575827 | Consumables                                                 |                                                                                                                                                                                                                                                                                                                              | 796088 |
| 797 | 02/16/2016 | 575827 | SEAT ASSY ISRI A6008 MECH LUMBAR C/O                        |                                                                                                                                                                                                                                                                                                                              | 795859 |
| 797 | 02/13/2016 | 575827 | Body Drivers Seat Controls - Drivers seat weight needs to   | drivers seat worn out so remove seat and replace with anoth S/H seat fromvehicle 721 seed away for repairs                                                                                                                                                                                                                   | 792604 |
| 797 | 02/11/2016 | 575496 | Consumables                                                 |                                                                                                                                                                                                                                                                                                                              | 795278 |
| 797 | 02/11/2016 | 575496 | Campaign 23_15 A3 Poster Change                             | Complete                                                                                                                                                                                                                                                                                                                     | 792604 |
| 797 | 02/10/2016 | 573040 | Engine (None) engine oil filter spinner needs replacing     | Ordered parts                                                                                                                                                                                                                                                                                                                | 792604 |
| 797 | 02/08/2016 | 573040 | Consumables                                                 |                                                                                                                                                                                                                                                                                                                              | 794369 |
| 797 | 02/08/2016 | 573040 | SWITCH REAR START L113                                      |                                                                                                                                                                                                                                                                                                                              | 794098 |
| 797 | 02/01/2016 | 570901 | DIRECT PURCHASE - BUS INSPECTI                              | Creditor #;IB-ROA003 ROAD SAFETY INSPECTIONS P/L P/O #:V160745 Receiving #:167690 Date :2016-02-11                                                                                                                                                                                                                           | 794369 |
| 797 | 02/01/2016 | 573040 | Rotor Oil Filter Scania                                     | Creditor #;IB-SCA001 SCANIA AUSTRALIA PTY LTD P/O #:V161224 Receiving #:167718 Date :2016-02-11                                                                                                                                                                                                                              | 794744 |
| 797 | 01/28/2016 | 572573 | Service                                                     | TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS                                                                                                                                                                                                                                                                                 | 792115 |
| 797 | 01/28/2016 | 572573 | Service                                                     | VEHICLE SAFETY INSPECTION                                                                                                                                                                                                                                                                                                    | 792115 |
| 797 | 01/28/2016 | 572573 | Service                                                     | VEHICLE SAFETY INSPECTION                                                                                                                                                                                                                                                                                                    | 792115 |
| 797 | 01/28/2016 | 572573 | Consumables                                                 |                                                                                                                                                                                                                                                                                                                              | 792604 |
| 797 | 01/28/2016 | 572573 | Consumables                                                 |                                                                                                                                                                                                                                                                                                                              | 792604 |
| 797 | 01/28/2016 | 572573 | FILTER FUEL SCANIA L94UAB (H7090WK30)                       |                                                                                                                                                                                                                                                                                                                              | 792115 |
| 797 | 01/28/2016 | 572573 | FILTER FUEL SCANIA SR4( H17WK04)                            |                                                                                                                                                                                                                                                                                                                              | 792115 |
| 797 | 01/28/2016 | 572573 | FILTER AIR DRYER SCANIA K230 (2081360)(1774598)             |                                                                                                                                                                                                                                                                                                                              | 792115 |
| 797 | 01/28/2016 | 572573 | FILTER TRANSMISSION ZF 4139-298-038/4139 298 038 01         |                                                                                                                                                                                                                                                                                                                              | 792115 |
| 797 | 01/28/2016 | 572573 | FILTER OIL SCANIA SR4 EARLY K320 (LF3730)(2059778)(H200W20) |                                                                                                                                                                                                                                                                                                                              | 792115 |
| 797 | 01/28/2016 | 572573 | O-RING KIT OIL SPINNER FILTER SCANIA ABOVE ENG #6203050     |                                                                                                                                                                                                                                                                                                                              | 792115 |
| 797 | 01/28/2016 | 572573 | Service                                                     | CARRY OUT C SERVICE AS PER CHECK LIST                                                                                                                                                                                                                                                                                        | 792115 |
| 797 | 01/28/2016 | 572573 | FILTER HYD COOLING FAN SCANIA SR3 (E90HD149)                |                                                                                                                                                                                                                                                                                                                              | 792115 |
| 797 | 01/28/2016 | 572573 | FILTER AIR OUTER SCANIA SR3 SR4 AF2506 395773 E218L         |                                                                                                                                                                                                                                                                                                                              | 792115 |
| 797 | 01/28/2016 | 572573 | FILTER P/STEER SCANIA VOLVO M/BENZ 0153468-1585618-0-153468 |                                                                                                                                                                                                                                                                                                                              | 792115 |
| 797 | 01/28/2016 | 572573 | Consumables                                                 |                                                                                                                                                                                                                                                                                                                              | 792604 |
| 797 | 01/28/2016 | 572573 | Consumables                                                 | CARRY OUT B SERVICE AS PER CHECK LIST                                                                                                                                                                                                                                                                                        | 792604 |
| 797 | 01/28/2016 | 572573 | Service                                                     |                                                                                                                                                                                                                                                                                                                              | 792115 |
| 797 | 01/28/2016 | 572573 | Consumables                                                 |                                                                                                                                                                                                                                                                                                                              | 792604 |
| 797 | 01/28/2016 | 572573 | Consumables                                                 |                                                                                                                                                                                                                                                                                                                              | 792604 |
| 797 | 01/28/2016 | 572573 | Service                                                     | CARRY OUT A SERVICE AS PER CHECK LIST                                                                                                                                                                                                                                                                                        | 792115 |
| 797 | 01/23/2016 | 571954 | Drv entered - Body Drivers Seat Leaning                     | Checked and adjusted all ok                                                                                                                                                                                                                                                                                                  | 791613 |
| 797 | 01/21/2016 | 571574 | Graffiti in back on bus walls and floor                     | has been painted over ok                                                                                                                                                                                                                                                                                                     | 791218 |
| 797 | 01/21/2016 | 571565 | Body Drivers Seat Controls does not adjust                  | checked over seat recalibrated weight control                                                                                                                                                                                                                                                                                | 791218 |
| 797 | 01/20/2016 | 555274 | Direct Purchase - MECHANICAL                                | Creditor #;IB-EAS003 EASTCOAST TRUCK & BUS SERVICE P/O #:V160115 Receiving #:166478 Date :2016-01-20 MM 40G8709W Air drier                                                                                                                                                                                                   | 791218 |
| 797 | 01/20/2016 | 555274 | SWITCH REAR START L113                                      | Creditor #;IB-EAS003 EASTCOAST TRUCK & BUS SERVICE P/O #:V160115 Receiving #:166478 Date :2016-01-20 MM                                                                                                                                                                                                                      | 791218 |
| 797 | 01/19/2016 | 570901 |                                                             | ANNUAL SAFETY INSPECTION SERIAL #001256                                                                                                                                                                                                                                                                                      | 791218 |
| 797 | 01/14/2016 | 570070 | PERFORM CAMPAIGN 22/15 POSITIONING OF 2016 PTV FARES DECALS | completed                                                                                                                                                                                                                                                                                                                    | 790482 |
| 797 | 01/14/2016 | 570017 | Camapign 20/15 Audit & Update of Safety Decals.Requires a   | Completed                                                                                                                                                                                                                                                                                                                    | 790482 |
| 797 | 01/13/2016 | 569726 | Elec and Light (None)REPACE REAR START SWITCH               | Fitted new rear tsart switch & test OK Note; switch was orded & booked to job #555274                                                                                                                                                                                                                                        | 789276 |
| 797 | 01/13/2016 | 569726 | Air System (None)REPLACE AIR DRYER                          | Replaced Haldex air dryer with Wabco type & test. OK. Note; Dryer was orded & booked to job #555274                                                                                                                                                                                                                          | 789276 |
| 797 | 01/12/2016 | 568408 | Drv entered - Elec and Light Next Stop Button               | Traced fault in Thoreb system with auto elect. 100 AMP fuse near master relay blown. Replaced fuse & test most componets returned Traced through next stop bell system wrepair damaged wires & rewire correct polaraty to bell try to locate broken wires in pannels. by pass broken wiring & wire direct to Thoreb node. Te | 789276 |
| 797 | 01/12/2016 | 569454 | DIRECT PURCHASE - GLASS                                     | Creditor #;IB-A1W001 A-1 Windscreens P/O #:V160495 Receiving #:166242 Date :2016-01-14 reseal rear window                                                                                                                                                                                                                    | 790482 |
| 797 | 01/12/2016 | 569454 | Body Windows Rear Rear window loose                         | Rear window resealed by A1 glass                                                                                                                                                                                                                                                                                             | 789276 |
| 797 | 01/11/2016 | 569188 |                                                             | PRE ANNUAL SAFETY INSPECTION CHECK                                                                                                                                                                                                                                                                                           | 790150 |
| 797 | 01/11/2016 | 569237 | PUMP WIPER-WASHER 24 VOLT 80826                             |                                                                                                                                                                                                                                                                                                                              | 790150 |
| 797 | 01/11/2016 | 569237 | Wipers and Washers Washers Not Working O/S washers N/W      | Replaced washer motor. Modify & reroute O/S washer hose test. OK                                                                                                                                                                                                                                                             | 790150 |
| 797 | 01/11/2016 | 569237 | TORQUE ROD BUSH SUIT V STAY SCANIA 49Y3304ZF 1435944        |                                                                                                                                                                                                                                                                                                                              | 790150 |
| 797 | 01/11/2016 | 569237 | Front sway bar D-rubbers                                    | Checked bushes OK                                                                                                                                                                                                                                                                                                            | 790150 |
| 797 | 01/11/2016 | 569237 | Suspension O/S/R track rod bushes need replacing            |                                                                                                                                                                                                                                                                                                                              | 790150 |
| 797 | 01/11/2016 | 569237 | Engine hydraulic resivor leaking                            | Checked Hyd res. Ok                                                                                                                                                                                                                                                                                                          | 790150 |
| 797 | 01/11/2016 | 569237 | Monitor radiator coolant leak                               | Checked radiator leak OK                                                                                                                                                                                                                                                                                                     | 790150 |
| 797 | 01/11/2016 | 569237 | Ops Entered - Fault - Elec and Light Next Stop Buzzer N/W   | Try to trace fault in next stop circuit. Requires further testing buzzer OK                                                                                                                                                                                                                                                  | 790150 |
| 797 | 01/11/2016 | 569237 | GLOBE+HOLDER INSTRUMENT (GREY) NR47774                      |                                                                                                                                                                                                                                                                                                                              | 790150 |
| 797 | 01/11/2016 | 569237 | Elec and Light Interior Lights Dash lights N/W              | Replaced 3 globes                                                                                                                                                                                                                                                                                                            | 790150 |
| 797 | 01/11/2016 | 569237 | Elec and Light Exterior Lights O/S headlight kicks up to r  | Remove & reset head light to kick up to left & adjust beam Test OK                                                                                                                                                                                                                                                           | 790150 |
| 797 | 01/11/2016 | 569237 | GLOBE WEDGE 24V 1.2W HLW241.2 47706 SWFLED E-596FWLED       |                                                                                                                                                                                                                                                                                                                              | 790150 |
| 797 | 01/11/2016 | 569237 | Elec and Light Interior Lights Switch lights N/W            | Replaced globe                                                                                                                                                                                                                                                                                                               | 790150 |
| 797 | 01/11/2016 | 569237 | Body - Drivers seat hard                                    | Checked seat operation OK                                                                                                                                                                                                                                                                                                    | 790150 |
| 797 | 01/11/2016 | 569237 | Ops Entered - Fault - Body Drivers Seat Leaning - Route: 69 | Checked drivers seat. No fault found                                                                                                                                                                                                                                                                                         | 790150 |
| 797 | 01/11/2016 | 569237 | Body Rego label missing                                     |                                                                                                                                                                                                                                                                                                                              | 790150 |
| 797 | 01/11/2016 | 567002 | Direct Purchase - BODYWORK                                  | Creditor #;IB-EAS003 EASTCOAST TRUCK & BUS SERVICE P/O #:V160010A Receiving #:166081 Date :2016-01-12 CARRY OUT VANDALISM REPAIRS AS REQUIRED                                                                                                                                                                                | 790263 |
| 797 | 01/07/2016 | 568713 | Elec and Light Next Stop Button N/W                         |                                                                                                                                                                                                                                                                                                                              | 789841 |
| 797 | 01/07/2016 | 568713 | Drivers Seat Controls Cant move seat back far               | Checked drivers seat operation ok                                                                                                                                                                                                                                                                                            | 789841 |
| 797 | 01/07/2016 | 567002 | DIRECT PURCHASE ACCIDENT                                    | Creditor #;IB-EAS003 EASTCOAST TRUCK & BUS SERVICE P/O #:V160010 Receiving #:166080 Date :2016-01-12 UNREPORTED ACCIDENT DAMAGE - ACC #42264                                                                                                                                                                                 | 790263 |
| 797 | 01/06/2016 | 568408 | Drv entered - Elec and Light Next Stop Button               | Checked next stop system operation . Only buzzer componet N/W. Bus went out.                                                                                                                                                                                                                                                 | 789276 |
| 797 | 01/05/2016 | 555274 | Ops Entered - Fault - Wheels and Tyres Flat or Leaking - Ro | Checked OSR tyres. Pressures down 5 & 10 psi. Inflate tyres to 90 psi OK                                                                                                                                                                                                                                                     | 789276 |
| 797 | 01/05/2016 | 555274 | Mechanic entered - Elec and Light Other                     | Trace fault with bus not starting from front most times. System came good. Suspect faulty rear start switch. Order new switch                                                                                                                                                                                                | 789276 |
| 797 | 01/05/2016 | 555274 | Mechanic entered - Air System Air Not Building_Up           | Checked air system operation. Tighten union at moisture ejector& test. OK.                                                                                                                                                                                                                                                   | 789276 |
| 797 | 12/31/2015 | 567735 | Fixed                                                       | fixed                                                                                                                                                                                                                                                                                                                        | 788754 |
| 797 | 12/24/2015 | 567002 | Accident - unreported accident damage                       |                                                                                                                                                                                                                                                                                                                              | 788432 |
| 797 | 12/01/2015 | 562514 | Consumables                                                 |                                                                                                                                                                                                                                                                                                                              | 788432 |
| 797 | 12/01/2015 | 562514 | Remove Old Poster and Fit new All Night Public Transport Po | Carried out                                                                                                                                                                                                                                                                                                                  | 788432 |
| 797 | 11/01/2015 | 555274 |                                                             | SERVICE MOISTURE EJECTOR                                                                                                                                                                                                                                                                                                     | 786219 |
| 797 | 11/01/2015 | 555274 |                                                             | CARRY OUT TUNE-UP SERVICE AS PER CHECK LIST                                                                                                                                                                                                                                                                                  | 786219 |
| 797 | 11/01/2015 | 554800 | PERFORM CAMPAIGN 13/15 AIR CONDITIONING ELECTRICAL FIRE PRE |                                                                                                                                                                                                                                                                                                                              | 786219 |

|     |            |        |                                                             |                                                                                                                                                                                                                                             |        |
|-----|------------|--------|-------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|
| 797 | 11/01/2015 | 555420 | AIR CONDITIONING REPAIR                                     | Creditor #:IB-TRA012 TRACS (WA) PTY LTD P/O #:V157407 Receiving #:163565 Date :2015-11-12 CHECKED AND REPLACED FAULTY COND FAN MOTORS. FIT NEW DRIER AND REPLACED OIL. CLEANED COILS AND FILTER MEDIA. CHECKED FOR LEAKS. RUN AND TESTED OK | 788432 |
| 797 | 11/01/2015 | 556512 | GLOBE WEDGE 24V 1.2W HLW241.2 (47706 SWFLED E-596WLED )     | changed out globe for indicator signal light on instrument cluster                                                                                                                                                                          | 787858 |
| 797 | 11/01/2015 | 556213 | No turn signal on dash displayed                            | Bus sent to E.C.T.B Rebook                                                                                                                                                                                                                  | 787670 |
| 797 | 10/31/2015 | 556512 | Dash Dash_Lights Not Working - indicator / hazard light te  | changed out globe for indicator signal light on instrument cluster                                                                                                                                                                          | 787858 |
| 797 | 10/29/2015 | 556213 | LED NO PLATE+EXIT LIGHT                                     |                                                                                                                                                                                                                                             | 787670 |
| 797 | 10/29/2015 | 556213 | GLOBE WEDGE 24V 1.2W HLW241.2 (47706 SWFLED E-596WLED )     |                                                                                                                                                                                                                                             | 787670 |
| 797 | 10/29/2015 | 556213 | Saloon lights not working                                   | Replaced 3 fluros                                                                                                                                                                                                                           | 787670 |
| 797 | 10/29/2015 | 556213 | Front step light not working                                | replace step light globe                                                                                                                                                                                                                    | 787670 |
| 797 | 10/29/2015 | 556213 | Number plate light not working + switch lights not working  | replace no. plate light                                                                                                                                                                                                                     | 787670 |
| 797 | 10/29/2015 | 556213 | TUBES FLUORESCENT 18W                                       |                                                                                                                                                                                                                                             | 787670 |
| 797 | 10/29/2015 | 556213 | Saloon lights not working                                   | replace salloon light globes                                                                                                                                                                                                                | 787670 |
| 797 | 10/29/2015 | 556213 | Door ok light not working                                   | replace door ok lighting                                                                                                                                                                                                                    | 787670 |
| 797 | 10/29/2015 | 556213 | Rear door outside button stuck                              | clean outside door button clean outside door buttons                                                                                                                                                                                        | 787670 |
| 797 | 10/29/2015 | 556213 | Consumables                                                 |                                                                                                                                                                                                                                             | 787858 |
| 797 | 10/29/2015 | 556213 | Disabled seat wall hinges loose                             | repair seat wall hinge                                                                                                                                                                                                                      | 787670 |
| 797 | 10/27/2015 | 555452 | N/S/F air bags need replacing                               | Assisted                                                                                                                                                                                                                                    | 786219 |
| 797 | 10/26/2015 | 555450 | Service                                                     | VEHICLE SAFETY INSPECTION                                                                                                                                                                                                                   | 786219 |
| 797 | 10/26/2015 | 555450 | Service                                                     | TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS                                                                                                                                                                                                | 786219 |
| 797 | 10/26/2015 | 555452 | N/S/F air bags need replacing                               | Replaced front air bag EX SCANIA TEST BAG                                                                                                                                                                                                   | 786219 |
| 797 | 10/26/2015 | 555420 | A/C Heating Not Cooling                                     | Refer to Fault # 55526                                                                                                                                                                                                                      | 786219 |
| 797 | 10/26/2015 | 555420 | A/C Heating Not Heating                                     | Refer to Fault # 55526                                                                                                                                                                                                                      | 786219 |
| 797 | 10/26/2015 | 555420 | Drv entered - Cool & AC Sys                                 | Refer to Fault # 55526                                                                                                                                                                                                                      | 786219 |
| 797 | 10/26/2015 | 555420 | A/C Heating Not CoolingWith fans set to speed 5 can fe      | Refer to Fault # 55526                                                                                                                                                                                                                      | 786219 |
| 797 | 10/26/2015 | 555420 | A/C Heating Not Cooling                                     | Refer to Fault # 55526                                                                                                                                                                                                                      | 786219 |
| 797 | 10/26/2015 | 555420 | A/C Heating - Fans n/w                                      | SERVICED AND REPAIRED BY TRACS A/C TECH AND FAULTY REPLACED EVAP FANS                                                                                                                                                                       | 786219 |
| 797 | 10/26/2015 | 555420 | A/C Heating Not Cooling                                     | Refer to Fault # 55526                                                                                                                                                                                                                      | 786219 |
| 797 | 10/26/2015 | 555251 | Consumables                                                 |                                                                                                                                                                                                                                             | 787072 |
| 797 | 10/26/2015 | 555251 | Body Drivers Seat Controls seat will not lift up high eno   | Lubricated all seat pivots calibrated seat adjuster and checked operation of seat controls ok at this time                                                                                                                                  | 786219 |
| 797 | 10/26/2015 | 555450 | O-RING KIT OIL SPINNER FILTER SCANIA ABOVE ENG #6203050     |                                                                                                                                                                                                                                             | 786219 |
| 797 | 10/26/2015 | 555450 | FILTER TRANSMISSION ZF 4139-298-038/4139 298 038 01         |                                                                                                                                                                                                                                             | 786219 |
| 797 | 10/26/2015 | 555450 | FILTER FUEL SCANIA SR4( H17WK04)                            |                                                                                                                                                                                                                                             | 786219 |
| 797 | 10/26/2015 | 555450 | FILTER OIL SCANIA SR4 EARLY K320 (LF3730)(2059778)(H200W20) |                                                                                                                                                                                                                                             | 786219 |
| 797 | 10/26/2015 | 555450 | Service                                                     | B SERVICE AS PER CHECK LIST                                                                                                                                                                                                                 | 786219 |
| 797 | 10/26/2015 | 555450 | Consumables                                                 |                                                                                                                                                                                                                                             | 786219 |
| 797 | 10/26/2015 | 555450 | Consumables                                                 |                                                                                                                                                                                                                                             | 787072 |
| 797 | 10/26/2015 | 555450 | Consumables                                                 |                                                                                                                                                                                                                                             | 787072 |
| 797 | 10/26/2015 | 555450 | Consumables                                                 | A SERVICE AS PER CHECK LIST                                                                                                                                                                                                                 | 787072 |
| 797 | 10/26/2015 | 555450 | Service                                                     |                                                                                                                                                                                                                                             | 786219 |
| 797 | 10/26/2015 | 555450 | Consumables                                                 |                                                                                                                                                                                                                                             | 787072 |
| 797 | 10/26/2015 | 555450 | Consumables                                                 |                                                                                                                                                                                                                                             | 787072 |
| 797 | 10/26/2015 | 555450 | Consumables                                                 |                                                                                                                                                                                                                                             | 787072 |
| 797 | 10/26/2015 | 555450 | Consumables                                                 |                                                                                                                                                                                                                                             | 787072 |
| 797 | 10/08/2015 | 552007 | Complete task as instructed in Fleet Campaign 09/15         | completed                                                                                                                                                                                                                                   | 782848 |
| 797 | 10/08/2015 | 552139 | Consumables                                                 |                                                                                                                                                                                                                                             | 783373 |
| 797 | 10/08/2015 | 551913 | Consumables                                                 |                                                                                                                                                                                                                                             | 783373 |
| 797 | 10/08/2015 | 552139 | Replace A3 poster with Victorian Seniors Festival Poster    | completed                                                                                                                                                                                                                                   | 782848 |
| 797 | 10/08/2015 | 551913 | Campaign 11/15. Fit 2 x Supplied Decals to Internal Saloo   | completed                                                                                                                                                                                                                                   | 782848 |
| 797 | 10/01/2015 | 550712 | Consumables                                                 |                                                                                                                                                                                                                                             | 782167 |
| 797 | 10/01/2015 | 550712 | as per Campaign 08/15Fit Hi Vis Vest DecalFit Coat Hook i   | completed as per campaign 08/15                                                                                                                                                                                                             | 781307 |
| 797 | 09/29/2015 | 549759 | Horn not working                                            | horn repaired bu Mr Caminiti on 28-9-15                                                                                                                                                                                                     | 781307 |
| 797 | 09/29/2015 | 549759 | Check CCTV                                                  | CCTV checks out ok. Cannot fault                                                                                                                                                                                                            | 781307 |
| 797 | 09/29/2015 | 549759 | Check CCTV                                                  | CCTV checks out ok. Cannot fault                                                                                                                                                                                                            | 781307 |
| 797 | 09/29/2015 | 549759 | Drivers seat pivots worn (all)                              | Tightened up drivers seat cusion                                                                                                                                                                                                            | 781307 |
| 797 | 09/29/2015 | 549759 | Step edge to rear of bus lifting                            | Step edges re-secured                                                                                                                                                                                                                       | 781307 |
| 797 | 09/28/2015 | 549373 | Check Two Way Radio                                         | checked two way operation ok                                                                                                                                                                                                                | 781090 |
| 797 | 09/28/2015 | 549373 | Elec and Light Horn horn not working                        | cleaned horn contacts and test working ok                                                                                                                                                                                                   | 781090 |
| 797 | 09/28/2015 | 549373 | Elec and Light Horn Horn not working                        | cleaned horn contacts and test working ok                                                                                                                                                                                                   | 781090 |
| 797 | 09/28/2015 | 549373 | Fire extinguisher out of date                               | checked ok in date                                                                                                                                                                                                                          | 781090 |
| 797 | 09/28/2015 | 549373 | No triangle sticker fitted                                  | fitted decal                                                                                                                                                                                                                                | 781090 |
| 797 | 09/28/2015 | 549373 | DECAL SAFETY TRIANGLES                                      |                                                                                                                                                                                                                                             | 781090 |
| 797 | 09/28/2015 | 549373 | Hand rail screws loose in roof                              | replaced missing screw and nipped up other loose screws                                                                                                                                                                                     | 781090 |
| 797 | 09/28/2015 | 549373 | Rear door sensitive edge not working                        | Adjusted door edge                                                                                                                                                                                                                          | 781090 |
| 797 | 09/28/2015 | 549373 | Wheelchair ramp hinge pin                                   | checked pushed back in                                                                                                                                                                                                                      | 781090 |
| 797 | 09/23/2015 | 548555 | Update destination Files and Check display                  | COMPLETED CAMPAIGN                                                                                                                                                                                                                          | 780574 |
| 797 | 09/15/2015 | 547182 | BATTERY 700CCA EMFN120                                      |                                                                                                                                                                                                                                             | 779356 |
| 797 | 09/15/2015 | 547182 | Mechanic entered - Elec and Light Other Batteries u/s       | Replaced batteries. Start and test ok                                                                                                                                                                                                       | 779356 |
| 797 | 09/15/2015 | 547180 | LED FRONT POSITION MARKER LIGHT                             |                                                                                                                                                                                                                                             | 779356 |
| 797 | 09/15/2015 | 547180 | N/S emergency exit light not working                        | Replaced N/S emergency exit light                                                                                                                                                                                                           | 779356 |
| 797 | 09/04/2015 | 544977 | Consumables                                                 |                                                                                                                                                                                                                                             | 777488 |
| 797 | 09/04/2015 | 544977 | Consumables                                                 |                                                                                                                                                                                                                                             | 777488 |
| 797 | 09/04/2015 | 544977 | Consumables                                                 |                                                                                                                                                                                                                                             | 777488 |
| 797 | 09/04/2015 | 544977 | Service                                                     | A SERVICE AS PER CHECK LIST                                                                                                                                                                                                                 | 777192 |
| 797 | 09/03/2015 | 544977 | Service                                                     | TRANSMISSION CHECK AS PER CHECK LIST                                                                                                                                                                                                        | 777192 |
| 797 | 09/03/2015 | 544977 | Service                                                     | TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS                                                                                                                                                                                                | 777192 |
| 797 | 09/03/2015 | 544977 | Service                                                     | VEHICLE SAFETY INSPECTION                                                                                                                                                                                                                   | 777192 |
| 797 | 08/27/2015 | 541130 | DIRECT PURCHASE - AIR CONDITIO                              | Creditor #:IB-EAS003 EASTCOAST TRUCK & BUS SERVICE P/O #:V154795 Receiving #:160520 Date :2015-08-27                                                                                                                                        | 775511 |
| 797 | 08/24/2015 | 542948 | Consumables                                                 |                                                                                                                                                                                                                                             | 775041 |
| 797 | 08/24/2015 | 542948 | Elec and Light (None) - Flat Battery                        | Batteries put on charge                                                                                                                                                                                                                     | 774765 |
| 797 | 08/20/2015 | 542371 | Complete Campaign 6/15 A3 Marketing Poster Change           | Complete                                                                                                                                                                                                                                    | 774452 |
| 797 | 08/20/2015 | 542236 | Audit Route buses for correct Decals and positions. Replace | Complete                                                                                                                                                                                                                                    | 774452 |
| 797 | 08/14/2015 | 541130 |                                                             | REPLACE A/C FILTER/DRIER                                                                                                                                                                                                                    | 773902 |
| 797 | 08/14/2015 | 541130 |                                                             | CARRY OUT B SERVICE                                                                                                                                                                                                                         | 773902 |
| 797 | 08/14/2015 | 541130 |                                                             | CHECK BOOST PUMP OPERATION                                                                                                                                                                                                                  | 773902 |
| 797 | 08/14/2015 | 541130 |                                                             | CHECK & REPLACE ELECTRIC MOTOR BRUSHES WHERE APPLICABLE                                                                                                                                                                                     | 773902 |
| 797 | 08/14/2015 | 541130 |                                                             | REPLACE A/C COMPRESSOR OIL                                                                                                                                                                                                                  | 773902 |
| 797 | 08/14/2015 | 541130 |                                                             | UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensor pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation | 773902 |
| 797 | 08/14/2015 | 541130 |                                                             | CONDENSOR AREA: Clean condensor coils; check boltsclamps for tension                                                                                                                                                                        | 773902 |
| 797 | 08/14/2015 | 541130 |                                                             | INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condensor fan grills                 | 773902 |
| 797 | 08/14/2015 | 541130 |                                                             | EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check boltsclamps & fittings; clean condensate drains; clean drip tray                                                                                                 | 773902 |
| 797 | 08/14/2015 | 541130 |                                                             | REFRIGERATION FILTER DRYER: Replace filter dryer; check pump operation;                                                                                                                                                                     | 773902 |
| 797 | 08/14/2015 | 541130 |                                                             | DRIVE PULLEY'S: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear                                                                                                                    | 773902 |
| 797 | 08/14/2015 | 541130 |                                                             | DRIVE PULLEY'S: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;                                                                                                                                    | 773902 |
| 797 | 08/14/2015 | 541130 |                                                             | FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)                                                                                                                                                                        | 773902 |
| 797 | 08/14/2015 | 541130 |                                                             | Clean R/A & F/A filters; inspect and report on condition; Replace filter media                                                                                                                                                              | 773902 |
| 797 | 08/14/2015 | 541130 |                                                             | COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose                                                                             | 773902 |

|                                                                                    |                                                                                                                       |        |
|------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------|--------|
| 797 08/14/2015 541130                                                              | COMPRESSOR DRIVE BELTS: Inspect belt wear; Retension belts;                                                           | 773902 |
| 797 08/13/2015 540904 A/C Heating Noisy - Noisy bearing from roof                  | AC not excessively loud at this time.                                                                                 | 773902 |
| 797 08/13/2015 540904 Consumables                                                  |                                                                                                                       | 774078 |
| 797 08/13/2015 540904 Elec and Light desto requires reprogramming. Old 670 file    | Desto requires reprograming.                                                                                          | 773902 |
| 797 08/13/2015 540904 Elec and Light AM-FM Radio - driver speaker cutting in and   | Speaker not cutting out just reception dropping out due to trees.                                                     | 773902 |
| 797 08/13/2015 540904 Body Drivers Seat Leaning to the left                        | Replaced drivers seat base.                                                                                           | 773902 |
| 797 08/13/2015 540904 CUSHION FOAM ISRI SEAT                                       |                                                                                                                       | 773902 |
| 797 08/13/2015 540904 Ops Entered - Fault - Body Drivers Seat Leaning - Route: 69  | Replaced drivers seat base.                                                                                           | 773902 |
| 797 07/28/2015 535874 Water ejector leaking air at top fitting                     | Replaced air bag control valve block.                                                                                 | 770379 |
| 797 07/25/2015 537146 WHEEL NUTS RE-TENSION Bookback from W/O:537146 Wheels and Ty | WHEEL NUTS RE-TENSIONED                                                                                               | 770076 |
| 797 07/24/2015 535874 Water ejector leaking air at top fitting                     | Checked air leak. Air bag valve needs replacing. Air coming from solenoid vlave.                                      | 768112 |
| 797 07/24/2015 537092 Front N/S air bag split                                      | Checked air bag. Split only exposed when bag deflated. Not leaking at this time.                                      | 769447 |
| 797 07/24/2015 537092 Monitor - tail shaft unit has movement                       | Checked tail shaft unis. No movement. Slight play in slip joint. Not excessive at this stage.                         | 769447 |
| 797 07/24/2015 537092 Wash engine                                                  | Washed engine for leaks.                                                                                              | 769447 |
| 797 07/24/2015 537092 CCTV not working                                             | Checked CCTV operation. Could not fault. All Cameras working Hard drive recording. Test ok                            | 769447 |
| 797 07/24/2015 537092 Top door guide rail front and rear U/S                       | Replaced top guide rollers on front and rear doors.                                                                   | 769447 |
| 797 07/23/2015 537146 Consumables                                                  |                                                                                                                       | 770076 |
| 797 07/23/2015 537146 TYRE NEW 295/80R22.5                                         |                                                                                                                       | 769447 |
| 797 07/23/2015 537146 Wheels and Tyres front tyre Worn 3mm 9/07/15                 | Replaced front tyres ok                                                                                               | 769447 |
| 797 07/23/2015 537092 INDICATOR SWITCH SCANIA L94UAB 40v4703                       |                                                                                                                       | 769447 |
| 797 07/23/2015 537092 Elec and Light - Indicator self cancel n/w                   | Replaced indiactor stalk                                                                                              | 769447 |
| 797 07/23/2015 537092 Drivers seat excessive movement                              | Checked ok                                                                                                            | 769447 |
| 797 07/23/2015 537092 Front N/S seat mount                                         | Checked ok                                                                                                            | 769447 |
| 797 07/23/2015 537092 Rear door lower pivot excessive movement                     |                                                                                                                       | 769447 |
| 797 07/23/2015 537092 GUIDE ROD DOOR LONG TYPE                                     |                                                                                                                       | 769447 |
| 797 07/23/2015 537092 Body - Drivers seat lacks suspension                         | Adjusted suspension weight control ok                                                                                 | 769447 |
| 797 07/22/2015 536863 Elec and Light Flat batteries                                | Jump start bus                                                                                                        | 769447 |
| 797 07/17/2015 535874 Direct Purchase - MECHANICAL                                 | Creditor # :IB-PIR001 PIRTEK BAYSWATER P/O #:V153804 Receiving #:158841 Date :2015-07-21 Make up hose as required     | 769447 |
| 797 07/16/2015 535874 HOSE COMP FEED                                               |                                                                                                                       | 768112 |
| 797 07/16/2015 535874 Mechanic entered - Air System Air_Leak Rear Air hose from ai | Replaced split hose                                                                                                   | 768112 |
| 797 07/15/2015 535874 Vandalism Vandalism/ Graffiti Interior                       | clean graffiti from seat backs & trim                                                                                 | 768112 |
| 797 07/15/2015 535871 TUBES FLUORESCENT 18W                                        |                                                                                                                       | 768112 |
| 797 07/15/2015 535871 Rear outside exit light not working                          | Replaced rear door external step light globe                                                                          | 768112 |
| 797 07/09/2015 534908 Service                                                      | TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS                                                                          | 767082 |
| 797 07/09/2015 534908 Service                                                      | VEHICLE SAFETY INSPECTION                                                                                             | 767082 |
| 797 07/09/2015 534908 Consumables                                                  |                                                                                                                       | 767597 |
| 797 07/09/2015 534908 Consumables                                                  |                                                                                                                       | 767597 |
| 797 07/09/2015 534908 Consumables                                                  |                                                                                                                       | 767597 |
| 797 07/09/2015 534908 FILTER OIL SCANIA SR4 EARLY K320 (LF3730)(2059778)(H200W20)  |                                                                                                                       | 767082 |
| 797 07/09/2015 534908 FILTER FUEL SCANIA SR4( H17WK04)                             |                                                                                                                       | 767082 |
| 797 07/09/2015 534908 FILTER TRANSMISSION ZF ( 4139-298-038)(4139 298 038 01)      |                                                                                                                       | 767082 |
| 797 07/09/2015 534908 O-RING KIT OIL SPINNER FILTER SCANIA                         |                                                                                                                       | 767082 |
| 797 07/09/2015 534908 Service                                                      | B SERVICE AS PER CHECK LIST                                                                                           | 767082 |
| 797 07/09/2015 534908 Consumables                                                  |                                                                                                                       | 767597 |
| 797 07/09/2015 534908 Consumables                                                  |                                                                                                                       | 767597 |
| 797 07/09/2015 534908 Consumables                                                  |                                                                                                                       | 767597 |
| 797 07/09/2015 534908 Service                                                      | A SERVICE AS PER CHECK LIST                                                                                           | 767082 |
| 797 06/16/2015 531245 Consumables                                                  |                                                                                                                       | 762695 |
| 797 06/16/2015 531245 Body Drivers Seat Controls - seat is leaning loose & boun    | Dismantle & lube seat adjuster & pivots. Check base cusion OK assemble seat & reset adjuster> Test seat operation OK  | 762321 |
| 797 06/09/2015 530196 Elec and Light Nearside front bottom Indicator Not Working   | Refitted globe in holder                                                                                              | 761068 |
| 797 06/03/2015 529465 GLOBE H1 24V 70W                                             |                                                                                                                       | 760048 |
| 797 06/03/2015 529465 Elec and Light :- Headlight not working                      | Replace headlight globe                                                                                               | 760048 |
| 797 05/31/2015 527132 Body Drivers Seat Controls Hieght control not working. As    | Rebook                                                                                                                | 756935 |
| 797 05/26/2015 526551 Body Windows Side :- drivers side window no latch.           | fitted new latch                                                                                                      | 756935 |
| 797 05/26/2015 526551 Body Windows Side :- drivers side window no latch.           | Replaced catch                                                                                                        | 756935 |
| 797 05/26/2015 517592 TURBO SCANIA L94                                             | Creditor # :IB-EAS003 EASTCOAST TRUCK & BUS SERVICE P/O #:V150943 Receiving #:155955 Date :2015-05-26                 | 758858 |
| 797 05/22/2015 526551 DRIVERS WINDOW CATCH                                         | Creditor # :IB-EAS003 EASTCOAST TRUCK & BUS SERVICE P/O #:V150943 Receiving #:155868 Date :2015-05-22 MM              | 758212 |
| 797 05/20/2015 527152 Body . Light cover in rear off Bus fallen out.               | Refitted light difuser                                                                                                | 756935 |
| 797 05/20/2015 527132 Body Drivers Seat Controls Hieght control not working. As    | springs over streched change over/referbed seat needed hight control and weight control working                       | 756935 |
| 797 05/18/2015 526551 Graffiti on rear seat                                        | cleaned off                                                                                                           | 756935 |
| 797 05/18/2015 526551 N/S/R seat base torn                                         | repaired base                                                                                                         | 756935 |
| 797 05/18/2015 526551 N/S/R seat base torn                                         | repaired seat base                                                                                                    | 756935 |
| 797 05/18/2015 526551 Pinion seal leaking                                          | slight swet washed off and run ok                                                                                     | 756935 |
| 797 05/18/2015 526551 N/S saloon light N/W                                         | replaced light tube                                                                                                   | 756935 |
| 797 05/18/2015 526551 Front door fluro N/W                                         | replaced light tube                                                                                                   | 756935 |
| 797 05/18/2015 526551 GLOBE WEDGE 24V 1.2W HLW241.2 (47706 SWFLED E-596WLED )      |                                                                                                                       | 756935 |
| 797 05/18/2015 526551 TUBES FLUORESCENT 18W                                        |                                                                                                                       | 756935 |
| 797 05/18/2015 526551 AM/FM radio intermittantly looses power.                     | working ok no fault found                                                                                             | 756935 |
| 797 05/18/2015 526551 N/S number plate light N/W                                   | checked working ok                                                                                                    | 756935 |
| 797 05/18/2015 526551 Switch lights N/W                                            | replaced globe                                                                                                        | 756935 |
| 797 05/18/2015 526551 L/H tachometer light N/W                                     | replaced globes                                                                                                       | 756935 |
| 797 05/18/2015 526551 O/S/R 2nd last seat base needs securing                      | refixed bolard                                                                                                        | 756935 |
| 797 05/18/2015 526551 Drivers modesty panel stickers?                              | sticker ok                                                                                                            | 756935 |
| 797 05/18/2015 526551 Steering wheel rubber peeling                                | removed rubber ok to run                                                                                              | 756935 |
| 797 05/18/2015 526551 Body Drivers Seat Controls :- Weight control just spins ar   | un jam weight control and refitted handle                                                                             | 756935 |
| 797 05/18/2015 526551 Accelerator pedal squeeks                                    | lubed pedal                                                                                                           | 756935 |
| 797 05/18/2015 526551 No Bin in Bus                                                | BIN IS IN BUS                                                                                                         | 756935 |
| 797 05/18/2015 526551 Desto sign scrambled                                         | checked working ok no fault found                                                                                     | 756935 |
| 797 05/18/2015 526551 No rubbish bin                                               | removed loose rubber ok to run bin in bus                                                                             | 756935 |
| 797 05/15/2015 526323 Service                                                      | TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS                                                                          | 756935 |
| 797 05/15/2015 526323 Service                                                      | VEHICLE SAFETY INSPECTION                                                                                             | 756935 |
| 797 05/15/2015 526323 Consumables                                                  |                                                                                                                       | 757171 |
| 797 05/15/2015 526323 Consumables                                                  |                                                                                                                       | 757171 |
| 797 05/15/2015 526323 Service                                                      | A SERVICE AS PER CHECK LIST                                                                                           | 756935 |
| 797 05/14/2015 525999 TUBES FLUORESCENT 18W                                        |                                                                                                                       | 756935 |
| 797 05/14/2015 525999 Outdoor step light n/w                                       | Replaced fluro tube                                                                                                   | 756935 |
| 797 05/09/2015 525293 Replace See Something Say Something Poster                   | Replace See Something Say Something Poster                                                                            | 755380 |
| 797 04/16/2015 519085 DIRECT PURCHASE - ELECTRICAL                                 |                                                                                                                       | 750437 |
| 797 04/16/2015 519085 Emergency hammer alarm not working                           | Rewired hammer circuit and fitted relay to buzzer and light circuits                                                  | 750437 |
| 797 04/15/2015 519085 Emergency hammer alarm not working                           | Traced through all hammer circuits Fit resistor to buzzer circuit to stop buzzer constantly on Test OK but A bit soft | 750437 |
| 797 04/14/2015 519085 Secure bracket blow A/C compressor holding wet tank          | Secure bracket                                                                                                        | 750437 |
| 797 04/14/2015 519085 Emergency hammer alarm not working                           | Traced through hammer circuits                                                                                        | 750437 |
| 797 04/14/2015 519732 Not starting from front                                      | Checked starting Ok at this time                                                                                      | 750437 |

|                |        |                                                             |                                                                                                                                                                      |        |
|----------------|--------|-------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|
| 797 04/13/2015 | 519085 | Muffler missing off relay valve                             | Fitted new silencer mount & S/H silencer to rear relay valve replacedheader tank & clean low coolant sensor. Secure coolant filler neck &repostion sightglass piping | 750204 |
| 797 04/13/2015 | 519085 | Header tank leaking                                         |                                                                                                                                                                      | 750204 |
| 797 04/13/2015 | 519732 | Not starting from front                                     | Test start circuits Batt voltage low21.5v Load test batts OK Checked charge rate OK. 27.5v Put batts on charge                                                       | 750204 |
| 797 04/09/2015 | 519085 | SILENCER AIR VALVE 22MM                                     | Creditor #:IB-EAS003 EASTCOAST TRUCK & BUS SERVICE P/O #:V149859 Receiving #:153511 Date :2015-04-09                                                                 | 750204 |
| 797 04/08/2015 | 519085 | RELAY VALVE                                                 | Creditor #:IB-EAS003 EASTCOAST TRUCK & BUS SERVICE P/O #:V149859 Receiving #:153492 Date :2015-04-08                                                                 | 749976 |
| 797 04/07/2015 | 519085 | EXPANSION                                                   | Creditor #:IB-EAS003 EASTCOAST TRUCK & BUS SERVICE P/O #:V149859 Receiving #:153346 Date :2015-04-07                                                                 | 749587 |
| 797 04/07/2015 | 519732 | Not starting from front                                     |                                                                                                                                                                      | 749587 |
| 797 04/04/2015 | 519732 | Not starting from front                                     | Checked for no starting fault moved bus and put o/r                                                                                                                  | 749587 |
| 797 04/01/2015 | 519085 | Header tank leaking                                         | Replaced header tank & clean low coolant sensor. Secure coolant filler neck&repostion sight glass piping                                                             | 749047 |
| 797 03/31/2015 | 519085 | Muffler missing off relay valve                             | Check & order rear valve muffler                                                                                                                                     | 749047 |
| 797 03/31/2015 | 519085 | Header tank leaking                                         | Check header tank leak & order tank                                                                                                                                  | 749047 |
| 797 03/31/2015 | 519085 | Secure bracket blow A/C compressor holding wet tank         | Wash brackets & chassis attempt to secure wet tank brackets further work required                                                                                    | 749047 |
| 797 03/31/2015 | 519085 | Consumables                                                 |                                                                                                                                                                      | 749047 |
| 797 03/31/2015 | 519085 | GLOBE WEDGE 24V 1.2W HLW241.2 (47706 SWFLED E-596WLED )     |                                                                                                                                                                      | 749047 |
| 797 03/31/2015 | 519085 | FLURO TUBE 24V 18W 24"                                      |                                                                                                                                                                      | 749047 |
| 797 03/31/2015 | 519085 | Saloon lights not working                                   | Replaced saloon light fluro                                                                                                                                          | 749047 |
| 797 03/31/2015 | 519085 | Switch light not working                                    | Replaced 4 switch light globes                                                                                                                                       | 749047 |
| 797 03/31/2015 | 519085 | Front brakes low                                            | Remove both front wheels & check pads rebook 2 weeks n/sf worst                                                                                                      | 749047 |
| 797 03/26/2015 | 518124 | Fan motor shaft seal leaking                                | Checked not excessive at this time                                                                                                                                   | 746868 |
| 797 03/26/2015 | 517584 | Afetr a loud bang engine won't go over 20kph                | Finished replacing turbo                                                                                                                                             | 746868 |
| 797 03/25/2015 | 517270 | WHEEL NUTS RE-TENSION Bookback from W/O:517270 N/Side inner | WHEEL NUTS RE-TENSIONED                                                                                                                                              | 746868 |
| 797 03/25/2015 | 517584 | Afetr a loud bang engine won't go over 20kph                | Removed turbo cleaned debris out of intercooler washed intake pipingchanged engine oil and filters replaced air filter started fitting up new turbo                  | 746868 |
| 797 03/25/2015 | 517584 | FILTER AIR OUTER SCANIA SR3 SR4 (AF25066)(0395773)          |                                                                                                                                                                      | 746868 |
| 797 03/25/2015 | 517584 | O-RING KIT OIL SPINNER FILTER SCANIA                        |                                                                                                                                                                      | 746868 |
| 797 03/25/2015 | 517584 | FILTER OIL SCANIA SR4 EARLY K320 (LF3730)(2059778)(H200W20) |                                                                                                                                                                      | 746868 |
| 797 03/24/2015 | 517584 | Afetr a loud bang engine won't go over 20kph                |                                                                                                                                                                      | 746868 |
| 797 03/24/2015 | 517715 | ENGINE TURBO NEEDS REPLACING                                | Engine turbo needs relplacing                                                                                                                                        | 746868 |
| 797 03/24/2015 | 517592 | Direct Purchase - MECHANICAL                                | TOW BUS INTO WORKSHOP AND STAR TO REMOVE TURBO                                                                                                                       | 746868 |
| 797 03/24/2015 | 517592 | Ops Entered - Breakdown - Breakdown Mech Defect Affects Ser | Creditor #:IB-EAG001 EAGLE TOWING AND SALVAGE P/O #:V149651 Receiving #:153266 Date :2015-04-02 TOW BUS FROM MT EVELYN YORK RD TO LILYDALE DEPOT                     | 749321 |
| 797 03/23/2015 | 517342 | Can only start Bus from rear.                               | Mechanic sent to Mt evelyn to investergate turbo u/s call and assist tow truck                                                                                       | 746868 |
| 797 03/21/2015 | 517270 | Consumables                                                 | Inspected vehicle starts from key all ok                                                                                                                             | 746868 |
| 797 03/21/2015 | 517270 | TYRE RECAP 295/80R22.5                                      |                                                                                                                                                                      | 747760 |
| 797 03/21/2015 | 517270 | N/Side inner tyre punctured.                                | Fitted 2 new caps to OSR                                                                                                                                             | 746868 |
| 797 03/20/2015 | 516854 | WHEEL NUTS RE-TENSION Bookback from W/O:516854 O/S/R/I tyre | WHEEL NUTS RE-TENSIONED                                                                                                                                              | 746868 |
| 797 03/20/2015 | 517153 | Consumables                                                 |                                                                                                                                                                      | 747724 |
| 797 03/20/2015 | 517153 | Rear seat base removed                                      | Replaced seat base                                                                                                                                                   | 746868 |
| 797 03/20/2015 | 516819 | Consumables                                                 |                                                                                                                                                                      | 747724 |
| 797 03/20/2015 | 516819 | Consumables                                                 |                                                                                                                                                                      | 747724 |
| 797 03/20/2015 | 516819 | Consumables                                                 |                                                                                                                                                                      | 747724 |
| 797 03/20/2015 | 516819 | HYDRAULIC TORQUE FLUID 414                                  |                                                                                                                                                                      | 746868 |
| 797 03/20/2015 | 516819 | OIL ENGINE DELO 400LE 15W40 (LU18)                          |                                                                                                                                                                      | 746868 |
| 797 03/19/2015 | 516819 | FILTER OIL SCANIA SR4 EARLY K320 (LF3730)(2059778)(H200W20) |                                                                                                                                                                      | 746868 |
| 797 03/19/2015 | 516819 | O-RING KIT OIL SPINNER FILTER SCANIA                        |                                                                                                                                                                      | 746868 |
| 797 03/19/2015 | 516819 | FILTER FUEL SCANIA SR4( H17WK04)                            |                                                                                                                                                                      | 746868 |
| 797 03/19/2015 | 516819 | Service                                                     | TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS                                                                                                                         | 746868 |
| 797 03/19/2015 | 516819 | Service                                                     | VEHICLE SAFETY INSPECTION                                                                                                                                            | 746868 |
| 797 03/19/2015 | 516819 | FILTER TRANSMISSION ZF ( 4139-298-038)(4139 298 038 01)     |                                                                                                                                                                      | 746868 |
| 797 03/19/2015 | 516854 | Consumables                                                 |                                                                                                                                                                      | 747454 |
| 797 03/19/2015 | 516854 | O/S/R/I tyre tread low                                      | Replaced O/S/R/I tyre with good second hand tyre                                                                                                                     | 746868 |
| 797 03/19/2015 | 516819 | FILTER AIR OUTER SCANIA SR3 SR4 (AF25066)(0395773)          |                                                                                                                                                                      | 746868 |
| 797 03/19/2015 | 516819 | Service                                                     |                                                                                                                                                                      | 746868 |
| 797 03/19/2015 | 516819 | Consumables                                                 | B SERVICE AS PER CHECK LIST                                                                                                                                          | 747454 |
| 797 03/19/2015 | 516819 | Consumables                                                 |                                                                                                                                                                      | 747454 |
| 797 03/19/2015 | 516819 | Consumables                                                 |                                                                                                                                                                      | 747454 |
| 797 03/19/2015 | 516819 | Service                                                     |                                                                                                                                                                      | 747454 |
| 797 03/18/2015 | 516607 | Drv entered - Brakes Noisy                                  | A SERVICE AS PER CHECK LIST                                                                                                                                          | 746868 |
| 797 03/17/2015 | 516614 | Consumables                                                 |                                                                                                                                                                      | 747066 |
| 797 03/17/2015 | 516614 | back seat has been slashed foam exposed                     | Repaired seat back cushion                                                                                                                                           | 746868 |
| 797 03/13/2015 | 516030 | Service                                                     | TRANSMISSION CHECK AS PER CHECK LIST                                                                                                                                 | 745969 |
| 797 03/06/2015 | 515082 | Consumables                                                 |                                                                                                                                                                      | 745371 |
| 797 03/06/2015 | 515082 | COMPLETE VEHICLE DETAILS AUDIT CHECK LIST                   | COMPLETE VEHICLE DETAILS AUDIT CHECK LIST                                                                                                                            | 744197 |
| 797 02/28/2015 | 513875 | Drv entered - Wipers & Washers Not Cleaning Screen          | Top up water                                                                                                                                                         | 743103 |
| 797 02/28/2015 | 513875 | Drv entered - Wipers & Washers Washers Not Working          | Top up water                                                                                                                                                         | 743103 |
| 797 02/28/2015 | 513875 | Unable to start Bus via ignition key.                       | Check and isolator switch                                                                                                                                            | 743103 |
| 797 02/28/2015 | 513875 | Desto sign jumbled                                          | Desto reseted                                                                                                                                                        | 743103 |
| 797 02/24/2015 | 512968 | A3 Poster Change                                            | campaign completed                                                                                                                                                   | 742527 |
| 797 02/24/2015 | 512967 | A3 Poster Change                                            | campaign completed                                                                                                                                                   | 742527 |
| 797 02/03/2015 | 509250 | O/S/F upper torque rod bush needs replacing                 | rebooked                                                                                                                                                             | 737395 |
| 797 02/03/2015 | 509250 | N/S number plate light n/w                                  | rebooked                                                                                                                                                             | 737395 |
| 797 02/03/2015 | 509250 | Pressure limiting valve needs adjusting                     | rebooked                                                                                                                                                             | 737395 |
| 797 01/31/2015 | 509250 | N/S number plate light n/w                                  | Parts ordered. waiting on led number plate light                                                                                                                     | 737395 |
| 797 01/31/2015 | 509250 | Rear door internal step light needs securing                | Secured rear door step light ok                                                                                                                                      | 737395 |
| 797 01/31/2015 | 509250 | D light N/W                                                 | Fit second hand globe to gear selector ok                                                                                                                            | 737395 |
| 797 01/31/2015 | 509250 | Coolant leak at header tank                                 | Replaced section of bleeder hose off header tank washed and checked for leaks ok                                                                                     | 737395 |
| 797 01/31/2015 | 509249 | Consumables                                                 |                                                                                                                                                                      | 737796 |
| 797 01/31/2015 | 509249 | DECAL 2 WHEEL CHAIR SPACES                                  |                                                                                                                                                                      | 737395 |
| 797 01/31/2015 | 509249 | External wheelchair decal needs replacing                   | Replaced external wheelchair ramp sticker ok                                                                                                                         | 737395 |
| 797 01/29/2015 |        | Imported Service History                                    | Imported Service History                                                                                                                                             | 737395 |
| 797 01/29/2015 | 508917 | Consumables                                                 |                                                                                                                                                                      | 737489 |
| 797 01/29/2015 | 508917 | Consumables                                                 |                                                                                                                                                                      | 737489 |
| 797 01/29/2015 | 508917 | Service                                                     | A - Service & Bus Safety Inspection                                                                                                                                  | 737395 |
| 797 01/29/2015 | 508917 | Service                                                     | Tension ALL Wheel Nuts to OEM Specs                                                                                                                                  | 737395 |
| 797 01/29/2015 | 508917 | Service                                                     | A - Service & Bus Safety Inspection                                                                                                                                  | 737395 |
| 797 01/19/2015 | 505226 | DIRECT PURCHASE - BUS INSPECTI                              | Creditor #:IB-ROA003 ROAD SAFETY INSPECTIONS P/L P/O #:V147285 Receiving #:149685 Date :2015-01-21                                                                   | 735205 |
| 797 01/11/2015 | 505226 | Service                                                     | RSI R.W.C # 486233                                                                                                                                                   | 734168 |
| 797 01/05/2015 | 501838 | Door ramp trim missing                                      | Fitted ramp trim                                                                                                                                                     | 733038 |
| 797 01/05/2015 | 504922 | Door ramp trim missing                                      |                                                                                                                                                                      | 733038 |
| 797 01/05/2015 | 504922 | Consumables                                                 |                                                                                                                                                                      | 733256 |
| 797 01/05/2015 | 504922 | Wheelchair ramp missing piece                               | fitted trim                                                                                                                                                          | 733038 |
| 797 01/02/2015 | 496882 | Service                                                     | AB AUTO AIR REPLACED EVP FANS AND SECURED CONDENSOR FANS AS REQUIRED                                                                                                 | 730793 |
| 797 01/01/2015 | 496882 | AIR CONDITIONING REPAIR                                     | Creditor #:IB-ABA001 AB AUTO AIR P/O #:V146441 Receiving #:149606 Date :2015-01-19 Replaced and secured loose evp / condensor fans                                   | 735205 |
| 797 12/31/2014 | 501838 | Floor hatch al surround                                     | Creditor #:IB-EAS003 EASTCOAST TRUCK & BUS SERVICE P/O #:V146530 Receiving #:149050 Date :2014-12-31                                                                 | 732792 |
| 797 12/24/2014 | 503763 | GLOBE WEDGE 24V 1.2W HLW241.2 (47706 SWFLED E-596WLED )     |                                                                                                                                                                      | 732290 |

|     |            |        |                                                              |                                                                                                                      |  |        |
|-----|------------|--------|--------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------|--|--------|
| 797 | 12/24/2014 | 503763 | FLURO TUBE 24V 18W 24'                                       |                                                                                                                      |  | 732290 |
| 797 | 12/24/2014 | 503763 | Rear door external step light N/W                            | Fit new fluro tube to rear door step light ok                                                                        |  | 732290 |
| 797 | 12/24/2014 | 503763 | Saloon lights N/W                                            | Fit new fluro tubes to saloon lights ok                                                                              |  | 732290 |
| 797 | 12/24/2014 | 503763 | Switch lights N/W                                            | Fit new switch light globes ok                                                                                       |  | 732290 |
| 797 | 12/24/2014 | 503763 | Rego label peeling off                                       | Fit new rego sticker ok                                                                                              |  | 732290 |
| 797 | 12/24/2014 | 503763 | Guide post missing from windscreen sunblind                  | Refit drivers blind guide post ok                                                                                    |  | 732290 |
| 797 | 12/24/2014 | 503763 | Trim coming off N/S mirror                                   | Refit trim to n/s mirror ok                                                                                          |  | 732290 |
| 797 | 12/18/2014 | 502953 | Service                                                      | Inspect vehicle as per RSI Checklist                                                                                 |  | 731965 |
| 797 | 12/15/2014 | 501838 | Door ramp trim missing                                       | rebooked                                                                                                             |  | 731122 |
| 797 | 12/13/2014 | 501919 | Complete AM/FM radio saloon speaker modification             | Complete Campaign 13/14                                                                                              |  | 731122 |
| 797 | 12/12/2014 | 495609 | SEAT DRIVERS ISRI FAT BOY A686                               | Creditor #::IB-EAS003 EASTCOAST TRUCK & BUS SERVICE P/O #:V146047 Receiving #:148473 Date :2014-12-12                |  | 731411 |
| 797 | 12/09/2014 | 500851 | Wheel Nuts Re-Tension Bookback from W/O:500547 O/S/R/I tyre  | Wheel Nuts Re-Tensioned                                                                                              |  | 726031 |
| 797 | 12/09/2014 | 501007 |                                                              | CCTV Hard Drive Check                                                                                                |  | 726031 |
| 797 | 12/09/2014 | 501007 |                                                              | Door Service                                                                                                         |  | 726031 |
| 797 | 12/06/2014 | 500547 | O/S/R/I tyre tread low                                       | Fitted run out tyre to O/S/R/I                                                                                       |  | 726031 |
| 797 | 12/05/2014 | 495609 | Wont adjust properly. Seat bouncing.                         | rebooked                                                                                                             |  | 726031 |
| 797 | 11/28/2014 | 495873 | O ring- rear cover                                           | Creditor #::IB-EAS003 EASTCOAST TRUCK & BUS SERVICE P/O #:V145569 Receiving #:147946 Date :2014-11-28 MM             |  | 728842 |
| 797 | 11/28/2014 | 495873 | Cover inductive sensor - rear                                | Creditor #::IB-EAS003 EASTCOAST TRUCK & BUS SERVICE P/O #:V145569 Receiving #:147946 Date :2014-11-28 MM             |  | 728842 |
| 797 | 11/28/2014 | 496882 | SWITCH REAR HATCH LIMIT                                      | Creditor #::IB-EAS003 EASTCOAST TRUCK & BUS SERVICE P/O #:V145569 Receiving #:147946 Date :2014-11-28                |  | 728842 |
| 797 | 11/26/2014 | 498773 | GLOBE 24V 21W SINGLE CONTACT                                 |                                                                                                                      |  | 727400 |
| 797 | 11/26/2014 | 498773 | O/S/F/T flasher light not working                            | Replaced globe                                                                                                       |  | 727400 |
| 797 | 11/24/2014 | 495873 | Trans leak                                                   | Replaced plastic cap on trans and replaced oil                                                                       |  | 726031 |
| 797 | 11/24/2014 | 495873 | Wash and check trans oil leaks                               | Washed and road tested - ok                                                                                          |  | 726031 |
| 797 | 11/18/2014 | 496882 | Service                                                      | Replaced engine hatch switch                                                                                         |  | 726031 |
| 797 | 11/17/2014 | 496882 | Rear Vbar bush needs replacing diff end                      | Checked bush still ok for service                                                                                    |  | 726031 |
| 797 | 11/17/2014 | 496882 | Drv entered - Air Cond Air Conditioner                       |                                                                                                                      |  | 726031 |
| 797 | 11/17/2014 | 496882 | A/C fans are noisy                                           | Checked for fan noise ok no fault found                                                                              |  | 726031 |
| 797 | 11/17/2014 | 496882 | trouble starting from key                                    | Checked for starting fault rear engine hatch switch u/s order new switch                                             |  | 726031 |
| 797 | 11/16/2014 | 497326 | Remove old decal and fit new Authorised Officers Decal DO N  | Completed Campaign                                                                                                   |  | 727323 |
| 797 | 11/16/2014 | 497325 | Remove Legacy Poster and replace with See Something Say So   | Completed Campaign                                                                                                   |  | 727323 |
| 797 | 11/13/2014 | 495873 | Rear door sensitive edge not working                         | Adjusted sensitive edge and checked operation                                                                        |  | 726849 |
| 797 | 11/11/2014 | 495873 | Rear door sensitive edge not working                         | Adjusted sensitive edge and checked operation                                                                        |  | 726031 |
| 797 | 11/11/2014 | 495873 | Wash and check trans oil leaks                               | Washed trans roadtest and checked leaks. requires further work                                                       |  | 726031 |
| 797 | 11/11/2014 | 495873 | Switch light not working                                     | Replaced switch light globes                                                                                         |  | 726031 |
| 797 | 11/11/2014 | 495873 | Coolant leak at header tank                                  | Tightened hose clamps as required washed and checked for leaks ok                                                    |  | 726031 |
| 797 | 11/11/2014 | 495873 | Engine hatch struts needs replacing                          | Replaced engine hatch struts                                                                                         |  | 726031 |
| 797 | 11/11/2014 | 495873 | GLOBE WEDGE 24V 1.2W HLW241.2 (47706 SWFLED E-596WLED )      |                                                                                                                      |  | 726031 |
| 797 | 11/11/2014 | 495873 | GAS STRUT 350NM X 565MM                                      |                                                                                                                      |  | 726031 |
| 797 | 11/10/2014 | 495567 | Consumables                                                  |                                                                                                                      |  | 0      |
| 797 | 11/10/2014 | 495567 | Consumables                                                  |                                                                                                                      |  | 0      |
| 797 | 11/10/2014 | 495567 | Consumables                                                  |                                                                                                                      |  | 0      |
| 797 | 11/10/2014 | 495567 | Consumables                                                  |                                                                                                                      |  | 0      |
| 797 | 11/10/2014 | 495567 | O RING FILTER KIT K93                                        | Kit . filter Cent                                                                                                    |  | 726031 |
| 797 | 11/10/2014 | 495567 | FILTER OIL K124 / L94UAB (H200W20)2059778                    | Filter Oil                                                                                                           |  | 726031 |
| 797 | 11/10/2014 | 495567 | HYDRAULIC TORQUE FLUID 414                                   | Torque fluid                                                                                                         |  | 726031 |
| 797 | 11/10/2014 | 495567 | FILTER TRANSMISSION ZF 4139-298-038E39HD119                  | Filter ZF Trans                                                                                                      |  | 726031 |
| 797 | 11/10/2014 | 495567 | FILTER FUEL K124 / LU94A (1411894 / H17WK05)                 | Fuel Filter                                                                                                          |  | 726031 |
| 797 | 11/10/2014 | 495567 | Service                                                      | Tension ALL Wheel Nuts to OEM Specs                                                                                  |  | 726031 |
| 797 | 11/10/2014 | 495567 | Service                                                      | A - Service & Bus Safety Inspection                                                                                  |  | 726031 |
| 797 | 11/10/2014 | 495567 | ENGINE OIL DELO 400LE 15W40 (LU18)                           | Engine Oil                                                                                                           |  | 726031 |
| 797 | 11/10/2014 | 495567 | Consumables                                                  |                                                                                                                      |  | 0      |
| 797 | 11/10/2014 | 495567 | Consumables                                                  |                                                                                                                      |  | 0      |
| 797 | 11/10/2014 | 495567 | Consumables                                                  |                                                                                                                      |  | 0      |
| 797 | 11/10/2014 | 495567 | Consumables                                                  |                                                                                                                      |  | 0      |
| 797 | 11/10/2014 | 495567 | Service                                                      | A - Service & Bus Safety Inspection                                                                                  |  | 726031 |
| 797 | 11/06/2014 | 494844 | Wheel Nuts Re-Tension Bookback from W/O:494414 N/S/R/O tread | Wheel Nuts Re-Tensioned                                                                                              |  | 724954 |
| 797 | 11/03/2014 | 494414 | N/S/R/O tread low                                            | Replaced n/s/r tyres                                                                                                 |  | 724954 |
| 797 | 11/01/2014 | 493031 | Wheel steering RECO L94                                      | Creditor #::IB-EAS003 EASTCOAST TRUCK & BUS SERVICE P/O #:V144707 Receiving #:147062 Date :2014-11-01 MM             |  | 724954 |
| 797 | 10/30/2014 | 493031 | Steering wheel peeling                                       | Replaced steering wheel & fit indicator cancel modification                                                          |  | 724317 |
| 797 | 10/30/2014 | 493031 | Engine idle low                                              | Adjust idle & r/test ok                                                                                              |  | 724317 |
| 797 | 10/29/2014 | 493031 | Steering wheel peeling                                       | Remove steering wheel & check stock wheel - incorrect order correct wheel & refit old                                |  | 723618 |
| 797 | 10/29/2014 | 493031 | Engine idle low                                              | Checked for idle adjustment connector r/test to operating temp & adjust idle speed to 550 rpm.                       |  | 723618 |
| 797 | 10/27/2014 | 493031 | Front sway bar rubber needs replacing                        | Replaced bushes                                                                                                      |  | 723618 |
| 797 | 10/27/2014 | 493031 | Steering wheel peeling                                       | Ordered new steering wheel                                                                                           |  | 723618 |
| 797 | 10/27/2014 | 493031 | Engine idle low                                              | Start checking for idle adjustment                                                                                   |  | 723618 |
| 797 | 10/27/2014 | 493031 | FLURO TUBE 24V 18W 24'                                       |                                                                                                                      |  | 723618 |
| 797 | 10/27/2014 | 493031 | STABILIZER BAR BUSH FRONT L94UAB                             |                                                                                                                      |  | 723618 |
| 797 | 10/27/2014 | 493031 | LIGHT DIFFUSER 3M LENGHT                                     |                                                                                                                      |  | 723618 |
| 797 | 10/27/2014 | 493031 | GLOBE WEDGE 24V 1.2W HLW241.2 (47706 SWFLED E-596WLED )      |                                                                                                                      |  | 723618 |
| 797 | 10/27/2014 | 493031 | L/H tachometer globe not working                             | Replaced globe                                                                                                       |  | 723618 |
| 797 | 10/27/2014 | 493031 | Saloon lights not working                                    | Replaced light Stubes                                                                                                |  | 723618 |
| 797 | 10/27/2014 | 493031 | Switch lights not working                                    | Replaced GLOBES                                                                                                      |  | 723618 |
| 797 | 10/23/2014 | 492430 | 1MT MULTI FIT WIPER REFILL                                   |                                                                                                                      |  | 722928 |
| 797 | 10/23/2014 | 492430 | Mechanic entered - Wipers & Washers Not Cleaning Screen      | Replaced wiper inserts.                                                                                              |  | 722928 |
| 797 | 10/23/2014 | 492430 | Consumables                                                  |                                                                                                                      |  | 0      |
| 797 | 10/23/2014 | 492430 | Mechanic entered - Body & Acc Mirrors Exterior               | Tightened O/S mirror head.                                                                                           |  | 722928 |
| 797 | 10/23/2014 | 492430 | Consumables                                                  |                                                                                                                      |  | 0      |
| 797 | 10/23/2014 | 492430 | Consumables                                                  |                                                                                                                      |  | 0      |
| 797 | 10/23/2014 | 492430 | Service                                                      | Tension ALL Wheel Nuts to OEM Specs                                                                                  |  | 722928 |
| 797 | 10/23/2014 | 492430 | Service                                                      | A - Service & Bus Safety Inspection                                                                                  |  | 722928 |
| 797 | 10/22/2014 | 492208 | Tank 2 not filling.                                          | Checked gauge working correctly.                                                                                     |  | 722928 |
| 797 | 10/21/2014 | 492215 | No 2 air gage reading Below 2 bar .                          | Mechanic sent to chirnside park shopping centre to investigate Check air system ok sticky gage return bus back depot |  | 722928 |
| 797 | 10/09/2014 | 490319 | Rear passenger door lower pannel on inside of door loose.    | Secured panel                                                                                                        |  | 719593 |
| 797 | 10/06/2014 | 489525 | Drv entered - Vandalism Graffiti                             | Removed graffiti                                                                                                     |  | 718738 |
| 797 | 10/06/2014 | 489525 | A/C very noisy when operating and vibrates the bus           | a/c belt adjusted                                                                                                    |  | 718738 |
| 797 | 10/06/2014 | 489525 | PUMP BOOST A/C HEATER                                        |                                                                                                                      |  | 718738 |
| 797 | 10/06/2014 | 489525 | Drv entered - Heat & Demist                                  | Check boost pump faulty remove and replaced                                                                          |  | 718738 |
| 797 | 10/06/2014 | 489525 | Drv entered - Heat & Demist No Demisters                     | Check boost pump faulty remove and replaced                                                                          |  | 718738 |
| 797 | 10/06/2014 | 489525 | Drv entered - Heat & Demist No Demisters                     | Check boost pump faulty remove and replaced                                                                          |  | 718738 |
| 797 | 09/22/2014 | 486961 | Service                                                      | Transmission /check as per Check List                                                                                |  | 716350 |
| 797 | 09/22/2014 | 486970 | Drv entered - Comm Equip Faulty                              | Secured arial connector                                                                                              |  | 716350 |
| 797 | 09/18/2014 | 486562 | Graffiti inside rear of bus                                  | Removed graffiti                                                                                                     |  | 715945 |
| 797 | 09/18/2014 | 486562 | FLURO TUBE 24V 18W 24'                                       |                                                                                                                      |  | 715945 |

|     |            |        |                                                                |                                                                                                                                        |        |
|-----|------------|--------|----------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------|--------|
| 797 | 09/18/2014 | 486562 | Front and rear steps light not working                         | Replaced fluoro tube                                                                                                                   | 715945 |
| 797 | 09/18/2014 | 486562 | Battery cable needs to be insulated                            | Replaced insulation                                                                                                                    | 715945 |
| 797 | 09/18/2014 | 486562 | Front inner door exit light not working                        | Secure elec plug                                                                                                                       | 715945 |
| 797 | 09/18/2014 | 486562 | CCTV hard drive unit missing                                   | Checked ok                                                                                                                             | 715945 |
| 797 | 09/18/2014 | 486538 | Service                                                        | CCTV Hard Drive Check                                                                                                                  | 715945 |
| 797 | 09/18/2014 | 486538 | Service                                                        | Door Service                                                                                                                           | 715945 |
| 797 | 09/16/2014 | 485085 | FITTING                                                        | Creditor #:#B-MIC002 MICHELIN AUSTRALIA P/O #:#V143548 Receiving #:#145369 Date :2014-09-16                                            | 715461 |
| 797 | 09/16/2014 | 485085 | 295/80R22.5 RECAMIC DRIVE PATT                                 | Creditor #:#B-MIC002 MICHELIN AUSTRALIA P/O #:#V143548 Receiving #:#145369 Date :2014-09-16                                            | 715461 |
| 797 | 09/13/2014 | 485243 | Service                                                        | Wheel Nuts Re-Tensioned                                                                                                                | 714890 |
| 797 | 09/11/2014 | 485243 | Wheel Nuts Re-Tension Bookback from W/O:485085 N/S/R/i tyre    | Wheel Nuts Re-Tensioned                                                                                                                | 714890 |
| 797 | 09/10/2014 | 485085 | N/S/R/i tyre tread low                                         | Replaced N/S/R/i tyre with 2nd hand retread.                                                                                           | 714890 |
| 797 | 09/10/2014 | 485085 | Oil leak at gear box                                           | Washed and checked oil leak at gear box. Not excessive at this time.                                                                   | 714890 |
| 797 | 09/10/2014 | 485011 | Service                                                        | Tension ALL Wheel Nuts to OEM Specs service complete                                                                                   | 714890 |
| 797 | 09/10/2014 | 485011 | Service                                                        | A - Service & Bus Safety Inspection service complete                                                                                   | 714890 |
| 797 | 08/30/2014 | 483016 | GLOBE 24V 5W BAYONETT                                          |                                                                                                                                        | 712349 |
| 797 | 08/30/2014 | 483016 | Top Offside front Park Light not working.                      | Replaced globe                                                                                                                         | 712349 |
| 797 | 08/28/2014 | 482490 | GLOBE 24V 21W SINGLE CONTACT                                   | Replaced globe                                                                                                                         | 712349 |
| 797 | 08/28/2014 | 482490 | Front Offside Indicator not working.                           | Modify dash & till carrier to fit new security lockdown pin                                                                            | 712349 |
| 797 | 08/28/2014 | 482490 | Security Door till can not be locked in pin missing.           | Completed campaign                                                                                                                     | 711155 |
| 797 | 08/23/2014 | 481686 | Remove old A3 poster & replace with Legacy or Penalty Fares    |                                                                                                                                        | 711155 |
| 797 | 08/23/2014 | 481762 | L.E.D.STOP+TAIL LIGHT                                          | Replaced stop light and adapted plug to fit working OK                                                                                 | 710715 |
| 797 | 08/23/2014 | 481762 | Top rear N/Side Parker not working                             | Replaced switch and rewired                                                                                                            | 710715 |
| 797 | 08/20/2014 | 471524 | Door ramp inter lock switch faulty                             | Coolant pipe bracket broken removed and weld                                                                                           | 710715 |
| 797 | 08/20/2014 | 480956 | A/c system noisy from rooftop                                  | Secured connectors on unit                                                                                                             | 710094 |
| 797 | 08/20/2014 | 480956 | AM/FM radio loose connection. Radio keeps dropping out with    |                                                                                                                                        | 707327 |
| 797 | 08/15/2014 | 471524 | PROXIMITY SWITCH W/CHAIR FLAP                                  | Checked ok. 5mm                                                                                                                        | 707327 |
| 797 | 08/08/2014 | 479006 | N/S/R/O tyre tread low                                         |                                                                                                                                        | 707327 |
| 797 | 08/05/2014 | 477813 | REAR AIR BAG (DRIVE AXLE) SCANIA L94UAB 2024287                | Replaced both n/s/r air bags                                                                                                           | 707327 |
| 797 | 08/05/2014 | 477813 | N/S/R/F air bag needs replacing                                | Checked for leak cover plate at rear of trans weeping nipped up cover nuts washed off ok                                               | 707327 |
| 797 | 08/05/2014 | 477813 | Transmission cooler needs washing & checking for oil leaks?    |                                                                                                                                        | 707327 |
| 797 | 08/05/2014 | 477813 | GLOBE H1 24V 70W                                               | Replaced head light globe                                                                                                              | 707327 |
| 797 | 08/05/2014 | 477813 | Offside Headlight not working.                                 | Washed wet off around pinion road test ok                                                                                              | 707327 |
| 797 | 08/05/2014 | 477813 | Diff pinion needs washing & checking for leaks?                | Removed graffiti check no fault come at this time                                                                                      | 706761 |
| 797 | 08/01/2014 | 477813 | Graffiti on rear passenger seats & floor                       | Replaced globes                                                                                                                        | 706761 |
| 797 | 08/01/2014 | 477813 | N/S dash tachometer & switch lights N/W                        | Replaced fluoro tube                                                                                                                   | 706761 |
| 797 | 08/01/2014 | 477813 | O/S saloon lights dull                                         |                                                                                                                                        | 706761 |
| 797 | 08/01/2014 | 477813 | GLOBE WEDGE 24V 1.2W                                           |                                                                                                                                        | 706761 |
| 797 | 08/01/2014 | 477813 | GLOBE WEDGE 24V 1.2W                                           |                                                                                                                                        | 706761 |
| 797 | 08/01/2014 | 477813 | FLURO TUBE 24V 18W 24'                                         |                                                                                                                                        | 706761 |
| 797 | 08/01/2014 | 477813 | The stop light is coming on intermittently                     | Check no fault come at this time                                                                                                       | 706761 |
| 797 | 08/01/2014 | 477813 | Door on locker for video recording unit is sticking out about  | Secured lock                                                                                                                           | 706761 |
| 797 | 07/28/2014 | 476794 |                                                                | A - Service & Bus Safety Inspection                                                                                                    | 705402 |
| 797 | 07/28/2014 | 476794 |                                                                | Tension ALL Wheel Nuts to OEM Specs                                                                                                    | 705402 |
| 797 | 07/28/2014 | 476794 | O RING FILTER KIT K93                                          | Kit . filter Cent                                                                                                                      | 705402 |
| 797 | 07/28/2014 | 476794 | FILTER OIL K124 / L94UAB (H200W20)2059778                      | Filter Oil                                                                                                                             | 705402 |
| 797 | 07/28/2014 | 476794 | HYDRAULIC TORQUE FLUID 414                                     | Torque fluid                                                                                                                           | 705402 |
| 797 | 07/28/2014 | 476794 | FILTER TRANSMISSION ZF 4139-298-038E39HD119                    | Filter ZF Trans                                                                                                                        | 705402 |
| 797 | 07/28/2014 | 476794 | FILTER FUEL K124 / LU94A (1411894 / H17WK05)                   | Fuel Filter                                                                                                                            | 705402 |
| 797 | 07/28/2014 | 476794 | ENGINE OIL DELO 400LE 15W40 (LU18)                             | Engine Oil                                                                                                                             | 705402 |
| 797 | 07/28/2014 | 476794 |                                                                | A - Service & Bus Safety Inspection                                                                                                    | 705402 |
| 797 | 07/15/2014 | 474309 | NEARside TOP Stop light not working.                           | Checked all rear stop/tail lights no fault found at this time                                                                          | 703097 |
| 797 | 07/12/2014 | 473986 | Fit Wheel Nut Pointers to all wheel nuts on the front axle     | Completed campaign                                                                                                                     | 703097 |
| 797 | 07/12/2014 | 473986 | Fit Tyre Valve Extensions To All Inner Rear Axle Wheels        | Completed campaign                                                                                                                     | 703097 |
| 797 | 07/12/2014 | 473986 | Fit New Myki Decal as Per PTV fitting instructions             | Completed campaign                                                                                                                     | 703097 |
| 797 | 07/12/2014 | 473986 | Fit Myki decals as requiredFit Recruitment decal as required   | Completed campaign                                                                                                                     | 703097 |
| 797 | 07/12/2014 | 473986 | Remove Fair Evasion A3 Poster & Replace with MYKI AUTO TOP     | Completed campaign                                                                                                                     | 703097 |
| 797 | 07/03/2014 | 472360 | Coolant filler pipe bracket broken just behind cap. Pipe is    | Replaced header tank sender cap with good second unit                                                                                  | 701285 |
| 797 | 06/30/2014 | 471524 | Door ramp inter lock switch faulty                             | Ordered switch                                                                                                                         | 700531 |
| 797 | 06/30/2014 | 471493 | Service                                                        | Door Service                                                                                                                           | 700531 |
| 797 | 06/30/2014 | 471493 | Service                                                        | CCTV Hard Drive Check                                                                                                                  | 700531 |
| 797 | 06/25/2014 | 470637 | Washer not working                                             | No fault found.                                                                                                                        | 699541 |
| 797 | 06/25/2014 | 470637 | FLURO TUBE 24V 18W 24'                                         |                                                                                                                                        | 699541 |
| 797 | 06/25/2014 | 470637 | Rear step light not working                                    | Replaced front and rear step lights.                                                                                                   | 699541 |
| 797 | 06/25/2014 | 470524 | Service                                                        | A - Service & Bus Safety Inspection                                                                                                    | 699541 |
| 797 | 06/25/2014 | 470524 | Service                                                        | Tension ALL Wheel Nuts to OEM Specs                                                                                                    | 699541 |
| 797 | 06/23/2014 | 470276 | T/L/R Indicator not working. Should be 798.                    | Secured loose connection.                                                                                                              | 699283 |
| 797 | 05/30/2014 | 448585 | Direct Purchase - BODYWORK                                     | Creditor #:#B-EAS003 EASTCOAST TRUCK & BUS SERVICE P/O #:#V139641 Receiving #:#141551 Date :2014-06-05 RECTIFY BROKEN WHEEL CHAIR RAMP | 695701 |
| 797 | 05/17/2014 | 463703 | Perform Campaign 1_14 School Bus Light Globe Check Check       | Completed campaign                                                                                                                     | 692150 |
| 797 | 05/17/2014 | 463702 | Remove A3 Marketing Poster CATCHING A BUSFit A3 Marketing      | Completed campaign                                                                                                                     | 692150 |
| 797 | 05/16/2014 | 448585 | EMERGENCY EXIT DECAL 600MM X 8                                 | Creditor #:#B-EAS003 EASTCOAST TRUCK & BUS SERVICE P/O #:#V138631 Receiving #:#140722 Date :2014-05-16                                 | 692150 |
| 797 | 05/13/2014 | 462438 | EMERGENCY EXIT DECAL HAMMER SYMBOL                             |                                                                                                                                        | 691047 |
| 797 | 05/13/2014 | 462438 | DECAL EMERGENCY EXIT LARGE                                     |                                                                                                                                        | 691047 |
| 797 | 05/13/2014 | 462438 | DECAL BREAK GLASS/HAMMER                                       |                                                                                                                                        | 691047 |
| 797 | 05/13/2014 | 462438 | GIVE WAY SIGN (LARGE)                                          |                                                                                                                                        | 691047 |
| 797 | 05/13/2014 | 462438 | Rear window needs relevant decals fitted after window replaced | Fitted decals to rear window window replaced refer to W/O # 462305                                                                     | 691047 |
| 797 | 05/12/2014 | 462305 | DIRECT PURCHASE ACCIDENT                                       | Creditor #:#B-GLA002 GLASS ASSIST PTY LTD P/O #:#V138717 Receiving #:#140733 Date :2014-05-16 Supply & fit rear window                 | 691902 |
| 797 | 05/12/2014 | 462305 | REAR WINDOW KAPOWED BY N/S MIRROR OF BUS 834                   | Glass Assist replaced supplied & fitted rear window                                                                                    | 691047 |
| 797 | 05/09/2014 | 461892 | Suspension reset switch N/W                                    | Removed switch cleaned out & refitted working OK                                                                                       | 690928 |
| 797 | 05/09/2014 | 461892 | Engine & transmission need washing & checking for leaks?       | Washed transmission road tested & checked for leaks tightened coolant hose clamp & rechecked for leaks OK                              | 690928 |
| 797 | 05/09/2014 | 461892 | Coolant header tank needs securing                             | Tightened header tank bracket                                                                                                          | 690928 |
| 797 | 05/08/2014 | 461657 | FILTER AIR DRYER KIT(HALDEX)                                   | Filter Air Dryer                                                                                                                       | 690883 |
| 797 | 05/08/2014 | 461657 | FUEL FILTER ELEMENT SCANIA L94UAB/volvo (R90T / H7090WK10)     | Raycor filter                                                                                                                          | 690883 |
| 797 | 05/08/2014 | 461657 | HYDRAULIC TORQUE FLUID 414                                     | Hydraulic oil                                                                                                                          | 690883 |
| 797 | 05/08/2014 | 461657 | FILTER K124EB HYD COOLING FAN                                  | Hydraulic filter                                                                                                                       | 690883 |
| 797 | 05/08/2014 | 461657 | POWER STEERING FILTER VOLVO                                    | Power steering filter                                                                                                                  | 690883 |
| 797 | 05/08/2014 | 461657 | Diff Oil Borate EP 460                                         | diff oil                                                                                                                               | 690883 |
| 797 | 05/08/2014 | 461657 |                                                                | Service as per check list                                                                                                              | 690883 |
| 797 | 05/08/2014 | 461657 |                                                                | Tension ALL Wheel Nuts to OEM Specs                                                                                                    | 690883 |
| 797 | 05/08/2014 | 461657 |                                                                | A - Service & Bus Safety Inspection                                                                                                    | 690883 |
| 797 | 05/02/2014 | 460553 | CUSHION PAN GUIDE KIT ISRI 6860                                |                                                                                                                                        | 689592 |
| 797 | 05/02/2014 | 460553 | Drivers seat base loose                                        | Replaced seat base pan guides & secured trim OK                                                                                        | 689592 |
| 797 | 05/01/2014 | 460387 | Sway bar D rubbers need replacing                              | Checked swaybar rubbers worn ok to run at this time                                                                                    | 689480 |
| 797 | 05/01/2014 | 460387 | A/C belts missing                                              | Checked a/c belts ok at this time                                                                                                      | 689480 |

|     |            |        |                                                              |                                                                                                                                                                                      |        |
|-----|------------|--------|--------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|
| 797 | 04/22/2014 | 457723 | CAB DOOR BROKEN OFF                                          | Replaced bottom hinge                                                                                                                                                                | 686170 |
| 797 | 04/22/2014 | 457723 | HINGE DRIVERS COMPARTMENT                                    |                                                                                                                                                                                      | 686170 |
| 797 | 04/16/2014 | 458249 |                                                              | Transmission /check as per Check List                                                                                                                                                | 686529 |
| 797 | 04/16/2014 | 458109 | Drv entered - Air System Other                               | Checked over air system for air leaks none found ok at this time                                                                                                                     | 686529 |
| 797 | 04/15/2014 | 458109 | Drv entered - Vandalism Graffiti                             | Removed graffiti                                                                                                                                                                     | 686350 |
| 797 | 04/15/2014 | 458109 | GLOBE+HOLDER INSTRUMENT (GREY)                               |                                                                                                                                                                                      | 686350 |
| 797 | 04/15/2014 | 458109 | Batteries need securing                                      | Secured batteries                                                                                                                                                                    | 686350 |
| 797 | 04/15/2014 | 458109 | Tacho light & guage light N/W                                | Replaced globes                                                                                                                                                                      | 686350 |
| 797 | 04/15/2014 | 458109 | GLOBE WEDGE 24V 1.2W                                         |                                                                                                                                                                                      | 686350 |
| 797 | 04/15/2014 | 458109 | Switch lights N/W                                            | Replaced globe                                                                                                                                                                       | 686350 |
| 797 | 04/15/2014 | 458109 | Header tank needs securing                                   | Secured header tank                                                                                                                                                                  | 686350 |
| 797 | 04/15/2014 | 458109 | Windscreen blind jamming                                     | Lubricated drivers blind guide rails and checked operation ok                                                                                                                        | 686350 |
| 797 | 04/15/2014 | 458109 | Rear passenger seat hinge bolts loose                        | Tightened rear passenger seat hinge bolts                                                                                                                                            | 686350 |
| 797 | 04/12/2014 | 457723 | CAB DOOR BROKEN OFF                                          | Replaced top hinge & ordered bottom hinge                                                                                                                                            | 686170 |
| 797 | 04/11/2014 | 457533 | HYDRAULIC TORQUE FLUID 414                                   | Torque fluid                                                                                                                                                                         | 685682 |
| 797 | 04/11/2014 | 457533 | FILTER TRANSMISSION ZF 4139-298-038E39HD119                  | Filter ZF Trans                                                                                                                                                                      | 685682 |
| 797 | 04/11/2014 | 457533 | FILTER FUEL K124 / LU94A (1411894 / H17WK05)                 | Fuel Filter                                                                                                                                                                          | 685682 |
| 797 | 04/11/2014 | 457533 | ENGINE OIL DELO 400LE 15W40                                  | Engine Oil                                                                                                                                                                           | 685682 |
| 797 | 04/11/2014 | 457533 |                                                              | Tension ALL Wheel Nuts to OEM Specs                                                                                                                                                  | 685682 |
| 797 | 04/11/2014 | 457533 |                                                              | A - Service & Bus Safety Inspection                                                                                                                                                  | 685682 |
| 797 | 04/11/2014 | 457533 | O RING FILTER KIT K93                                        | Kit . filter Cent                                                                                                                                                                    | 685682 |
| 797 | 04/11/2014 | 457533 | FILTER OIL K124 / L94UAB (H200W20)2059778                    | Filter Oil                                                                                                                                                                           | 685682 |
| 797 | 04/11/2014 | 457533 |                                                              | A - Service & Bus Safety Inspection                                                                                                                                                  | 685682 |
| 797 | 04/07/2014 | 456586 |                                                              | Door Service                                                                                                                                                                         | 684838 |
| 797 | 04/07/2014 | 456586 |                                                              | CCTV Hard Drive Check                                                                                                                                                                | 684838 |
| 797 | 03/28/2014 | 454675 | Drv entered - Ticket Equip Not Printing                      | Checked ticket equipment security OK at this time                                                                                                                                    | 683088 |
| 797 | 03/28/2014 | 454675 | Transmission needs washing & checking for leaks?             | Washed transmission road test and checked for leaks ok at this time                                                                                                                  | 683088 |
| 797 | 03/28/2014 | 454675 | FLURO TUBE 24V 18W 24                                        |                                                                                                                                                                                      | 683088 |
| 797 | 03/28/2014 | 454675 | O/S/R saloon lights N/W                                      | Replaced fluro tubes working OK                                                                                                                                                      | 683088 |
| 797 | 03/28/2014 | 454675 | Bolt missing & bolts loose on O/S/R outrigger frame in engin | Fitted new bolt and tightened all other bolts                                                                                                                                        | 683088 |
| 797 | 03/27/2014 | 448585 | Steering wheel de-laminated                                  | Replaced steering wheel                                                                                                                                                              | 683059 |
| 797 | 03/27/2014 | 454452 |                                                              | Tension ALL Wheel Nuts to OEM Specs                                                                                                                                                  | 683059 |
| 797 | 03/27/2014 | 454452 |                                                              | A - Service & Bus Safety Inspection                                                                                                                                                  | 683059 |
| 797 | 03/26/2014 | 448585 | Wheel steering RECO L94                                      | Creditor #:IB-EAS003 EASTCOAST TRUCK & BUS SERVICE P/O #:V135519 Receiving #:138575 Date :2014-03-26                                                                                 | 683059 |
| 797 | 03/25/2014 | 454073 | Direct Purchase - BODYWORK                                   | Creditor #:IB-GLA002 GLASS ASSIST PTY LTD P/O #:V136888 Receiving #:138507 Date :2014-03-25 Supply & replace windscreen                                                              | 682800 |
| 797 | 03/25/2014 | 454073 | Drv entered - Body & Acc Windows windscreen cracked          | Glass Assist replaced windscreen                                                                                                                                                     | 682800 |
| 797 | 03/18/2014 | 452509 |                                                              | Adjusted tappets & replaced coolant hose                                                                                                                                             | 681283 |
| 797 | 03/17/2014 | 452528 |                                                              | Adjust Tappets                                                                                                                                                                       | 681283 |
| 797 | 03/17/2014 | 452509 |                                                              | Adjusted tappets & replaced coolant hose                                                                                                                                             | 681283 |
| 797 | 03/07/2014 | 451113 | GLOBE H1 24V 70W                                             |                                                                                                                                                                                      | 679687 |
| 797 | 03/06/2014 | 451113 | Headlight not working                                        | Replace n/s head light globe                                                                                                                                                         | 679687 |
| 797 | 03/01/2014 | 447741 | AIR CONDITIONING REPAIR                                      | Creditor #:IB-ABA001 AB AUTO AIR P/O #:V136235 Receiving #:137854 Date :2014-03-12 REPAIRED DAMAGED COPPER PIPING                                                                    | 680452 |
| 797 | 02/28/2014 | 446179 | RECOVER SEAT BASE                                            | Creditor #:IB-TRI001 TRIM IMPROVEMENTS P/O #:V133538 Receiving #:137379 Date :2014-03-03                                                                                             | 678931 |
| 797 | 02/20/2014 | 448585 | Steering wheel de-laminated                                  | Ordered steering wheel                                                                                                                                                               | 676646 |
| 797 | 02/20/2014 | 448585 | Engine stalled will not start                                | Rectified short circuitrewired and sercured wire underneth .refitted axle shafts                                                                                                     | 676646 |
| 797 | 02/20/2014 | 448585 | Wheelchair ramp broken                                       | ECTB panel shop rectified wheel chair ramp                                                                                                                                           | 676646 |
| 797 | 02/19/2014 | 447741 | A/C blowing warm air                                         | Refer to fault # 462923                                                                                                                                                              | 676646 |
| 797 | 02/19/2014 | 448407 | TOW BUS TO DEPOT                                             | Creditor #:IB-EAG001 EAGLE TOWING AND SALVAGE P/O #:V135606 Receiving #:137233 Date :2014-02-27 AFTER HOURS TOW FROM TECOMA TO LILYDALE                                              | 678129 |
| 797 | 02/19/2014 | 448407 | Bus would not start                                          | Mechanic sent burwood hwy Tecoma to investergate not starting try trace elec fault .call and wait for tow truck assist tow truck and return back to depot                            | 676646 |
| 797 | 02/17/2014 | 447741 | Drv entered - Air Cond Air Conditioner                       | AB Auto Air traced A/C fault broken a/c pipe in corner of body repaired pipe tested forleaks & charged system working OK                                                             | 676312 |
| 797 | 02/06/2014 | 446179 | O/S passenger seat base slashed                              | Replaced seat base                                                                                                                                                                   | 674530 |
| 797 | 02/06/2014 | 446179 | FLURO TUBE 24V 18W 24'                                       |                                                                                                                                                                                      | 674530 |
| 797 | 02/06/2014 | 446179 | External rear step light N/W                                 | Replaced fluro tube                                                                                                                                                                  | 674530 |
| 797 | 02/06/2014 | 446179 | Header tank loose                                            | Tightened header tank clamps                                                                                                                                                         | 674530 |
| 797 | 02/06/2014 | 446179 | Ducting over front door needs refitting                      | Refitted ducting                                                                                                                                                                     | 674530 |
| 797 | 02/05/2014 | 445964 |                                                              | Tension ALL Wheel Nuts to OEM Specs                                                                                                                                                  | 674416 |
| 797 | 02/05/2014 | 445964 |                                                              | A - Service & Bus Safety Inspection                                                                                                                                                  | 674416 |
| 797 | 02/04/2014 | 445894 | DELO EXTENDED LIFE COOLANT PRE-MIX                           |                                                                                                                                                                                      | 674181 |
| 797 | 02/04/2014 | 445894 | THERMOSTAT L94                                               |                                                                                                                                                                                      | 674181 |
| 797 | 02/04/2014 | 445894 | Engine overheating                                           | Washed out radiator removed and replaced thermostat road tested OK                                                                                                                   | 674181 |
| 797 | 02/04/2014 | 445894 | SEAL THERMOSTAT HOUSING K230 L94                             |                                                                                                                                                                                      | 674181 |
| 797 | 02/03/2014 | 445485 | Annual Inspections                                           | Creditor #:IB-ROA003 ROAD SAFETY INSPECTIONS P/L P/O #:V134515 Receiving #:136591 Date :2014-02-10 Bus 797                                                                           | 674882 |
| 797 | 02/02/2014 | 445485 |                                                              | RSI Inspection (RWC # 676475)                                                                                                                                                        | 673606 |
| 797 | 02/02/2014 | 445485 | GLOBE WEDGE 24V 1.2W                                         |                                                                                                                                                                                      | 673606 |
| 797 | 01/30/2014 | 445189 | HOSE                                                         |                                                                                                                                                                                      | 673198 |
| 797 | 01/30/2014 | 445189 | DELO EXTENDED LIFE COOLANT PRE-MIX                           |                                                                                                                                                                                      | 673198 |
| 797 | 01/29/2014 | 445189 | Driver reported a coolant leak coming from the engine area   | Breakdown @ Lilydale traced coolant leak topped up coolant & returned bus to depot replaced bottom radiator hose & topped up coolant washed off road tested & rechecked for leaks OK | 673198 |
| 797 | 01/28/2014 | 444824 |                                                              | Inspect vehicle as per RSI Checklist                                                                                                                                                 | 672907 |
| 797 | 01/28/2014 | 444824 | GLOBE WEDGE 24V 1.2W                                         |                                                                                                                                                                                      | 672907 |
| 797 | 01/28/2014 | 444824 | Switch lights N/W                                            | Replaced globe                                                                                                                                                                       | 672907 |
| 797 | 01/28/2014 | 444969 | Battery condition needs checking ?                           | Checked battery condition replaced 1 battery using good S/H battery                                                                                                                  | 672907 |
| 797 | 01/28/2014 | 444824 | Coolant leak at thermostat                                   | Tightened hose clamps at thermostat hoses road tested & rechecked OK                                                                                                                 | 672907 |
| 797 | 01/28/2014 | 444824 | DECAL-NO SMOKING (LARGE)                                     |                                                                                                                                                                                      | 672907 |
| 797 | 01/28/2014 | 444824 | Last N/S grab handle damaged                                 | Repaired clamp                                                                                                                                                                       | 672907 |
| 797 | 01/28/2014 | 444824 | 1 Safety triangle missing from box                           | Fitted S/H triangle                                                                                                                                                                  | 672907 |
| 797 | 01/28/2014 | 444824 | Double folding passenger seat end cap missing                | Adjusted seat & fitted cap                                                                                                                                                           | 672907 |
| 797 | 01/28/2014 | 444824 | N/S/R no smoking decal needs fitting                         | Fitted decal                                                                                                                                                                         | 672907 |
| 797 | 01/28/2014 | 444824 | DECAL BREAK GLASS WITH ROCK                                  |                                                                                                                                                                                      | 672907 |
| 797 | 01/28/2014 | 444824 | Rock decal on rear window needs replacing                    | Replaced decal                                                                                                                                                                       | 672907 |
| 797 | 01/28/2014 | 444824 | Main air compressor pipe to moisture ejector leaking         | Tightened pipe union                                                                                                                                                                 | 672907 |
| 797 | 01/28/2014 |        | 0 Imported Service History                                   | Imported Service History                                                                                                                                                             | 672907 |
| 797 | 01/25/2014 | 444728 | Remove A3 Hold On Poster and Fit A3 Catching a bus poster    | Completed campaign                                                                                                                                                                   | 672907 |
| 797 | 01/24/2014 | 444644 | Dave Obrien reported the engine stalling under braking and w | Tested batteries repaired damaged cable & negative battery terminal checked charge rate OK                                                                                           | 672907 |
| 797 | 01/24/2014 | 444644 | Battery condition needs checking?                            | Refer to fault # 462502                                                                                                                                                              | 672907 |
| 797 | 01/23/2014 | 444404 | Drv entered - Wipers & Washers Washers Not Working           | Topped up washer bottle and bleed washers                                                                                                                                            | 672652 |
| 797 | 01/13/2014 | 442946 |                                                              | CCTV Hard Drive Check                                                                                                                                                                | 671686 |
| 797 | 01/13/2014 | 442946 |                                                              | Door Service                                                                                                                                                                         | 671686 |
| 797 | 01/06/2014 | 441997 | Battery condition needs checking?                            | Tested batteries & charge rate OK at this time                                                                                                                                       | 670391 |
| 797 | 01/06/2014 | 441997 | Ops Entered - Fault - Elec & Light Indicators - Lower O/Sid  | Fitted S/H light & new resistor tested operation OK                                                                                                                                  | 670391 |
| 797 | 01/03/2014 | 418357 | BELT A/C                                                     |                                                                                                                                                                                      | 669715 |
| 797 | 01/03/2014 | 418357 | AIR CONDITIONING REPAIR                                      | Creditor #:IB-ABA001 AB AUTO AIR P/O #:V133952 Receiving #:135495 Date :2014-01-14 A/C Repair                                                                                        | 671906 |
| 797 | 01/03/2014 | 418357 | Drv entered - Heat & Demis                                   | AB Auto Air traced A/C fault resealed fittings at A/C compressor rechecked for leaks &recharged A/C system with refridgerant working OK                                              | 669715 |
| 797 | 01/03/2014 | 441784 | Remove BTS Equipment Fuses                                   | Removed fuses                                                                                                                                                                        | 669715 |

|                       |                                                             |                                                                                                                                          |        |
|-----------------------|-------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------|--------|
| 797 12/24/2013 418357 | Air Conditioner - blowing hot air.                          | Refer to fault # 438777                                                                                                                  | 668575 |
| 797 12/13/2013 439123 | BELT A/C                                                    |                                                                                                                                          | 666403 |
| 797 12/13/2013 439123 | A/C belts needs replacing                                   | Replaced a/c belt                                                                                                                        | 666403 |
| 797 12/13/2013 439123 | GLOBE+HOLDER INSTRUMENT (GREY)                              |                                                                                                                                          | 666403 |
| 797 12/13/2013 439123 | Tacho light not working                                     | Replaced tacho light globe                                                                                                               | 666403 |
| 797 12/13/2013 439123 | O/S wheel chair seat loose                                  | Dismantled seat tightened frame bolts & reassembled                                                                                      | 666403 |
| 797 12/12/2013 439047 | engine belt idler pulley noisey                             | Checked idler pullys no fault found                                                                                                      | 666403 |
| 797 12/12/2013 439047 | N/S number plate light not working                          | Checked number plate lights working ok                                                                                                   | 666403 |
| 797 12/12/2013 438887 | Flat batteries                                              | Checked battery and charging system ok                                                                                                   | 666403 |
| 797 12/12/2013 439047 | DECAL EMERGENCY EXIT BLACK PUSH BUTTON UNDER BUMPER         |                                                                                                                                          | 666403 |
| 797 12/12/2013 439047 | Emergency exit decal missing on front bumper                | Fitted decal to bumper                                                                                                                   | 666403 |
| 797 12/12/2013 439047 | Bolt missing from O/S upright pole                          | Fitted bolt to pole                                                                                                                      | 666403 |
| 797 12/12/2013 438917 | O RING FILTER KIT K93                                       | Kit . filter Cent                                                                                                                        | 666403 |
| 797 12/12/2013 438917 | FILTER OIL K124 / L94UAB (H200W02)                          | Filter Oil                                                                                                                               | 666403 |
| 797 12/12/2013 438917 | HYDRAULIC TORQUE FLUID 414                                  | Torque fluid                                                                                                                             | 666403 |
| 797 12/12/2013 438917 | FILTER TRANSMISSION ZF 4139-298-038E39HD119                 | Filter ZF Trans                                                                                                                          | 666403 |
| 797 12/12/2013 438917 | FILTER FUEL K124 / LU94A (1411894 / H17WK05)                | Fuel Filter                                                                                                                              | 666403 |
| 797 12/12/2013 438917 | ENGINE OIL DELO 400LE 15W40                                 | Engine Oil                                                                                                                               | 666403 |
| 797 12/12/2013 438917 | Service                                                     | Tension ALL Wheel Nuts to OEM Specs                                                                                                      | 666403 |
| 797 12/12/2013 438917 | Service                                                     | A - Service & Bus Safety Inspection                                                                                                      | 666403 |
| 797 12/12/2013 438917 | Service                                                     | A - Service & Bus Safety Inspection                                                                                                      | 666403 |
| 797 12/10/2013 437076 | BALANCE OFF VEHICLE                                         | Creditor #:IB-MIC002 MICHELIN AUSTRALIA P/O #:V132590 Receiving #:134477 Date :2013-12-12                                                | 666403 |
| 797 12/10/2013 437076 | FITTING                                                     | Creditor #:IB-MIC002 MICHELIN AUSTRALIA P/O #:V132590 Receiving #:134477 Date :2013-12-12                                                | 666403 |
| 797 12/10/2013 437076 | 295/80R22.5 XZE2+                                           | Creditor #:IB-MIC002 MICHELIN AUSTRALIA P/O #:V132590 Receiving #:134477 Date :2013-12-12                                                | 666403 |
| 797 12/05/2013 437813 | BELT ALT-CRANK B10B LE                                      |                                                                                                                                          | 665171 |
| 797 12/05/2013 437813 | Air con not working - A/C belts missing                     | Replaced A/C belts                                                                                                                       | 665171 |
| 797 11/29/2013 437076 | O/S/F tyre tread low                                        | Replaced front tyres removed O/S/R/I tyre and checked for punctures no punctures replaced valve extension and inflated OK                | 664142 |
| 797 11/26/2013 436356 | Mechanic entered - Eng Cool Leaking                         | Replaced header tank rechecked for coolant leaks OK                                                                                      | 663529 |
| 797 11/25/2013 436356 | HEADER TANK SCANIA L94 SIDE                                 | Creditor #:IB-MUL001 MULTISPARES LIMITED P/O #:V132271 Receiving #:133779 Date :2013-11-26                                               | 663529 |
| 797 11/25/2013 436356 | Mechanic entered - Eng Cool Leaking                         | Checked for coolant leak under pressure ordered new header tank                                                                          | 663393 |
| 797 11/21/2013 435912 | BELT POLY SCANIA                                            |                                                                                                                                          | 662865 |
| 797 11/21/2013 435912 | Engine belt needs replacing                                 | Replaced engine belt                                                                                                                     | 662865 |
| 797 11/21/2013 435912 | Engine needs washing & checking for leaks?                  | Washed engine road tested & checked for leaks OK at this time                                                                            | 662865 |
| 797 11/21/2013 435912 | FLURO TUBE 18W                                              |                                                                                                                                          | 662865 |
| 797 11/21/2013 435912 | Rear saloon light N/W                                       | Replaced fluoro tube                                                                                                                     | 662865 |
| 797 11/21/2013 435912 | SQUAB COVER BLACK ISRI 8008                                 |                                                                                                                                          | 662865 |
| 797 11/21/2013 435912 | FOAM CUSHION ISRI 6860 (THICK)                              |                                                                                                                                          | 662865 |
| 797 11/21/2013 435912 | Drivers seat base needs replacing                           | Replaced drivers seat base cushion and cover                                                                                             | 662865 |
| 797 11/20/2013 435672 |                                                             | A - Service & Bus Safety Inspection                                                                                                      | 662749 |
| 797 11/20/2013 435672 |                                                             | Tension ALL Wheel Nuts to OEM Specs                                                                                                      | 662749 |
| 797 11/20/2013 435672 |                                                             | A - Service & Bus Safety Inspection                                                                                                      | 662749 |
| 797 11/11/2013 434187 | GLOBE 24V 21W SINGLE CONTACT                                |                                                                                                                                          | 660671 |
| 797 11/11/2013 434187 | O/S/F indicator light N/W                                   | Replaced indicator globe                                                                                                                 | 660671 |
| 797 11/09/2013 432918 | REPAIR/REPLACE SEAT COVER/FOAM                              | Creditor #:IB-TRI001 TRIM IMPROVEMENTS P/O #:V131654 Receiving #:133134 Date :2013-11-11                                                 | 660671 |
| 797 11/01/2013 425040 | IMAGE RELATED REPAIRS TO BUSES                              | Creditor #:IB-TRA001 TRANSCAL P/O #:V132028 Receiving #:134064 Date :2013-12-03                                                          | 664830 |
| 797 10/31/2013 432918 | Passenger Seat Cushion damaged offside 2nd last seat.       | Replaced seat base                                                                                                                       | 658808 |
| 797 10/28/2013 432347 |                                                             | Transmission /check as per Check List                                                                                                    | 657967 |
| 797 10/25/2013 432147 |                                                             | CCTV Hard Drive Check                                                                                                                    | 657765 |
| 797 10/25/2013 432147 |                                                             | Door Service                                                                                                                             | 657765 |
| 797 10/21/2013 431158 | SHOCKER ADJUSTER                                            |                                                                                                                                          | 656795 |
| 797 10/21/2013 431158 | Drivers seat shocker control n/w                            | Replaced drivers seat control adjuster                                                                                                   | 656795 |
| 797 10/19/2013 431117 | Remove A3 Poster 15/8Fit Poster (HOLD ON) as per Campaign   | Completed campaign                                                                                                                       | 656795 |
| 797 10/09/2013 429355 | Washers N/W                                                 | Cleaned out washer jets washers working OK                                                                                               | 654850 |
| 797 10/09/2013 429355 | Graffiti on passenger seats & floor                         | Removed graffiti                                                                                                                         | 654850 |
| 797 10/09/2013 418357 | AIR CONDITIONING REPAIR                                     | Creditor #:IB-COL004 COLDDRIVE P/O #:V130505 Receiving #:132086 Date :2013-10-15 REPLACED 1 X CONDENSOR & 2 X EVAP FAN ASSEMBLIES        | 655587 |
| 797 10/09/2013 429355 | LIGHT DIFFUSER 3M LENGHT                                    |                                                                                                                                          | 654850 |
| 797 10/09/2013 429355 | GLOBE+HOLDER INSTRUMENT (GREY)                              |                                                                                                                                          | 654850 |
| 797 10/09/2013 429355 | GLOBE WEDGE 24V 1.2W                                        |                                                                                                                                          | 654850 |
| 797 10/09/2013 429355 | Switch lights N/W                                           | Replaced globes                                                                                                                          | 654850 |
| 797 10/09/2013 429355 | Saloon light N/W & N/S/R saloon light defuser missing?      | Replaced light defuser fluoro light invertor & replaced fluoro tube working OK                                                           | 654850 |
| 797 10/09/2013 429355 | Tacho light N/W                                             | Replaced globes                                                                                                                          | 654850 |
| 797 10/09/2013 429355 | FLURO INVERTER 24V 40W                                      |                                                                                                                                          | 654850 |
| 797 10/09/2013 429355 | FLURO TUBE 18W                                              |                                                                                                                                          | 654850 |
| 797 10/09/2013 429253 |                                                             | Tension ALL Wheel Nuts to OEM Specs                                                                                                      | 654850 |
| 797 10/09/2013 429253 |                                                             | A - Service & Bus Safety Inspection                                                                                                      | 654850 |
| 797 10/05/2013 428703 | Perform sticker audit on vehicles ensuring that correct sti | Carried out campaign                                                                                                                     | 654413 |
| 797 10/02/2013 418357 | Drv entered - Heat & Demist                                 | Assitted Colddrive & checked over a/c system a/c hose at compressor leaking requires further work                                        | 653681 |
| 797 09/26/2013 423489 | FITTING                                                     | Creditor #:IB-MIC002 MICHELIN AUSTRALIA P/O #:V129934 Receiving #:131465 Date :2013-09-30                                                | 653443 |
| 797 09/26/2013 423489 | 295/80R22.5 RECAMIC DRIVE PATT                              | Creditor #:IB-MIC002 MICHELIN AUSTRALIA P/O #:V129934 Receiving #:131465 Date :2013-09-30                                                | 653443 |
| 797 09/26/2013 427359 | GLOBE H1 24V 70W                                            |                                                                                                                                          | 652597 |
| 797 09/26/2013 427359 | N/S Headlight n/w                                           | Replaced globe                                                                                                                           | 652597 |
| 797 09/24/2013 426823 | Not starting                                                | Checked starting tested batteries replaced one battery using S/H battery starting OK                                                     | 651967 |
| 797 09/19/2013 425858 | BALANCE OFF VEHICLE                                         | Creditor #:IB-MIC002 MICHELIN AUSTRALIA P/O #:V129687 Receiving #:131108 Date :2013-09-20                                                | 651967 |
| 797 09/19/2013 425858 | FITTING                                                     | Creditor #:IB-MIC002 MICHELIN AUSTRALIA P/O #:V129687 Receiving #:131108 Date :2013-09-20                                                | 651967 |
| 797 09/19/2013 425858 | 295/80R22.5 XZE2+                                           | Creditor #:IB-MIC002 MICHELIN AUSTRALIA P/O #:V129687 Receiving #:131108 Date :2013-09-20                                                | 651967 |
| 797 09/18/2013 425858 | Ops Entered - Fault - Whls & Tyres Soft - Route: - Arrive   | Replaced N/S/F tyre                                                                                                                      | 651158 |
| 797 09/18/2013 425921 | Ops Entered - Fault - Elec & Light Interior Lights - Route: | Replaced switch on saloon lights                                                                                                         | 651158 |
| 797 09/18/2013 425921 | INTERIOR LIGHTS SWITCH BROKEN                               | Replaced switch                                                                                                                          | 651158 |
| 797 09/18/2013 425921 | 3WAY SWITCH 24V OFF-1/2 LIT                                 |                                                                                                                                          | 651158 |
| 797 09/18/2013 425921 | SYMBOL (SALOON LIGHT) SWF SWITCH                            |                                                                                                                                          | 651158 |
| 797 09/18/2013 425921 | Coolant leaking from radiator                               | Pressured test hose broken removed and fitted 2nd hand hose                                                                              | 651158 |
| 797 09/12/2013 425040 | Carry out campaign as per Fleet re-branding Procedure.      | Removed decals                                                                                                                           | 650163 |
| 797 09/12/2013 425040 | Carry out campaign as per Fleet re-branding Procedure.      | Removed decals                                                                                                                           | 650163 |
| 797 09/11/2013 424665 | ROADSIDE BREAKDOWN                                          | Creditor #:IB-EAS003 EASTCOAST TRUCK & BUS SERVICE P/O #:V129385 Receiving #:130783 Date :2013-09-12 CHANGE O/S/R TYRE - WAVERLY GARDENS | 650315 |
| 797 09/11/2013 424665 | Bus had a flat O/S/R/O tyre at Waverly Garderns S/C Eastco  | Refer to W/O # 424659                                                                                                                    | 649882 |
| 797 09/11/2013 424659 | Bus had a flat O/S/R/O tyre at Waverly Garderns S/C Eastco  | Eastcoast replaced tyre                                                                                                                  | 649882 |
| 797 09/09/2013 422204 | BUMPER CORNER N/S CR228L                                    |                                                                                                                                          | 649316 |
| 797 09/04/2013 423489 | O/S/R/I Tyre flat                                           | Tyre changed by eastcoast knox                                                                                                           | 648258 |
| 797 09/04/2013 423490 | Ops Entered - Breakdown - Breakdown 1-Mech Defect Affects S | Tyre changed by eastcoast                                                                                                                | 648258 |
| 797 08/30/2013 422945 | GLOBE 24V 21W SINGLE CONTACT                                |                                                                                                                                          | 647363 |
| 797 08/30/2013 422945 | N/S/L INDICATOR OUT                                         | Replaced globe                                                                                                                           | 647363 |
| 797 08/29/2013 421740 | VALVE FOOT SERVICE BRAKE                                    | Creditor #:IB-EAS003 EASTCOAST TRUCK & BUS SERVICE P/O #:V128709 Receiving #:130152 Date :2013-08-29                                     | 647089 |
| 797 08/28/2013 421567 | Graffiti on & torn passenger seats                          | Refitted rear seat base                                                                                                                  | 647089 |

|     |            |        |                                                             |                                                                                                                                                                                                        |        |
|-----|------------|--------|-------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|
| 797 | 08/28/2013 | 421740 | Air leak at brake foot valve when brakes applied heavily    | Replaced foot valve & setup Road test OK brake temps NSR 98c OSF98c NSR 98cOSR105c                                                                                                                     | 647089 |
| 797 | 08/28/2013 | 422204 | PAINT SUPPLIES                                              |                                                                                                                                                                                                        | 647089 |
| 797 | 08/28/2013 | 422204 | BODY SHOP SUPPLIES                                          |                                                                                                                                                                                                        | 647089 |
| 797 | 08/28/2013 | 422204 | Accident Damaged # 37852 R/R.Front bumper-bar. Repair front | Repaired Accident Damaged # 37852                                                                                                                                                                      | 647089 |
| 797 | 08/28/2013 | 422204 | Accident Damaged # 37852                                    | Repaired Accident Damaged # 37852                                                                                                                                                                      | 647089 |
| 797 | 08/26/2013 | 422075 | BUSH TORQUE ROD KIT                                         |                                                                                                                                                                                                        | 647089 |
| 797 | 08/26/2013 | 422075 | O/S/F/F track rod bush needs replacing                      | Replaced both O/S/F track rod bushes                                                                                                                                                                   | 647089 |
| 797 | 08/24/2013 | 421885 | Remove A3 Marketing Poster 30/9Fit Marketing Poster 15/8    | Complete campaign                                                                                                                                                                                      | 647089 |
| 797 | 08/23/2013 | 421567 | REPAIR/REPLACE SEAT COVER/FOAM                              | Creditor #:IB-TRI001 TRIM IMPROVEMENTS P/O #:V128602 Receiving #:130148 Date :2013-08-29                                                                                                               | 647089 |
| 797 | 08/23/2013 | 421567 | Graffiti on & torn passenger seats                          | Removed rear seat base for repair Refitted rear seat base After repair                                                                                                                                 | 647089 |
| 797 | 08/23/2013 | 421567 | A/C filter material needs replacing                         | Replaced A/C filter material                                                                                                                                                                           | 647089 |
| 797 | 08/23/2013 | 421740 | Air leak at brake foot valve when brakes applied heavily    | Checked foot valve & ordered                                                                                                                                                                           | 647089 |
| 797 | 08/22/2013 | 421476 | GLOBE WEDGE 24V 1.2W                                        |                                                                                                                                                                                                        | 647089 |
| 797 | 08/22/2013 | 421476 | FLURO TUBE 18W                                              |                                                                                                                                                                                                        | 647089 |
| 797 | 08/22/2013 | 421476 | Switch light N/W                                            | Replaced switch light globes                                                                                                                                                                           | 647089 |
| 797 | 08/22/2013 | 421476 | O/S/F saloon light N/W                                      | Replaced saloon light fluro tubes                                                                                                                                                                      | 647089 |
| 797 | 08/22/2013 | 421476 | Front step light N/W                                        | Replaced front step light fluro tube                                                                                                                                                                   | 647089 |
| 797 | 08/22/2013 | 421384 | O RING FILTER KIT K93                                       | Kit . filter Cent                                                                                                                                                                                      | 647089 |
| 797 | 08/22/2013 | 421384 | FILTER OIL K124 / L94UAB (H200W02)                          | Filter Oil                                                                                                                                                                                             | 647089 |
| 797 | 08/22/2013 | 421384 | HYDRAULIC TORQUE FLUID 414                                  | Torque fluid                                                                                                                                                                                           | 647089 |
| 797 | 08/22/2013 | 421384 | FILTER TRANSMISSION ZF 4139-298-038E39HD119                 | Filter ZF Trans                                                                                                                                                                                        | 647089 |
| 797 | 08/22/2013 | 421384 | FILTER FUEL K124 / LU94A (1411894 / H17WK05)                | Fuel Filter                                                                                                                                                                                            | 647089 |
| 797 | 08/22/2013 | 421384 | ENGINE OIL DELO 400LE 15W40                                 | Engine Oil                                                                                                                                                                                             | 647089 |
| 797 | 08/22/2013 | 421384 |                                                             | Tension ALL Wheel Nuts to OEM Specs                                                                                                                                                                    | 647089 |
| 797 | 08/22/2013 | 421384 |                                                             | A - Service & Bus Safety Inspection                                                                                                                                                                    | 647089 |
| 797 | 08/22/2013 | 421384 |                                                             | A - Service & Bus Safety Inspection                                                                                                                                                                    | 647089 |
| 797 | 08/10/2013 | 419547 | Perform Campaign as per Instructions Ensure that appropri   | Carried out campaign                                                                                                                                                                                   | 645070 |
| 797 | 08/09/2013 | 419353 |                                                             | CCTV Hard Drive Check                                                                                                                                                                                  | 644973 |
| 797 | 08/09/2013 | 419353 |                                                             | Door Service                                                                                                                                                                                           | 644973 |
| 797 | 08/08/2013 | 419144 | Low pad indicator light on                                  | Traced brake electrical fault removed O/S/F wheel and secured loose terminal connector road tested OK                                                                                                  | 644858 |
| 797 | 08/06/2013 | 418648 | GLOBE H1 24V 70W                                            |                                                                                                                                                                                                        | 644126 |
| 797 | 08/06/2013 | 418648 | N/S Headlight n/w                                           | Replaced globe                                                                                                                                                                                         | 644126 |
| 797 | 08/06/2013 | 418711 | Pad wear indicator light coming on                          | Darie Hipolito - Checked brake pads all ok cleaned connectors on N/S/F sensor road tested ok                                                                                                           | 644126 |
| 797 | 08/02/2013 | 418357 | Drv entered - Air Cond Air Conditioner                      | Refer to fault # 438777                                                                                                                                                                                | 644046 |
| 797 | 08/02/2013 | 418357 | Drv entered - Heat & Demist                                 | Checked a/c operation and componants ordered new condenser fan motor(secondfrom front) ordered new evaporator fan motor (o/s middle) a/c system low ongas to bechecked for leaks (possibly shaft seal) | 644046 |
| 797 | 08/02/2013 | 418357 | Drv entered - Heat & Demist                                 | Refer to fault # 438777                                                                                                                                                                                | 644046 |
| 797 | 08/02/2013 | 418357 | Drv entered - Other                                         | Refer to fault # 438777                                                                                                                                                                                | 644046 |
| 797 | 08/02/2013 | 418357 | 25mm BLACK NUMERAL                                          |                                                                                                                                                                                                        | 644046 |
| 797 | 08/02/2013 | 418357 | LTC external numbers need replacing                         |                                                                                                                                                                                                        | 644046 |
| 797 | 08/02/2013 | 418357 | LTC external numbers need replacing                         | Replaced number                                                                                                                                                                                        | 644046 |
| 797 | 08/02/2013 | 418357 | Drv entered - Body & Acc Mirrors Exterior                   | Adjusted all mirrors no faults found at this time                                                                                                                                                      | 644046 |
| 797 | 08/02/2013 | 417907 | PAINT SUPPLIES                                              |                                                                                                                                                                                                        | 644046 |
| 797 | 08/02/2013 | 417907 | BODY SHOP SUPPLIES                                          |                                                                                                                                                                                                        | 644046 |
| 797 | 08/02/2013 | 417907 | Accident Damaged # 37691 R/R. o/s/r. fleet No decals o/s/r  | Repaired accident damage # 37691                                                                                                                                                                       | 644046 |
| 797 | 08/01/2013 | 417907 | Complete Campaign 16/12 as required                         | Painted rims as required                                                                                                                                                                               | 644046 |
| 797 | 08/01/2013 | 417907 | Accident Damaged # 37691 R/R. o/s/r. fleet No decals o/s/r  | Repaired accident damage # 37691                                                                                                                                                                       | 644046 |
| 797 | 08/01/2013 | 417907 | Accident Damaged # 37691 R/R. o/s/r. fleet No decals o/s/r  | Repaired accident damage # 37691                                                                                                                                                                       | 644046 |
| 797 | 07/30/2013 | 417674 |                                                             | Tension ALL Wheel Nuts to OEM Specs                                                                                                                                                                    | 643879 |
| 797 | 07/30/2013 | 417674 |                                                             | A - Service & Bus Safety Inspection                                                                                                                                                                    | 643879 |
| 797 | 07/24/2013 | 416368 | BALANCE OFF VEHICLE                                         | Creditor #:IB-MIC002 MICHELIN AUSTRALIA P/O #:V127462 Receiving #:128634 Date :2013-07-25                                                                                                              | 642586 |
| 797 | 07/24/2013 | 416368 | FITTING                                                     | Creditor #:IB-MIC002 MICHELIN AUSTRALIA P/O #:V127462 Receiving #:128634 Date :2013-07-25                                                                                                              | 642586 |
| 797 | 07/24/2013 | 416368 | 295/80R22.5 XZE2+                                           | Creditor #:IB-MIC002 MICHELIN AUSTRALIA P/O #:V127462 Receiving #:128634 Date :2013-07-25                                                                                                              | 642586 |
| 797 | 07/23/2013 | 416368 | O/S/F tyre tread low                                        | Replaced O/S/F tyre using s/h steer tyre 6mm                                                                                                                                                           | 642253 |
| 797 | 07/22/2013 | 416305 | GLOBE 24V 21/SW STOP/TAIL                                   |                                                                                                                                                                                                        | 642171 |
| 797 | 07/22/2013 | 416305 | Park Lights OFFSIDE TOP REAR. n/w                           | Replaced globe                                                                                                                                                                                         | 642171 |
| 797 | 07/18/2013 | 415649 | HAZZRAD SWITCH SCANIA L94                                   |                                                                                                                                                                                                        | 641568 |
| 797 | 07/18/2013 | 415649 | Mechanic entered - Elec & Light Hazard Lights               | Replaced broken hazard light switch                                                                                                                                                                    | 641568 |
| 797 | 07/13/2013 | 414957 | Drv entered - Vandalism Graffiti                            | Removed graffiti                                                                                                                                                                                       | 640148 |
| 797 | 07/04/2013 | 413288 | L.E.D SIDE MARKER RED/AMBER                                 |                                                                                                                                                                                                        | 638941 |
| 797 | 07/04/2013 | 413288 | O/S rear side light ripped off.                             | Replaced o/s side light                                                                                                                                                                                | 638941 |
| 797 | 06/18/2013 | 410742 | FLURO TUBE 18W                                              |                                                                                                                                                                                                        | 636260 |
| 797 | 06/18/2013 | 410742 | LED NO PLATE+EXIT LIGHT                                     |                                                                                                                                                                                                        | 636260 |
| 797 | 06/18/2013 | 410742 | O/S number plate light N/W                                  | Replaced o/s number plate lamp                                                                                                                                                                         | 636260 |
| 797 | 06/18/2013 | 410742 | N/S saloon light & O/S step light N/W                       | Fitted new fluro to o/s step light n/s light disconnect due to glare on windscreen                                                                                                                     | 636260 |
| 797 | 06/18/2013 | 410742 | O/S/R saloon panel needs securing                           | Secured rear duct panel                                                                                                                                                                                | 636260 |
| 797 | 06/18/2013 | 410742 | O/S wheel chair seat mounting bolts loose                   | Removed passenger seat pins tightened seat bolts & refitted seat pins                                                                                                                                  | 636260 |
| 797 | 06/17/2013 | 410443 |                                                             | Tension ALL Wheel Nuts to OEM Specs                                                                                                                                                                    | 636129 |
| 797 | 06/17/2013 | 410443 |                                                             | A - Service & Bus Safety Inspection                                                                                                                                                                    | 636129 |
| 797 | 06/03/2013 | 408383 | Mechanic entered - Elec & Light Headlights                  | Replaced O/S headlight globe                                                                                                                                                                           | 633614 |
| 797 | 06/03/2013 | 408383 | GLOBE H1 24V 70W                                            |                                                                                                                                                                                                        | 633614 |
| 797 | 05/30/2013 | 407615 | Drv entered - Desto Signs                                   | Traced desto fault cleaned all connections on desto slave ribbon working ok at this time                                                                                                               | 632912 |
| 797 | 05/29/2013 | 407817 |                                                             | CCTV Hard Drive Check                                                                                                                                                                                  | 632828 |
| 797 | 05/29/2013 | 407817 |                                                             | Door Service replaced front step light fluro tube                                                                                                                                                      | 632828 |
| 797 | 05/29/2013 | 407817 | FLURO TUBE 18W                                              |                                                                                                                                                                                                        | 632828 |
| 797 | 05/28/2013 | 407615 | Drv entered - Air Cond Other Fan motor on roof noisy        | Checked a/c operation and componants secured condenser fan mounting plate to structural support of a/c roof pod a/c working ok at this time                                                            | 632649 |
| 797 | 05/28/2013 | 407615 | FLURO TUBE 18W                                              |                                                                                                                                                                                                        | 632649 |
| 797 | 05/28/2013 | 407615 | Drv entered - Elec & Light Interior Lights                  | Replaced fluro tube                                                                                                                                                                                    | 632649 |
| 797 | 05/20/2013 | 406175 | Drv entered - Air Cond Other                                | Checked a/c operation and componants working ok at this time no faultsfound                                                                                                                            | 630745 |
| 797 | 05/20/2013 | 406175 | A/C is very noisy on the roof.                              | Refer to fault # 427969                                                                                                                                                                                | 630745 |
| 797 | 05/16/2013 | 405634 | GLOBE+HOLDER INSTRUMENT (GREY)                              |                                                                                                                                                                                                        | 630288 |
| 797 | 05/16/2013 | 405634 | Drv entered - Elec & Light Speedo light blown.              | Replaced speedo light globes                                                                                                                                                                           | 630288 |
| 797 | 05/15/2013 | 405634 | Speedo light n/w                                            | Refer to fault # 427578                                                                                                                                                                                | 630049 |
| 797 | 05/14/2013 | 405445 |                                                             | Transmission /check as per Check List                                                                                                                                                                  | 629822 |
| 797 | 05/14/2013 | 405376 | Drv entered - Vandalism Graffiti                            | Removed graffiti                                                                                                                                                                                       | 629822 |
| 797 | 05/14/2013 | 405376 | Engine - Won't Start from front.                            | Checked over starting circuit & operation cleaned and lubed hatchswitch & tested engine starting ok                                                                                                    | 629822 |
| 797 | 05/14/2013 | 405376 | Drivers windscreen blind won't stay down while driving alon | Refer to fault # 426875                                                                                                                                                                                | 629822 |
| 797 | 05/14/2013 | 405376 | Drv entered - Body & Acc Drivers Blind keeps falling down.  | Repaired sun blind mechanism & refitted                                                                                                                                                                | 629822 |
| 797 | 05/06/2013 | 404045 | FILTER AIR DRYER SCANIA K124EB (T350W)                      | Filter Air Dryer                                                                                                                                                                                       | 627690 |
| 797 | 05/06/2013 | 404045 | Diff Oil Borate EP 460                                      | diff oil                                                                                                                                                                                               | 627690 |
| 797 | 05/06/2013 | 404045 |                                                             | Service as per check list                                                                                                                                                                              | 627690 |
| 797 | 05/06/2013 | 404045 | FILTER K124EB HYD COOLING FAN                               | Hydraulic filter                                                                                                                                                                                       | 627690 |
| 797 | 05/06/2013 | 404045 | POWER STEERING FILTER VOLVO                                 | Power steering filter                                                                                                                                                                                  | 627690 |
| 797 | 05/06/2013 | 404045 | FUEL FILTER ELEMENT SCANIA L94UAB (R90T / H7090WK10)        | Raycor filter                                                                                                                                                                                          | 627690 |

|     |            |        |                                                              |                                                                                                                                          |        |
|-----|------------|--------|--------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------|--------|
| 797 | 05/06/2013 | 404045 | HYDRAULIC TORQUE FLUID 414                                   | Hydraulic oil                                                                                                                            | 627690 |
| 797 | 05/06/2013 | 404045 |                                                              | Tension ALL Wheel Nuts to OEM Specs                                                                                                      | 627690 |
| 797 | 05/06/2013 | 404045 |                                                              | A - Service & Bus Safety Inspection                                                                                                      | 627690 |
| 797 | 05/03/2013 | 402708 | PAINT SUPPLIES                                               |                                                                                                                                          | 627690 |
| 797 | 05/03/2013 | 402708 | BODY SHOP SUPPLIES                                           |                                                                                                                                          | 627690 |
| 797 | 05/03/2013 | 402709 | PAINT SUPPLIES                                               |                                                                                                                                          | 627690 |
| 797 | 05/03/2013 | 402709 | BODY SHOP SUPPLIES                                           |                                                                                                                                          | 627690 |
| 797 | 05/01/2013 | 403379 | MOTOR CONDENSOR FAN AC353                                    |                                                                                                                                          | 627690 |
| 797 | 05/01/2013 | 403379 | Drv entered - Heat & Demist Noisy                            | Checked heaters and a/c operation replaced three faulty condenser fan motors a/c and heating working ok at this time                     | 627690 |
| 797 | 04/30/2013 | 403236 | N/S wiper blade needs replacing                              | Fitted new wiper blade to o/s & swapped o/s to n/s                                                                                       | 627690 |
| 797 | 04/30/2013 | 403236 | BELT VEE                                                     |                                                                                                                                          | 627690 |
| 797 | 04/30/2013 | 403236 | A/C belts need replacing                                     | Replaced A/C belts                                                                                                                       | 627690 |
| 797 | 04/30/2013 | 403236 | BOLLARD SP-RBOLLARD S570155                                  |                                                                                                                                          | 627690 |
| 797 | 04/30/2013 | 403236 | DO NOT OVERTAKE TURNING DECAL                                |                                                                                                                                          | 627690 |
| 797 | 04/30/2013 | 403236 | REAR MARKER DECAL                                            |                                                                                                                                          | 627690 |
| 797 | 04/30/2013 | 403236 | Passenger seat base loose                                    | Fitted bollard to seat & secured                                                                                                         | 627690 |
| 797 | 04/30/2013 | 403236 | O/S/R body panels loose                                      | Fitted & secured body panels                                                                                                             | 627690 |
| 797 | 04/30/2013 | 403236 | DNOT decals & marker plates need replacing                   | Fitted new marker plate decals & DNOT decals                                                                                             | 627690 |
| 797 | 04/29/2013 | 402709 | Accident Damaged # 36953 * To be repaired on site * R/R. n/  | Repaired accident damage # 36953                                                                                                         | 627690 |
| 797 | 04/26/2013 | 402709 | Accident Damaged # 36953 * To be repaired on site * R/R. n/  | Repaired accident damage # 36953                                                                                                         | 627690 |
| 797 | 04/26/2013 | 402708 | Accident Damaged # 36923 * To be repaired on site* R/R. o/s  | Repaired accident damage # 36923                                                                                                         | 627690 |
| 797 | 04/24/2013 | 402620 | FILTER AIR SCANIA USE AF25066                                |                                                                                                                                          | 627690 |
| 797 | 04/24/2013 | 402620 | O RING FILTER KIT K93                                        | Kit . filter Cent                                                                                                                        | 627690 |
| 797 | 04/24/2013 | 402620 | FILTER OIL K124 / L94UAB (H200W02)                           | Filter Oil                                                                                                                               | 627690 |
| 797 | 04/24/2013 | 402620 | HYDRAULIC TORQUE FLUID 414                                   | Torque fluid                                                                                                                             | 627690 |
| 797 | 04/24/2013 | 402620 | FILTER TRANSMISSION ZF 4139-298-038E39HD119                  | Filter ZF Trans                                                                                                                          | 627690 |
| 797 | 04/24/2013 | 402620 | FILTER FUEL K124 / LU94A (1411894 / H17WK05)                 | Fuel Filter                                                                                                                              | 627690 |
| 797 | 04/24/2013 | 402620 | ENGINE OIL DELO 400LE 15W40                                  | Engine Oil                                                                                                                               | 627690 |
| 797 | 04/24/2013 | 402620 |                                                              | Tension ALL Wheel Nuts to OEM Specs                                                                                                      | 627690 |
| 797 | 04/24/2013 | 402620 |                                                              | A - Service & Bus Safety Inspection                                                                                                      | 627690 |
| 797 | 04/24/2013 | 402620 |                                                              | A - Service & Bus Safety Inspection                                                                                                      | 627690 |
| 797 | 04/09/2013 | 399416 | SCANIA L94UAB ACC PEDAL SENSOR                               | Creditor #:EAS002 EASTSIDE TRUCK & BUS SERVICE P/O #:V122367 Receiving #:123661 Date :2013-04-15                                         | 626004 |
| 797 | 04/08/2013 | 400092 | Transmission needs washing & checking for leaks?             | Washed and checked transmission for leaks tightened plate on back oftransmission                                                         | 624576 |
| 797 | 04/08/2013 | 400092 | GLOBE WEDGE 24V 1.2W                                         |                                                                                                                                          | 624576 |
| 797 | 04/08/2013 | 400092 | MUDFLAP UNIVERSAL                                            |                                                                                                                                          | 624576 |
| 797 | 04/08/2013 | 400092 | Tacho light N/W                                              | Replaced globe                                                                                                                           | 624576 |
| 797 | 04/08/2013 | 400092 | N/S/T tail light N/W                                         | Checked tail light ok at this time                                                                                                       | 624576 |
| 797 | 04/08/2013 | 400092 | N/S/F mudflap torn                                           | Replaced mudflap                                                                                                                         | 624576 |
| 797 | 04/05/2013 | 399416 | BALL JOINT LOAD SENSOR 4HP500                                |                                                                                                                                          | 624576 |
| 797 | 04/05/2013 | 399416 | Under light throttle engine feels as it is surging           | Replaced TPS made & fitted new link & replaced ball joints deleted faultcodes & road tested                                              | 624576 |
| 797 | 04/05/2013 | 399749 |                                                              | Tension ALL Wheel Nuts to OEM Specs                                                                                                      | 624576 |
| 797 | 04/05/2013 | 399749 |                                                              | A - Service & Bus Safety Inspection                                                                                                      | 624576 |
| 797 | 04/03/2013 | 399416 | Engine light comes on and bus loses power and comes to a sto | Refer to fault # 420683                                                                                                                  | 624576 |
| 797 | 04/03/2013 | 399416 | Under light throttle engine feels as it is surging           | Checked engine fault codes & removed road tested throttle pot fault returned checked pot with testman pot has dead sectors ordered parts | 624576 |
| 797 | 03/27/2013 | 398778 | DELO EXTENDED LIFE COOLANT PRE-MIX                           |                                                                                                                                          | 624144 |
| 797 | 03/27/2013 | 398778 | CAP EXPANSION TANK K93 SCANIA                                |                                                                                                                                          | 624144 |
| 797 | 03/27/2013 | 398778 | Coolant filler cap needs replacing                           | Replaced coolant pressure cap & topped up coolant                                                                                        | 624144 |
| 797 | 03/25/2013 | 398426 | W'rning Light engine de-rating frequently.                   | Checked fault codes 15 not active removed and cleaned boost sensorroad tested not faulting                                               | 623948 |
| 797 | 03/22/2013 | 398221 | Drv entered - Wipers & Washers Washers Not Working           | Filled washer bottle & bleed washer motor working OK                                                                                     | 623226 |
| 797 | 03/18/2013 | 385183 | Muffler missing from quick reease valve                      | Removed broken muffler muffler not required                                                                                              | 622261 |
| 797 | 03/15/2013 | 397043 | Driver's blind won't lock in place. Moves while driving.     | Checked drivers blind operation repaired faulty componant refitted to bus and tested working ok at this time                             | 621706 |
| 797 | 03/15/2013 | 397043 | Drivers blind front windscreen goes up while driving         | Refer to fault # 418838                                                                                                                  | 621706 |
| 797 | 03/12/2013 | 396589 |                                                              | CCTV Hard Drive Check                                                                                                                    | 620894 |
| 797 | 03/12/2013 | 396589 |                                                              | Door Service                                                                                                                             | 620894 |
| 797 | 03/04/2013 | 395432 | Engine hatch switch faulty                                   | Cleaned and lubed hatch switch working ok at this time                                                                                   | 619464 |
| 797 | 03/04/2013 | 395337 | GLOBE WEDGE 24V 1.2W                                         |                                                                                                                                          | 619464 |
| 797 | 03/03/2013 | 395337 |                                                              | RSI Inspection (RWC 920999 )                                                                                                             | 619464 |
| 797 | 02/26/2013 | 394662 | O/S windscreen has large stone chip                          | Elite replaced windscreen                                                                                                                | 618458 |
| 797 | 02/26/2013 | 394662 | ONE PIECE WINDSCREEN                                         | Creditor #:ELI001 ELITE WINDSCREENS P/O #:V120836 Receiving #:121652 Date :2013-02-28                                                    | 618956 |
| 797 | 02/23/2013 | 394311 | Perform Campaign 01_13 CCTV and GPS AUDIT inspect vehicles   | Carried out audit                                                                                                                        | 617996 |
| 797 | 02/22/2013 | 385183 | SILENCER BRAKE RELAY VALVE L                                 | Creditor #:EAS002 EASTSIDE TRUCK & BUS SERVICE P/O #:V118077 Receiving #:121536 Date :2013-02-26                                         | 618774 |
| 797 | 02/21/2013 | 393917 |                                                              | Inspect vehicle as per RSI Checklist                                                                                                     | 617862 |
| 797 | 02/21/2013 | 393988 | FLURO TUBE 18W                                               |                                                                                                                                          | 617862 |
| 797 | 02/21/2013 | 393988 | Saloon lights N/W                                            | Replaced fluro                                                                                                                           | 617862 |
| 797 | 02/21/2013 | 393988 | L.E.D.STOP+TAIL LIGHT                                        |                                                                                                                                          | 617862 |
| 797 | 02/21/2013 | 393988 | O/S lower tail light dull                                    | Replaced lamp                                                                                                                            | 617862 |
| 797 | 02/21/2013 | 393988 | PANEL SCREW 6X30                                             |                                                                                                                                          | 617862 |
| 797 | 02/21/2013 | 393988 | Rubber edge strip falling out behind 5 O/S passenger seat &  | Cleaned & refitted strip                                                                                                                 | 617862 |
| 797 | 02/21/2013 | 393988 | Screw missing from O/S/R wheel arch panel                    | Replaced panel screw                                                                                                                     | 617862 |
| 797 | 02/21/2013 | 393988 | Drivers door hinge pin needs refitting                       | Refitted hinge                                                                                                                           | 617862 |
| 797 | 02/19/2013 | 393719 | Will not start from front. Only from rear.                   | Checked starting replaced faulty start interlock relay using second hand relay                                                           | 617495 |
| 797 | 02/12/2013 | 392669 | O/S/R track rod bush steel around rubber cracked             | Removed track rod and removed broken circlip replaced bush and refitted                                                                  | 616228 |
| 797 | 02/12/2013 | 392669 | V bar bush chassis end needs to be refitted circlip popped   | Circlip groove has slight damage locktight new circlip in and refitted v bar                                                             | 616228 |
| 797 | 02/12/2013 | 392669 | TORQUE ROD BUSH SUIT V STAY SCANIA                           |                                                                                                                                          | 616228 |
| 797 | 02/12/2013 | 392669 | Silencer broken off quick release valve                      | Silencer ordered refer to W/O # 385183                                                                                                   | 616228 |
| 797 | 02/11/2013 | 392669 | V bar bush chassis end needs to be refitted circlip popped   | Removed v bar                                                                                                                            | 616228 |
| 797 | 02/08/2013 | 392334 |                                                              | A - Service & Bus Safety Inspection                                                                                                      | 616228 |
| 797 | 02/08/2013 | 392334 |                                                              | Tension ALL Wheel Nuts to OEM Specs                                                                                                      | 616228 |
| 797 | 01/17/2013 | 389179 | Won't start with key. Have to start from rear.               | Checked starting and charging delay in starting curcuit fitted S/H module & tested starting ok at this time                              | 611857 |
| 797 | 01/07/2013 | 386167 | Coolant leak at radiator area?                               | Replaced radiator road tested and checked for leaks ok                                                                                   | 610148 |
| 797 | 12/27/2012 | 386167 | RADIATOR ASSY (690MM WIDE)                                   | Creditor #:MUL001 MULTISPARES LTD P/O #:V118324 Receiving #:118939 Date :2012-12-27                                                      | 610148 |
| 797 | 12/24/2012 | 386167 | Coolant leak at radiator area?                               | Checked over for coolant leaks and ordered new radiator                                                                                  | 609893 |
| 797 | 12/21/2012 | 385183 | O/S wiper not clearing screen                                | Replaced wiper blade                                                                                                                     | 609364 |
| 797 | 12/21/2012 | 386030 | Brake lights not working                                     | Replaced burt out relay reset fuse tested ok moisture ejectoru/s disassembled & replaced coil overhauled unit tested ok                  | 609364 |
| 797 | 12/21/2012 | 386030 | RELAY 24V MERC 0500LE INDICATORS                             |                                                                                                                                          | 609364 |
| 797 | 12/21/2012 | 386030 | CYCLONE CONDENSER VALVE KIT                                  |                                                                                                                                          | 609364 |
| 797 | 12/21/2012 | 386030 | HALDEX COIL KIT 0500LE                                       |                                                                                                                                          | 609364 |
| 797 | 12/19/2012 | 380708 | DISPOSAL CHARGE                                              | Creditor #:MIC050 MICHELIN AUSTRALIA PTY LTD P/O #:V118047 Receiving #:118703 Date :2012-12-20 CAP RETURNED NWR                          | 609364 |
| 797 | 12/19/2012 | 385183 | 900MM WIPER BLADE                                            | Creditor #:MUL001 MULTISPARES LTD P/O #:V118075 Receiving #:118684 Date :2012-12-20                                                      | 609364 |
| 797 | 12/18/2012 | 380708 | FITTING                                                      | Creditor #:MIC050 MICHELIN AUSTRALIA PTY LTD P/O #:V117904 Receiving #:118695 Date :2012-12-20                                           | 609364 |
| 797 | 12/18/2012 | 380708 | 295/80R22.5 RECAMIC DRIVE PATT                               | Creditor #:MIC050 MICHELIN AUSTRALIA PTY LTD P/O #:V117904 Receiving #:118695 Date :2012-12-20                                           | 609364 |
| 797 | 12/18/2012 | 380708 | DISPOSAL CHARGE                                              | Creditor #:MIC050 MICHELIN AUSTRALIA PTY LTD P/O #:V117904 Receiving #:118695 Date :2012-12-20                                           | 609364 |
| 797 | 12/18/2012 | 380708 | FRANCHISEE CASE                                              | Creditor #:MIC050 MICHELIN AUSTRALIA PTY LTD P/O #:V117904 Receiving #:118695 Date :2012-12-20                                           | 609364 |

|     |            |        |                                                              |                                                                                                                 |        |
|-----|------------|--------|--------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|--------|
| 797 | 12/17/2012 | 385183 | O/S wiper not clearing screen                                | Wiper blade on order                                                                                            | 608739 |
| 797 | 12/17/2012 | 385183 | O/S/R track rod bush housing split                           | Washed off and checked housing ok tin cover has small crack ok                                                  | 608739 |
| 797 | 12/17/2012 | 385183 | Oil leaks at A/C hose fittings                               | Washed off and checked ok checked compressor oil level ok                                                       | 608739 |
| 797 | 12/17/2012 | 385183 | Switch lights N/W                                            | Replaced globes                                                                                                 | 608739 |
| 797 | 12/17/2012 | 385183 | O/S/R saloon light N/W                                       | Replaced light tube                                                                                             | 608739 |
| 797 | 12/17/2012 | 385183 | Speedo light N/W                                             | Replaced globe                                                                                                  | 608739 |
| 797 | 12/17/2012 | 385183 | GLOBE+HOLDER INSTRUMENT (GREY)                               |                                                                                                                 | 608739 |
| 797 | 12/17/2012 | 385183 | GLOBE WEDGE 24V 1.2W                                         |                                                                                                                 | 608739 |
| 797 | 12/17/2012 | 385183 | FLURO TUBE 18W                                               |                                                                                                                 | 608739 |
| 797 | 12/17/2012 | 385183 | Front external step light dull                               | Replaced light tube                                                                                             | 608739 |
| 797 | 12/17/2012 | 385183 | N/S/R seat frame loose                                       | Replaced missing bolt                                                                                           | 608739 |
| 797 | 12/17/2012 | 385183 | N/S/R step tread loose behind seat                           | Refitted tread down                                                                                             | 608739 |
| 797 | 12/17/2012 | 385183 | Muffler missing from quick release valve                     | New muffler ordered                                                                                             | 608739 |
| 797 | 12/17/2012 | 385219 |                                                              | CCTV Hard Drive Check                                                                                           | 608739 |
| 797 | 12/17/2012 | 385219 |                                                              | Door Service                                                                                                    | 608739 |
| 797 | 12/12/2012 | 380708 | N/S/R tyre treads low                                        | Replaced N/S/R tyres                                                                                            | 605727 |
| 797 | 12/11/2012 | 384583 | FILTER OIL K124 / L94UAB (H200W02)                           | Filter Oil                                                                                                      | 608225 |
| 797 | 12/11/2012 | 384583 | O RING FILTER KIT K93                                        | Kit . filter Cent                                                                                               | 608225 |
| 797 | 12/11/2012 | 384583 |                                                              | A - Service & Bus Safety Inspection                                                                             | 608225 |
| 797 | 12/11/2012 | 384583 |                                                              | Tension ALL Wheel Nuts to OEM Specs                                                                             | 608225 |
| 797 | 12/11/2012 | 384583 | ENGINE OIL DELO 400LE 15W40                                  | Engine Oil                                                                                                      | 608225 |
| 797 | 12/11/2012 | 384583 | FILTER FUEL K124 / LU94A (1411894 / H17WK05)                 | Fuel Filter                                                                                                     | 608225 |
| 797 | 12/11/2012 | 384583 | FILTER TRANSMISSION ZF 4139-298-038E39HD119                  | Filter ZF Trans                                                                                                 | 608225 |
| 797 | 12/11/2012 | 384583 | HYDRAULIC TORQUE FLUID 414                                   | Torque fluid                                                                                                    | 608225 |
| 797 | 12/11/2012 | 384583 |                                                              | A - Service & Bus Safety Inspection                                                                             | 608225 |
| 797 | 11/27/2012 | 380708 | V bar bush needs replacing                                   | Finished off fitting v bar                                                                                      | 605727 |
| 797 | 11/27/2012 | 381998 | Starter motor needs replacing                                | Replaced starter motor                                                                                          | 605727 |
| 797 | 11/26/2012 | 380708 | V bar bush needs replacing                                   | Removed v bar replaced bushes and refitted v bar                                                                | 605727 |
| 797 | 11/26/2012 | 380708 | SCANIA L94UAB V STAY BUSH KIT                                |                                                                                                                 | 605727 |
| 797 | 11/26/2012 | 380708 | TORQUE ROD BUSH SUIT V STAY SCANIA                           |                                                                                                                 | 605727 |
| 797 | 11/22/2012 | 380708 | V bar bush needs replacing                                   |                                                                                                                 | 605727 |
| 797 | 11/22/2012 | 381998 | STARTER MOTOR 9T 35MM                                        |                                                                                                                 | 605727 |
| 797 | 11/21/2012 | 381407 | BODY SHOP SUPPLIES                                           |                                                                                                                 | 605727 |
| 797 | 11/21/2012 | 381407 | PAINT SUPPLIES                                               |                                                                                                                 | 605727 |
| 797 | 11/21/2012 | 381535 | BODY SHOP SUPPLIES                                           |                                                                                                                 | 605727 |
| 797 | 11/21/2012 | 381535 | PAINT SUPPLIES                                               |                                                                                                                 | 605727 |
| 797 | 11/20/2012 | 381535 | DECAL EMERGENCY EXIT PUSH BUTTON UNDER PANEL                 |                                                                                                                 | 605727 |
| 797 | 11/20/2012 | 381535 | Accident Damaged # 35955 R/R. rear door apeture rubber. Re   | Repaired accident damage # 35955                                                                                | 605727 |
| 797 | 11/19/2012 | 381407 | Accident Damaged # 36268 Repair front bumper-bar ~ centre.   | Repaired accident damage # 36268                                                                                | 605727 |
| 797 | 11/13/2012 | 380708 | Give way decal needs replacing                               | Replaced decal                                                                                                  | 605727 |
| 797 | 11/13/2012 | 380708 | Bus makes a clunking sound when accelerating around corners. | Checked for fault v bar bush u/s on order and o/s/r track rod bush cracked put off road refer to fault # 401480 | 605727 |
| 797 | 11/13/2012 | 380708 | Loose screw in upright grab rails                            | Tightened all loose screws and replaced missing screws                                                          | 605727 |
| 797 | 11/13/2012 | 380708 | GIVE WAY SIGN (LARGE)                                        |                                                                                                                 | 605727 |
| 797 | 10/30/2012 | 378829 |                                                              | A - Service & Bus Safety Inspection                                                                             | 604277 |
| 797 | 10/30/2012 | 378829 |                                                              | Tension ALL Wheel Nuts to OEM Specs                                                                             | 604277 |
| 797 | 10/30/2012 | 378829 |                                                              | Replaced batteries                                                                                              | 601678 |
| 797 | 10/17/2012 | 376931 | Batteries constantly needing jump start on AM shift?         |                                                                                                                 | 601678 |
| 797 | 10/17/2012 | 376931 | BATTERY 800CCA                                               |                                                                                                                 | 601493 |
| 797 | 10/16/2012 | 376710 |                                                              | Transmission /check as per Check List                                                                           | 599592 |
| 797 | 10/10/2012 | 376109 | Drv entered - Elec & Light Indicators                        | Replaced O/S/F side indicator light globe                                                                       | 599592 |
| 797 | 10/10/2012 | 376109 | GLOBE 24V 21W SINGLE CONTACT                                 |                                                                                                                 | 599592 |
| 797 | 10/09/2012 | 374959 | 295/80R22.5 RECAMIC DRIVE PATT                               | Creditor #:MIC050 MICHELIN AUSTRALIA PTY LTD P/O #:V114698 Receiving #:115430 Date :2012-10-10                  | 599592 |
| 797 | 10/09/2012 | 374959 | FITTING                                                      | Creditor #:MIC050 MICHELIN AUSTRALIA PTY LTD P/O #:V114698 Receiving #:115430 Date :2012-10-10                  | 599592 |
| 797 | 10/09/2012 | 374959 | DISPOSAL CHARGE                                              | Creditor #:MIC050 MICHELIN AUSTRALIA PTY LTD P/O #:V114698 Receiving #:115430 Date :2012-10-10                  | 599592 |
| 797 | 10/02/2012 | 374959 | O/S/R/l tyre tread low                                       | Replaced o/s/r tyres fitted new caps                                                                            | 598583 |
| 797 | 10/02/2012 | 374999 | Drv entered - Body & Acc Mirrors Exterior - Needs adjustment | Adjusted mirror arm & head                                                                                      | 598583 |
| 797 | 09/25/2012 | 373873 |                                                              | Door Service                                                                                                    | 596998 |
| 797 | 09/25/2012 | 373873 |                                                              | CCTV Hard Drive Check                                                                                           | 596998 |
| 797 | 09/18/2012 | 372904 | Rear door pivot bracket loose                                | Tightened door bracket                                                                                          | 595995 |
| 797 | 09/18/2012 | 372904 | O/S/R low pad wiring needs securing                          | Secured wiring                                                                                                  | 595995 |
| 797 | 09/18/2012 | 372904 | LIGHT DIFFUSER 3M LENGHT                                     |                                                                                                                 | 595995 |
| 797 | 09/18/2012 | 372904 | Starter motor only cranking 50 percent of the time           | Tested starter operation no fault found at this time                                                            | 595995 |
| 797 | 09/18/2012 | 372904 | O/S/F saloon light defuser broken                            | Replaced defuser                                                                                                | 595995 |
| 797 | 09/18/2012 | 372904 | GLOBE 24V 5W BAYONETT                                        |                                                                                                                 | 595995 |
| 797 | 09/18/2012 | 372904 | Globe N/W in bus stopping sign                               | Replaced globes                                                                                                 | 595995 |
| 797 | 09/18/2012 | 372904 | N/S/F wheel arch brush damaged                               | Replaced wheel brush                                                                                            | 595995 |
| 797 | 09/18/2012 | 372904 | Bolts loose at several folding seats at wall                 | Secured loose seat bolts                                                                                        | 595995 |
| 797 | 09/18/2012 | 372904 | Rivots missing from several roll tops                        | Replaced rivots                                                                                                 | 595995 |
| 797 | 09/18/2012 | 372904 | Hand rail screws loose in roof                               | Secured loose hand rail screws                                                                                  | 595995 |
| 797 | 09/18/2012 | 372904 | PIPE JOINER 12MM                                             |                                                                                                                 | 595995 |
| 797 | 09/18/2012 | 372904 | Air leak from O/S/F brake                                    | Replaced leaking o/s/f diaphram and replaced rubbed through brake line                                          | 595995 |
| 797 | 09/18/2012 | 372814 |                                                              | A - Service & Bus Safety Inspection                                                                             | 595995 |
| 797 | 09/18/2012 | 372814 |                                                              | Tension ALL Wheel Nuts to OEM Specs                                                                             | 595995 |
| 797 | 09/05/2012 | 371198 | Drv entered - Wipers & Washers Washers Not Working           | Replaced faulty washer pump motor washers working OK                                                            | 593000 |
| 797 | 09/05/2012 | 371198 | PUMP WIPER-WASHER 24 VOLT                                    |                                                                                                                 | 593000 |
| 797 | 09/05/2012 | 371198 | Drv entered - Brakes ABS On                                  | Checked abs codes (85 inactive) cleared codes road tested vehicle no further faults found at this time          | 593000 |
| 797 | 08/22/2012 | 368654 | Engine warning light ON                                      | Replaced engine charge air sensor road tested ok                                                                | 590316 |
| 797 | 08/17/2012 | 368654 | Engine warning light ON                                      | Traced engine warning light fault charge air sensor needs replacing ordered sensor                              | 588969 |
| 797 | 08/17/2012 | 368654 | SENSOR T47 CHARGE AIR                                        | Creditor #:EAS002 EASTSIDE TRUCK & BUS SERVICE P/O #:V112511 Receiving #:113098 Date :2012-08-22 BUS 797        | 590316 |
| 797 | 08/15/2012 | 368282 | Engine warning light ON                                      | Cleared fault codes road tested checked codes no codes logged okat this time                                    | 588763 |
| 797 | 08/10/2012 | 367527 | Alternator belt idler pulley bearing noisey metal pulley ab  | Replaced metal engine idler pulley bearing                                                                      | 588089 |
| 797 | 08/10/2012 | 367527 | 152 FAN HUB BEARING                                          |                                                                                                                 | 588089 |
| 797 | 08/10/2012 | 367521 | Switch light N/W                                             | Replaced switch light globes                                                                                    | 588089 |
| 797 | 08/10/2012 | 367521 | GLOBE WEDGE 24V 1.2W                                         |                                                                                                                 | 588089 |
| 797 | 08/10/2012 | 367555 | ROLLER PIVOT                                                 |                                                                                                                 | 588089 |
| 797 | 08/10/2012 | 367555 | A/C panels rattling                                          | Road tested and found no loose a/c panels rear door rattling replaced bottom pivot bush                         | 588089 |
| 797 | 08/09/2012 | 367341 |                                                              | A - Service & Bus Safety Inspection                                                                             | 587861 |
| 797 | 08/09/2012 | 367341 |                                                              | Tension ALL Wheel Nuts to OEM Specs                                                                             | 587861 |
| 797 | 08/09/2012 | 367341 | ENGINE OIL DELO 400LE 15W40                                  | Engine Oil                                                                                                      | 587861 |
| 797 | 08/09/2012 | 367341 | HYDRAULIC TORQUE FLUID 414                                   | Torque fluid                                                                                                    | 587861 |
| 797 | 08/09/2012 | 367341 | FILTER TRANSMISSION ZF 4139-298-038E39HD119                  | Filter ZF Trans                                                                                                 | 587861 |
| 797 | 08/09/2012 | 367341 | FILTER OIL K124 / L94UAB (H200W02)                           | Filter Oil                                                                                                      | 587861 |
| 797 | 08/09/2012 | 367341 | O RING FILTER KIT K93                                        | Kit . filter Cent                                                                                               | 587861 |
| 797 | 08/09/2012 | 367341 | FILTER FUEL K124 / LU94A (1411894 / H17WK05)                 | Fuel Filter                                                                                                     | 587861 |

|     |            |        |                                                                                                                                                                                                                                           |        |
|-----|------------|--------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|
| 797 | 08/09/2012 | 367341 | A - Service & Bus Safety Inspection                                                                                                                                                                                                       | 587861 |
| 797 | 07/27/2012 | 365507 | Adjusted both mirror arms cleaned off debris from bodywork                                                                                                                                                                                | 585681 |
| 797 | 07/26/2012 | 365507 |                                                                                                                                                                                                                                           | 585462 |
| 797 | 07/26/2012 | 365507 | Checked over roof & removed branches from a/c pod check under vehicle & removed dirt no mechanical faults evident road tested bus for tracking & braking ok replaced o/s/f mirror arm & refitted mirror                                   | 585462 |
| 797 | 07/19/2012 | 364318 | Checked am/fm radio operation & aerial OK                                                                                                                                                                                                 | 584237 |
| 797 | 07/13/2012 | 360489 | Replaced N/S/R mud flap                                                                                                                                                                                                                   | 583344 |
| 797 | 07/11/2012 | 363286 | Refit isle step edge                                                                                                                                                                                                                      | 582818 |
| 797 | 07/11/2012 | 363285 | Door Service                                                                                                                                                                                                                              | 582818 |
| 797 | 07/11/2012 | 363285 | CCTV Hard Drive Check                                                                                                                                                                                                                     | 582818 |
| 797 | 07/06/2012 | 361192 | Replaced drivers seat shocker                                                                                                                                                                                                             | 582227 |
| 797 | 07/06/2012 | 362490 |                                                                                                                                                                                                                                           | 582227 |
| 797 | 07/06/2012 | 362490 | Repaired accident damage # 35559                                                                                                                                                                                                          | 582227 |
| 797 | 07/06/2012 | 362490 |                                                                                                                                                                                                                                           | 582227 |
| 797 | 07/04/2012 | 361192 | Creditor #:ISR001 ISRINGHAUSEN P/L P/O #:V110219 Receiving #:112631 Date :2012-08-13                                                                                                                                                      | 588283 |
| 797 | 06/28/2012 | 360175 | Creditor #::MIC050 MICHELIN AUSTRALIA PTY LTD P/O #:V109906 Receiving #:110650 Date :2012-06-29                                                                                                                                           | 581155 |
| 797 | 06/28/2012 | 360175 | Creditor #::MIC050 MICHELIN AUSTRALIA PTY LTD P/O #:V109906 Receiving #:110650 Date :2012-06-29                                                                                                                                           | 581155 |
| 797 | 06/27/2012 | 361150 | Adjust Tappets                                                                                                                                                                                                                            | 580828 |
| 797 | 06/27/2012 | 361150 |                                                                                                                                                                                                                                           | 580828 |
| 797 | 06/27/2012 | 361192 | Checked seat top shocker mount bushes worn out order shocker kit                                                                                                                                                                          | 580828 |
| 797 | 06/26/2012 | 361045 | Checked over brakes and pad wiring for low pad light coming on road testedand checked operation ok at this time                                                                                                                           | 580765 |
| 797 | 06/22/2012 | 360490 | Replaced faulty washer pump motor                                                                                                                                                                                                         | 580429 |
| 797 | 06/22/2012 | 360490 |                                                                                                                                                                                                                                           | 580429 |
| 797 | 06/22/2012 | 360155 | Replaced faulty boost pump cleaned filter and tested solinoid road tested heating ok at this time                                                                                                                                         | 580429 |
| 797 | 06/22/2012 | 360492 | Tightened hoses above air filter cleaned heater coolant filter and tested solinoid OK                                                                                                                                                     | 580429 |
| 797 | 06/22/2012 | 360488 | Replaced strut with second hand strut                                                                                                                                                                                                     | 580429 |
| 797 | 06/22/2012 | 360489 | Ordered new mud flap                                                                                                                                                                                                                      | 580429 |
| 797 | 06/22/2012 | 360493 | Secured wiring                                                                                                                                                                                                                            | 580429 |
| 797 | 06/20/2012 | 360175 | Replaced N/S/R/l tyre and valve extension                                                                                                                                                                                                 | 580242 |
| 797 | 06/20/2012 | 360175 |                                                                                                                                                                                                                                           | 580242 |
| 797 | 06/20/2012 | 360155 | Checked all heating componants possibly faulty boost pump heater solenoid working ok (low flow through roof heater cores) further investigation required                                                                                  | 580242 |
| 797 | 06/20/2012 | 360187 | Replaced switch light globes                                                                                                                                                                                                              | 580242 |
| 797 | 06/20/2012 | 360187 |                                                                                                                                                                                                                                           | 580242 |
| 797 | 06/20/2012 | 360186 | Replace fluro tubes                                                                                                                                                                                                                       | 580242 |
| 797 | 06/20/2012 | 360186 |                                                                                                                                                                                                                                           | 580242 |
| 797 | 06/20/2012 | 360161 | A - Service & Bus Safety Inspection                                                                                                                                                                                                       | 580242 |
| 797 | 06/20/2012 | 360161 | Tension ALL Wheel Nuts to OEM Specs                                                                                                                                                                                                       | 580242 |
| 797 | 05/30/2012 | 357064 | Replaced coolant sight glass & bleed hoses from glass back to header tank replaced coolant t-piece run & checked for leaksOK                                                                                                              | 576196 |
| 797 | 05/30/2012 | 357064 |                                                                                                                                                                                                                                           | 576196 |
| 797 | 05/30/2012 | 357064 |                                                                                                                                                                                                                                           | 576196 |
| 797 | 05/30/2012 | 357064 |                                                                                                                                                                                                                                           | 576196 |
| 797 | 05/30/2012 | 357064 |                                                                                                                                                                                                                                           | 576196 |
| 797 | 05/30/2012 | 357064 |                                                                                                                                                                                                                                           | 576196 |
| 797 | 05/30/2012 | 357101 | Replaced 2 new hinge's to drivers door                                                                                                                                                                                                    | 576196 |
| 797 | 05/30/2012 | 357101 |                                                                                                                                                                                                                                           | 576196 |
| 797 | 05/30/2012 | 357101 |                                                                                                                                                                                                                                           | 576196 |
| 797 | 05/24/2012 | 356222 | Traced coolant leak boost pump leaking fitted up new boost pumpchecked operation & for leaks ok                                                                                                                                           | 575097 |
| 797 | 05/24/2012 | 356222 |                                                                                                                                                                                                                                           | 575097 |
| 797 | 05/16/2012 | 354586 | Creditor #::TRA060 TRANSCAL GRAPHICS P/O #:V108250 Receiving #:109329 Date :2012-06-01 Supply and fit decals to bus 797 as per order sheet                                                                                                | 576469 |
| 797 | 05/15/2012 | 354586 | Repaired accident damage # 35201                                                                                                                                                                                                          | 573065 |
| 797 | 05/14/2012 | 354586 |                                                                                                                                                                                                                                           | 573065 |
| 797 | 05/14/2012 | 354586 | Repaired accident damage # 35201                                                                                                                                                                                                          | 573065 |
| 797 | 05/14/2012 | 354586 |                                                                                                                                                                                                                                           | 573065 |
| 797 | 05/14/2012 | 354586 |                                                                                                                                                                                                                                           | 573065 |
| 797 | 05/12/2012 | 354566 | Transmission /check as per Check List                                                                                                                                                                                                     | 573065 |
| 797 | 05/08/2012 | 353809 | Swapped n/s/r tyres                                                                                                                                                                                                                       | 572405 |
| 797 | 05/08/2012 | 353811 | Secured pipe bracket                                                                                                                                                                                                                      | 572405 |
| 797 | 05/08/2012 | 353752 |                                                                                                                                                                                                                                           | 572405 |
| 797 | 05/08/2012 | 353752 | Replaced globes                                                                                                                                                                                                                           | 572405 |
| 797 | 05/08/2012 | 353755 | Replaced fluro tube                                                                                                                                                                                                                       | 572405 |
| 797 | 05/08/2012 | 353755 |                                                                                                                                                                                                                                           | 572405 |
| 797 | 05/08/2012 | 353756 |                                                                                                                                                                                                                                           | 572405 |
| 797 | 05/08/2012 | 353756 | Replaced LED light                                                                                                                                                                                                                        | 572405 |
| 797 | 05/08/2012 | 353761 |                                                                                                                                                                                                                                           | 572405 |
| 797 | 05/08/2012 | 353761 | Replaced globe in dash                                                                                                                                                                                                                    | 572405 |
| 797 | 05/08/2012 | 353762 |                                                                                                                                                                                                                                           | 572405 |
| 797 | 05/08/2012 | 353762 | Replaced hydraulic filter & oil                                                                                                                                                                                                           | 572405 |
| 797 | 05/08/2012 | 353808 | Mudflap ok for now                                                                                                                                                                                                                        | 572405 |
| 797 | 05/08/2012 | 353877 | Replaced seal in two way check valve                                                                                                                                                                                                      | 572405 |
| 797 | 05/07/2012 | 353606 |                                                                                                                                                                                                                                           | 572162 |
| 797 | 05/07/2012 | 353606 | Service as per check list                                                                                                                                                                                                                 | 572162 |
| 797 | 05/07/2012 | 353606 | diff oil                                                                                                                                                                                                                                  | 572162 |
| 797 | 05/07/2012 | 353606 | Raycor filter                                                                                                                                                                                                                             | 572162 |
| 797 | 05/07/2012 | 353606 | Hydraulic oil                                                                                                                                                                                                                             | 572162 |
| 797 | 05/07/2012 | 353606 | Power steering filter                                                                                                                                                                                                                     | 572162 |
| 797 | 05/07/2012 | 353606 | Hydraulic filter                                                                                                                                                                                                                          | 572162 |
| 797 | 05/07/2012 | 353606 | QAM checkover and road tested                                                                                                                                                                                                             | 572162 |
| 797 | 05/07/2012 | 353606 | A - Service & Bus Safety Inspection                                                                                                                                                                                                       | 572162 |
| 797 | 05/07/2012 | 353606 | Tension ALL Wheel Nuts to OEM Specs                                                                                                                                                                                                       | 572162 |
| 797 | 05/03/2012 | 353232 | Door Service                                                                                                                                                                                                                              | 571642 |
| 797 | 05/03/2012 | 353232 | CCTV Hard Drive Check                                                                                                                                                                                                                     | 571642 |
| 797 | 05/02/2012 | 352977 | Checked all light operation ok at this time                                                                                                                                                                                               | 571479 |
| 797 | 05/02/2012 | 352978 | Checked starting intermintant delay in starting from the time the key isturned to the start position checked ignition switch ok checked starter motor ok swapped starter interlock relay with reverse light relay working OK at this time | 571479 |
| 797 | 04/30/2012 | 352453 | Cleaned low coolant probe topped up coolant & road tested                                                                                                                                                                                 | 570945 |
| 797 | 04/20/2012 | 350499 | Creditor #::ROA001 Road Safety Inspections P/O #:V106699 Receiving #:107651 Date :2012-04-27 Bus 797                                                                                                                                      | 570713 |
| 797 | 04/19/2012 | 350558 | Welded up seat frame and refitted to bus                                                                                                                                                                                                  | 569161 |
| 797 | 04/18/2012 | 350956 |                                                                                                                                                                                                                                           | 569161 |
| 797 | 04/18/2012 | 350956 | Replaced bush                                                                                                                                                                                                                             | 569161 |
| 797 | 04/18/2012 | 350964 | Replaced bearing                                                                                                                                                                                                                          | 569161 |
| 797 | 04/18/2012 | 350964 |                                                                                                                                                                                                                                           | 569161 |
| 797 | 04/18/2012 | 350558 | Started removing seat frame                                                                                                                                                                                                               | 569161 |
| 797 | 04/15/2012 | 350499 | RSI Inspection (RWC 284069)                                                                                                                                                                                                               | 568864 |
| 797 | 04/12/2012 | 350151 | A - Service & Bus Safety Inspection                                                                                                                                                                                                       | 568647 |
| 797 | 04/12/2012 | 350151 | Tension ALL Wheel Nuts to OEM Specs                                                                                                                                                                                                       | 568647 |
| 797 | 04/12/2012 | 350151 | Engine Oil                                                                                                                                                                                                                                | 568647 |
| 797 | 04/12/2012 | 350151 | Fuel Filter                                                                                                                                                                                                                               | 568647 |
| 797 | 04/12/2012 | 350151 | Filter ZF Trans                                                                                                                                                                                                                           | 568647 |

|     |            |        |                                                             |                                                                                                                         |        |
|-----|------------|--------|-------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------|--------|
| 797 | 04/12/2012 | 350151 | Hydraulic Oil Torque Fluid 414                              | Torque fluid                                                                                                            | 568647 |
| 797 | 04/12/2012 | 350151 | FILTER OIL K124 / L94UAB (H200W02)                          | Filter Oil                                                                                                              | 568647 |
| 797 | 04/12/2012 | 350151 | O RING FILTER KIT K93                                       | Kit . filter Cent                                                                                                       | 568647 |
| 797 | 04/12/2012 | 350151 |                                                             | A - Service & Bus Safety Inspection                                                                                     | 568647 |
| 797 | 04/12/2012 | 350151 |                                                             | A - Service & Bus Safety Inspection                                                                                     | 568647 |
| 797 | 04/03/2012 | 349219 | Accident Damaged NSR side light ripped off                  | Rewired and fitted new side light                                                                                       | 567066 |
| 797 | 04/03/2012 | 349219 | L.E.D SIDE MARKER RED/AMBER                                 |                                                                                                                         | 567066 |
| 797 | 03/27/2012 | 348160 | Front brake pads need replacing                             | Replaced front brake pads & road tested                                                                                 | 565927 |
| 797 | 03/27/2012 | 348160 | DISC PAD SET SCANIA MB0500                                  |                                                                                                                         | 565927 |
| 797 | 03/27/2012 | 348170 | Rear brake pads & rotors need replacing                     | Checked and have been replaced on the 15 March 2012                                                                     | 565927 |
| 797 | 03/24/2012 | 347725 | Dash main beam warning light not working.                   | Removed dash tightened globe connections & refit globe                                                                  | 565189 |
| 797 | 03/22/2012 | 347344 | Not starting from front                                     | Checked starting checked hatch switch operation no fault found at this time                                             | 564968 |
| 797 | 03/19/2012 | 346694 | V bar bush worn                                             | Checked V bar bush still ok for service                                                                                 | 564096 |
| 797 | 03/19/2012 | 346704 | Front track rod bushes worn                                 | Checked bushes worn but still ok for service                                                                            | 564096 |
| 797 | 03/19/2012 | 346695 | Saloon light lenses damaged & some fitted incorrectly       | Replaced light covers                                                                                                   | 564096 |
| 797 | 03/19/2012 | 346696 | FLURO TUBE 18W                                              |                                                                                                                         | 564096 |
| 797 | 03/19/2012 | 346696 | Rear external door light N/W                                | Replaced light fluoro tube                                                                                              | 564096 |
| 797 | 03/19/2012 | 346699 | Some dash lights N/W                                        | Replaced globe                                                                                                          | 564096 |
| 797 | 03/19/2012 | 346699 | GLOBE+HOLDER INSTRUMENT (GREY)                              |                                                                                                                         | 564096 |
| 797 | 03/19/2012 | 346700 | Saloon lights N/W                                           | Replaced fluoro light tube                                                                                              | 564096 |
| 797 | 03/19/2012 | 346700 | FLURO TUBE 18W                                              |                                                                                                                         | 564096 |
| 797 | 03/19/2012 | 346698 | Saloon light lenses damaged & some fitted incorrectly       | Replaced light covers                                                                                                   | 564096 |
| 797 | 03/19/2012 | 346698 | ELLAMP LIGHT COVER 3MT                                      |                                                                                                                         | 564096 |
| 797 | 03/19/2012 | 346701 | Several screws loose or missing for hand rail in roof       | Tightened loose screws and fitted up missing screw                                                                      | 564096 |
| 797 | 03/19/2012 | 346702 | Brake pad warning light coming ON intermittantly            | Traced fault replaced faulty o/s/f low pad loom road tested ok                                                          | 564096 |
| 797 | 03/17/2012 | 346606 |                                                             | Tension ALL Wheel Nuts to OEM Specs                                                                                     | 564096 |
| 797 | 03/17/2012 | 346606 |                                                             | A - Service & Bus Safety Inspection                                                                                     | 564096 |
| 797 | 03/16/2012 | 346354 | Brake linnings warning light on in dash                     | Replaced rear brake rotors pads & rear calipers                                                                         | 564096 |
| 797 | 03/16/2012 | 346354 | RATIONALISED CALIPER                                        | Creditor #::MUL001 MULTISPARES LTD P/O #::V105634 Receiving #::106090 Date :2012-03-16                                  | 564096 |
| 797 | 03/16/2012 | 346354 | RATIONALISED CALIPER                                        | Creditor #::MUL001 MULTISPARES LTD P/O #::V105634 Receiving #::106090 Date :2012-03-16                                  | 564096 |
| 797 | 03/15/2012 | 346354 | Brake linnings warning light on in dash                     | Replaced N/S/R brake rotor                                                                                              | 564096 |
| 797 | 03/15/2012 | 346354 | WEAR SENSOR SCANIA DISC BRAKE                               |                                                                                                                         | 564096 |
| 797 | 03/15/2012 | 346354 | FRONT DISC BRAKE ROTORS SCANIA(40F3319)                     |                                                                                                                         | 564096 |
| 797 | 03/15/2012 | 346354 | DISC PAD SET SCANIA MB0500                                  |                                                                                                                         | 564096 |
| 797 | 03/15/2012 | 346354 | Brake linnings warning light on in dash                     | Assisted with removing rear pads                                                                                        | 564096 |
| 797 | 03/09/2012 | 345043 | Not starting from ignition key                              | Replaced rear start switch & tested OK                                                                                  | 563496 |
| 797 | 03/07/2012 | 340212 | RECIEVER/DRYER A/C CAPRI 280 & GR60                         |                                                                                                                         | 563093 |
| 797 | 03/07/2012 | 345210 | Door OK light N/W                                           | Replaced door ok light globe                                                                                            | 563093 |
| 797 | 03/07/2012 | 345210 | GLOBE WEDGE 24V 1.2W                                        |                                                                                                                         | 563093 |
| 797 | 03/07/2012 | 345043 | SWITCH START REAR ELECTRICAL                                | Creditor #::SCA001 SCANIA AUSTRALIA PTY LTD P/O #::V105221 Receiving #::105999 Date :2012-03-14                         | 563807 |
| 797 | 03/07/2012 | 345212 | No red reflectors fitted to rear of bus                     | Replaced red reflectors                                                                                                 | 563093 |
| 797 | 03/07/2012 | 345212 | RED REFLECTOR NARVA 90x40mm                                 |                                                                                                                         | 563093 |
| 797 | 03/07/2012 | 345217 | Hand rail screws missing from roof                          | Replaced missing screws                                                                                                 | 563093 |
| 797 | 03/06/2012 | 345042 |                                                             | Inspect vehicle as per RSI Checklist                                                                                    | 563093 |
| 797 | 03/06/2012 | 345043 | Not starting from ignition key                              | Traced start circuit fault Ordered rear start switch                                                                    | 563093 |
| 797 | 02/24/2012 | 343498 | Interior light cover fallen off.                            | Fitted new light defuser                                                                                                | 560814 |
| 797 | 02/17/2012 | 340212 | A/C compressor leaking requires wash & check?               | Vaccumed down a/c system checked for leaks charged with gas (7.5kg R134a) tested a/c operation ok                       | 559039 |
| 797 | 02/17/2012 | 340212 | AIR CON REFRIDGERANT                                        |                                                                                                                         | 559039 |
| 797 | 02/17/2012 | 340212 | RECEIVER DRYER CARRIER CLASS                                | Creditor #::TRA061 TRANSIT REFRIGERATION & AIR CONDITIONING SERVICE P/O #::V104409 Receiving #::105102 Date :2012-02-20 | 559622 |
| 797 | 02/16/2012 | 340212 | A/C compressor leaking requires wash & check?               | Recovered gas replaced leaking shaft seal fitted brass hand tap covers reciver/ dryer needs replacing                   | 559039 |
| 797 | 02/16/2012 | 340212 | REFRIDGERANT OIL CARRIER R134a COMPATIBLE                   |                                                                                                                         | 559039 |
| 797 | 02/16/2012 | 340212 | CAP SERVICE VALVE O5G                                       |                                                                                                                         | 559039 |
| 797 | 02/13/2012 | 341643 | Accident Damaged # 34619 Repair n/s/ff. corner panels Polis | Repaired accident damage # 34619                                                                                        | 558366 |
| 797 | 02/13/2012 | 341512 |                                                             | Door Service                                                                                                            | 558366 |
| 797 | 02/13/2012 | 341512 |                                                             | CCTV Hard Drive Check                                                                                                   | 558366 |
| 797 | 02/08/2012 | 340212 | SEAL SHAFT O5G A/C COMPRESSOR                               | Creditor #::TRA061 TRANSIT REFRIGERATION & AIR CONDITIONING SERVICE P/O #::V103817 Receiving #::104754 Date :2012-02-10 | 558667 |
| 797 | 02/08/2012 | 340212 | RECIEVER/DRYER A/C CAPRI 280                                | Creditor #::TRA061 TRANSIT REFRIGERATION & AIR CONDITIONING SERVICE P/O #::V103817 Receiving #::104754 Date :2012-02-10 | 558667 |
| 797 | 02/08/2012 | 340212 | REFRIDGERANT OIL CARRIER R134                               | Creditor #::TRA061 TRANSIT REFRIGERATION & AIR CONDITIONING SERVICE P/O #::V103817 Receiving #::104754 Date :2012-02-10 | 558667 |
| 797 | 02/08/2012 | 340877 | Drv entered - Body & Acc Mirrors Exterior                   | Checked all mirrors no fault found                                                                                      | 557836 |
| 797 | 02/03/2012 | 340212 | A/C compressor leaking requires wash & check?               | Checked for leaks leaking shaft seal order parts                                                                        | 557278 |
| 797 | 02/03/2012 | 340202 | BELT POLY                                                   |                                                                                                                         | 557278 |
| 797 | 02/03/2012 | 340202 | Engine drive belt needs replacing                           | Replaced belt                                                                                                           | 557278 |
| 797 | 02/03/2012 | 340201 | Door OK & door alarm light N/W                              | Replaced globe                                                                                                          | 557278 |
| 797 | 02/03/2012 | 340201 | GLOBE WEDGE 24V 1.2W                                        |                                                                                                                         | 557278 |
| 797 | 02/03/2012 | 340205 | N/S side light needs securing                               | Secured light into base with sikaflex                                                                                   | 557278 |
| 797 | 02/03/2012 | 340209 | O/S number plate light needs securing                       | Fitted new nut to o/s number plate light base                                                                           | 557278 |
| 797 | 02/02/2012 | 340076 | Drv entered - Wipers & Washers Washers Not Working          | Refitted washer hose to wiper arm                                                                                       | 556937 |
| 797 | 02/02/2012 | 340076 | Drv entered - Wipers & Washers Not Cleaning Screen          | Filled water bottle & bleed motor                                                                                       | 556937 |
| 797 | 02/02/2012 | 340011 |                                                             | Tension ALL Wheel Nuts to OEM Specs                                                                                     | 556937 |
| 797 | 02/02/2012 | 340011 |                                                             | A - Service & Bus Safety Inspection                                                                                     | 556937 |
| 797 | 02/02/2012 | 340011 |                                                             | A - Service & Bus Safety Inspection                                                                                     | 556937 |
| 797 | 01/19/2012 | 338157 | Drv entered - Air Conditioning duct above rear door falling | Repaired panel and secured in place                                                                                     | 553955 |
| 797 | 01/14/2012 | 337399 | Drv entered - Vandalism Graffiti                            | Removed graffiti off passenger seats & floor                                                                            | 552633 |
| 797 | 01/12/2012 | 337131 | Drv entered - Body & Acc Security Door                      | Checked drivers door no fault found at this time                                                                        | 552633 |
| 797 | 01/05/2012 | 335986 | Driver reported lights and doors would not operate          | Traced fault with Thoreb master relay and repaired faulty connection behind P2 board                                    | 551550 |
| 797 | 01/05/2012 | 335986 | Service                                                     | Assisted tracing thoreb electrical fault                                                                                | 551550 |
| 797 | 01/03/2012 | 335630 | Drv entered - Throttle Other                                | Checked & road tested throttle operation ok could not fault                                                             | 550639 |
| 797 | 01/03/2012 | 335704 | Doors stop operating with no warning. (Thoreb master relay  | Checked wirnig and relays. Unable to fault at this time                                                                 | 550639 |
| 797 | 12/21/2011 | 334495 | Drv entered - Ticket Equip VAL                              | Checked ticket equipment could not fault at this time secure                                                            | 549633 |
| 797 | 12/21/2011 | 334494 | Drv entered - Elec & Light Indicators                       | Checked indicator operation could not fault at this time                                                                | 549633 |
| 797 | 12/15/2011 | 333800 | N/S/R/O tyre sidewall damaged                               | Checked side wall OK at this time                                                                                       | 548545 |
| 797 | 12/15/2011 | 329937 | Drv entered - Comm Equip Aerial - No Am/Fm aerial.          | Repaced aerial for AM/FM radio                                                                                          | 548545 |
| 797 | 12/14/2011 | 333655 | GLOBE WEDGE 24V 1.2W                                        |                                                                                                                         | 548518 |
| 797 | 12/14/2011 | 333655 | Switch lights N/W                                           | Replaced globe                                                                                                          | 548518 |
| 797 | 12/14/2011 | 333610 | O RING FILTER KIT K93                                       | Kit . filter Cent                                                                                                       | 548518 |
| 797 | 12/14/2011 | 333610 | FILTER OIL K124 / L94UAB (H200W02)                          | Filter Oil                                                                                                              | 548518 |
| 797 | 12/14/2011 | 333610 | Hydraulic Oil Torque Fluid 414                              | Torque fluid                                                                                                            | 548518 |
| 797 | 12/14/2011 | 333610 | FILTER TRANSMISSION ZF 4139-298-038E39HD119                 | Filter ZF Trans                                                                                                         | 548518 |
| 797 | 12/14/2011 | 333610 | FILTER FUEL K124 / LU94A (1411894 / H17WK05)                | Fuel Filter                                                                                                             | 548518 |
| 797 | 12/14/2011 | 333610 | ENGINE OIL DELO 400LE 15W40                                 | Engine Oil                                                                                                              | 548518 |
| 797 | 12/14/2011 | 333610 |                                                             | A - Service & Bus Safety Inspection                                                                                     | 548518 |
| 797 | 12/14/2011 | 333610 |                                                             | Tension ALL Wheel Nuts to OEM Specs                                                                                     | 548518 |
| 797 | 12/14/2011 | 333610 |                                                             | A - Service & Bus Safety Inspection                                                                                     | 548518 |

|     |            |        |                                                             |                                                                                                                                                                 |        |
|-----|------------|--------|-------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|
| 797 | 12/12/2011 | 329937 | Direct Purchase - ELECTRICAL                                | Creditor # :VOL001 VOLGREN AUSTRALIA P/L P/O # :V101525 Receiving # :102477 Date :2011-12-12 PLEASE SUPPLY BOSCH TYPE AERIAL - BODY NO. VG1878                  | 548270 |
| 797 | 11/30/2011 | 329937 | Drv entered - Comm Equip Aerial - No Am/Fm aerial.          | Checked am/fm radio aerial u/s ordered bosch type                                                                                                               | 545611 |
| 797 | 11/25/2011 | 330888 | Rear saloon light lens U/S                                  | Replaced fluoro tube defuser                                                                                                                                    | 544452 |
| 797 | 11/25/2011 | 330888 | ELLAMP LIGHT COVER 3MT                                      |                                                                                                                                                                 | 544452 |
| 797 | 11/25/2011 | 330887 | FLURO TUBE 18W                                              |                                                                                                                                                                 | 544452 |
| 797 | 11/25/2011 | 330887 | Saloon light fluoro N/W                                     | Replaced fluoro tubes                                                                                                                                           | 544452 |
| 797 | 11/25/2011 | 330886 | Switch lights N/W                                           | Replaced globes                                                                                                                                                 | 544452 |
| 797 | 11/25/2011 | 330886 | GLOBE WEDGE 24V 1.2W                                        |                                                                                                                                                                 | 544452 |
| 797 | 11/25/2011 | 330898 |                                                             | CCTV Hard Drive Check                                                                                                                                           | 544452 |
| 797 | 11/25/2011 | 330898 |                                                             | Door Service                                                                                                                                                    | 544452 |
| 797 | 11/24/2011 | 330699 |                                                             | Tension ALL Wheel Nuts to OEM Specs                                                                                                                             | 544452 |
| 797 | 11/24/2011 | 330699 |                                                             | A - Service & Bus Safety Inspection                                                                                                                             | 544452 |
| 797 | 11/22/2011 | 330399 | Engine warning light staying ON                             | Checked for engine light ON no light on removed code 15 & road testedno light ON                                                                                | 544353 |
| 797 | 11/19/2011 | 330062 |                                                             | Transmission /check as per Check List                                                                                                                           | 543986 |
| 797 | 11/18/2011 | 329937 | Drv entered - Comm Equip Aerial - No Am/Fm aerial.          | Checked type of aerial & ordered                                                                                                                                | 543840 |
| 797 | 11/18/2011 | 329938 | Drv entered - Body & Acc Windows bulls eye in windscreen in | Fitted temporary windscreen repair stickers to bulls eye                                                                                                        | 543840 |
| 797 | 11/03/2011 | 327363 | GLOBE 24V 2W BA29                                           |                                                                                                                                                                 | 540541 |
| 797 | 11/03/2011 | 327363 | Drv entered - Elec & Light Park Lights                      | Replaced n/side park light globe                                                                                                                                | 540541 |
| 797 | 11/02/2011 | 327350 | GLOBE H1 24V 70W                                            |                                                                                                                                                                 | 540541 |
| 797 | 11/02/2011 | 327350 | Drv entered - Elec & Light Headlights                       | Fitted new globe to N/S low beam                                                                                                                                | 540541 |
| 797 | 11/02/2011 | 327137 | L.E.D.STOP+TAIL LIGHT                                       |                                                                                                                                                                 | 540541 |
| 797 | 11/02/2011 | 327137 | Drv entered - Elec & Light Stop lights                      | Replaced o/side upper park light                                                                                                                                | 540541 |
| 797 | 10/17/2011 | 324987 | Drv entered - Elec & Light Park Lights                      | Replaced o/s park light globe                                                                                                                                   | 537284 |
| 797 | 10/17/2011 | 324987 | GLOBE 24V 5W BAYONETT                                       |                                                                                                                                                                 | 537284 |
| 797 | 10/13/2011 | 324479 | Graffiti on passenger seats                                 | Removed graffiti from seats & trim                                                                                                                              | 536832 |
| 797 | 10/13/2011 | 324484 | Front door rear leaf upper pivot loose                      | Tightened front door pivot screws                                                                                                                               | 536832 |
| 797 | 10/13/2011 | 324293 | GLOBE 24V 5W BAYONETT                                       |                                                                                                                                                                 | 536832 |
| 797 | 10/13/2011 | 324293 | Globe N/W in bus stopping sign                              | Replaced globe                                                                                                                                                  | 536832 |
| 797 | 10/13/2011 | 324294 | Switch lights N/W                                           | Replaced globes                                                                                                                                                 | 536832 |
| 797 | 10/13/2011 | 324294 | GLOBE WEDGE 24V 1.2W                                        |                                                                                                                                                                 | 536832 |
| 797 | 10/13/2011 | 324481 | Front door external light N/W                               | Replaced fluoro globe                                                                                                                                           | 536832 |
| 797 | 10/13/2011 | 324481 | FLURO TUBE 18W                                              |                                                                                                                                                                 | 536832 |
| 797 | 10/13/2011 | 324482 | Corrosion on battery terminals                              | Cleaned terminals inspected & lubed                                                                                                                             | 536832 |
| 797 | 10/13/2011 | 324485 | REFLECTOR ORANGE                                            |                                                                                                                                                                 | 536832 |
| 797 | 10/13/2011 | 324485 | N/S body panel reflector missing                            | Fitted reflector                                                                                                                                                | 536832 |
| 797 | 10/12/2011 | 324154 | Service                                                     | A - Service & Bus Safety Inspection                                                                                                                             | 536832 |
| 797 | 10/12/2011 | 324154 |                                                             | Tension ALL Wheel Nuts to OEM Specs                                                                                                                             | 536832 |
| 797 | 10/12/2011 | 324154 |                                                             | A - Service & Bus Safety Inspection                                                                                                                             | 536832 |
| 797 | 10/06/2011 | 323397 | Drv entered - Wipers & Washers Wipers Not Working           | Refitted o/s wiper arm pivot                                                                                                                                    | 535888 |
| 797 | 10/03/2011 | 311932 | Two way radio turns OFF when using volume control without   | Fitted original 2 way checked operation OK                                                                                                                      | 523900 |
| 797 | 09/28/2011 | 322020 | DOWNLIGHT 24V 20W                                           |                                                                                                                                                                 | 534760 |
| 797 | 09/28/2011 | 322020 | Drivers overhead light U/S                                  | Replaced faulty drivers light globe and wiring                                                                                                                  | 534760 |
| 797 | 09/26/2011 | 311932 | REPAIR RADIO AS REQUIRED                                    | Creditor # :REB001 CIM CONCEPTS P/O # :V98293 Receiving # :99244 Date :2011-09-28 Two way turns off when volume is adjusted                                     | 534760 |
| 797 | 09/19/2011 | 320519 | FLURO TUBE 18W                                              |                                                                                                                                                                 | 532983 |
| 797 | 09/19/2011 | 320519 | Drv entered - Elec & Light Cab Light                        | Replaced step light                                                                                                                                             | 532983 |
| 797 | 09/14/2011 | 319837 | Drv entered - Elec & Light Park Lights                      | Replaced N/S/F side marker light surround                                                                                                                       | 532005 |
| 797 | 09/12/2011 | 319221 | Drv entered - Engine Wont Start                             | Checked over starting system electrical curcuit could not fault                                                                                                 | 531502 |
| 797 | 09/12/2011 | 319220 | Drv entered - Brakes ABS On                                 | Checked fault codes (85 inactive) cleared codes                                                                                                                 | 531502 |
| 797 | 09/07/2011 | 318561 |                                                             | Door Service                                                                                                                                                    | 530921 |
| 797 | 09/07/2011 | 318561 |                                                             | CCTV Hard Drive Check                                                                                                                                           | 530921 |
| 797 | 08/29/2011 | 313476 | STRUT                                                       | Creditor # :UNI001 UNIVERSAL ENG. SUPPLIES P/L P/O # :V96429 Receiving # :98373 Date :2011-09-07                                                                | 531006 |
| 797 | 08/26/2011 | 316620 | Engine flap keeps falling open                              | Fitted new engine hatch strut                                                                                                                                   | 529150 |
| 797 | 08/25/2011 | 316275 | Front and rear door rollers loose                           | Tightened door rollers                                                                                                                                          | 528966 |
| 797 | 08/25/2011 | 316252 | GLOBE WEDGE 24V 1.2W                                        |                                                                                                                                                                 | 528966 |
| 797 | 08/25/2011 | 316252 | Switch lights not working                                   | Replaced switch light globes                                                                                                                                    | 528966 |
| 797 | 08/25/2011 | 316276 | Perimeter seat hinge pins need refitting and screws missing | Fitted new screw in upright pole reseated seat hinge pins                                                                                                       | 528966 |
| 797 | 08/24/2011 | 315970 | FILTER TRANSMISSION ZF 4139-298-038E39HD119                 | Filter ZF Trans                                                                                                                                                 | 528864 |
| 797 | 08/24/2011 | 315970 | FILTER AIR SCANIA USE AF25066                               |                                                                                                                                                                 | 528864 |
| 797 | 08/24/2011 | 315970 | Hydraulic Oil Torque Fluid 414                              | Torque fluid                                                                                                                                                    | 528864 |
| 797 | 08/24/2011 | 315970 | FILTER FUEL K124 / LU94A (1411894 / H17WK05)                | Fuel Filter                                                                                                                                                     | 528864 |
| 797 | 08/24/2011 | 315970 | ENGINE OIL DELO 400LE 15W40                                 | Engine Oil                                                                                                                                                      | 528864 |
| 797 | 08/24/2011 | 315970 |                                                             | A - Service & Bus Safety Inspection                                                                                                                             | 528864 |
| 797 | 08/24/2011 | 315970 | O RING FILTER KIT K93                                       | Kit . filter Cent                                                                                                                                               | 528864 |
| 797 | 08/24/2011 | 315970 | FILTER OIL K124 / L94UAB (H200W02)                          | Filter Oil                                                                                                                                                      | 528864 |
| 797 | 08/24/2011 | 315970 |                                                             | Tension ALL Wheel Nuts to OEM Specs                                                                                                                             | 528864 |
| 797 | 08/24/2011 | 315970 | Service                                                     | A - Service & Bus Safety Inspection                                                                                                                             | 528864 |
| 797 | 08/23/2011 | 315852 | High beam not very high                                     | Adjusted headlights                                                                                                                                             | 528772 |
| 797 | 08/23/2011 | 315850 | High beam lights are pointing at the ground need adjustment | Adjusted o/s low beam and and both high beams                                                                                                                   | 528772 |
| 797 | 08/23/2011 | 315848 | Speedo illumination not working                             | replaced globe                                                                                                                                                  | 528772 |
| 797 | 08/23/2011 | 315844 | GLOBE+HOLDER INSTRUMENT (GREY)                              |                                                                                                                                                                 | 528772 |
| 797 | 08/23/2011 | 315844 | Dash light behind speedo not working                        | replaced globe                                                                                                                                                  | 528772 |
| 797 | 08/19/2011 | 314139 | SEAT BELT BUCKLE NTS                                        |                                                                                                                                                                 | 527686 |
| 797 | 08/19/2011 | 314139 | Drivers seat belt clip missing cover                        | Fitted new seat belt clip                                                                                                                                       | 527686 |
| 797 | 08/12/2011 | 314154 | Washers N/W                                                 | Un-block jets tubes & check valve working OK                                                                                                                    | 526709 |
| 797 | 08/12/2011 | 314156 | N/S/R saloon light N/W                                      | Fitted new 4' fluoro tube                                                                                                                                       | 526709 |
| 797 | 08/12/2011 | 314166 | O/S/R saloon light cover U/S                                | Make up lens from several S/H pieces                                                                                                                            | 526709 |
| 797 | 08/12/2011 | 314142 | Switch lights N/W                                           | Fitted 3 new globes                                                                                                                                             | 526709 |
| 797 | 08/12/2011 | 314142 | GLOBE WEDGE 24V 1.2W                                        |                                                                                                                                                                 | 526709 |
| 797 | 08/12/2011 | 314156 | FLURO TUBE 18W                                              |                                                                                                                                                                 | 526709 |
| 797 | 08/12/2011 | 314139 | Drivers seat belt clip missing cover                        | Remove buckle to match Order parts & re-fit.                                                                                                                    | 526709 |
| 797 | 08/12/2011 | 314168 | Drv entered - Body & Acc Exterior                           | Check all out side lights OK                                                                                                                                    | 526709 |
| 797 | 08/11/2011 | 313476 | STRUT                                                       | Creditor # :UNI001 UNIVERSAL ENG. SUPPLIES P/L P/O # :V96429 Receiving # :97560 Date :2011-08-17                                                                | 527430 |
| 797 | 08/11/2011 | 313797 |                                                             | A - Service & Bus Safety Inspection                                                                                                                             | 526600 |
| 797 | 08/11/2011 | 313797 |                                                             | Tension ALL Wheel Nuts to OEM Specs                                                                                                                             | 526600 |
| 797 | 08/09/2011 | 313477 | AIR CON REFRIDGERANT                                        |                                                                                                                                                                 | 524232 |
| 797 | 08/09/2011 | 313477 | A/C service & coil clean                                    | Carried out a/c service and coil clean replaced return air filter materialsystem vacumed down from previous repair gassed system (5kg R134a)system operating ok | 524232 |
| 797 | 08/09/2011 | 313476 | The bus would not start from the front have to start from b | Checked starting cleaned and lubricated hatch switch refitted hatch hinge pin starting ok                                                                       | 524232 |
| 797 | 07/30/2011 | 312060 | Broom missing                                               | Fitted S/H broom                                                                                                                                                | 524232 |
| 797 | 07/29/2011 | 311932 | Two way radio turns OFF when using volume control without   | Checked 2 way operation faulty fitted spare unit & send away original forrepair                                                                                 | 523900 |
| 797 | 07/20/2011 | 310345 | N/S/F park light N/W                                        | Replaced N/S/F park light globe                                                                                                                                 | 522090 |
| 797 | 07/20/2011 | 310345 | GLOBE WEDGE 24V 1.2W                                        |                                                                                                                                                                 | 522090 |
| 797 | 07/01/2011 | 307835 | GLOBE 24V 21W SINGLE CONTACT                                |                                                                                                                                                                 | 518604 |
| 797 | 07/01/2011 | 307835 | Drv entered - Elec & Light Other                            | Replaced N/S/F/T park light globe                                                                                                                               | 518604 |

|     |            |        |                                                            |                                                                                                                                     |        |
|-----|------------|--------|------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------|--------|
| 797 | 07/01/2011 | 365507 | Direct Purchase - BODYWORK                                 | Creditor #:ELI001 ELITE WINDSCREENS P/O #:V111543 Receiving #:111964 Date :2012-07-27 Supply and fit desto glass to bus 797         | 585681 |
| 797 | 06/29/2011 | 307341 | Graffiti on rear seats                                     | clean graffiti                                                                                                                      | 517965 |
| 797 | 06/29/2011 | 307332 | O/S/F park light N/W                                       | Replaced globe                                                                                                                      | 517965 |
| 797 | 06/29/2011 | 307332 | GLOBE 24V SW BAYONETT                                      |                                                                                                                                     | 517965 |
| 797 | 06/29/2011 | 307334 | O/S/F park light N/W                                       | replace globe                                                                                                                       | 517965 |
| 797 | 06/29/2011 | 307334 | GLOBE 24V 2W BA29                                          |                                                                                                                                     | 517965 |
| 797 | 06/29/2011 | 307335 | Switch lights N/W                                          | replaced switch globes                                                                                                              | 517965 |
| 797 | 06/29/2011 | 307335 | GLOBE WEDGE 24V 1.2W                                       |                                                                                                                                     | 517965 |
| 797 | 06/29/2011 | 307342 | N/S mirror stem/arm loose                                  | Secured N/S mirror arm                                                                                                              | 517965 |
| 797 | 06/28/2011 | 303160 | CUSHION ASSEMBLY ISRI 6860 TR                              | Creditor #:ISR001 ISRINGHAUSEN P/L P/O #:V93664 Receiving #:95551 Date :2011-06-30                                                  | 518604 |
| 797 | 06/28/2011 | 303160 | CONSUMABLE DELIVERY CHARGE                                 | Creditor #:ISR001 ISRINGHAUSEN P/L P/O #:V93664 Receiving #:95551 Date :2011-06-30                                                  | 518604 |
| 797 | 06/28/2011 | 307120 |                                                            | Tension ALL Wheel Nuts to OEM Specs                                                                                                 | 517754 |
| 797 | 06/28/2011 | 307120 |                                                            | A - Service & Bus Safety Inspection                                                                                                 | 517754 |
| 797 | 06/28/2011 | 307120 | Service                                                    | A - Service & Bus Safety Inspection                                                                                                 | 517754 |
| 797 | 06/24/2011 | 306718 |                                                            | CCTV Hard Drive Check Checked as per list                                                                                           | 517044 |
| 797 | 06/24/2011 | 306718 |                                                            | Door Service                                                                                                                        | 517044 |
| 797 | 06/24/2011 | 306718 |                                                            | Door Service                                                                                                                        | 517044 |
| 797 | 06/15/2011 | 305187 |                                                            | Transmission /check as per Check List                                                                                               | 515657 |
| 797 | 06/14/2011 | 304936 | 2 NS Windows smashed                                       | Smashed windows replaced by Elite                                                                                                   | 515391 |
| 797 | 06/14/2011 | 304936 | Direct Purchase - BODYWORK                                 | Creditor #:ELI001 ELITE WINDSCREENS P/O #:V93771 Receiving #:94720 Date :2011-06-14 2 Side windows for bus 797                      | 515391 |
| 797 | 06/10/2011 | 304705 | N/S/R side windows smashed                                 | Take bus to Elite windcreens and return to depot                                                                                    | 515391 |
| 797 | 06/04/2011 | 292027 | Direct Purchase - BODYWORK                                 | Creditor #:TRA060 TRANSCAL GRAPHICS P/O #:V91326 Receiving #:95657 Date :2011-07-01 Please supply and fit decals as per order sheet | 518604 |
| 797 | 06/04/2011 | 297805 | Direct Purchase - BODYWORK                                 | Creditor #:TRA060 TRANSCAL GRAPHICS P/O #:V91328 Receiving #:95658 Date :2011-07-01 Please supply and fit decals as per order sheet | 518604 |
| 797 | 06/01/2011 | 303160 | Drivers seat knock too hard driving long time hurt back    | Replaced drivers seat base                                                                                                          | 513601 |
| 797 | 05/30/2011 | 303160 | Drivers seat knock too hard driving long time hurt back    | Checked drivers seat not adjusted correctly seat base cushion needsreplacing                                                        | 512835 |
| 797 | 05/26/2011 | 301916 | 295/80R22.5 RECAMIC DRIVE PATT                             | Creditor #:MIC050 MICHELIN AUSTRALIA PTY LTD P/O #:V92799 Receiving #:93890 Date :2011-05-27                                        | 512835 |
| 797 | 05/26/2011 | 301916 | FITTING                                                    | Creditor #:MIC050 MICHELIN AUSTRALIA PTY LTD P/O #:V92799 Receiving #:93890 Date :2011-05-27                                        | 512835 |
| 797 | 05/24/2011 | 301916 | N/S/R tyres need to be replaced SMART BUS tyres fitted at  | Replaced N/S/R tyres using urban tread pattern                                                                                      | 512178 |
| 797 | 05/24/2011 | 301916 | Rubbish bin hinge broken                                   | Removed broken rubbish bin                                                                                                          | 512178 |
| 797 | 05/17/2011 | 300845 | N/S/R tyre flat                                            | Replaced N/S/R tyres using SMART BUS WHEELS as temporary tyres                                                                      | 510266 |
| 797 | 05/13/2011 | 299626 | ROAD SAFETY INSPECTIONS                                    | Creditor #:ROA001 Road Safety Inspections P/O #:V92353 Receiving #:93278 Date :2011-05-13 bus 797                                   | 510219 |
| 797 | 05/12/2011 | 298652 | Graffiti on N/S/R seat base                                | Remover graffit from seat bases                                                                                                     | 510220 |
| 797 | 05/12/2011 | 298652 | SCANIA DIP STICK L94UAB                                    |                                                                                                                                     | 510220 |
| 797 | 05/12/2011 | 298652 | Idler pulley bearing U/S                                   | Replaced idler pulley bearing                                                                                                       | 510220 |
| 797 | 05/12/2011 | 298652 | Engine dip stick U/S                                       | Replaced engine dip stick                                                                                                           | 510220 |
| 797 | 05/12/2011 | 298652 | Engine not starting from front                             | Checked over engine starting system could not fault at this time                                                                    | 510220 |
| 797 | 05/12/2011 | 298652 | N/S/R brake chamber leaking                                | Tightened N/S/R brake chamber clamp                                                                                                 | 510220 |
| 797 | 05/09/2011 | 299588 | FILTER K124EB HYD COOLING FAN (49M1601)                    | Hydraulic filter                                                                                                                    | 509629 |
| 797 | 05/09/2011 | 299588 | Hydraulic Oil Torque Fluid 414                             | Hydraulic oil                                                                                                                       | 509629 |
| 797 | 05/09/2011 | 299588 | Filter Raycor                                              | Raycor filter                                                                                                                       | 509629 |
| 797 | 05/09/2011 | 299588 | Filter P/S                                                 | Power steering filter                                                                                                               | 509629 |
| 797 | 05/09/2011 | 299588 | Diff Oil Borate EP 460                                     | diff oil                                                                                                                            | 509629 |
| 797 | 05/09/2011 | 299588 |                                                            | Service as per check list                                                                                                           | 509629 |
| 797 | 05/09/2011 | 299588 | FILTER AIR DRYER SCANIA K124EB (T350W)                     | Filter Air Dryer                                                                                                                    | 509629 |
| 797 | 05/09/2011 | 299588 |                                                            | Tension ALL Wheel Nuts to OEM Specs                                                                                                 | 509629 |
| 797 | 05/09/2011 | 299588 |                                                            | A - Service & Bus Safety Inspection                                                                                                 | 509629 |
| 797 | 05/08/2011 | 299626 | Service                                                    | RSI Inspection RWC583129                                                                                                            | 509629 |
| 797 | 05/08/2011 | 299626 | GLOBE                                                      |                                                                                                                                     | 509629 |
| 797 | 05/04/2011 | 298652 | Engine dip stick U/S                                       | Ordered engine dip stick                                                                                                            | 510220 |
| 797 | 05/04/2011 | 298652 | Idler pulley bearing U/S                                   | Order idler pulley bearing                                                                                                          | 510220 |
| 797 | 05/04/2011 | 298652 | GLOBE                                                      |                                                                                                                                     | 509152 |
| 797 | 05/04/2011 | 298652 | Switch lights N/W                                          | Replaced switch light globes                                                                                                        | 509152 |
| 797 | 05/04/2011 | 298652 | Emergency exit light above rear door N/W                   | Checked emergency exit light no fault found working OK                                                                              | 509152 |
| 797 | 05/04/2011 | 298652 | Bus stopping light N/W                                     | Cleaned bus stopping light globe contacts                                                                                           | 509152 |
| 797 | 05/04/2011 | 298652 | Broom handle U/S                                           | New handle fitted                                                                                                                   | 509152 |
| 797 | 05/03/2011 | 298993 |                                                            | Tension ALL Wheel Nuts to OEM Specs                                                                                                 | 509069 |
| 797 | 05/03/2011 | 298993 |                                                            | A - Service & Bus Safety Inspection                                                                                                 | 509069 |
| 797 | 05/03/2011 | 298993 | Kit Scania Cent Oil filter                                 | Kit , filter Cent                                                                                                                   | 509069 |
| 797 | 05/03/2011 | 298993 | FILTER OIL K124 / L94UAB (H200W01)                         | Filter Oil                                                                                                                          | 509069 |
| 797 | 05/03/2011 | 298993 | Hydraulic Oil Torque Fluid 414                             | Torque fluid                                                                                                                        | 509069 |
| 797 | 05/03/2011 | 298993 | FILTER TRANSMISSION ZF 4139-298-038E39HD119                | Filter ZF Trans                                                                                                                     | 509069 |
| 797 | 05/03/2011 | 298993 | FILTER FUEL K124 / LU94A (1411894 / H17WK05)               | Fuel Filter                                                                                                                         | 509069 |
| 797 | 05/03/2011 | 298993 | ENGINE OIL DELO 400LE 15W40                                | Engine Oil                                                                                                                          | 509069 |
| 797 | 05/03/2011 | 298993 |                                                            | A - Service & Bus Safety Inspection                                                                                                 | 509069 |
| 797 | 04/29/2011 | 298652 | A/C low pressure fitting under hand tap leaking oil & gas  | Repaired leaking AC fitting on compressor replaced comp oil and vac down waiting on gas                                             | 510220 |
| 797 | 04/20/2011 | 297990 | Wash check and report on eng oil leaks                     | Washed checked and reported ok                                                                                                      | 507424 |
| 797 | 04/20/2011 | 297972 | GLOBE                                                      |                                                                                                                                     | 507424 |
| 797 | 04/20/2011 | 297990 | GLOBE                                                      |                                                                                                                                     | 507424 |
| 797 | 04/20/2011 | 297990 | Bus stopping sign not working                              | Replaced blown globe ok                                                                                                             | 507424 |
| 797 | 04/20/2011 | 297972 | Heater hoses loose at boost pump                           | Tied up heater hoses                                                                                                                | 507424 |
| 797 | 04/20/2011 | 297972 | Header tank isolator strp coming out                       | Secured header tank insulator                                                                                                       | 507424 |
| 797 | 04/20/2011 | 297990 | Wash check and report on diff oil leaks                    | Washed checked and reported ok                                                                                                      | 507424 |
| 797 | 04/20/2011 | 297972 | Centre OS seat base loose                                  | Nipped up loose seat base                                                                                                           | 507424 |
| 797 | 04/20/2011 | 297972 | Rear marker plates faded                                   | Replaced both rear marker plates                                                                                                    | 507424 |
| 797 | 04/20/2011 | 297972 | NS mirror arm bent                                         | Straightened mirror arm                                                                                                             | 507424 |
| 797 | 04/20/2011 | 297972 | Exterior body panel screws loose                           | Tightened screws                                                                                                                    | 507424 |
| 797 | 04/20/2011 | 297972 | REAR MARKER DECAL                                          |                                                                                                                                     | 507424 |
| 797 | 04/20/2011 | 297972 | Air lines rubbing on fuel tank                             | Tied up loose air lines                                                                                                             | 507424 |
| 797 | 04/19/2011 | 297793 |                                                            | Inspect vehicle as per RSI Checklist                                                                                                | 507417 |
| 797 | 04/19/2011 | 297805 | Accident Damaged # 32985 R/R. rear bumper-bar - 1 Piece re |                                                                                                                                     | 507417 |
| 797 | 04/19/2011 | 297805 | LAMP INTERIOR AND REVERSING                                |                                                                                                                                     | 507417 |
| 797 | 04/19/2011 | 297805 | Accident Damaged # 32985 R/R. rear bumper-bar - 1 Piece re | Repair accident damage #32985                                                                                                       | 507417 |
| 797 | 04/19/2011 | 297805 | Accident Damaged # 32985 R/R. rear bumper-bar - 1 Piece re | Repair accident damage #32985                                                                                                       | 507417 |
| 797 | 04/14/2011 | 297805 | Direct Purchase - BODYWORK                                 | Creditor #:VOL001 VOLGREN AUSTRALIA P/L P/O #:V91151 Receiving #:92440 Date :2011-04-21 BUS 797 - REAR BUMPER                       | 507417 |
| 797 | 04/08/2011 | 296521 | FLURO TUBE 18W                                             |                                                                                                                                     | 507207 |
| 797 | 04/08/2011 | 296521 |                                                            | Door Service                                                                                                                        | 507207 |
| 797 | 04/08/2011 | 296521 | Service                                                    | CCTV Hard Drive Check                                                                                                               | 507207 |
| 797 | 04/07/2011 | 295910 | 295/80R22.5 RECAMIC DRIVE PATT                             | Creditor #:MIC050 MICHELIN AUSTRALIA PTY LTD P/O #:V90627 Receiving #:92151 Date :2011-04-18                                        | 507417 |
| 797 | 04/07/2011 | 295910 | FITTING                                                    | Creditor #:MIC050 MICHELIN AUSTRALIA PTY LTD P/O #:V90627 Receiving #:92151 Date :2011-04-18                                        | 507417 |
| 797 | 04/05/2011 | 296182 | Air leak at N/S/R tyre                                     | Replaced leaking N/S/R/O tyre valve                                                                                                 | 506799 |
| 797 | 04/04/2011 | 295910 | O/S/R/I tyre U/S                                           | Replaced O/S/R tyres                                                                                                                | 506536 |
| 797 | 04/04/2011 | 295910 | Rip in rear seat base                                      | Repaired passenger seat                                                                                                             | 506536 |
| 797 | 04/04/2011 | 295910 | Graffiti on back of seat                                   | Removed graffiti                                                                                                                    | 506536 |

|     |            |        |                                                             |                                                                                                                                                                 |  |        |
|-----|------------|--------|-------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------|--|--------|
| 797 | 04/04/2011 | 295910 | BUSH SWAY BAR FRONT K230                                    |                                                                                                                                                                 |  | 506536 |
| 797 | 04/04/2011 | 295910 | Front sway bar rubbers U/S                                  | Replaced front sway bar rubbers                                                                                                                                 |  | 506536 |
| 797 | 04/04/2011 | 295910 | Drv entered - Heat & Demist No Heaters                      | Road tested control set at 28 degrees 26.5 coming from the vents                                                                                                |  | 506536 |
| 797 | 04/04/2011 | 295910 | Heater did not work at all                                  | Refer to fault # 315107                                                                                                                                         |  | 506536 |
| 797 | 04/04/2011 | 295910 | GLOBE                                                       |                                                                                                                                                                 |  | 506536 |
| 797 | 04/04/2011 | 295910 | Needed to start from rear twice?                            | Checked starting operation could not fault at this time                                                                                                         |  | 506536 |
| 797 | 04/04/2011 | 295910 | ELLAMP LIGHT COVER 3MT                                      |                                                                                                                                                                 |  | 506536 |
| 797 | 04/04/2011 | 295910 | Switch lights N/W                                           | Replaced switch light globes                                                                                                                                    |  | 506536 |
| 797 | 04/04/2011 | 295910 | Door OK light N/W                                           | Replaced door OK light globe                                                                                                                                    |  | 506536 |
| 797 | 04/04/2011 | 295910 | Battery terminals need washing & checking?                  | Washed & checked battery terminals no fault found                                                                                                               |  | 506536 |
| 797 | 04/04/2011 | 295910 | O/S park light N/W                                          | Replaced O/S/F park light globe                                                                                                                                 |  | 506536 |
| 797 | 04/04/2011 | 295910 | Saloon lights N/W                                           | Replaced saloon light fluro tubes & covers                                                                                                                      |  | 506536 |
| 797 | 04/04/2011 | 295910 | 2 way radio switched itself OFF stayed ON once turned ON a  | Turns OFF when volume control moved only did it once                                                                                                            |  | 506536 |
| 797 | 04/04/2011 | 295910 | DECAL STAND BEHIND THIS LINE                                |                                                                                                                                                                 |  | 506536 |
| 797 | 04/04/2011 | 295910 | DECAL EMERGENCY EXIT PUSH BUTTON UNDER PANEL                |                                                                                                                                                                 |  | 506536 |
| 797 | 04/04/2011 | 295910 | 25mm BLACK NUMERAL                                          |                                                                                                                                                                 |  | 506536 |
| 797 | 04/04/2011 | 295910 | GIVE WAY SIGN (LARGE)                                       |                                                                                                                                                                 |  | 506536 |
| 797 | 04/04/2011 | 295910 | DECAL - LICENCED TO CARRY                                   |                                                                                                                                                                 |  | 506536 |
| 797 | 04/04/2011 | 295910 | Wheelchair hinge pin needs to be refitted                   | Refitted wheel chair hinge pin                                                                                                                                  |  | 506536 |
| 797 | 04/04/2011 | 295910 | Trim missing off back of seat 2nd from rear on N/S          | Replaced passenger seat trim                                                                                                                                    |  | 506536 |
| 797 | 04/04/2011 | 295910 | Give way decal faded                                        | Replaced give way decal                                                                                                                                         |  | 506536 |
| 797 | 04/04/2011 | 295910 | External licence to carry decal faded                       | Replaced licence to carry decal                                                                                                                                 |  | 506536 |
| 797 | 04/04/2011 | 295910 | Rear door emergency exit decal U/S                          | Replaced rear door emergency exit decal                                                                                                                         |  | 506536 |
| 797 | 04/04/2011 | 295910 | Stand behind yellow line decal U/S                          | Replaced stand behind yellow line decal                                                                                                                         |  | 506536 |
| 797 | 04/04/2011 | 295910 | O/S/F seat base loose                                       | Secured seat bases                                                                                                                                              |  | 506536 |
| 797 | 04/04/2011 | 295910 | ABS light came ON after half of the shift and stayed ON til | Road tested no fault found at this time                                                                                                                         |  | 506536 |
| 797 | 04/04/2011 | 295910 | Drv entered - Brakes ABS On                                 | Checked brakes no fault found                                                                                                                                   |  | 506536 |
| 797 | 04/04/2011 | 295910 | Air line rubbing on V bar                                   | Secured air line                                                                                                                                                |  | 506536 |
| 797 | 04/01/2011 | 295722 | Service                                                     | A - Service & Bus Safety Inspection                                                                                                                             |  | 505923 |
| 797 | 04/01/2011 | 295722 |                                                             | Tension ALL Wheel Nuts to OEM Specs                                                                                                                             |  | 505923 |
| 797 | 03/25/2011 | 294933 | OS head light not working                                   | Replaced blown headlight globe                                                                                                                                  |  | 504063 |
| 797 | 03/25/2011 | 294933 | GLOBE HEADLAMP H1                                           |                                                                                                                                                                 |  | 504063 |
| 797 | 03/23/2011 | 294382 | N/S mirror U/S                                              | Replace N/S mirror                                                                                                                                              |  | 503148 |
| 797 | 03/23/2011 | 294382 | MIRROR METAGAL L/H                                          |                                                                                                                                                                 |  | 503148 |
| 797 | 03/01/2011 | 292027 | PAINT SUPPLIES                                              |                                                                                                                                                                 |  | 498354 |
| 797 | 03/01/2011 | 292027 | Accident Damaged # 32653 R/R. n/s. lower body panel No4 n/  | Repair accident damage # 32653                                                                                                                                  |  | 498354 |
| 797 | 03/01/2011 | 292027 | Accident Damaged # 32653 R/R. n/s. lower body panel No4 n/  | Repair accident damage # 32653                                                                                                                                  |  | 498354 |
| 797 | 03/01/2011 | 292027 | BODY SHOP SUPPLIES                                          |                                                                                                                                                                 |  | 498354 |
| 797 | 02/28/2011 | 291489 | Moisture ejector N/W                                        | Check moisture ejector operation no fault found                                                                                                                 |  | 498145 |
| 797 | 02/24/2011 | 291115 | Bus stopping light N/W                                      | Replace bus stopping light globe                                                                                                                                |  | 497392 |
| 797 | 02/24/2011 | 291115 | N/S fluro above first seat N/W                              | Check OK                                                                                                                                                        |  | 497392 |
| 797 | 02/24/2011 | 291115 | GLOBE                                                       |                                                                                                                                                                 |  | 497392 |
| 797 | 02/24/2011 | 291115 | Coolant leak at water manifold                              | Replace header tank hoses                                                                                                                                       |  | 497392 |
| 797 | 02/24/2011 | 291115 | N/S/R body panel reflector U/S                              | Replace body panel reflectors                                                                                                                                   |  | 497392 |
| 797 | 02/24/2011 | 291115 | Front door emergency exit decal missing                     | Replace decal                                                                                                                                                   |  | 497392 |
| 797 | 02/24/2011 | 291115 | DECAL EMERGENCY EXIT BLACK PUSH BUTTON UNDER BUMPER         |                                                                                                                                                                 |  | 497392 |
| 797 | 02/24/2011 | 291115 | Rear door emergency exit decal missing                      | Ordered                                                                                                                                                         |  | 497392 |
| 797 | 02/24/2011 | 291115 | Trim missing from N/S/R seat back                           | Ordered                                                                                                                                                         |  | 497392 |
| 797 | 02/23/2011 | 290941 |                                                             | Tension ALL Wheel Nuts to OEM Specs                                                                                                                             |  | 497130 |
| 797 | 02/23/2011 | 290941 | Service                                                     | A - Service & Bus Safety Inspection                                                                                                                             |  | 497130 |
| 797 | 02/23/2011 | 290941 | Service                                                     | A - Service & Bus Safety Inspection                                                                                                                             |  | 497130 |
| 797 | 02/21/2011 | 290482 | AM/FM radio dosen't work                                    | Check AM/FM radio aerial broken aerial base order required parts                                                                                                |  | 496896 |
| 797 | 02/21/2011 | 290482 | Interior light on dash is blown                             | Replace dash globes                                                                                                                                             |  | 496896 |
| 797 | 02/21/2011 | 290482 | Bus would not start from ignition switch this mourning at R | Check starting operation & starter wiring could not fault at this time                                                                                          |  | 496896 |
| 797 | 02/21/2011 | 290482 | Top right hand parker light not working                     | Replace O/S/F top indicator globe                                                                                                                               |  | 496896 |
| 797 | 02/21/2011 | 290482 | GLOBE                                                       |                                                                                                                                                                 |  | 496896 |
| 797 | 02/07/2011 | 288434 | Indicator light in dash does not work dash light for speed  | Replace globes secure dash                                                                                                                                      |  | 495003 |
| 797 | 02/07/2011 | 288434 | No audible or visible signal on the dash board to show when | Replace globes secure dash                                                                                                                                      |  | 495003 |
| 797 | 02/07/2011 | 288434 | Dash lights & indicators not working cannot read speedomet  | Replace globes secure dash                                                                                                                                      |  | 495003 |
| 797 | 02/07/2011 | 288434 | Bus warning or indicator lights in dash not working         | Replace globes secure dash                                                                                                                                      |  | 495003 |
| 797 | 02/07/2011 | 288434 | No light in the speedo you just have to guess your speedin  | Replace globes secure dash                                                                                                                                      |  | 495003 |
| 797 | 02/07/2011 | 288434 | GLOBE+HOLDER INSTRUMENT (GREY)                              |                                                                                                                                                                 |  | 495003 |
| 797 | 02/07/2011 | 288434 | GLOBE                                                       |                                                                                                                                                                 |  | 495003 |
| 797 | 01/31/2011 | 287548 | Accident Damaged # 32405 R/R. n/s. lower panel No2 Repairs  | Repair accident damage #32405                                                                                                                                   |  | 492970 |
| 797 | 01/31/2011 | 287548 | Accident Damaged # 32405 R/R. n/s. lower panel No2 Repairs  | Repair accident damage #32405                                                                                                                                   |  | 492970 |
| 797 | 01/31/2011 | 287548 | BODY SHOP SUPPLIES                                          |                                                                                                                                                                 |  | 492970 |
| 797 | 01/31/2011 | 287548 | PAINT SUPPLIES                                              |                                                                                                                                                                 |  | 492970 |
| 797 | 01/28/2011 | 287526 | OSFT indicator not working                                  | Replace OSFT indicator globe                                                                                                                                    |  | 492561 |
| 797 | 01/28/2011 | 287526 | GLOBE                                                       |                                                                                                                                                                 |  | 492561 |
| 797 | 01/18/2011 | 285910 | AC comp leaking gas at low side fitting on compressor       | check a/c components o.k. low a/c gas recover gas perfrom leak test vac down fill with gas check oil leak                                                       |  | 490707 |
| 797 | 01/18/2011 | 285910 | Drv entered - Air Cond Air Conditioner                      | check a/c components ok. low a/c gas recover gas perform leak test vac down fill with gas check oil leak                                                        |  | 490707 |
| 797 | 01/18/2011 | 285910 | Air-con not functioning                                     | check a/c components ok. low a/c gas recover gas perform leak test vac down fill with gas check oil leak                                                        |  | 490707 |
| 797 | 01/18/2011 | 285910 | Air con blowing warm air                                    | check a/c components ok. low a/c gas recover gas perform leak test vac down fill with gas check oil leak                                                        |  | 490707 |
| 797 | 01/18/2011 | 285910 | AIR CON REFRIDGERANT                                        |                                                                                                                                                                 |  | 490707 |
| 797 | 01/14/2011 | 283245 | Direct Purchase - BODYWORK                                  | Creditor #:TRA060 TRANSCAL GRAPHICS P/O #:V86917 Receiving #:88956 Date :2011-02-01 Please supply and install decals to Bus 797 as per order sheet (ACC #32360) |  | 493160 |
| 797 | 01/11/2011 | 285000 | N/S/R rear wheel missing valve extension                    | Fit valve extension                                                                                                                                             |  | 489823 |
| 797 | 01/11/2011 | 285000 | TYRE VALVE EXTENSION                                        |                                                                                                                                                                 |  | 489823 |
| 797 | 01/11/2011 | 285000 | Both rear front air bags U/S                                | Replace both air bags                                                                                                                                           |  | 489823 |
| 797 | 01/11/2011 | 285000 | Both front air bags U/S                                     | Replace both air bags                                                                                                                                           |  | 489823 |
| 797 | 01/11/2011 | 285000 | Front sway bar bushes U/S                                   | Still servicablereplace close to RSI                                                                                                                            |  | 489823 |
| 797 | 01/11/2011 | 285000 | REAR AIR BAG (DRIVE AXLE) SCANIA L94UAB                     |                                                                                                                                                                 |  | 489823 |
| 797 | 01/11/2011 | 285000 | AIR BAG FRONT L94                                           |                                                                                                                                                                 |  | 489823 |
| 797 | 01/11/2011 | 285000 | Oil leak at A/C compressor wash & check?                    | Wash and checked OK                                                                                                                                             |  | 489823 |
| 797 | 01/11/2011 | 285000 | Rear door roller mount loose                                | Nipp up mounting arm bolts                                                                                                                                      |  | 489823 |
| 797 | 01/11/2011 | 285000 | Saloon lights N/W                                           | Replace saloon light tube                                                                                                                                       |  | 489823 |
| 797 | 01/11/2011 | 285000 | N/S/F park light N/W                                        | Replace globe                                                                                                                                                   |  | 489823 |
| 797 | 01/11/2011 | 285000 | Switch lights N/W                                           | Replace switch light globes                                                                                                                                     |  | 489823 |
| 797 | 01/11/2011 | 285000 | GLOBE                                                       |                                                                                                                                                                 |  | 489823 |
| 797 | 01/11/2011 | 285002 | Service                                                     | Door Service                                                                                                                                                    |  | 489823 |
| 797 | 01/11/2011 | 285002 | Service                                                     | CCTV Hard Drive Check and replace hard drive                                                                                                                    |  | 489823 |
| 797 | 01/11/2011 | 285002 | FLURO TUBE 18W                                              |                                                                                                                                                                 |  | 489823 |
| 797 | 01/11/2011 | 285002 | SATA HARD DRIVE & SHELL (VIDEO DVR UNIT)                    |                                                                                                                                                                 |  | 489823 |
| 797 | 01/06/2011 | 284392 | Hydraulic Oil Torque Fluid 414                              | Torque fluid                                                                                                                                                    |  | 489313 |

|     |            |        |                                                             |                                                                                                                                                             |        |
|-----|------------|--------|-------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|
| 797 | 01/06/2011 | 284392 | FILTER OIL K124 / L94UAB (H200W01)                          | Filter Oil                                                                                                                                                  | 489313 |
| 797 | 01/06/2011 | 284392 | Kit Scania Cent Oil filter                                  | Kit . filter Cent                                                                                                                                           | 489313 |
| 797 | 01/06/2011 | 284392 |                                                             | A - Service & Bus Safety Inspection                                                                                                                         | 489313 |
| 797 | 01/06/2011 | 284392 |                                                             | Tension ALL Wheel Nuts to OEM Specs                                                                                                                         | 489313 |
| 797 | 01/06/2011 | 284392 | ENGINE OIL DELO 400LE 15W40                                 | Engine Oil                                                                                                                                                  | 489313 |
| 797 | 01/06/2011 | 284392 | FILTER FUEL K124 / LU94A (1411894 / H17WK05)                | Fuel Filter                                                                                                                                                 | 489313 |
| 797 | 01/06/2011 | 284392 | FILTER TRANSMISSION ZF 4139-298-038E39HD119                 | Filter ZF Trans                                                                                                                                             | 489313 |
| 797 | 01/06/2011 | 284392 | WORKSHOP SUPPLIES                                           |                                                                                                                                                             | 489313 |
| 797 | 01/06/2011 | 284392 |                                                             | A - Service & Bus Safety Inspection                                                                                                                         | 489313 |
| 797 | 01/05/2011 | 284242 | Windscreen washer bottle empty                              | Repair Washers                                                                                                                                              | 489129 |
| 797 | 01/05/2011 | 284242 | Touch volume knob on two way and it closes off              | Repair knob on 2 way                                                                                                                                        | 489129 |
| 797 | 01/05/2011 | 284242 | Windscreen needs cleaning                                   | Clean Windscreen                                                                                                                                            | 489129 |
| 797 | 01/05/2011 | 284242 | Ring lift missing from the ramp very difficult to lift up   | Fit new pull ring                                                                                                                                           | 489129 |
| 797 | 01/05/2011 | 284242 | LIFT RING                                                   |                                                                                                                                                             | 489129 |
| 797 | 01/05/2011 | 283245 | BODY SHOP SUPPLIES                                          |                                                                                                                                                             | 488063 |
| 797 | 01/05/2011 | 283245 | PAINT SUPPLIES                                              |                                                                                                                                                             | 488063 |
| 797 | 01/04/2011 | 283245 | Accident Damaged # 32360 R/R. front bumper-bar-centre secti | Repair accident damage # 32360                                                                                                                              | 488063 |
| 797 | 01/04/2011 | 283245 | Accident Damaged # 32360 R/R. front bumper-bar-centre secti | Repair accident damage # 32360                                                                                                                              | 488063 |
| 797 | 12/24/2010 | 283245 | Accident Damaged # 32360 R/R. front bumper-bar-centre secti | Repair accident damage # 32360                                                                                                                              | 488063 |
| 797 | 12/17/2010 | 282383 | Service                                                     | Transmission /check as per Check List                                                                                                                       | 486815 |
| 797 | 12/15/2010 | 281127 | FITTING                                                     | Creditor #:MICO50 MICHELIN AUSTRALIA PTY LTD P/O #:V86085 Receiving #:87270 Date :2010-12-15 Please fit customer supplied run out tyres                     | 486368 |
| 797 | 12/15/2010 | 281127 | BALANCE OFF VEHICLE                                         | Creditor #:MICO50 MICHELIN AUSTRALIA PTY LTD P/O #:V86085 Receiving #:87270 Date :2010-12-15                                                                | 486368 |
| 797 | 12/13/2010 | 281127 | Front tyres U/S                                             | Replace front tyres with Michelin run out XZU3                                                                                                              | 485893 |
| 797 | 12/13/2010 | 281127 | All air bags need checking for leaks leaning                | Replace leaking NSR of rear air bag                                                                                                                         | 485893 |
| 797 | 12/13/2010 | 281127 | REAR AIR BAG (DRIVE AXLE) SCANIA L94UAB                     |                                                                                                                                                             | 485893 |
| 797 | 12/08/2010 | 281127 | All air bags need checking for leaks leaning                |                                                                                                                                                             | 485893 |
| 797 | 12/07/2010 | 280825 | Service                                                     | Check air bags and report bags leaking                                                                                                                      | 484432 |
| 797 | 12/07/2010 | 280825 | ROCKER COVER GASKET L94UAB                                  | Adjust Tappets                                                                                                                                              | 484432 |
| 797 | 11/26/2010 | 274938 | Direct Purchase - BODYWORK                                  |                                                                                                                                                             | 482505 |
| 797 | 11/20/2010 | 278714 | NSF indicator not working                                   | Creditor #:TRA060 TRANSCAL GRAPHICS P/O #:V83908 Receiving #:86410 Date :2010-11-26 Please supply and fit decals to bus 797 as per order sheet (ACC #32055) | 481265 |
| 797 | 11/20/2010 | 278714 | GLOBE                                                       | Replace NSF indicator globe                                                                                                                                 | 481265 |
| 797 | 11/15/2010 | 277957 | ABS light comes on                                          |                                                                                                                                                             | 480136 |
| 797 | 11/13/2010 | 277870 | Transcal to fit decals                                      | Check ABS fault codes. nil codes stored road test ok                                                                                                        | 479652 |
| 797 | 11/09/2010 | 277168 | Wiper blades U/S                                            | Decals fitted by Transcal                                                                                                                                   | 479098 |
| 797 | 11/09/2010 | 277168 | WIPER BLADE 36                                              | Replace both wiper blades                                                                                                                                   | 479098 |
| 797 | 11/09/2010 | 277168 | Front door switch infill broken & in switch                 |                                                                                                                                                             | 479098 |
| 797 | 11/09/2010 | 277168 | FLURO TUBE 18W                                              | Replace switch insert                                                                                                                                       | 479098 |
| 797 | 11/09/2010 | 277168 | GLOBE                                                       |                                                                                                                                                             | 479098 |
| 797 | 11/09/2010 | 277168 | Switch lights N/W                                           | Replace blown switch light globes                                                                                                                           | 479098 |
| 797 | 11/09/2010 | 277168 | No. 3 saloon fluro light N/W                                | Replace 3 fluro tubes and cover                                                                                                                             | 479098 |
| 797 | 11/09/2010 | 277168 | Rear external door light N/W                                | Replace fluro tube                                                                                                                                          | 479098 |
| 797 | 11/09/2010 | 277168 | Bus stopping globe N/W                                      | Replace globe                                                                                                                                               | 479098 |
| 797 | 11/09/2010 | 277168 | Battery terminals corroded                                  | Wash batteries                                                                                                                                              | 479098 |
| 797 | 11/09/2010 | 277168 | Side reflectors missing                                     | Replace missing reflectors                                                                                                                                  | 479098 |
| 797 | 11/09/2010 | 277168 | REFLECTOR ORANGE                                            |                                                                                                                                                             | 479098 |
| 797 | 11/06/2010 | 276916 | Service                                                     | A - Service & Bus Safety Inspection                                                                                                                         | 478647 |
| 797 | 11/06/2010 | 276916 |                                                             | Tension ALL Wheel Nuts to OEM Specs                                                                                                                         | 478647 |
| 797 | 10/26/2010 | 274939 | BODY SHOP SUPPLIES                                          |                                                                                                                                                             | 475451 |
| 797 | 10/26/2010 | 274939 | PAINT SUPPLIES                                              |                                                                                                                                                             | 475451 |
| 797 | 10/26/2010 | 274938 | ALUMINIUM SUPPLIES                                          |                                                                                                                                                             | 475451 |
| 797 | 10/26/2010 | 274938 | BODY SHOP SUPPLIES                                          |                                                                                                                                                             | 475451 |
| 797 | 10/26/2010 | 274938 | PAINT SUPPLIES                                              |                                                                                                                                                             | 475451 |
| 797 | 10/25/2010 | 274939 | Accident Damaged #31895 Repair o/s. lower panel No 5. Polis | Repair accident damage #31895                                                                                                                               | 475451 |
| 797 | 10/25/2010 | 274938 | Accident Damaged # 32055 R/R. o/s. lower body panels No3    | Repair accident damage #32055                                                                                                                               | 475451 |
| 797 | 10/22/2010 | 274938 | Accident Damaged # 32055 R/R. o/s. lower body panels No3    | Repair accident damage #32055                                                                                                                               | 475451 |
| 797 | 10/22/2010 | 274938 | Accident Damaged # 32055 R/R. o/s. lower body panels No3    | Repair accident damage #32055                                                                                                                               | 475451 |
| 797 | 10/07/2010 | 272934 | Service                                                     | Door Service                                                                                                                                                | 472528 |
| 797 | 10/07/2010 | 272934 |                                                             | CCTV Hard Drive Check                                                                                                                                       | 472528 |
| 797 | 10/04/2010 | 272383 | No heating from air con blowing cold air regardless of sel  | Check a/c system no fault found                                                                                                                             | 471847 |
| 797 | 09/30/2010 | 271850 | GLOBE                                                       |                                                                                                                                                             | 470366 |
| 797 | 09/30/2010 | 271850 | FLURO TUBE 18W                                              |                                                                                                                                                             | 470366 |
| 797 | 09/29/2010 | 271850 | Graffiti on N/S/R seat backs                                | Clean off graffiti                                                                                                                                          | 470366 |
| 797 | 09/29/2010 | 271850 | A/C hose in the way of spin filter                          | Reposition hoses                                                                                                                                            | 470366 |
| 797 | 09/29/2010 | 271850 | Batteries require a wash                                    | Wash off batteries                                                                                                                                          | 470366 |
| 797 | 09/29/2010 | 271850 | Switch lights N/W                                           | Replace blown switch light globes                                                                                                                           | 470366 |
| 797 | 09/29/2010 | 271850 | N/S/F saloon light N/W                                      | Replace blown saloon fluro                                                                                                                                  | 470366 |
| 797 | 09/29/2010 | 271850 | O/S/R saloon light is dull                                  | Replace blown saloon fluro                                                                                                                                  | 470366 |
| 797 | 09/29/2010 | 271850 | Front door external light N/W                               | Replace blown fluro tube                                                                                                                                    | 470366 |
| 797 | 09/29/2010 | 271850 | Wash & check diff for leaks                                 | Wash eand check diff oil leaks ok                                                                                                                           | 470366 |
| 797 | 09/29/2010 | 271850 | Step tread on O/S/R step missing                            | Replace step tread                                                                                                                                          | 470366 |
| 797 | 09/28/2010 | 271791 | WORKSHOP SUPPLIES                                           |                                                                                                                                                             | 470360 |
| 797 | 09/28/2010 | 271791 | ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL              | Engine Oil                                                                                                                                                  | 470360 |
| 797 | 09/28/2010 | 271791 |                                                             | Tension ALL Wheel Nuts to OEM Specs                                                                                                                         | 470360 |
| 797 | 09/28/2010 | 271791 |                                                             | A - Service & Bus Safety Inspection                                                                                                                         | 470360 |
| 797 | 09/28/2010 | 271791 | Service                                                     | A - Service & Bus Safety Inspection                                                                                                                         | 470360 |
| 797 | 09/28/2010 | 271791 | Kit Scania Cent Oil filter                                  | Kit . filter Cent                                                                                                                                           | 470360 |
| 797 | 09/28/2010 | 271791 | FILTER OIL K124 / L94UAB (H200W01)                          | Filter Oil                                                                                                                                                  | 470360 |
| 797 | 09/28/2010 | 271791 | Hydraulic Oil Torque Fluid 414                              | Torque fluid                                                                                                                                                | 470360 |
| 797 | 09/28/2010 | 271791 | FILTER TRANSMISSION ZF 4139-298-038E39HD119                 | Filter ZF Trans                                                                                                                                             | 470360 |
| 797 | 09/28/2010 | 271791 | FILTER FUEL K124 / LU94A (1411894 / H17WK05)                | Fuel Filter                                                                                                                                                 | 470360 |
| 797 | 09/28/2010 | 271791 | Service                                                     | A - Service & Bus Safety Inspection                                                                                                                         | 470360 |
| 797 | 09/28/2010 | 271791 | Service                                                     | Tension ALL Wheel Nuts to OEM Specs                                                                                                                         | 470360 |
| 797 | 09/28/2010 | 271791 |                                                             | A - Service & Bus Safety Inspection                                                                                                                         | 470360 |
| 797 | 09/17/2010 | 269642 | ABS light came on                                           | No active codes stored clear out and roadtest ok                                                                                                            | 467714 |
| 797 | 09/16/2010 | 270244 | Engine hatch switch needs adjusting or replacing            | Adjust lube and check operation of switch ok                                                                                                                | 467349 |
| 797 | 09/14/2010 | 269642 | 2-Way turns itself off when driving                         | Check 2-way operation could not fault at thistime                                                                                                           | 466502 |
| 797 | 09/13/2010 | 269642 | ABS light on                                                | No active codes stored clear out and roadtest ok                                                                                                            | 467714 |
| 797 | 09/02/2010 | 268286 | CCTV not working Graham (Supervisor) put tape in in the m   | Check record settings on recorder repiar wiring at camera 2 and test ok                                                                                     | 464863 |
| 797 | 08/30/2010 | 267717 | WHEEL NUT SQUIRREL                                          |                                                                                                                                                             | 463247 |
| 797 | 08/28/2010 | 267717 | Fit wheel nut squirrels to rear wheel hubs                  | Fit squirrels to rear wheels                                                                                                                                | 463247 |
| 797 | 08/28/2010 | 267717 | Indicators do not self cancel                               | Check indicator self cancel and working ok                                                                                                                  | 463247 |
| 797 | 08/19/2010 | 266414 | BODY SHOP SUPPLIES                                          |                                                                                                                                                             | 461614 |
| 797 | 08/19/2010 | 266414 | Vac & charge A/C system                                     | Vac down A/C system and charge with refridgerant                                                                                                            | 461614 |

|     |            |        |                                                        |                                                                                                                                |        |
|-----|------------|--------|--------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------|--------|
| 797 | 08/19/2010 | 266414 | AIR CON REFRIDGERANT                                   |                                                                                                                                | 461614 |
| 797 | 08/18/2010 | 266280 | Check A/C system for operation and for leaks           | Test Ac operation check pressures remove 4.5 kg of gas charge with nitrogen and check for leaks replace AC comp oil put on vac | 461614 |
| 797 | 08/16/2010 | 265933 | AC coil clean and service                              | AC coil clean and service                                                                                                      | 460947 |
| 797 | 08/11/2010 | 265398 | Rear flat tyre                                         | Replace punctured OSRO tyre with good second hand Rotar recap                                                                  | 460033 |
| 797 | 08/10/2010 | 265217 | GAS STAY 500N X 330MM                                  |                                                                                                                                | 460033 |
| 797 | 08/10/2010 | 265217 | Battery hatch struts U/S - In stock                    | Remove and fit new battery hatch struts                                                                                        | 460033 |
| 797 | 08/10/2010 | 265203 | ABS light coming on                                    | Check wiring and road test could not fault                                                                                     | 460033 |
| 797 | 08/05/2010 | 264437 | BELT VEE                                               |                                                                                                                                | 457305 |
| 797 | 08/04/2010 | 264437 | Graffiti on O/S/R seat & window ledge                  | Clean off graffiti                                                                                                             | 457305 |
| 797 | 08/04/2010 | 264437 | A/C belts split                                        | Fit 2 new AC belts                                                                                                             | 457305 |
| 797 | 08/04/2010 | 264437 | No heat from heater/demister                           | Check heater operation and road test vent temp 22 ok                                                                           | 457305 |
| 797 | 08/04/2010 | 264437 | Battery hatch struts take notes & order                | Measure and order hatc struts                                                                                                  | 457305 |
| 797 | 08/03/2010 | 264228 |                                                        | A - Service & Bus Safety Inspection                                                                                            | 457305 |
| 797 | 08/03/2010 | 264228 |                                                        | Tension ALL Wheel Nuts to OEM Specs                                                                                            | 457305 |
| 797 | 07/28/2010 | 263821 | NS convex mirror fallen out                            | Refit convex mirror to head                                                                                                    | 457305 |
| 797 | 07/21/2010 | 262681 | Service                                                | Transmission /check as per Check List                                                                                          | 456578 |
| 797 | 07/21/2010 | 262681 | Service                                                | Transmission /check as per Check List                                                                                          | 456578 |
| 797 | 07/17/2010 | 262192 |                                                        | CCTV Hard Drive Check                                                                                                          | 456182 |
| 797 | 07/17/2010 | 262192 |                                                        | Door Service                                                                                                                   | 456182 |
| 797 | 07/07/2010 | 260830 | Heater in drivers area not working                     | Check heater operation check boost pump and heat valve ok check boost fan and evap fans ok could not fault                     | 453193 |
| 797 | 06/28/2010 | 259656 | Check Batts & put on charge                            | Load test batteries and put on charge check charge rate at 27V ok                                                              | 452412 |
| 797 | 06/18/2010 | 258611 | O/S windscreen washer jets blocked and misaligned      | Clean out and adjust washer jets                                                                                               | 449999 |
| 797 | 06/18/2010 | 258611 | Rear door pivot arm loose and door requires adjustment | Adjust rear door roller arms                                                                                                   | 449999 |
| 797 | 06/18/2010 | 258611 | Globe in hazard light N/W                              | Replace globe in hazard light switch                                                                                           | 449999 |
| 797 | 06/18/2010 | 258611 | Guage lights N/W                                       | Replace globe                                                                                                                  | 449999 |
| 797 | 06/18/2010 | 258611 | Saloon fluro's and door fluro internal lights N/W      | Replaceblown fluro tubes                                                                                                       | 449999 |
| 797 | 06/18/2010 | 258611 | FLURO TUBE 18W                                         |                                                                                                                                | 449999 |
| 797 | 06/18/2010 | 258611 | GLOBE                                                  |                                                                                                                                | 449999 |
| 797 | 06/18/2010 | 258611 | GLOBE                                                  |                                                                                                                                | 449999 |
| 797 | 06/18/2010 | 258611 | Graffiti on N/S/R duct                                 | Clean off graffiti                                                                                                             | 449999 |
| 797 | 06/18/2010 | 258611 | Slashed N/S 2nd from rear seat slashed                 | Stitch up torn seat                                                                                                            | 449999 |
| 797 | 06/17/2010 | 258467 | FILTER TRANSMISSION ZF 4139-298-038E39HD119            | Filter ZF Trans                                                                                                                | 449999 |
| 797 | 06/17/2010 | 258467 | ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL         | Engine Oil                                                                                                                     | 449999 |
| 797 | 06/17/2010 | 258467 |                                                        | A - Service & Bus Safety Inspection                                                                                            | 449999 |
| 797 | 06/17/2010 | 258467 | FILTER OIL K124 / L94UAB (H200W01)                     | Filter Oil                                                                                                                     | 449999 |
| 797 | 06/17/2010 | 258467 | FILTER FUEL K124 / LU94A (1411894 / H17WK05)           | Fuel Filter                                                                                                                    | 449999 |
| 797 | 06/17/2010 | 258467 | Kit Scania Cent Oil filter                             | Kit . filter Cent                                                                                                              | 449999 |
| 797 | 06/17/2010 | 258467 | Hydraulic Oil Torque Fluid 414                         | Torque fluid                                                                                                                   | 449999 |
| 797 | 06/17/2010 | 258467 |                                                        | Tension ALL Wheel Nuts to OEM Specs                                                                                            | 449999 |
| 797 | 06/17/2010 | 258467 |                                                        | A - Service & Bus Safety Inspection                                                                                            | 449999 |
| 797 | 06/08/2010 | 257459 | Fire extinguisher tag missing                          | Replace fire extinguisher                                                                                                      | 448309 |
| 797 | 06/08/2010 | 257459 | Fit reflectors to rear of bus                          | Check bus for reflectors nill stock order reflectors                                                                           | 448309 |
| 797 | 06/08/2010 | 257459 | Secure front door heater outlet vent                   | Secure N/S heater vent above door                                                                                              | 448309 |
| 797 | 06/06/2010 | 257321 | RSI Inspection                                         | RSI Inspection (BC 126652)                                                                                                     | 448089 |
| 797 | 06/05/2010 | 257178 | Wash and check over for RSI                            | Wash and check over for RSI                                                                                                    | 448089 |
| 797 | 06/05/2010 | 257178 | Wash and check over for RSI                            | Wash and check over for RSI                                                                                                    | 448089 |
| 797 | 06/03/2010 | 257018 | Low coolant light on                                   | Clean low coolant probe and test coolant ok                                                                                    | 447931 |
| 797 | 05/28/2010 | 256093 | No water in washers                                    | Refill washer bottle                                                                                                           | 446636 |
| 797 | 05/28/2010 | 256093 | Horn does not work                                     | Refit wire onto horn button                                                                                                    | 446636 |
| 797 | 05/28/2010 | 256093 | ABS light on                                           | Check ABS system and road test ok                                                                                              | 446636 |
| 797 | 05/22/2010 | 255410 | GLOBE 24V SW SINGLE CONTACT                            |                                                                                                                                | 445660 |
| 797 | 05/22/2010 | 255410 | OSF park light not working                             | Replace OSF park globe                                                                                                         | 445660 |
| 797 | 05/13/2010 | 253575 | Service                                                | Replace headlight switch knob                                                                                                  | 442744 |
| 797 | 05/13/2010 | 253575 | KNOB HEAD LIGHT SWITCH                                 |                                                                                                                                | 442744 |
| 797 | 05/11/2010 | 253809 | Boost pump to be replaced                              | Replace coolant boost pump                                                                                                     | 442926 |
| 797 | 05/11/2010 | 253809 | BRASS FITTING                                          |                                                                                                                                | 442926 |
| 797 | 05/11/2010 | 253809 | BOOSST PUMP HEATER                                     |                                                                                                                                | 442926 |
| 797 | 05/10/2010 | 253575 | Headlight knob loose                                   | Check headlight knob and order new one                                                                                         | 442744 |
| 797 | 05/10/2010 | 253575 | fit new air dryer canister nil stock at ser            | Order air dryer canisters                                                                                                      | 442744 |
| 797 | 05/10/2010 | 253575 | ABS light on                                           | Road test and check all wheel speed sensors. Could not fault                                                                   | 442744 |
| 797 | 05/10/2010 | 253575 | Sounds liken brakes catching. Squeeky noise            | Road test for noisy brakes. Check all linings. Could not fault                                                                 | 442744 |
| 797 | 05/08/2010 | 253542 | Height adjustment lever on seat broken.                | find & fit s/h height adjuster lever & cable                                                                                   | 442744 |
| 797 | 05/07/2010 | 253455 | A/C Belts us                                           | Fit second hand belts                                                                                                          | 442744 |
| 797 | 05/07/2010 | 253455 | GLOBE 24V 1.2W SWF SWITCH                              |                                                                                                                                | 442744 |
| 797 | 05/07/2010 | 253455 | switch lights n/w                                      | Replace switch light globes                                                                                                    | 442744 |
| 797 | 05/07/2010 | 253455 | Screw missing on upright pole at roof opp rear door    | Secure upright pole                                                                                                            | 442744 |
| 797 | 05/07/2010 | 253455 | refit pad sensor wire to N/S/f                         | Refit sensor to pads                                                                                                           | 442744 |
| 797 | 05/06/2010 | 253268 | Heater cold                                            | Check heater operation. Boost pump U/S. Order new pump                                                                         | 442744 |
| 797 | 05/06/2010 | 253246 | Filter Raycor                                          | Raycor filter                                                                                                                  | 442744 |
| 797 | 05/06/2010 | 253246 | Hydraulic Oil Torque Fluid 414                         | Hydraulic oil                                                                                                                  | 442744 |
| 797 | 05/06/2010 | 253246 | FILTER K124EB HYD COOLING FAN (49M1601)                | Hydraulic filter                                                                                                               | 442744 |
| 797 | 05/06/2010 | 253246 | TEXAMATIC 1888                                         | Power Steering oil                                                                                                             | 442744 |
| 797 | 05/06/2010 | 253246 | Filter P/S                                             | Power steering filter                                                                                                          | 442744 |
| 797 | 05/06/2010 | 253246 | Diff Oil Borate EP 460                                 | diff oil                                                                                                                       | 442744 |
| 797 | 05/06/2010 | 253246 |                                                        | Service as per check list                                                                                                      | 442744 |
| 797 | 05/06/2010 | 253246 | FILTER OIL GEARBOX DIFF K124                           | Filter Diff                                                                                                                    | 442744 |
| 797 | 05/06/2010 | 253246 | FILTER AIR DRYER SCANIA K124EB (T350W)                 | Filter Air Dryer                                                                                                               | 442744 |
| 797 | 05/06/2010 | 253246 |                                                        | A - Service & Bus Safety Inspection                                                                                            | 442744 |
| 797 | 05/06/2010 | 253246 |                                                        | Tension ALL Wheel Nuts to OEM Specs                                                                                            | 442744 |
| 797 | 05/04/2010 | 252923 | QWont start from the front                             | Check starting fault and could not fault                                                                                       | 441871 |
| 797 | 05/04/2010 | 252923 | ABS light came on                                      | Check ABS codes. None active and no fault found                                                                                | 441871 |
| 797 | 05/03/2010 | 252825 |                                                        | Inspect vehicle as per RSI Checklist                                                                                           | 441871 |
| 797 | 04/22/2010 | 251743 | AC coil clean and service                              | Clean out AC coils and AC service                                                                                              | 439846 |
| 797 | 04/21/2010 | 251573 |                                                        | CCTV Hard Drive Check                                                                                                          | 438792 |
| 797 | 04/21/2010 | 251573 |                                                        | Door Service                                                                                                                   | 438792 |
| 797 | 04/16/2010 | 251034 | A/C leaking water on floor of bus                      | Blow out AC drain tubes and test ok                                                                                            | 438792 |
| 797 | 03/26/2010 | 248916 | Seat adjuster not working                              | Replace seat adjuster knob                                                                                                     | 431949 |
| 797 | 03/26/2010 | 248916 | SEAT ADJUSTER KNOB ISRI                                |                                                                                                                                | 431949 |
| 797 | 03/03/2010 | 246307 | Service                                                | Transmission /check as per Check List                                                                                          | 428035 |
| 797 | 03/01/2010 | 360489 | MUDFLAPS                                               | Creditor #:VOL001 VOLGREN AUSTRALIA P/L P/O #:V110709 Receiving #:111246 Date :2012-07-13 BUS 797                              | 583344 |
| 797 | 03/01/2010 | 362490 | Direct Purchase - BODYWORK                             | Creditor #:VOL001 VOLGREN AUSTRALIA P/L P/O #:V110709 Receiving #:111246 Date :2012-07-13 N/S/F BUMPER BAR - BODY NO. VG1878   | 583344 |
| 797 | 01/28/2010 | 243427 |                                                        | Door Service                                                                                                                   | 420671 |
| 797 | 01/28/2010 | 243427 |                                                        | CCTV Hard Drive Check                                                                                                          | 420671 |

