T02-3

TOTAL INSPECTION SERVICES INC.
aka CUSTOM VALVE SOLUTIONS

Test and Inspection Report in Accordance with CSA B620

Facility Name:	Total Inspection Services Inc.	Work Order Number:	5279
Address:	7018 Stanley Drive PO Box 974	Date:	APRIL 29 2026
	Dawson Creek BC V1G 4H9	Transport Canada	
Telephone:	250-784-7966	Facility Registration #:	25-0847
Tank Owner:	SWAMP DONKEY OILFIELD SERVICES	331 Construction:	N/A
Address:	PO BOX 2394	Tank TCRN/MDIN:	6782
	DAWSON CREEK BC V1G4T8	Unit #:	261
Telephone:	250-219-8370		

Tank Serial #:	11609	Tank Spec:	TC / DOT 407
Manufacturer:	TREMCAR	Mfr. Date:	04/2013
Special Service:	N/A	Lined:	Yes ☐ No ☒
MAWP or Design Pressure:	25 PSI	Insulated:	Yes ☐ No ☒
Min Shell thickness:	3.277MM	Min Head Thickness:	3.429 MM
Cert. Date:	04/2013	Assembler:	TREMCAR
Gauge Calibration Checked:	Yes ☒ No ☐	Gauge #:	D3
Capacity:	☐ Total US gals	☒ Total Litres	☐ Total Imp gals
Compartments:	1. 31675	2.	3. 4.

TEST PERFORMED ☒**V – shall signify external inspection** ☒**K – shall signify leakage test**

EXTERNAL VISUAL INSPECTION "V"

	Complies	Reject	N/A	Complies on Retest
Data plate, present and legible	☒	☐	☐	☐
Shell & Heads, corrosion, abrasion, dents, overlay patches, leaks etc.	☒	☐	☐	☐
Structural members, outriggers, cross members, etc.	☒	☐	☐	☐
Piping and valves for leakage, damage, corrosion	☐	☒	☐	☒
Remote closures, emergency shut off decals, thermal devices	☐	☒	☐	☒
Hoses for defects, identification and test dates	☒	☐	☐	☐
Gaskets on full opening rear heads for damage or cuts	☐	☐	☒	☐
Tank attachments to frame or running gear	☒	☐	☐	☐
Ladders, walkways, etc.	☒	☐	☐	☐
Fill covers, manways and closure devices	☒	☐	☐	☐
Relief valves and vents (replace or test if tank in service where lading corrosive to relieve device)	☒	☐	☐	☐

Accident damage protection	☒	☐	☐	☐

LEAKAGE TEST "K"

Test Pressure: 20 PSI *(80% of MAWP Min.)* Test Medium: WATER Hold Time: 5 MIN

Item Tested	Pass	Fail	Complies on Retest	Item Tested	Pass	Fail	Complies on Retest
Compartment # 1	☒	☐	☐	Compartment # 1 Piping	☒	☐	☐
Compartment # 2	☐	☐	☐	Compartment # 2 Piping	☐	☐	☐
Compartment # 3	☐	☐	☐	Compartment # 3 Piping	☐	☐	☐
Compartment # 4	☐	☐	☐	Compartment # 4 Piping	☐	☐	☐

Defects found, location and corrective action *(use additional sheets if necessary)*

RH FRONT GATE VALVE LEAKING
LABEL ESD
RH FRONT VALVE LEAKING

Defects corrected and released ☒ Yes ☐ No

Tank successfully retested after repair ☒ Yes ☐ No

Tank Disposition:

- ☐ Returned to service as no defects or damage was discovered
- ☒ Returned to service after retest
- ☐ Removed from service

Tank Marking: 04 26 VK 847 Month, year and service symbol (MMYY XXXXXX 000) after all defects are corrected.

Tank markings applied ☒ Yes ☐ No

Tank Tester Name: Gary Grant **Signature:**  **Date:** APRIL 29 2026