

Truck ID	T14	
Registration	SB40NR	
Description	2014 Volvo FH16	
Date	Odometer	Service
7/21/2025		
6/18/2025	1,763,000	B
8/15/2024		
10/22/2024	1,720,776	
7/31/2024	1,719,490	
5/19/2024	1,704,844	
5/7/2024	1,700,000	B
5/4/2024	1,710,000	
4/3/2024		
3/28/2024		A
3/21/2024		A
3/16/2024	1,674,031	
2/12/2024		
2/9/2024	1,663,000	B
2/2/2024		A
11/8/2023	1,630,000	B
8/25/2023	1,601,000	B
8/17/2023		
6/21/2023		
6/15/2023	1,580,950	A
6/13/2023		
5/16/2023	1,569,700	B
4/28/2023		
4/13/2023		A
3/16/2023		
2/27/2023	1,539,446	
2/15/2023	1,536,289	
1/25/2023	1,530,000	B
12/8/2022		

11/6/2022		
11/2/2022		
11/2/2022	1,498,000	B
10/24/2022	1,494,665	
10/14/2022		
10/13/2022		
10/11/2022	1,491,277	
9/29/2022		
8/18/2022	1,464,100	
8/4/2022	1,461,768	
7/29/2022	1,461,762	B
7/4/2022		
6/20/2022		A
5/23/2022	1,428,500	B
5/9/2022	1,418,062	
4/21/2022	1,416,135	
4/21/2022	1,416,135	
4/5/2022	1,412,746	
4/5/2022	1,412,746	
3/25/2022		A
3/8/2022		
3/2/2022		A
2/25/2022		A
2/8/2022	1,382,550	B
12/23/2021		
12/10/2021	1,362,910	
11/18/2021	1,352,000	B
11/8/2021		A
10/19/2021		A
9/13/2021	1,324,132	
8/27/2021	1,316,500	B
7/16/2021	1,301,163	

6/30/2021	130,000	
5/10/2021		A
4/30/2021	1,259,328	
4/19/2021	1,271,800	B
3/31/2021		A
1/29/2021	1,235,000	B
1/22/2021		
1/20/2021	2,230,500	
1/16/2021		A
12/23/2020		A
12/4/2020		A
10/22/2020		A
10/22/2020		
10/12/2020	1,183,500	B
10/7/2020	1,181,218	
10/6/2020	1,180,728	
9/5/2020		A
8/21/2020		A
8/14/2020	1,152,000	A
7/31/2020	1,145,840	B
7/5/2020	1,134,000	
6/25/2020		A
5/13/2020	1,109,800	B
5/7/2020		
3/27/2020	1,090,000	
3/2/2020	1,079,000	B
2/14/2020		A
2/10/2020	1,067,539	
1/22/2020	1,230,501	
1/20/2020		A
1/10/2020		A
12/23/2019	1,056,000	B
12/9/2019		
12/9/2019		A

11/18/2019		A
11/12/2019		
11/8/2019	1,028,385	
10/26/2019	1,269,000	
10/18/2019	1,022,500	B
9/23/2019		A
9/7/2019	1,000,859	
9/2/2019	996,000	
8/31/2019		
8/27/2019		A
8/23/2019		
8/14/2019	992,930	
8/13/2019	992,126	
8/12/2019		A
7/31/2019	986,500	B
7/12/2019	977,455	
7/2/2019	972,178	A
6/27/2019	972,000	
6/11/2019		A
5/14/2019	954,787	
5/3/2019		A
4/29/2019	948,047	
4/26/2019		
4/5/2019		
3/28/2019	932,285	B
2/13/2019		A
1/11/2019		
1/10/2019	908,185	
1/7/2019		A
12/19/2018		
12/10/2018	903,500	B
10/16/2018	873,500	B
10/3/2018	866,310	B
8/19/2018	839,943	B
7/3/2018	820,500	B

6/26/2018		
6/26/2018	817,500	A
5/18/2018	7	A
5/16/2018		
5/4/2018	791,000	B
4/27/2018		A
4/20/2018	784,688	
4/13/2018		A

Notes/Repairs
Replaced air drier & South Central Trucks re-programmed air drier & repaired wiring harness
Truckmech - Replaced stop plate in gear box, replaced harness daignosed possible brake ECU issue
South Central - Replaced TECU, programmed and calibrated gearbox & clutch, replace EMS software
Truckmech - remove & pressure clean adblue tank & lines, replace dosage valve, PWM valve replaced on gearbox, air
Southern Truck Ctr, Queyanbeyan - replace alternator and water pump belts
Replace compressor & air drier filter, 2 new steer tyres & 8 new drive tyres, replace RHS front drive wheel bearings
Batteries Direct Ingleburn NSW - 2 new batteries
Replace tensioners & idler
Replace turbo & intercooler hoses
Truckmech - Computer analysis
Heavylec - A/C repair
Replace boost control valve
Replace exhaust brake cylinder
Heavylec - Replace EBS speed sensor re ABS faults
Replace pinion seal on diff
2 new steer tyres, new hub caps on drive
Truckmech - Valve & wastegate adjustment, check & clear fault codes
Active Batteries - 2 new batteries
New exhaust manifold
New drive tyres - 4 across rear, fixed mudguards
Heavylec - A/C repair - replaced compressor & TX valve
South Central - Rectify engine light on dash - wire rubbed through on engine air filter sensor
Rotated all tyres - steer and drive

KMA Engineering , Windradyne NSW - repair main shaft of wiper arm
Complete Wingscreens - new windscreen
South Central Trucks - replace sensor to rectify electrical fault
Replace all air bags x 8, replace torsion bar RHS rear drive
Adel Ind Bandag - trial new steer tyres
South Central Trucks - Replace engine fan
Replace brake pads rear axle, fit 4 new drive tyres on rear, rotate front axle tyres
South Central Trucks - Rectify body builder codes, change idle shut down
Truckmech - computer code - low coolant rectified, truck brake and body builder fault, believe faults linked and caused by wiring issue or failed ECU. Adjusted idle shut down.
Full service, rotate steer tyres, Annual Inspection
New drive tyres from Tyre Ace Chaoyang 11R22.5 CM335
Repair guards
Replace starter motor
Truckmech - replace clutch, replace fan belt, replace steer brakes and re-bush calipers
Truckmech - Gear box diagnosis
Truckmech - Gear box diagnosis
Truckmech - Replace PWM valve re gearbox fault
Truckmech - Replace PWM valve re gearbox fault
Replace RHS rear cab air bag; adjust turn table
Rebuild idler pulley and belt tensioner; repaired wiring loom; new coolant; new power steering hose from reservoir & filter; 40 litres coolant
Replace power steering hose & cap off washer bottle
Repair LHS mud flap & safety sign
New sun visor, mirror cover, fascia board front of truck
Replace RH spring hanger bushes, change trans oil, rotate steer tyres
South Central Trucks - Supply and fit parkbrake door alarm & Air dryer filter APM filter replaced
New air cleaners inner/outer, 2 new cab stabiliser shockers
New air drier filter
8 new drive tyres, front right drive replace wheel bearings, change diff oils
Viking Mechanical - Engine derate problem - replaced NOX sensor & cleared faults, completed valve adjustment, NOTE SLAVE CYLINDER NEEDS REPLACING

Heavylec - look for issue with nox codes, inspect wiring to chassis power unit & nox sensor
Rotate steer tyres, replace spring hanger bushes LHS, replace stabiliser links, repair RHS headlight panel, repair windscreen washer bottle, repair power steering hose
Complete Alignments - wheel align front and rear
Repair drive tyre, replace fog light globes
New flex pipe from motor to exhaust pipe
South Central Trucks - clear codes
2 new steer tyres
Replaced LHS headlight globe - low beam
Replace coolant pipe
New windscreen and wiper blades
Gawler Windscreens - new windscreen
Volvo Commercial Brisbane - Replace with correct alternator & replaced one battery
Anderson Truck & Tractor, Goondiwindi - replace alternator & one battery
New drive tyres
Full service
Elite Heavy Equip - Rectify engine derate - Replaced adblue pump and filter
Put fridge back in truck - fixed slides
Replace LH window
Replace air dryer filter
Elite Mining - Remove and replace faulty engine fan
New cab bag on RH back of cab
Elite Mining - Full engine rebuild - replaced pistons, liners, cylinder head and all bearings
Elite Heavy Equip - Valve set/tune up
New header tank
2 new steer tyres, new air filter
Actice Batteries - 2 new batteries
New hoses and fitting on power steering

New RH indicator
Elite Mining - Check ABS fault, found software mismatch b/w abs and vehicle ecu, truck requires re-programming
Volvo Sydney - replace starter motor
Elite Mining - Rectify ABS issue, diagnosed as faulty wheel speed sensor - removed and replaced, recalibrated
Johnson's Mildura - break down - replace bottom boost hose
Elite Mining Mechanical - Replace catalytic converter (muffler) as supplied by SCT
South Central Trucks - supply new muffler/silencer
New exhaust manifold, Re-bush both front calipers
Gunther Engineering - face off manifold
Southern Truck Centre, Queanbeyan - breakdown, replace turbocharger
Johnson's Mildura - rectify adblue issues
Rotate steer tyres
Southern Truck Centre, Queanbeyan - breakdown, replace coolant pipe
New drive tyres
Elite Mining Mechanical - Valve set
Volvo Brisbane - Replace power steering pump
Chris Barron - welded up RH step
Sydey call out - Batteries replaced
New air dryer filter
Gawler Windscreens - new windscreen
Replaced LH step and cover
*new batteries x 2
South Central Trucks - replace voltage converter
Cavpower - Battery call out - Moomba
New air cleaners
New cab shocker RH front and replaced LH mirror
New steer tyres & rims (super singles)
1 new fuel bowl water separator, change front diff oil

Active batteries - 2 new batteries
8 new drive tyres
New steer tyres
Gawler Windscreens - new windscreen
New bottom intercooler hose & new cab air bag RHS
New suzi coils, new fuel breather at back of cab
Complete Alignments - wheel alignment