Vehicle History Summary

Fleet #	DIV-017
Registration	DIV-017
Make	Kenworth
Model	T409 SAR
VIN / Chassis #	6F5000000EA453264
Build Date	02/09/2013

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
R-34848	22/03/2021	975709		Brakes, Brakes Trailer Brakes	1. Replaced brake shoes on axle one right hand side of dolly. 2. Replaced brake shoes on axle two left hand side of dolly torqued all wheel ends on assembly.	Blake kehoe, Cameron Tosswill, Daniel Phelps, Lucas Walsh
S-33736	22/03/2021	975709	0	A - Fortnighly/5000km	Completed "A" service.	Blake kehoe, Cameron Tosswill, Daniel Phelps, Lucas Walsh
R-34868	20/03/2021			Trailer	Fitted new step to trailer tailgate.	Steelfab Mobile Welding
S-33679	16/03/2021	973177	0	D - Brakes	Checked and adjusted brakes.	Cameron Woodgate
S-33579	10/03/2021	907299	0	A - Fortnighly/5000km	Completed "A" service.	Brad Williams, Cameron Woodgate, Ricky Eddy
S-33478	01/03/2021	965924	0	D - Brakes	Checked and adjusted brakes.	Rhys Neal
S-33388	24/02/2021	963943	0	A - Fortnighly/5000km	Completed A service	Mat Norton
R-34573	20/02/2021	962195		Tow Coupling.	Replaced plastic plate in ring feeder.	Matt Norton
R-34594	20/02/2021	962195		Suspension	Replaced sway bar bushes	Mat Norton
S-33339	16/02/2021	960284		D - Brakes	Checked and ajusted brakes.	Rhys Cranston

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
R-34503	16/02/2021	960284		Trailer	Replaced brake shoes and drum on 4th axle LHS	Rhys Cranston
R-34502	16/02/2021	960284		Engine	Replaced engine air filters.	Ricky Eddy
S-33366	16/02/2021	960284		B - 20 000km	Completed B service.	Rhys Cranston
S-33211	09/02/2021	957517		A - Fortnighly/5000km	Completed "A" service.	Brodie Connor
S-33148	01/02/2021	954139		D - Brakes	Checked and adjusted brakes.	Brett Waters
R-34281	27/01/2021	952192		Hydraulics	Replaced female Tema fitting on truck. Replaced male fitting on trailer hose.	Brad Williams
S-33052	25/01/2021	951754		A - Fortnighly/5000km	Completed "A" service.	Lachlan Latham
S-32965	21/01/2021	950710		D - Brakes	Checked & adjusted brakes	Brodie Connor
R-34138	14/01/2021	947843		Engine	Replaced oil filler cap on front of engine. Checked oil level and cleaned engine bay area.	Cameron Woodgate
R-34140	14/01/2021	947843		Clutch	Adjusted clutch	Rhys Cranston
R-34122	13/01/2021	947246		Electrical	Replaced H4 headlight housing. Replaced RHS indicator bulb. Replaced 2nd clearance light LHS of truck.	Cameron Woodgate
S-32854	13/01/2021	947246		A - Fortnighly/5000km	Completed "A" service.	Rhys Cranston
R-34122	13/01/2021	947246		Brakes	Replace brake shoes LHS 3rd axle.	Rhys Cranston
R-34127	13/01/2021	947246		Engine	Connected Davie and found fault code for adblue level low. Replaced blown dash globe for ad blue gauge and filledadblue tank and all tested ok.	Daniel Phelps
R-34127	13/01/2021	947246		Electrical	Inspected and replaced a number of failed dash globes.	Daniel Phelps
R-34079	08/01/2021	945377		Suspension	Replaced leaking air bag on 2nd axle LHS	Brad Williams
R-34069	07/01/2021	944442		Trailer	Repaired trailer clearance light wiring at black box of dolly	Brett Waters
S-32803	07/01/2021	944888		D - Brakes	Checked and adjusted brakes.	Brad Williams
R-34069	06/01/2021	944442		Engine	Inspected and found fault code for after treatment. Carried out tests and found dosing module to be faulty. Replaced doing module, cleared faults and tested all ok.	Brett Waters

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
R-34069	06/01/2021	944442		Driveline	Replaced front diff breather .	Brett Waters
S-32694	21/12/2020	942089		A - Fortnighly/5000km	Completed "A" service.	Lachlan Latham
R-33950	21/12/2020	942089		Trailer	Tightened loose grain chute.	Lachlan Latham
R-33950	21/12/2020	942089		Electrical	Repaired multiple sections of faulty wiring along LHS of trailer Replaced clearance light 2nd from rear LHS.	Lachlan Latham
R-33950	21/12/2020	942089		Cab	Replaced missing headlight surround.	Lachlan Latham
R-33952	21/12/2020	942089		Driveline	Adjusted ride height on trailer.	Lachlan Latham
R-33927	18/12/2020	941684		Electrical	Inspected wiring for RHS trailer indicator. Found rubbed through wiring in dolly light bar. Repaired wiring and tested all ok.	Brad Williams
R-33928	18/12/2020	941684		Air System	Inspected for air leaks on truck unable to loacate any.	Brad Williams
R-33925	18/12/2020	941684		Body	Replaced missing bonnet hinge mounting bolts.	Mat Norton
S-32644	14/12/2020	938912		D - Brakes	Checked and adjusted brakes.	Mat Norton
R-33870	14/12/2020	938912		Suspension	Replaced blown air bag RHS 3rd axle and LHS 4th axle on trailer.	Brett Waters
R-33808	08/12/2020	935601		Brakes	Reline 2nd axle RHS of trailer.	Daniel Phelps
S-32540	08/12/2020	935601		A - Fortnighly/5000km	Completed "A" service.	Daniel Phelps
S-32487	04/12/2020	934185		D - Brakes	Checked and adjusted brakes.	Josh Mills
S-32382	26/11/2020	929947		A - Fortnighly/5000km	Completed "A" service.	Josh Mills
R-33648	20/11/2020	927865		Air conditioning_heater	Removed and replaced failed blower fan assy .	Mat Norton
R-33615	19/11/2020	927131		Steering	Replaced hub caps and gaskets, Replaced all bolts and torqued to spec. Refilled front hubs with oil.	Rhys Neal
R-33655	19/11/2020	927131		Air conditioning_heater	Recovered 1.1kg of R134a from system. Replaced blocked evaporator and heater core. Reassembled , replaced drier and vack down system. Recharged with R134A and tested operation = all ok.	Daniel Phelps
S-32338	17/11/2020	927013		D - Brakes	Checked and adjusted brakes	Brad Williams

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
R-33601	17/11/2020	927013		Trailer	Disassembled wheel hub RHS axle due to leaking inner hub seal on trailer. Cleaned and inspected bearings and brake components. Replaced inner hub seal and adjusted to specification. Torqued wheel nuts	Brad Williams
R-33601	17/11/2020	927013		Steering	Replacd inner hub seals and bearings on both sides of steer axle. Cleaned up brake shoes , drums and re-used.	Brad Williams
R-33548	12/11/2020	924602		Electrical	Repaired rubbed wires in light bar for clearance and park lights.	Brodie Connor
S-32218	11/11/2020	923885		A - Fortnighly/5000km	Completed "A" service.	Brodie Connor
S-32117	04/11/2020	920495		D - Brakes	Checked and adjusted brakes.	Rhys Cranston
S-32196	04/11/2020	920495		B - 20 000km	Completed B service.	Rhys Cranston
R-33466	04/11/2020	920495		Trailer	Repaired rubbed wires to rhs dolly light bar.	Brett Waters
I-869	04/11/2020	920464		COR	Roadworthy inspection and brake test.	Rhys Cranston
R-33416	30/10/2020	917985		Suspension	Replaced air bag RHS 2nd drive.	Cameron Woodgate
S-32058	29/10/2020	917548		A - Fortnighly/5000km	Carried out A service	Josh Mills
R-33397	29/10/2020	917548		Trailer	Carried out reline on 1st axle LHS trailer	Josh Mills
S-31957	23/10/2020	915217		D - Brakes	Checked and adjusted brakes	Michael Pratten
S-31870	13/10/2020	909083		A - Fortnighly/5000km	Carried out A service	Mat Norton
R-33189	06/10/2020	905805		Trailer	Replaced brake shoes, drum and air bag on 1st axle LHS of trailer after brake drum exploded and caused damge.	Josh Mills
S-31832	06/10/2020	905805		D - Brakes	Checked and adjusted brakes.	Daniel Phelps
R-33193	06/10/2020	905805		Driveline	Replaced inner hub seal 2nd axle RHS . Replaced brake shoes , drum and wheel bearings.	Daniel Phelps
T-5066	01/10/2020	904180		New	fitted 4 x Doublecoin RLB1 11R22.5 to axle 2 LH & RH Sides	Daniel Graham
R-33147	29/09/2020	902736		Electrical	Replaced roof light	Rhys Cranston
R-33148	29/09/2020	902736		Suspension	Replaced leaking air bag RHS axle 2	Rhys Cranston

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
R-33137	28/09/2020	902161		Electrical	Replaced both LHS and RHS headlight lens / casing.	Ricky Eddy
S-31727	28/09/2020	902161		A - Fortnighly/5000km	Completed 'A' service.	Brett Waters
R-33125	25/09/2020	901563		Fuel System	Travelled to truck , fillied 100Ltrs of fuel into tank as truck had run out of fuel. Primed fuel system and started.	Michael Pratten
S-31680	23/09/2020	899893		D - Brakes	Checked and adjusted brakes.	Michael Pratten
R-33085	23/09/2020	899893		Electrical	Replaced blown bulb in RHS front indicator.	Lachlan Latham
R-33088	23/09/2020	899893		Air System	Replaced air filters, replaced bonnet pads LHS.	Michael Pratten
R-33085	23/09/2020	899893		Cab	Replaced wiper blades.	Lachlan Latham
R-33026	21/09/2020	897681		Trailer	Replaced leaking air bag on 3rd axle LHS	Josh Mills
R-32987	16/09/2020	895588		Electrical	Locate and repair shourt to ground fault at rear light bar for RHS indicator. Replaced LED reverse light insert.	Mat Norton
R-32985	16/09/2020	895588		Electrical	Checked fuses for 12V power socket , fuse blown. Replaced fuse and checked both power sockets all ok.	Cameron Woodgate
S-31570	16/09/2020	895587		A - Fortnighly/5000km	Completed 'A' Service.	Brad Williams
R-32961	15/09/2020	894804		Steering	Tightened both fittings on power steer resevior.	Michael Pratten
R-32961	15/09/2020	894804		Cab	Replaced both cab shocks.	Michael Pratten
R-32961	15/09/2020	894804		Hydraulics	Replaced hydraulic pump suction hose.	Michael Pratten
R-32961	15/09/2020	894804		Electrical	Wired in power socket for fridge under dash. Rewired UHF and camera in top console.	Michael Pratten
R-32961	15/09/2020	894804		Driveline	Replaced torque rod bushes on both drive axles.	Michael Pratten
R-32961	15/09/2020	894804		Air conditioning_heater	Removed Complete HVAC assembly , Replaced tumbler , AC harness and broken ducting. Reinstalled HVAC unit. Replaced reciever drier and vack down system. Recharged with R134A and tested operation. Vent temp 6.3'C @ 15'C ambient.	Michael Pratten
R-32892	08/09/2020	894208		Tailgate	Removed tailgate seal , cleaned surface and installed new seal.	Daniel Phelps

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
R-32892	08/09/2020	894208		Electrical	Inspected 12V socket, found to had fallen apart, located all parts and re assembled- all tested ok. Inpsected top console UHF , has power source issue in loom will need further diagnosis.	Daniel Phelps
R-32892	08/09/2020	894208		Air conditioning_heater	Inspected A/C found preasure switch had failed . Replaced and all tested ok. Repaired air vent actuator tumber as it had dislodged and not allowing door to move.	Daniel Phelps
S-31512	08/09/2020	894208		D - Brakes	Checked and adjusted brakes.	Brodie Connor
S-31411	31/08/2020	889635		A - Fortnighly/5000km	Completed 'A' service.	Josh Mills
R-32767	27/08/2020	888358		Electrical	Replaced blown globe and repaired wiring at back of headlight.	Rhys Cranston
S-31351	27/08/2020	888358		D - Brakes	Checked and adjusted brakes .	Rhys Cranston
R-32711	24/08/2020	886906		Trailer	Replaced broken trailer tarp cable.	Brad Williams
R-32667	19/08/2020	885861		Electrical	Repaired wiring behind RH rear blinker on trailer.	Michael Pratten
R-32640	18/08/2020	885400		Electrical	Replaced clearance light on RHS of truck. Replace both number plate lights as shrouds broken.	Cameron Woodgate
S-31233	18/08/2020	885400		A - Fortnighly/5000km	Completed 'A' service.	Brad Williams
T-5033	18/08/2020	885401		New	Fitted 4 x Doublecoin RLB1 11R22.5 to axle 3	Daniel Graham
R-32601	14/08/2020	883296		Steering	Replaced leaking power steering resevoir.	Brodie Connor
S-31159	12/08/2020	882540		D - Brakes	Checked and adjusted brakes	Josh Mills
S-31137	05/08/2020	879934		B - 20 000km	Completed 40,000km B service	Josh Mills
R-32496	05/08/2020	879934		Tarps_dust covers	Replaced truck tarp cable	Brett Waters
R-32478	04/08/2020	879276		Air conditioning_heater	Checked fuses and relays , had voltage at blower fan but fan not working. Replaced fan and resistor , all ok. **Suggest changing wiring loom due to high number of fans and resistors being fitted. Parts ordered**	Rhys Cranston
S-31081	03/08/2020	878409		A - Fortnighly/5000km	Completed 'A' service.	Josh Mills
R-32464	03/08/2020	878409		Exhaust	Replaced broken flanged exhaust flex.	Josh Mills
R-32467	03/08/2020	878409		Steering	Straightened steering wheel	Rhys Cranston

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
R-32452	01/08/2020	877547		Steering	Remove Cummins style steering box and fit paccar type.Refill power steering resevior and centre steering wheel and test drove. Ok.	Mat Norton
S-31033	29/07/2020	875466		D - Brakes	Checked and adjusted brakes.	Michael Pratten
R-32403	28/07/2020	875845		Steering	Replaced steering box due to stering wheel going out of alignment numerous times. Bled out air as per procedure.	Josh Mills
R-32357	23/07/2020	873565		Clutch	Completed clutch adjustment.	Mat Norton
R-32358	23/07/2020	873565		Trailer	Removed and replaced broken mudguard axle 1 LHS of trailer	Lachlan Latham
R-32357	23/07/2020	873565		Cab	Removed weather shields as per driver request (stored in truck pigeon hole).	Mat Norton
S-30952	21/07/2020	872457		A - Fortnighly/5000km	Completed 'A' service.	Brad Williams
R-32350	21/07/2020	872457		Electrical	Replaced cracked headlight inserts and blown bulbs. Removed and replaced clearance lights on RHS front of truck bin.	Mat Norton
R-32327	20/07/2020	871603		Steering	Remove steering shaft from steering box and rotate to realign steering wheel.	Mat Norton
R-32285	17/07/2020	870746		Air conditioning_heater	Recovered A/C gas for engine removal. Removed and replaced reciever drier , cab filter and cab filter retainer. Vack down and recharge with R134A. Check operation , vent temp 4.6'C at 12'C .	Brad Williams
R-32293	17/07/2020	870746		Cab	Replaced wiper blades	Cameron Toswill
R-32286	17/07/2020	870746		Engine	Fitted rebuilt engine out of DIV-033 Replaced 2 x hump hoses Replaced Clutch assy. Replaced A/C belt. Replaced front and rear engine mounts	Michael Pratten
R-32298	17/07/2020	870750		Body	Weld cracks in hoist well and tailgate. Fitted grain scraper Welded cracks in trailer tailgate	Luke Netrval
S-30850	17/07/2020	870746		D - Brakes	Checked and adjusted brakes.	Michael Pratten
S-30768	06/07/2020	869370		A - Fortnighly/5000km	Completed 'A' service.	Daniel Phelps

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
R-32200	06/07/2020	869371		Engine	Connected diagnostic computer and found fault code P0528 "fan speed too low". Troubleshoot fault and found electric fan hub had failed. Removed and replaced fan hub and carried out slippage test. Tested ok. Fitted new fan belt.	Daniel Phelps
S-30711	03/07/2020	869086		D - Brakes	Checked and adjusted brakes.	Brodie Connor
S-30594	24/06/2020	864793		A - Fortnighly/5000km	Completed 'A' service.	Lachlan Latham
R-32019	19/06/2020	862642		Suspension	Removed and replaced leaking air bag on left side of axle 3 on truck.	Lachlan Latham
R-32003	18/06/2020	861116		Trailer	Checked trailer tail light wiring. All ok. Removed and replaced failed tail light insert on trailer.	Lachlan Latham
R-32003	18/06/2020	861116		Cooling system	Removed left side lower body panel from cab. Removed and replaced leaking coolant hose behind cylinder head on the engine, filled cooling system up and test drove truck to obtain normal operating temperature. Rechecked for leaks to confirm repair. Refitted lower cab panel.	Lachlan Latham
R-32003	18/06/2020	861116		Engine	Removed engine belts and inspected all components. Water pump has minimal movement in bearing. Removed tensioner pulley and inspected. Senior mechanic on shift also inspected. Refitted tensioner and belts. Noise still present. **Further diagnosis needed.**	Lachlan Latham
R-31998	18/06/2020	861606		Cooling system	Carried out temporary repair on leaking coolant hose at left side rear of engine. Scheduled for night shift to carry out repair.	Rhys Cranston
R-32003	18/06/2020	861116		Electrical	Removed and replaced blown globe in left side front light on truck.	Lachlan Latham
R-32003	18/06/2020	861116		Air System	Inspected all air lines/hoses near ring feeder. Fitted new clamp to 1 x hose and tightened.	Lachlan Latham
R-32274	17/06/2020	860644		Steering	Completed wheel alignment	Align Right
S-30543	16/06/2020	861008		D - Brakes	Checked and adjusted brakes.	Lachlan Latham
R-31911	11/06/2020	859180		Air System	Removed and replaced leaking air line manifolds/bulk head fittings on firewall of truck.	Michael Pratten

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
R-31911	11/06/2020	859180		Steering	Removed and replaced left side stub axle on axle 1 on truck. Removed and replaced left and right side kingpin and bush assemblies on axle 1 on truck. Replaced tie rod assembly.	Michael Pratten
R-31911	11/06/2020	859180			Removed and replaced worn ring feeder pin. Removed and replaced worn suppression plate on ring feeder.	Michael Pratten
R-31911	11/06/2020	859180		Electrical	Removed and replaced coolant level sensor.	Michael Pratten
S-30454	11/06/2020	859180		A - Fortnighly/5000km	Completed 'A' service. Added 2.0 litres of coolant. Added 3.0 litres of engine oil.	Michael Pratten
R-31911	11/06/2020	859180		Engine	Removed and replaced cracked section of exhaust manifold. Replaced all exhaust manifold gaskets and bolts. Replaced flex pipe V-band clamp between turbo and piping.	Michael Pratten
R-31911	11/06/2020	859180		Driveline	Removed and replaced leaking front diff input shaft seal. Replaced front diff pinion nut and washer.	Michael Pratten
R-31911	11/06/2020	859180		Trailer	Relined brakes on left side of axle 2 on trailer.	Michael Pratten
R-31911	11/06/2020	859180		Brakes	Relined brakes on left and right sides of axle 1, replaced S-cam bushes and seals, replaced left side S-cam, replaced all wheel bearings and seals also on axle 1 on truck, replaced left and right side brake drums and slack adjusters at time of repair.	Michael Pratten
R-31911	11/06/2020	859180		Exhaust	Tightened loose retaining bolts on turbo dump pipe mounting bracket.	Michael Pratten
T-4983	10/06/2020	859180		New	Fitted 2 x new 295/80R22.5 Bridgestone R168 tyres onto axle 1 left and right sides.	Daniel Graham
S-30387	01/06/2020	856748		D - Brakes	Checked and adjusted brakes.	Lachlan Latham
S-30276	01/06/2020	856748		A - Fortnighly/5000km	Completed 'A' service. Added 5.0 litres of engine oil.	Lachlan Latham
R-31816	01/06/2020	856748		Trailer	Removed and replaced damaged wiring on draw bar of trailer.	Cameron Toswill
S-30204	19/05/2020	851089		D - Brakes	Checked and adjusted brakes.	Daniel Phelps
R-31733	19/05/2020	851089		Body	Tightened grain locks on truck and trailer bodies.	Daniel Phelps

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
R-31733	19/05/2020	851089		Engine	Tested engine brake with diagnostic computer and found leak after the actuator. Removed and replaced leaking copper seals and retested to confirm engine brake operation.	Daniel Phelps
R-31655	15/05/2020	849748		Trailer	Removed and replaced right side rear clearance light and right side reverse light on trailer.	Rhys Neal
R-31654	15/05/2020	849748		Trailer	Removed and replaced shock absorbers on left side of axle 1, and right side of axle 3 on trailer.	Cameron Woodgate
S-30099	12/05/2020	847573		A - Fortnighly/5000km	Completed 'A' service.	Brett Waters
S-30041	04/05/2020	843352		D - Brakes	Checked and adjusted brakes.	Lachlan Latham
R-31480	30/04/2020	842056		Trailer	Removed and replaced broken draw bar leg retaining latch on trailer.	Brodie Connor
S-30007	28/04/2020	840741		B - 20 000km	Completed 'B' service.	Lachlan Latham
S-29945	28/04/2020	840741		A - Fortnighly/5000km	Completed 'A' service.	Lachlan Latham
R-31401	22/04/2020	837605		Trailer	Relined brakes on left side of axle 2 on trailer. Re-adjusted brake.	Josh Mills
S-29893	22/04/2020	837605		D - Brakes	Checked and adjusted brakes.	Josh Mills
S-29786	14/04/2020	832911		A - Fortnighly/5000km	Completed 'A' service. Added 5.0 litres of engine oil.	Brodie Connor
S-29744	08/04/2020	831609		D - Brakes	Checked and adjusted brakes.	Lachlan Latham
R-31232	08/04/2020	831609		Trailer	Relined brakes on right side of axle 1.	Lachlan Latham
S-29631	01/04/2020	827838		A - Fortnighly/5000km	Completed 'A' service.	Lachlan Latham
S-29568	24/03/2020	822989		D - Brakes	Checked and adjusted brakes.	Daniel Phelps
R-31065	24/03/2020	822989		Clutch	Carried out clutch adjustment.	Daniel Phelps
R-31066	24/03/2020	822989		Body	Greased tailgate hinges.	Ricky Eddy
R-31040	20/03/2020	820786		Brakes	Removed and replaced leaking hose on right side brake booster on axle 1 on truck.	Brett Waters
R-31044	20/03/2020	820786		Air System	Repaired rubbed air line on firewall.	Brett Waters
R-31040	20/03/2020	820786		Trailer	Removed and replaced leaking air bag on axle 4 RHS trailer.	Brett Waters

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
R-31043	20/03/2020	820786		Cab	Replaced blown fuse for 12 volt accessory plug and for UHF in roof console.	Brett Waters
R-31040	20/03/2020	820786		Hydraulics	Removed and resealed leaking hydraulic coupling and elbow on rear of truck. Refitted and cleaned oil residue from fittings and hoses.	Brett Waters
R-31043	20/03/2020	820786		Engine	Removed and replaced air filters.	Lachlan Latham
S-29468	18/03/2020	819291		A - Fortnighly/5000km	Completed A service	Lachlan Latham
S-29403	09/03/2020	813449		D - Brakes	Checked and adjusted brakes.	Josh Mills
R-30911	05/03/2020	812432		Engine	Checked for engine oil leak. Found rocker cover gasket leaking. Removed and replaced rocker cover gasket, re-assembled and run engine. Rechecked for oil leak to confirm repair.	Mat Norton
R-30911	05/03/2020	812432		Cooling system	Removed leaking electric heater tap from firewall and retro fitted updated Paccar part. Topped up cooling system, run engine and rechecked for coolant leak.	Mat Norton
S-29304	04/03/2020	812433		A - Fortnighly/5000km	Completed 'A' service.	Josh Mills
R-30851	04/03/2020	812432		Hydraulics	Removed and replaced leaking male and female Tema hydraulic fittings at rear of truck.	Mat Norton
R-30840	03/03/2020	812432		Air conditioning_heater	Checked all fuses/circuit breakers etc for heater fan. Checked power supply at blower motor. Removed and replaced blower motor and heater fan resistor. Checked all heater/air con controls for correct operation.	Mat Norton
R-30840	03/03/2020	812432		Steering	Removed and replaced power steering pump. Resealed all power steering pump and fuel transfer pump fittings. Refilled steering reservoir. Bled fuel and steering systems. Operated and checked for leaks to confirm repair.	Mat Norton
S-29236	27/02/2020	811307		D - Brakes	Checked and adjusted brakes.	Brodie Connor
R-30731	20/02/2020	808120		Electrical	Removed and replaced inoperative clearance light on left side of truck.	Nathan George
R-30733	20/02/2020	808120		Trailer	Fitted new chassis wear plate on right side of trailer as required.	Nathan George

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
R-30732	20/02/2020	808120		Electrical	Disassembled electrical junction box under truck, cleaned dirt and corrosion from terminals and box and reassembled. Checked operation of lights to confirm repair.	Cameron Woodgate
R-30734	20/02/2020	808120		Trailer	Removed and replaced draw bar pivot pins and bushes.	Nathan George
R-30737	20/02/2020	808120		Cooling system	Tested 'low coolant' level sensor. Found to be faulty. Removed and replaced sensor.	Rhys Cranston
R-30690	18/02/2020	806740		Air conditioning_heater	Checked air con system. All controls working correctly. Removed and replaced air con controller as requested. Rechecked operation of air con. Vent temp 11.8* Celsius at 32* C, ambient temp.	Rhys Cranston
S-29137	18/02/2020	806740		A - Fortnighly/5000km	Completed 'A' service.	Lachlan Latham
R-30604	10/02/2020	802686		Trailer	Relined brakes on left side of axle 2 on trailer.	Daniel Phelps
S-29086	10/02/2020	802686		D - Brakes	Checked and adjusted brakes.	Daniel Phelps
S-29047	06/02/2020	801460		C - 200 000km	Completed 'C' service.	Mat Norton
S-29048	06/02/2020	801460		B - 20 000km	Completed 'B' service.	Mat Norton
R-30558	05/02/2020	800915		Engine	Removed and replaced alternator and air con belts, tensioners and idler pullies.	Mat Norton
S-28984	04/02/2020	800223		A - Fortnighly/5000km	Completed 'A' service.	Mat Norton
R-30548	04/02/2020	800223		Clutch	Carried out clutch adjustment.	Mat Norton
S-28926	28/01/2020	796673		D - Brakes	Checked and adjusted brakes.	Lachlan Latham
S-28826	23/01/2020	795123		A - Fortnighly/5000km	Completed A service	Josh Mills
R-30364	17/01/2020	792660		Trailer	Removed worn tailgate seal on trailer, cleaned surface and fitted and glued new tailgate seal into place.	Lachlan Latham
S-28771	16/01/2020	791699		D - Brakes	Checked and adjusted brakes.	Lachlan Latham
S-28668	06/01/2020	786336		A - Fortnighly/5000km	Completed 'A' service.	Lachlan Latham
R-30246	06/01/2020	786336		Tarps_dust covers	Removed and replaced several loose screws on tarp bow ends on truck and trailer. Drilled new holes in some bow ends and fitted new screws.	Lachlan Latham

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
S-28614	18/12/2019	784156		D - Brakes	Checked and adjusted brakes.	Lachlan Latham
R-30188	18/12/2019	784156		Driveline	Removed and replaced leaking inner hub seal on left side of axle 2 on truck. Cleaned, inspected and re-used wheel bearings. Replaced contaminated brake linings and brake drum on same wheel end during repair. Reassembled and torqued components to specification.	Lachlan Latham
S-28516	10/12/2019	777847		A - Fortnighly/5000km	Completed 'A' service.	Lachlan Latham
R-30081	05/12/2019	777122		Trailer	Replaced bottom section of tailgate seal on trailer.	Rhys Neal
S-28453	05/12/2019	777122		D - Brakes	Checked and adjusted brakes.	Josh Mills
R-30075	05/12/2019	777122		Engine	Removed and replaced air filters.	Cameron Woodgate
I-756	29/11/2019	774346		COR	Carried out Roadworthy inspection. Replaced wear plate on Ringfeeder.	Michael Pratten
R-29984	29/11/2019	774346			Removed and replaced worn wear plate on ringfeeder on truck.	Michael Pratten
R-29984	29/11/2019	774346		Trailer	1.Removed and replaced worn tow eye bush. 2.Repaired ABS wires on right side of axle 2 on trailer.	Michael Pratten
R-29995	29/11/2019	774346		Trailer	Fitted and welded spring bolt lock assembly to support/retain draw bar leg on trailer.	Steelfab Mobile Welding
R-29954	28/11/2019	773644		Trailer	Drilled and removed broken lower shock absorber mounting on left side of axle 1 on trailer. Cleaned thread and fitted shock and new mounting bolt.	Brodie Connor
R-29941	27/11/2019	773644		Electrical	Removed and replaced combination switch.	Cameron Woodgate
R-29939	27/11/2019	773644		Body	Removed and replaced worn left side bonnet hinge bush.	Nathan George
R-29910	25/11/2019	772518		Engine	Removed and replaced faulty starter motor. Tested to confirm repair.	Caylon Jackson
S-28347	25/11/2019	772518		A - Fortnighly/5000km	Completed 'A' service.	Caylon Jackson
S-28285	21/11/2019	770803		D - Brakes	Checked and adjusted brakes.	Michael Pratten
R-29877	20/11/2019	770803		Electrical	Lights and reverse alarm found to be coming on when rocking cab of truck. Checked wiring and found damaged loom above engine where it was rubbing on a bracket. Repaired wiring loom and insulated with conduit. Tested to confirm repair.	Michael Pratten

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
S-28187	12/11/2019	766040		A - Fortnighly/5000km	Completed 'A' service.	Mat Norton
R-29791	12/11/2019	766040		Brakes	Relined brakes and replaced brake drum on left side of axle 3 on truck. Replaced leaking inner hub seal, S-cam and bushes, wheel bearings, slack adjuster and axle gasket at time of reline. Reassembled and torqued all components to specification.	Mat Norton
R-29791	12/11/2019	766040		Trailer	1.Removed and replaced leaking brake booster on left side of axle 4 on trailer. 2.Relined brakes on left side of axle 1 on trailer. 3.Relined brakes and replaced brake drum on left side of axle 4 on trailer.	Mat Norton
R-29723	05/11/2019	762022		Clutch	Carried out clutch adjustment.	Lachlan Latham
S-28127	05/11/2019	762022		D - Brakes	Checked and adjusted brakes.	Lachlan Latham
R-29684	01/11/2019	760094		Trailer	Removed and replaced leaking quick fit air line fitting above axles 1 and 2 on trailer. Rechecked for leaks to confirm repair.	Nathan George
S-28092	01/11/2019	760094		B - 20 000km	Completed 'B' service.	Brett Waters
R-29643	29/10/2019	757860		Electrical	Removed and replaced reverse alarm on truck. Checked operation of alarm once fitted.	Cameron Woodgate
R-29631	28/10/2019	757110		Electrical	Removed and replaced reverse alarm on trailer. Checked operation of alarm. Ok. **Need truck unloaded to access reverse alarm on truck.** Repaired 1 x broken wire for number plate light. Checked operation of light. Ok.	Cameron Woodgate
S-28024	28/10/2019	757110		A - Fortnighly/5000km	Completed 'A' service.	Brett Waters
R-29599	24/10/2019	755531		Air conditioning_heater	Inspeced heater fan fault and wiring. Found 25 amp fuse for blower motor missing. Replaced fuse and checked all fan speed operations.	James Hanger
R-29599	24/10/2019	755531		Electrical	Inspected truck and drove around but unable to replicate fault of reverse lights coming on while driving. Cleaned out trailer plug and blew out truck and trailer electrical junction boxes.	James Hanger
R-29549	21/10/2019	753691		Trailer	Plugged leaking air fitting back in under axles 1 and 2 on trailer.	Josh Mills
S-27980	21/10/2019	753691		D - Brakes	Checked and adjusted brakes.	Josh Mills

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
R-29466	14/10/2019	750286		Air conditioning_heater	Removed air con contrl unit and fitted new unit . Fan still only worked on 4th speed only. Checked all fuses and relays. Removed fan speed resistor and tested with new one. Fan still not working on all speeds. Further diagnosis time required.	Nathan George
R-29467	14/10/2019	750286		Clutch	Carried out clutch adjustment.	Josh Mills
R-29467	14/10/2019	750286		Trailer	Reattached left side draw bar spring on trailer. Fitted new bow shackle to retain spring.	Josh Mills
S-27867	14/10/2019	750286		A - Fortnighly/5000km	Completed 'A' service. Added 1.0 litre of coolant. Added 0.5 litres of engine oil.	Josh Mills
S-27830	11/10/2019	749722		D - Brakes	Checked and adjusted brakes.	Lachlan Latham
R-29431	09/10/2019	748841		Body	Removed and replaced 2 x hinges on submarine door on the truck body. Drilled and tapped 2 x new mounting holes for the door hinges.	Brodie Connor
R-29432	09/10/2019	748841		Body	Tightened loose left side bonnet hinge mounting bolt.	Brodie Connor
T-4656	04/10/2019	747660		New	Fitted 4 x new 11R22.5 Doublecoin RLB-1 tyres onto axle 3 left and right side inner and outers.	Daniel Graham
R-29361	30/09/2019	745527		Trailer	Repaired air leak around axles 1 and 2 on trailer.	Steve Corby
S-27738	30/09/2019	745530		A - Fortnighly/5000km	Completed 'A' service.	Steve Corby
R-29330	26/09/2019	744803		Electrical	Adjusted "transmission pressure" warning light switch. Rechecked warning light was no longer on to confirm repair.	Daniel Phelps
R-29331	26/09/2019	744803		Trailer	Checked leak on left side hub on axle 4 on trailer. Found 1 x bolt missing and others loose on bearing cap. Replaced gasket, refitted bolts and tightened.	Cameron Woodgate
S-27695	24/09/2019	743669		D - Brakes	Checked and adjusted brakes.	Josh Mills
R-29267	20/09/2019	742113		Electrical	Checked transmission oil level. Removed and replaced transmission pressure switch. Checked wiring around transmission. **Further diagnosis time required. Light still on even when switch is bridged.**	Michael Pratten
R-29267	20/09/2019	742113		Trailer	Repaired damaged wiring and replaced electrical plug for trailer tarp.	Michael Pratten

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
R-29229	18/09/2019	740803		Air conditioning_heater	Diagnosed fault with heater fan. Found faulty fan motor causing fuses to blow and fan resistor to fail. Removed and replaced heater fan and resistor and checked all heater/air con controls for correct operation.	Mat Norton
S-27595	17/09/2019	740803		A - Fortnighly/5000km	Completed 'A' service.	Josh Mills
R-29169	12/09/2019	739207		Trailer	Repaired air leak on draw bar of trailer.	Lachlan Latham
R-29169	12/09/2019	739207		Clutch	Carried out clutch adjustment.	Lachlan Latham
R-29169	12/09/2019	739207		Driveline	Removed and replaced diff breather.	Lachlan Latham
S-27547	10/09/2019	737934		D - Brakes	Checked and adjusted brakes.	Mat Norton
R-29056	03/09/2019	734245		Trailer	Removed and replaced left and right side quarter guards on front of axle 1 on trailer.	Daniel Phelps
R-29056	03/09/2019	734245		Electrical	Removed and replaced heater/air con fan motor. Fault still present. Carried out further testing of system, but need furhter diagnosis time. **Suspect air con controller to be faulty.** Ordered new controller.	Daniel Phelps
R-29041	03/09/2019	733449		Electrical	Repaired wiring in trailer plug	Cameron Woodgate
T-4608	03/09/2019	734248		New	1.Fitted 2 x new 295/80R22.5 Bridgestone R150 tyres onto axle 1 left and right sides. 2.Fitted 4 x new 11R22.5 Doublecoin RLB1 tyres onto axle 2 left and right side inner and outers.	Daniel Graham
R-29042	02/09/2019	733449		Hydraulics	Removed and cleaned hydraulic fitting on truck. Reassembled and checked for leaks. None present.	Cameron Woodgate
R-29040	02/09/2019	733449		Air conditioning_heater	Checked all fuses and relays for heater fan. All ok. Checked power at control. Air con light illuminates when switched on. Suspect faulty air con controller. **Ordered new controller.**	Lachlan Latham
S-27446	02/09/2019	733449		A - Fortnighly/5000km	Completed 'A' service.	Daniel Phelps
S-27395	30/08/2019	732436		D - Brakes	Checked and adjusted brakes.	Brett Waters
R-29003	29/08/2019	731808		Air conditioning_heater	Tested and replaced fan resistor. Fan still cutting out. Tested power at fan motor. 24 volts present. Ordered new fan assembly.	Brett Waters

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
R-28966	27/08/2019	730204		Cooling system	Travelled to Breadalbane. Checked for coolant leak-found air compressor hoses leaking. Topped coolant up and escorted truck back to workshop for further repairs. Drained coolant, removed and replaced leaking hoses. Refilled cooling system, bled air and rechecked for leaks to confirm repair.	Mat Norton
R-28966	27/08/2019	730204		Fuel System	Removed and replaced leaking injector line on number 1 cylinder. Run engine and rechecked for leaks.	Mat Norton
R-28935	22/08/2019	728587		Tarps_dust covers	Removed and replaced failed tarp motor and gearbox on truck. Replaced tarp motor clutch assembly and tested operation of tarp to confirm repair.	James Hanger
S-27294	22/08/2019	729388		A - Fortnighly/5000km	Completed 'A' service.	James Hanger
S-27240	14/08/2019	725032		D - Brakes	Checked and adjusted brakes.	Caylon Jackson
R-28823	08/08/2019	722360		Suspension	Replaced LHS axle 3 air bag	Mat Norton
R-28823	08/08/2019	722360		Trailer	Replaced leaking air bag LHS axle 1 on trailer	Mat Norton
S-27148	06/08/2019	720835		A - Fortnighly/5000km	Completed 'A' service.	Mat Norton
R-28760	05/08/2019	720075		Electrical	Removed and replaced faulty fuel gauge.	Caylon Jackson
S-27133	01/08/2019	719463		B - 20 000km	Completed 'B' service.	Steve Corby
S-27095	01/08/2019	719463		D - Brakes	Checked and adjusted brakes.	Steve Corby
R-28686	25/07/2019	716313		Electrical	Checked all lights on truck and trailer. All working.	Rhys Cranston
S-26990	25/07/2019	716314		A - Fortnighly/5000km	Completed 'A' service.	Josh Mills
R-28653	23/07/2019	714942		Trailer	Tightened loose fittings on hydraulic hose on draw bar of trailer and at rear of truck.	Rhys Cranston
S-26925	18/07/2019	713093		D - Brakes	Checked and adjusted brakes.	Michael Pratten
R-28624	18/07/2019	713093		Electrical	Removed and replaced blown bulb in park light.	Caylon Jackson
R-28623	18/07/2019	713093		Engine	Checked air intake system. Replaced air filters.	Michael Pratten
R-28496	09/07/2019	708568		Electrical	Removed and replaced cracked right side head light insert. Re-used original globes.	Rhys Neal

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
S-26806	09/07/2019	708568		A - Fortnighly/5000km	Completed 'A' service.	Josh Mills
R-28497	09/07/2019	708568		Trailer	Checked reverse lights on trailer-spread pins in 7 pin Utilux trailer plug and reconnected. Checked reverse lights to confirm repair.	Josh Mills
S-26759	04/07/2019	706926		D - Brakes	Checked and adjusted brakes	Josh Mills
R-28460	04/07/2019	707430		Body	Fitted new bumber bar	Daniel Phelps
S-26653	24/06/2019	702975		A - Fortnighly/5000km	Completed 'A' service.	Brett Waters
R-28311	20/06/2019	701518		Trailer	Repaired air leak on trailer.	Caylon Jackson
S-26590	19/06/2019	701165		D - Brakes	Checked and adjusted brakes.	James Hanger
R-28305	19/06/2019	701165		Trailer	Tightened loose hoist hose joiner at rear section of draw bar on trailer.	James Hanger
R-28235	12/06/2019	698296		Hydraulics	Tightened leaking hydraulic quick coupler fitting up at rear of truck.	Caylon Jackson
S-26489	12/06/2019	698296		A - Fortnighly/5000km	Completed 'A' service. Replaced T-piece air line fitting at diverter valve on trailer.	Matt Norton
R-28202	07/06/2019	697104		Chassis	Greased ringfeeder and checked it worked correctly.	Lachlan Latham
R-28202	07/06/2019	697104		Electrical	Inspected wiring for mirror heaters. Found no power to mirrors. Checked fuse-ok. Inspected wiring between fuse and electrical plug unde dash. Rewired earth circuit and retested mirror heaters with temp gun to confirm repair.	Lachlan Latham
R-28202	07/06/2019	697104		Trailer	Replaced damaged wiring to Wabco trailer plug, trailer lights and electric tarp power cables. Repaired steel hydraulic hoist hose line on drawbar of trailer. Replaced rubber hydraulic hoist hose. Reassembled and tested all hydraulics and electrical components on trailer.	Lachlan Latham
S-26444	05/06/2019	696783		D - Brakes	Checked and adjusted brakes.	Josh Mills
R-28177	05/06/2019	696783		Suspension	Removed and replaced leaking shock absorber on right side of axle 2 on truck.	Josh Mills
R-28176	05/06/2019	696783		Trailer	1.Relined brakes on right side of axle 1 on trailer. 2.Relined brakes and replaced brake drum on left side of axle 2 on trailer.	Josh Mills
R-28149	04/06/2019	696326		Electrical	Rejoined and soldered damaged wires on draw bar of trailer. Checked right side indicators on trailer worked to confirm repair.	Brodie Connor

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
S-26341	27/05/2019	692564		A - Fortnighly/5000km	Completed 'A' service. Replaced wiper blades.	Rhys Cranston
R-28035	22/05/2019	690040		Tailgate	Re-glued detached tailgate seal.	Caylon Jackson
S-26286	21/05/2019	689861		D - Brakes	Checked and adjusted brakes.	Rhys Cranston
S-26186	15/05/2019	687673		A - Fortnighly/5000km	Completed 'A' service.	Michael Pratten
S-26145	08/05/2019	683340		D - Brakes	Checked and adjusted brakes.	Daniel Phelps
R-27880	07/05/2019	685028		Cab	Removed and replaced drivers seat and seat base.	Brodie Connor
R-27862	04/05/2019	683026		Trailer	Repaired cracks in trailer hoist well. Fitted step to trailer tailgate.	Steelfab Mobile Welding
R-27876	04/05/2019	683026		Trailer	Fitted 'bolt-on' step onto trailer tailgate.	Steelfab Mobile Welding
R-27855	03/05/2019	683028		Trailer	Replaced ABS lead on trailer	Rhys Cranston
R-27855	03/05/2019	683028		Air System	Replaced 3/8" air lines on RHS of dolly.	Rhys Cranston
S-26041	30/04/2019	681805		A - Fortnighly/5000km	Completed 'A' service. Replaced broken oil filler cap on rocker cover.	Caylon Jackson
S-26029	26/04/2019	680302		B - 20 000km	Completed 'B' service.	Brodie Connor
S-26000	24/04/2019	679613		D - Brakes	Checked and adjusted brakes.	Brodie Connor
S-25899	15/04/2019	675880		A - Fortnighly/5000km	Completed 'A' service.	Matt Norton
R-27733	15/04/2019	675880		Air conditioning_heater	Removed and replaced broken cab filter cover.	James Hanger
R-27735	15/04/2019	675880		Clutch	Cleaned clutch brake and carried out clutch pedal freeplay adjustment.	Matt Norton
R-27734	15/04/2019	675880		Driveline	Removed and replaced leaking inner hub seal on left side of axle 1. Inspected hub,bearings etc, cleaned and reassembled and adjusted to Meritor specification. Filled hub with oil to required level.	Matt Norton
S-25851	09/04/2019	673333		D - Brakes	Checked and adjusted brakes.	Steve Corby
R-27628	04/04/2019	671110		Clutch	Carried out clutch adjustment.	Rhys Cranston
R-27631	04/04/2019	671110		Cab	Checked seat and seat base. Found seat base fitted incorrectly and seat collapsed on the left side. Ordered new seat.	Rhys Cranston

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
R-27594	02/04/2019	669964		Trailer	Repaired damged/leaking air lines on the draw bar of the trailer.	Rhys Cranston
S-25739	02/04/2019	669964		A - Fortnighly/5000km	Completed 'A' service.	Rhys Cranston
R-27594	02/04/2019	669964		Clutch	Carried out clutch adjustment.	Rhys Cranston
R-27560	01/04/2019	668330		Engine	Removed and replaced leaking engine fan hub assembly.	Lachlan Latham
R-27560	01/04/2019	668330		Air conditioning_heater	Replaced receiver drier and cab filter. Vacc'd down air con system and recharged with R134A. Tested operation of air con. Vent temperature 4.6* Celsius at 11* C, ambient temp. **Air con compressor replaced previous week on site.**	James Hanger
S-25659	29/03/2019	668630		D - Brakes	Checked and adjusted brakes.	Michael Pratten
R-27487	23/03/2019	665655		Cab	Removed and replaced worn left side bonnet pivot bracket.	Rhys Cranston
R-27487	23/03/2019	665655		Cooling system	Replaced coolant. Fitted new radiator cap.	Rhys Cranston
R-27484	23/03/2019	665394		Engine	Removed and replaced seized air con compressor. Removed and replaced main belt tensioner and both belts.	Rhys Cranston
R-27468	21/03/2019	665132		Trailer	Removed and replaced all (8 x) hub and bearing assemblies on trailer.	Daniel Phelps
R-27444	19/03/2019	664642		Steering	Removed and replaced lower mounting bracket on power steering reservoir.	Rhys Neal
S-25588	19/03/2019	664642		A - Fortnighly/5000km	Completed 'A' service. Bled air from trailer hoist. Re-glued section of tailgate seal on trailer.	Daniel Phelps
R-27445	19/03/2019	664642		Trailer	Relined brakes and replaced brake drums on left side of axle 1 and left and right sides of axle 2 on trailer. Tensioned wheel nuts and adjusted bakes.	Daniel Phelps
S-25547	11/03/2019	660093		D - Brakes	Checked and adjusted brakes.	Brett Waters
R-27356	11/03/2019	660093		Trailer	Tightened loose air line fittings on draw bar of trailer.	Brett Waters
R-27356	11/03/2019	660093		Tarps_dust covers	Tightened loose screws on sides of tarps.	Brett Waters
R-27356	11/03/2019	660093		Engine	Removed and replaced air filters.	Brett Waters
S-25445	05/03/2019	656310		A - Fortnighly/5000km	Completed 'A' service. Secured leaking air line in quick fit connector on trailer.	James Hanger

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
R-27197	25/02/2019	654964		Trailer	Relined brakes and replaced brake drum on right side of axle 4 on trailer. Checked S-cam/bush movement during repair. Adjusted brake.	Matt Norton
S-25405	25/02/2019	654964		D - Brakes	Checked and adjusted brakes. Tightened leaking Adblue injector fitting.	Brodie Connor
R-27163	21/02/2019	652639		Adblue System	Connected diagnostic computer and checked for fault codes. Code 109 and 74-5 present. Removed and replaced dosing module and NOX sensor before catalyst. Cleaned Adblue lines out.	Brodie Connor
S-25303	21/02/2019	653783		A - Fortnighly/5000km	Completed 'A' service.	Steve Corby
R-27141	19/02/2019	652589		Electrical	Removed and replaced cracked left and right side head light inserts.	Josh Mills
R-27131	16/02/2019	652588		Chassis	Removed and replaced broken exhaust mounting bracket on right side of chassis.	Matt Norton
R-27119	15/02/2019	652587		Trailer	1.Removed and replaced worn tow eye bush. 2.Removed and replaced draw bar pivot pins and bushes.	Brodie Connor
S-25253	14/02/2019	652584		D - Brakes	Checked and adjusted brakes.	Michael Pratten
S-25148	08/02/2019	649656		A - Fortnighly/5000km	Completed 'A' service.	Rhys Cranston
T-4359	01/02/2019	646305		New	Tyre removed damaged on side wall. Fitted 1 x new 11R22.5 Doublecoin RLB1 tyre onto axle 3 right side outer.	Daniel Graham
S-25092	29/01/2019	644754		D - Brakes	Checked and adjusted brakes.	Daniel Phelps
R-26989	29/01/2019	644745		Steering	Removed and realigned steering wheel.	Daniel Phelps
S-24989	21/01/2019	641417		A - Fortnighly/5000km	Completed 'A' service.	Brett Waters
S-24933	15/01/2019	639437		D - Brakes	Checked and adjusted brakes.	James Hanger
R-26822	15/01/2019	639437		Trailer	Removed and replaced sections of damaged tail gate seal on trailer.	Daniel Phillips
S-24961	15/01/2019	639437		B - 20 000km	Completed 'B' service.	James Hanger
S-24830	10/01/2019	638152		A - Fortnighly/5000km	Completed 'A' service.	Brodie Connor

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
R-26784	10/01/2019	638151		Trailer	1.Removed and replaced draw bar pivot pins and bushes on trailer. 2.Removed and replaced leaking tap in water tank on trailer.	Michael Pratten
R-26787	10/01/2019	638152		Trailer	Relined brakes on left side of axle 2 on trailer.	Josh Mills
T-4323	07/01/2019	637631		New	Fitted 4 x new 11R22.5 Doublecoin RLB1 tyres onto axle 3 left and right sides.	Daniel Graham
S-24776	20/12/2018	635414		D - Brakes	Checked and adjusted brakes.	Steve Corby
R-26595	10/12/2018	630398		Electrical	Removed and replaced failed clock spring in steering wheel. Tets drove truck- cruise control, horn and engine brake buttons all working correctly.	Rhys Cranston
S-24661	10/12/2018	630398		A - Fortnighly/5000km	Completed 'A' service.	Rhys Cranston
I-647	06/12/2018	628916		COR	Carried out Roadworthy inspection.	Michael Pratten
R-26576	06/12/2018	628915		Trailer	Shortened ABS wiring and replaced electrical plug. Repaired damaged tarp cable electrical leads.	Michael Pratten
R-26576	06/12/2018	628915		Trailer	Relined brakes on left side of axle 1 on trailer.	Michael Pratten
S-24614	05/12/2018	628106		D - Brakes	Checked and adjusted brakes.	Michael Pratten
R-26503	30/11/2018	625290		Trailer	Removed and replaced failed tarp motor and gearbox on trailer.	Rhys Cranston
R-26495	29/11/2018	625142		Trailer	Repaired damaged power cable for electric tarp on draw bar of trailer.	Michael Pratten
R-26484	27/11/2018	624533		Trailer	Relined brakes on right side of axle 1 on trailer.	Daniel Phelps
R-26484	27/11/2018	624533		Trailer	Relined brakes and replaced brake drum on left side of axle 2 on trailer.	Daniel Phelps
S-24515	27/11/2018	624533		A - Fortnighly/5000km	Completed 'A' service.	Daniel Phelps
S-24453	22/11/2018	622294		D - Brakes	Checked and adjusted brakes.	Brett Waters
R-26444	22/11/2018	622294		Trailer	Relined brakes on left side of axle 3 on trailer.	Brendan Widdows
R-26361	13/11/2018	617784		Trailer	Relined brakes on left sides of axles 1 and 2 on trailer.	Michael Pratten
S-24366	13/11/2018	617784		A - Fortnighly/5000km	Completed 'A' service.	Michael Pratten
R-26278	06/11/2018	614634		Trailer	Relined brakes and replaced brake drum on right side of axle 1 on trailer.	James Hanger

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
R-26279	06/11/2018	614634		Driveline	Inspected oil leak at right side of axle 3. Removed axle, tightened loose mounting studs, cleaned hub and axle surfaces and refitted axle with new gasket. Tightend loose hub fill plug and refilled with 85-140 oil. Cleaned wheel end with pressure washer.	James Hanger
S-24317	06/11/2018	614634		D - Brakes	Checked and adjusted brakes.	James Hanger
R-26233	31/10/2018	611608		Electrical	1.Ordered clock spring for smart wheel. 2.Removed and replaced hand piece for CB radio. 3.Cleaned dirt from female ABS plug and reconnected.	Steve Corby
R-26216	30/10/2018	610890		Clutch	Carried out clutch adjustment. Pedal had no freeplay.	Steve Corby
S-24208	29/10/2018	610064		A - Fortnighly/5000km	Completed 'A' service.	Steve Corby
S-24158	25/10/2018	608664		D - Brakes	Checked and adjusted brakes.	Brodie Connor
S-24056	16/10/2018	603570		A - Fortnighly/5000km	Completed 'A' service.	Rhys Cranston
R-26043	13/10/2018	602171		Engine	Removed and replaced fan clutch. Connected 'Davie' diagnostic computer and performed fan clutch test to confirm repair.	Brett Waters
R-26034	11/10/2018	602171		Trailer	Removed and replaced tailgate seal on trailer.	Daniel Phelps
S-24036	09/10/2018	600310		B - 20 000km	Completed 'B' service.	Daniel Phelps
S-24035	09/10/2018	600310		C - 200 000km	Completed 'C' service.	Daniel Phelps
S-24006	08/10/2018	599753		D - Brakes	Checked and adjusted brakes.	Daniel Phelps
R-25980	08/10/2018	599753		Trailer	Relined brakes on left side of axles 1 and 2 on trailer. Replaced 1 x brake drum during repair.	Daniel Phelps
R-25962	05/10/2018	598138		Trailer	Replaced tarp cable on trailer	Brodie Connor
R-25945	03/10/2018	597969		Transmission	Removed and replaced leaking gear knob assembly.	Brett Waters
R-25934	02/10/2018	597135		Brakes	Removed and replaced leaking inner hub seal on right side of axle 3 on truck. Replaced contaminated brake linings, cleaned and re-used brake drum and wheel bearings, replaced S-cam and bushes and slack adjuster. Torqued hub and bearings to specification.	Brett Waters

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
S-23911	02/10/2018	597135		A - Fortnighly/5000km	Completed 'A' service. Replaced 1 x mudflap on trailer.	Brett Waters
S-23857	27/09/2018	595636		D - Brakes	Checked and adjusted brakes.	Michael Pratten
R-25905	26/09/2018	594978		Engine	Connected Davey diagnostic computer to truck and performed engine fan tests. All passed. Checked fan operation-working correctly after tests carried out.	Michael Pratten
R-25896	25/09/2018	594486		Engine	Removed and replaced air con belt.	Daniel Phillips
S-23765	21/09/2018	593122		A - Fortnighly/5000km	Completed A service	James Hanger
R-25860	21/09/2018	591896		Electrical	Removed and replaced electrical junction boxes on truck and trailer.	Rhys Cranston
R-25860	21/09/2018	591896		Trailer	Removed and replaced tow eye bush. Removed and replaced drawbar bushes.	Rhys Cranston
R-25860	21/09/2018	591896			Removed and replaced Ringfeeder assembly.	Rhys Cranston
R-25831	18/09/2018	591837		Trailer	Repaired cracks in trailer hoistwell.	Steelfab Mobile Welding
S-23706	13/09/2018	591276		D - Brakes	Checked and adjusted brakes.	Steve Corby
R-25747	10/09/2018	588656		Electrical	Load tested batteries and found to be faulty. Removed and replaced batteries and checked charging system. All ok.	Daniel Phelps
R-25745	08/09/2018	588655		Steering	Removed and replaced power steering box and bled system as per procedure.	James Hanger
R-25696	04/09/2018	587011		Trailer	Relined brakes and replaced brake drum on rights of axles 1 and 4 on trailer. Relined brakes on right side of axle 2 on trailer.	Rhys Cranston
S-23617	04/09/2018	587011		A - Fortnighly/5000km	Completed 'A' service.	Rhys Cranston
R-25697	04/09/2018	587011		Trailer	Removed and replaced shock absorbers on left side of axle 1 on trailer. Removed and replaced left and right side shock absorbers on axle 2 on trailer.	Rhys Cranston
S-23571	30/08/2018	585051		D - Brakes	Checked and adjusted brakes	Michael Pratten
R-25583	21/08/2018	581241		Brakes	Relined brakes on left side of axle 3 on truck.	Daniel Phelps

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
R-25584	21/08/2018	581241		Brakes	Removed and replaced slack adjusters on left side of axles 2 and 3 on truck. Shimmed S-cam end float on left side of axles 2 and 3.	Daniel Phelps
S-23476	21/08/2018	581241		A - Fortnighly/5000km	Completed 'A' service.	Daniel Phelps
S-23410	15/08/2018	578854		D - Brakes	Checked and adjusted brakes.	Brett Waters
R-25494	13/08/2018	577692		Trailer	Repaired wiring running to left side tail/clearance light on dolly light bar on trailer.	Brett Waters
S-23321	08/08/2018	575883		A - Fortnighly/5000km	Completed 'A' service.	James Hanger
R-25443	08/08/2018	575883		Brakes	Removed and replaced leaking inner hub seals on left and right sides of axle 1 on truck. Replaced brake linings and drums, S-cams. slack adjusters and wheel bearing cups and cones. Reassembled and torqued to specifications. Refilled hubs with oil.	Josh Mills
S-23283	02/08/2018	573575		D - Brakes	Checked and adjusted brakes.	Steve Corby
S-23196	23/07/2018	569041		A - Fortnighly/5000km	Completed 'A' service.	Rhys Cranston
R-25300	23/07/2018	569041		Electrical	Removed and replaced left side centre clearance light. Replaced junction box and rewired left side tail light on truck.	Robert Harmond
S-23149	18/07/2018	566935		D - Brakes	Checked and adjusted brakes.	Michael Pratten
R-25159	11/07/2018	562952		Transmission	Replaced gear shift knob	Lachlan Latham
R-25138	10/07/2018	561790		Suspension	Removed and replaced worn torque rod bushes on axle 2 on truck.	Rhys Cranston
R-25138	10/07/2018	561790		Engine Emission Systems	Connected Davie diagnostic tool and found Nox sensor after catalyst to be faulty. Replaced sensor and rechecked to confirm repair.	Rhys Cranston
S-23059	10/07/2018	562349		A - Fortnighly/5000km	Completed 'A' service.	Daniel Phelps
R-25138	10/07/2018	561790		Trailer	Removed and replaced worn tow eye bush.	Rhys Cranston
S-22994	05/07/2018	560270		D - Brakes	Checked and adjusted brakes.	Brett Waters
S-23045	05/07/2018	560270		B - 20 000km	Completed 'B' service.	Brett Waters
S-22900	26/06/2018	555826		A - Fortnighly/5000km	Completed 'A' service.	James Hanger

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
S-22850	20/06/2018	553853		D - Brakes	Checked and adjusted brakes.	Steve Corby
R-24883	14/06/2018	551121		Trailer	Relined brakes on left side of axle 4 on trailer.	Rhys Cranston
S-22757	13/06/2018	550403		A - Fortnighly/5000km	Completed 'A' service.	Rhys Cranston
T-4074	13/06/2018	550402		New	Fitted 4 x new 11R22.5 Doublecoin RLB1 tyres onto axle 3.	Daniel Graham
S-22668	07/06/2018	548601		D - Brakes	Checked and adjusted brakes	Michael Pratten
R-24712	30/05/2018	544423			Removed and replaced worn tow eye bush.	Brett Waters
S-22580	30/05/2018	544423		A - Fortnighly/5000km	Completed 'A' service.	Brett Waters
R-24712	30/05/2018	544423		Air System	Removed and replaced leaking female Wabco air fitting on left side rear of truck.	Brett Waters
R-24659	24/05/2018	542669		Engine	Replaced air filters. Replaced 2 x air filter retaining nuts.	Robert Harmond
S-22536	24/05/2018	542669		D - Brakes	Checked and adjusted brakes.	Brett Waters
R-24562	16/05/2018	538324		Electrical	Repaired broken wire for number plate light. Removed and replaced blown bulb in right side front park light.	Rhys Neal
S-22438	16/05/2018	536324		A - Fortnighly/5000km	Completed 'A' service.	James Hanger
R-24548	15/05/2018	537809		Tailgate	Removed and replaced leaking tailgate seals on truck and trailer.	Matt Norton
R-24515	11/05/2018	536404		Trailer	Replaced trailer tarp bearing and pulley	Robert Harmond
S-22395	10/05/2018	535914		D - Brakes	Checked and adjusted brakes	Steve Corby
S-22303	04/05/2018	532349		A - Fortnighly/5000km	Completed A service	Rhys Cranston
S-22262	26/04/2018	528451		D - Brakes	Checked and adjusted brakes.	Michael Pratten
R-24285	17/04/2018	524398		Brakes	Relined brakes on right side of axle 2 on truck.	Daniel Phelps
S-22170	17/04/2018	524398		A - Fortnighly/5000km	Completed 'A' service.	Daniel Phelps
T-3988	17/04/2018	574398		Puncture	Repaired puncture in axle 3 right side inner tyre.	Daniel Graham

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
R-24254	16/04/2018	523282		Electrical	Active codes-U1197, can communication ABS-D/EBS. Can message reported speed to high. SPN520227-exhaust emission controller undocumented fault. Contact manufacturer. Isolated vehicle for 5 minutes and U1197 was no longer active. Further diagnosis needed. (Possibly Canberra Truck Repairs).	James Hanger
R-24250	14/04/2018	523281		Suspension	Fitted and plumbed up onboard scale system.	Rhys Cranston
R-24191	09/04/2018	520754		Trailer	Relined brakes on left side of axle 2 on trailer.	Josh Mills
S-22145	09/04/2018	520754		B - 20 000km	Completed 'B' service.	Brett Waters
S-22120	09/04/2018	520754		D - Brakes	Checked and adjusted brakes.	Brett Waters
R-24138	03/04/2018	517747		Trailer	Removed and replaced damaged shock absorber on right side of axle 1 on trailer.	James Hanger
T-3956	03/04/2018	517747		New	Fitted 2 x new 295/80R22.5 Bridgestone R150 steer tyres onto axle 1.	Daniel Graham
R-24137	03/04/2018	517747		Hydraulics	Removed and replaced male and female hydraulic quick coupler fittings between truck and trailer.	Robert Harmond
S-22036	03/04/2018	517747		A - Fortnighly/5000km	Completed 'A' service.	James Hanger
S-21997	26/03/2018	514668		D - Brakes	Checked and adjusted brakes.	Steve Corby
R-24054	22/03/2018	513098		Electrical	Removed and replaced blown bulb in right side low beam light. Checked wiring, etc. Found and repaired rubbed wire at left side low beam light.	Rhys Cranston
S-21906	19/03/2018	511014		A - Fortnighly/5000km	Completed 'A' service.	Rhys Cranston
R-23978	14/03/2018	508307		Brakes	Disassembled wheel end/hub on left side of axle 2 on truck. Cleaned, inspected, replaced leaking inner hub seal, brake linings and drum,S-cam and slack adjuster and reassembled. Torqued to specification.	Daniel Phelps
S-21845	12/03/2018	506586		D - Brakes	Checked and adjusted brakes.	Michael Pratten
R-23885	06/03/2018	503595		Trailer	Removed and replaced leaking height control valve on trailer.	Daniel Phelps

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
R-23884	06/03/2018	503595		Brakes	Removed and replaced slack adjusters on right side of axle 2 and left side of axle 3 on truck. Shimmed S-cam endfloat.	Daniel Phelps
S-21752	06/03/2018	503595		A - Fortnighly/5000km	Completed 'A' service.	Daniel Phelps
S-21691	02/03/2018	501988		D - Brakes	Checked and adjusted brakes.	Brodie Connor
R-23773	22/02/2018	497835		Air conditioning_heater	Removed and replaced blower fan assembly. Checked operation.	James Hanger
S-21574	21/02/2018	497248		A - Fortnighly/5000km	Completed 'A' service.	James Hanger
R-23740	15/02/2018	494315		Air conditioning_heater	Tested switch for air con fan operation. Working correctly. Removed and replaced fan resistor.	Steve Corby
R-23740	15/02/2018	494315		Body	Removed and replaced left and right side upper bonnet support blocks/rubbers.	Steve Corby
S-21515	14/02/2018	493478		D - Brakes	Checked and adjusted brakes.	Steve Corby
R-23741	13/02/2018	492638		Cab	Test drove truck to confirm noise when turning hard right. Found low coolant level sensor sounding on cab cooler. Topped up water level on cooler system.	Steve Corby
R-23742	13/02/2018	492638		Brakes	Test drove truck and brake tested for noise when braking. None evident when testing.	Steve Corby
R-23741	13/02/2018	492638		Driveline	Topped up low oil level in left side hub on axle 1.	Steve Corby
R-23881	08/02/2018	488937		Chassis	1.Truck presented with broken gusset/fish plate. Removed and replaced gussets. Replaced torque rod bushes. 2.Found Adblue fault light on dash. Removed and replaced Adblue filter. Found water in air tanks. Replaced air drier filter.	Canberra Truck Repairs
R-23672	07/02/2018	489591		Brakes	Removed and replaced slack adjuster on left side of axle 2 on truck. Shimmed S-cam end float.	Matt Norton
S-21433	07/02/2018	489591		A - Fortnighly/5000km	Completed 'A' service.	Rhys Cranston
R-23641	05/02/2018	488932		Suspension	Travelled to Bredbo. Removed broken bolt from left side front torque rod. Inspected torque rod and found chassis gusset/torque rod mount broken where top bolt should secure. Installed new bottom bolt and followed truck to Canberra Truck Repairs for further repair.	James Hanger

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
S-21382	02/02/2018	488445		D - Brakes	Checked and adjusted brakes.	Michael Pratten
S-21300	23/01/2018	483158		A - Fortnighly/5000km	Completed 'A' service.	Daniel Phelps
R-23527	22/01/2018	483157		Engine	Removed and replaced engine brake valve. Checked and adjusted valve clearances. Replaced rocker cover gasket.	Brett Waters
R-23491	18/01/2018	482417		Engine	Replaced and adjusted clutch switch for engine brake.	Brett Waters
S-21279	16/01/2018	480796		B - 20 000km	Completed 'B' service. Replaced air filters.	Brett Waters
S-21254	16/01/2018	480796		D - Brakes	Checked and adjusted brakes.	Brett Waters
S-21173	09/01/2018	477179		A - Fortnighly/5000km	Completed 'A' service.	Jordan Mcgrath
T-3837	09/01/2018	477178		New	Fitted 4 x new Doublecoin RLB1 drive tyres onto axle 2.	Daniel Evans
S-21135	05/01/2018	475846		D - Brakes	Checked and adjusted brakes.	Steve Corby
R-23373	04/01/2018	475845		Trailer	Removed and replaced worn tow eye bush on trailer.	Steve Corby
R-23373	04/01/2018	475845			Rekitted ringfeeder.	Steve Corby
R-23351	03/01/2018	475845		Air conditioning_heater	Removed and replaced 2 x damaged air vents on left and right sides above instrument cover.	Lachlan Latham
R-23292	20/12/2017	474906		Brakes	Relined brakes and replaced brake drum on right side of axle 3 on truck.	Rhys Cranston
S-21051	20/12/2017	474906		A - Fortnighly/5000km	Completed 'A' service.	Rhys Cranston
R-23252	18/12/2017	473240		Cooling system	Travelled to Woodhouselee. Fitted new fan belt and topped up coolant level.	Michael Pratten
S-20991	14/12/2017	472620		D - Brakes	Checked and adjusted brakes.	Michael Pratten
R-23200	11/12/2017	470491		Trailer	Repaired wiring in electrical junction box under trailer and re-routed cables.	Michael Pratten
R-23200	11/12/2017	470491		Tarps_dust covers	Removed,replaced and adjusted tarp cable on truck.	Michael Pratten
R-23159	07/12/2017	469104		Trailer	Located and repaired rubbed wire in rear light bar for right side indicator.	Michael Pratten
R-23136	05/12/2017	467718		Trailer	Relined brakes on right side of axle 1 on trailer.	Michael Pratten
S-20914	05/12/2017	467718		A - Fortnighly/5000km	Completed 'A' service.	Michael Pratten

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
R-23135	05/12/2017	467718		Engine	Removed and replaced failed alternator belt tensioner.	Michael Pratten
S-20816	30/11/2017	465927		D - Brakes	Checked and adjusted brakes.	Daniel Phelps
T-3810	30/11/2017	465927		New	Fitted 2 x new 295/80 Bridgestone R150 steer tyres onto axle 1.	Daniel Evans
R-23009	20/11/2017	460378		Trailer	Relined brakes on left side of axle 1 on trailer.	Josh Mills
S-20725	20/11/2017	460378		A - Fortnighly/5000km	Completed 'A' service.	James Hanger
I-549	18/11/2017	459611		COR	Carried out Roadworthy Inspection.	Steve Corby
S-20674	15/11/2017	458697		D - Brakes	Checked and adjusted brakes.	Rhys Cranston
S-20586	06/11/2017	454110		A - Fortnighly/5000km	Completed 'A' service.	Brett Waters
R-22892	04/11/2017	453889		Trailer	Inspected tow eye bush and fingfeeder with go/no-go gauge. Both within specifications and wear limits.	Josh Mills
S-20547	03/11/2017	453888		D - Brakes	Checked and adjusted brakes.	Steve Corby
R-22799	25/10/2017	449568		Clutch	Carried out clutch adjustment.	Daniel Phelps
S-20469	24/10/2017	448927		A - Fortnighly/5000km	Completed 'A' service.	Daniel Phelps
R-22780	24/10/2017	448927		Clutch	Carried out clutch adjustment.	Daniel Phelps
S-20423	19/10/2017	446966		D - Brakes	Checked and adjusted brakes.	Michael Pratten
S-20339	09/10/2017	441571		A - Fortnighly/5000km	Completed 'A' service.	James Hanger
S-20329	05/10/2017	440265		B - 20 000km	Completed 'B' service.	Brett Waters
S-20304	05/10/2017	440265		D - Brakes	Checked and adjusted brakes.	Brett Waters
S-20217	26/09/2017	436365		A - Fortnighly/5000km	Completed 'A' service. (Truck only).	Rhys Cranston
R-22732	26/09/2017			Trailer	Reweld tailgate skin on trailer. Repair hoistwell. Repair front walkways.	Tefco Pty Ltd
S-20172	21/09/2017	435972		D - Brakes	Checked and adjusted brakes.	Daniel Phelps
R-22481	20/09/2017	435971		Suspension	Removed and replaced front springs on truck.	Brett Waters
R-22455	19/09/2017	435971		Engine	Removed and replaced leaking exhaust manifold gaskets.	Brett Waters

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
S-20081	11/09/2017	433155		A - Fortnighly/5000km	Completed 'A' service.	Michael Pratten
S-20038	07/09/2017	431998		D - Brakes	Checked and adjusted brakes.	Daniel Phelps
S-19941	28/08/2017	426186		A - Fortnighly/5000km	Completed 'A' service.	James Hanger
R-22251	28/08/2017	426185		Trailer	Removed and replaced seized right side rear tarp cable pulley on trailer. Replaced seized adjuster bolt. Replaced stretched tarp motor drive chain.	James Hanger
S-19901	22/08/2017	422853		D - Brakes	Checked and adjusted brakes.	Brett Waters
S-19822	14/08/2017	420454		A - Fortnighly/5000km	Completed 'A' service.	Rhys Cranston
S-19777	10/08/2017	419609		D - Brakes	Checked and adjusted brakes.	Steve Corby
T-3667	02/08/2017	416523		Repair	Repaired 3 x punctures in axle 2 right side inner tyre.	Daniel Evans
S-19697	31/07/2017	415251		A - Fortnighly/5000km	Completed 'A' service.	Daniel Phelps
S-19656	26/07/2017	413773		D - Brakes	Checked and adjusted brakes.	James Hanger
R-21913	20/07/2017	411393		Driveline	Replaced 2nd axle RHS axle gasket	Brett Waters
S-19565	17/07/2017	409852		A - Fortnighly/5000km	Completed A service	Brett Waters
R-21853	12/07/2017	408211		Brakes	Relined brakes and replaced brake drum on right side of axle 2 on truck.	Rhys Cranston
S-19528	12/07/2017	408211		D - Brakes	Checked and adjusted brakes.	Rhys Cranston
R-21836	11/07/2017	407684		Trailer	Checked and adjusted ride height on trailer.	Rhys Cranston
S-19438	03/07/2017	404367		A - Fortnighly/5000km	Completed 'A' service.	Steve Corby
S-19392	26/06/2017	401063		D - Brakes	Checked and adjusted brakes.	Daniel Phelps
S-19364	23/06/2017	400228		B - 20 000km	Completed 'B' service.	James Hanger
S-19363	23/06/2017	400228		C - 200 000km	Completed 'C' service.	Matt Norton
S-19298	19/06/2017	398072		A - Fortnighly/5000km	Completed 'A' service.	James Hanger
S-19262	14/06/2017	396031		D - Brakes	Checked and adjusted brakes.	Brett Waters

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
R-21522	06/06/2017	392998		Trailer	Removed and replaced leaking brake booster on left side of axle 3 on trailer.	Rhys Cranston
S-19178	05/06/2017	392114		A - Fortnighly/5000km	Completed 'A' service.	Rhys Cranston
R-21503	05/06/2017	392114		Trailer	Removed and replaced shock absorber on right side of axle 4 on trailer.	Rhys Cranston
R-21503	05/06/2017	392114		Suspension	1.Removed and replaced shock absorber on right side of axle 3 on truck.	Rhys Cranston
S-19124	30/05/2017	389471		D - Brakes	Checked and adjusted brakes.	Steve Corby
T-3564	25/05/2017	387471		New	Fitted 2 x Bridgestone R150 steer tyres onto axle 1.	Daniel Evans
S-19037	22/05/2017	385202		A - Fortnighly/5000km	Completed 'A' service.	Daniel Phelps
R-21355	22/05/2017	385202		Clutch	Carried out clutch adjustment.	Daniel Phelps
R-21355	22/05/2017	385202		Cab	Loosened lower body panel under drivers door, re-aligned and tightened.	Daniel Phelps
R-21345	19/05/2017	384577		Cab	Removed KAB seat and fitted new Isri seat and base.	James Hanger
S-18975	17/05/2017	383328		D - Brakes	Checked and adjusted brakes.	James Hanger
S-18895	09/05/2017	378870		A - Fortnighly/5000km	Completed 'A' service.	Brett Waters
T-3537	09/05/2017	378870		Rotate	Rotated tyres on axle 1 of truck.	Daniel Evans
S-18846	02/05/2017	375526		D - Brakes	Checked and adjusted brakes.	Rhys Cranston
R-21155	02/05/2017	375526		Suspension	Inspected for clunking noise when turning. Located broken weld on left side spring eye bush causing bush to move when turning. Scheduled for repair.	Rhys Cranston
R-21155	02/05/2017	375526		Clutch	Carried out clutch adjustment. *Note-through shaft bearings/bushes worn.* Cleaned out excessive amount of grease and oil in bell housing.	Rhys Cranston
R-21158	02/05/2017	375526		Brakes	Relined brakes and replaced brake drum, S-cam and bushes, inner and outer hub seals and slack adjuster on left side of axle 3 on truck.	Rhys Cranston

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
R-21155	02/05/2017	375526		Cab	Removed and replaced left and right side low beam headlight inserts. Removed and replaced right side high beam headlight insert.	Rhys Cranston
S-18764	24/04/2017	371569		A - Fortnighly/5000km	Completed 'A' service.	Steve Corby
S-18711	19/04/2017	369338		D - Brakes	Checked and adjusted brakes.	Sean Alessi
R-20947	13/04/2017	367766		Trailer	Inspected abnormal light operation on dolley axles on trailer. Located rubbed wires at lights. Rewired completed left side of dolley and replaced indicator and tail light inserts. Rechecked light operation.	Daniel Phelps
S-18631	13/04/2017	367765		A - Fortnighly/5000km	Completed 'A' service.	Daniel Phelps
S-18582	05/04/2017	363290		D - Brakes	Checked and adjusted brakes.	Brett Waters
S-18498	27/03/2017	358854		A - Fortnighly/5000km	Completed 'A' service.	Rhys Cranston
R-20748	23/03/2017	357928		Trailer	Relined brakes and replaced brake drum on left side of axle 2 on trailer.	Steve Corby
S-18437	23/03/2017	357928		D - Brakes	Checked and adjusted brakes.	Steve Corby
S-18357	15/03/2017	353051		A - Fortnighly/5000km	Completed 'A' service.	Michael Pratten
R-20629	10/03/2017	350980		Brakes	Removed and replaced leaking brake booster on left side of axle 2 on truck. Adjusted brake and tested operation.	Daniel Phelps
S-18312	10/03/2017	350980		D - Brakes	Checked and adjusted brakes.	Daniel Phelps
S-18231	02/03/2017	346551		A - Fortnighly/5000km	Completed 'A' service.	Sean Alessi
T-3482	02/03/2017	346551		New	Fitted 8 x Doublecoin RLB-1 drive tyres onto axles 2 and 3. Axle 2 Left side inn off=DAC140,on=DAD308. Left side out off=DAC141,on=DAD309. Right side inn off=DAC142,on=DAD310. Right side out off=DAC143,on=DAD311. Axle 3 Left side inn off=DAC818,on=DAD312. Left side out off=DAC819,on=DAD313. Right side inn off=DAC820,on=DAD314. Right side out off=DAC821,on=DAD315.	Geoff Hobden
T-3477	27/02/2017	344384		Spare	Put spare onto axle 3 left side outer.	Geoff Hobden

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
S-18186	22/02/2017	314919		D - Brakes	Checked and adjusted brakes.	Brett Waters
S-18085	17/02/2017	339638		A - Fortnighly/5000km	Completed A service	Steve Corby
S-18040	10/02/2017	336212		D - Brakes	Checked and adjusted brakes.	Rhys Cranston
R-20347	10/02/2017	336212		Trailer	Removed and replaced damaged tarp cable on trailer.	Rhys Cranston
T-3439	07/02/2017	334267		Spare	Put spare onto axle 2 left side inner.	Geoff Hobden
S-17953	31/01/2017	330370		A - Fortnighly/5000km	Completed 'A' service.	Michael Pratten
R-20294	30/01/2017	325412		Hydraulics	Travelled to Western Leg Road, inspected for repairs. Removed, manufactured and replaced hoist hose as required.	TTH Industries Pty Ltd
S-17920	25/01/2017	328494		D - Brakes	Checked and adjusted brakes.	Daniel Killeen
R-20136	18/01/2017	325448		Steering	Replaced power steering resovoir cap	Sean Alessi
T-3391	16/01/2017	325448		Repair	Repaired leak in axle 3 left side inner tyre.	Geoff Hobden
S-17836	16/01/2017	323974		A - Fortnighly/5000km	Completed 'A' service.	Sean Alessi
R-20079	13/01/2017	325448		Trailer	Adjusted trailer tarp cable	Brodie Connor
S-17790	13/01/2017	322946		D - Brakes	Checked and adjusted brakes	Michael Pratten
R-20080	13/01/2017	325448		Hydraulics	Replaced female hydraulic connector on truck	Josh Mills
S-17757	04/01/2017	319388		B - 20 000km	Completed 'B' service.	Rhys Cranston
S-17714	03/01/2017	318834		A - Fortnighly/5000km	Completed 'A' service.	Rhys Cranston
R-19959	03/01/2017	318834		Brakes	Relined brakes and replaced S-cam and bushes on right side of axle 3 on truck.	Rhys Cranston
S-17663	19/12/2016	315819		D - Brakes	Checked and adjusted brakes.	Steve Corby
R-19840	14/12/2016	314117		Electrical	1.Removed and replaced left and right side outer headlight inserts and globes. 2.Rewired right side of dolly to repair inoperative park light.	Daniel Phelps

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
R-19821	13/12/2016	313364		Air System	Checked trailer brake release button/system. Located faulty traction solenoid. Removed and replaced solenoid and rechecked operation of trailer brake release button.	Steve Corby
S-17586	12/12/2016	312499		A - Fortnighly/5000km	Completed 'A' service.	Daniel Killeen
I-454	25/11/2016	304371		COR	Carried out Roadworthy Inspection.	Steve Corby
R-19541	15/11/2016	298564		Trailer	Removed and replaced drawbar pivot pins and bushes.	Rhys Cranston
T-3272	04/11/2016	294033		New	Fitted and balanced 2 x Bridgestone R-150 tyres on Axle 1. Left side off=DAC286,on=DAD002. Right side off=DAC287,on=DAD003.	Geoff Hobden
R-19114	07/10/2016	279823		Engine	Travelled to Hill Top. Check fan belt tensioner, idlers, etc. Fitted new fan belt, topped up and bled cooling system.	Sean Alessi
R-18962	12/09/2016	194702		Brakes	Relined brakes on right side of axle 2 on truck.	Sean Alessi
R-18933	08/09/2016	265695		Trailer	1.Located and repaired short in right side indicator at back of dolly axles. 2.Removed and replaced right side reverse light insert on rear of trailer.	Brett Waters
R-18843	31/08/2016	262371		Electrical	Inspected wiring plug for right side indicator.Checked ok. Located and replaced inoperative indicator light assembly.	Rhys Cranston
T-3158	27/08/2016	260101		New	Fitted 4 x Bridgestone 722 tyres onto axle 3. Left side inn off=DAC140,on=DAC818. Left side out off=DAC141,on=DAC819. Right side inn off=DAC142,on=DAC820. Right side out off=DAC143,on=DAC821.	Geoff Hobden
R-18791	25/08/2016	260100		Clutch	Adjusted clutch	Jordan Mcgrath
T-3130	10/08/2016	250852		Puncture	Repaired loose valve in axle 2 left side outer wheel.	Geoff Hobden
T-3118	03/08/2016	249736		Puncture	Repaired leaking valve on axle 3 left side outer wheel.	Geoff Hobden
R-18481	28/07/2016	246692		Electrical	Removed and replaced batteries.	Michael Pratten
R-18419	21/07/2016	243279		Brakes	Relined brakes on right side of axle 2 on truck. Relined brakes on left side of axle 2 and left side of axle 3 on truck and replaced S-cams and bushes,slack adjusters and inner hub seals.	Rhys Cranston

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
R-18352	16/07/2016	241027			Kitted ringfeeder.	Michael Pratten
R-18486	12/07/2016			Tarps_dust covers	Repair Auto tarp, straighten bow and re-cable tarp system.	Georges Auto Tarps
S-16173	06/07/2016	237466		D - Brakes	Checked and adjusted brakes.	Brett Waters
R-18032	08/06/2016	227636		Engine	Removed and replaced fan belt tensioner and pulley.	Brett Waters
R-18005	04/06/2016	226845		Trailer	Removed and replaced worn tow eye bush.	Brett Waters
R-17955	30/05/2016	223948		Electrical	Repaired broken wire for left side trailer indicators.	Rhys Cranston
R-17944	26/05/2016	222393		Electrical	1.Repaired pinched/damaged tail light wiring. 2.Removed and replaced trailer Utilux plug.	Daniel Killeen
R-17690	04/05/2016	211420		Clutch	Carried out clutch adjustment.	Brad Redman
S-15425	12/04/2016	200388		C - 200 000km	Completed 'C' service.	Michael Pratten
S-15403	12/04/2016	200388		D - Brakes	Checked and adjusted brakes.	Michael Pratten
S-15424	12/04/2016	200388		B - 20 000km	Completed 'B' service.	Michael Pratten
S-15320	04/04/2016	195555		A - Fortnighly/5000km	Completed 'A' service.	Daniel Phelps
R-17437	30/03/2016	192954		Brakes	Relined brakes on right side of axle 3 on truck.	Sean Alessi
S-15291	30/03/2016	192954		D - Brakes	Checked and adjusted brakes	Sean Alessi
S-15183	22/03/2016	189841		A - Fortnighly/5000km	Completed A service	Brad Redman
T-2833	17/03/2016	170926		New	Fitted and balanced 2 x Bridgestone R-150 onto axle 1. Left side off=unb,on=DAC286. Right side off=unb,on=DAC287.	Geoff Hobden
S-15152	16/03/2016	186666		D - Brakes	Checked and adjusted brakes	Steve Corby
S-15075	10/03/2016	183858		A - Fortnighly/5000km	Completed 'A' service.	Michael Pratten
S-15032	01/03/2016	177493		D - Brakes	Checked and adjusted brakes.	Brett Waters
S-14964	22/02/2016	172960		A - Fortnighly/5000km	Completed 'A' service.	Sean Alessi
S-14911	18/02/2016	171543		D - Brakes	Checked and adjusted brakes.	Brad Redman

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
T-2832	17/02/2016	170582		Spare	Put spare onto axle 1 left side.	Geoff Hobden
T-2831	17/02/2016	170378		Spare	Put spare onto axle 1 right side.	Geoff Hobden
T-2824	13/02/2016	168798		New	Fitted 4 x Bridgestone 722 onto axle 2. Left side inn off=unb,on=DAC280. Left side out off=unb,on=DAC281. Right side inn off=unb,on=DAC282. Right side out off=unb,on=DAC283.	Geoff Hobden
S-14825	09/02/2016	166946		A - Fortnighly/5000km	Completed 'A' service.	Steve Corby
S-14787	04/02/2016	164527		D - Brakes	Checked and adjusted brakes.	Daniel Phelps
S-14668	25/01/2016	159944		D - Brakes	Checked and adjusted brakes.	Michael Pratten
S-14743	25/01/2016	159944		B - 20 000km	Completed 'B' service.	Michael Pratten
S-14712	25/01/2016	159944		A - Fortnighly/5000km	Completed 'A' service.	Michael Pratten
R-16784	15/01/2016	155317		Engine	Carried out full engine valve adjustment.	Michael Pratten
R-16768	15/01/2016	155317		Cooling system	Removed and replaced cracked coolant pipe on rear of engine. Refilled with coolant.	Michael Pratten
T-2746	11/01/2016	153154		New	Fitted 4 x Bridgestone 722 onto axle 3. Left side inn off=DAB226,on=DAC140. Left side out off=DAB227,on=DAC141. Right side inn off=unb,on=DAC142. Right side out off=unb,on=DAC143.	Geoff Hobden
S-14585	11/01/2016	154209		A - Fortnighly/5000km	Completed 'A' service.	Daniel Phelps
S-14561	04/01/2016	154208		D - Brakes	Checked and adjusted brakes.	Daniel Phelps
S-14490	23/12/2015	152406		A - Fortnighly/5000km	Completed 'A' service.	Brett Waters
S-14424	17/12/2015	149003		D - Brakes	Checked and adjusted brakes.	Sean Alessi
S-14345	09/12/2015	145113		A - Fortnighly/5000km	Completed 'A' service.	Brad Redman
R-16456	03/12/2015	142746		Trailer	Removed and replaced leaking brake booster on right side of axle 2 on trailer.	Daniel Evans
S-14310	03/12/2015	142746		D - Brakes	Checked and adjusted brakes.	Trent Blake
R-16385	24/11/2015	137331		Brakes	Relined brakes on left side of axle 3. Tensioned wheel nuts and fitted tyre tag to steering wheel.	Steve Corby

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
S-14235	24/11/2015	137331		A - Fortnighly/5000km	Completed 'A' service.	Steve Corby
R-16358	21/11/2015	135814		Electrical	Fitted and wired up dash camera.	Rhys Cranston
I-366	19/11/2015	134768		COR	Completed Roadworthy inspection	Sean Alessi
S-14198	16/11/2015	132853		D - Brakes	Checked and adjusted brakes.	Rhys Cranston
S-14117	09/11/2015	130029		A - Fortnighly/5000km	Completed 'A' service.	Trent Blake
T-2654	05/11/2015	128957		Runout	Fitted 2 x runouts onto axle 3 left side. Left side inn off=unb,on=DAB226. Left side out off=unb,on=DAB227.	Geoff Hobden
S-14061	04/11/2015	128243		D - Brakes	Checked and adjusted brakes.	Brad Redman
R-16099	29/10/2015	124695		Clutch	Carried out clutch adjustment.	Steve Corby
S-13975	27/10/2015	124113		A - Fortnighly/5000km	Completed A service	Steve Corby
S-13950	19/10/2015	120101		B - 20 000km	Completed 'B' service.	Brad Redman
S-13930	19/10/2015	120101		D - Brakes	Checked and adjusted brakes.	Brad Redman
R-16014	16/10/2015	219526		Cab	Fitted and wired up electrical accessory plug for fridge.	Brett Waters
R-16004	15/10/2015	119020		Cab	Fitted and wired up UHF radio and aerial.	Brett Waters
S-13861	14/10/2015	118455		A - Fortnighly/5000km	Completed 'A' service.	Rhys Cranston
S-13821	09/10/2015	116514		D - Brakes	Checked and adjusted brakes.	Daniel Phelps
R-15979	29/09/2015			Hydraulics	Trailer bin stuck up in the air,got trailer to lower and checked air system.Top up oil as level was low.Change leaking coupling and bleed air from both hoists.Test truck and trailer up and down ok.	Hydreco Hydraulics
S-13740	28/09/2015	111490		A - Fortnighly/5000km	Completed 'A' service.	Michael Pratten
S-13706	25/09/2015	110739		D - Brakes	Checked and adjust brakes.	Steve Corby
R-15812	17/09/2015	106614		Air conditoning_heater	Travelled to workshop,inspected air con system,checked gas and vent temperatures,tightened up low pressure charge port,checked operation as required.	TTH Industries Pty Ltd

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
S-13629	14/09/2015	105773		A - Fortnighly/5000km	Completed 'A' service.	Brett Waters
S-13580	11/09/2015	105773		D - Brakes	Checked and adjusted brakes.	Rhys Cranston
R-15681	11/09/2015	105773		Trailer	Removed and replaced leaking brake booster on right side of axle 4 on trailer.	Rhys Cranston
T-2571	04/09/2015	102587		New	Fitted and balanced 1 x Bridgestone R-150 onto axle 1 left side. Off=unb,on=DAB791.	Geoff Hobden
R-15598	03/09/2015	101984		Fuel System	Cleaned left and right side fuel tank breather pipes to clear any blockages.	Jacob Woods
S-13505	31/08/2015	100128		A - Fortnighly/5000km	Completed 'A' service.	Brad Redman
S-13469	26/08/2015	98160		D - Brakes	Checked and adjusted brakes.	Steve Corby
S-13390	18/08/2015	95581		A - Fortnighly/5000km	Completed A service	Sean Alessi
S-13342	14/08/2015	94172		D - Brakes	Checked and adjusted brakes.	Michael Pratten
S-13261	04/08/2015	89007		A - Fortnighly/5000km	Completed 'A' service.	Brett Waters
R-15279	31/07/2015	87704		Trailer	Removed bent bow in trailer and fitted chain and bow shackles.	Steve Corby
S-13220	31/07/2015	87704		D - Brakes	Checked and adjusted brakes.	Steve Corby
S-13145	20/07/2015	82496		A - Fortnighly/5000km	Completed 'A' service.	Steve Corby
S-13096	15/07/2015	81195		D - Brakes	Checked and adjusted brakes.	Trent Blake
S-13127	15/07/2015	81195		B - 20 000km	Completed 'B' service.	Trent Blake
S-13024	06/07/2015	76915		A - Fortnighly/5000km	Completed A service	Sean Alessi
S-12988	03/07/2015	76382		D - Brakes	Checked and adjusted brakes.	Daniel Phelps
S-12913	22/06/2015	70784		A - Fortnighly/5000km	Completed 'A' service.	Trent Blake
S-12868	15/06/2015	68157		D - Brakes	Checked and adjusted brakes.	Brad Redman
S-12800	09/06/2015	65845		A - Fortnighly/5000km	Completed 'A' service.	Daniel Phelps
T-2452	09/06/2015	65844		New	Fitted 1 x Bridgestone R-150 onto right side of Axle 1 and balanced. Right side off=unb,on=DAB594.	Geoff Hobden

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
R-14780	09/06/2015	65845		Electrical	Removed and replaced left and right side outer headlight inserts.	Michael Pratten
R-14780	09/06/2015	65845		Body	Tapped damaged thread out and fitted helicoil to left side bonnet mounting bracket.Fitted new retaining bolt.	Michael Pratten
S-12752	04/06/2015	65451		D - Brakes	Checked and adjusted brakes.	Brad Redman
S-12676	27/05/2015	62041		A - Fortnighly/5000km	Completed A service	Jacob Woods
S-12633	22/05/2015	59906		D - Brakes	Checked and adjusted brakes.	Daniel Phelps
S-12542	14/05/2015	56510		A - Fortnighly/5000km	Completed 'A' service.	Trent Blake
S-12458	06/05/2015	52426		D - Brakes	Checked and adjusted brakes.	Brad Redman
S-12370	27/04/2015	47746		A - Fortnighly/5000km	Completed 'A' service.	Sean Alessi
S-12330	23/04/2015	46680		D - Brakes	Checked and adjusted brakes.	Jacob Woods
S-12263	13/04/2015	43461		A - Fortnighly/5000km	Completed 'A' service.	Trent Blake
S-12231	09/04/2015	42208		D - Brakes	Checked and adjusted brakes.	Michael Pratten
S-12199	01/04/2015	40181		B - 20 000km	Completed 'B' service.	Brett Waters
R-14180	31/03/2015			Body	Supply and fit grain scraper.	Tefco Pty Ltd
S-12165	30/03/2015	38945		A - Fortnighly/5000km	Completed 'A' service.	Brad Redman
S-12111	25/03/2015	37149		D - Brakes	Checked and adjusted brakes.	Trent Blake
S-12029	17/03/2015	33323		A - Fortnighly/5000km	Completed 'A' service.	Brad Redman
S-11991	13/03/2015	32110		D - Brakes	Checked and adjusted brakes.	Steve Corby
R-13869	05/03/2015	28078		Body	Removed and replaced grain lock type door latches on truck submarine door.	Michael Pratten
S-11922	04/03/2015	27341		A - Fortnighly/5000km	Completed 'A' service.	Rhys Cranston
S-11872	26/02/2015	24898		D - Brakes	Checked and adjusted brakes.	Brett Waters
S-11803	16/02/2015	20125		A - Fortnighly/5000km	Completed 'A' service.	Daniel Phelps
S-11769	09/02/2015	16974		D - Brakes	Checked and adjusted brakes.	Jacob Woods

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
S-11703	02/02/2015	13835		A - Fortnighly/5000km	Completed 'A' service. Repaired air lines at Wabco fitting on rear of truck.	Steve Corby
S-11660	29/01/2015	12763		D - Brakes	Checked and adjusted brakes.	Michael Pratten
S-11574	19/01/2015	10078		A - Fortnighly/5000km	Completed 'A' service.	Trent Blake
R-13409	19/01/2015	10078		Trailer	Adjusted tarp cable on trailer.	Brett Waters
S-11497	15/01/2015	9282		D - Brakes	Checked and adjusted brakes.	Sean Alessi
S-11419	09/01/2015	7747		A - Fortnighly/5000km	Completed 'A' service.	Jacob Woods
R-13276	06/01/2015	6290		Electrical	Repaired severed trailer wiring and Utilux plug on trailer. Re routed wiring away from ringfeeder.	Rob Wilkinson
S-11386	29/12/2014	5867		D - Brakes	Checked and adjusted brakes.	Rhys Cranston
R-13174	17/12/2014	3733		Air System	Fitted air blower/airline kit to cab.	Sean Alessi
S-11291	17/12/2014	3734		A - Fortnighly/5000km	Completed 'A' service.	Brad Redman
R-2059	04/05/2011	271102		Body	1. Fitted new cooling fan clutch assy	

Signed: _____

Name: _____

Date: _____