

Asset History Report

Thursday, 29 October 2

W/O No	Description	Complete	Down time	Repair time	Dur.	P/M	Job Type	Cost
775F-WT03	Caterpillar 775F Dump Truck - TE753							
1124	250HR Caterpillar 775F	8/05/2014	.00	.00	.00	95	PM	\$0.00
1184	Fit new check valve in fuel system	9/04/2014	.00	.00	.00		Unplanned	\$0.00
1232	Fit mine radio	20/04/2014	.00	.00	.00		Planned M	\$0.00
1245	Repair Sprays	25/04/2014	.00	.00	.00		Unplanned	\$0.00
1246	Cracks in tank	19/09/2014	.00	.00	.00		Planned M	\$0.00
1247	Mud Guard U/S pos 4	30/04/2014	.00	.00	.00		Planned M	\$0.00
1248	Water pump bearing U/s	1/05/2014	.00	.00	.00		Unplanned	\$0.00
1307	UHF fault	5/05/2014	.00	.00	.00		Unplanned	\$0.00
1309	Blown main grease line	10/05/2014	.00	.00	.00		Planned M	\$0.00
1358	Jumped out of 6th gear under load	10/05/2014	.00	.00	.00		Unplanned	\$0.00
1359	RH Window doesn't close	9/11/2014	.00	.00	.00		Planned M	\$0.00
1452	Repair Vision Link	23/09/2014	.00	.00	.00		Planned M	\$0.00
1472	Signs need replacing - they are unreadable.	29/08/2014	.00	.00	.00		Planned M	\$0.00
1493	2000HR Caterpillar 775F	15/07/2014	.00	.00	.00	98	PM	\$0.00
1511	Lights failing.	6/05/2014	.00	.00	.00		Opportune	\$0.00
1520	left window latch broken	9/11/2014	.00	.00	.00		Opportune	\$0.00
1548	Tank leaking.	20/09/2014	.00	.00	.00		Opportune	\$0.00
1569	Rear work lights not working. Cannot see during night shift. Get lights fixed.	15/06/2014	.00	.00	.00		Opportune	\$0.00
1602	2000HR Caterpillar 775F	15/07/2014	.00	.00	.00	98	PM	\$0.00

W/O No	Description	Complete	Down time	Repair time	Dur.	P/M	Job Type	Cost
1603	500HR Caterpillar 775F	15/07/2014	.00	.00	.00	96	PM	\$0.00
1701	no rubber door stop	9/11/2014	.00	.00	.00		Opportune	\$0.00
1776	2000HR Caterpillar 775F	15/07/2014	.00	.00	.00	98	PM	\$0.00
1779	1000HR Caterpillar 775F	15/07/2014	.00	.00	.00	97	PM	\$0.00
1782	500HR Caterpillar 775F	15/07/2014	.00	.00	.00	96	PM	\$0.00
1784	250HR Caterpillar 775F	15/07/2014	.00	.00	.00	95	PM	\$0.00
1791	starting fault	16/02/2015	.00	.00	.00		Opportune	\$0.00
1817	2000HR Caterpillar 775F	16/07/2014	.00	.00	.00	98	PM	\$0.00
1819	1000HR Caterpillar 775F	16/07/2014	.00	.00	.00	97	PM	\$0.00
1821	500HR Caterpillar 775F	16/07/2014	.00	.00	.00	96	PM	\$0.00
1829	door window seal needs replacing	9/11/2014	.00	.00	.00		Opportune	\$0.00
1830	wheel end off 453 fitted to lhr	9/11/2014	.00	.00	.00		Planned M	\$0.00
1831	monitor steering oil, getting water in it	4/05/2015	.00	.00	.00		Inspection	\$0.00
2638	need to change out eng breathers	1/10/2014	.00	.00	.00		Planned M	\$0.00
2639	change out middle spary tap	30/01/2015	.00	.00	.00		Planned M	\$0.00
2761	Grease fault - dump vavle not working, requires change out.	9/11/2014	.00	.00	.00		Planned M	\$0.00
2968	lhr spary u/s	11/04/2015	.00	.00	.00		Unplanned	\$0.00
2969	check hose real on back off tank	30/01/2015	.00	.00	.00		Inspection	\$0.00
3018	back flashing light not working	6/02/2015	.00	.00	.00			\$0.00
3020	frount disc brake pads down to only approxy 4mm linning left, replaced at15050hrs	16/05/2015	.00	.00	.00		Preventati	\$0.00
3021	changed out @ 15050 with re sealed strut	16/05/2015	.00	.00	.00		Opportune	\$0.00
3022	4 x fuel injectors u/s	16/02/2015	.00	.00	.00		Unplanned	\$0.00
3023	fit new fuel lift pump reman	16/02/2015	.00	.00	.00		Opportune	\$0.00

W/O No	Description	Complete	Down time	Repair time	Dur.	P/M	Job Type	Cost
3057	hoist and brake pump replace with new 14990hrs , new accumulator charge valve fitted	22/02/2015	.00	.00	.00			\$0.00
3071	replace fan hub groupfitted updated fan hub assembly group smu 14990	7/03/2015	.00	.00	.00		Opportune	\$0.00
3072	replace tran harness	1/03/2015	.00	.00	.00			\$0.00
3180	changed out with reseald strut @15050hrs	16/05/2015	.00	.00	.00		Opportune	\$0.00
3181	fitted tran@ 15050hrs	4/05/2015	.00	.00	.00		Opportune	\$0.00
3182	replace trans harness parts ordered	4/05/2015	.00	.00	.00		Opportune	\$0.00
3183	fit up brake pipes and pies to filter that are all rusted out	25/04/2015	.00	.00	.00		Opportune	\$0.00
3276		5/06/2015	.00	.00	.00			\$0.00
3339	replace grease controller / fitted new controller	19/06/2015	.00	.00	.00		Planned M	\$0.00
3362	stair light not working	16/07/2015	.00	.00	.00			\$0.00
3363	flashing light not working	16/07/2015	.00	.00	.00			\$0.00
3364	auto grease pump faulty / resealed grease pump leg 15278	16/07/2015	.00	.00	.00			\$0.00
3365	spray valve control box wont lock shut	15/08/2016	.00	.00	.00			\$0.00
3366	replace rubber on front assces steps, strighten rh step bracket / done 15278	16/07/2015	.00	.00	.00			\$0.00
3367	replace screws in steering colomn parts ordered	28/08/2015	.00	.00	.00			\$0.00
3368	check frunt strut hights and regas	8/08/2015	.00	.00	.00			\$0.00
3369	replace raditor hose bottom of raditor/ done	16/07/2015	.00	.00	.00			\$0.00
3370	corrored break line part no: 246-4521 ;parts ordered	28/08/2015	.00	.00	.00			\$0.00
3371	replace lh mud flap missing	15/08/2016	.00	.00	.00			\$0.00
3372	fit caps to rear grease injectors	28/08/2015	.00	.00	.00			\$0.00
3373	reseal starter motor ;parts ordered	28/08/2015	.00	.00	.00			\$0.00

W/O No	Description	Complete	Down time	Repair time	Dur.	P/M	Job Type	Cost
3374	repair oil leak at batter spary valve	10/08/2015	.00	.00	.00			\$0.00
3375	replace all window seals and door; parts ordered	18/08/2016	.00	.00	.00			\$0.00
3669	Overhaul Transmission/ change out	18/10/2015	.00	.00	.00		Planned M	\$0.00
3693	grease system fault alram going off	18/08/2016	.00	.00	.00		Planned M	\$0.00
3757	Reel Motor on retractable hose reel at rear of tank loose and leaking	18/08/2016	.00	.00	.00		Opportune	\$0.00
3758	Adjust spray on canon - slow down change up and down	18/08/2016	.00	.00	.00		Opportune	\$0.00
3759	Reverse Light	18/08/2016	.00	.00	.00		Opportune	\$0.00
3760	Transmission temp - getting hot	18/10/2015	.00	.00	.00		Opportune	\$0.00
3906	Install Torque convertor from spare truck in Nerang yard. (Not rebuilt)	6/10/2015	.00	.00	.00		Planned M	\$0.00
7115		30/05/2018	.00	.00	.00		Planned M	\$0.00
7735	replaced a/c delay timer'	29/02/2016	.00	.00	.00		Opportune	\$0.00
11392	rear suspension strut needs to be Removed and resealed - complete	25/09/2017	.00	.00	.00		Planned M	\$0.00
14500	Chassis and guards to have rust repaired including handrails mirrors etc	17/12/2018	.00	.00	.00		Planned M	\$0.00
15807	Remove Cab from body & Re-Assembly body parts back onto truck as req,d b Luke Turner	17/12/2018	.00	.00	.00		Planned M	\$0.00
15846	Exhaust lines and pipes & turbo lines Machine Hours 15661	17/12/2018	.00	.00	.00		Opportune	\$0.00
15851		17/09/2018	.00	.00	.00			\$0.00
15854	Tank electrical harness to be repairedLower two sensors are not workingLights are not all working Check all lights and harness	17/12/2018	.00	.00	.00		Opportune	\$0.00
15880	Hydraulic Tank and Hose Repairs in work shop Nerang	17/12/2018	.00	.00	.00		Opportune	\$0.00
17146	Rear suspension wish bone movment at both pins	17/12/2018	.00	.00	.00		Planned M	\$0.00
17147	Steering cylinder lh rh barrel end movment at ball joint	17/12/2018	.00	.00	.00		Planned M	\$0.00

W/O No	Description	Complete	Down time	Repair time	Dur.	P/M	Job Type	Cost
17148	Steering cylinder pivot point at chassis, investergate up and down movment, possible loose pin retaining bolts	17/12/2018	.00	.00	.00		Planned M	\$0.00
17149	A frame movment at pin and bearing investergate	17/12/2018	.00	.00	.00		Planned M	\$0.00
17152	Replace trans scavange hose	17/12/2018	.00	.00	.00		Planned M	\$0.00
17157	Rh side steer cylinder leaking, chrome on rod scored	17/12/2018	.00	.00	.00		Planned M	\$0.00
17172	Check Rear Pins / Bushes on Suspension Nerang work shop	17/12/2018	.00	.00	.00		Planned M	\$0.00
17181	Fire extinguishers & Brackets to be installed	17/12/2018	.00	.00	.00		Planned M	\$0.00
17182	Mud Flaps to be istalled	17/12/2018	.00	.00	.00		Planned M	\$0.00
17183	Check last Service is up to date Nerang work shop	17/12/2018	.00	.00	.00		Planned M	\$0.00
17184	Water tank to shimmed tank Pads	17/12/2018	.00	.00	.00		Planned M	\$0.00
17185	Cab filter door panel missing retainer bolt	17/12/2018	.00	.00	.00		Planned M	\$0.00
17186	Cab am/fm radio to be replaced	17/12/2018	.00	.00	.00		Planned M	\$0.00
17187	Cannon control panel missing screws to be replaced	17/12/2018	.00	.00	.00		Planned M	\$0.00
17188	Seat belt frayed & broken switches & valves on seat	17/12/2018	.00	.00	.00		Planned M	\$0.00
17189	Cab - Auxiliary switches in overhead to be replaced	17/12/2018	.00	.00	.00		Planned M	\$0.00
17190	Air filter indicator to be replaced	17/12/2018	.00	.00	.00		Planned M	\$0.00
17191	Hydraulic tank Breather to be replaced	17/12/2018	.00	.00	.00		Planned M	\$0.00
17192	Engine bay clamps to be replaced, remove zip ties	17/12/2018	.00	.00	.00		Planned M	\$0.00
17193	Cab pin L/H/R bolts re-tighten	17/12/2018	.00	.00	.00		Planned M	\$0.00
17194	Water tank Funnels to have bolts replaced	17/12/2018	.00	.00	.00		Planned M	\$0.00
17196	Dash to have missing screws replaced	17/12/2018	.00	.00	.00		Planned M	\$0.00
17197	Antennna Grommet to be replaced	17/12/2018	.00	.00	.00		Planned M	\$0.00
24765	steering - remove tank clean out debrie / completed	5/12/2019	.00	.00	.00		Planned M	\$0.00

W/O No	Description	Complete	Down time	Repair time	Dur.	P/M	Job Type	Cost
24766	steering - replace failed steering piston pump with reman / fitted reman pump	5/12/2019	.00	.00	.00		Planned M	\$0.00
24767	steering - replace hoses to piston pump / completed	5/12/2019	.00	.00	.00		Planned M	\$0.00
24768	chassis - complete paint job, refit all panels etc	5/12/2019	.00	.00	.00		Planned M	\$0.00
24769	water tank - replace hoses to spray heads as required / completed	5/12/2019	.00	.00	.00		Planned M	\$0.00
24770	truck - fit up decals and call up signs / completed	5/12/2019	.00	.00	.00		Planned M	\$0.00
24771	chassis - fit up wheel chocks / done	5/12/2019	.00	.00	.00		Planned M	\$0.00
24772	truck - bma spec machine / done	5/12/2019	.00	.00	.00		Planned M	\$0.00
24773	engine - replace sight gauge for radiator	5/12/2019	.00	.00	.00		Planned M	\$0.00
24816	chassis - replace all rims and tires / compliant rims from caval ridge fitted x 6. 2 x new bridgstone fitted to steer. 4 x michellin fited to drive	5/12/2019	.00	.00	.00		Planned M	\$0.00
24853	Cab - wire for mine radio / done	5/12/2019	.00	.00	.00		Planned M	\$0.00
24854	Engine - fit up turbo manifold blankets/ done	5/12/2019	.00	.00	.00		Planned M	\$0.00
24855	Cab - replace missing rh side mirrors / done 2 x new	5/12/2019	.00	.00	.00		Planned M	\$0.00
24856	Water tank - locate gutter guards and send with truck / completed	5/12/2019	.00	.00	.00		Planned M	\$0.00
24857	electrical - replace starter lock out / done	5/12/2019	.00	.00	.00		Planned M	\$0.00
25209	Chassis - fabricate mine radio bracket to suit supplied radio. blackwater department to complete	30/03/2020	.00	.00	.00		Planned M	\$0.00
25210	Chassis - Tire and rim info to relevant register, Blackwater department	30/03/2020	.00	.00	.00		Inspection	\$0.00
25359	Body - Steps to make BMA compliant	30/03/2020	.00	.00	.00		Planned M	\$0.00
25459	Coolant to be changed onsite	30/03/2020	.00	.00	.00		Planned M	\$0.00
25460	RHS Rear strut leaking from schroder valve	1/04/2021	.00	.00	.00		Planned M	\$0.00
25461	4.5kg fire extinguisher install RHS	30/03/2020	.00	.00	.00		Unplanned	\$0.00

W/O No	Description	Complete	Down time	Repair time	Dur.	P/M	Job Type	Cost
25462	Hand rails at front of machine to be welded	30/03/2020	.00	.00	.00		Unplanned	\$0.00
25463	Engine- Alternator belt cover for compliance	30/03/2020	.00	.00	.00		Unplanned	\$0.00
25464	Install Steps- BMA compliance	30/03/2020	.00	.00	.00		Planned M	\$0.00
25468	hydraulic actuators for rear sprays are leaking	8/06/2020	.00	.00	.00		Unplanned	\$0.00
25470	Fuel water seperator rubbers are worn, need replacing	22/12/2019	.00	1.00	.00		Planned M	\$0.00
25471	coolant- sight glass and -o ring replace	22/12/2019	.00	1.00	.00		Planned M	\$0.00
25478	stauf clamps from Ryco for installing fire ex onto machine BMA compliance	30/03/2020	.00	.00	.00		Unplanned	\$0.00
25480	Lights- Replace LHS brake-indicator light	8/06/2020	.00	.00	.00		Planned M	\$0.00
25480	Lights- Replace LHS brake-indicator light	22/12/2019	.00	1.00	.00		Planned M	\$0.00
25774	Check valve from Ryco for fuel tank	28/02/2020	.00	.00	.00		Planned M	\$0.00
28919	engine-replace blown hose on R/H turbo outlet	18/03/2020	.00	.00	.00		Unplanned	\$0.00
29042	Repair Grease hose	28/03/2020	.00	1.00	.00		Unplanned	\$0.00
29155	Replace UHF radio	29/02/2020	.00	1.00	.00		Unplanned	\$0.00
29158	Start fault/ winding over after priming fuel.	3/06/2020	.00	.00	.00		Monitor	\$0.00
29160	Engine- Tapper cover Gasket leaking c/o	27/04/2020	20.00	20.0	.00		Unplanned	\$0.00
29161	Exhaust- LH exhaust clamp to turbo missing	17/04/2020	.00	.00	.00		Unplanned	\$0.00
29193	1000HR SERVICE	2/09/2020	.00	.00	.00		Planned M	\$0.00
29280	WATER SYSTEM PUMP TURNS OFF	8/06/2020	.00	.00	.00		Unplanned	\$0.00
29309	diagnose Starting issue, check valve engine fuel return	3/06/2020	.00	.00	.00			\$0.00
29415	1000hr Service	14/04/2020	.00	.00	.00		Planned M	\$0.00
29625	Lights- RHS top work light not working	8/06/2020	.00	.00	.00		Planned M	\$0.00
29626	Water level lights need to be checked u/s	1/04/2021	.00	.00	.00		Planned M	\$0.00

W/O No	Description	Complete	Down time	Repair time	Dur.	P/M	Job Type	Cost
29627	sprays- Stones blocking sprays- Flush and repair	8/06/2020	.00	.00	.00		Planned M	\$0.00
29792	Cracked Intimediate cover- Replace Harness	8/06/2020	.00	.00	.00		Unplanned	\$0.00
29810	LHS Steer Cylinder weeping	3/06/2020	.00	.00	.00		Monitor	\$0.00
29811	Fire suppression gauge on bottle missing top, gauge u/s	8/06/2020	.00	.00	.00		Unplanned	\$0.00
29857	Replace Fuel Priming pump	10/05/2020	.00	.00	.00		Unplanned	\$0.00
29857	Replace Fuel Priming pump	10/05/2020	.00	.00	.00		Unplanned	\$0.00
29992	Corrective Action- Flush Coolant x3 extremely high Iron.	8/05/2020	2.00	2.00	.00		Planned M	\$0.00
30027	BMA Fire Suppression - 6 Monthly - CMS requirement	8/06/2020	.00	.00	.00	293	BMA CMS	\$0.00
30067	Rear Blue flashing light u/S	18/06/2020	.00	.00	.00			\$0.00
30068	LHS rear tail light U/S	30/06/2020	.00	.00	.00			\$0.00
30069	LHS rear mud flap is torn	8/06/2020	.00	.00	.00			\$0.00
30070	Tank level indicator light U/S	1/04/2021	.00	.00	.00			\$0.00
30075	Replace Diff dog bone pin retainer	9/05/2020	.00	1.00	.00		Unplanned	\$0.00
30084	Engine oil Leak	23/05/2020	.00	.00	.00			\$0.00
30105	Damage to steps- Front LHS step change if required	18/06/2020	.00	.00	.00		Accident	\$0.00
30106	Engine- Water pump leaking out of tell tale hole Replaced water pump.	14/05/2020	.00	.00	.00		Unplanned	\$0.00
30192	Steering- replace leaking LH steering cylinder	30/06/2020	.00	.00	.00		Monitor	\$0.00
30234	boilermaker-	8/06/2020	.00	.00	.00			\$0.00
30241	Replace A/C compressor	22/05/2020	.00	.00	.00		Unplanned	\$0.00
30421	Service- 250hr	8/06/2020	.00	.00	.00		Planned M	\$0.00
30535	Radiator- Leaking core	25/11/2020	.00	.00	.00			\$0.00
30638	Hoist valve leaking	9/07/2020	.00	.00	.00			\$0.00
30639	Engine oil Leak front timing cover	9/07/2020	.00	.00	.00			\$0.00

W/O No	Description	Complete	Down time	Repair time	Dur.	P/M	Job Type	Cost
30699	Valve for auxiliary water pump is leaking- needs to be washed and diagnosed(possibly the hoist pump valve	9/07/2020	.00	.00	.00		Monitor	\$0.00
30700	Aux Water pump oil lines are leaking- requires o-rings	1/07/2021	.00	.00	.00		Monitor	\$0.00
30730	Radiator- C/O leaking radiator	9/07/2020	.00	.00	.00		Planned M	\$0.00
30814	LHS front cam shaft cover seal	9/07/2020	.00	.00	.00		Unplanned	\$0.00
30871	Eng-fuel dilution in eng oil	2/09/2020	.00	.00	.00			\$0.00
31389	Replace Injector o-rings	9/07/2020	.00	.00	.00		Unplanned	\$0.00
31643	CAB- indicator/ washer switch	25/08/2020	.00	.00	.00		Unplanned	\$0.00
31715	Cab-replace door seal	26/07/2020	.00	.00	.00			\$0.00
31813	500hr Service	27/08/2020	.00	5.00	.00		Planned M	\$0.00
31825	C/O leaking heater taps	14/08/2020	.00	.00	.00		Planned M	\$0.00
31984	Brake/ Hoist pump failure	14/08/2020	.00	.00	.00		Planned M	\$0.00
32001	PO required for Boom Crane hire to complete hoist pump remove and install onsite	6/08/2020	.00	.00	.00		Planned M	\$0.00
32369	Brake temp sensor	21/06/2021	.00	.00	.00		Unplanned	\$0.00
32394	Park brake filters	15/10/2020	.00	.00	.00		Planned M	\$0.00
32481	Indicator switch C/O	2/09/2020	.00	.00	.00		Unplanned	\$0.00
32515	Pressure switch 300 BAR U/S	2/09/2020	.00	.00	.00		Unplanned	\$0.00
32518	RHR window seal and lower hingeJob completed Mario	3/12/2021	.00	.00	.00		Planned M	\$0.00
32547	water pump primming issue	15/06/2021	.00	.00	.00			\$0.00
32548	Grease line leak RHS rear	15/06/2021	.00	.00	.00			\$0.00
32775	C/O brake cooler Return hose	25/11/2020	.00	.00	.00		Planned M	\$0.00
32776	Hydraulic oil tank repair minor leak next 1000hr service	5/02/2022	.00	.00	.00			\$0.00
33274	250hr service	13/10/2020	.00	4.00	.00		Planned M	\$0.00

W/O No	Description	Complete	Down time	Repair time	Dur.	P/M	Job Type	Cost
33723	inspect Auto greaser fault	15/06/2021	.00	.00	.00			\$0.00
34073	BMA Fire Suppression & Extinguishers - 6 Monthly - CMS requirement	19/11/2020	.00	.00	.00	293	BMA CMS	\$0.00
34739	Replace faulty grease dump valve solenoid	12/11/2020	.00	.00	.00			\$0.00
34925	1000hr service	20/11/2020	.00	8.00	.00			\$0.00
35181	BMA Mechanical Compliance - 12 Monthly Inspection - CMS Requirement	1/12/2020	.00	.00	4.00	283	BMA CMS	\$0.00
35208	Starter motor leaking	23/05/2021	.00	.00	3.00			\$0.00
35209	Cab mount missing bolt and washer and cab mount has fallen out	15/06/2021	.00	.00	.00		Planned M	\$0.00
35210	Front of Oil coolers leaking	1/07/2021	.00	.00	4.00		Planned M	\$0.00
35211	Steering Cylinder RH Weeping	2/02/2022	.00	.00	5.00		Planned M	\$0.00
35219	Rear hose reel motor needs securing	15/06/2021	.00	.00	.00			\$0.00
35220	Both RH struts need pumping up	15/06/2021	.00	.00	.00			\$0.00
35221	The wiring harness over the tank needs replacing u/s green death through it all. Temp sensors to be installed	15/06/2021	.00	.00	.00		Planned M	\$0.00
35223	PO required for Blue chip to transport the machine from Blackwater mine to Blue chip yard, then Blue chip yard to Vulcan mine	2/12/2020	.00	.00	.00			\$0.00
35702	replace fingers in water pump drive coupling omega couplings fitted	15/12/2020	.00	.00	.00			\$0.00
35838	Tail light repair rear left	23/05/2021	.00	.00	.00		Planned M	\$0.00
35841	Horn button replace	15/06/2021	.00	.00	.00		Unplanned	\$0.00
35857	Hose reel shaft broken	15/06/2021	.00	.00	.00		Unplanned	\$0.00
36522	Water Pump Hose Blown	21/01/2021	.00	.00	.00		Unplanned	\$0.00
36956	Exhaust leak to be repaired	23/05/2021	.00	.00	.00		Planned M	\$0.00
36957	Replace fan and alternator belt, Completed By Rab	18/04/2021	.00	.00	.00		Planned M	\$0.00

W/O No	Description	Complete	Down time	Repair time	Dur.	P/M	Job Type	Cost
36959	Sensor faults	23/05/2021	.00	.00	.00		Planned M	\$0.00
37071	777 Off Highway Truck - 750 Hour Service	25/02/2021	.00	.00	.00	178	Preventati	\$0.00
37146	Fuel cooler failed	15/06/2021	.00	.00	.00		Unplanned	\$0.00
37280	777 Off Highway Truck - 1000 Hour Service, Service Completed On 14/03/21	3/04/2021	.00	.00	.00	177	Preventati	\$0.00
37622	Engine speed sensor	3/04/2021	.00	.00	.00		Unplanned	\$0.00
37940	replace batteries1x N150, Replaced By Chris Grant On 15/04/21	18/04/2021	.00	.00	.00			\$0.00
38270	AM/FM not working	25/04/2021	.00	.00	.00		Planned M	\$0.00
38271	Cracked wheel chock frame	15/06/2021	.00	.00	.00		Planned M	\$0.00
38411	777 Off Highway Truck - 250 Hour Service, Completed By Chris Grant On 15/04/21	10/04/2021	.00	.00	.00	175	Preventati	\$0.00
39098	777 Off Highway Truck - 500 Hour Service	18/07/2021	.00	.00	.00	176	Preventati	\$0.00
39111	Strut RH rear replacement	5/02/2022	.00	.00	.00		Planned M	\$0.00
39241	777 Off Highway Truck - 250 Hour Service	21/06/2021	.00	.00	.00	178	Preventati	\$0.00
39300	BMA Fire Suppression & Extinguishers - 6 Monthly - CMS requirement	24/05/2021	.00	.00	.00	293	BMA CMS	\$0.00
39558	777 Off Highway Truck - 1000 Hour Service	19/05/2021	.00	.00	.00	177	Preventati	\$0.00
39735	Transmission screen	1/07/2021	.00	.00	.00		Planned M	\$0.00
39736	Replace fan and ac belt	15/06/2021	.00	.00	.00		Planned M	\$0.00
39740	Transmission charge hose	15/06/2021	.00	.00	.00		Planned M	\$0.00
39741	SOS caps	15/06/2021	.00	.00	.00		Planned M	\$0.00
39742	Transmission output sensor to be replaced	15/06/2021	.00	.00	.00		Planned M	\$0.00
39743	Transmission hose replace	15/06/2021	.00	.00	.00		Planned M	\$0.00
39744	Fuel cooler	1/07/2021	.00	.00	.00		Planned M	\$0.00

W/O No	Description	Complete	Down time	Repair time	Dur.	P/M	Job Type	Cost
39747	LH step rubbers	21/06/2021	.00	.00	.00		Planned M	\$0.00
40181	Steering link pin and bush worn	5/02/2022	.00	.00	.00		Planned M	\$0.00
40327	Tail light replace LH assembly	5/02/2022	.00	.00	.00		Planned M	\$0.00
40602	TE454 500hr Service	28/07/2021	.00	.00	.00		Preventati	\$0.00
41650	777 Off Highway Truck - 750 Hour Service	16/08/2021	.00	6.00	.00	178	Preventati	\$0.00
42305	replace A frame bearing	5/02/2022	.00	.00	.00		Planned M	\$0.00
42306	replace worn steering ball joints	5/02/2022	.00	6.00	.00			\$0.00
42706	777 Off Highway Truck - 1000 Hour Service	7/09/2021	.00	18.0	.00	177	Preventati	\$0.00
42857	replace bent trans suction screen	4/12/2021	.00	.00	.00			\$0.00
42858	re-seal leaking starter motor mount	12/01/2022	.00	.00	.00			\$0.00
43343	repauir blown trans hoseHoses 24 #TK06-2309	24/09/2021	.00	6.00	6.00		Unplanned	\$0.00
43344	replace worn trans hose	12/01/2022	.00	.00	.00		Planned M	\$0.00
43352	777 Off Highway Truck - 250 Hour Service	6/10/2021	.00	8.00	.00	175	Preventati	\$0.00
43711	777 Off Highway Truck - 500 Hour Service	21/10/2021	.00	12.0	.00	176	Preventati	\$0.00
44076	replace a/c low pressurevswitch	28/10/2021	.00	4.00	.00			\$0.00
44139	Brake Test - 6 Monthly Inspection - CMS Requirement	8/11/2021	.00	.00	.00	384	BMA CMS	\$0.00
44396	777 Off Highway Truck - 250 Hour Service	7/11/2021	.00	8.00	.00	175	Preventati	\$0.00
44453	777 Off Highway Truck - 1000 Hour Service	3/12/2021	.00	12.0	.00	177	Preventati	\$0.00
44608	check trans for slipping Trans overhauled Mario November 2021	4/12/2021	.00	.00	.00		Unplanned	\$0.00
44642	Transmission rebuildReplace 1st & 2nd clutch seals	19/11/2021	.00	.00	.00		Unplanned	\$0.00
44810	Starting fault	22/11/2021	.00	.00	.00		Unplanned	\$0.00
44854	replace fuel hose	29/11/2021	.00	6.00	.00		Planned M	\$0.00
44900	Fire Suppression & Extinguishers - 6 Monthly - CMS	3/12/2021	.00	.00	.00	293	BMA CMS	\$0.00

W/O No	Description	Complete	Down time	Repair time	Dur.	P/M	Job Type	Cost
45106	requirement Level 2 service	16/12/2021	.00	.00	.00			\$0.00
45123	777 Off Highway Truck - 250 Hour Service	5/01/2022	.00	8.00	.00	175	Preventati	\$0.00
45667	Water leaking into cab	20/02/2022	.00	.00	.00		Unplanned	\$0.00
45790	777 Off Highway Truck - 500 Hour Service Service completed and defect W/O raised.	21/01/2022	.00	18.0	.00	176	Preventati	\$0.00
46012	Air filter clips	24/04/2022	.00	1.00	.00		Unplanned	\$0.00
46013	Broken radiator fan shroud	6/02/2022	.00	.00	.00		Unplanned	\$0.00
46181	777 Off Highway Truck - 250 Hour Service	6/02/2022	.00	12.0	.00	175	Preventati	\$0.00
46196	777 Off Highway Truck - 1000 Hour Service	20/02/2022	.00	12.0	.00	177	Preventati	\$0.00
46566	Rock box leaking	5/02/2022	.00	.00	.00		Unplanned	\$0.00
46589	WDS fault	20/02/2022	.00	.00	.00		Unplanned	\$0.00
46833	Spray bar fault	10/02/2022	.00	.00	.00		Planned M	\$0.00
46862	Pre start - headlights	12/02/2022	.00	.00	.00		Planned M	\$105.00
46914	Tap on rear of machine fallen off	11/02/2022	.00	.00	.00		Planned M	\$0.00
46923	sprays not working	12/02/2022	.00	.00	.00		Unplanned	\$0.00
46934	replace pos 2 tyre	12/03/2022	.00	.00	.00		Planned M	\$0.00
47166	Fit new ID numbers	12/03/2022	.00	.00	.00		Planned M	\$0.00
47405	777 Off Highway Truck - 250 Hour Service-WT753 (454)	9/03/2022	.00	10.0	.00	175	Preventati	\$0.00
47409	Prestart - Water leaking into cab	22/04/2022	.00	.00	.00		Unplanned	\$0.00
47411	Prestart - Water meter not working	24/04/2022	.00	1.00	.00			\$0.00
47430	Prestart - AM/FM radio not working properly	27/03/2022	.00	.00	.00			\$210.00
47444	777 Off Highway Truck - 500 Hour Service	25/03/2022	.00	12.0	.00	176	Preventati	\$1,023.00
47728	Prestart - AM/FM radio reception poor (2)	27/03/2022	.00	.00	.00			\$0.00

W/O No	Description	Complete	Down time	Repair time	Dur.	P/M	Job Type	Cost
47729	Prestart - All windows scratched	22/04/2022	.00	.00	.00			\$0.00
47730	Prestart - R/H rear light bracket broken	22/04/2022	.00	.00	.00			\$180.00
47731	Prestart - Requires new window seals	27/06/2022	.00	.00	.00		Pre-Start	\$0.00
47918	Prestart - AM/FM radio aerial u/s	27/06/2022	.00	3.00	.00		Unplanned	\$0.00
47919	prestart - Water level indicators hard to read. (2)	24/04/2022	.00	1.00	.00		Unplanned	\$0.00
47920	Prestart - RH rear light bracket (2)	22/04/2022	.00	.00	.00		Unplanned	\$0.00
47921	Prestart - Cab seals leaking	27/06/2022	.00	.00	.00		Pre-Start	\$0.00
47922	Prestart - UHF reception poor	24/04/2022	.00	1.00	.00		Unplanned	\$0.00
47988	Prestart-lube system alarm fault (2)	22/04/2022	.00	.00	.00		Unplanned	\$0.00
48069	POS 1 steer cylinder	17/09/2022	.00	.00	.00		Planned M	\$0.00
48473	Prestart - Centre barrel leaking	22/04/2022	.00	.00	.00			\$0.00
48474	Prestart - Side wall cut in tyre Pos 2	22/04/2022	.00	.00	.00			\$0.00
48499	777 Off Highway Truck - 750 Hour Service	7/04/2022	.00	6.00	.00	175	Preventati	\$0.00
48549		24/03/2022	.00	.00	.00		Unplanned	\$192.00
48558		24/03/2022	.00	.00	.00		Unplanned	\$210.00
48610	Prestart - Leak in Dropbox	22/04/2022	.00	.00	.00			\$180.00
48620		25/03/2022	.00	.00	.00		Planned M	\$180.00
48633	Grease system not working	22/04/2022	.00	.00	.00		Unplanned	\$861.00
48704	Prestart - Windows scratched	22/04/2022	.00	.00	.00		Unplanned	\$0.00
48717	777 Off Highway Truck - 1000 Hour Service	22/04/2022	.00	12.0	.00	177	Preventati	\$0.00
48793	Prestart - Steering column vertical lock U/S	5/04/2022	.00	1.00	.00		Unplanned	\$0.00
48840	Fuel leak at engine	15/05/2022	.00	.00	.00		Unplanned	\$525.00
49056	Replace grease hose on truck	5/04/2022	.00	1.00	.00		Unplanned	\$105.00

W/O No	Description	Complete	Down time	Repair time	Dur.	P/M	Job Type	Cost
49065		6/04/2022	.00	.00	.00		Unplanned	\$0.00
49080	Adjust seat head rest	6/04/2022	.00	.50	.00		Unplanned	\$0.00
49184	Steering column wont adjust	15/05/2022	.00	.00	.00		Planned M	\$0.00
49190	Engine fuel line replacements	15/05/2022	.00	.00	.00		Planned M	\$445.00
49208	LH sprays not working	22/04/2022	.00	.00	.00		Unplanned	\$0.00
49420	Vulcan Mechanical Compliance - 12 Monthly Inspection - CMS Requirement	4/05/2022	.00	.00	4.00	385	Vulcan CM	\$0.00
50340	WDS water pump leaking	15/05/2022	.00	.00	.00		Unplanned	\$2,270.00
50393		22/04/2022	.00	.00	.00		Planned M	\$270.00
50394		22/04/2022	.00	.00	.00		Planned M	\$360.00
50406		23/04/2022	.00	.00	.00		Unplanned	\$32.50
50723	Seat not pumping up	25/04/2022	.00	.00	.00		Unplanned	\$105.00
50956	Replace blown hydraulic hose under tank	15/05/2022	.00	.00	.00		Unplanned	\$785.00
50966	Exhaust leak	7/07/2022	.00	4.00	.00		Planned M	\$105.00
50988	Prestart - Grease Fault	27/06/2022	.00	.00	.00		Pre-Start	\$817.50
51063	Fire Suppression & Extinguishers - 6 Monthly - CMS requirement level 1 Service	16/06/2022	.00	.00	.00	293	BMA CMS	\$0.00
51154	TC hose and steering column strut	10/05/2022	.00	.00	.00		Planned M	\$402.00
51174		8/05/2022	.00	.00	.00		Unplanned	\$630.00
51497	Grease Fault	27/06/2022	.00	.00	.00		Pre-Start	\$105.00
51498	Door rubber loose	27/06/2022	.00	.00	.00		Pre-Start	\$210.00
51827	Prestart - Water leaking into cab again	27/06/2022	.00	.00	.00		Pre-Start	\$0.00
51828	Prestart - Heater doesn't work	26/06/2022	.00	.00	.00		Pre-Start	\$0.00
51829	Prestart - Needs new high beam lights	5/09/2022	.00	.00	.00		Pre-Start	\$0.00

W/O No	Description	Complete	Down time	Repair time	Dur.	P/M	Job Type	Cost
52050	775 - 777 Off Highway Truck - 250 Hour Service	24/09/2022	.00	.00	.00	175	Preventati	\$0.00
52108	Prestart - Drivers door hard to open	27/06/2022	.00	.00	.00		Pre-Start	\$0.00
52202	Door latch U/S	27/06/2022	.00	.00	.00		Planned M	\$105.00
52208	Prestart - Missing front & back call signs	5/09/2022	.00	.00	.00		Pre-Start	\$0.00
52328	emergency steering fault - nerang for failure analysis as requested by Luke	13/07/2022	.00	.00	.00		Unplanned	\$210.00
52330	777 Off Highway Truck - 500 Hour Service	24/09/2022	.00	.00	.00	176	Preventati	\$420.00
52890	Prestart - Cab seals need replacing	28/10/2022	.00	.00	.00		Pre-Start	\$0.00
52891	Prestart - No AM/FM radio	5/09/2022	.00	.00	.00		Pre-Start	\$0.00
53873	hydraulic hose from hoist control valve to cooler	30/09/2022	.00	.00	.00		Unplanned	\$0.00
56153	Prestart - Drop Box leaking at top	5/09/2022	.00	.00	.00		Pre-Start	\$0.00
56166	pos3 wheel studs and rim u/s	17/09/2022	.00	.00	.00		Unplanned	\$0.00
56189	Pos 3 Tyre re torque	17/09/2022	.00	.00	.00		Unplanned	\$0.00
57084	Retarder fault	17/09/2022	.00	.00	.00		Planned M	\$0.00
57319	Prestart - Struggles to select gears sometimes	3/09/2022	.00	.00	.00		Pre-Start	\$0.00
57320	Prestart - Horn doesn't always work	5/09/2022	.00	.00	.00		Pre-Start	\$0.00
57322	Prestart - Retarder playing up	5/09/2022	.00	.00	.00		Pre-Start	\$0.00
57333	Prestart - Water leaks into back of cab	28/10/2022	.00	.00	.00		Pre-Start	\$0.00
57334	Prestart - Needs new high beams	5/09/2022	.00	.00	.00		Pre-Start	\$0.00
57441	LH indicator staying on	3/09/2022	.00	.00	.00		Unplanned	\$0.00
58140	Prestart - Needs rear ID sticker	5/09/2022	.00	.00	.00		Pre-Start	\$0.00
58141	Prestart - Left indicator stuck on	5/09/2022	.00	.00	.00		Pre-Start	\$0.00
58142	Prestart - Centre barrel leak	5/09/2022	.00	.00	.00		Pre-Start	\$0.00
58208	775 - 777 Off Highway Truck - 500 Hour Service	24/09/2022	.00	.00	.00	176	Preventati	\$0.00

W/O No	Description	Complete	Down time	Repair time	Dur.	P/M	Job Type	Cost
58470	Prestart - Lubricator fault alarm goes off	5/09/2022	.00	.10	.00		Pre-Start	\$0.00
58474	Prestart - Auto grease fault	18/08/2022	.00	.00	.00		Pre-Start	\$0.00
58552		18/08/2022	.00	.00	.00		Planned M	\$0.00
58567	Brake Test - 6 Monthly Inspection - CMS Requirement	18/08/2022	.00	.00	.00	384	Vulcan CM	\$0.00
58588	trans fault	22/08/2022	.00	.00	.00		Unplanned	\$0.00
58685	1000 HR SERVICE	5/09/2022	12.00	12.0	.00	177	Preventati	\$0.00
58857	Prestart - Leak front right of tank	5/09/2022	.00	.00	.00		Pre-Start	\$0.00
58865	Prestart - Front hand rail bracket broken	5/09/2022	.00	.00	.00		Pre-Start	\$0.00
59257	CALL SIGNS FRONT AND REAR	30/09/2022	.00	.00	.00		Planned M	\$0.00
59258	HORN NOT WORKING -BUTTON KIT REQUIRED	30/09/2022	.00	.00	.00		Planned M	\$0.00
59260	AM FM RADIO REPLACE	17/09/2022	.00	.00	.00		Planned M	\$0.00
59261	REPLACE HIGH BEAM LIGHTS	17/09/2022	.00	.00	.00		Planned M	\$0.00
59262	HAND RAIL FRONT REPAIR - BOILERMAKER	30/09/2022	.00	.00	.00		Planned M	\$0.00
59263	CENTER BARREL LEAK- BOILERMAKER TO REPAIR	17/09/2022	.00	.00	.00		Planned M	\$0.00
59265	LUBRICATION ALARM -INSPECT AND REPAIR	17/09/2022	.00	.00	.00		Planned M	\$0.00
59266	REPAIR LEAK RIGHT FRONT OF TANK	17/09/2022	.00	.00	.00		Planned M	\$0.00
59478	Brake hose / done	12/06/2024	.00	.00	.00		Planned M	\$0.00
59492	STEERING VALVE PIPE LH SIDE LEAKING / done	12/06/2024	.00	.00	.00		Monitor	\$0.00
59863	Rear right tank repair boily	30/09/2022	.00	.00	.00		Preventati	\$0.00
59896		30/09/2022	.00	.00	.00		Complianc	\$0.00
60031	Prestart - No hose on rear hose reel	28/10/2022	.00	.00	.00		Pre-Start	\$0.00
60042	Prestart - Poor visibility out of left window - scratched	18/10/2022	.00	.00	.00		Pre-Start	\$0.00
60043	Prestart - Battery isolator switch loose	18/10/2022	.00	.00	.00		Pre-Start	\$0.00

W/O No	Description	Complete	Down time	Repair time	Dur.	P/M	Job Type	Cost
60044	Prestart - Minor oil leaks in the rear	18/10/2022	.00	.00	.00		Pre-Start	\$0.00
60221	Prestart - Auto grease issue	18/10/2022	.00	.00	.00		Pre-Start	\$0.00
60232	Prestart - Horn stopped working	18/10/2022	.00	.00	.00		Pre-Start	\$0.00
60391	775 - 777 Off Highway Truck - 250 Hour Service	18/10/2022	12.00	12.0	.00	175	Preventati	\$0.00
60508	Dog bone bolt has snapped nut has been put on but isn't holding requires urgent repairs / fitted new bearings and pins	12/06/2024	.00	.00	.00		Preventati	\$0.00
60658	Replace rock box/ resealed	12/06/2024	.00	.00	.00		Planned M	\$0.00
60706		30/10/2022	.00	.00	.00		Planned M	\$0.00
60798	Prestart - Red isolator stuck / new isolator fitted	12/06/2024	.00	.00	.00		Pre-Start	\$0.00
60857	Prestart - Bottom step bent / repaired workshop	12/06/2024	.00	.00	.00		Pre-Start	\$0.00
60872	C/O Hoist to control valve hose / replaced	12/06/2024	.00	.00	.00		Planned M	\$0.00
61083	Prestart - Steering wheel won't extend / repaired wshop	12/06/2024	.00	.00	.00		Pre-Start	\$0.00
61084	Prestart - Both top headlights missing / done wshop	12/06/2024	.00	.00	.00		Pre-Start	\$0.00
61085	Prestart - RH window needs to be re-sealed. Water gets in side / fitted updated window frame and glass	12/06/2024	.00	.00	.00		Pre-Start	\$0.00
61132	Fire Suppression & Extinguishers - 6 Monthly - CMS requirement NOT SERVICED	30/11/2022	.00	.00	.00	293	Complianc	\$0.00
62111	fire damage - repair/ done	12/06/2024	.00	.00	.00		Accident	\$0.00
71161	Replace all harness engine, chassis etc / fitted new engine harness, machine harness, front harness	12/06/2024	.00	.00	.00		Planned M	\$0.00
71163	cab repair rust and leak / done wshop	12/06/2024	.00	.00	.00		Planned M	\$0.00
71164	fuel lines / replaced all fuel lines after fire damage	12/06/2024	.00	.00	.00		Planned M	\$0.00
71165	intake pipes / removed blasted repaired, fit all new hose clamps etc	12/06/2024	.00	.00	.00		Planned M	\$0.00
71166	a/c compressor / fitted new compressor new hoses new evaporator and fans new drier new accumulator, test and gas	12/06/2024	.00	.00	.00		Planned M	\$0.00

W/O No	Description	Complete	Down time	Repair time	Dur.	P/M	Job Type	Cost
	system							
71167	fan cowling / fitted second hand replacment	12/06/2024	.00	.00	.00		Planned M	\$0.00
71168	alternator / fitted new	12/06/2024	.00	.00	.00		Planned M	\$0.00
71169	hoist lift cylinder / fitted replacment hoist cylinder, hoses, pin bearing	12/06/2024	.00	.00	.00		Planned M	\$0.00
71170	steering tank / stripped blasted and resealed	12/06/2024	.00	.00	.00		Planned M	\$0.00
71171	fire suppression / chubb upgrade completed	12/06/2024	.00	.00	.00		Planned M	\$0.00
71172	seat / fitted new isri seat	3/05/2024	.00	.00	.00		Planned M	\$0.00
71316	repair fan hub / rebuilt	12/06/2024	.00	.00	.00		Planned M	\$0.00
71324	Brake accumulator hoses worn / new fitted	12/06/2024	.00	.00	.00		Planned M	\$0.00
71327	Radiator hoses / new fitted	12/06/2024	.00	.00	.00		Planned M	\$0.00
71517	Fuel cooler cracked / new fitted	12/06/2024	.00	.00	.00		Unplanned	\$0.00
71730	L/H exhaust pipe U/S / done new part fitted	12/06/2024	.00	.00	.00		Planned M	\$0.00
72090	HYD tank cap missing/ fitted new	12/06/2024	.00	.00	.00		Unplanned	\$0.00
73037	strutt poss 3 rear / line boared top and bottom mounting holes, fitted new bearings	12/06/2024	.00	.00	.00		Planned M	\$0.00
73038	mud gaurds fit up / fitted all new	12/06/2024	.00	.00	.00		Planned M	\$0.00
73039	tires turn and refit and retension / done advised shaun croaker to advise site to retorque all wheels after first load	12/06/2024	.00	.00	.00		Planned M	\$0.00
73040	tub fit up and shim to chassis / fitted second hand tub to truck, extensive wear in rear wear plate in tub (pics on onhire doc)	12/06/2024	.00	.00	.00		Planned M	\$0.00
73041	tires rear locate and refit / fitted tires and rims sent from vitrnite, turned front tires from transport position	12/06/2024	.00	.00	.00		Planned M	\$0.00
73264	rims send poss4 poss 5 rims for crack testing / done	5/11/2024	.00	.00	.00		Planned M	\$0.00
73470	exhaust leaks / fitted new exhaust tube lh and rh turbo to muffler	12/06/2024	.00	.00	.00		Planned M	\$0.00
73575	A-Frame has movement / replaced bearing and pin reset	12/06/2024	.00	.00	.00		Planned M	\$0.00

W/O No	Description	Complete	Down time	Repair time	Dur.	P/M	Job Type	Cost
75094	preload poss 4 strutt line boar mounting holes , replace bearings / line boarded top and bottom fitted new bearings and pins	12/06/2024	.00	.00	.00		Planned M	\$0.00
76893	torque convertor over heating fault / stripped down no fault found, re fit new bearings seal, rebuild scavange pump, replace lock up valve, clean trans cooler. run up and found transmission was the over heating fault	20/08/2024	.00	.00	.00		Planned M	\$0.00
77036	transmission fault / trans rebuild all new disc, new seals new bearings, calibrate run and test ok	5/09/2024	.00	.00	.00		Planned M	\$0.00
77200	transmission housing repair crack / done	3/09/2024	.00	.00	.00		Unplanned	\$0.00
83354	1000 hr service / done	30/06/2025	.00	.00	.00		Preventati	\$0.00
85847	250 service due / done 25276	12/11/2025	.00	.00	.00		Preventati	\$0.00
85927	starter isolator failed / new fitted	9/12/2025	.00	.00	.00		Planned M	\$0.00
88679	demob off site / done	11/09/2026	.00	.00	.00		Planned M	\$0.00
417		Total	46.00	258.6				\$11,043.00