

Asset History Report

Thursday, 29 October 2

W/O No	Description	Complete	Down time	Repair time	Dur.	P/M	Job Type	Cost
775F-2	Caterpillar 775F Haul Truck - TE767							
561	grease system not working ,fault code, grease timer fault order part, fit timer, check operation ok	13/01/2013	.00	.00	.00			\$0.00
976	Prep water truck for transport by Andrew Punter @ TE GC	6/08/2013	.00	.00	.00		Request	\$0.00
1178	500HR Caterpillar 775F	15/07/2014	.00	.00	.00	96	PM	\$0.00
1237	Replace Fan hub	30/04/2014	.00	.00	.00		Unplanned	\$0.00
1285	Change out fitting in torque filter	30/04/2014	.00	.00	.00		Opportune	\$0.00
1303	Clean out Sprays	4/05/2014	.00	.00	.00		Planned M	\$0.00
1357	UHF not working properly,	16/07/2014	.00	.00	.00		Planned M	\$0.00
1362	Replace missing spray	27/05/2014	.00	.00	.00		Planned M	\$0.00
1590	250HR Caterpillar 775F	15/07/2014	.00	.00	.00	95	PM	\$0.00
1746	2000HR Caterpillar 775F	15/07/2014	.00	.00	.00	98	PM	\$0.00
1999	R/H steering cylinder bearing u/s	16/02/2015	.00	.00	.00		Planned M	\$0.00
2001	flat tyre pos 3	14/09/2014	.00	.00	.00		Planned M	\$0.00
2002	call sign to be fitted	29/08/2014	.00	.00	.00		Planned M	\$0.00
2003	grease hose to be made (pump to vent valve)	4/02/2015	.00	.00	.00		Planned M	\$0.00
2004	grease inlet screen to be fitted	4/02/2015	.00	.00	.00		Planned M	\$0.00
2014	A frame bearing u/s (line bore)	14/09/2014	.00	.00	.00		Planned M	\$0.00
2015	Dog bone bearings u/s (line bore)	14/09/2014	.00	.00	.00		Planned M	\$0.00
2016	grease vent valve to be mounted	4/02/2015	.00	.00	.00		Planned M	\$0.00
2017	rear flashing light to be fitted	14/09/2014	.00	.00	.00		Planned M	\$0.00

W/O No	Description	Complete	Down time	Repair time	Dur.	P/M	Job Type	Cost
2018	magnum control box to be fitted out of 775F-4 (455)	9/11/2014	.00	.00	.00		Planned M	\$0.00
2019	panels to be fitted in cab after control box fitted	9/11/2014	.00	.00	.00		Planned M	\$0.00
2020	bracket for VHF hand piece to be made once control box is fitted	16/02/2015	.00	.00	.00		Planned M	\$0.00
2021	Steering tank breather cover	1/03/2015	.00	.00	.00		Planned M	\$0.00
2022	Needs new rear tyres and 1 rim repaired or replaced	19/01/2015	.00	.00	.00		Planned M	\$0.00
2023	T/C cooler hose u/s	29/08/2014	.00	.00	.00		Planned M	\$0.00
2043	Hose reel valve spool needs repairs	22/02/2015	.00	.00	.00		Planned M	\$0.00
2505	500HR Caterpillar 775F	22/02/2015	.00	.00	.00	96	PM	\$0.00
2786	pos1 brake line needs replacing	4/02/2015	.00	.00	.00			\$0.00
3077	pressure control valve u/s for cannon /in containor new one fitted	4/05/2015	.00	.00	.00			\$0.00
3106		1/03/2015	.00	.00	.00			\$0.00
3107	smoke comming off wires on tank. desconted power to wires	1/03/2015	.00	.00	.00			\$0.00
3174	lh rear strut leaking bad, done 12719	5/06/2015	.00	.00	.00			\$0.00
3175	pos 3 tyre down to 30 psi mointor	21/04/2015	.00	.00	.00			\$0.00
3176	needs a new wing bolt for external a/c filter cover/ fitted new bolt	20/04/2015	.00	.00	.00			\$0.00
3193	replaced grease pump 12378hrs	11/04/2015	.00	.00	.00			\$0.00
3194	lh tail light out, rh tail light flickering	5/06/2015	.00	.00	.00			\$0.00
3216	remove failed trans	25/04/2015	.00	.00	.00		Unplanned	\$0.00
3228	tank water pump noise new one ored, done 12719	5/06/2015	.00	.00	.00			\$0.00
3232	change out toggle swiches for sparys	5/06/2015	.00	.00	.00			\$0.00
3248	replaced 2 cores and resealed radiator @12600	16/05/2015	.00	.00	.00			\$0.00
3275	oil leak at cannon	16/07/2015	.00	.00	.00			\$0.00

W/O No	Description	Complete	Down time	Repair time	Dur.	P/M	Job Type	Cost
3283	changed out injectors 1,3,6 @12721hrs	5/06/2015	.00	.00	.00			\$0.00
3284	injertors 7,8 need to be changed out / done at 12721	20/06/2015	.00	.00	.00			\$0.00
3555	replace missing spary solinoids/coils	28/11/2015	.00	.00	.00			\$0.00
4182		30/05/2018	.00	.00	.00		Planned M	\$0.00
4183	need to replace off side mirrors	18/04/2016	.00	.00	.00			\$0.00
4184	radiotr needs to be checked top lhs posabile leek	18/04/2016	.00	.00	.00			\$0.00
4185	hose on second steering motor leaking	2/07/2018	.00	.00	.00		Planned M	\$0.00
4186	brake pipe rh wheel end leaking oring	11/05/2016	.00	.00	.00		Opportune	\$0.00
4187	cannon fog / jet acautor missing : parts ordered	18/04/2016	.00	.00	.00			\$0.00
4188	hyd tank sight glass weeping	3/12/2018	.00	.00	.00		Planned M	\$0.00
4189	rear water pump seals weeping oil	2/07/2018	.00	.00	.00		Planned M	\$0.00
6732	777f 250 SERVICE	20/04/2016	.00	.00	.00	164		\$0.00
7114	FIT REAR TYRES AND CHANGE RIMS FRT	11/01/2016	.00	.00	.00			\$0.00
7753	discharged fire supression 1:40 sec of afff +30 sec of nitrogen in reserve removed out of date bottle stole grease pump for d11r-5	15/03/2016	.00	.00	.00		Preventati	\$0.00
7812	FITTED NEW GREASE PUMP	19/04/2016	.00	.00	.00		Preventati	\$0.00
7852	frt right hand indicator not working	3/06/2016	.00	.00	.00		Planned M	\$0.00
7853	right hand indicator rear and tail light not wrking	3/06/2016	.00	.00	.00		Planned M	\$0.00
7854	needs new bolt for external cab filter door	3/06/2016	.00	.00	.00		Planned M	\$0.00
7855	diesel filter had a lot of water in it	20/04/2016	.00	.00	.00		Inspection	\$0.00
7944	Radio dont work	3/06/2016	.00	.00	.00		Unplanned	\$0.00
8065	front flashing blue light not working	3/06/2016	.00	.00	.00		Opportune	\$0.00
8066		30/05/2018	.00	.00	.00		Opportune	\$0.00

W/O No	Description	Complete	Down time	Repair time	Dur.	P/M	Job Type	Cost
8067	lower front work light out	3/06/2016	.00	.00	.00		Opportune	\$0.00
9981	777 Off Highway Truck - 250 Hour Service	7/03/2017	.00	.00	.00	175	Preventati	\$0.00
10475	RH step ladder broken	2/07/2018	.00	.00	.00		Opportune	\$0.00
10485	Top RH mirror smashed	2/07/2018	.00	.00	.00		Opportune	\$0.00
10486	Front wiper needs new blade	2/07/2018	.00	.00	.00		Opportune	\$0.00
10495	oil leak under right wheel	3/12/2018	.00	.00	.00		Opportune	\$0.00
10965	777 Off Highway Truck - 2000 Hour Service	28/05/2018	.00	.00	.00	178	Preventati	\$0.00
11068	Hydraulic leak	2/07/2018	.00	.00	.00		Opportune	\$0.00
11069	Lubrication fault alarm sounding	2/07/2018	.00	.00	.00		Opportune	\$0.00
11310		30/05/2018	.00	.00	.00		Opportune	\$0.00
11312	oil leak left rear struck	3/12/2018	.00	.00	.00		Opportune	\$0.00
11313	1 chock missing	2/07/2018	.00	.00	.00		Opportune	\$0.00
11314	left indicators not working with hazard lights	2/07/2018	.00	.00	.00		Opportune	\$0.00
11315	Crack windscreen	2/07/2018	.00	.00	.00		Opportune	\$0.00
11317		30/05/2018	.00	.00	.00		Opportune	\$0.00
11553	Front tyres to be inspected for the reason they are chopping outside and inside tread? Check Wheel alignment and replace front tyres	2/07/2018	.00	.00	.00		Inspection	\$0.00
11555	Change Front Tyres	2/07/2018	.00	.00	.00		Planned M	\$0.00
12333	Failed Grease controller	2/07/2018	.00	.00	.00		Unplanned	\$0.00
12353	777 Off Highway Truck - 1000 Hour Service	28/05/2018	.00	.00	.00	177	Preventati	\$0.00
12704	777 Off Highway Truck - 250 Hour Service	28/05/2018	.00	.00	.00	175	Preventati	\$0.00
12705	777 Off Highway Truck - 250 Hour Service	28/05/2018	.00	.00	.00	175	Preventati	\$0.00
12939	replace blown hose on grease pilot line	2/07/2018	.00	.00	.00		Unplanned	\$0.00

W/O No	Description	Complete	Down time	Repair time	Dur.	P/M	Job Type	Cost
13005	777 Off Highway Truck - 500 Hour Service	28/05/2018	.00	.00	.00	176	Preventati	\$0.00
13203	Water Level Gauge to be repaired	2/07/2018	.00	.00	.00		Opportune	\$0.00
13204	UHF Bracket to be repaired	2/07/2018	.00	.00	.00		Opportune	\$0.00
13259	Main pipe to hydraulic tank to be replaced	1/12/2018	.00	.00	.00		Opportune	\$0.00
13293	Faulty brake temperature switch to be replaced	2/07/2018	.00	.00	.00		Opportune	\$0.00
13375	Cracked bowl assembly to be replaced	2/07/2018	.00	.00	.00		Opportune	\$0.00
13532	777 Off Highway Truck - 4000 Hour Service	28/05/2018	.00	.00	.00	179	Preventati	\$0.00
13562	777 Off Highway Truck - 2000 Hour Service	28/05/2018	.00	.00	.00	178	Preventati	\$0.00
13582	777 Off Highway Truck - 1000 Hour Service	28/05/2018	.00	.00	.00	177	Preventati	\$0.00
13590	777 Off Highway Truck - 250 Hour Service	28/05/2018	.00	.00	.00	175	Preventati	\$0.00
13597	777 Off Highway Truck - 500 Hour Service	28/05/2018	.00	.00	.00	176	Preventati	\$0.00
13601	777 Off Highway Truck - 4000 Hour Service	28/05/2018	.00	.00	.00	179	Preventati	\$0.00
13602	777 Off Highway Truck - 2000 Hour Service	28/05/2018	.00	.00	.00	178	Preventati	\$0.00
13603	777 Off Highway Truck - 1000 Hour Service	28/05/2018	.00	.00	.00	177	Preventati	\$0.00
13606	777 Off Highway Truck - 500 Hour Service	28/05/2018	.00	.00	.00	176	Preventati	\$0.00
13611	777 Off Highway Truck - 250 Hour Service	28/05/2018	.00	.00	.00	175	Preventati	\$0.00
14318	Water tank leak to be resealed	12/12/2018	.00	.00	.00		Opportune	\$0.00
14349	Headlights to be repaired	2/07/2018	.00	.00	.00		Opportune	\$0.00
14350	Fuel Gauge to be replaced	2/07/2018	.00	.00	.00		Opportune	\$0.00
14351	Left arm nest to be tightened	2/07/2018	.00	.00	.00		Opportune	\$0.00
14460	Exhaust tail pipe to be repaired	16/03/2019	.00	.00	.00		Opportune	\$0.00
14589	Chain holding wheel chock to be repaired	2/07/2018	.00	.00	.00		Opportune	\$0.00
14607	Coolers to be replaced	17/12/2018	.00	.00	.00		Opportune	\$0.00

W/O No	Description	Complete	Down time	Repair time	Dur.	P/M	Job Type	Cost
14638	777 Off Highway Truck - 250 Hour Service	12/11/2018	.00	.00	.00	175	Preventati	\$0.00
14744	Cannon leak to be resealed	12/12/2018	.00	.00	.00		Opportune	\$0.00
14745	Hand rails to be replaced	1/12/2018	.00	.00	.00		Opportune	\$0.00
14746	Rear blue beacon to be replaced	21/10/2018	.00	.00	.00		Opportune	\$0.00
14747	Headlights to be replaced	1/07/2018	.00	.00	.00		Opportune	\$0.00
14805	Reverse lights to be repaired/replaced	21/10/2018	.00	.00	.00		Opportune	\$0.00
14806	RH steering cylinder to be resealed	10/08/2018	.00	.50	.00		Opportune	\$0.00
14854	Centre spray to be repaired	21/10/2018	.00	.00	.00		Opportune	\$0.00
14855	Water level gauge to be repaired	1/12/2018	.00	.00	.00		Opportune	\$0.00
14872	Door where you check oil to be replaced	13/04/2019	.00	3.00	.00		Opportune	\$0.00
15038	LH Batter spray leak to be resealed	24/04/2019	.00	.00	.00		Opportune	\$0.00
15039	RH head light out on low beam to be repaired	21/10/2018	.00	.00	.00		Opportune	\$0.00
15040	Cracked windscreen to be repaired	1/12/2018	.00	.00	.00		Planned M	\$0.00
15041	Wipers rubber to be repaced	12/11/2018	.00	.00	.00		Planned M	\$0.00
15101	Rear flashing light to be replaced	21/10/2018	.00	.00	.00		Opportune	\$0.00
15202	Flashing light to be replaced	21/10/2018	.00	.00	.00		Opportune	\$0.00
15204	777 Off Highway Truck - 1000 Hour Service	2/08/2018	.00	.00	.00	177	Preventati	\$0.00
15449	777 Off Highway Truck - 4000 Hour Service	12/11/2018	.00	.00	.00	179	Preventati	\$0.00
15466	777 Off Highway Truck - 250 Hour Service	12/11/2018	.00	.00	.00	175	Preventati	\$0.00
15782	Trans fill point cap to be replaced	1/12/2018	.00	.00	.00		Planned M	\$0.00
16023	RHR window latch broken	21/10/2018	.00	.00	.00			\$0.00
16024	Mud flaps to be replaced	16/03/2019	.00	.00	.00			\$0.00
16025	Hose real on back is missing holder bearing	15/04/2019	.00	6.00	.00			\$0.00

W/O No	Description	Complete	Down time	Repair time	Dur.	P/M	Job Type	Cost
16026	Elbow missing from muffler to dump pipe	29/03/2019	.00	.00	.00			\$0.00
16027	Hood cover missing for engine oil level dipstick	16/03/2019	.00	.00	.00			\$0.00
16028	RH window needs new seal	1/12/2018	.00	.00	.00			\$0.00
16029	Front window cracked	1/12/2018	.00	.00	.00			\$0.00
16030	RH steering cylinder leaking	1/12/2018	.00	.00	.00			\$0.00
16088	VHF & UHF not working, found broke wire in cab harness	25/09/2018	.00	.00	.00			\$0.00
16298	Diagnose & repair no power - found battery cable terminal came off, refitted & cleaned surface.	21/10/2018	.00	.00	.00			\$0.00
16419	777 Off Highway Truck - 500 Hour Service	10/11/2018	.00	.00	.00	176	Preventati	\$0.00
16668	Replace starter motor	22/10/2018	.00	.00	.00			\$0.00
16681	Replace Alternator	23/10/2018	.00	.00	.00			\$0.00
16684	Steering cylinder seal kit	1/12/2018	.00	.00	.00			\$0.00
16705	Broke down with no power, headlights turned off. Low voltage alarms. Trouble shoot problem, found alt not charging, replaced with alt from 476. Also found head light switch broken as well, replaced with 476 parts	21/10/2018	.00	.00	.00		Planned M	\$0.00
16706	Not starting (flat battery?), Found loose terminals, tightened and sanded all terminals and connections. Still not starting, replaced 1 x battery as post was damaged, replaced rusty isolator, still no start	12/11/2018	.00	.00	.00		Planned M	\$0.00
16782	Faulty mine radio & speaker replaced(Used radio out of dozer 57)	29/10/2018	.00	.00	.00		Planned M	\$0.00
16912	install 2nd 2 way radio	2/11/2018	.00	.00	.00		Unplanned	\$0.00
17009	Engine not starting - Found that one of the power supplies to the ECM was faulty- repaired bad connection on circuit breaker	5/11/2018	.00	.00	.00		Planned M	\$0.00
17587	Remove and replace compressor and drier, vac and re-gas system. Run aircon to test - tested good	4/12/2018	5.50	.00	.00		Unplanned	\$0.00

W/O No	Description	Complete	Down time	Repair time	Dur.	P/M	Job Type	Cost
17601	Front window cracked	1/12/2018	.00	.00	.00			\$0.00
17602	Reverse lights to be replaced	12/12/2018	.00	.00	.00		Opportune	\$0.00
17660	Waist belt parts used for 453 water cart to go into stock	4/12/2018	.00	.00	.00			\$0.00
17662	Mud guard LH	16/03/2019	.00	.00	.00			\$0.00
17664	Replace Vision link Cable	16/03/2019	.00	.00	.00			\$0.00
17754	Compressor is worn out, remove shim from clutch plate and reassembled. Test operation.	27/11/2018	2.10	.00	.00		Unplanned	\$0.00
17837	777 Off Highway Truck - 250 Hour Service	2/01/2019	.00	.00	.00	175	Preventati	\$0.00
17891	Replace cab side hand rail and platform	13/04/2019	.00	6.00	.00		Planned M	\$0.00
17927	Repair Damaged Spray Bar screen	8/12/2018	2.00	.00	.00			\$0.00
17935	Leaking Right hand steering arm to inspect	16/03/2019	.00	.00	.00		Planned M	\$0.00
17936	Inspect Cracked window screen	29/03/2019	.00	.00	.00		Planned M	\$0.00
18022	crack test & repair 2 rims	24/04/2019	.00	.00	.00			\$0.00
18049	seal kit for RH steering Cylinder	23/03/2019	.00	.00	.00			\$0.00
18136	C/O rear Water pump, HYD motor and coupling	3/01/2019	1.00	.00	.00		Unplanned	\$0.00
18141	Remove LH spray head clean and reseal	3/01/2019	1.00	.00	.00		Unplanned	\$0.00
18149	Fit shackle to cannon left right actuator cylinder Inspect cannon and sort a solution on how to get it to turn left to right.Use D shackle and anchor bolt	2/01/2019	1.00	.00	.00		Unplanned	\$0.00
18327	replace blue flashing beacons	17/01/2019	.00	.00	.00		Unplanned	\$0.00
18333	Wheel chocks to be replaced	29/03/2019	.00	.00	.00			\$0.00
18569	Replace coupling water pump	24/01/2019	3.00	.00	.00			\$0.00
18635	hoses 24 supply hose for pump	16/03/2019	.00	.00	.00			\$0.00
18941	Inspect and repair starting fault	24/04/2019	.00	.00	.00		Unplanned	\$0.00

W/O No	Description	Complete	Down time	Repair time	Dur.	P/M	Job Type	Cost
18964	battery u/s	8/02/2019	1.00	.00	.00		Unplanned	\$0.00
19026	Stairs missing RH to be replaced	25/03/2019	.00	6.00	.00		Planned M	\$0.00
19029	install QRT fitting to the rear spray bar	31/03/2019	.00	.00	.00		Planned M	\$0.00
19032	Disassemble cannon spray adjuster, clean out rocks. Test - OK.	28/03/2019	13.00	.00	.00		Planned M	\$0.00
19043	W/O 19043 Starting issue. Checked batteries, cleaned terminals & posts, cleaned lugs & isolator post. Found green death on lugs. Battery terminals broken, found one battery un-serviceable. Change out 2 battery terminals, repaired damaged stairs.	12/02/2019	12.00	.00	.00		Unplanned	\$0.00
19328	Requires a Set of Chocks	16/03/2019	.00	.00	.00		Accident	\$0.00
19335	Reseal hyd plug on valve block for water pump - Valve block oil leak	13/02/2019	.50	.00	.00		Opportune	\$0.00
19365	Adjust rear sprays to 7 meters	20/02/2019	1.50	1.50	.00		Planned M	\$0.00
19369	Fit 2 x New steer tyres. BMA back charge.	23/06/2019	.00	.00	.00		Planned M	\$0.00
19655	777 Off Highway Truck - 250 Hour Service	31/12/2018	.00	.00	.00	175	Preventati	\$0.00
19748	Air Cleaner box Replacement	24/04/2019	.00	.00	.00		Planned M	\$0.00
19859	Inspect head light, move and adjust bent walkway lights	2/03/2019	2.50	.00	.00		Accident	\$0.00
19969	777 Off Highway Truck - 1000 Hour Service	25/04/2019	12.00	14.0	.00	177	Preventati	\$0.00
20041	Seal wiper needs to be replaced RHF cylinder	26/03/2019	.00	.00	.00			\$0.00
20096	Emergency Steel Pipe Needs Replaced	14/04/2019	.00	.00	.00			\$0.00
20100	Cannon- Replace leaking seal, Bearing Repair Kit	1/04/2021	.00	.00	.00		Planned M	\$0.00
20219	Fuel Injectors-Re seal	5/04/2019	.00	.00	.00			\$0.00
20318	Replace Inlet manifold	19/04/2019	.00	.00	.00		Unplanned	\$0.00
20335	Repair Leaking intake manifold	9/04/2019	15.50	15.5	.00		Unplanned	\$0.00
20405	Hydraulic - Replace steering pipe RH chassis	23/06/2019	.00	.00	.00		Planned M	\$0.00

W/O No	Description	Complete	Down time	Repair time	Dur.	P/M	Job Type	Cost
20477	Replace LH hand rail	14/04/2019	.00	.00	.00			\$0.00
20495	repair cracks to rock box	14/04/2019	.00	3.00	.00			\$0.00
20615		17/04/2019	.00	.00	.00			\$0.00
20631	Suck and blow take engine oil sample due to major engine repair	18/04/2019	2.00	2.00	.00			\$0.00
20710	Cannon- broken eye bolt, cannon jammed.	23/06/2019	.00	.00	.00		Unplanned	\$0.00
20876	Exhaust - Replace failed muffler and pipe	11/12/2019	.00	.00	.00		Planned M	\$0.00
21622	Brake lights out, no reverse lights	23/06/2019	.00	.00	.00		Unplanned	\$0.00
21627		13/06/2019	.00	.00	.00		Planned M	\$0.00
21736	Repair Water Cannon	30/10/2019	.00	.00	.00		Accident	\$0.00
21745	Cannon Snapped side shift bolt, manually adjusted cannon so it can be used	14/06/2019	1.00	1.00	1.00		Inspection	\$0.00
21762		16/06/2019	.00	.00	.00			\$0.00
21773	Centre spray magnum U/S need to order one	16/06/2019	4.00	4.00	.00			\$0.00
21864	Repair broken step	18/06/2019	1.00	.00	.00		Unplanned	\$0.00
21899	Wiper - Replace windscreen wipers and repair washer	1/04/2021	.00	.00	.00		Planned M	\$0.00
21900	Hydraulic - Oil leak behind pos 1 tyre	1/04/2021	.00	.00	.00		Planned M	\$0.00
21912	Fuel tank - Fuel tank is full of rust so return and suction fittings have been swapped around	24/06/2019	15.00	7.00	.00		Unplanned	\$0.00
24361	777 Off Highway Truck - 250 Hour Service	20/01/2020	.00	.00	.00	175	Preventati	\$0.00
30824	strutts front reseal and refit to truck	5/02/2022	.00	.00	.00		Planned M	\$0.00
30825	steer cylinder removed and sent to blackwater. rebuild and refit return cylinder	5/02/2022	.00	.00	.00		Planned M	\$0.00
30826	radiator rebuild and refit. old one removed and sent for replacement	5/02/2022	.00	.00	.00		Planned M	\$0.00
30874	777 Off Highway Truck - 500 Hour Service	31/07/2020	.00	.00	.00	176	Preventati	\$0.00

W/O No	Description	Complete	Down time	Repair time	Dur.	P/M	Job Type	Cost
30879	777 Off Highway Truck - 750 Hour Service	31/07/2020	.00	.00	.00	178	Preventati	\$0.00
30887	777 Off Highway Truck - 250 Hour Service	31/07/2020	.00	.00	.00	175	Preventati	\$0.00
30890	777 Off Highway Truck - 500 Hour Service	31/07/2020	.00	.00	.00	176	Preventati	\$0.00
30892	777 Off Highway Truck - 750 Hour Service	31/07/2020	.00	.00	.00	178	Preventati	\$0.00
36462	777 Off Highway Truck - 1000 Hour Service	2/02/2022	.00	.00	.00	177	Preventati	\$0.00
36835	air con replace core	5/02/2022	.00	.00	.00		Planned M	\$0.00
36836	engine - replace fuel cooler core	5/02/2022	.00	.00	.00		Planned M	\$0.00
36837	hoist replace and fit missing lift cylinder and hoses, control electrical etc	5/02/2022	.00	.00	.00		Planned M	\$0.00
36838	fuel tank mount to chassis fabricate required brackets plum fuel hoses etc	5/02/2022	.00	.00	.00		Planned M	\$0.00
36868	radiator - fit new	5/02/2022	.00	.00	.00		Planned M	\$0.00
37141	mirror replace on rh side hand rail	5/02/2022	.00	.00	.00		Planned M	\$0.00
37142	clearance lights need replacing	5/02/2022	.00	.00	.00		Planned M	\$0.00
37143	lift ram for body fit new pin and shim	5/02/2022	.00	.00	.00		Planned M	\$0.00
37144	sensor missing from steering valve	5/02/2022	.00	.00	.00		Planned M	\$0.00
37145	air cleaners need replacing	5/02/2022	.00	.00	.00		Planned M	\$0.00
40554	777 Off Highway Truck - 250 Hour Service	2/02/2022	.00	.00	.00	175	Preventati	\$0.00
61497	Rock guards missing from tray	27/04/2023	.00	.00	.00		Planned M	\$0.00
61498	Engine panels not bolted down	27/04/2023	.00	.00	.00		Planned M	\$0.00
61499	Fire suppression no bottle	27/04/2023	.00	.00	.00		Planned M	\$0.00
61500	Fire suppression needs attention	27/04/2023	.00	.00	.00		Planned M	\$0.00
61501	Auto greaser faulting	27/04/2023	.00	.00	.00		Planned M	\$0.00
61502	Poss 1 tyre deflated possible leak	27/04/2023	.00	.00	.00		Planned M	\$0.00

W/O No	Description	Complete	Down time	Repair time	Dur.	P/M	Job Type	Cost
61503	Seat base needs attention	27/04/2023	.00	.00	.00		Planned M	\$0.00
61504	No horn	27/04/2023	.00	.00	.00		Planned M	\$0.00
61505	Cab to be detailed	27/04/2023	.00	.00	.00		Planned M	\$0.00
61506	No power down on tray.	27/04/2023	.00	.00	.00		Planned M	\$0.00
61507	Steering tilt missing parts in cab	27/04/2023	.00	.00	.00		Planned M	\$0.00
61508	Cab door glass missing latch	27/04/2023	.00	.00	.00		Planned M	\$0.00
61509	Dash assembly not bolted in switches in dash not secured	27/04/2023	.00	.00	.00		Planned M	\$0.00
61510	A/c not working	27/04/2023	.00	.00	.00		Planned M	\$0.00
61513	Tyre report	27/04/2023	.00	.00	.00		Planned M	\$0.00
61514	No reverse alarm Reverse light not working	27/04/2023	.00	.00	.00		Planned M	\$0.00
61515	Rear Estop not working	27/04/2023	.00	.00	.00		Planned M	\$0.00
61517	Flashing light not working	27/04/2023	.00	.00	.00		Planned M	\$0.00
64587	struts rear replace / resealed by wshop	24/06/2024	.00	.00	40.00		Planned M	\$0.00
64589	strut fronts remove and reseal. resealed by wshop	24/06/2024	.00	.00	.00		Planned M	\$0.00
75408	service 500 hr due / done by rob	24/06/2024	.00	.00	.00		Planned M	\$0.00
75409	hazard lights staying on / done sparky	5/11/2024	.00	.00	.00		Planned M	\$0.00
75725	lh and rh damage to front bumper, damaged wheel chocks and access steps / repaired 20175	21/09/2026	.00	.00	.00		Planned M	\$0.00
75726	coolant required water only / flushed system added coolant 20175	21/09/2026	.00	.00	.00		Planned M	\$0.00
76548	SERVICE REQUIRED 500 HR / done	24/07/2024	.00	.00	.00		Preventati	\$0.00
76742	cab lh window catch broken water in cab / latch replaced 20175	21/09/2026	.00	.00	.00		Planned M	\$0.00
76743	traction control not working / new sensor and harness fitted 20175	21/09/2026	.00	.00	.00		Planned M	\$0.00

W/O No	Description	Complete	Down time	Repair time	Dur.	P/M	Job Type	Cost
76744	replace alternator belt / new fitted 20175	21/09/2026	.00	.00	.00		Planned M	\$0.00
76745	steering cylinders leaking both sides / resealed with new tie rod ends both cylinders 20175	21/09/2026	.00	.00	.00		Planned M	\$0.00
76746	step and bumper damaged / repaired 20175	21/09/2026	.00	.00	.00		Planned M	\$0.00
77233	1000 hr service due / done	6/09/2024	.00	.00	.00		Preventati	\$0.00
77335	fire extinguisher no tag / done	21/09/2026	.00	.00	.00		Complianc	\$0.00
77336	mirror lh side broken / replaced 20175	21/09/2026	.00	.00	.00		Complianc	\$0.00
77338	side window broken latch / replaced	21/09/2026	.00	.00	.00		Planned M	\$0.00
77343	estop at ground level not working / replaced 20175	21/09/2026	.00	.00	.00		Planned M	\$0.00
77345	exhaust leak rh manifold / resealed new studs and gskts	11/07/2025	.00	.00	.00		Planned M	\$0.00
77346	steering column loose at adjuster / new fitted 20175	21/09/2026	.00	.00	.00		Planned M	\$0.00
83625	Grease pump removed / done	11/07/2025	.00	.00	.00		Planned M	\$0.00
84142	hyd brake pump fit to truck / new pump fitted	11/07/2025	.00	.00	.00		Planned M	\$0.00
84357	walkways cracked / repaired	21/09/2026	.00	.00	.00		Planned M	\$0.00
84358	exhaust tube falling down / new tube and clamp fitted 20175	21/09/2026	.00	.00	.00		Planned M	\$0.00
84360	wiring harness issue's / remounted harness as needed 20175	21/09/2026	.00	.00	.00		Planned M	\$0.00
84362	poss 3 duo leaking / new duo fitted 20175	21/09/2026	.00	.00	.00		Planned M	\$0.00
85621	750 service due / done 19892	12/11/2025	.00	.00	.00		Preventati	\$0.00
85928	poss 4 tyre failed / new tyre fitted by carolls tyre's	25/11/2025	.00	.00	.00		Planned M	\$0.00
88680	demob of site / done 20175	11/09/2026	.00	.00	.00		Planned M	\$0.00
88918	brake cooler hose leaking / new hoses fitted 20175	21/09/2026	.00	.00	.00		Planned M	\$0.00
88919	service required / 2000 hr service completed 20175	21/09/2026	.00	.00	.00		Planned M	\$0.00
88925	hoses various required / new hoses fitted 20175	21/09/2026	.00	.00	.00		Planned M	\$0.00
88927	engine rocker cover leaking / new base covers fitted both	21/09/2026	.00	.00	.00		Planned M	\$0.00

W/O No	Description	Complete	Down time	Repair time	Dur.	P/M	Job Type	Cost
88928	sides 20175 a/c system needs refurb / new compressor, new hoses, new charge ports, evap core cleaned, regased with new dryer 20175	21/09/2026	.00	.00	.00		Planned M	\$0.00
88929	fuel lines need replacing / new hoses fitted 20175	21/09/2026	.00	.00	.00		Planned M	\$0.00
89644	poss 4 duo leaking / new duo fitted 20175	21/09/2026	.00	.00	.00		Planned M	\$0.00
89659	fuel cooler leaking / new cooler fitted 20175	21/09/2026	.00	.00	.00		Planned M	\$0.00
89949	2000hrs service	2/07/2026	.00	.00	.00	357	Preventati	\$0.00
281		Total	96.60	69.50				\$0.00