

Repair Service Summary - Vehicles

Page 1
Date Printed 14/10/2026

Vehicle : V10

Service Type : All Service Types

Date Range : All Dates

Vehicle Status : All

Category Type : All

Transaction Type : Repair and Purchase Orders

Depot : All Depots

Vehicle Type : All

Vehicle	Order Number	Open Date	Close Date	Depot	Registration	Service Type	Hours	Kilometres	Type
V10	00012032	12/04/2016	12/04/2016	TVILL	775WJN	A B	0.0	0	Repair Order
V10	00012033	12/04/2016	12/04/2016	TVILL	775WJN	C D	0.0	0	Repair Order
V10	00012172	06/05/2016	06/05/2016	TVILL	775WJN	A	0.0	8800	Repair Order
V10	00012205	06/05/2016	06/05/2016	TVILL	775WJN	A	0.0	8804	Repair Order
V10	00012295	04/08/2016	04/08/2016	TVILL	775WJN	A B	0.0	39621	Repair Order
V10	00012594	02/12/2016	02/12/2016	TVILL	775WJN	A B	0.0	76694	Repair Order
V10	00012826	07/04/2017	07/04/2017	TVILL	775WJN	B C	0.0	105418	Repair Order
V10	00012827	07/04/2017	07/04/2017	TVILL	775WJN	D	0.0	105418	Repair Order
V10	00013187	12/10/2017	13/10/2017	TVILL	775WJN	B	0.0	152536	Repair Order
V10	00013448	21/02/2018	23/02/2018	TVILL	775WJN	B	0.0	191967	Repair Order
V10	00013537	28/03/2018	28/03/2018	TVILL	775WJN	D	0.0	204390	Repair Order
V10	00013669	06/06/2018	11/06/2018	TVILL	775WJN	B	0.0	229850	Repair Order
V10	00013814	20/08/2018	21/08/2018	TVILL	775WJN	B C	0.0	261121	Repair Order
V10	00014120	24/01/2019	25/01/2019	TVILL	775WJN	B	0.0	301034	Repair Order
V10	00014121	24/01/2019	25/01/2019	TVILL	775WJN	D	0.0	301034	Repair Order
V10	00014310	20/05/2019	20/05/2019	TVILL	775WJN	B	0.0	343761	Repair Order
V10	00014549	09/09/2019	09/09/2019	TVILL	775WJN	B	0.0	384854	Repair Order
V10	00014760	16/12/2019	16/12/2019	TVILL	775WJN	B C	0.0	425232	Repair Order
V10	00014761	16/12/2019	16/12/2019	TVILL	775WJN	D	0.0	425232	Repair Order
V10	00014938	15/04/2020	15/04/2020	TVILL	775WJN	B	0.0	461895	Repair Order
V10	00015152	27/08/2020	27/08/2020	TVILL	775WJN	B	0.0	505222	Repair Order
V10	00015325	03/12/2020	04/12/2020	TVILL	775WJN	B	0.0	540213	Repair Order
V10	00015326	04/12/2020	04/12/2020	TVILL	775WJN	D	0.0	540213	Repair Order
V10	00015504	15/04/2021	15/04/2021	TVILL	775WJN	B C	0.0	574515	Repair Order
V10	00015684	29/07/2021	30/07/2021	TVILL	775WJN	B	0.0	608801	Repair Order
V10	00015824	03/11/2021	03/11/2021	TVILL	775WJN	B	0.0	646164	Repair Order
V10	00015825	03/11/2021	03/11/2021	TVILL	775WJN	D	0.0	646164	Repair Order
V10	00016019	21/03/2022	21/03/2022	TVILL	775WJN	B	0.0	690258	Repair Order
V10	00016291	08/08/2022	08/08/2022	TVILL	775WJN	B C	0.0	735821	Repair Order
V10	00016441	08/11/2022	08/11/2022	TVILL	775WJN	D	0.0	764448	Repair Order
V10	00016611	02/03/2023	02/03/2023	TVILL	775WJN	B	0.0	778066	Repair Order
V10	00016927	07/10/2023	07/10/2023	TVILL	775WJN	B	0.0	829743	Repair Order
V10	00016946	18/10/2023	18/10/2023	TVILL	775WJN	D	0.0	829743	Repair Order
V10	00017248	15/05/2024	15/05/2024	TVILL	775WJN	B C	0.0	867644	Repair Order
V10	00017466	23/09/2024	23/09/2024	TVILL	775WJN	D	0.0	886321	Repair Order
V10	00017746	21/03/2025	21/03/2025	TVILL	775WJN	B	0.0	910691	Repair Order
V10	00018098	13/09/2025	13/09/2025	TVILL	775WJN	D	0.0	935524	Repair Order
V10	00018486	21/05/2026	21/05/2026	TVILL	775WJN	B	0.0	948745	Repair Order
V10	00018708	03/09/2026	03/09/2026	TVILL	775WJN	D	0.0	974195	Repair Order
V10	00018756	05/10/2026	05/10/2026	TVILL	775WJN	B	0.0	991093	Repair Order

Repair Order 00015557

From : [Redacted]
PO BOX 277
DEERAGUN
QLD
Tel : 07 4774 5620 4818
Fax : 07 4774 5477
A.C.N : 98106584034

Customer : [Redacted]
Fleet Number : V10
Make : VOLVO
Registration : 775WJN
Speedo : 558069
Hours : 0.0
Service Type :
Opening Date : 15/02/2021
Closing Date : 04/06/2021
Status : Complete
Raised By : E

Invoice No	Costcode	Part No	Description	Mechanic	Qty	Rate	Value
		ELAB	EXTERNAL LABOUR	WESTERN TRUCK	1.00	850.5000	850.50

Notes : REPAIR REQUEST NO: 3493
DATE: 15/02/2021
CLASSIFICATION: LOW
ACTION TAKEN : MONITORED - 60 DAYS.
INSPECTED - LOW -MONITORED
V10 -775WJN IS GOING TO HAVE 'C' SERVICE WITHIN THE NEXT 60 DAYS TO BE INSPECTED AGAIN THEN.

15/04/2021
MONITORED - 30 DAYS
FNQ MECHANICS COMPLETED 'C' SERVICE FOUND IT TO BE OK. V10 WILL NEED TO BE LOOKED AT BY VOLVO/ WTG.

04/06/2021 - BOOKED INTO WTG.

FIXED
WESTERN TRUCK GROUP
INVOICE NO. 3353124

ENGINE SYSTEM FAULT ENGINE FAN.

EXHAUST PRESSURE GOVERN, CHECK

CONNECT VCADS COMPUTER AND READ VEHICLE INSPECTION
FOUND EGINE SYSTEM FAULTS FOR COOLING FAN
CARRIED OUT ENGINE FAN TEST AND FAILED
DRAINED AND CAPTURED ENGINE COOLANT
DISCONNECTED PIPES TO ACCESS AND REPLACED ENGINE FAN
REFIT REMOVED PIPERS AND HOSES
REFILLED BLEED AND TOPPED UP COOLANT
CLEANED AND WASHED DOWN AREA
START AND RUN ENGINE AND RECHECKED ENGINE FAN OPERATION.

EXHUAST BACK PRESSURE SENSOR, REPLACE

ENGINE BRAKE FUNCTION, TEST

WARM HOLD FUNCTION, TEST

CONNECT-DISCONNECT OF DIAGNOSTIC TOOL

FAULT CODES READING.
ALSO FOUND ENGINE SYSTEM FAULTS FOR EXHAUST BACK PRESSURE
CHECKED WIRING AND CONNECTIONS TO PRESSURE SENSOR
REPLACED PRESSURE SENSOR AND WIRING ADAPTION HARNESS AND SECURE
CLEARED FAULT CODE.

Repair Order 00015557

Page 2

From : [REDACTED]

PO BOX 277
DEERAGUN
QLD

4818

Tel : 07 4774 5620

Fax : 07 4774 5477

A.C.N : 98106584034

Customer : [REDACTED]

Fleet Number : V10

Make : VOLVO

Registration : 775WJN

Speedo : 558069

Hours : 0.0

Service Type :

Opening Date : 15/02/2021

Closing Date : 04/06/2021

Status : Complete

Raised By :
E

Invoice No	Costcode	Part No	Description	Mechanic	Qty	Rate	Value
ROAD TEST AND RECHECK AFTER.							
		EPAR	EXTERNAL PARTS	WESTERN TRUCK	1.00	1834.4100	1834.41
Notes : PARTS: 1 X FAN, EXCH 4 X FLANGE LOCK NUT 1 X V-RIBBED BELT 1 X M8 X 25MM FLANGED HE 1 X SEALING RING 1 X SEALING STRIP 1 X SEALING RING 1 X CABLE TIE 1=10PK 1 X CABLE TIE 1=10PK 1 X VOLVO RUBBER GREASE 2 X GASKET							
		ECON	EXTERNAL CONSUMABLES	WESTERN TRUCK	1.00	75.6100	75.61
Notes : WORKSHOP CONSUMABLES ENVIRONMENTAL LEVY							
Total Value :							2760.52

Printed Name :

Signature :

Date :

Repair Order 00017106

Page 1

From : [REDACTED]
PO BOX 277
DEERAGUN
QLD
Tel : 07 4774 5620 4818
Fax : 07 4774 5477
A.C.N : 98106584034

Customer : [REDACTED]
Fleet Number : V10
Make : VOLVO Opening Date : 15/02/2024
Registration : 775WJN Closing Date : 15/02/2024
Speedo : 848355 Status : Complete
Hours : 0.0 Raised By :
Service Type : K

Invoice No	Costcode	Part No	Description	Mechanic	Qty	Rate	Value
		ELAB	EXTERNAL LABOUR	WESTERN TRUCK	1.00	2887.5000	2887.50

Notes : WTG
WESTERN TRUCK GROUP
INVOICE NO: 6357962

POWER STEERING PIPE REPLACE
RADIATOR, REMOVE
RADIATOR, INSTALL
TOP UP OIL AND FLUID LEVELS.
HYDRAULIC SYSTEM, BLEEDING
ROAD TEST
INSPECT FOR POWER STEERING LEAK
PIPE SET RUNNING UNDER RADIATOR LEAKING.
COULD NOT BRING TRUCK INTO WORKSHOP NO STEERING, TOP UP POWER STEERING RESERVOIR TO MOVE IN AND CONFIRM LEAK LOCATION.
TILT CAB DRAIN COOLANT, DISCONNECTED COMPONENTS FROM RADIATOR HOSES, LINES ETC. ATTEMPTED TO REMOVE RADIATOR FOUND TO BE LODGED STUCK FAST, REMOVED LOWER GRILL RAILS FOR RADIATOR IN ORDER TO REMOVE THE UNIT.
DRAINED ALL POWER STEERING LINES, REMOVED HOSES AND PIPE SET, FITTED NEW PIPE SET REPLACED BOTH STEERING BOX HOSES REQUIRED FURTHER FITTINGS FOR INSTALL OF PIPE SET INTO HYDRAULIC BLOCK AS CURRENT FITTINGS SEIZED. FITTED HOSES TO HYDRAULIC BLOCK TIGHTED ALL FITTINGS AND INSTALLED RADIATOR BACK IN, MOUNT AND PLACE GUIDE BRACKETS.
BACK AROUND AFTER INSTALL.
CONNECT ALL RADIATOR HOSES AND INTERCOOLER PIPES FILLED POWER STEERING FLUID AND FILLED COOLANT.
START TRUCK AND INSPECT FOR LEAKS FOUND ALL TO BE OK.
WASH DOWN TRUCK AND CARRY OUT ROAD TEST.
RECHECK OVER VEHICLE ON RETURN FOUND TO BE ALL OK.
RETURN TO SERVICE.

CONNECT-DISCONNECT OF DIAGNOSTIC TOOL
CCOM, CHECK HARNESS POSITION. ONLY CAMPAIGN.
ADDITIONAL CAMPAIGN WORK. CAMPAIGN ONLY

BRAKE PEDAL TEST.
CONNECTED AND CHECKED FOR FAULT CODES NIL ACTIVE FAULT CODES COULD NOT FAULT AT THIS TIME- MONITOR.

EPAR	EXTERNAL PARTS	WESTERN TRUCK	1.00	2485.5200	2485.52
------	----------------	---------------	------	-----------	---------

Notes : 1 X 23261164 - HOSE
1 X 22795480 - QUICK COUPLING
1 X 984800 - NIPPLE
1 X 23261154 - PIPE
1 X 1161995 - ATF DEXTRON 3 5
10 X 980464 - CABLE TIE - LAR
1 X 23261167 - HOSE
1 X 23296894 - FITTING
1 X 22795480 - QUICK COUPLING

Repair Order 00017106

Page 2

From :

PO BOX 277
DEERAGUN
QLD

Tel : 07 4774 5620

4818

Fax : 07 4774 5477

A.C.N : 98106584034

Customer :

Fleet Number : V10

Make : VOLVO

Registration : 775WJN

Speedo : 848355

Hours : 0.0

Service Type :

Opening Date : 15/02/2024

Closing Date : 15/02/2024

Status : Complete

Raised By :

K

Invoice No	Costcode	Part No	Description	Mechanic	Qty	Rate	Value
4 X 994396 - M10 X 75MM FLAN 1 X AMP24078863 - VOLVO VCS-2 COO							
ECON		EXTERNAL CONSUMABLES		WESTERN TRUCK	1.00	213.0800	213.08
Notes : 1 X ENVIRONMENTAL LEVY 1 X WORKSHOP CONSUMABLES							
Total Value :							5586.10

Printed Name : _____

Signature : _____

Date : _____

Repair Order 00017423

Page 1

From : [REDACTED]
PO BOX 277
DEERAGUN
QLD
Tel : 07 4774 5620 4818
Fax : 07 4774 5477
A.C.N : 98106584034

Customer : [REDACTED]
Fleet Number : V10
Make : VOLVO Opening Date : 27/08/2024
Registration : 775WJN Closing Date : 27/08/2024
Speedo : 874343 Status : Complete
Hours : 0.0 Raised By :
Service Type : K

Invoice No	Costcode	Part No	Description	Mechanic	Qty	Rate	Value
		ELAB	EXTERNAL LABOUR	WESTERN TRUCK	1.00	2257.5000	2257.50

Notes : WTG

WESTERN TRUCK GROUP.
INVOICE NO: 6359384

FAULT CODES ENGINE.

LIFTED TRUCK ON HOIST, REMOVED ADBLUE TANK FROM UNDER TRUCK, 2 BOLTS CEASED IN, TOOK TIME TO REMOVE BOLTS.
ONCE ADBLUE TANK WAS DROPPED, REMOVED SPIKE AND FLUSHED TANK.

REPLACED FILTER ON SPIKE, REFIT TANK TO BOTTOM OF TRUCK,, LOWER TRUCK DOWN FROM HOIST, PLUG ON SPIKE WAS
BRITTLE AND THE LOCKING MECHANISM CRACKED.
HAD TO REPIN NEW CONNECTOR AND REFIT WIRING.

SWITCH ON STEERING WHEEL, REPLACE.

BUTTONS ON STEERING WHEEL NOT WORKING AS THEY SHOULD BE.

REMOVED AND REPLACED STEERING WHEEL BUTTONS.

TESTED FUNCTIONS, ALL WORKING OKAY.

ADBLUE CONNECTOR NO LOCKING - DAMAGED.

CONNECTOR ON THE ADBLUE TANK NOT LOCKING, LOCKER DAMAGED.

REPLACED THE ADBLUE CONNECTOR ON THE TANK WITH A NEW CONNECTOR.

MAIN SWITCH, REPLACE

FILTER INSERT, AIR CLEANER, REPLACE.

ONLY VALID FOR PRIMARY FILTER.

SECONDARY AIR FILTER, REPLACE.

AIR FILTER INSERT REMOVED.

CONNECT TECH TOOL, FOUND CODES FOR AIR PRESSURE MANAGEMENT.

REMOVED BLOCKED FILTERS AND REPLACED WITH NEW AIR CLEANER FILTERS.

CLEARED ALL CODES.

EPAR	EXTERNAL PARTS	WESTERN TRUCK	1.00	1139.0000	1139.00
------	----------------	---------------	------	-----------	---------

Notes : 1 X 22492706 - ADBLUE VENTILAT

1 X 2240683 - ADBLUE PICKUP F

1 X 984734 - M8 X 20MM FLANG

1 X 22629273 - SWITCH

1 X FREIGHT

1 X 21106105 - HOUSING

10 X 948211 - CABLE TIE- SMALL

1 X 20786947 - FUEL TANK TAP

1 X 22629276 - SWITCH

1 X 21834205 - FILTER

1 X 23294956 - FILTER

Repair Order 00017423

Page 2

From :

PO BOX 277
DEERAGUN
QLD

Tel : 07 4774 5620

4818

Fax : 07 4774 5477

A.C.N : 98106584034

Customer :

Fleet Number : V10

Make : VOLVO

Registration : 775WJN

Speedo : 874343

Hours : 0.0

Service Type :

Opening Date : 27/08/2024

Closing Date : 27/08/2024

Status : Complete

Raised By :
K

Invoice No	Costcode	Part No	Description	Mechanic	Qty	Rate	Value
	ECON		EXTERNAL CONSUMABLES	WESTERN TRUCK	1.00	149.0000	149.00

Notes : WORKSHOP CONSUMABLES.

Total Value : 3545.50

Printed Name :

Signature :

Date :

Repair Order 00017903

Page 1

From : [REDACTED]
PO BOX 277
DEERAGUN
QLD
4818
Tel : 07 4774 5620
Fax : 07 4774 5477
A.C.N : 98106584034

Customer : [REDACTED]
Fleet Number : V10
Make : VOLVO
Registration : 775WJN
Speedo : 924410
Hours : 0.0
Service Type :
Opening Date : 30/06/2025
Closing Date : 30/06/2025
Status : Complete
Raised By : K

Invoice No	Costcode	Part No	Description	Mechanic	Qty	Rate	Value
		ELAB	EXTERNAL LABOUR	WESTERN TRUCK	1.00	1406.0000	1406.00
Notes : WTG WESTERN TRUCK GROUP. INVOICE NO: 6361763 DERATING ISSUES. FAULT FOR LOW REAGENT PRESSURE, CONFIRMED PUMP WILL NOT BUILD PRESSURE, REMOVED PUMP FILTER AND STRAINER AND FOUND FILTER LEVELED WITH DIRT, INSPECTED TANK AND FOUND TO BE DAMAGED AND LETTING DIRT INSIDE, REMOVED TANK, PUMP AND FILTERS, CLEANED LINES OUT AND REASSEMBLED WITH NEW PARTS, REPROGRAMMED PUMP AND TESTED ALL WORKING AS NORMAL.							
		EPAR	EXTERNAL PARTS	WESTERN TRUCK	1.00	7255.3700	7255.37
Notes : 1 X 22670998 - TANK 1 X 22716720 - COMBINED TANK U 1 X 24132668 - FILLER & BRKT A 1 X 21584844 - FILLER CAP (ADB) 1 X3944785 - AIR CLEANER 1 X 22681764 - MANIFOLD 10.5 X 949995 - HOSE 40 X 980464 - CABLE TIE (MEDI 1 X 24344205 - PUMP UNIT 10.5 X 21429181 - HOSE 1 X 20748166 - CONNECTOR, SAE 3 X 21032572 - CLAMP 1 X 20744599 - CONNECTOR, 5/16 20 X 21178207 - HEAT INSULATION 1 X 20757803 - HOSE CLAMP (80M 1 X 23381562 - FILTER (AD BLUE 20 X 980464 - CABLE TIE (LARG 1 X 20744598 - CONNECTOR, SAE 5 1 X 21954674 - STRAINER (AD BLUE							
		ECON	EXTERNAL CONSUMABLES	WESTERN TRUCK	1.00	92.8000	92.80
Notes : WORKSHOP CONSUMABLES							
Total Value :							8754.17
Printed Name :							
Signature :				Date :			

Repair Order 00018680

From :

PO BOX 277
DEERAGUN
QLD

Tel : 07 4774 5620
Fax : 07 4774 5477
A.C.N : 98106584034

4818

Customer :

Fleet Number : V10

Make : VOLVO

Registration : 775WJN

Speedo : 969002

Hours : 0.0

Service Type :

Opening Date : 31/08/2026

Closing Date : 31/08/2026

Status : Complete

Raised By : K

Invoice No	Costcode	Part No	Description	Mechanic	Qty	Rate	Value
		ELAB	EXTERNAL LABOUR	WESTERN TRUCK	1.00	3318.0000	3318.00

Notes : WTG
WESTERN TRUCK GROUP
INVOICE NO:6364593

ALTERNATOR FAULT ON DASH- ALTERNATOR HAS BEEN CHANGED AND FAULT STILL PRESENT.

DASH IS CUTTING OUT WHILE DRIVING

CHECKED AND FOUND FAULT CODE P250000, ALTERNATOR CIRCUIT LOW, CHECK BATTERIES, ALTERNATOR AND BELF - OKAY.
FOUND FAULT INTERMITTENT, FOUND ENGINE HARNESS AND WIRING TO ALTERNATOR INSULATION BRITTLE AND WIRES RUBBING IN HARNESS, ALSO CAUSING ALOT OF INTERMITTENT FAULTS.
CHECKED CONTUNITY FROM X302 CONNECTOR TO CC10M - ALL OKAY.
DISCONNECTED BATTERIES AND REMOVED OLD HARNESS, CLEANED AND FITTED NEW ENGINE HARNESS AND SECURED IT.
CLEARED ALL CODES, CHECKED ALTERNATOR CHARGING - ALL OKAY.
DASH FLICKERING WHILE DRIVING, FOUND A LOT OF INTERMITENT FAULTS RELATED TO POWER.
CHECKED HARNESS, POWER AND GROUND CABLES - FOUND CRACKED TERMINAL LUG ON CABLE FROM BATTERY TO CHASSIS GROUND.
REPLACE LUG AND SECURE IT.

COMPRESSOR LINE DAMAGED, REPLACED

FOUND COMPRESSOR CHARGE PIPE DAMAGED.
STEEL BRAIDED PIPE AND REPLACE PIPE.
ROAD TESTED AND FOUND FAULT FOR ENGINE BRAKE COMING UP.
REMOVED VALVE COVER, CHECKED SOLENOID, POWER SUPPLY - ALL OKAY.
FAULTY SOLENOID.
NO PARTS IN STOCK, ASSEMBLED BACK TOGETHER.
PARTS ON ROAD FREIGHT.
CUSTOMER CAN STILL USE TRUCK, ENGINE BRAKE NOT WORKING.
CUSTOMER HAS COLLECT SOLENOID AND IS REPAIRING THEMSELVES.

EPAR	EXTERNAL PARTS	WESTERN TRUCK	1.00	3121.9400	3121.94
------	----------------	---------------	------	-----------	---------

Notes : PARTS:

1 X 22343361 - CABLE HARNESS
20 X 948211 - CABLE TIES SMALL
20 X 980464 - CABLE TIES (MEDIUM)
2 X WUR0890108700 - BRAKE CLEAN 700
1 X 20538793 - GASKET (13L TAP
1 X 21634017 - SENSOR (CRANKCA
2 X 1677370 - SEALING RING
1 X 20526428 - SEALING RING
1 X 23960136 - HOSE
1 X 22833163 - COOLING COIL
1 X 22899626 - SENSOR (FUEL/OIL

Repair Order 00018680

Page 2

From : [REDACTED]
PO BOX 277
DEERAGUN
QLD
Tel : 07 4774 5620 4818
Fax : 07 4774 5477
A.C.N : 98106584034

Customer : [REDACTED]
Fleet Number : V10
Make : VOLVO
Registration : 775WJN
Speedo : 969002
Hours : 0.0
Service Type :
Opening Date : 31/08/2026
Closing Date : 31/08/2026
Status : Complete
Raised By : K

Invoice No	Costcode	Part No	Description	Mechanic	Qty	Rate	Value
		ECON	EXTERNAL CONSUMABLES	WESTERN TRUCK	1.00	200.0000	200.00

Notes : CONSUMABLES:
1 X WORKSHOP CONSUMABLES

Total Value : 6639.94

Printed Name :

Signature :

Date :