

Work Order

CORNWALL

Number: 887

05. WORK FINISHED

Unit N° 356

Plate: PA84462

VIN: 3AKJGEDV0GDHE2247

Make: FRHT

Model:

Year: 2016

Kilometer: 948525

Engine hours: 18775

Date opened: 2026-02-12

Date closed: 2026-02-20

☐ SCHEDULED WORK

T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	*\$/u*	Total
	REP	018			BLAKE VOLPI, 2026-02-12						
	REP	018			Comment / Request						
	REP	018			Pass side needs new wheel gasket.						
	REP	018			*****						
	REP	018			BLAKE VOLPI, 2026-02-12						
	REP	018			Corrections						
	REP	018			Removed wheel axle flange, passenger side 1st axel rear						
	REP	018			Pulled out cleaned the gasket maker off.						
	REP	018			Replaced with new gasket						
	REP	018			Torqued both passenger and driver side.						
	REP	018			Filling up with oil currently.						
	REP	018			*****						
	REP	018			BLAKE VOLPI, 2026-02-13						
	REP	018			Corrections						
	REP	018			Filled with oil.						
	REP	018			Everything is done.						
	REP	018			*****						
	REP	018	75W90		LUCAS GEAR OIL				1.00		

Subtotal-parts:	0.00	+	
Subtotal labor:	254.15		
Shop supply:	38.12		
TOTAL (\$):	292.27		
Hrs.	2.99		

Comment:

WHEELS AND HUB ASSEMBLY

Signature :

Date :

Work Order

CORNWALL

Number:

887

05. WORK FINISHED

Unit N° 356

VIN: 3AKJGEDV0GDHE2247

Make: FRHT

Model:

Year: 2016

Kilometer:

18775

2026-02-12

2026-02-20

T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	*\$/u*	Total
1	REP	018	BVOLPI		BLAKE VOLPI				2.99	85.00	254.15

Comment:

WHEELS AND HUB ASSEMBLY

Signature :

Date:

Subtotal-parts:

0.00

Subtotal labor:	254.15
-----------------	--------

0.00

Shop supply:	38.12
--------------	-------

1

TOTAL (\$) :

92.27

Hrs

2.99

Work Order

CORNWALL

Number: 1156

Unit N°

356

05. WORK FINISHED

☐ SCHEDULED WORK

VIN: 3AKJGEDV0GDHE2247

Make: FRHT

Model:

Year: 2016

Plate: PA84462

Kilometer: 9666289

Engine hours: 18972

Date opened: 2026-03-26

Date closed: 2026-06-26

T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	*\$/u*	Total
☒	REP	DPF	PTS4		DPF MAINTENANCE						
	REP	DPF			TALENT TAMBAOGA, 2026-03-26						
	REP	DPF			Comment / Request						
	REP	DPF			derate						
	REP	DPF			Corrections						
	REP	DPF			plugged scan tool found scr efficiency codes and regen doc inlet pressure too						
	REP	DPF			high						
	REP	DPF			performed quantity test- passed, regen completed but doc pressure code still						
	REP	DPF			active						
	REP	DPF			check and cleaned dpf inlet pipe for pressure sensor- it was normal						
	REP	DPF			Initiated DOC face cleaning procedure - completed						
	REP	DPF			initiated verification regen -completed fault went inactive and all parameters						
	REP	DPF			were reading normal						
	REP	DPF			Initiated SCR efficiency test and it passed						
	REP	DPF			ABS fault front right wiring removed and replaced						
	REP	DPF			ABS fault off						
	REP	DPF			*****						

Comment:

END OF SHIFT

Signature :

Date :

Subtotal-parts:

546.69 +

Subtotal labor:

525.30

Shop supply:

78.80

TOTAL (\$):

1150.79

Hrs.

10.26

Printed: 2026-08-26

by: ST DENIS, ROLLAND

Page : 1

Work Order	CORNWALL	Number:	1156
VIN: 3AKJGEDV0GDHE2247 Make: FRHT Model: Year: 2016		Unit N° 356 Plate: PA84462	05. WORK FINISHED ☐ SCHEDULED WORK
Engine hours: 18972 Kilometer: 9666289		Date opened: 2026-03-26 Date closed: 2026-06-26	

T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	*\$/u*	Total
	REP	DPF			(15381) >> TTALENT 2026-03-26 23:30:56:01						
	REP	DPF			derate (15381) (15381) >> OK						
	REP	DPF			(15382) >> TTALENT 2026-03-26 23:31:11:38						
	REP	DPF			ABS warning light (15382) (15382) >> OK						
	REP	034			GARY ROLLAND, 2026-04-02						
	REP	034			Comment / Request						
	REP	034			LEFT SIDE HEAD LIGHT LOW BEAM IS NOT WORKING.						
	REP	034			Corrections						
	REP	034			LOOKED AT HEAD LIGHT AND FOUND NO POWER GOING TO THE HEAD LIGHT ASSEMBLY.						
	REP	034			LOOKED UP WIRING DIAGRAM AND FOUND POWER COMING OUT OF THE FIREWALL BUT NOT						
	REP	034			REACHING THE LIGHT. RAN AN OVERLAY WIRE .						
	REP	034			LIGHT WORKS NOW BUT HALF THE LOW BEAM IS OUT. INSTALLED A USED UNIT. OK.						
	REP	034			PARTS USED. 6 FEET 14 GUSGE WIRE.						
	REP	034			ONE USED HEAD LIGHT ASSEMBLY.						
	REP	034			12 TIE STRAPS. 960097KM ON UNIT.						
	REP	034									

Comment: END OF SHIFT	Subtotal-parts:	546.69 +	0.00
	Subtotal labor:	525.30	0.00
	Shop supply:	78.80	
	TOTAL (\$):		1150.79
Signature : _____		Date : _____	
Hrs.		10.26	

Work Order

CORNWALL

Number: 1156

Unit N°

356

05. WORK FINISHED

☐ SCHEDULED WORK

VIN: 3AKJGEDV0GDHE2247

Make: FRHT

Model:

Year: 2016

Plate: PA84462

Kilometer: 9666289

Engine hours: 18972

Date opened: 2026-03-26

Date closed: 2026-06-26

T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	*\$/u*	Total
	REP	013			check brake adjustment						
	REP	013			*****						
	INS	PMA	PTS2		SERVICE A						
	INS	PMA			BLAKE VOLPI, 2026-04-23						
	INS	PMA			Comment / Request						
	INS	PMA			A service complete						
	INS	PMA			Tagged the truck with a new sticker						
	INS	PMA			Corrections						
	INS	PMA			Brakes adjusted						
	INS	PMA			truck greased from front to back						
	INS	PMA			5th wheel adjusted						
	INS	PMA			air leak from red line in frame being rubbed through fixed						
	INS	PMA			Filled up power steering to max						
	INS	PMA			Filled up brake fluid to max						
	INS	PMA			Filled coolant from under min to max cold						
	INS	PMA			Changed trailer 7 way plug as it had corroded wires cut back 3inches.						
	INS	PMA			changed tailgate cable as it was corroded also.						
	INS	PMA			Cleaned 7 way and tailgate plugs						

Comment:

END OF SHIFT

Signature :

Date :

Subtotal-parts:

546.69 +

Subtotal labor:

525.30

Shop supply:

78.80

TOTAL (\$):

1150.79

Hrs.

10.26

Work Order

CORNWALL

Number: 1156

VIN: 3AKJGEDV0GDHE2247

Make: FRHT

Model:

Year: 2016

Unit N° 356

Plate: PA84462

Kilometer: 9666289

Engine hours: 18972

05. WORK FINISHED

☐ SCHEDULED WORK

Date opened: 2026-03-26

Date closed: 2026-06-26

T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	*\$/u*	Total
🔧	INS	PMA			Cleaned and sprayed batteries						
🔧	INS	PMA			*****						
🔧	INS	PMA	DDE A4700781810		INJECTOR TUBE		PTS2		1.00	116.090	116.090
🔧	INS	PMA	POWER STEERING FLUID		POWER STEERING FLUID		PTS2		1.00		
🔧	INS	PMA	EP2 GREASE		EP2 GREASE		PTS2		3.00		
🔧	INS	PMA	10W30		MOTOR OIL		PTS2		5.00	4.630	23.150
🔧	INS	PMA	BRAKE CLEAN		BRAKE KLEAN		PTS2		2.00		
🔧	INS	PMA	15-730		7 WAY PLUG		PTS2		1.00	10.930	10.930
🔧	INS	PMA	AUT-179.3022.12		TAILGATE LIFT CABLE 4 GA		PTS2		1.00	58.643	58.640
🔧	INS	PMA	OWI-23539617		COOLANT		PTS2		2.00	11.500	23.000
🔧	INS	PMA	DOT 3		BRAKE FLUID		PTS2		1.00		
🔧	INS	PMA			BLAKE VOLPLI, 2026-04-23						
🔧	INS	PMA			Corrections						
🔧	INS	PMA			Changed injector tube 2 as it was leaking.						
🔧	INS	PMA			Removed old injector tube						
🔧	INS	PMA			replaced with new one and seal.						
🔧	INS	PMA			Torqued to spec.						
🔧	INS	PMA			Started truck and 0 leak.						

Comment:

END OF SHIFT

Signature : _____

Date : _____

Subtotal-parts: 546.69 +

Subtotal labor: 525.30

Shop supply: 78.80

TOTAL (\$) : 1150.79

Hrs. 10.26

Work Order

CORNWALL

Number: 1156

Unit N° 356

05. WORK FINISHED

☐ SCHEDULED WORK

VIN: 3AKJGEDV0GDHE2247

Make: FRHT

Model:

Year: 2016

Plate: PA84462

Kilometer: 9666289

Engine hours: 18972

Date opened: 2026-03-26

Date closed: 2026-06-26

T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	*\$/u*	Total
6	INS	PMA									
6	INS	PMA			Checked all systems						
6	INS	PMA			Brakes are in great standings						
6	INS	PMA			Rad has 0 leaks						
6	INS	PMA			small oil leak around pan at front more sweating then leak.						
6	INS	PMA			Tightened cat walk as it was rattling.						
6	INS	PMA			Full service completed.						
6	INS	PMA			*****						
6	INS	PMA			(679.684) >> BVOLPI 2026-04-23 01:04:45:81						
6	INS	PMA			FIFTH WHEEL MOUNTING, SECURITY, OPERATION OF SLIDING MECHANISM & LOCKS: TO ADJUS						
6	INS	PMA			(679.687) >> BVOLPI 2026-04-23 01:04:47:13						
6	INS	PMA			VEHICLE LIGHTING & TRAILER, AIR & ELECTRICAL CONNECTIONS: TO CHANGE (679.687) >>						
6	INS	PMA			(691.693) >> BVOLPI 2026-04-23 01:04:47:60						
6	INS	PMA			FRAME, ATTACHMENTS, FASTENERS, LINES, WIRING: TO REPAIR (691.693) >> OK						
6	INS	PMA			(717.718) >> BVOLPI 2026-04-23 01:04:48:13						
6	INS	PMA			GENERAL CONDITION OF ENGINE & COMPONENTS: TO REPAIR (717.718) >> OK						
6	INS	PMA			(717.725) >> BVOLPI 2026-04-23 01:04:48:60						

Comment:

END OF SHIFT

Signature :

Date :

Subtotal-parts:

546.69 +

0.00

Subtotal labor:

525.30

0.00

Shop supply:

78.80

TOTAL (\$):

1150.79

Hrs. 10.26

Work Order

CORNWALL

Number: 1156

VIN: 3AKJGEDV0GDHE2247

Unit N° 356

05. WORK FINISHED

Make: FRHT

Plate: PA84462

☐ SCHEDULED WORK

Model:

Engine hours: 18972

Date opened: 2026-03-26

Year: 2016

Kilometer: 9666289

Date closed: 2026-06-26

T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	*\$/u*	Total
	INS	PMA			FLUID LEVELS, LEAKS ETC.: TO ADJUST (717.725)						
	INS	PMA			>> OK						
	INS	PMA			(717.727) >> BVOLPI 2026-04-23 01:04:49:13						
	INS	PMA			SERVICE POWER STEERING FILTER & FLUID: TO ADJUST (717.727) >> OK						
	INS	PMB	PTS3		SERVICE B						
	INS	PMB	DDE A0111539228		OIL PRESSURE SENSOR		PTS3		1.00	128.790	128.790
	INS	PMB			TALENT TAMBAOGA, 2026-05-25						
	INS	PMB			Corrections						
	INS	PMB			AB service not due						
	INS	PMB			plugged scan tool and found communication fault between mcm and egr smart						
	INS	PMB			actuator						
	INS	PMB			diagnosed and found high resistance in the power supply wiring						
	INS	PMB			Found that the engine wiring harness has seen better days - ordered harness						
	INS	PMB			Patched the harness and found a sulphated part and repaired (temporary fix)						
	INS	PMB			performed EGR relearn procedure -passed						
	INS	PMB			Calibrated EGR delta P sensor - passed						
	INS	PMB			Performed verification procedure and fault codes went inactive						

Comment:

END OF SHIFT

Signature :

Date :

Subtotal-parts:

546.69

+

0.00

Subtotal labor:

525.30

0.00

Shop supply:

78.80

TOTAL (\$):

1150.79

Hrs.

10.26

Work Order	CORNWALL	Number:	1156
VIN: 3AKJGEDV0GDHIE2247 Make: FRHT Model: Year: 2016		Unit N° 356 Plate: PA84462	05. WORK FINISHED ☐ SCHEDULED WORK
Date opened: 2026-03-26 Date closed: 2026-06-26		Engine hours: 18972 Kilometer: 9666289	

T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	*\$/u*	Total
	INS	PMB			replaced leaking oil pressure sen						
	INS	PMB			*****						
	REP	045			TALENT TAMBAOGA, 2026-05-28						
	REP	045			Corrections						
	REP	045			Removed and replaced engine wiring harness						
	REP	045			*****						
	REP	045			(19953) >> TTALENT 2026-05-28 18:10:56:97						
	REP	045			Engine wiring harness (19953) (19953) >> OK						
	REP	045			(20163) >> TTALENT 2026-05-28 18:11:01:98						
	REP	045			Def level guage (20163) (20163) >> OK						
	REP	DEF	PTS5		DEF MAINTENANCE						
	REP	DEF	PART # A6805402117		INLET NOX SENSOR		PTS5		1.00	62.310	62.310
	REP	DEF	PART # A0001421180		DEF DOSER GASKET		PTS5		1.00	22.790	22.790
	REP	DEF			TALENT TAMBAOGA, 2026-05-29						
	REP	DEF			Corrections						
	REP	DEF			followed diagnostic procedure						
	REP	DEF			performed def qauntity test, def qauality test- passed						
	REP	DEF			initiated regen						

Comment:
 END OF SHIFT

Signature : _____ Date : _____

Subtotal-parts:	546.69 +	
Subtotal labor:	525.30	
Shop supply:	78.80	
TOTAL (\$):		1150.79
Hrs.		10.26

Work Order

CORNWALL

Number: 1156

Unit N° 356

05. WORK FINISHED

☐ SCHEDULED WORK

VIN: 3AKJGEDV0GDHE2247

Make: FRHT

Model:

Year: 2016

Plate: PA84462

Engine hours: 18972

Date opened: 2026-03-26

Date closed: 2026-06-26

T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	*\$/u*	Total
	REP	DEF			replaced outlet nox sensor						
	REP	DEF			initiated Nox verification - passed						
	REP	DEF			initiated scr efficiency test - failed						
	REP	DEF			performed another Scr efficiency test- failed						
	REP	DEF			checked again for a drifted sensor - normal						
	REP	DEF			conclusion- SCR failed need one box						
	REP	DEF			*****						
	REP	DEF			TALENT TAMBAOGA, 2026-06-05						
	REP	DEF			Corrections						
	REP	DEF			removed and replaced one box						
	REP	DEF			installed DPF filters						
	REP	DEF			swoped sensors and accessories from old box a new one						
	REP	DEF			performed parked regen-completed and derate got lifted						
	REP	DEF			initiated SCR efficiency test- completed and passed						
	REP	DEF			all engine check lights cleared						
	REP	DEF			send unit out as we monitor it closely						
	REP	DEF			Installed all covers and attachments						
	REP	DEF			*****						

Comment:

END OF SHIFT

Signature :

Date :

Subtotal-parts:

546.69 +

0.00

Subtotal labor:

525.30

0.00

Shop supply:

78.80

TOTAL (\$):

1150.79

Hrs. 10.26

Work Order		CORNWALL		Number: 1156	
VIN: 3AKJGEDV0GDHE2247		Unit N° 356		05. WORK FINISHED	
Make: FRHT		Plate: PA84462		☐ SCHEDULED WORK	
Model:		Kilometer: 9666289		Date opened: 2026-03-26	
Year: 2016		Engine hours: 18972		Date closed: 2026-06-26	

T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	*\$/u*	Total
	REP	DEF	DPF FILTER		DPF FILTER		PTS5		2.00		
	REP	DEF	1410		DPF GASKET		PTS5		2.00		
	REP	DEF	PART #A0001421180		DEF DOSER GASKET		PTS5		1.00	22.790	22.790
	REP	DEF	DDE AC00049022421		EXHAUST CLAMP		PTS5		2.00		
	REP	DEF	PART #A6805401317		ONE BOX TEMP SENSOR		PTS5		1.00	78.200	78.200
	REP	DEF			(20171) >> TTALENT 2026-06-05 01:11:39:98						
	REP	DEF			SCR closed loop maximum need diagnosis (20171)						
	REP	DEF			(20171) >> OK						
	REP	DEF			(20525) >> TTALENT 2026-06-05 01:14:21:13						
	REP	DEF			Install one box used (20525) (20525) >> OK						
	REP	DPF	TTALENT		TALENT TAMBAOGA				0.16	85.00	13.60
	REP	034	GROLLAND		GARY ROLLAND				4.08		
	REP	013	SAUBIN		SEBASTIEN AUBIN				0.94	85.00	79.90
	INS	PMA	BVOLPI		BLAKE VOLPI				4.62	85.00	392.70
	INS	PMB	TTALENT		TALENT TAMBAOGA				0.17	85.00	14.45
	REP	DEF	TTALENT		TALENT TAMBAOGA				0.29	85.00	24.65

Comment: END OF SHIFT	Subtotal-parts: 546.69 +		0.00
	Subtotal labor: 525.30		0.00
	Shop supply: 78.80		
	TOTAL (\$) : 1150.79		Hrs. 10.26
Signature : _____		Date : _____	

Work Order

CORNWALL

Number: 1776

Unit N° 356

05. WORK FINISHED

☐ SCHEDULED WORK

VIN: 3AKJGEDV0GDHE2247

Make: FRHT

Model:

Year: 2016

Plate: PA84462

Kilometer: 9666289

Engine hours: 18972

Date opened: 2026-07-16

Date closed: 2026-08-19

T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	*\$/u*	Total
	REP	045			AARON ANDERSON, 2026-07-16						
	REP	045			Comment / Request						
	REP	045			Complaint of lack of power, MIL on						
	REP	045			*****						
	REP	045			AARON ANDERSON, 2026-07-16						
	REP	045			Comment / Request						
	REP	045			brought truck in, scanned, active code for vehicle speed						
	REP	045			eratic, code will						
	REP	045			affect lack of power, had 2 emmissions codes that havent						
	REP	045			been active in 2 weeks						
	REP	045			at least, dpf 60% full, followed troubleshoot, found tail						
	REP	045			shaft sensor damaged						
	REP	045			from rubbing on hall effect grooves on output yoke,						
	REP	045			connector lock broken and						
	REP	045			zip tied in place, everything seized and severely						
	REP	045			corroded, got new sensor and						
	REP	045			connector pieces from globocam, eventually got sensor						
	REP	045			bolt off and sensor out,						
	REP	045			sensor came out in pieces, went back to globocam to						
	REP	045			pick up Talent, took a						
	REP	045			while to clean out bracket area where sensor mounts,						
	REP	045			once sensor installed I						
	REP	045			replaced connector, soldered wires and fibretaped,						
	REP	045			drove around yard,						
	REP	045			speedometer working, cleared codes, put on regen to						
	REP	045			see if any codes come up,						

Comment:

ENGINE

Signature :

Date :

Subtotal-parts:

0.00

Subtotal labor:

641.75

Shop supply:

96.26

TOTAL (\$):

738.01

Hrs.

7.55

+

0.00

+

0.00

Printed: 2026-08-26

by: ST DENIS, ROLLAND

Page : 1

Work Order		CORNWALL	Number: 1776
		Unit N° 356	05. WORK FINISHED
VIN: 3AKJGEDV0GDHE2247 Make: FRHT Model: Year: 2016		Plate: PA84462	☐ SCHEDULED WORK
		Engine hours: 18972	Date opened: 2026-07-16 Date closed: 2026-08-19
		Kilometer: 9666289	

T	Reas	Cod	Part/user N°	Po	Description/Name	Supplier N°	Reference	Ext	Qty	*\$/u*	Total
	REP	045			swept bay, put away tools, Chris said he will check on truck during regen						
	REP	045			*****						
	REP	014			SEBASTIEN AUBIN, 2026-07-20						
	REP	014			Comment / Request						
	REP	014			secured splash guard						
	REP	014			Causes						
	REP	014			worn						
	REP	014			Corrections						
	REP	014			secured driver side splash guard						
	REP	014			*****						
	REP	014			(19952) >> SAUBIN 2026-07-20 18:30:19:95						
	REP	014			Driver side splash shield need to be secured (19952)						
	REP	014			(19952) >> OK						
	REP	014			(19954) >> SAUBIN 2026-07-20 18:30:17:87						
	REP	014			Steer tires (19954) (19954) >> OK						
	REP	045	AANDERSON		AARON ANDERSON				3.75	85.00	318.75
	REP	014	SAUBIN		SEBASTIEN AUBIN				3.80	85.00	323.00

Comment: ENGINE	Subtotal-parts:	0.00	+	0.00
	Subtotal labor:	641.75		0.00
	Shop supply:	96.26		
	TOTAL (\$):		738.01	
Hrs.		7.55		