

Repair Service Summary - Vehicles

Vehicle : V6

Service Type : All Service Types

Date Range : All Dates

Vehicle Status : All

Category Type : All

Transaction Type : Repair and Purchase Orders

Depot : All Depots

Vehicle Type : All

Vehicle	Order Number	Open Date	Close Date	Depot	Registration	Service Type	Hours	Kilometres	Type
V6	00010534	26/09/2014	26/09/2014		232VCO	A B	0.0	0	Repair Order
V6	00010535	26/09/2014	26/09/2014		232VCO	C	0.0	0	Repair Order
V6	00010580	25/10/2014	25/10/2014		232VCO	A B	0.0	10386	Repair Order
V6	00010855	30/01/2015	30/01/2015		232VCO	A B	0.0	51665	Repair Order
V6	00011036	01/04/2015	30/04/2015		232VCO	A B	0.0	85364	Repair Order
V6	00011147	02/06/2015	03/06/2015		232VCO	A B	0.0	115590	Repair Order
V6	00011417	11/08/2015	11/08/2015		232VCO	A B	0.0	147157	Repair Order
V6	00011511	24/09/2015	24/09/2015		232VCO	A B	0.0	149863	Repair Order
V6	00011512	24/09/2015	24/09/2015		232VCO	C	0.0	149863	Repair Order
V6	00011656	10/11/2015	11/11/2015		232VCO	A B	0.0	200496	Repair Order
V6	00011814	22/01/2016	22/01/2016		232VCO	A B	0.0	237172	Repair Order
V6	00011908	15/02/2016	15/02/2016		232VCO	A	0.0	237172	Repair Order
V6	00012037	19/04/2016	19/04/2016		232VCO	A B	0.0	266821	Repair Order
V6	00012038	20/04/2016	20/04/2016		232VCO	C D	0.0	266821	Repair Order
V6	00012198	22/06/2016	22/06/2016		232VCO	A B	0.0	295728	Repair Order
V6	00012396	14/09/2016	14/09/2016		232VCO	B	0.0	327310	Repair Order
V6	00012626	23/12/2016	23/12/2016		232VCO	A B	0.0	359338	Repair Order
V6	00012822	27/03/2017	27/03/2017		232VCO	B C	0.0	387814	Repair Order
V6	00012823	27/03/2017	27/03/2017		232VCO	D	0.0	387814	Repair Order
V6	00012986	28/06/2017	28/06/2017		232VCO	B	0.0	419577	Repair Order
V6	00013098	01/08/2017	01/08/2017		232VCO	A	0.0	437515	Repair Order
V6	00013082	26/08/2017	26/08/2017		232VCO	B	0.0	449217	Repair Order
V6	00013258	04/11/2017	04/11/2017		232VCO	B	0.0	479072	Repair Order
V6	00013377	18/01/2018	18/01/2018		232VCO	B C	0.0	509630	Repair Order
V6	00013378	18/01/2018	18/01/2018		232VCO	D	0.0	509630	Repair Order
V6	00013593	13/04/2018	13/04/2018		232VCO	B	0.0	539940	Repair Order
V6	00013682	05/06/2018	05/06/2018		232VCO	B	0.0	570797	Repair Order
V6	00013762	03/08/2018	03/08/2018		232VCO	B C	0.0	601200	Repair Order
V6	00013970	02/10/2018	02/10/2018		232VCO	B	0.0	629916	Repair Order
V6	00014090	10/12/2018	10/12/2018		232VCO	B	0.0	660133	Repair Order
V6	00014091	10/12/2018	10/12/2018		232VCO	D	0.0	660133	Repair Order
V6	00014270	01/04/2019	01/04/2019		232VCO	B	0.0	701046	Repair Order
V6	00014487	19/07/2019	19/07/2019		232VCO	B	0.0	742680	Repair Order
V6	00014663	18/10/2019	18/10/2019		232VCO	B	0.0	782704	Repair Order
V6	00014750	22/11/2019	22/11/2019		232VCO	B C	0.0	798803	Repair Order
V6	00014751	22/11/2019	22/11/2019		232VCO	D	0.0	798803	Repair Order
V6	00014864	14/02/2020	14/02/2020		232VCO	B	0.0	821628	Repair Order
V6	00015063	10/06/2020	10/06/2020		232VCO	B	0.0	864134	Repair Order
V6	00015272	19/10/2020	19/10/2020		232VCO	B	0.0	904721	Repair Order
V6	00015312	20/11/2020	20/11/2020		232VCO	D	0.0	915922	Repair Order
V6	00015489	01/03/2021	01/03/2021		232VCO	B C	0.0	944389	Repair Order
V6	00015621	25/06/2021	25/06/2021		232VCO	B	0.0	987520	Repair Order

Repair Service Summary - Vehicles

Page 2
Date Printed 14/10/2026

Vehicle : V6

Service Type : All Service Types

Date Range : All Dates

Vehicle Status : All

Category Type : All

Transaction Type : Repair and Purchase Orders

Depot : All Depots

Vehicle Type : All

Vehicle	Order Number	Open Date	Close Date	Depot	Registration	Service Type	Hours	Kilometres	Type
V6	00015846	29/10/2021	29/10/2021		232VCO	B	0.0	1027554	Repair Order
V6	00015925	19/11/2021	19/11/2021		232VCO	D	0.0	1032518	Repair Order
V6	00016134	11/05/2022	11/05/2022		232VCO	B	0.0	1065493	Repair Order
V6	00016315	18/08/2022	18/08/2022		232VCO	B	0.0	1106853	Repair Order
V6	00016375	28/09/2022	28/09/2022		232VCO	B C	0.0	1124125	Repair Order
V6	00016376	28/09/2022	28/09/2022		232VCO	D	0.0	1124125	Repair Order
V6	00016597	03/02/2023	03/02/2023		232VCO	B	0.0	1165521	Repair Order
V6	00016891	15/09/2023	15/09/2023		232VCO	D	0.0	1192216	Repair Order
V6	00017037	06/12/2023	06/12/2023		232VCO	B	0.0	1206497	Repair Order
V6	00017246	09/05/2024	09/05/2024		232VCO	B	0.0	1247742	Repair Order
V6	00017376	18/07/2024	18/07/2024		232VCO	B C	0.0	1285960	Repair Order
V6	00017438	09/09/2024	09/09/2024		232VCO	D	0.0	1298198	Repair Order
V6	00017557	04/11/2024	04/11/2024		232VCO	B	0.0	1325508	Repair Order
V6	00017731	11/03/2025	11/03/2025		232VCO	B	0.0	1365020	Repair Order
V6	00017892	16/06/2025	30/06/2025		232VCO	B	0.0	1405218	Repair Order
V6	00017993	20/08/2025	22/08/2025		232VCO	B C	0.0	1447804	Repair Order
V6	00017994	20/08/2025	22/08/2025		232VCO	D	0.0	1447804	Repair Order
V6	00018200	14/11/2025	14/11/2025		232VCO	B	0.0	1487904	Repair Order

Page 1

Customer :			
Fleet Number :	V6		
Make :	VOLVO	Opening Date :	03/08/2018
Registration :	232VCO	Closing Date :	03/08/2018
Speedo :	601200	Status :	Complete
Hours :	0.0	Raised By :	L
Service Type :	B C		

Invoice No	Costcode	Part No	Description	Mechanic	Qty	Rate	Value
		ELAB	B SERVICE AS PER CHECKLIST	WESTERN TRUCK	0.00	0.0000	0.00
Notes :							
	ECON	CONW	B WORKSHOP CONSUMABLES		0.00	0.0000	0.00
Notes : WESTERN TRUCK GROUP TOOWOOMBA INVOICE NO. 66509							
		ELAB	C SERVICE AS PER CHECKLIST	WESTERN TRUCK	1.00	2082.5000	2082.50
Notes : WESTERN TRUCK GROUP TOOWOOMBA INVOICE NO. 66509							
JOB#1 CARRY OUT ANNUAL SERVICE AS PER MANUFACTURERS SPECIFICATION MAINTENANCE MANUAL. ALL BELT TENSIONERS ARE ORIGINAL AND 6000,000 - REMOVED AND REPLACED BELTS AND TENSIONERS. LEAK ON POWER STEERING PUMP GEARBOX COOLER HOSES LEAKING LH STEER BRAKE CALIPER HAS MOVEMENT CUSTOMERS INSTRUCTIONS: COMPLETED AND APPLIED SERVICE STICKER.							
JOB#2 REPLACE TURBO REMOVED ALL LINES TO THE TURBO AND REMOVED TURBO. FOUND THE EXHAUST MANIFOLD TO BE LEAKING. REMOVED MANIFOLD. CLEANED AND CHANGED SLIP JOINTS. REFIT WITH STAINLESS SPACERS. FIT NEW TURBO AND CONNECTED PIPES. TEST DROVE VEHICLE - ALL CORRECT.							
JOB#3 FRONT CAB SHOCKS ARE LEAKING OIL AND RUBBER ARE U/S INSPECT REAR CAB SHOCKS NO FRONT CAB SHOCK ABSORBERS IN STOCK TO COMPLETED JOB.							
	ECON	CONW	C WORKSHOP CONSUMABLES		1.00	134.9300	134.93
Notes : 1 X CONSUMABLES							
		EPAR	EXTERNAL PARTS	WESTERN TRUCK	1.00	4472.8400	4472.84
Notes : OILS:							
36 X VT85121796 VDS4 ENGINE OIL 1L 38 X VT8394843 GEAR OIL, 1000L IBC 18 X VT8394840 TRANS OIL SAE50 1L							
PARTS:							

Repair Order 00013762

Page 2

From :
PO BOX 277
DEERAGUN
QLD

Tel : 07 4774 5620
Fax : 07 4774 5477
A.C.N : 98106584034

4818

Customer :

Fleet Number : V6

Make : VOLVO

Registration : 232VCO

Speedo : 601200

Hours : 0.0

Service Type : B C

Opening Date : 03/08/2018

Closing Date : 03/08/2018

Status : Complete

Raised By :
L

Invoice No	Costcode	Part No	Description	Mechanic	Qty	Rate	Value
			1 X VT21834205 FILTER				
			1 X VT85136742 FILTER KIT				
			1 X VT20779040 SERVICE KIT,				
			1 X VT21516229 ADBLUE FILTER				
			2 X VT21743197 AIR CLEANER				
			1 X VT23260134 AIR DRYER FILTER				
			1 X VT20538793 SEALING STRIP				
			1 X VT21392404 FILTER				
			1 X VT3944785 AIR FILTER - COMP.				
			1 X VT82354791 VENTILATION FILTER				
			6 X VT20855371 GASKET				
			1 X VT22718180 KIT				
			2 X VT20883450 SEALING RING				
			2 X VT21433769 SEALING RING				
			1 X VT21479276 BELT TENSIONER				
			1 X VT21766717 IDLER PULLEY				
			1 X VT21819687 BELT TENSIONER				
			1 X VT85020372 EXCH TURBOCHARGER				
			1 X VT20784537 TURBO BASE GASKET				
			4 X VT993811 FLANGE SCREW				
			1 X VT469601 TURBO DRAIN SEAL				
			1 X VT420643 TURBO DRAIN GASKET				
			1 X VT22206133 TURBO FEED GASKET				
			1 X VT21940615 TURBO DRN SEAL (BLOCK)				
Total Value :							6690.27

Printed Name :

Signature :

Date :

Repair Order 00014787

Page 1

From : [REDACTED]
PO BOX 277
DEERAGUN
QLD
4818
Tel : 07 4774 5620
Fax : 07 4774 5477
A.C.N : 98106584034

Customer : [REDACTED]
Fleet Number : V6
Make : VOLVO
Registration : 232VCO
Speedo : 810559
Hours : 0.0
Service Type :
Opening Date : 09/01/2020
Closing Date : 09/01/2020
Status : Complete
Raised By : L

Invoice No	Costcode	Part No	Description	Mechanic	Qty	Rate	Value
		ELAB	EXTERNAL LABOUR	WESTERN TRUCK	1.00	499.7000	499.70
Notes : WESTERN TRUCK GROUP INVOICE NO. 6001612 MUFFLER BLOCKED UP CAUSING HIGH BACK PRESSURE AND EXHAUST TEMPS. REMOVED OLD MUFFLER AND STRIPPED DOWN WHILE STRIPPING MUFFLER DOWN BOLTS WERE SIZED HAD TO USE OXY AND HEAT BOLTS UP WHEN UNDONE CLEANED BOLTS ALL CORRECT SWAPPED OVER PARTS AND ANTI SIEZED TO NEW MUFFLER AND FITTED NEW MUFFLER TEST DROVE ALL CORRECT NEW SERIAL NUMBER P 20920708300619							
		ECON	EXTERNAL CONSUMABLES		1.00	29.9800	29.98
Notes : 1 X WORKSHOP CONSUMABLES							
		EPAR	EXTERNAL PARTS	WESTERN TRUCK	1.00	4938.2000	4938.20
Notes : PARTS: 1 X VO 20920708 SILENCER 1 X ROAD FREIGHT							
						Total Value :	5467.88

Printed Name : [REDACTED]
Signature : [REDACTED]

Date : [REDACTED]

Repair Order 00015951

Page 1

From : [REDACTED]
PO BOX 277
DEERAGUN
QLD
Tel : 07 4774 5620 4818
Fax : 07 4774 5477
A.C.N : 98106584034

Customer : [REDACTED]
Fleet Number : V6
Make : VOLVO Opening Date : 13/01/2022
Registration : 232VCO Closing Date : 20/01/2022
Speedo : 1041773 Status : Complete
Hours : 0.0 Raised By :
Service Type : K

Invoice No	Costcode	Part No	Description	Mechanic	Qty	Rate	Value
		ELAB	EXTERNAL LABOUR	WESTERN TRUCK	1.00	2280.0000	2280.00

Notes :

WTG
WESTERN TRUCK GROUP PTY LTD.
INVOICE NO: 6008712

ALTERNATOR FAILURE WARNING COMING UP ON DASH. PLEASE INSPECT.

ALTERNATOR BELT.

TECH INSPECTED.

CONFIRMED ISSUE.

FOUND ALTERNATOR DRIVE BELT SNAPPED.

FURTHER INSPECTION FOUND BELT TENSIONER PULLEY TO BE SEIZED & ALTERNATOR REAR BEARING DRY/ NOISY.

TECH ALSO FOUND BELT TO HAVE DAMAGED FAN HUB WIRING.

REPLACEMENT ALTERNATOR, BELT, TENSIONER PULLEY & FAN HUB REQUIRED TO RECTIFY.

TECH DRAINED COOLANT & REMOVED RADIATOR ASSEMBLY.

TECH NOTD RADIATOR PIPE FOUND TO BE PARTIALLY SPLIT & WEEPING.

REPLACEMENT PART ORDERED.

TECH CARRIED OUT REPLACEMENT OF FAN HUB, REPLACING HAB STUDS THAT SNAPPED UPON REMOVAL - ONCE REMOVED
TECH ALSO FOUND FAN VISCOUS CLUTCH ASSEMBLY SHOWING SIGNS OF WEAR.

REPLACED AS PREVENTATIVE MAINTENANCE.

UPON REINSTALLATION OF RADIATOR, BOTTOM HOSE MOUNT CAUGHT ON BULLBAR MOUNT AND WAS DAMAGED.

TECH REPLACED RADIATOR ASSEMBLY & REFILLED WITH FRESH COOLANT - OLD COOLANT BELOW AVERAGE CONDITION.
BLED SYSTEM & CARRIED OUT ROAD TEST.

ENGINE LIGHT CAME ON DURING ROAD TEST.

CONNECTED TECH TOOL & FOUND FAULTS RELATING TO BOOST PRESSURE SENSOR.

FURTHER INSPECTION FOUND SENSOR TO BE INTERMITTENTLY OPEN CIRCUIT.

TECH REPLACED SENSOR & CLEARED FAULT CODES.

CHECKED FOR COOLANT LEAKS.

ALL OK

EPAR	EXTERNAL PARTS	WESTERN TRUCK	1.00	4212.9100	4212.91
------	----------------	---------------	------	-----------	---------

Notes : 1 X 85020836 - EXCH ALTERNATOR
1 X 21819687 - BELT TENSIONER
1 X 85023556 - FAN, EXH
1 X 22031832 - FAN HUB
1 X 22275091 - ALTERNATOR BELT
1 X 21479276 - BELT TENSIONER
1 X 21766717 - IDLER PULLEY FA
1 X 984735 - BOLT FLANGE M8
4 X 953053 - STUD
4 X 990950 - NUT FLANGE M8 X
1 X 21112140 - CONNECTOR
40LTS X AMP22567335 - VCS COOLANT 20L
1 X 22241727 - PIPE
1 X FREIGHT AND HANDLING
1 X 22422785 - SENSOR

Repair Order 00015951

Page 2

From : [REDACTED]
PO BOX 277
DEERAGUN
QLD
Tel : 07 4774 5620 4818
Fax : 07 4774 5477
A.C.N : 98106584034

Customer : [REDACTED]
Fleet Number : V6
Make : VOLVO
Registration : 232VCO
Speedo : 1041773
Hours : 0.0
Service Type :
Opening Date : 13/01/2022
Closing Date : 20/01/2022
Status : Complete
Raised By : K

Invoice No	Costcode	Part No	Description	Mechanic	Qty	Rate	Value
	ECON		EXTERNAL CONSUMABLES	WESTERN TRUCK	1.00	150.4800	150.48
Notes : WORKSHOP CONSUMABLES.							
	RADA	21122253	TEMPERATURE SENSOR		1.00	207.1800	207.18
Notes :							
Total Value :							6850.57

Printed Name :

Signature :

Date :

Repair Order 00016164

Page 1

From : [REDACTED]
PO BOX 277
DEERAGUN
QLD
Tel : 07 4774 5620 4818
Fax : 07 4774 5477
A.C.N : 98106584034

Customer : [REDACTED]
Fleet Number : V6
Make : VOLVO Opening Date : 26/05/2022
Registration : 232VCO Closing Date : 26/05/2022
Speedo : 1065455 Status : Complete
Hours : 0.0 Raised By :
Service Type : K

Invoice No	Costcode	Part No	Description	Mechanic	Qty	Rate	Value
		ELAB	EXTERNAL LABOUR	WESTERN TRUCK	1.00	3420.0000	3420.00

Notes : WTG

WESTERN TRUCK GROUP.
INVOICE NO: 6010034

CORRECTION: DRAINED COOLANT, REMOVED COOLANT LINE TO GEARBOX, REMOVED DRIVESHAFT.
REMOVED AIR TANK, REMOVED GEARBOX, REMOVE CLUTCH AND FLYWHEEL.
TOOK FLY WHEEL TO ENGINE ROOM FOR MACHINING.
REMOVED GEARBOX CONTROL UNTIL REMOVED SHIFTER ASSEMBLY.
REMOVED REAR HOUSING.
REMOVED FLY WHEEL HOUSING AND PRESSURE PLATE ASSEMBLY.
REMOVED INPUT SHAFT.
REMOVED BEARING AND GEAR FROM INPUT SHAFT.
FITTED NEW INPUT SHAFT WITH NEW BEARING.
FITTED SHIFTER ASSEMBLY, REAR HOUSING.
FILLED GEARBOX WITH OLD OIL.
FITTED SHIFTER CONTROL UNIT.
FITTED NEW REAR MAIN SEAL.
FITTED FLY WHEEL AND CLUTCH.
PUT GEARBOX IN AND CONNECTED COOLANT LINES.
ELECTRICAL LINE AND DRIVE SHAFT.
REPROGRAMMED GEARBOX AND CLUTCH.
FILLED COOLANT AND TEST DROVE.
ALL WAS GOOD AFTER TEST DRIVE.
REPLACED GEARBOX COOLER LINES WERE LEAKING SO REPLACED THEM.

EPAR	EXTERNAL PARTS	WESTERN TRUCK	1.00	10882.9300	10882.93
------	----------------	---------------	------	------------	----------

Notes : 1 X 85022461 - CLUTCH KIT
8 X 995906 - BOLT HEX M14 X
8 X 25339078 - NUT TAILSHAFT
1 X 85013166 - CLUTCH CYCLINDER
1 X 22327063 - PWM VALVE VOLVO
1 X 22485772 - SEAL KIT CLUTCH
4 X 983472 - SMALL GREY CABL
1 X 20483426 - M DRIVE INPUT S
1 X SEALANT VOLVO G
1 X 20497205 - CLUTCH BRAKE GA
1 X 22358444 - INPUT SHAFT
1 X FREIGHT
1 X21626057 - ROLLER BEARING
1 X 85108352 - REAR CRANKSHAFT
1 X SPIGOT BEARING
1 X 21244695 - M DRIVE CONTROL
1 X 20785252 - M DRIVE OIL COO
1 X 2370846 - M DRIVE OIL COO
1 X 20992763 - M DRIVE CLUTCH

Repair Order 00016164

Page 2

From :
PO BOX 277
DEERAGUN
QLD
Tel : 07 4774 5620 4818
Fax : 07 4774 5477
A.C.N : 98106584034

Customer :
Fleet Number : V6
Make : VOLVO
Registration : 232VCO
Speedo : 1065455
Hours : 0.0
Service Type :
Opening Date : 26/05/2022
Closing Date : 26/05/2022
Status : Complete
Raised By : K

Invoice No	Costcode	Part No	Description	Mechanic	Qty	Rate	Value
1 X 20860677 - SEALING RING							
ECON			EXTERNAL CONSUMABLES	WESTERN TRUCK	1.00	200.0000	200.00
Notes : WORKSHOP CONSUMABLES							
Total Value :							14502.93

Printed Name :

Signature :

Date :

Repair Order 00016949

Page 1

From : [REDACTED]
PO BOX 277
DEERAGUN
QLD
4818
Tel : 07 4774 5620
Fax : 07 4774 5477
A.C.N : 98106584034

Customer : [REDACTED]
Fleet Number : V6
Make : VOLVO
Registration : 232VCO
Speedo : 1195169
Hours : 0.0
Service Type :
Opening Date : 11/10/2023
Closing Date : 11/10/2023
Status : Complete
Raised By : K

Invoice No	Costcode	Part No	Description	Mechanic	Qty	Rate	Value
		ELAB	EXTERNAL LABOUR	ROAD	1.00	2581.3800	2581.38

Notes : ROAD TRANSPORT SPECIALISTS.
INVOICE NO: 148720

D SERVICE REPAIRS.

OPERATION:

REPLACE TURNTABLE AND FEET BUSHES.

REPLACE RH TAIL LIGHT BRACKET.

REPLACE REAR DRIVE SWAY BAR LINKS.

FIT ORING TO BREATHER PIPE IN TAPPET COVER.

REPLACE EXHAUST PIPE BETWEEN TURBO AND MUFFLER.

OUTSIDE REPAIRS:

MANUFACTURE CHROME STACK

REPAIR BROKEN WIRING TO PASSENGER SIDE TAIL LIGHT.

		EPAR	EXTERNAL PARTS	ROAD	1.00	4646.8500	4646.85
--	--	------	----------------	------	------	-----------	---------

Notes : PARTS:
1 X JOST
1 X SEALING RING
1 X REFLECTOR
1 X RH TAIL LIGHT BRACKET
1 X LED TAIL LAMP LHS LONG
2 X SWAY BAR LINK
1 X EXHAUST PIPE

		ECON	EXTERNAL CONSUMABLES	ROAD	1.00	25.0000	25.00
--	--	------	----------------------	------	------	---------	-------

Notes : SUPPLIES:
1 X SUPPLIES

Total Value : 7253.23

Printed Name :

Signature :

Date :

Total Value : 8257.54

Printed Name :

Signature :

Date : 11/11/2011

Page 1

Customer :			
Fleet Number :	V6		
Make :	VOLVO	Opening Date :	16/06/2025
Registration :	232VCO	Closing Date :	30/06/2025
Speedo :	1405218	Status :	Complete
Hours :	0.0	Raised By :	
Service Type :	B	K	

Notes : ROAD TRANSPORT SPECIALISTS.
INVOICE NO:152743

B SERVICE.

OPERATION:

CARRY OUT B SERVICE AS PER SERVICE SHEET.
CHANGE ENGINE OIL, 3 X FILTERS AND 2 X FUEL FILTERS.
RESET AIR DRYER THROUGH COMPUTER SYSTEM.
FIT PLASTIC PANEL BELOW WINDSCREEN.
REPLACE REAR CAB CROSS SHOCKS.
REPLACE LH HEAD LIGHT ASSEMBLY.
REPLACE LOW BEAM BULB.
CLEARED FAULT CODES FOR ADBLUE COUNTDOWN.
ROAD TEST.
REPLACE STONEGUARD AND AND MODIFY SUPPORT BRACKETS.
DELIVER VEHICLE TOWTG FOR WINDSCREEN CALIBRATION AND PICK UP.

OUTSIDE REPAIRS.
CALIBRATE WINDSCREEN AND ADJUST CAMERAS.

Notes : SUPPLIES:
1 X SUPPLIES

Notes : OILS:

- 1 X CHASSIS GREASE
- 1 X ENGINE OIL
- 5 X FILTER DISPOSAL FEE
- 1 X FILTER KIT
- 1 X TAIL LAMP
- 1 X AIR DRYER SERVICE KIT
- 1 X TAIL LAMP CLUST
- 1 X PANEL
- 1 X FREIGHT ON PARTS.
- 1 X HEADLAMP ASSY - LHS SILVER
- 2 X STONE GUARD
- 4 X FLANGE LOCK NUT
- 4 X FLANGE SCREW
- 1 X HOUSING
- 4 X CABLE TERMINAL
- 9 X CABLE SEAL

Repair Order 00017892

Page 2

From : **[REDACTED]**
PO BOX 277
DEERAGUN
QLD
4818
Tel : 07 4774 5620
Fax : 07 4774 5477
A.C.N : 98106584034

Customer : **[REDACTED]**
Fleet Number : V6
Make : VOLVO
Registration : 232VCO
Speedo : 1405218
Hours : 0.0
Service Type : B
Opening Date : 16/06/2025
Closing Date : 30/06/2025
Status : Complete
Raised By : K

Invoice No	Costcode	Part No	Description	Mechanic	Qty	Rate	Value
			8 X CABLE SEAL				
			8 X CABLE TERMINAL				
			4 X ANTI TAMPER SEAL				
			2 X SHOCK ABSORBERS				
			1 X STONE GUARD				
			1 X PLUG				
Total Value :							7543.95

Printed Name :

Signature :

Date :

From : [REDACTED]
PO BOX 277
DEERAGUN
QLD

Tel : 07 4774 5620
Fax : 07 4774 5477
A.C.N : 98106584034

4818

Customer :			
Fleet Number :	V6		
Make :	VOLVO	Opening Date :	12/12/2025
Registration :	232VCO	Closing Date :	12/12/2025
Speedo :	1498989	Status :	Complete
Hours :	0.0	Raised By :	
Service Type :		K	

Invoice No	Costcode	Part No	Description	Mechanic	Qty	Rate	Value
	ELAB		EXTERNAL LABOUR	ROAD	1.00	8575.0000	8575.00

Notes : ROAD TRANSPORT SPECIALISTS.
INVOICE NO: 50493

TOWING & REPAIRS ON TRUCK & TRAILERS.

REMOVE TURBO, EXHAUST PIPING, BOOST PIPING, RADIATOR COMPONENTS, BULLBAR AND RADIATOR FOR REPAIRS ON TURBO FAILURE.

CLEAN OUT INTAKE PIPES.

INSPECT CHARGE AIR COOLER. (NOT SERVICEABLE)

INSPECT SCR MUFFLER. (NOT SERVICEABLE)

REPLACE AIR FILTER ELEMENTS

REPAIR FAN SHROUD.

FIT NEW TURBO ASSEMBLY.

FIT NEW CHARGE AIR COOLER.

REPLACE HOSES AS REQUIRED.

REMOVE MUFFLER ASSEMBLY.

FIT NEW MUFFLER.

COMPLETE ASSEMBLY OF ENGINE.

REFIT BULLBAR.

TOP UP ENGINE OIL.

TOP UP COOLANT.

START ENGINE AND CHECK OPERATION.

REFIT TAIL SHAFT.

TEST DRIVE AND CHECK OVER.

TOWING SUBLET

FRONT LIFT:

MOVE TOW TRUCK INTO POSITION.

UNDERLIFT FRONT OF VEHICLE AND SECURE.

TIE STEERING WHEEL IN STRAIGHT POSITION.

SUPPLY AIR TO TRUCK

SUPPLY AIR & SERVICE BRAKE TO TRAILERS.

FIT LIGHT BOARD & SIGN TO TRUCK/TRAILER.

DROP TRAILERS AT VINIDEX WELLCAMP QLD.

REFIT LIGHT AND SIGN ETC TO TRUCK.

DELIVER TO ROAD TRANSPORT SPECIALISTS.

EPAR	EXTERNAL PARTS	ROAD	1.00	10155.2400	10155.24
------	----------------	------	------	------------	----------

Notes : PARTS:

1 X HOSE INTERCOOLER

1 X AIR FILTER

1 X FILTER AIR

4 X TURBO MOUNT BOLT

1 X CHARGE AIR COOLER VOLVO

1 X FREIGHT ON PARTS

Page 2

Page 2

Customer :			
Fleet Number :	V6	Opening Date :	12/12/2025
Make :	VOLVO	Closing Date :	12/12/2025
Registration :	232VCO	Status :	Complete
Speedo :	1498989	Raised By :	K
Hours :	0.0		
Service Type :			

Invoice No	Costcode	Part No	Description	Mechanic	Qty	Rate	Value
1 X TURBO ASSY HOLSTEL WITH GASKETS 1 X HOSE ELBOW AIR CLEANER 1 X EXHAUST CLAMP 1 X BOLT FLANGED M10 X 1.5 X 50MM 1 X NUT FLANGED M10X1.5 1 X MUFFLER CATALYST 1 X COOLANT 20LTR							
ECON		EXTERNAL CONSUMABLES		ROAD	1.00	75.0000	75.00
Notes : CONSUMABLES: 1 X ENGINE OIL 1 X WORKSHOP CONSUMABLES							
						Total Value :	18805.24
Printed Name : Signature : Date :							