

Work Order History Report

Asset	W/O No	Description	Finished	Done Reading
CB1335		Cat 730 ADT #2 (7302)		
	193311	POS 1 Plug repair (Premiums)	20/05/2026	Hours
	192425	Pumped tyre up	18/05/2026	
	192467	Repair flat tyre	5/05/2026	
	193027	250 Hour Earthmoving service	4/05/2026	Hours
	60670	Standard Work Order	16/02/2026	
	60669	A/C not working	16/02/2026	
	189000	500 Hour Earthmoving Service	18/12/2025	
	188421		16/12/2025	
	189550	No Start - Flat Batteries, Jump started - Checked charge rate - 26.8V	2/12/2025	
	187258	A/C re-gassed and charged	3/09/2025	
	186862	250 Hour Earthmoving service	2/09/2025	
	187054	Transmission = Inspected-OK Cleaned ECM plugs	18/07/2025	
	185335	Re-built brake brake	21/06/2025	
	182237	500 Hour Earthmoving Service	13/02/2025	
	181271	Replaced LHFR caliper and front shaft	27/11/2024	
	180904	250 Hour Earthmoving service	27/11/2024	
	180368	Inspect machine = OK	23/10/2024	
	173857	A/C drain un-blocked	16/08/2024	
	170926	UHF mount replaced	6/08/2024	

Asset	W/O No	Description	Finished	Done Reading
	168636	Remove front Left wheel/ Final drive and brake assembly to fit to 730#4 # refit wheel and brake assembly	4/07/2024	
	173956	Tyre replaced	1/03/2024	
	173823	Isolator left on = Replaced LH battery	25/02/2024	
	173708	Park brake adjusted	22/02/2024	
	173699	A/C = Inspected/OK	14/02/2024	
	170845	SEAT BELT REPLACEMENT	7/12/2023	
	170836	500 Hour Earthmoving Service	28/11/2023	
	171002	Pos#3 tyre inflated	30/10/2023	
	170500	Pos#3 tyre inflated - 29.09.2023 Pos#3 tyre inflated - 04.10.2023 Pos#3 tyre inflated - 23.10.2023	23/10/2023	
	169891	Repaired steering coulumn cable/lever assembly	25/09/2023	
	169856	Fuel pressure sensor replaced Replaced steering column pivot bushes and lubricated	21/09/2023	
	169867	Pos#3 tyre inflated	18/09/2023	
	169860	Wheel nuts tensioned	15/09/2023	
	169873	Cleaned oil pressure sensor plug Repaired transmission filter wiring GPS tracker un-plugged	14/09/2023	
	168474	250 Hour Earthmoving service	11/09/2023	
	170537	Pos#3, 4, 6, 1 tyres replaced Rotated Pos#2 to #6	7/09/2023	
	168322	Replaced window	9/08/2023	
	168071	Cab cleaned out	7/08/2023	
	165528	Flashing light wiring and transfer fuel pump repaired	23/05/2023	
	164552	2000 Hour earthmoving service	29/04/2023	
	163032	Replaced exhaust, clamps and brackets	6/04/2023	
	163061	500 Hour Earthmoving Service	24/02/2023	

Asset	W/O No	Description	Finished	Done Reading
	159858	Pressure switch plugged in = OK	21/02/2023	
	155926	Reverse camera monitor replaced	15/11/2022	
	158419	Water pump replaced	15/09/2022	
	158299	Replaced hose from front of engine to LH cooler	8/09/2022	
	155608	250 Hour Earthmoving service	7/09/2022	
	155921	LHR #5 tyre pumped up as needed	27/06/2022	
	155657	Tyre pumped up by 5psi	15/06/2022	
	154976	Steering adjuster lever, cable and strut replaced	9/06/2022	
	149117	Hinge point on back of truck = Inspected/OK	9/06/2022	
	155402	Tyre inflated as needed	7/06/2022	
	155404	Replaced coupling seal from transmission pipe	3/06/2022	
	154939	Tyre #5 inflated	31/05/2022	
	153454	Steering column adjuster bolt repaired	16/05/2022	
	153844	500 Hour Earthmoving Service	6/05/2022	
	154605	UHF cable and aerial base replaced	5/05/2022	
	154599	RH mirror replaced	3/05/2022	
	154321	Metal aerial cable secured as needed	28/04/2022	
	154329	LH hoist cylinder replaced	21/04/2022	
	154327	Park brake adjusted	21/04/2022	
	153734	Replaced fuel filters	11/04/2022	
	153578	Hose under cab replaced PIRTEK	11/04/2022	
	153738	Flashing light and wiring replaced	6/04/2022	
	151669	250 Hour Earthmoving service	14/02/2022	
	151774	Front suspension cylinders serviced and heights adjusted	8/02/2022	
	152001	Transmission filter replaced	7/02/2022	

Asset	W/O No	Description	Finished	Done Reading
	151775	Trans/gear filters replaced as needed	4/02/2022	
	150976	Replaced batteries	14/01/2022	
	151902	Jump started	11/01/2022	
	151468	Hose under hatch area replaced as needed	20/12/2021	
	150022	500 Hour Earthmoving Service	9/12/2021	
	149844	Trans filter fault replaced filter and cleared code reeve F	22/11/2021	
	149086	250 Hour Earthmoving service	18/11/2021	
	149327	Coolant leak, music radio not working Replaced stereo + wiring, replaced leaking heater tap, topped up coolant Sealed window for rain Reeve F	5/11/2021	
	148506	Replaced front wiper blade Reeve F	13/10/2021	
	148505	Retarder not engaging, suspension stiff Purged front suspension cylinder and changed oil, set to correct height Replaced retarder actuator valve Ben P Replaced cab mounts and bushes/pins replaced leaking joint on trans pipe Reeve F	29/09/2021	
	148117	Running slow Checked codes air filter restriction Cleaned air filter-ok Reeve F	26/08/2021	
	143674	No E-stop in cabin Insp. for E-stop in cab. Already fitted	24/08/2021	
	146599	Broken seat Pick up seat from WesTrac. Removed faulty seat/base. Fitted new seat & base	19/08/2021	
	146372		13/08/2021	
	146371	Flat tyre/missing lock R/H/F tyre low 15psi. Middle right tyre missing wheel lock /lock ring turned & not aligning. Informed w/shop G.Withers & job	10/08/2021	

Asset	W/O No	Description	Finished	Done Reading
		assigned to Premium tyres(see attachment)		
146259		500 Hour Earthmoving Service	6/08/2021	
145479		Steering doesn't lock. Column locked on test. Could not reproduce problem on test. If problem reoccurs, operator will need to show specific issue.	30/06/2021	
144249		250 Hour Earthmoving service	29/06/2021	
145518		Reverse camera faulty. Fitted new camera. Ran new AV wiring to camera. Rectified power to screen.	25/06/2021	
145541		Fire extinguisher. Fit new fire ext.	24/06/2021	
144294		No reverse camera Ran dummy RCA cable to test camera-ok, cable too short ordered longer one Replaced AV cable Reeve F	11/06/2021	
146462		Milky substance from undercarriage Found milky substance to be aerated trans. oil. Checked level-good. Removed cover from belly guard & inspected-lots of oil around multiple parts of transmission. Cleaned down & ran. Could not see any new oil appearing. Sent machine back to work to get hot & check at first break. Found leak from donut clamps. Tightened & rechecked-Ok	9/06/2021	
140865		Reverse Camera not working Fixed all broken wires C Buck	26/05/2021	
143310		Leaks Fixed radiator leak, replaced sensor, fixed rear cover C Buck	6/05/2021	
143057		No A/C Compressor shorting out, replaced compressor, reciever drier, cab filters tested-ok Reeve F	3/05/2021	
143192		No A/C ordered fan motor C Buck A/C compressor replaced, replaced receiver/ dryer, filters Reeve F	30/04/2021	

Asset	W/O No	Description	Finished	Done Reading
	143173	Replaced A/C compressor, dryer and cab filters Serviced A/C	30/04/2021	
	143105	UHF not working, oilo leak Check UHF cable-ok. clean connections working-ok Needs pressure sender under cab fitted (parts ordered) Needs new coolant sight glass(parts ordered) B Wise	27/04/2021	
	141481	2000 Hour earthmoving service	19/03/2021	
	141559	Removed ECM to fit 730#6 engine Tagged out machine Reeve F	15/03/2021	
	140264	Fire extinguisher out of date Fit E-stop in cab Carried out wiring repairs, installed E-stop, dug out brakes Brad C Replaced fire extinguisher Reeve F	23/02/2021	
	140722	Won't start Checked battery voltage-ok13.2v, checked outside e-stop and cleaned contacts, machine starting ok Reeve F	19/02/2021	
	147550	Plant Risk Assessment Review Assessment done by Steven R.	5/02/2021	
	139093	Side window latch broken Repaired latch C Buck	15/12/2020	
	135877	Check movement in Left side steering rams and lift ram bearings. No steering movement,needs rod bearings and pins/spacers Replaced steering bearings and pins C Buck	14/12/2020	
	136497	Needs new horn,roof leaking on fuse box,no wiper,no washer Fitted temporary horn to missing steering wheel button-ordered parts ,fitted correct horn button Reeve F	10/12/2020	
	138664	Engine miss R&R #4 cat Reman injector B Wise	30/11/2020	
	137634	250 Hour Earthmoving service	12/11/2020	
	137152	water leak Replaced water hose from header tank to top of radiator Ryan L	13/10/2020	
	135353	500 Hour Earthmoving Service	26/08/2020	

Asset	W/O No	Description	Finished	Done Reading
	133614	Hyd oil leak	8/07/2020	
	131895	250 Hour Earthmoving service	28/05/2020	
	130711	500 Hour Earthmoving Service	17/04/2020	
	129149	NO A/C	2/03/2020	
	129154	Seat wont pump up Remove seat and remove old air bag out of base and replaced it with a new one. Put back in and tested it	27/02/2020	
	128780	250 Hour Earthmoving service	20/02/2020	
	128589	Wipers not working New wiper motor C Buck	11/02/2020	
	128873	Seat belt not working Un jammed seat belt, working fine	11/02/2020	
	127143	Hitch u/s ,walkway, struts, alt, air compressor pulleys, belt tensioner, brakes, bushings, wiring PKWS see attach S Alexis Guard repairs G Acevedo	13/01/2020	
	127496	Compressor clutch u/s, evac system, replace compressor and drier, new seals, pressure test system vac down, 25ml of oil, charge system, clean evaporator external core, change filters B Patrick	9/01/2020	
	126010	Front hub lock RHS front wheel brake pipe u/s, fit genuine CAT front RHS wheel brake calliper pipe ass. B Wise	18/10/2019	
	125854	Park brake not working, check all brakes Adjusted up parkbrake truck would not drive through brake R Latham	17/10/2019	
	125710	500 Hour Earthmoving Service	17/10/2019	
	124579	Needs A/C fan not working Removed fan motor and fans from aircon box and replaced them with new ones R Latham	13/09/2019	
	125064	Wont change up gears No 4 clutch pack modulation valve not responding swap with No2 clutch pack valve test ok @ time of inspection Brad Wise	4/09/2019	

Asset	W/O No	Description	Finished	Done Reading
	124260	Suspension mounts U/S Rear suspension bushes Changed all 4 rear suspension bushes Cameron Buck	3/09/2019	
	124108	Need to check wheel tension Retension front wheel nuts ok Brad Wise	28/08/2019	
	123997	Flat FLH tyre	22/08/2019	
	124122	Front brakes Replaced all brake pads on both sides on front wheels Resealed RHS front calliper	22/08/2019	
	123834	Suspension bushes need changing Front brake pads need changing Bushes in rear bar Remove rear bar take to workshop,press new bushes in,press bar straight,reinstall in truck Ben Patrick	17/08/2019	
	123655	Front brake pads very low Truck inspection for worn mounts, bushes All rear mounts/cross braces & suspension blocks within manufacturers specs @ time of inspection Steer rams,centre articulation frame within spec @ time of inspection Brad Wise	8/08/2019	
	123593	250 Hour Earthmoving service	7/08/2019	
	123294	Air line off in cab seat wont stay up Fixed air leak on seat ,fixed reverse camera Cameron Buck	26/07/2019	
	123264	no reverse alarm Broken wire at hitch,fixed with a crimp fitting C Buck	24/07/2019	
	123082	RMS audit fit reflective tape rms spec to sides of body,r&r 2x brake globes on rear tail lights,check steering components ok Brad Wise	12/07/2019	
	123125	RHS mirror u/s mount new cat mirror bracket,clamps& rubbersto rhs mirror Brad Wise	2/07/2019	
	121594	mirror b broken ,lift cylinder,shocks SEE WORK ORDER 23125	2/07/2019	

Asset	W/O No	Description	Finished	Done Reading
	121307	2000 Hour earthmoving service	15/06/2019	
	121582	oil leak order new gear shift handle [G.W] reseal fitting in control valve under cab clean area run machine no leaks Ben Patrick	16/05/2019	
	121358	oil leak front left hand wheel changed oring on hose and replaced hyd hose Cameron Buck	15/05/2019	
	121237	Oil leak LHside SEE WORK ORDER 21358	9/05/2019	
	120270	shock down pumped up RHS shock Ryan Latham	29/03/2019	
	120229	LHF shock down Re gas LHF shock	28/03/2019	
	119654	water leak dropped belly guard and found water hose from thermostat housing to cooler blown replaced hose and clamps RYAN LATHAM	4/03/2019	
	119181	Wont start Replaced battery's	30/01/2019	
	118926	Flashing light not working Replaced flashing light unit	15/01/2019	
	118548	250 Hour Earthmoving service	19/12/2018	
	117437	A/C Not cold Get truck at 10am or 1pm. Check A/C operation OK repair wire to reverse camera	25/10/2018	

Asset	W/O No	Description	Finished	Done Reading
	113590	front shock down Pumped up suspension with nitrogen	24/10/2018	
	117473	No UHF or radio Tested 24V to 12V reduced and found it to be faulty. parts ordered	23/10/2018	
	117386	Getting hot Removed guards and washed out the radiator	20/10/2018	
	117252	No power in cab UHF and inclinometer plus reverse camera and music not working	17/10/2018	
	117190	Power keeps cutting out Cleaned dirt and corrosion from 80 amp circuit breaker in LH front cover	15/10/2018	
	116961	Brake lights not working Replaced def brake light switch test OK	15/10/2018	
	116795	500 Hour Earthmoving Service	9/10/2018	
	116658	Need in date fire Extinguisher Fitted new in date extinguisher	18/09/2018	
	116553	Shock down on gas. Pumped up shock	14/09/2018	
	116117	Steering column won't stay up. oil leaks. Adjust gas strut control cable and test OK	12/09/2018	
	115900	Transmission getting Hot and A/C not cold. Replaced temp sensor for trans	30/08/2018	
	113567	250 Hour Earthmoving service	27/07/2018	
	116142	Replace o ring under pressure switch	7/06/2018	
	110214	hyd oil leak	4/06/2018	
	113391	Removed L/H/R shock top pin lowered ram then removed head and resealed with kit for PKWS	15/05/2018	
	111038	500 Hour Earthmoving Service	1/02/2018	

Asset	W/O No	Description	Finished	Done Reading
	109687	250 Hour Earthmoving service	14/11/2017	
	109282	Blown exhuast gasket Turbo pipe came off refit pipe and clamp	28/09/2017	
	105578	500 Hour Earthmoving Service	29/06/2017	
	105363	Trans light on	10/05/2017	
	107835	Engine miss Remove and replace No.5 injector	31/03/2017	
	104796	UHF not working Complete	14/03/2017	
	104435	250 Hour Earthmoving service	24/02/2017	
	103960	sliding side window shattered replace right hand sliding window new latch	20/01/2017	
	103827	Need fire extinguisher bracket Installed bracket from my service truck & mounted on front R.H guard .	10/01/2017	
	107788	Right front shock. Remove and install right hand front shock, charge with oil and gas #new seals and cylinder bearings	21/12/2016	
	102692	2000 Hour earthmoving service	9/11/2016	
	101525	broken hose on inlet pipe needs fire extinguisher #	24/08/2016	
	100969	250 Hour Earthmoving service	27/07/2016	
	106090	O-Ring under cab leaking replaced o-ring put cab back down.	6/07/2016	
	100345	oil leak onto the exhaust	4/06/2016	
	100158	bad oil leak front right wheel	3/06/2016	
	100076	500 Hour Earthmoving Service	20/05/2016	
	100061	hyd oil leak under cab	10/05/2016	