

Work Order History Report

Asset	W/O No	Description	Finished	Done Reading
P0758		Komatsu HM300-2 ADT		
	192860	May R&M Put trans filter housing back on donor machine. Inspect park brake. Fix UHF Fix passenger door Moxy Oil Leak Removed hose on steering accumulator and changed o-ring.	27/05/2026	Hours
	191965	April R&M Replace tub sensor Low cab pressure Grease line Remove old tilt sensor and fit new adjust to the correct position. Repair broken bucket tilt lever. Replace 2 way	7/05/2026	Hours
	192151	ADT HM300-2 - Hepa - 500hr Service	7/04/2026	13536 Hours
	60659	ADT HM300-2 - Hepa - 250hr Service 13278 hrs	10/02/2026	13278 Hours
	58849	December / January R&M Test system pressure, low gas. Pressure test, no leaks found. Replace charge valve cores. Re-gas system. - Work done by Anderson auto repairs Fire suppression Check AC for issues	22/01/2026	Hours
	58793	October R&M Replace steer pilot hose under cab. Inspect oil leak and report to Pete to order parts Chase up tyre fitting, pump up R/H rear tyre so machine could go to town to be repaired	2/12/2025	Hours
	59013	Excavator - 1000hr service 12985 hrs	14/11/2025	Hours
	56273	"On-hire inspection/12859hrs Pre-hire inspection" * Remove rusted and broken bolts from exhaust cradle. * Clean out rust & debri from exhaust enclosure/ fit new exhaust from turbo to muffler, no lagging was supplied, paint exhaust tip and mounting plate * Cut off rusted cradle mount bolts, find suitable material to replace./ replaced * Weld new strips to cradle, sit in place tack weld puts in place. Remove & weld nuts in place install cradle clean work area	19/09/2025	12859 Hours

Asset	W/O No	Description	Finished	Done Reading
		put truck batteries on charge. - wheel nut indicators fitted - fit drivers seat adjustment handle - carry out weed and seed - carry out fulcrum on -hire and photo's and tyre report		
56175	IPAS installation		17/09/2025	Hours
54498	Pre hire repairs as per HME inspection. Remove rusted exhaust Remove exhaust, remove seat and diagnose problems, fit wheel bolt, begin to remove suspension pad Repair seat, fit to machine, repair coupling leaks, fit up high vis tape Repairs Repairs Fit seat not pumping up Check auto greaser, check fire supression, fit pos 4 suspension pad, sort out exhaust Fit tyres Finish fab on extinghiser, prime for paint, start fab on part 2		22/05/2025	Hours
54297	Offhire, Check over, pre hire repairs. *Finish 12,857hrs		17/04/2025	Hours
53300	Capital Works - #Refurbish Tub Replace exhaust system Check over. *Pre hire repairs as per HME inspection. *Fulcrum photos on hire. *Complete pre hire paperwork. *Check over machine after repairs. *Finish 12828.7hrs		3/04/2025	Hours
50441	Repair pos 2 flat		22/11/2024	Hours
18240	P0758, Pre hire repairs as per HME inspection, W/O 18130 BACKCHARGE-Clean cab, \$70 BACKCHARGE-Fill fuel, ? BACKCHARGE- Wash machine (10 HR LABOUR @ \$70 PER HR= \$700) Repair battery box lid Refit seat slide handle Tighten seatbelt bolt on dicky seat Repair RH middle blinker Fill washer bottle Fit grip tape to brake pedal Fit frame to radio Repair hole in walkway Fill auto greaser and test		26/08/2024	12855 Hours

Asset	W/O No	Description	Finished	Done Reading
		Replace 1x plant ID sticker Replace hi vis tape as required Remove old client stickers Clean cooler pack Tighten/replace coupler near transmission fill tube Repair leak on hyd filter housing Repair leaking couplers RHS Reseal cab jack cylinder Clean hyd tank breather Replace steer cylinders rod end pin and bush Reseal RH steer cylinder Replace LH lift cylinder rod end pin and bearing Replace RH lift cylinder rod end pin and bearing Repair headboard Paperwork, fulcrum photos		
18130		HME Inspection - Articulated Dump Truck Quote #: 135	21/06/2024	12822 Hours
14022		P0758 Pre hire repairs as per HME inspection. W/O 12588 Fit new tag to fire suppression bottle Supply first aid kit Repair seat, doesn't slide or go up. rubber missing off the bottom. Fit new seat belt. Operators manual in cab Repair RH front front light and rear light not working LH lens cracked Replace wiper blades Replace cap missing from washer bottle Repair bent access step Replace torn LH mudflap Repair grease line on RH tub and LH tub cylinder Replace machine stickers only as required Replace RH Maas decal Replace Hi vis as required Top up coolant Wash out cooler pack. Wash machine. Replace vactuators on air cleaner Adjust engine belts Secure engine bay exhaust lagging Top up rear diff oil Repair leaking fitting on RH steer cylinder Repair leak at brake tank Repair bend in RH of head board. Repair battery box door Repair bent LH E stop bracket. Bonnet hard to open. Lubricate hinges, must open with no resistance. Replace missing fuel cap Replace leaking front diff LH brake hose leaking. Replace LH cab lock	23/04/2024	12661 Hours

Asset	W/O No	Description	Finished	Done Reading
		Replace broken window latch Repair seized lock box fire suppression Replace missing wheel chocks Replace missing door handle Tidy up wiring in cab Repair cracked/bent RH rear fender cracked Clean cab		
10183	ADT HM300-2 - Hepa filter - 500hr Service		9/04/2024	12661 Hours
12588	March 2024 Off Hire Inspection M6 - C2. Dubbo inspection and repair estimate. HME Quote #72		22/03/2024	12661 Hours
10006	Diagnose L03 fault, found tub up fault being adjuster rod bent Removed & straightened rod Refitted rod Machine would not start found battery terminals damaged, need replacing Travel to site Take batteries to truck & charge out Replaced negative battery terminal Cleared codes & set tub up sensor Repair tub sensor & function test Ok Replace park brake switch, tested - Ok		12/02/2024	Hours
8814	6 Month Fire Suppression Servicing		18/01/2024	12359 Hours
8291	M6 ADT HM300-2 - 250hr Service Check over drivers seat Inspect fire suppression system Check window latch		17/01/2024	12337 Hours
8444	- Inspect machine for site defects - Repair harness for head hydraulic loom - Remove & install new head lights - Replace both wiring plugs		16/01/2024	12337 Hours
7431	Carry out suspension repairs - Replace 2 x elastomar blocks - Replace 1 x broken torque rod bush retaining bolt - Replace 2 x missing torque rod mount bolts. - Installed dog bone mount - Carry out dog bone repairs E-stop/turbo fault - Found all switched ignition power joined together, fixed issue & tested - Ok Check transmission fault - Truck stuck in gear. Machine was reported stuck 2nd gear transmission fault code, located & repaired faulty plug underneath cabin causing issues once plug was repaired & secured fault was no longer present + no active codes on dash.		5/12/2023	12064 Hours
7115	M6 ADT HM300-2 - 2000 Hour Service Replace suspension blocks		27/11/2023	12041 Hours

Asset	W/O No	Description	Finished	Done Reading
		Repair e-stop wiring		
6636		Repair rotating beacon. Repair front left lights. Secure seat belt.	9/11/2023	11857 Hours
6471		Minor R&M 26/10/23 No dash power	26/10/2023	Hours
5992		M6 ADT - 500hr Service	13/10/2023	11589 Hours
5711		M6 ADT - 250hr Service	25/09/2023	Hours
4865		Articulated Dump Truck - 1000hr Service	5/09/2023	10968 Hours
4767		Minor R&M Monday 28.08.23 - 03.08.2023	3/09/2023	Hours
3083		500hr service, HME inspection & Pre hire repairs A/C low air flow, check cab filters or evaporator. this has the Hepa filtration fitted. Repair as required. both front parker lights are out - replaced with LED check all final drive & diff mag plugs check auto greaser is working correctly & replace the front display screen. check brake wear on all wheel ends clean out radiator Service fire extinguishers. Service fire suppression fit mine radio fit wheel nut indicators Check all suspension pins/bearings Fit 2 new tyres on the front, front to rear Fit 2 x A4 P758 hi vis plant numbers Supply first aid kit, put in cab Fit tyre to match up with pos 4 Fit safety stickers re mount turbo timer stop switch into dash remove 3rd camera that does not work. Remove dirt from around the brake pedal & blow the cab out. repair top of bonnet where it is cracked out replace 2 x A/C vents in the dash replace door seal replace light/ buzzer for the inclinometer (Hummingbird) replace the am/fm radio Replace missing wheel bolt & tension all bolts Removed seat, replaced slide adjuster & refit top up coolant top up washer fluid Re- fit tub lock (it is in the cab) may need a new clip Re- fit tub sensor rod (it is in the cab)	9/08/2023	10770 Hours

Asset	W/O No	Description	Finished	Done Reading
		Replaced e-stops Replaced fan belt Replaced missing a-frame bolts Replaced artic hose support spring Replaced artic hose Replaced suspension blocks Repair oil leaks under cab - replaced coupler front RHS Replaced rear a-frame bearing Replaced, rotated tyres		
	10802	Check truck won't reverse - body position sensor u/s. Found body position sensor adjuster and sensor u/s borken, replaced both.	7/06/2023	Hours
	10803	Check oil leak - found oil leak from valve - left rear under cab, replaced o-ring, cleaned up.	27/02/2023	Hours
	10804	Carry out manually generated 500 hours service. Obtain engine oil sample, change engine oil and filter, replace fuel/water separator, replace fuel filter, fuel water tap - drain water, fuel tank - drain sediment and water, fuel tanks, lines and systems - leaks corrosion damage, replace engine primary air filter, engine air intake system pipe work and clamps, engine exhaust system, inspect/adjust/replace belts, inspect belt idlers and tensioners, clean cab air filters, carry out service and par brake tests, check brake accumulator, check/lubricate driveshafts, check final drive oils, check differential oils, check transmission oil level, check coolant level, engine cooling system radiator and cap, engine cooling system hoses and clamps, check hydraulic oil level, top up window washer bottle and check/replace wiper blades, clean battery terminals, battery mounting and terminals, electrical wiring harnesses, head and work lights, horn, amber beacon, reverse alarm/camera operation, cabin/windows/guards, service gauges/instruments, bucket and steering cylinders, loader frame/bucket linkages and pins, all hydraulic lines, secondary steering pump, wheel rims, check articulation joint, all grease lines and auto-grease system, grease all points of machine, clear open defects, replace service sticker.	6/02/2023	Hours
	10805	Fire suppression fault - truck won't start. Found wiring to pressure sensor broken. Fixed wiring, machine operation all ok.	16/01/2023	Hours
	10808	Pos 3 tyre - slow leak. Strip pos 3, cleaned up - found rim wasn't Komatsu and was worn, replaced rim. All coast tyres. Pos 1 and 2 replacement - replaced pos one and two tyres, replaced pos three rim and put run out on. Load up tyres and take to c2c for storage.	31/10/2022	Hours
	10806	A/C not working - started truck, found fan not working/not cold, checked compressor, checked power - found no power, removed cab pressurisation unit to get to fuse panel, replaced fuse - fuse immediately blown, checked wiring - found wire rubbed through at compressor - repaired wiring, a/c operation all ok.	31/10/2022	Hours
	10809	Pos 1 tyre - repair leak.	30/10/2022	Hours
	10807	Repair split grease lines - repair split grease lines to lift pins, shorten and fit back to fittings, test.	17/10/2022	Hours
	10810	Carry out manually generated 1000 hours service. Replace primary air filter, clean/replace cab filters, check oil and coolant levels, check/adjust fan, alternator, a/c belts, carry out foot, park and retarding brake tests, check and lubricate drive shafts and universal joints, refill auto greaser, obtain oil sample, change engine oil and filter, change fuel pre-filter, lubricate cab pins, check final drive oils, check differential oils, clean out cooler pack, replace service sticker and update service counters, replace main fuel filter, replace fuel tank air breather element, change oil in transmission and brake tank, replace transmission filter, brake filter, brake cooling filter, check transmission screens, replace hydraulic oil filter, clean/replace hydraulic tank breather.	29/08/2022	Hours

Asset	W/O No	Description	Finished	Done Reading
	11347	Locate tracker, C/O faulty UHF radio, pump up POS 1 tyres, adjusted bonnet, topped up water	17/08/2022	Hours
	11342	Perform general check over, check tyres - pumped up POS 1,4,5,6. Tighten valve stem POS 6. Blowout all air filters, fill auto greaser.	20/03/2022	Hours
	11340	Check over A/C system - ok.	22/11/2021	Hours
	11339	Fit tracker and activate.	16/11/2021	Hours
	11337	Carry out inspection around machine, inspection under cab for leaks, filled up hydraulic oil, tidy up seat, remove old site stickers, test auto greaser, carry out pre hire checks and washed machine.	10/11/2021	Hours
	11336	Fixed operator seat, cleaned and fixed wipers.	10/11/2021	Hours
	11335	Finish welding plates on, paint yellow.	6/11/2021	Hours
	11334	Straighten and fit guards, check over, straighten tub safety pin ears.	5/11/2021	Hours
	11332	Bolted cab down, finished fitting guards, topped up hydraulic tank.	3/11/2021	Hours
	11331	Fitted o-ring to leaking components, fitted radio aerial, installed UHF bracket, fixed flashing light, washed full machine, started installing guards.	2/11/2021	Hours
	11329	Located leak under cab. Washed and tightened hydraulic tan couplings.	1/11/2021	Hours
	11328	Fitted UHF, detailed cab, fitted wheel back on.	22/10/2021	Hours
	11327	Removed jab pack, replaced work light guard.	21/10/2021	Hours
	11326	Removed Pos 1 tyre. Removed LHS steer cylinder. Re-sealed steer cylinder and installed.	20/10/2021	Hours
	11324	Re-sealed RHS steer cylinder, installed cylinders.	19/10/2021	Hours
	11323	Perform off hire inspection.	8/10/2021	Hours
	11320	Carried out 500hr service - changed oil filters, changed both fuel filters and out filter, checked over and greased.	28/07/2021	Hours
	11319	Carried out 500hr service - changed oil and filter, replaced fuel filters and air filters, checked over - all ok.	30/06/2021	Hours
	11318	Checked for service - not due. Checked middle a frame bearing, slight movement - need to monitor.	2/06/2021	Hours
	11317	Check hitch and a frame bearings.	1/06/2021	Hours
	11316	Carried out 1000hr service. Changed oil and filter, fuel filters, air filters, trans filters, hydraulic return filters, changed brake cooling oil, changed transmission oil, checked A frame bearings, greased drive shafts, clear service info on dash, checked over machine, found two broken bolts and damaged door seal - bolts and door seal ordered. Rem up machine - all ok.	4/05/2021	Hours

Asset	W/O No	Description	Finished	Done Reading
	11315	Keeps blowing A/C fuse - found blower fan u/s. removed breath safe and panels and covers to get to fan, replaced fan and fuse, checked over, refitted panels, covers and breathe safe.	2/03/2021	Hours
	11314	Replaced transmission lever assembly. Repair auto greaser system. Remove and unblock lines.	13/01/2021	Hours
	11313	Replace radiator caps and rear wiper blade, due for service.	24/11/2020	Hours
	11312	Removed and repaired gear shift selector connected fire suppression module for engine and tested - no power, found fuse blow - replaced fuse.	10/11/2020	Hours
	11310	Replaced main grease valve, replaced pumping element, bled system, replaced blown grease line to RH body pin, tested system - ok.	4/11/2020	Hours
	11309	Brake fault - follow diagnostic code, troubleshooting - tested retarder solenoid - ok, checked retarder level - ok, checked service brake operation - ok, disconnect sensors and checked codes, found retarder pressure sensor faulty - replace sensor, manually greased truck, bled grease system, changed grease in auto greaser, found valve seized - pump not working, unblocked 6 grease nipples at rear of truck and ordered parts.	29/10/2020	Hours
	11307	Auto greaser not working, remove rear ejector back from P759.	28/10/2020	Hours
	11302	Breakdown - engine getting air in fuel system. Diagnose - hand priming pump failed. Ordered and picked up part, returned to site. Fitted hand pump, bled system and tested - operation ok.	21/10/2020	Hours
	11301	Pick broken pos sensor, take to site fitted sensor, adjusted and tested - ok.	12/10/2020	Hours
	11300	Fit reverse sensor, replace coolant overflow hose from radiator to overflow bottle, adjust battery cover box, adjust bonnet catch. Investigate oil leak under trans belly plate - found o-ring leaking, drained transmission, removed plate, cleaned and checked trans screen. Fit new o-ring, refilled trans.	2/10/2020	Hours
	11299	Complete site paperwork, supply safety stickers for fitting after respray.	31/08/2020	Hours
	11298	Check stats of repairs/pre hire paperwork, top up hyd oil, remove UHF antenna, repair muffler straps.	28/08/2020	Hours
	11295	Remove covers, muffler for DPF install and refit covers. Handrails - paint, cut, fabricate and reinstall.	27/08/2020	Hours
	11293	Handrails - cut, fabricate, paint and install.	26/08/2020	Hours
	11291	Finish installing UHF, fit bonnet cable, paperwork.	20/08/2020	Hours
	11290	Put belly guards up/remove broken bolt, clean up bay.	20/08/2020	Hours
	11289	Set max strut heights, check and fill final drives, gas up fire suppression bottle, replace bonnet lock and engaging arm, replace bonnet lock and engaging arm, replace bonnet sticker, fit new door lock button, change tram filters, change steer, brake, hydraulic filter.	19/08/2020	Hours
	11163	Drain/fills trans oil, replace trans screen plate, install rear light, fix wiring, install tub position sensor rod, fill hyd, straighten LH mid light stand, replace oxy hand piece.	19/08/2020	Hours

Asset	W/O No	Description	Finished	Done Reading
	11285	Weld new hinges on belly guard, paint cab jack bracket, fit cab jack, check and change brake accumulators, fit new uhf aerial, fit uhf and bracket, fit uhf power lead, fit new stereo aerial. wire up LED lights, install grip tape on pedal, install Maas stickers, get operators manual.	18/08/2020	Hours
	11284	Check service history, organise parts.	18/08/2020	Hours
	11281	Change out RHS tub lift ram, change coolant, complete 500hr service.	17/08/2020	Hours
	11278	Bleed fuel system and jumpstart machine, bypass fire suppression shut down, complete condition report, organise parts.	17/08/2020	Hours
	11276	Make 2 x fire extinguisher brackets - remove belly guard and straighten tag extinguisher.	17/08/2020	Hours
	11274	Pump up tyres.	15/08/2020	Hours
	11272	Remove belly guards. Cut hole in battery box, use oxy on rusty bolts.	24/07/2019	Hours