

Work Order History Report

Asset	W/O No	Description	Finished	Done Reading
AX150		Drake Widening 4x4 Float		
	194676	Repairs to broke widening pin	18/08/2026	
	57671	Replace brakes	7/05/2026	
	58950	Grease Float Ben Swarbrick 5/11/2025 2 New tyres 10/11/25	21/04/2026	
	192218	Repair cracks in ramps. Repair cracks in front of the deck - first beam from the gooseneck. Repair cracks on the deck at the rear - where chains go through the floor to secure the ramps.	24/03/2026	
	191874	grease float and 2 new tyres	11/03/2026	
	56143	09/07/25 Grease float 21/07/25 Scott Grease trailer 05/08/25 Scott Grease float 22/08/25 Scott Grease float Replace missing spare tyre hold down	11/02/2026	
	60346	8 New tyres	29/01/2026	
	59738	Grease float, Adjust brakes, replace axle 4 rhs slack adjuster, fixed honda pump off on switch broken wire. Grease Float 16/01/26 Grease Float 28/01/26	28/01/2026	Hours
	59439	Replace 4 tyres	28/11/2025	
	57634	Float - 20,000km B service - replace clearance light and repair wires for other 2 - tighten honda motor mounting bolts - grind out and repair crack in float- non structuale - tighten rear RHS beacon	11/09/2025	

Asset	W/O No	Description	Finished	Done Reading
		- carry out service as required		
	57070	Change tyer LHS 2nd axle inner Replace tyres on 1st axle LHS and 4th axle LHS	14/08/2025	
	56039	Supplied and fitted 2 x Michelin XTE2 TL 9.5R17.5 Tyres (143/141J) Disposal of 2 old tyres (7.50R15 to 315/80R22.5)	7/07/2025	
	55311	adjust brakes, repair air leak	3/06/2025	
	53752	Pull start cord snapped - replaced Pull start rope	1/04/2025	
	53570	Replace 10x Tyres.	25/03/2025	
	52891	replace 3 tyres	27/02/2025	
	52639	replace 2 tyres	21/02/2025	
	52496	replace 2 tyres	14/02/2025	
	52383	diagnose and repair brakes coming on hard	11/02/2025	
	52202	Welding Repairs	7/02/2025	
	51386	Replace 2 tyres	7/01/2025	
	50929	Float - 100,000km/Annual C service	13/12/2024	
	50137	Float - 20,000km B service	13/11/2024	
	50098	1 x puncture repair	12/11/2024	
	49784	Replace 1 tyre	1/11/2024	
	49236	Replace Two Tyres	15/10/2024	
	21222	Replace water tank and brackets for trailer (Damaged)	19/09/2024	
		R&R LHS Taillight Assy		
	48165	Float - 20,000km B service - carry out service as per service sheet	11/09/2024	
	20465	Replace 3 tyres	1/08/2024	
	18567	Minor R&M	4/07/2024	620456 KM

Asset	W/O No	Description	Finished	Done Reading	
		- inspect & repair for accident damage (kangaroo damage) - RHS rear hydraulic tap for locking out suspension cylinders - handle broken - replace broken handle with new - adjust brakes			
	18313	Puncture repair	25/06/2024		
	18217	Replace 1x Tyre and 1x Puncture Repair	21/06/2024		
	17842	Replace float motor;	12/06/2024	596101	KM
		Fault: faulty motor Cause: wear & tear Correction: R+R float motor			
	17475	Float - 20,000km B service	29/05/2024		
		- complete service as per service checklist - no faults found			
	16042	replace 2 tyres, repair 4 tyres	10/05/2024		
	14120	Replace 6 tyres. FLOAT TYRES - DOUBLE COIN 9.5R17.5 RT500 (18) 143/141J	11/04/2024		
	10278	Float - 20,000km B service	4/03/2024	596101	KM
		- completed as per checklist - cracks welded by boileys			
	10053	Repair lights	27/02/2024		
		- diagnose / repair indicators not working & park lights - harness rubbed through - repair & test			
	9473	Supply/Fit 2x MAXXIS 9.5R17.5 143/141K (16) UR275. LHR Rear Axle.	8/02/2024		
	9290	replace various tyres Qty.5	1/02/2024		
	10558	(Float) Check air, electrics and hydraulic couplings and EBS(If fitted) for correct engagement Failed - Clearance light between quad groupRHS	22/01/2024		
	10560	Broken size sign, needs new signs light out left hand side	22/01/2024		
	7968	Grease and adjust brakes	20/12/2023		
		Broken mounting plate for brakes. Clearance light bracket (broken in middle of quad axle group)			
		Fault: clearance light bracket broken Cause: impact damage Correction: repaired bracket			

Asset	W/O No	Description	Finished	Done Reading
		Fault: multiple clearance lights inoperative Cause: wear & tear Correction: R+R lights		
		Fault: brakes low Cause: wear & tear Correction: R+R brakes		
		Fault: broken fish plate Cause: wear & tear Correction: R+R bracket, scam, brakes		
		- completed check over & grease		
7982		Replace damaged tires	12/12/2023	
10559		(Float) Inspect chassis, ramp mountings, tie down points Failed - Cracked in outer rail at beaver tailRHS	11/12/2023	
7925		Kangaroo Damage. (oil leak) - check for oil leaks - remove hydraulic hose & tightened loose fitting in valve at rear, fit hose & test - fix spring for pull cord on motor - remove trailer from Southlakes compound & bring back to w./shop	8/12/2023	
7224		Float Grease (supply)	21/11/2023	
7209		Replace tyre	17/11/2023	
6489		Replace Tyre Hannafor Tyre & Suspension 1x. MAXXIS 9.5R17.5 143/141K (16) UR275 1x. Puncture Repair - Truck Tyre	23/10/2023	
5908		Replace two Tyres (michelin) two tyres (maxxis)	5/10/2023	
5154		weld clearance light bracket back on RHS	28/09/2023	
10561		(Float) Check operation of all lights, reflective tape, compulsory signs and reflectors Failed - Clearance light bracket broken in middle of quad group	28/09/2023	
5021		Replace Tyres x3	26/09/2023	
5532		Puncture Repair	21/09/2023	
5004		Float - 20,000km B service - replace marker signs rear - straighten rear oversize signs - weld light into place	5/09/2023	

Asset	W/O No	Description	Finished	Done Reading	
	10562	Weld one light ,2 x tyres on back, trailer very slow to open and close	2/08/2023		
	3779	REPLACE TYRES	31/07/2023		
	2629	Float - 100,000km/Annual C service	29/06/2023	42687	KM
	10563	(Float) Check air, electrics and hydraulic couplings and EBS(If fitted) for correct engagement Failed - Wiring loose back of trailer	16/06/2023		
	10564	Cut the holes in the floor for the tie down points	1/02/2023		
	10565	20000 km service	21/12/2022		
	10569	Replaced all pins and bushes	21/12/2022		
	10567	LHSClearance light bracket broken. Welded clearance light back on and painted it. Replace wiring to number plate light and replaced number plate light and all inoperative lights	12/12/2022		
	10566	Oxy cut holes	7/11/2022		
	10568	Fix ramps. Fix the lugs where the hydraulic rambolts to it. Welded new lugs on and plated both sides of the lug did it to both ramps	10/10/2022		
	10571	B- 20000 km service	6/06/2022		
	10570	ComplianceCheck	12/04/2022		
	10572	Side marker light - 2x Rims &Tyres - Faded warning signs Missing wheel nuts Remove and replace all lift cylinders. Replace all hydraulic hoses for suspension and ramps. Replace taps and hose at hyd tankExchange suspension cylinder returned toDrake on 22/06/22 on Tamex ConNote 8553868	7/03/2022		