

Work Order History Report

Asset	W/O No	Description	Finished	Done Reading	
T0161		Toyota Hilux SR Dual Cab 4X4			
	57481				
	55726	New brake shoes and cylinders on the rear	30/06/2025		
	55490	Replace LHS front tyre after bowout Repair spare tyre flat	11/06/2025		
	58214	10,000km Light Vehicle Service/pink slip/Repairs 489,273kms old invoice)	28/04/2025	489273	KM
	54405	10,000km Light Vehicle Service and rego check - Replaced LHF lower control arm - replaced both universals on front drive shaft - replaced RHF seat belt - replaced RH bunker globe - tidied up wiring near battery, live wires not insulated	28/04/2025	489273	KM
	52267	Vibration when driving, no aircon, diagnose and repair 484309km -replaced cab filter - Test drive & wash mud off - Wheels tested ok	6/02/2025	484309	KM
	50859	PUNCTURE REPAIR X 2	21/11/2024	484309	KM
	18575	DIAGNOSE & REPAIR STARTING FAULT Replaced started motor, made new earth cables, removed busted isolator	3/07/2024	475594	KM
	17434	10,000km Light Vehicle Service SERVICE INCLUDING NEW FRONT BRAKE PADS @ A1 Earthworx	24/05/2024		
	13393	Replacement battery	25/03/2024		
	10131	A1 Earth Worx REPLACE BOTH FRONT LOWER STRUT BUSHES, REPLACE BOTH FRONT LOWER CONTROL ARMS, REPLACE LEAKING INJECTORS, REPLACE CRACKED ENGINE ROCKER COVERS, PINK	29/02/2024		
	8450	Pink Slip Inspection - Light Vehicle	25/01/2024	465924	KM

Asset	W/O No	Description	Finished	Done Reading	
	8983	10,000km Light Vehicle Service A1 Earthworx replace melted fuse holder, grease driveshaft, grease rear shackles, adjust rear brakes, replace 4 tyres	24/01/2024		
	8195	Diagnose fuel leak, remove & replace No. 2 injector line	18/12/2023		
	2647	Mudgee Service & Repair Centre - Replace fuel injectors. Replace injectors as per po carry out programming of comp values and programming of pilot learn. Had to use injector slide hammer and had trouble removing them due to being seized in head. Replaced injector seals in rocker cover and replaced rocker cover gasket.	26/06/2023	452638	KM