

Work Order History Report

Asset	W/O No	Description	Finished	Done Reading
P0737		Komatsu HM300-2 ADT		
	193657	June R&M Transmission code 09/06/2026 - Found transmission oil low, found no leaks * Attempted to unlock filler cap and key snapped off in barrel (will source new key) * Unlocked cap topped up oil * Locked out isolator on machine 10/06/2026 * Found broken wire on transmission filter sensor, sensor requires replacement * Inspected bonnet latch, found sleeve on latch missing latch requires replacing * Order all parts 24/06/2026 * Remove & Replace transmission filter sensor * Remove & replace transmission filter * Remove & replace bonnet latch * Test operation, all ok	24/06/2026	12778 Hours
	194089	July R&M - 12818 Hrs - 08/07/2026 * Inspect autogreaser being inoperable * Found autogreaser operating correctly * Topped up auto greaser * Check all main inlets and outlets over valve banks for grease lines, all ok * Pack up tooling and return to workshop - 17/06/2026 * Collect UHF from supplier * Install UHF and test operation, all ok	17/06/2026	Hours
	192445	Pre hire repairs as per WO192438 Wash & clean cab First aid kit R&R steer cylinder rod end pin & bush	22/04/2026	Hours
	192003	HM300-2 - 250hr Service 7612 - Question: Seat in good condition, adjusted correctly and secure? Answer: FAIL Comment: Seat won't lift up and fill with air 7953 - Question: Check fire extinguisher present and in test date Answer: FAIL	15/04/2026	12741 Hours

Asset	W/O No	Description	Finished	Done Reading
		Comment: Fire System Fault		
	192438	Off hire ACJV	9/04/2026	Hours
	192220	28/3/2026 Fix seat pump up issue, loose seat compressor wire 30/3/26 fault, failed starter motor. Cause, worn out. Correction replace starter motor when parts arrive.	30/03/2026	Hours
	191335	Feb R&M Diagnose hydraulic filter fault, found broken sensor wire from bonnet hot latching and coming up and snapped it	26/02/2026	Hours
	60687	Pre Hire Repairs as per WO60569 Machine wash \$420.00 Backcharge Cab Clean \$210.00 Backcharge straighten left front Mudguard \$105.00 Backcharge replace brocken access step rubbers \$558.00 Backcharge Repair cab flood lights \$210.00 Replace rear cab light \$155.00 Replace LHS fire extinguisher \$155.00 Replace Battery isolator stickers \$55.00	18/02/2026	12670 Hours
	60569	Offhire Hollingsworth	6/02/2026	Hours
	60073	January R&M Re adjust bonnet assembly/remove/replace seat valve, adjust isolator door latch 1264hrs	8/01/2026	Hours
	59728	December Monthly WO R&M Seat wont pump and bonnet won't close, order switch and straighten bonnet	10/12/2025	Hours
	59522	Re-seal brake accumulator 12640hrs	2/12/2025	Hours
	59257	Off hire inspection	27/11/2025	Hours
	58796	November R&M Oil leaks	27/11/2025	Hours
	57932	Replace all tyres x 6	29/10/2025	Hours
	57392	On hire inspection / uungala 12609hrs - replace broken tail lights - change connectors to deutch plugs - replace missing door latch - replace missing seat adjuster - test grease system - carryout and complete on-hire fulcrum for Hollingsworth	21/10/2025	12609 Hours

Asset	W/O No	Description	Finished	Done	Reading
		- carry out and complete weed and seed - inflate POS 2 and test for leaks - clean cab - test horn and clean bad contact			
	54979	Off hire 12609hrs	17/05/2025	12609	Hours
	55759	Capital Repairs - #Refurbish Tub	30/04/2025		Hours
	53504	Carry out on hire inspection 12481hrs	21/03/2025		Hours
	51022	Complete on hire inspection	10/12/2024	12476	Hours
	50323	Carry Out Off Hire Inspection	20/11/2024	12476	Hours
	49954	HM300-2 - 500hr Service	18/11/2024	12475	Hours
	49344	Transmission fault - Diagnose & repair Fault code DDTMKA. Found broken plug on 3rd clutch ECM. Replace plug, test - ok.	17/10/2024	12427	Hours
	49106	Broken wire on transmission filter sensor vibration replace sensor	9/10/2024	12390	Hours
	48504	Oil leak under cab Travel from workshop to Stubbo wait for truck to come to lay down area. Jack cab over clean around pipe. remove pipe replace orings and fit new pipe. Top up oil and test	8/10/2024	12381	Hours
	48710	Diagnose and repair fire suppression alarm	24/09/2024	12322	Hours
	48397	HME Inspection 12243.3HRS	12/09/2024	12243	Hours
	48138	Grease fault alarm fill grease tank	9/09/2024	12227	Hours
	21217	oil leak leaking steering hose replace hose	27/08/2024	12156	Hours
	20850	Oil leak Replace cracked pipe	15/08/2024	12102	Hours
	18732	HM300-2 - 2000hr Service Window washer bottle missing lid. Pos 3 missing wheel stud	7/08/2024	12077	Hours

Asset	W/O No	Description	Finished	Done Reading
	18731	250 Hour service	9/07/2024	11918 Hours
	18115	HME Stubbo inspection	17/06/2024	11787 Hours
	15405	HM300-2 - 500hr Service PARTS ONLY A1	2/05/2024	Hours
	13096	asset inspection	22/03/2024	Hours
	11003	Carry out mechanical check, check over drive shaft, order parts for HM300's in workshop.	11/03/2024	Hours
	8048	Receiver tank/condenser/hoses/ fuel primer Parts request by Clyntin Perry - A1 Earthworx Parts sale only	22/02/2024	Hours
	9174	Prehire repairs as per HME inspection. Check and tag fire extinguishers Check and tag fire suppression Fit reverse alarm Fit first aid kit Repair passenger seat Replace passenger seat belt Repair RH park light Fill washer bottle, test washers Replace rear wiper motor Replace rear wiper blade Fit safety stickers as required Replace Maas, thinksafe stickers Remove old client stickers Check and top up oils Fit wheel nut indicators Clean cab	1/02/2024	11098 Hours
	9113	HM300-2 - 1000hr Service	1/02/2024	11098 Hours
	9071	HME Inspection - Articulated Dump Truck Quote #: 53	29/01/2024	11098 Hours
	7737	HM300-2 - 1000hr Service (parts supply - labour by A1 Earthworx)	20/12/2023	11030 Hours
	7497	Minor R&M 27/11/23 A1 - Boost hose	30/11/2023	10938 Hours
	6589	REMOVE & REPLACE FRONT BONNET HINGE BOLTS - A1 EARTHWORX	2/10/2023	Hours
	4577	Articulated Dump Truck - 500hr Service 10462 Hours	24/08/2023	10516 Hours
	4835	5 yearly fire suppression service.	12/08/2023	Hours
	3069	July - Minor R&M	8/07/2023	

Asset	W/O No	Description	Finished	Done Reading	
	2009	GB Auto Group INV0128558: Removed regs from vent actuator to get heater to work. Pull console up to refit window switch that had fallen down.	26/05/2023		
	2008	Maintenance Docket #29526: Inspected all fuses on visible wiring to auto greaser, attempted to run a manual lube cycle - appears auto grease system has failed.	15/05/2023		
	367	Articulated Dump Truck - 2000hr Service Completed by A1 Earthworx	10/05/2023	10064	Hours
	10462	Remove tailgate attachments. Fit and mount wheel chock brackets, put tub down and fit pins.	22/03/2023		Hours
	10464	Carry out check over of machine - checked over and greased all shafts, completed tyre report, fitted window blanking, replaced door handle, finished all paperwork.	20/03/2023		Hours
	10463	Fix headboard - cut off plates and straighten headboard out, weld new plates on.	20/02/2023		Hours
	10466	Fitted tracker.	17/01/2023		Hours
	10467	Carried out manually generated 250 hour service: Cleaned/replaced cab filters Checked oil and coolant levels Checked/adjusted fan, alternator, A/C belts Carried out foot, park and retarding brake tests Checked and lubricated driveshafts and universal joints Re-filled auto greaser.	21/11/2022		Hours
	11025	Carry out 500hr service Pump up pos 5 tyre Fill auto greaser	31/08/2022		Hours
	11023	Talk to operator - troubleshoot code. Looked up code and instructed operator to adjust tub sensor rod.	25/08/2022		Hours
	11022	Fit new fan belts, fit new trans sensor on filter housing.	25/06/2022		Hours
	11021	Check unis, belts and trans code.	24/06/2022		Hours
	11020	Pump up all tyres to 60 psi, fill up auto greaser.	7/06/2022		Hours
	11019	Carried out 1000hr service.	17/05/2022		Hours
	11018	Fit new brake pressure cut in and fit new seat slider.	4/05/2022		Hours
	11017	Fill auto greaser.	14/04/2022		Hours
	11016	Check oils, fit new air filter.	14/04/2022		Hours
	11015	Carry out check over, stamp extinguishers.	11/03/2022		Hours
	11014	R & R window regulator.	1/03/2022		Hours
	11013	Carried out 1000 hours service, check screens.	18/02/2022		Hours

Asset	W/O No	Description	Finished	Done Reading
	11012	Fill up auto greaser and check over.	28/01/2022	Hours
	11011	Tested auto greaser - was not building pressure. Swapped out parts from another auto greaser.	9/12/2021	Hours
	11010	Fitted Pos 1 and Pos 2 drive shafts.	7/12/2021	Hours
	11009	Check autogreaser operation and make mudflap.	6/12/2021	Hours
	11008	Fit mudflap to Pos 1 tyre, tested autogreaser.	6/12/2021	Hours
	11007	Fit new AM/FM aerial Check machine fluid levels Inspect all final drive levels	6/12/2021	Hours
	11006	Clean units and measure for replacement parts.	3/12/2021	Hours
	11005	Fixed light, checked over cab.	2/12/2021	Hours
	11004	Remove drive shaft.	1/12/2021	Hours
	11002	Remove front drive shaft covers and shafts Measure units Grease and fill auto greaser Remove wheel and straighten front LHS mudguard Straighten LHS artic light mount	1/12/2021	Hours
	11001	Checked over machine wash.	30/11/2021	Hours
	11000	Check over machine for defects.	30/11/2021	Hours
	10999	Carried out 250hr service.	29/11/2021	Hours
	10998	Checked over machine.	26/11/2021	Hours
	10997	Fit new accumulator and tested. Filled grease pots and check over.	7/05/2021	Hours
	10996	Disassembled brake accumulator, found cap seized up and stuck.	1/05/2021	Hours
	10995	Test brake accumulator pressures.	30/04/2021	Hours
	10994	Inspect park brake and diagnose.	29/04/2021	Hours
	10993	Escort float onsite, assist with unloading and reload, checked over machine, topped up hyd oil and coolant.	5/03/2021	Hours
	10991	Changed out LH middle axle suspension block Unbolt park brake caliper Change brake pads Re-assemble park brake Adjusted park brake Complete Yarra Dam check over	2/03/2021	Hours

Asset	W/O No	Description	Finished	Done Reading
		Replaced bottom RH work light bulb and top LH bulb Wash truck		
	10990	Begin 2000hr service Changed all hyd filters, air filters, engine filters, engine oil, trans oil and filters.	10/02/2021	Hours
	10989	A/C poor - checked pressure - ok Cleaned filters Adjusted A/C belt Blew out radiator and condensor Turn heater taps off - A/C ok	23/01/2021	Hours
	10988	Performed general checkover Checked tyre pressure Adjusted bonnet guides	7/01/2021	Hours
	10987	Not selecting reverse - Remove gear selector knob and button File bar of plastic guide Adjusted and fitted knob and button Checked RV plug for power - no power Checked fuses - all ok Ran twin core from UHF power to 12 V plug	8/12/2020	Hours
	10986	Replace seat covers.	18/11/2020	Hours
	10984	Fabricate handrail for cab.	17/11/2020	Hours
	10983	Repair handrails, guard hinges.	16/11/2020	Hours
	10982	Clean out evaporator.	16/11/2020	Hours
	10981	Replace safety pin plates.	14/11/2020	Hours
	10980	Clean out evaporator.	14/11/2020	Hours
	10979	Start to install AM/FM radio, clear gas lifter, fit maas stickers.	1/09/2020	Hours
	10977	Install UHF - clean floor and around pedals, fill up auto greaser, fit belly plates, warm up truck and top up coolant, fit seat sticker, tag fire suppression and fire extinguisher, remove and fit indicator stalk.	31/08/2020	Hours
	10975	Replace tranny screen o-rings and cover x 2, top up tranny oil, top up hyd oil, fit sliding window latch, clean out window washer, replace fire extinguisher bracket, fit cab jack, replace 2 x flex couplings of RH side of tranny.	28/08/2020	Hours
	10972	Change 3x flex couplings behind hyd tank, drain/fill coolant, check charge accumulators, drain tranny oil - remove reseal L/H tranny screen, remove redundants brake charge hose, change park light globes, blow dirt out of frame around tranny and chassis.	27/08/2020	Hours
	10971	Remove pos 1 - remove inner guards - stack to replace flex couplings.	26/08/2020	Hours
	10970	Clean area, driver workshop sack up pos 1.	25/08/2020	Hours

Asset	W/O No	Description	Finished	Done Reading
	10969	Jump start, pump up tyres, condition report - organise parts.	21/08/2020	Hours
	10968	Jump start, bleed fuel system.	17/05/2019	Hours
	10967	Remove belly guards, jump start.	16/05/2019	Hours
	10966	Flat battery, bleed fuel system.	14/05/2019	Hours
	10965	Remove belly guard. Jump start.	8/05/2019	Hours