

Work Order History Report

Asset	W/O No	Description	Finished	Done Reading
		Toyota Hilux SR Dual Cab 4X		
	193919	Adjust Handbrake as per Craig Whitfield request Pull car onto hoist, adjust up rear drum brakes than adjust handbrake cable	19/06/2026	342690 KM
	192474	Pink Slip Inspection - Light Vehicle	13/04/2026	KM
	55938	Repairs for Rego Date Completed: 04/07/2025 Odometer: 330,400 km Scope of Works Completed: Removed & replaced rear diff shaft seal and o-ring (LHS) Removed & replaced CV shaft seal, tie rod ends, rack ends (both sides), and tailshaft universal joints Removed & replaced brake shoes, inspected & cleaned brake kit and drums Replaced park brake cable Removed damaged airbag module and fitted replacement (incl. clock spring check) Changed differential oil & brake oil, carried out brake system bleed Installed new reversing/back-up alarms Performed drive test - all OK Parts & Materials Supplied: Diff side seal, tie rod ends, rack ends, uni joints, axle & hub components Rear brake shoes & park brake cable Clock spring & airbag module replacement Reversing/back-up alarms	4/07/2025	330400 KM
	58491	Pink Slip Inspection - Light Vehicle	1/07/2025	330397 KM

Asset	W/O No	Description	Finished	Done Reading	
	54650	replace rear window. charge back to civil	11/06/2025		
	54863	Replace Tyres x4 PACE 225/75R16 LT 10PLY 115/112S ZIVARO A/T 329393 km	14/05/2025	329393	KM
	49899	1 puncture repair	27/11/2024		
	49065	Minor repairs. Inspect Ute for lacking power etc Fault code P0046 turbo solenoid drawing too much current or staying at 100% power - Had fault codes P0046147. Inspected actuator on turbo - possibly seized. Removed MAF sensor filter & cleaned. Needs replacing. Codes cleared did not return starter motor - also needs replacing 324144 KM - lubricate rear window winder. - fit new spare tyre and rim. - replace starter motor. - repair siezed clutch cylinder. - replace air bag module/clock spring. - replace driver seat cushion and seat cover. - clean out blocked egr and replace all gaskets. - replace lhs cv shaft and seal. - replace stone guard on fuel tank. - replace rear pinion seal. - replace uni joint in tailshaft.	11/10/2024		
	48500	10,000km Light Vehicle Service Replace CV Shaft - completed service as per checklist - R+R CV shaft at LHS - remove & lubricate sliding adjuster of driver's seat - perform drive test	21/09/2024	324312	KM
	19382	10,000km Light Vehicle Service Carry out 10k service as per sheet. Test drive vehicle, return to service.	17/07/2024		
	15628	10,000km Light Vehicle Service - perform routine service, change all fluids - carry out suspension underneath - R+R brake pads, brake disc, rubber bush in sway bar tie rod end, lower ball joint, sway bar, bush in leaf spring, hand brake cable, globes in taillight timing belt & reset in dashboard - check & diagnose window switch not working, took from V5 ute & test - change window switch	7/05/2024	301568	KM
	14131	Pink Slip Inspection - Light Vehicle	6/05/2024	299628	KM

Asset	W/O No	Description	Finished	Done Reading	
	10111	Replace rear uni; - removed drive shaft to replace faulty uni - found yoke was damaged - ordered 2nd hand yoke from Scotts - fit yoke & new uni to driveshaft & fitted to vehicle - grease driveline	18/03/2024	297000	KM
	9319	Replace 3x tyres. WESTLAKE 225/75R16 115/112Q SL369 AT x3.	2/02/2024		
	8882	10,000km Light Vehicle Service - replace R+R taillight bulb - replace battery	22/01/2024	292628	KM
	8362	Hannaford's Called out. Relaced Tyre	12/12/2023	289218	KM
	4456	10,000km Light Vehicle Service Remove and replaced battery, wiper blades, blown globes and fuse. Rotate tyre Replace A/C knob assembly Inspect and repair wiring harness (Blinkers) Replace Transfer case seal	27/09/2023	281294	KM
	179	Pink Slip Inspection	11/05/2023	267862	KM
	438	10,000km Light Vehicle Service Replace globes in number plate light Replace driving light bracket	10/05/2023	267842	KM