

Work Order History Report

Asset	W/O No	Description	Finished	Done Reading
T0145		Toyota Hilux SR Dual Cab 4X4		
	196736	Pink Slip Inspection	15/06/2026	
	195327	Check out front end (COMPLETE) Wheel Alignment ODOMETER: 333456 (15/05/26) *Check and inspect front end due to uneven wear of tyre (LHS) *Swap spare tyre to front left hand side tyre	12/06/2026	
	192886	Odometer: 336890KM 10/04/26 Diagnose engine fault - Started diagnose procedures on UTE-over fuel & stalling - Compression tested cylinders - were all good - Checked scan tool had a fault code for injectors - Pulled injectors out they look ok but I sent them for testing - Noticed radiator starting to leak so ordered a new one - Removed & replaced radiator - Noticed fuel tank was covered in dirt suggesting leak - Drained fuel & was full of sludge - Removed & replaced fuel tank * flushed lines - Carried out full service on UTE - Injectors failed testing due to contamination-kit coming - Refit new injectors & fuel lines, then coded new injectors - Primed fuel system, started UTE & carried out injector learn - Filled UTE up with fresh fuel & took for test drive - UTE was all good, no fault codes - Washed engine bay JOB completed 10-4-26 Comment - further work required - UTE needs a wheel alignment - Pulled bad on road test	11/06/2026	
	192871	tow vehicle back to Dubbo Brocken down Travel to broken down ute Golden hwy East of Elong NSW, load onto tilt tray. Transport to Maas work shop Dubbo unload.	2/06/2026	
	56854	replace lost fuel cap	26/03/2026	

Asset	W/O No	Description	Finished	Done Reading
		WON56854 Should Charge Civil		
	61113	Inspect A/C *Diagnose A/C fault *Remove and replace A/C compressor - pressure test *Regas and test operation *Diagnose intermittent blower fault *Remove and replace blower motor	6/02/2026	
	60113	10,000km Light Vehicle Service WON 60113 Odo: 334,130km - carry out routine service	15/12/2025	
	56138	Repairs (Engine Light) Replace Turbo Odo: 331,947km - check & diagnose engine lights on & low power - removed & clean EGR system - R+R turbo charge - scanned & erased engine lights on - removed & change turbo electronic control module	18/09/2025	