

Work Order History Report

Asset	W/O No	Description	Finished	Done Reading	
LV0937		Toyota Hilux 4 x 4 Utility			
	192471	Pink Slip Inspection - Light Vehicle	9/06/2026		
	193308	Diagnose electrical issue no blinker - Check rh indicator fault - Found to have bad connection behind the battery for the bull bar indicator - Repair connection and all lights started to work - Scan vehicle and found to have multiple code related excessive crank times - All history related - Clear all DTC's - Test operation : all ok - Test all light operations : all ok	19/05/2026		
	60866	Spotlights to be fixed 344058km - run new switch wire for relay	12/02/2026		
	60080	replace Alternator	9/01/2026		
	59555	Breakdown 03.12.2025 Gearbox issue 339437km - replaced rear diff centre - replaced tail shaft - replaced hub seal	15/12/2025	339437	KM
	59267	Diagnose no start - jump start ute, check terminals for loose connections and check charge rate	21/11/2025		
	59107	Front tyres and WA	12/11/2025		
	58410	Breakdown tow back to yard to assess	20/10/2025		
	58317	Repair trailer plug wiring, brake light wire shorted to reverse light wiring Reverse alarm would come on with brake being used, rubbed through the wire, cut & rejoin wire, test to ensure working	13/10/2025	334097	KM

Asset	W/O No	Description	Finished	Done Reading	
		334097km			
	58009		30/09/2025		
	57513	Repair loss of battery power - Install 2 way, replace fuse on top of battery - Not starting, blown fuse, test to find blown fuse and replace - Open circuit causing loss of power, Swapped fuse	17/09/2025		
	55989	Recover vehicle after engine failure 332206km - put in shed and start to strip down to get ready to put injectors from the old engine into the new one. striped down old engine, pulled the injectors out as well as some further investigation on the old motor. - fit new engine,*please see attached work order for thorough notes*	12/08/2025		
	55934	Repair no park lights on trailer connection -trace wires, find broken wire and repair, test	2/07/2025		
	55369	Pink Slip Inspection - Light Vehicle -Defect repairs as quoted to JH 04.06.2025 Odometer: 330,029 km Completed pink slip inspection. Replaced upper control arms with GVM upgrade kit. Removed and replaced tray bolts. Replaced front bull bar lights (LED assemblies).	6/06/2025	330029	KM
	55243	Acerez fit out Supply and fit Redarc handbrake door alarm and reverse sensor kit. Repair reverse camera screen bracket and test function of camera. All ok Extend power supply from Anderson on headboard of tray to towbar and fit an addition Anderson plug.	3/06/2025		
	54559	10,000km Light Vehicle Service Replace Timing Belt Adjust Handbrake Replace 4 x Tyres -rear brakes shoes -left rear axle seal and bearing topped up all drive line fluid - 328548km	2/05/2025	328548	KM
	53294	Replace Rear LHS seatbelt Replace failed driving light	25/03/2025	325634	KM

Asset	W/O No	Description	Finished	Done Reading
	52471	Inspect driveline for vibration 323988kms -Remove rear drive shaft and replace universals on each end. - Install drive shaft onto ute, give ute a good wash dut to build up in hubs and under the body. - diagnose broken wire at the R/H rear of the ute - repair in-line fuse and fuse holder - repair R/H low beam light as it was not working - diagnose fault with R/H parker light - repair broken R/H parker wire	13/02/2025	313668 KM
	48953	R+R DRIVELINE VIBRATION DIAGNOSE & REPAIR STEERING PULLING TO THE RIGHT	14/01/2025	
	48991	10,000km Light Vehicle Service	4/10/2024	313668 KM
	18794	R+R ALTERNATOR & BATTERY (parts only)	10/07/2024	
	47978	ULAN INSPECTION - 34121 - 5.6.2024 - RORY	5/06/2024	KM
	47553	40,000 km Service LV, REPLACE REAR BRAKE SHOES, REPLACE REAR UNI JOINT, CHECK DRIVING LIGHTS - HRR	4/04/2024	297400 KM
	47551	FITTED NEW FUEL TRANSFER PUMP, INSTALL NEW ADNERSON PLUG ONTO WIRES AND RELOCATE WHERE PLUG SITS - 30766,32356,30769 - JAYSON, ALEX	12/03/2024	KM
	46826	10,000 km Service LV, REPAIR R/H BULLBAR INDICATOR, REPAIR REVERSE CAMERA, REPLACE SWAY BAR BUSHES & LINK PINS, REPLACE L/H/F CV SHAFT, REPLACE SHACKLE BUSHES, REPLACE FRONT & REAR SHOCKS - HRR	8/12/2023	282983 KM
	46888	CHECK OVER FOR ITS, REPLACE BEACON WIRING HARNESS, FIT TRIANGLE, FIT & WIRE IN DRIVING LIGHTS, FIT BATTERY FUSABLE LINK, FIT ALL MINE SPEC STICKERS, FIT FLAG POLL & MOUNT - 29886, 29887 - BOWEN	1/12/2023	KM
	46561	REPLACE ROCKER COVER, REPLACE A/C & FAN BELTS, REPLACE BRAKE ROTORS & PADS, REPLACE IDLER PULLEY, REPLACE HEADLIGHT BULBS - HRR	6/10/2023	275976 KM
	46297	10,000 km Service, REPLACE FRONT BRAKE PADS, REPLACE REAR DRUMS & SHOES, REPLACE REAR DRIVE SHAFT UNI'S, REPLACE CV SHAFT SEAL, INSTALL SUPPLIED CAMERA - HRR	8/09/2023	272983 KM
	46229	DIAGNOSE BLOWN FUSE & BATTERY ISSUE, REPLACE BATTERY, NO SHORT & CHARGING CORRECTLY - GB AUTO	21/08/2023	KM
	45918	REPLACE STARTER MOTOR & TEST - 28332 - BROCK	5/07/2023	265046 KM
	45732	REGISTRATION RENEWAL - ANNUAL	27/06/2023	KM
	45576	10,000 km Service LV, WHEEL ALIGNMENT - HRR	15/06/2023	262433 KM
	45704	FIT 4 NEW TYRES - GREG'S TYRE & MECHANICAL	14/06/2023	KM
	45923	REPLACE BATTERIES & REPAIR MINE BAR LIGHTS - GB AUTO	17/05/2023	KM
	45404	FIT TFO TRACKER, REWIRE SPOT LIGHTS - 27445, 29215 - RORY, PETER	24/04/2023	KM

Asset	W/O No	Description	Finished	Done Reading
	45135	40,000 km Service LV, REPLACE BRAKE SHOES - HRR	27/03/2023	251527 KM
	44892	FIT ONE NEW TYRE - GREG'S TYRE & MECHANICAL	9/02/2023	KM
	45092	RE-INTRODUCTION TO SITE - MOOLARBEN - ANNUAL	31/01/2023	KM
	44879	REWIRE LIGHT BAR, FIT NEW REAR LIGHTS - 22391, 22392 - TIM	24/01/2023	KM
	44502	10,000 km Service LV, REPLACE L/H BULLBAR PARK LIGHT BULB, REPLACE R/H HEADLIGHT PARK LIGHT BULB, REPLACE L/H TAIL LIGHT BULB - MSRC	1/12/2022	241105 KM
	44415	REPLACE BULB IN PARK/BRAKE LIGHT - 16057 - KEV	3/11/2022	KM
	44358	BLEED FUEL SYSTEM - 25826 - TIM	18/10/2022	KM
	44079	10,000 km Service LV, REPLACE REAR UNI JOINT ON REAR MOST TAIL SHAFT, REPLACE BOTH RACK ENDS, REPLACE BOTH UPPER CONTROL ARMS, ADJUST REAR BRAKE SHOES, WHEEL ALIGNMENT - MSRC	14/09/2022	231705 KM
	43968	REPLACE 3 DRIVE LINE UNI'S - 22327 - TIM	5/08/2022	227302 KM
	43866	DIAGNOSE NOISE IN DRIVE LINE, DRAIN OIL & REPLACE WITH CORRECT OIL, REPAIR WIRING FOR LIGHTS - 22313 - TIM	15/07/2022	KM
	43733	REGISTRATION RENEWAL - ANNUAL	27/06/2022	KM
	43805	REPLACE WINDSCREEN & MOULDING - SEE THRU WINDSCREENS	23/06/2022	KM
	43495	10,000 km Service LV, REPLACE R/H BULLBAR PARK LIGHT BULB - MSRC	19/05/2022	219825 KM
	43498	FIT 1 NEW TYRE - GREG'S TYRE & MECHANICAL	14/05/2022	219267 KM
	43292	REPLACE DRIVING LIGHT, FIT FUSE BANK TO BATTERY - 20961 - TIM	1/04/2022	216109 KM
	43203	RE-INTRODUCTION TO SITE - MOOLARBEN - ANNUAL	23/02/2022	KM
	43023	DRAIN & CLEAN FUEL TANK DUE TO CONTAMINATION - MSRC	16/02/2022	KM
	43058	REMOVE FUEL POD, CLEAN OUT POD & REPLACE FILTER, RE-MOUNT POD - 24416 - GABI	16/02/2022	210400 KM
	43010	40,000 km Service LV, DUST BOOTS ON REAR SHOCKS TIED BACK ON, DIFF & FUEL TANK BREATHER CLEARED - MSRC	15/02/2022	210390 KM
	44887	TRAVEL TO SITE TO PRIME FUEL SYSTEM - 25862 - TIM	3/02/2022	KM
	42816	FIT LED REVERSE LIGHTS, REMOVE & REPLACE FRONT BRAKE PADS - 20908, 23808 - TIM, ALEX	12/01/2022	207418 KM
	42321	10,000 km Service LV, REPLACE REAR BRAKE PADS, INSPECT R/H UPPER BALL JOINT - PETER	21/10/2021	200500 KM
	42155	WHEEL BALANCE - GREG'S TYRE & MECHANICAL	22/09/2021	KM

Asset	W/O No	Description	Finished	Done Reading
	41658	REGISTRATION RENEWAL - ANNUAL	28/06/2021	KM
	41390	10,000 km Service LV, REPAIR LIGHTS, WIRE UP ACCESSORIES POWER SUPPLY & UHF TO CONSTANT POWER, REPLACE BOTH UPPER BALL JOINTS - MSRC	24/05/2021	190218 KM
	41176	SUPPLY & INSTALL CELFI GO UNIT - GB AUTO	19/03/2021	KM
	40862	SUPPLY & FIT 4 NEW TYRES - GREG'S TYRE & MECHANICAL	10/02/2021	KM
	40867	RE-INTRODUCTION TO SITE - MOOLARBEN - ANNUAL	29/01/2021	KM
	40094	40,000 km Service LV - MSRC	18/12/2020	180471 KM
	38677	10,000 km Service LV	27/07/2020	169716 KM
	39281	REGISTRATION RENEWAL - ANNUAL	23/06/2020	KM
	38426	FIX FUEL TANK TO BACK OF UTE - 14822 - TIM	24/01/2020	KM
	38343	MINE SPEC - 18106 - DANNY	17/01/2020	154304 KM
	38307	MINE SPEC, FIT ISOLATOR - 18335, 4593 - CHRIS, BEN	10/01/2020	KM
	38029	10000K Service LV, REPLACE TIMING KIT & TRAILER PLUG, REPAIR P/S REAR WINDOW MOULD	28/11/2019	150921 KM
	37790	REPAIR WIRING, FIT FLASHING LIGHT, FIT UHF, FIT NEW TRAILER PLUG, NEW STICKERS, MOUNT FIRE EXTINGUISHER - TIM - 17994, 17995, 17997	14/10/2019	141000 KM