

Work Order History Report

Asset	W/O No	Description	Finished	Done Reading
LV0910		Toyota Hilux 4 x 4 Utility		
	192626	Diagnose Clutch Issue, replace terminal block	16/04/2026	
	191616	Pink Slip Inspection - Light Vehicle	9/04/2026	
	59769	Air con repairs @ CBM	27/03/2026	
	192122	New Fuel Nozzle on POD	23/03/2026	
	54929	Defect list SRS Light Ball joint Rack end and wheel alignment CV shaft Front tail shaft Job was billed directly to MAAS Plant (invoice attached to Documents)	26/11/2025	
	58888	Replace battery and alternator 560599km - Remove & replace battery - Remove and replaced failed alternator and belt - Check operation, vehicles starting and charging all ok.	4/11/2025	
	57903	10,000km Light Vehicle Service ODO: 559,643 KMS Replaced RH tail light assembly and replaced bulb in position X2. Replaced blinker light bulb in position X2. Replaced LH headlight bulb and repaired wiring to headlight circuit as required. Supplied and fitted OEM Hilux headlight lens cover. Supplied and fitted replacement RH front seat belt. Carried out associated labour to complete lighting repairs, wiring rectification and seat belt replacement.	24/09/2025	559643 KM
	56101	Pink Slip Inspection - Light Vehicle	15/09/2025	
	57287	Change flat tyre	25/08/2025	

Asset	W/O No	Description	Finished	Done Reading
	56441	Fuel pump for pod	22/07/2025	
	55754	Site inspection 558050km - Carryout pre-site inspection mechanical and electrical for Moolarben and complete relevant paperwork. - Complete site inspection and diagnose wiring fault, repair fault and top up transmission fluid. Put hi-vis tape on ute.	26/06/2025	558050 KM
	55733	Replacement fuel cap and Battery terminal cover	23/06/2025	
	55488	Front RHS wheel locked up Gricks Tow truck needed 556398km - front diff locked up, strip down and replace diff - diff was full of water causing lack of lubrication and pinion bearing seized up - strip front end in order to pull diff out and put new one in	16/06/2025	
	54586	10,000km Light Vehicle Service 555794km	7/05/2025	KM
	53019	Remove and replace LHS mirror 1 x Tyre puncture repair 550887km	10/03/2025	550887 KM
	52377	Test diagnose driving light fault Found green death within head lights causing faults, replace some wiring and replace 12v relay	10/02/2025	548914 KM
	52219	Replace damaged wheel studs and nuts LH rear Replace 2 tyres inspect axle for damage test drive and re torque wheel nuts	5/02/2025	
	50656	-Test/diagnose brake lights not working -Brake lights are blown -Beacon/indicator bracket on head board lose added 2 nuts and bolts to secure bracket	28/11/2024	542384 KM
	50329	Supply clock spring	20/11/2024	
	50250	40,000km Light Vehicle Service @ Gladstone Street Mechanical	19/11/2024	541749 KM
	47827	10,000 km Service LV	27/05/2024	527565 KM
	47706	REMOVED REAR DRIVE SHAFT OUT OF CAR - 31159 - ABBY	24/04/2024	KM
	47636	REPLACE R/H/R BRAKE GLOBE, REPAIR DRIVING LIGHT WIRING, REPLACE SUPPLIED DRIVE SHAFT, REPLACE L/H/R WHEEL STUDS & NUTS - MSRC	3/04/2024	523468 KM

Asset	W/O No	Description	Finished	Done Reading
47609		RE-INTRODUCTION TO SITE - MOOLARBEN - ANNUAL	26/02/2024	KM
47161		10,000 km Service LV, WHEEL ALIGNMENT, REPLACE R/H/F HEADLIGHT BULB, REPLACE L/H/R BRAKE LIGHT BULB - HRR	25/01/2024	517924 KM
46442		10,000 km Service LV, REPLACE REAR DRIVE SHAFT UNI'S, REPLACE PARK LIGHT GLOBE, REPLCE FRONT CV SHAFT - HRR	20/09/2023	508402 KM
46388		REGISTRATION RENEWAL - ANNUAL	14/09/2023	KM
46300		REPLACE TYRES - GREG'S TYRES	3/09/2023	506975 KM
45575		40,000 km Service LV, REPLACE ROCKER COVER & L/H/F CV SHAFT, REPLACE FUEL PRIMER, REWIRE DRIVING LIGHTS, WHEEL ALIGNMENT, REPLACE MUDFLAP, REPLACE LOCK ON TOOLBOX, REPAIR HEATER, REPAIR D/S VENT - HRR	30/05/2023	498768 KM
45470		REPLACE BATTERY, REPLACE BLOWN MASTER FUSE - 26473, 29504 - CHRIS, DAVID	4/05/2023	KM
45074		WIRE IN MINE UHF - 25883 - TIM	1/03/2023	KM
45048		REPAIR ID TRANGLE, RE-WIRE FLASHING LIGHT, RE-WIRE REVERSE BEEPER - 25879 - TIM	24/02/2023	KM
44821		10,000 km Service LV, REPLACE COOLANT, REPLACE FRONT DRIVESHAFT UNI - HRR	6/02/2023	489000 KM
44662		RE-INTRODUCTION TO SITE - MOOLARBEN - ANNUAL	16/12/2022	KM
44684		FIT NEW TFO TRACKER, REPLACE L/H HEADLIGHT GLOBE, REPAIR L/H/R PARKER WIRING, REPLACE R/H/F HI VIZ TAPE - 26741 - PETER	14/12/2022	KM
44133		REGISTRATION RENEWAL - ANNUAL	12/09/2022	KM
44142		REPLACE BOTH AIR BAG SEAT BELT SENSORS - 22346 - TIM	2/09/2022	KM
44125		REPLACE WINDSCREEN - SEE THRU WINDSCREENS	1/09/2022	KM
44076		10,000 km Service LV, SECURE MINE LIGHT BAR & BEACON, REPLACE BOTH RACK ENDS - MSRC	31/08/2022	478860 KM
44083		REPAIR TYRE - GREG'S TYRE & MECHANICAL	25/08/2022	478743 KM
43713		REPAIRS - REPLACE D/S SEAT BELT - CLYNT	21/06/2022	KM
42965		10,000 km Service LV, TIGHTEN REAR SPRING CLAMPS, TIGHTEN FRONT TRAY MOUNTING BOLTS, REPLACE D/S BULLBAR BLINKER BULB, REPAIR BRAKE LIGHT, CLEAN MUD FROM RADIATOR BOTTOM CORE, TIGHTEN BATTERY CLAMP, TIGHTEN BULLBAR BOLTS, CHECK FOR REAR END NOISE (NO NOISE FOUND) - MSRC	17/02/2022	468350 KM
42634		DIAGNOSE & REPAIR FUEL POD PUMP - 23414 - BEN	29/11/2021	KM
42433		RE-INTRODUCTION TO SITE - MOOLARBEN - ANNUAL	5/11/2021	KM
42109		REGISTRATION RENEWAL - ANNUAL	14/09/2021	KM

Asset	W/O No	Description	Finished	Done Reading
	42086	REGISTRATION RENEWAL - ANNUAL	14/09/2021	KM
	42110	40,000 km Service LV, REPLACE TIMING BELT, SECURE STONE GUARDS, REPAIR & SECURE BEACON TRIANGLE, WELD UP BRACKET ON BULLBAR - MSRC	13/09/2021	457949 KM
	41909	REPLACE ALTERNATOR - 18823 - BLAKE	2/08/2021	KM
	41870	DIAGNOSE STARTING/CHARGING ISSUE, REPLACE ALTERNATOR FUSE, REPAIR ALTERNATOR PLUG WIRING - 18822 - BLAKE	30/07/2021	KM
	41331	10,000 km Service LV - NATHAN	17/06/2021	451039 KM
	41587	REPLACE RADIATOR - 10082 - CHRIS	7/06/2021	KM
	41452	REPAIRS - REPLACE ANDERSON PLUGS ON FUEL POD - JOHN	21/05/2021	KM
	41211	DIAGNOSE & REPAIR ENGINE LIGHT FAULT, REPLACE DIODE - MSRC	29/03/2021	KM
	41047	REPLACE WINDSCREEN - SEE THRU WINDSCREENS	11/03/2021	KM
	40997	REMOVE SPARE PUMP FROM SPARE ENGINE & FIT TO ENGINE, REMOVE & REPLACE ENGINE, REPLACE TIMING KIT AND WATER PUMP, REPLACE SERP BELT, SWAP CRANKSHAFT POSITION SENSOR FROM SPARE ENGINE, REPAIR HANDBRAKE, REPLACE SEIZED L/H/R CABLE, RELACE REAR SHOES & DRUMS, CHECK TYRES - MSRC	25/02/2021	440383 KM
	40330	10,000 km Service LV - MSRC	15/12/2020	434562 KM
	40822	REMOVE & CLEAN INLET MANIFOLD & EGR COOLER ASSY, REPLACE EGR VALVE & GASKETS, REPLACE CRACKED ROCKER COVER - MSRC	18/11/2020	KM
	40270	REMOVE & REPLACE TURBO - 23069, 23071 - BLAKE	3/11/2020	KM
	40320	RE-INTRODUCTION TO SITE - MOOLARBEN - ANNUAL	6/10/2020	KM
	40016	FIT NEW AM/FM RADIO, BALANCE FRONT WHEELS - MSRC	1/10/2020	427588 KM
	39829	REGISTRATION RENEWAL - ANNUAL	14/09/2020	KM
	39641	REPAIRS - CHECK VIBRATION IN STEERING - STEVE	11/08/2020	KM
	39394	10,000 km Service LV - MSRC	10/08/2020	423583 KM
	39093	REPAIRS - CHECK OIL LEAK, CHECK TYRES, CHECK DRIVING LIGHTS - STEVE	15/05/2020	KM
	38847	REPLACE TURBO CHARGER - MSRS	25/03/2020	KM
	38642	40,000 km Service LV, REPLACE FRONT BULLBAR LIGHTS	12/03/2020	413798 KM
	38518	REPAIR FLASHING LIGHT - WAYNE	7/02/2020	KM
	37730	10000K Service LV, REPLACE REAR PARK LIGHT BULB, REPLACE REAR SHOCKS	22/10/2019	402275 KM

Asset	W/O No	Description	Finished	Done Reading
	37675	RE-INTRODUCTION TO SITE - MOOLARBEN - ANNUAL	23/09/2019	KM
	37635	REPAIRS - R/H BRAKE LIGHT	16/09/2019	KM
	37589	REGISTRATION RENEWAL - ANNUAL	12/09/2019	KM
	37607	REPAIRS - CHECK STARTER MOTOR - STEVE	11/09/2019	KM
	37305	REPLACE BATTERY - STEVE	15/07/2019	KM
	37028	REPAIR FUEL POD & REFLECTIVE TRIANGLE - 17196 - BEN	20/05/2019	KM
	36969	REPAIRS - LIGHTS FOR FUEL & WATER, NOISE IN FRONT END - MSRC	20/05/2019	KM
	37562	10000K Service LV, REPLACE REAR L/H SHOCK, REPLACE MISSNG TRIM CLIPS FROM INTERCOOLER BEZEL, RESET WATER IN FUEL INDICATOR, TIGHTEN FRONT TRAY MOUNTING BOLTS	13/05/2019	392016 KM
	36935	REPAIRS - ADJUST HAND BRAKE - STEVE	13/05/2019	KM
	36823	REPAIR - BATTERY HOLDER - STEVE	29/04/2019	KM
	36118	REPAIR FAULTY DASH LIGHTS - STEVE	4/01/2019	KM
	35842	40000K Service LV	20/12/2018	381687 KM
	35399	TYRES,LIGHTS,CHANGE OIL 12740-658-742-739-728-634 J.HODGES-T.HODGES	23/09/2018	KM
	35467	WHEEL STUDS 12779 J.HODGES	20/09/2018	KM
	35523	REGISTRATION RENEWAL - ANNUAL	11/09/2018	KM
	35272	10000K Service LV	28/08/2018	370472 KM
	35167	STICKERS, FIX FLASHING LIGHT - 12199 -T HODGES	4/07/2018	KM
	35125	REPAIR COOLANT LEAK, REPAIR TO LIGHTS - 12268- J COLLINS	28/06/2018	KM
	35002	REPAIR OIL LEAK- 16572- K BOUCHER	4/06/2018	KM
	34933	10000K Service LV	1/06/2018	363951 KM
	34730	CHANGE R/H FRONT TYRE, MINE SEC, REPAIR LIGHTS- 14487-J COLLINS	11/04/2018	KM
	34632	10000K Service LV	29/03/2018	356752 KM
	34602	REPALCE EGR GASKET TEST EGR- 14445-46- J COLLINS	6/03/2018	KM

Asset	W/O No	Description	Finished	Done Reading	
	34299	40000K Service LV	2/12/2017	349000	KM
	34297	10000K Service LV - BEN SWARBRICK - 14271	2/12/2017	349000	KM
	34273	REPAIR OIL LEAK FROM CAM SEAL- 14271- BEN SWARBRICK	2/12/2017	349000	KM
	34003	FIT EGR VALVE - TIM HODGES - 10603	17/11/2017		KM
	33715	10000K Service LV	16/11/2017	346520	KM
	33782	REMOUNT BROKEN FLASHING LIGHT - TIM HODGES - 10961	12/10/2017		KM
	33783	REPAIR TOP BAR LIGHTS, FABRICATE NEW MOUNT - TIM HODGES - 10953	9/10/2017		KM
	33619	INSPECT A/C, CLEAN BLOCKED CAB FILTER - GB AUTO - 32477	22/09/2017		KM
	33507	REGISTRATION RENEWAL - ANNUAL	13/09/2017		KM
	33402	10000K Service LV	26/08/2017	335732	KM
	33220	FIT ENGINE - STEVEN BANNINK - 47916	22/07/2017		KM
	33219	REBUILD ENGINE, SERVICE - STEVEN BANNINK - 16204	19/07/2017		KM
	32729	REMOVE ENGINE, SUMP AND PISTONS - JOSH WAKELING 15599	28/04/2017		KM
	32633	10000K Service LV	26/04/2017	330800	KM
	32668	ASSIST STRIPING ENGINE - JASON DICKINSON 15255	19/04/2017		KM
	32507	SERVICE/WASH - JASON DICKINSON 13365	20/03/2017	330692	KM
	31315	40000K Service LV	20/03/2017		KM
	31109	REGISTRATION RENEWAL - ANNUAL	15/09/2016		KM
	31124	10000K Service LV	28/07/2016	311233	KM
	30398	5000K service LV	13/05/2016	305000	KM
	30271	SERVICE - JASON DICKINSON 9814	3/03/2016		KM
	29959	10000K Service LV	3/03/2016	296052	KM
	30165	COOLANT LEAK IN CAB; PULLED DASH APART FOUND LEAKING HEATER CORE; TURNED OFF HEATER TAPS; RADIATOR PRESSURIZING; POSSIBLE HEAD GASKET - BEN STIRLING 8489	10/02/2016		KM
	30006	REPLACE BLINKERS & LIGHTS IN BULL BAR OF UTE; REPLACE WITH LED'S - ANDREW BURKE 5626	15/01/2016	289163	KM
	29552	5000K service LV	15/12/2015		KM

Asset	W/O No	Description	Finished	Done Reading
	29387	SERVICE AND ROTATE TYRES - JASON COLLINS 7950	8/12/2015	KM
	29053	10000K Service LV, REPLACE REAR SHACKLES & REAR SHOCKS, RESEAL REAR DIFF, FIT TOOL BOXES - JOHN HODGE 7535, 7537	22/09/2015	276341 KM
	29264	REGISTRATION RENEWAL - ANNUAL	15/09/2015	KM
	28933	LOOKED AT FRONT END, CHECKED UNI JOINTS, RECLAMPED CU BOOT MISSING CLAMP ON LEFT OUTER BOOT - JASON COLLINS - 13979	23/07/2015	KM
	28671	5000K service LV	26/06/2015	265244 KM
	28176	40000K Service LV	20/05/2015	258042 KM
	27848	5000K service LV + REPAIRED HINGE ON RH TOOLBOX & PAINTED - GEOFF BETTS 6965	30/01/2015	246536 KM
	27770	10000K Service LV + REPLACE FRONT BRAKE PADS, CHECK DRIVING LIGHTS - JASON COLLINS 6598	21/11/2014	235436 KM
	27405	REGISTRATION RENEWAL - ANNUAL	15/09/2014	KM
	27404	10000K Service LV	22/08/2014	225992 KM
	26352	5000K service LV	21/07/2014	221004 KM
	27176	FIT NEW LED LIGHTBAR - JOHN WYNEN 5997	27/06/2014	KM
	27157	WIRED IN NEW CD PLAYER & PHONE KIT - JASON COLLINS 4899	13/06/2014	KM
	25738	200000K Service LV - JASON COLLINS 5179	20/01/2014	200296 KM
	25361	10000K Service LV	12/11/2013	193390 KM
	25479	REPAIR DRIVING LIGHTS, REPLACE LEFT HAND HEADLIGHT GLOBE - TOM WARNER 5543	12/11/2013	193390 KM
	25219	FIT TWO NEW TYRES TO FRONT AND ROTATE TYRES, GREASED AND CHECKED DRIVELINE - JASON COLLINS 5810	8/10/2013	187900 KM
	24937	REGISTRATION RENEWAL - ANNUAL	29/08/2013	
	24698	WIRE IN LGHT BAR CIRCUIT AND ANDERSON PLUG - JOHN WYNEN 0060	24/07/2013	182381 KM
	24701	FINISH WIRING TO ANDERSON PLUG AND MAKE CONNECTIONS - TEST - JOHN WYNEN - 0061	23/07/2013	182381 KM