

Work Order History Report

Asset	W/O No	Description	Finished	Done Reading
LV62		Holden Colorado Dual Cab 4X2		
	58183	O-ring EGR Pipe parts only credit card purchase.	7/10/2025	KM
	55937	Diagnose and repair over heating - perform pressure test in cooling system; no leak found - perform drive test from Dubbo to Geurie; shows normal temp - perform combustion leak test, no reaction / change colour of fluid - carry out routine service - replace brake pads	3/07/2025	KM
	52448	10,000km Light Vehicle Service	18/02/2025	212334 KM
	48470	Capital FFP - Brett Harvey Designs - fit tracker and activate - Fabricate ladder rack - Fit bull bar and driving lights	28/10/2024	
	21007	prep for sale. 206007 km 19/08/24 - Remove tracker. - Remove reverse camera. - Remove UHF. - Remove beacon. - Remove all hi-vis stickers, these were extremely hard to get off without ruining the paint. - Wash and detail.	19/08/2024	206007 KM
	20522	Repair tyre	2/08/2024	
	19712	Pink Slip Inspection - Light Vehicle	17/07/2024	202910 KM
	11581	10,000km Light Vehicle Service	14/03/2024	200372 KM
	3464	Puncture in the side wall of Pos 4 tyre	21/07/2023	190803 KM
	1152	Pink Slip Inspection - Light Vehicle	27/06/2023	190223 KM
	61	TFO W/O #6186: 10,000km Light Vehicle Service Remove and replace battery Replace windscreen replace wiper blades	22/03/2023	185801 KM