

Work Order History Report

Asset	W/O No	Description	Finished	Done Reading
T0141		Mazda Bravo B25		
	55130	replace windscreen - replace taillights, install resistors as the new taillights were led.	5/06/2025	KM
	55043	Replace Tyre and Wheel Alignment	29/05/2025	KM
	58482	Pink Slip Inspection - Light Vehicle	23/05/2025	224998 KM
	53201	Puncture repair. *MAXXIS 185R14C (8) 102/100R MCV3+ *cs QTY 2. *Disposal - Passenger Tyre QTY 2.	17/03/2025	KM
	51108	Repair coolant leak 219671km -check and diagnose coolant leak -removed and replace thermostat and hose.	20/12/2024	219671 KM
	49757	Rocker Cover Leaking Oil/ Replace water pump and gasket - remove, inspect & cleaned valve cover - replace valve cover gasket	4/11/2024	KM
	17091	Replace battery - R+R battery - fabricate wire & switch for pump	22/05/2024	215072 KM
	15810	Pink Slip Inspection - Light Vehicle WO# 8446 cancelled	19/03/2024	215072 KM
	4449	10,000km Light Vehicle Service Check and adjust torsion bars. Set ride height to be level Remove and replace window tint Functional test in sprays - no fault found	15/08/2023	213127 KM
	4138	Puncture Repairs Hannaford Tyre & Suspension LH Front	3/08/2023	KM