

Work Order History Report

Asset	W/O No	Description	Finished	Done Reading
CB1333		Powerscreen Warrior 1800 Screen (WAR1)		
	187249	Replaced hose	8/09/2025	
	182906	Replaced tail drum bearing and plumber block	27/02/2025	
	183194	Replaced RH bearing	21/02/2025	
	182723	Replaced hose from shaker box to oil cooler Adjusted fines belt	19/02/2025	
	182714	Replaced punch plate on clamp bar	15/02/2025	
	177651	Plant Risk Assessment Review	26/06/2024	
	176978	Replaced battery and starter motor	12/06/2024	
	175863	Repaired hose	30/04/2024	
	173285	250 Hour Earthmoving service	15/02/2024	
	172766	Un-bogged screen and adjusted tail drum	12/12/2023	
	171922	Getting hot = Tensioned fan belts, clean out radiator, wire up hydraulic cooler	30/11/2023	
	171716	Fines belt unbogged	28/11/2023	
	171721	Repaired top deck screen	27/11/2023	
	171722	Unbogged belts Replaced side skirts to screen deck	22/11/2023	
	171450	Installed lanyards Removed RH wing cylinder and bracket	21/11/2023	
	171471	Replaced screens	10/11/2023	
	170509	Replaced LH oversize belt cylinder	28/09/2023	
	169847	Replaced screens	12/09/2023	

Asset	W/O No	Description	Finished	Done Reading
	169852	Repaired belt	8/09/2023	
	167834	Packed up for transportation	25/07/2023	
	167514	Hydraulic hose replaced	19/07/2023	
	165902	500 Hour Earthmoving Service	18/07/2023	
	167521	Repaired and adjusted fines belt	18/07/2023	
	167348	Replaced screen	17/07/2023	
	167354	Eng wont start = Tighten key switch and replaced air filters	14/07/2023	
	167096	Inspected coolant/oil levels, belts = OK Air filter blocked= Blew out Greased machine	10/07/2023	
	166639	Replaced fines conveyor tail bearing and housing	22/06/2023	
	165786	Pack up machine for transport	30/05/2023	
	165782	Repaired screen guard Repaired grease line	26/05/2023	
	165791	Engine cuts out = Replaced oil pressure switch	24/05/2023	
	166637	Repaired LH wing hinge	22/05/2023	
	166636	Replaced fuel filters x2 Topped up coolant	20/05/2023	
	166032	Replaced top deck punch plate	19/05/2023	
	165532	Re-connected plug in elec board	18/05/2023	
	165535	LH lanyards re-fit	17/05/2023	
	165295	Screen set up and Inspected = OK	16/05/2023	
	158495	Fuse replaced	13/09/2022	
	158211	Side conveyor tail pulley replaced	8/09/2022	
	158712	Pack up - 05.09.2022 Set up as needed - 06.09.2022	6/09/2022	
	158288	Wont start = Inspected/OK	18/08/2022	
	155910	Belt un-jammed as needed	27/06/2022	

Asset	W/O No	Description	Finished	Done Reading
	155915	Setup machine as needed Replaced fines belt conveyor bearing, side skirts and top Deck screen	21/06/2022	
	154703	250 Hour Earthmoving service	30/05/2022	
	154798	Packed up for transport	23/05/2022	
	154815	Feeder head pulley cleaned as needed	19/05/2022	
	154615	Screens replaced Side conveyor hoses replaced as needed	11/05/2022	
	154310	Exhaust manifold gasket replaced	13/04/2022	
	153575	Blow out radiator and hydraulic cooler	4/04/2022	
	153364	Screen replaced	31/03/2022	
	153346	Side discharge belt repaired as needed	30/03/2022	
	153344	Patched holes in bottom deck Repaired counter weight guard	30/03/2022	
	153235	Fuel pump replaced	26/03/2022	
	152115	Alternator replaced	17/02/2022	
	150803	2000 Hour earthmoving service	21/12/2021	
	150866	Screen clamps tightened and replaced as needed	15/12/2021	
	151583	Repair/replaced lanyard box's as needed Replaced cables to LH conveyor	8/12/2021	
	149943	Replaced Screen	24/11/2021	
	149192	Grease line repaired Skirting replaced Bolts on screen deck replaced	15/11/2021	
	143583	Replaced tail conveyor	13/05/2021	
	143430	Feeder belt replaced Return roller replaced	10/05/2021	
	142112	Replaced roller under fines belt	10/05/2021	
	142873	250 Hour Earthmoving service	3/05/2021	
	143184	Screen bolts replaced as needed	28/04/2021	

Asset	W/O No	Description	Finished	Done Reading
	142945	Screen chute repaired as needed	28/04/2021	
	142416	Oversize belt LH skirt replaced Oversize chute from screen to deck replaced	12/04/2021	
	142355	Leveled out front conveyor as needed	12/04/2021	
	141797	Oversize belt coupling replaced LH skirt replaced	18/03/2021	
	141172	Starter replaced	4/03/2021	
	141017	Guards repaired as needed and screen adjusted	2/03/2021	
	140859	Belt need changing Replaced belt under screen deck, changed skirts, changed rollers C Buck	23/02/2021	
	141015	mid size belt tensioned	23/02/2021	
	141016	Removed guarding, lift screen, skirts and scraper Ready for repair	19/02/2021	
	140695	Lower deck screen Lift up screen & remove large screen, install new screen Scot R	11/02/2021	
	140834	Key broken off in ignition switch Fit new ignition switch & key Glen W	11/02/2021	
	140555	Blown hose replace hose from shaker box to control valve, add oil & test-ok Glen W	3/02/2021	
	139758	replaced bottom deck position 2 screen. 22mm Installed stringer rubbers, J bolts Changed top screen clamp bars.	21/01/2021	
	138502	control panel handrail section repaired as needed	21/01/2021	
	138998	Straightened drive motor bracket and frame, replaced drive couplings. replaced LH skirting and hoses on over size conveyor track belt on over size conveyor	11/12/2020	
	139113	Fabricate guard & fit to return roller Sam B Fab new conveyor belly guard & install Scot R	11/12/2020	
	138800	500 Hour Earthmoving Service	11/12/2020	

Asset	W/O No	Description	Finished	Done Reading
	139183	Bent bracket Straighten motor mount brackets and paint Scot R	10/12/2020	
	133750	roller under fines belt replaced cuts in belts, Replaced radiator W/O #37585 nGlen W other repairs in WO	24/11/2020	
	138464	Top deck #3 screen replaced	19/11/2020	
	138644	Change screen 1 X 125mm screen top deck Sam B	19/11/2020	
	137585	Radiator leaking Fit new radiator & add ELC, test OK Glen W	23/10/2020	
	136243	Loose belt on screen box. Other issues as per W/O 33750	14/09/2020	
	136328	Blown hose Replace blown tail conveyor hose G Windle	9/09/2020	
	135332	Belt damaged Cut belt & remove, remove skirts & clean rock out, ready for belt install S Rodgers Belt replaced by JL conveyor belt services (see attachments) Skirts Install skirts on tail conveyor, re-install guards, track belt & test OK S Rodgers	21/08/2020	
	133871	250 Hour Earthmoving service	31/07/2020	
	134506	Screen bolts Change screen bolts on top deck S Rodgers	16/07/2020	
	134260	Over size conveyor won't run Replace worn out HRC coupling & position & tighten taper lock G Windle	14/07/2020	
	134177	Warrior repairs Weld cracks & wear plate down, bolt screen in (needs correct bolts), pack up gear S Rodgers	12/07/2020	
	134148	Broken of wing off top hopper underneath screen deck broken Repaired underneath screen deck new plates cut, wing tacked back on, still need welding and fish plate, fish plate cut out N Mizzi	11/07/2020	
	136335	Fitted Alternator, fitted screen on top deck	9/07/2020	

Asset	W/O No	Description	Finished	Done Reading
		C Buck		
	134037	Wont start Jump start warrior check charge,not charging-fuse link also blown,battery will be u/s B Patrick Garry Winton (see attachment)	8/07/2020	
	133910	Middle deck chute Fit rams to tail so can move around-rams still leak chain up Gouge off patch-replace with full plate,weld in & set machine back up S Rodgers	30/06/2020	
	133340	Alt & belt u/s R&R OEX 12v 120amp alternator,R&R fan drive belts,check charge rate to battery OK B Wise	19/06/2020	
	132529	Blown hose Called pirtek and replaced 3 HYD hoses.	1/06/2020	
	132485	Repair bent and broken hand rails. S.Roders.	29/05/2020	
	132486	Machine all blocked up with dirt Lift up screen and dug out belt cleaned out belts and washed down machine. cleaned up pad. S.Rodgers	21/05/2020	
	131544	500 Hour Earthmoving Service	16/05/2020	
	130995	Rocks jamming in tail drum. Cleaned out tail Drum removed stuck rocks adjusted belt and repair skirt rubber. Scott rodgers.	21/04/2020	
	131417	Rock stuck in screen Removed stuck rock And retensioned & put pin in R Farquhar	17/04/2020	
	131634	Wont start Reconnected wires that had come loose R Farquhar	15/04/2020	
	131650	Repairs R/H-tighten belt & track,Re-install return rollers & guards,repair lanyards Remove ram-sent to PKWS for reseal,grease all bearings,check engine +oil levels OK Missing x2 rams-PKWS for reseal S Rodgers	1/04/2020	
	130173	Repairs Weld in new brackets for R/H side Re-install conveyor and tail drum R/H side Fold up tail conveyor and belt together Re-attach Hyd Hoses	27/03/2020	

Asset	W/O No	Description	Finished	Done Reading
		S Rodgers		
	130172	Repairs Repair tail drum, APWS Gouge of X 4 cleats for tail section Finish repairs on tail section Take back to warrior and install Install motor on tail conveyor S Rodgers	25/03/2020	
	130171	Repairs Remove R/H side conveyor Remove tail hopper section for repairs Install tail conveyor motor *Taper bush motor side missing re-order S Rodgers	24/03/2020	
	126015	bent head drum brackets Remove main head pulley and slide head pulley and frames Install head pulley tail end conveyor Remove hoses and electronics, side conveyor R/H ready for removal Remove damaged hoses L/H side Removed Bent rams for repair. S Rodgers	23/03/2020	
	129823	Coast to country Warriorscreen, set up machine as required B to B Set up conveyors as required Assist with screen setup in stockpile area Test and run machine B Wise	12/03/2020	
	126016	leaking hydraulic hoses	27/12/2019	
	127350	bolt broken on top deck replaced broken bolts	17/12/2019	
	127320	repaired faulty lanyard bracket	9/12/2019	
	126813	won't walk	29/11/2019	
	126280	Can't adjust belt	13/11/2019	
	126279	bent ram on conv SEE work order 26015 for Details	6/11/2019	
	126196	Wont start test start system gring noise from starter remove starter motor pinion gear very worn replaced starter motor	31/10/2019	

Asset	W/O No	Description	Finished	Done Reading
	125717	blown hydraulic hose	14/10/2019	
	125635	lanyards estops not working repaired bridged safety wiring repaired faulty lanyard	10/10/2019	
	124092	Wont start Removed old battery and replaced it with a new one.Cleaned out battery box Ryan Latham	27/08/2019	
	123495	Fit GPS Install GPS westrac unit as required Brad Wise	27/07/2019	
	123086	change out screens repair throttle lock on cable to engine. r&r 16mm bottom deck screens,r&r 53mm top deck screens Brad Wise	8/07/2019	
	122453	wont start starter motor doesn't mesh.remove starter & de-burr damaged pinion gear teeth some burring evident but still servicable refer PKWS Glen Windle	19/06/2019	
	122265	Won't start engine starts every time when tested Glen Windle	14/06/2019	
	120347	250 Hour Earthmoving service	10/04/2019	
	118909	500 Hour Earthmoving Service	25/02/2019	
	121082	fixed guard to stop spillage	1/02/2019	
	119111	Oil leak Fines belt hand control valve not staying on Replaced hose (Pirtek) Replaced control valve for fines belt	20/01/2019	
	119066	Feeder Repair skirts and brackets on hopper Put feeder back together install back onto warrior Spring for e stop missing B williams	18/01/2019	
	119067	Head pulley Remove feeder belt from machine Removed hopper cut belt off Remove motor and head pulley	17/01/2019	

Asset	W/O No	Description	Finished	Done Reading
	119068	Skirts Site measure skirt plates Order material start fab at PKWS Finish fab and press Pick up skirt and take to quarry Repair damaged skirt between feeder and screens	16/01/2019	
	119131	Oil leaks Replaced hose behind valves to pump on motor Replaced o-ring on RHS discharge belt hose	12/01/2019	
	118730	Screen worn (22mm) Replaced bottom deck long screen (22mm) Replaced frame rubbers underneath screen	4/12/2018	
	118729	Bottom long 22mm screen cracked and broken with holes Changed bottom long screen (22mm) Changed top and bottom screen to a 5mm punch plate	4/12/2018	
	118658	Bottom deck screen bouncing around Fitted hook bolts to stop screen from bouncing	29/11/2018	
	118216	screen loose (bottom deck smaller screen) installed new j-bolts & nuts screen will need to be replaced soon	27/11/2018	
	118229	hole in bottom deck screen cut section of screen & bolted over hole	21/11/2018	
	118241	guard missing from tail pulley fabricated & fitted guard to tail pulley	15/11/2018	
	117905	Wont start Test electrical system for starting problems found would not start due to hyd oil level sender fault test wiring to sender , fill hyd oil (sight glas U/S) Test starter, batteries i think there is a problem in the control board swap wiring from coolant level sensor with hyd level sensor still would not clear the light Make harness (around control) to start and function machine , 250 HR service Note all lantards cables ties off broken	8/11/2018	
	117566	250 Hour Earthmoving service	8/11/2018	

Asset	W/O No	Description	Finished	Done Reading
	117957	changed 2 tail drum pulley skirts	7/11/2018	
	117757	hole in screen bottom deck	2/11/2018	
		bolted a section of screen over hole		
	117765	hole in bottom screen	1/11/2018	
		bolted section of screen over hole		
	117494	holes in impact screen welded plate over holes	19/10/2018	
	114400	broken hydraulic hose	2/10/2018	
		Called pirtek		
	116828	blew out air filter	25/09/2018	
	116829	won't start found sticky starter motor solenoid tapped it to free it up	24/09/2018	
	115952	blown hydraulic hose	21/08/2018	
	116447	Remove and replace bottom deck screens RnR x1 top deck screen Repair broken plate weld Replace rubber piece on tail conveyor Clean rubbish out of top deck	31/07/2018	
	115260	leaking lift ram	25/07/2018	
	115245	fit cylinder	24/07/2018	
	115147	replace hydraulic hose	24/07/2018	
	113532	Conv drum out of center	13/06/2018	
	113665	Broken Bearing end discharge	31/05/2018	
	113531	broken conv belt	28/05/2018	
	112270	2000 Hour earthmoving service	17/04/2018	
	112576	Dismantle conveyors & gaurds Pirtek called R&R blown conveyor tilt hose needs to be reassembled before operation of conveyor & screening R&R top punch plate screen fit new bolts and nuts re assemble conveyors fit gaurds	8/03/2018	

Asset	W/O No	Description	Finished	Done Reading
	116292	Pick up and replace head pulley bearing ass under screen deck	6/03/2018	
	111930	250 Hour Earthmoving service	5/03/2018	
	112563	R&R top punch plate screen with half plate/half 50mm holes	27/02/2018	
	111651	wont start - battery flat. Fit new alternator & belt. Fit new battery.	15/02/2018	
	111679	Oversize belt has rocks under it. belt moved over & skirts are under belt. shaker deck lift rams to be fitted. Remove skirts & clean out rocks under oversize belt, Refit skirts. Fit rams to shaker deck Test ok.	5/02/2018	
	111672	Screen deck slowing down when loaded. Replace hydraulic pump and test. 950 unloaded 900rpm fully loaded - ok.	31/01/2018	
	111649	fit 2x resealed conveyor ram/cylinder ass test & run ok.	15/01/2018	
	111925	Pre-release check sheet. Ram rod bent/pitted. Cut 1 1/2" chrome to length. Machine ends to desired diameter. cut M30 thread on one end 50mm long. Gouge ram head off old rod. Clean with a grinder. Re-weld old head onto new ram bar	19/12/2017	
	110663	Belt stopped, conveyor rams broken, skirts on fines belt u/s. Remove cylinder of the oversize conveyor, remove material from tail drum, replace skirt rubber around tail drum, run, test - ok. Replace several skirts on all conveyors.	12/12/2017	
	111694	Air filter- blocked. Replace air filter.	1/12/2017	
	110115	500 Hour Earthmoving Service	22/11/2017	
	110367	Change top deck screens store old ones at level 1 crusher change bottom deck screens	9/11/2017	
	110078	Changed two bearings and housings greased entire warrior	30/10/2017	
	109369	250 Hour Earthmoving service	11/10/2017	
	109325	Fan belt damaged replace fan belt	23/09/2017	
	108764	Remote repairs	31/08/2017	

Asset	W/O No	Description	Finished	Done Reading
		forward and reverse coil wiring repairs bottom screen deck repairs replace bottom deck 16mm screen		
	108599	Deliver part to Ben Williams and help need to order new remote control and solenoid	28/08/2017	
	108718	Loose screens move screens back into position	24/08/2017	
	108598	Flashing light not working had to rewire tested OK	23/08/2017	
	108717	Change screens	8/08/2017	
	108330	Remove hopper and conveyor from rear	21/07/2017	
	106093	Changed top screen with blank plate and fitted new side bolts.	27/06/2017	
	108218	Drive coupling broken Removed pump from rear of engine replaced drive coupling refit pump Tested OK	30/05/2017	
	107740	Dug out belt and removed the last screen	16/05/2017	
	105086	500 Hour Earthmoving Service	9/05/2017	
	104916	Lanyards U/S replace 2x defective lanyard boxes	28/03/2017	
	104926	Buried discharge conveyor. Tail pulley taperlock us fit new coupling assembly to head pulley and test ok	24/03/2017	
	108201	Reported lanyard faults Replace lanyard cable on all 3 belts both sides Replace turn buckle and steel loop rings Tested all lanyard boxes manually and electronically	23/03/2017	
	108197	Guards loose skirting rubber need replacing Tighten guards and replace all of the worn skirts	22/03/2017	
	108271	Change top deck screen plates	20/03/2017	
	108253	Tension belt and track tension scrapper	7/03/2017	

Asset	W/O No	Description	Finished	Done Reading
	108254	Replace skirts	6/03/2017	

Asset	W/O No	Description	Finished	Done Reading
		put guards on and test		
	107918	Damaged conveyor belt Adjusted tail pulley accordingly for belt tradesman	2/03/2017	
	107912	New conveyor belt put on Refit hopper/feeder assembly and all hydraulic hoses, tracked belt.	22/02/2017	
	108332	Put warrior back together Tasted OK	22/02/2017	
	104483	Blown hose	22/02/2017	
	107910	Feeder belt is damaged remove hopper/feeder assembly and the belt company to access	21/02/2017	
	107979	Alternator not charging Replaced alternator, tested OK	15/02/2017	
	108320	Track conveyor belt and removed damaged guards	14/02/2017	
	104376	remote control box dropped and cracked. water getting in complete	9/02/2017	
	108165	Won't start Jump started Ordered battery	4/02/2017	
	108162	Starter motor And won't track Replaced after market starter with CAT repaired wiring in remote box	2/02/2017	
	103918	Engine stopped - won't start. Repair O/C at engine stop solenoid. Tested OK.	15/12/2016	
	102585	250 Hour Earthmoving service	19/10/2016	
	101483	500 Hour Earthmoving Service	5/09/2016	
	107798	Fitted: -New drive - 5 new slide deck strips - new skirt rubbers Repaired side guards New belt was fitted by J Conveyor services	6/08/2016	
	101297	250 Hour Earthmoving service	4/08/2016	
	106089	Alt U/S fitted new alternator and belt.	6/07/2016	
	100520	250 Hour Earthmoving service	16/06/2016	

Asset	W/O No	Description	Finished	Done Reading
	100153	feed belt u/s # Replace drive pulley ass, Drive pulley relaged, Fit new feed belt, Fit new hopper skirts,Fit new fines belt scraper B Wise	19/05/2016	
	108885	Fabricated new 150mm screens weld side hooks to plate as per drawing	26/04/2016	