

Work Order History Report

Asset	W/O No	Description	Finished	Done Reading
P1197		Cat 299D2 Posi Track		
	194183	July Monthly R&M WO: Replace cab mounts and bolts	9/07/2026	Hours
	194038	June R&M Monthly WO Replace cab mounts	30/06/2026	Hours
	192907	May R&M Check machine for fault causing the park brake to stay on.- Found to have a fault related to engine speed.- Checked at sensor and found to be losing its 5v supply.- Checked over harnesses and found wiring had rubbed through on a clamp on the backside of the engine.- Repair as required.- Test operation.- All ok. 2/5/26 evaporated core blocked, remove core and ducting clean as required. Reassembly and test aircon, remove Deutsch plug on compressor 21-5-26 engine derating, found failed air intake temp sensor order parts and fit when arrive	22/05/2026	Hours
	193036	Replace damaged RHS rear E-stop. Hollingsworth. 5336hrs. 04.05	4/05/2026	Hours
	192377	April R&M Monthly WO Make new wiring harness for quick hitch die to ripper Remove blown drive motor hose -Stuck quick hitch Blown hose / fan establisher Blown drive hose 20/04/2026 SMU=5305hrs Remove and replace blow drive motor hose.change out orings. Fill with 20L of hydraulic oils Prestart and run up machine to operation temperature Plug in sis I and confirm fan rotation is correct.calibrate fan speed and reverse timing Run Run up and test machine (test ok) Clean pack up tooling leave site 23/4/26 no start, replaced damaged battery cable lug and test	23/04/2026	5322 Hours
	191202	Positrack - 250hr Service * Grease machine * Take eng oil samples	3/03/2026	5236 Hours
	61023	Replace missing RHS mirror	19/02/2026	Hours
	60077	January R&M 5335hrs -Fuel sender faulty, remove and replace 14/01 - LH drive motor hose blown, replace oring	28/01/2026	Hours

Asset	W/O No	Description	Finished	Done Reading
	57241	Diagnose engine overheating problem. Replace EGR pipe. #Exhaust manifold removed to repair EGR. Re-seal lift cylinders Travel to site inspect final drive leak	16/12/2025	Hours
	58701	Pre hire repairs as per inspection, WO 58679 #Variance. Replaced final drive wheel bearing Pos1. 5134 hrs	27/11/2025	5134 Hours
	58679	Off hire inspection quote #419	29/10/2025	Hours
	55502	JUNE R&M - River ST. Repair pin and retainers on site. Replace EGR coolant hose - fit heat shield to avoid it blowing Coolant leak due to cap not being on Clean & wash out coolers and engine bay, check levels, test drive get to max temp to see if overheating still. Hook up laptop to clear codes assess info that is stored. Diagnose blowing blue from engine bay not exhaust Diagnose fault on posi track Operator removed coolant rad cap for prestart, Forgot and ran out of coolant locate cap. Fill with coolant Organise management to get running for site with retainer and test, Fit new plates to track frame Organise / find missing parts. Look up procedures for sleeve replacement, pick up westrac por fs. Go to site asses machine, Find defects report. Repair pin on cat bobcat lift arms. Note new pin and bush will need to be replaced Tension belt, diagnose over heat, make heat wrap cooling hose and fit re-fill coolant, look up parts.	30/06/2025	Hours
	55230	Positrack - 1000hr Service 5039 hrs - Grease all points - Found broken track frame axel mount retaining plate snapped in two. Diagnose cause of breakage. Look up parts to rectify problem speak with Reaan about plan of attack to fix. - Rear eng bay door is damaged - Broken / chopped bucket position wiring lume.	20/06/2025	Hours
	54701	5000 Hrs Fit track on site replace leaking idler.	14/05/2025	Hours

Asset	W/O No	Description	Finished	Done Reading
		coolant leak - Diagnose RH front idler leak & report to supervisor on which style idler it was so parts can be ordered. - Travel to site to see if idler in Mudgee measurements were the same as the one fitted to machine. Report back, Clean GH oil off idler & track. - Idler arrived. De-tension track, remover idler mount power down with bucket block in place, pry out old idler. Lift in new idler, pry out track enough so idler was past mount, bolt in place retention track. Take for test drive to ensure no slippage or track walk off. All good. Recheck track tension hand back to river st. - Instructed to strip down old idler & see what went wrong & quote parts needed to repair. Cheaper to purchase complete new idler, Instructed to throw in steel bin		
	53117	Replace fuel level sender. Diagnose low power / slow hydraulics. Checked all interlocks - ok. Replace fuel filter. Removed and cut filter - clean. Repair wiring harness.	1/04/2025	Hours
	52866	HME Inspection - Positrack Quote #: 329	27/02/2025	Hours
	51858	Machine park brake not releasing. 4774hrs -Diagnose and repair -Repair speed sensor wiring (cam shaft speed sensor)	28/01/2025	Hours
	50255	Repair fork attachment	18/11/2024	Hours
	49690	Diagnose bucket creep	29/10/2024	4748 Hours
	20139	P1197. Pre hire repairs as per HME inspection. W/O 19284	11/10/2024	Hours
	19284	HME Inspection - Positrack Quote #: 143 Hours 4713 12/07/24	12/07/2024	Hours
	19714	Complaint: Track coming off Cause: Ground conditions were uneven and muddy causing track to come off Correction: Released track tensions, retracted adjuster, flipped track back onto machine. Identified in inspection that track frame and all undercarriage is worn and is a contributing factor to track coming off. Machine overheated hydraulics. Inspected hydraulic system overheating, put issue down to quick coupler failure causing a restriction,	9/07/2024	Hours

Asset	W/O No	Description	Finished	Done Reading
	17977	Minor repairs Check over A/C repair Check attachment functions Wash	17/06/2024	4680 Hours
	17978	Positrack - 250hr Service	14/06/2024	4680 Hours
	13216	Travel to site, diagnose fuel issues. Replace fuel level sender, gas door struts Replace cutting edge. Repair fuel gauge wiring. Drain, flush fuel tank. blow out fuel lines	1/05/2024	4670 Hours
	9503	Investigate and repair exhaust aftertreatment low voltage fault code. Repair operator door - not latching properly.	1/03/2024	4643 Hours
	3552	HME inspection & repairs Repair A/C fan not working Repair inoperative bucket quick hitch actuator Check final drive oils Check tracker operation & mount Clean cab & wash machine Diagnose & repair coolant leak Supply first aid kit Fit plant numbers, Thinksafe, QR, safety sticker & reflective tape Fit UHF back into cradle Re-fit R/H top panel in cab Re-seal L/H boom lift cyl. Re-seal R/H 4 in 1 bucket cylinder Remove belt guard & check belts & idlers Remove client stickers from L/H rear Repair lights, parkers, top L/H front & rear, tail lights Replace 2nd & 3rd rollers from the front on the R/H side & 4th one back on the L/H Replace both rear idlers Replace bucket cutting edge Replace cracked exhaust manifold Replace engine oil pressure sensor & top up oil Replace front door seal Replace nut on ignition barrel Replace pin/bush on live end of L & R bucket tilt cylinders Replace step at front of cab Test & stamp fire extinguisher Top up hyd. oil Top up washer bottle	2/02/2024	4630 Hours
	2406	Hyd leak issue	14/05/2023	