

Work Order History Report

Asset	W/O No	Description	Finished	Done Reading
AX347		Mitsubishi Fuso Bus		
	196765	Off Hire and repairs 14605 WAITING ON CABLE TO BE REPLACED (COMPLETED) 14575 ALL CONTROL/S SWITCHES OPERATIONAL FAILED - ARICON SWITCHES CABLE TO BE REPLACED (COMPLETED) 14575 ABS LIGHT (COMPLETED) 14575 CHIPS IN SCREEN (COMPLETED) 14575 CABLE TO SWITCHES (COMPLETED) 14575 SOMETHING LOOSE IN DRIVERS DOOR (COMPLETED) 14534 ALL CONTROLS / SWITCHES OPERATIONAL FAILED - AIRCON SWITCHES (COMPLETED) OFF HIRE AND REPAIRS (COMPLETED) - REPLACE T/C CONTROLS - REMOVE DASH REPLACE A/C CABLE NEXT DISH & TES OPERATION - REPLACE 2X REFLECTORS - COMPLETE ON WIRE	24/08/2026	KM
	196956	10,000km Bus service Odo: 263,000km - complete service as per checklist - replace steering ball joints & boots	1/07/2026	KM
	191869	FORCE BURN AND CHECK ENGINE LIGHT *Force burn/eng light *Plug scan tool into vehicle, verify codes for crank angle sensor, DPF *Drive vehicle + verify limp mode *Do force burn + drive no better *Order + replace crank sensor *Test drive crank sensor fault *DPF still full even after forced burn + long drive *Take vehicle to specialty shop for DPF "cleaning" *Replace battery fusebox *Remove front row seats + [illegible] box cover *R&R damaged fuse panel *Refit cover + seats	2/06/2026	KM
	59540	replace headlight globe and repair radiator fins *Replaced drivers side headlight bulb *Ordered new condensor	29/05/2026	KM

Asset	W/O No	Description	Finished	Done Reading
		*Straightened some of the finns on current condensor *Fit asset stickers - Recovered A/C - Replaced Condensor - Pressue test A/C system - Gas A/C - Look at ABS light on dash - Hook up scan tool - Test ABS system - Checked fuses & power supply - Found burnt/melted fuse box - Pull dash apart & look at A/C controls - Found bent demister cable - Order parts		
	191870	FORCE BURN AND CHECK ENGINE LIGHT	9/03/2026	KM
	59157	10,000km Bus service WON59157 Odo: 140,841km - carried out service as per checklist - no other faults found	20/11/2025	KM