

Work Order History Report

Asset	W/O No	Description	Finished	Done Reading
T0447		Toyota Coaster - 21 Seater		
	195032	August R&M - New tyre	16/09/2026	KM
	191432	HVIS Inspection - 6 Monthly. Booked in Dubbo 1/04 @ 1:55pm Replace stereo. Upgrade headlights	22/04/2026	KM
	57505	10,000km Bus service and exhaust manifold gasket, inspect for noise 120000km - carry out service and replace exhaust manifold gasket	20/02/2026	KM
	59679	HVIS Inspection - 6 Monthly. Booked in Dubbo 19/12 @ 8:20am	19/12/2025	124544 KM
	58087	October R & M Monthly WO USO: Take service truck over to MCO from OSO for ITS inspection	2/12/2025	KM
	54012	"No emergency triangles x2 For use site compliance 110834kms	9/04/2025	110834 KM
	53146	Capital - FFP for USO - go through site paper work and order all required parts. - jump start bus, charge and test batteries- failed, replace batteries and terminals. - fit mine flag. - diagnose and repair reverse camera inop, replace faulty camera with good second hand one. - make bracket for beacon to be mounted to triangle asset sign. - fit roof rack, fabricate bracket to fit raised taillights and asset triangle. wire up raised taillights and beacon, had to remove roof lining to do so. - replace uhf. - fit wheel nut indicators. - mount 9kg fire extinguisher. - remove and replace hi-vis tape and asset stickers. - take fulcrum photos. - weed and seed inside and outside. - finish off check list for USO and maas pre-hire paperwork. - fill with fuel and park on the go line.	7/04/2025	KM
	52224	Brownslip, check air con, windscreen washers. *Rego Check.	5/02/2025	110687 KM

Asset	W/O No	Description	Finished	Done Reading
		*Replaced number plate globes. *Hook up A/C gauges & test. *Finish 110,264km		
48761		replace batterys, clean and repair air conditioner. - carry out full inspection. - remove LHS steer hub, check for excessive free play. re-pack bearings and re-assemble. - replace 2nd axle shocks. - replace all worn steering joints. - replace spring eye bushes on 2nd axle. - replace RHS 2nd axle wheel cylinders as they were leaking. - found brake imbalance between left and right side. - test drive, drove fine but still had a bad imbalance when put over the brake tester. - tried adjusting load sensing valve, did not work. - removed hub, cleaned up shoes and drum. - test again, swap brake lines on valve to see if the problem moved, stayed on the same wheel. - removed hub again, check brakes shoes sat perfectly in the drum, had to file them to get them to match. tested again, no change. - order drum and shoes, replace them, still had 25% imbalance but passed brake test fine. - amber flashing bus lights inoperative. - found open circuit in harness, locate the break in the harness and repair. - replace on/off switch for lights. - test operation lhs not working, repair bad connection in light.	18/11/2024	110687 KM
12695		Full check over and repairs for site Faults: 8033 Reverse alarm Failed - Reverse alarm not working 08.08.2023 7907 Check all engine fluid levels and leaks Failed - Coolant level low 22.07.2023 7803 Tyres - Condition/wheel nuts (Visual inspection) Failed - No spare tyre 09.07.2023 7553 Battery security and condition Failed - Terrible starting when hot 11.06.2023 7549 Reverse camera (if fitted) Failed - Not working 10.06.2023 7540 Battery security and condition Failed - Battery getting slow to start 09.06.2023 7530 Reverse camera (if fitted) Failed - Not working 08.06.2023 4256 Tyres - Condition/wheel nuts (Visual inspection) Failed - Tyres bad 19.12.2022 4127 Middle Door does not shut - closing manually 28.04.23 10.12.2022 3746 Service Brake operation Failed - Brakes dont feel correct 24.11.2022 8500 Gear problem auto warning light 21.10.23 8500 Gear problem auto warning light 21.10.23 Checked for report of A/C not working. Foundcondenser damaged- blocked. Cleaned out as well as possible, but still not great. Have requested new parts. 8736 Front passenger tyre wearing had mechanic look at it and said it should be replaced shortly 27.11.23 8730 Middle door sticks hard to open 27.11.23 8722 Middle door will not open 27.11.23 8903 Tyres - Condition/wheel nuts (Visual inspection) Failed - Two rear tyres need replacing asap as worn. Spare tyre needs replacing asap. Workshop notified. 09.01.24	21/03/2024	KM
9047		A/C Repairs	25/01/2024	KM

Asset	W/O No	Description	Finished	Done Reading
	8503	Minor R&M: Remove stud and nut Machine Hours:	9/01/2024	KM
	8377	Repair AC system - replace hose Remove and replace leaking AC hose Clean Condensor, access and clean evaporator. Vac and gas system, test after AC repairs operation ok.	30/12/2023	KM
	7991	Replace 2 x tyres	15/12/2023	106870 KM
	7420	Minor R&M Monday 04.12.23 to Sunday 10.12.23 Access door wouldn't open. Loose bolt was catching on back of door. Tightened bolts, and adjusted latch. OK . Check fault with AC system. Cleaned condensor unit .needs further investigation.Ordered parts required to repair side access door. investigate coolant leak. found thermostat housing leaking. had to send vehicle back for end of day bus run. will have to continue tommorrow.Check over bus tyres and tyre pressures	26/11/2023	KM
	6937	Minor R&M Monday 06/11/23 to Sunday 12/11/23 Modify rear bumper bar to allow spare wheel tool to fit. JNS Diesel Contracting 31-10-23 Tested aircon, found condenser fins faulty Removed entire dual condenser assembly and replaced front condenser Cleaned second condenser Replaced both driers Vacced and held system Regassed system	9/11/2023	103171 KM
	3318	Check over Vehicle Worn ball joints on suspension in front end, Remove and Replace. Adjust Belts	23/10/2023	KM
	6338	Minor R&M Monday 16-10-22 to Sunday 22-10-23 Checked for report of A/C not working. Found condenser damaged- blocked. Cleaned out as well as possible, but still not great. Have requested new parts.	21/10/2023	KM
	2744	10,000km Bus service and repairs Replaced rear brake cylinders Diagnose A/C. Leaking gas. Top up. Diagnose and repair starting. Dodgy isolator install causing bad earth to starter. Repair. Km's:96225	29/06/2023	96225 KM
	4088	Pulled old idler bracket and replaced with new. Replaced seals, hub and kit. Replaced brake cylinder, rear both sides. Set and adjusted brake. Replaced brake shoe. Bled brakes. Got spare tyre.	21/06/2023	KM

Asset	W/O No	Description	Finished	Done Reading
		Reassembled bus. Test drove and checked.		
	4082	Collected bus from site, set up in shed and began disassembling. Checked rear brakes. Pulled wheels off and hub left and right-hand sides. Pulled related parts and accessories. Checked diff oil and transmission. Checked CV joint and drivelines. Checked suspension and lift spring. Greased fitting points and CV joint.	20/06/2023	KM
	2632	Parts only - Brake fluid	19/06/2023	KM
	3875	Checked off fault reports and order parts	4/06/2023	KM
	3743	Changed out POS 5 tyre/ POS 3	2/06/2023	KM
	2440	Get tooling for service truck	30/05/2023	KM
	2115	Pre-checks, check batteries, fit and paint new rear bumper	26/05/2023	KM
	3918	Topped up brake fluid and tested brakes.	5/05/2023	KM
	2367	Replace LHS rear inner	11/04/2023	KM
	986	Replaced u/s tyre and repaired beacon	5/03/2023	90783 KM
	484	Bash cover fell off installed with tie wire	19/02/2023	1 KM
	1205	Tie wire belly guard up as all hoses have spilt on plastic belly guard	3/02/2023	KM