

Work Order History Report

Asset	W/O No	Description	Finished	Done Reading
CB1367		Cat 730 ADT #4 (7304)		
	194932	Pump up Right Middle Tyre	26/08/2026	Hours
	194528	Blown hose	6/08/2026	Hours
	194500	POS 6 Tyre Leaking new o ring and valve core	6/08/2026	Hours
	192978	730#4 - Trans Oil Leak	1/05/2026	Hours
	192037	730#4 broken tail lamp, extinguisher out of date and door latch faulty	24/04/2026	Hours
	192335	730#4 oil leak Sean D	8/04/2026	Hours
	191927	2000 Hour earthmoving service - Done @ 23980	19/03/2026	23980 Hours
	191348	pos 5 replace tyre	3/03/2026	Hours
	190603	(730#4) Right steer tyre leaking air	28/01/2026	
	188151	Water leak, uhf not working - Water leak ok, mistaken for AC drain - Changed setting on UHF to correct channel - Refit cab mount pins, adjusted door latch	16/11/2025	
	186206	250 Hour Earthmoving service	2/09/2025	
	185952	Replaced diff lock pipe with hose	7/07/2025	
	185644	Replaced bonnet open/close switch	30/06/2025	
	182908	Replaced hydraulic tank o-ring Tightened transmission filter bolts Bolt/repair and tightened transmission bolts	24/02/2025	
	183210	Repaired transmission filter and replaced o-rings	31/01/2025	
	181804	500 Hour Earthmoving Service	23/01/2025	
	181630	Replaced tailgate mount bolts	13/12/2024	
	181431	Replaced Park brake hose	4/12/2024	

Asset	W/O No	Description	Finished	Done Reading
	181265	Pos#3 inflated	26/11/2024	
	181064	Replaced wiper head assembly	25/11/2024	
	181068	Replaced body raise hose	22/11/2024	
	180897	Re-attached LH hydraulic tank cover	15/11/2024	
	180409	250 Hour Earthmoving service	14/11/2024	
	179880	Seat air hose replaced	20/09/2024	
	179393	Transmission filter plate bolts repaired	12/09/2024	
	179535	Replaced exhaust clamps	11/09/2024	
	177204	500 Hour Earthmoving Service	20/07/2024	
	176757	Repaired body tailgate chain	31/05/2024	
	176424	Replaced exhaust flex	27/05/2024	
	176431	Replaced seat base and airlines	23/05/2024	
	175129	Repaired RH tailgate chain bracket	4/04/2024	
	174592	A/C = Inspected/OK	11/03/2024	
	174404	Windscreen wipers re-attached RH tyre, Air bag on seat, A/C Transmission light = Inspected/OK	8/03/2024	
	174127	Topped up oils and repaired engine oil leak Inflated Pos#1 tyre	26/02/2024	
	172598	250 Hour Earthmoving service	23/02/2024	
	172149	A/C filter replaced Inflated Pos#2 tyre	9/12/2023	
	171715	Replaced pulley and belt	23/11/2023	
	171468	Replaced hydraulic hose	14/11/2023	
	170793	Jump started and repaired lights	30/10/2023	
	170795	Jump started	27/10/2023	
	169953	Park brake adjusted	19/10/2023	
	168870	SEAT BELT REPLACEMENT	23/09/2023	

Asset	W/O No	Description	Finished	Done Reading
	168807	500 Hour Earthmoving Service	23/09/2023	
	168954	Replaced latching pressure sensor	22/09/2023	
	168635	A/C hoses and receiver dryer replaced Transmission = Inspected ok	26/08/2023	
	168549	Repaired hand rail	22/08/2023	
	164567	A/C hose ordered	19/08/2023	
	168563	LH front wheel replaced	17/08/2023	
	167845	Pos #4,5 tyres repaired/replaced - 11.07.2023 Pos#1,2 tyres replaced - 25.07.2023	25/07/2023	
	167551	Transmission neutralising = Inspected/OK	18/07/2023	
	176692	External Tyre Inspection	11/07/2023	
	164248	-Seat = Inspected/OK -UHF, mounts, co-ax plug replaced	6/07/2023	
	166625	Removed A/C gas and cab	24/05/2023	
	165799	E-stop repaired	23/05/2023	
	164838	LH Mirror replaced	20/04/2023	
	163853	250 Hour Earthmoving service	19/04/2023	
	164846	Pos#5 tyre inflated	19/04/2023	
	164434	LH steering cylinder o-ring replaced	13/04/2023	
	164444	Chain on hitch and hitch bolt = Inspected/OK	28/03/2023	
	163686	Replaced driveshaft seal and o-rings	24/02/2023	
	162517	2000 Hour earthmoving service	18/02/2023	
	162505	A frame re-installed as needed	2/02/2023	
	155600	Brakes dragging	16/01/2023	
	160587	R&R transmission and body lever assembly	13/12/2022	
	161230	Replaced LH hose	30/11/2022	

Asset	W/O No	Description	Finished	Done Reading
	161239	Replaced/Repaired #6 tyre as needed Loose wheel repaired/Replaced as needed	23/11/2022	
	160046	250 Hour Earthmoving service	15/11/2022	
	160243	Reverse camera system replaced	7/11/2022	
	159968	Seat and LHF shock pumped up as needed	24/10/2022	
	159017	Re-sealed hoses and replaced fitting on filter housing	4/10/2022	
	158669	Front A frame pin re-attached	21/09/2022	
	158742	Exhaust pipe and A/C vents replaced as needed	14/09/2022	
	149115	Seat bolts tightened	7/09/2022	
	158296	Front LH final drive re-sealed and bearings replaced	2/09/2022	
	158262	Timing case blanking plate o-ring replaced	17/08/2022	
	157692	UHF and GPS tracker wiring repaired	2/08/2022	
	156563	Fuses and wiring = Inspected/OK Re-connected steering solenoid	19/07/2022	
	156294	Flat left hand rear tyre Premiums pumped up tyre ok	12/07/2022	
	156414	-Re-gassed A/C -Replaced heater hose/taps/fittings	6/07/2022	
	154958	Sandblast and Re-spray as needed	5/07/2022	
	155395	Installed A/C and heater box parts as needed	9/06/2022	
	156241	Replaced O-ring Position#1 31.05.2022 Re-seated Oring - 02.06.2022	2/06/2022	
	144414	Cracked windscreen #replaced by freeman's glass GWithers	9/05/2022	
	153895	A/C = Parts ordered	27/04/2022	
	154328	Exhaust pipe repaired	21/04/2022	
	153337	500 Hour Earthmoving Service	13/04/2022	
	152992	A/C compressor, receiver dryer and fittings replaced	12/04/2022	
	153568	Tyres inflated	11/04/2022	

Asset	W/O No	Description	Finished	Done Reading
	153736	Flashing light = Inspected/OK	6/04/2022	
	153010	Rear tyres pumped up	15/03/2022	
	153373	UHF cable re-routed as needed	14/03/2022	
	152613	Replaced tyre O-ring position #2	18/02/2022	
	151780	Replaced water pump, E-stop, fan motor and solenoid, sump gasket, exhaust tip and top elbow Repaired wiring harness, modified mounts for tail gate arms, radiator leak Re-sealed RH steering cylinder	8/02/2022	
	150747	LH middle tyre has pumped up	3/02/2022	
	150796	Wipers repaired as needed	18/01/2022	
	150975	A/C = Inspected/OK Exhaust leak = Parts ordered	14/01/2022	
	150938	Tyre down on pressure pumped up pos 4	11/01/2022	
	150689	A/C inspected and receiver dryer replaced	15/12/2021	
	150737	Exhaust fumes in cab, puncture RHF tyre Pkws to call Premium tyre's for repair Check exhaust for leaks found loose pipe under cab tightened and adjusted test-ok Reeve F	14/12/2021	
	150753	Hard suspension front struts adjusted to high, lowered and tested-ok Reeve F	8/12/2021	
	158746	=WO#49963 Replaced diff lock fuse	25/11/2021	
	158387	WO#49963 = Replaced diff lock fuse = OK	25/11/2021	
	149963	6 Wheel drive not working	25/11/2021	
	149261	250 Hour Earthmoving service	17/11/2021	
	149292	UHF not sending very far Replaced end of cable needs new cable and antenna, fitted new cable and antenna Sealed around wind screen stop rain Reeve F	5/11/2021	
	148218	Air cond leaks water under dash leaking onto floor(slip hazard) Found water coming A/C drain as it was blocked unblocked and blew out lines-ok Reeve F	4/11/2021	
	144800	500 Hour Earthmoving Service	16/08/2021	

Asset	W/O No	Description	Finished	Done Reading
	145567	Lost rev. & 2nd gear Watched shift sol. percentages while test driving. Swapped out solenoids to test. Still same problem. Removed tranny screen & filter. Found full of metal. Machine taken back to w/shop for repairs. Repaired transmission at PKWS (see all attachments)	16/08/2021	
	146532	Tyre air leak pos 5 Premium tyre's(see attachment)	12/08/2021	
	145622	A/C not cold or blowing. A/C sheet 2032 Topped up gas. Machine may have leak & could need further testing when machine is available. operator to test & report. A/C sheet 2034 Recovered gas. Pressure test system - leaks from high side valve & hose-comp. to cond. Repl. valve & hose. Re-test Ok.	7/07/2021	
	145506	Operator reports Top up eng. oil. Pumped up L/H/F tyre.	28/06/2021	
	144777	Check over truck after back off edge, bushes in rear sway bar worn cause more rear end tilt Rear sway bar Fitted new rear sway bar and new rear suspension blocks(ordered new for front) Reeve F, C Buck	17/06/2021	
	144786	Reverse light not working, gear changes erratic, oil leaks Check revers light-broken ordered new one, check trans oil, check fault codes need more info for codes at later date Reeve F	9/06/2021	
	144193	A/C not cold, \$ back tyre's are marginal, Handrail falling off Removed handrail and took to PKWS for repair, refitted repaired handrail Topped up A/C gas cleaned out and sealed evaporator box, repaired internal door linkage rear tyre's inspected and reported to supervisor Reeve F	3/06/2021	
	144226	Oil leak Replaced blown brake hose on rear Reeve F	3/06/2021	
	143894	No driveshaft Fitted driveshaft from 730 #3, Tested-good Reeve F	25/05/2021	
	143635	Coolant leak Tightened hose clamp, topped up coolant, got engine hot and rechecked-no leak, topped up transmission oil Pumped up LHF tyre, secured panel Reeve F	17/05/2021	
	143197	Flat tyre Pumped up front left and rear tyre's up C Buck	3/05/2021	

Asset	W/O No	Description	Finished	Done Reading
	143113	Fire extinguisher out of date replace fire extinguisher	30/04/2021	
	140901	250 Hour Earthmoving service	11/03/2021	
	139984	needs radiator cap Fitted new radiator cap Reeve F	19/02/2021	
	138657	no power to uhf and cab Uhf working ok now Reeve F	19/02/2021	
	138400	LH rear indicator not working, cracked front windscreen, No cracks in windscreen at inspection. Replaced LHR indicator globe Reeve F	19/02/2021	
	140382	Reverse camera not working Tested wire's replaced whole reverse camera system, set up new camera Brad C	16/02/2021	
	140445	Flat tyre Strip tyre and fit patch pos 6 Premium tyre's(see attach)	22/01/2021	
	139764	Flat tyre middle RHS Pumped up tyre to 75psi Blake R	5/01/2021	
	139763	2 x flat tyre's rear LHS Inflated both tyre's Blake R	19/12/2020	
	139721	Tyre repair Replace o-ring pos 1 Premium tyre's	10/12/2020	
	138969	Initial Plant Safety Audit	8/12/2020	
	138483	Park brake u/s R&R park brake assembly, fit new pads & actuator, check park brake release pressure 3000psi @ idle Complete park brake hold test as per manufacturers specifications OK B Wise	26/11/2020	
	138488	Drive shaft u/s RNR drive shaft in articulation to drop box Blake	19/11/2020	
	138157	500 Hour Earthmoving Service	19/11/2020	

Asset	W/O No	Description	Finished	Done Reading
	136514	Fire extinguisher out of date,some light out on front and brake lights out, No Nuetral start Replaced RHF light and parker globe, replaced light wiring, replaced fire extinguisher Further diagnosis on neutral start problem needed Reeve F Neutral start not working Remove after market wiring put back to original, test original wiring, start ok Ben P	9/11/2020	
	137763	Park brake problem, coolant leak Checked park brake solenoid for power-good,park brake operating but slow to come on, cleaned out orifice, check valve, solenoid actuator valve and all fittings on brake release valve Checked release pressure 3000psi-in spec, need to get longer gauge hose and check if pressure dropping off when driving replaced blown coolant hose, filled and tested, Reeve F	3/11/2020	
	136496	No fm radio Fitted new stereo Reeve F	14/10/2020	
	137236	Handrail broken Fixed cracked handrail C Buck	1/10/2020	
	138968	closed by accident = Does not effect schedule Last done 19.09.2020	19/09/2020	
	136312	Wont start,re-occurring problem Ran new pin/wiring to key switch retested all OK,fitted new reverse camera bracket(see attachment) Reeve F	16/09/2020	
	135704	Damage to L/H front guard,dump lever in two pieces,reverse camera holder broken, UHF radio wire snapped,camera reverse Fit new lever Started test for starter problem but stopped happening will look when re-occurs Reeve F	8/09/2020	
	135644	UHF not working Replaced UHF connector wiring(power to earth)Tested good needs hand lever for tub Reeve F	31/08/2020	
	135166	250 Hour Earthmoving service	20/08/2020	
	133277	2000 Hour earthmoving service	29/06/2020	
	133245	SHUTS DOWN,Wont start Found fuel primer had broken in half,removed and replaced hand primer Ryan L	22/06/2020	
	133425	Playing up Put computer on nothing wrong C Buck	19/06/2020	

Asset	W/O No	Description	Finished	Done Reading
	132249	Wont charge battery Replaced alternator & Belts C Buck	19/05/2020	
	131584	Wont start Fuse in box-removed ether start fuse and replaced,truck started Needs further diagnosing & wiring diagram back at w/shop and come back to truck R Farquhar	6/05/2020	
	131508	No windscreen wiper Replaced wiper arm C Buck	29/04/2020	
	131536	Wont start Check e-stop.check fuses,check start on spray would run no fuel checked fuel filters fuel/water seperator low as fuel,topped up and primed,machine ran,turned off and restarted to test OK R Farquhar	27/04/2020	
	130990	wont start Engine ECM disabled,R&R fuel filters prime system,tamper with ECM wires Clean out fuse panel,started OK B Patrick	23/04/2020	
	131228	Eng. wont start-kranks OK Check E-stops OK,Check with E.T-no eng,speed signal Crank Eng. again-speed signal present & truck started,repeatedly started after that G Windle	21/04/2020	
	130761	Wont start R&R 1x fuel filter,prime system and start B Wise	15/04/2020	
	130552	250 Hour Earthmoving service	9/04/2020	
	130294	Tyre repair pos 1 premium tyres	25/03/2020	
	129798	Not starting Checked all E-stops and resset them Bled air from fuel filter engine started #needs new hoist lever knob Reeve	14/03/2020	
	129591	Oil leaks R&R all seals in hyd fan motor ass.R&R stock RHS lift ram ass. Wash machine check warning devices & oil levels B Wise	4/03/2020	
	129231	wont shut down by key Removed and replacede key barrel	2/03/2020	

Asset	W/O No	Description	Finished	Done Reading
		R Latham		
	128394	No A/C Check air cond operation ok	4/02/2020	
	127867	Oil leak Replaced oring on steering hose C Buck	20/01/2020	
	127330	blown hose Dropped belly guards and replaced blown hose R Latham	19/12/2019	
	127255	Check hitch Inspect hitch nut/retainer B Patrick	13/12/2019	
	126945	500 Hour Earthmoving Service	6/12/2019	
	124147	Wont start Was sent to wrong truck 740 #4 originally not 730#4 R Latham	19/11/2019	
	127180	Oil leak Replace oring on steer cylinder B Patrick	19/11/2019	
	126608	Engine oil leak Filler cap came out of engine,refilled engine oil level ok B Wise	18/11/2019	
	126481	bonnet wont open Removed and replaced switch for bonnet R Latham	14/11/2019	
	126309	Wont start Had no power going to engine computer,looked for broken wires none were found cleaned plugs and got power back R Latham	6/11/2019	
	125307	Flat tyre Pumped front left tyre up Body pins need machining (1mm/2mm gap) C Buck	26/09/2019	
	125007	250 Hour Earthmoving service	23/09/2019	
	124106	Wont start has been jump started 3 times Install 2x new batteries,test charge ok Ben Patrick	28/08/2019	

Asset	W/O No	Description	Finished	Done Reading
	124054	wont start,flat battery Jump started Glen Windle	26/08/2019	
	123975	WONT START Truck winds over but will not fire,check e-stops,check E.T could not read ECM for engine,test battery power to ECM ok test earths Found blown diff lock mirror heater fuse blown,replace fuse and truck started & run,check operation of truck test Ben Patrick	21/08/2019	
	123779	Seat U/S,large rock jammed under seat all the wiring,repared wiring & compressor hose seat pump working ok Brad Wise	13/08/2019	
	123767	Truck inspection Check all diff cross braces,mounts,suspension,bushes/blocks ok within manufacturers specs @time of inspection. Check steering operation, bushes ok Brad Wise	8/08/2019	
	123771	Wont start Jump started ,charging fine Cameron Buck	6/08/2019	
	123461	500 Hour Earthmoving Service	5/08/2019	
	123164	Wont start jump started,key was left on Cameron Buck	9/07/2019	
	121649	250 Hour Earthmoving service	29/05/2019	
	121691	A/C COLD BUT NOT BLOWING CHANGE AIR CON FILTERS	24/05/2019	
	121581	brake line leaking replace center axle LH front caliper brake pipe bleed brake LH center perform brake test Ben Patrick	15/05/2019	
	120885	Seat wont stay up Replaced air valve on seat adjuster as it was leaking Cameron Buck	29/04/2019	
	120845		12/04/2019	
	119745	left hand front tyre going flat Called premiums	28/03/2019	
	119645	500 Hour Earthmoving Service	6/03/2019	

Asset	W/O No	Description	Finished	Done Reading
	118902	Front tyre flat Pumped up tyre to 65PSI	16/01/2019	
	118732	Exhaust leak Replaced exhaust pipe going to the muffler and replaced both clamps	18/12/2018	
	118555	Park brake stuck off Steering column wont move Ordered a new park brake switch Adjusted cable going to steering column strut	6/12/2018	
	118181	Park brake slow to engage Remove and clean around shaft Spray up shaft still tight need to replace switch	22/11/2018	
	117578	250 Hour Earthmoving service	21/11/2018	
	117602	left hand mirror shaking Tighten side mirror	7/11/2018	
	116711	front left tyre has a hole in it Called premiums	2/10/2018	
	116884	Fit new brake light switch	25/09/2018	
	116734	needs fire extinguisher out of date Fit in date fire extinguisher	24/09/2018	
	116726	Fit new secondary speed sensor and test with ET Delete old codes OK	17/09/2018	
	116503	Repair oil leak at trans Tighten loose door latch Repair oil leak at fan pipes	7/09/2018	
	113558	2000 Hour earthmoving service	30/07/2018	
	113993	Hyd leak under cabin Installed new LH front brake pipe	14/06/2018	
	116149	Check for leaks found front LH brake line leaking order new one block off brake line to prevent leakage	13/06/2018	
	110548	Rear A frame fallen out reported to workshop for further inspection	4/06/2018	

Asset	W/O No Description	Finished	Done Reading
	116096 Remove and replace starter motor	31/05/2018	
	112840 Pre release check sheet Replaced rear equalizer are bushes replaced broken mirror re sealed leaking final drive RH middle axle or "pos 4" Replaced drives seat belt holster	10/04/2018	
	112275 500 Hour Earthmoving Service	27/03/2018	
	111916 Pre-release check sheet. Remove water tank. Removed water tank and sprays. Fitted all lift ram hoses and change solenoid back over.	4/02/2018	
	110857 250 Hour Earthmoving service	3/01/2018	
	111792 oil leak. Fit new inline fittings for water pump. Hyd lines in hitch area.	21/12/2017	
	110272 No air cond, put gauges on no gas present in system. Inspect hoses/ connectors found 2x leaking hoses at rear of cab remove hoses to be made/ordered, remove quick connectors at receiver/dryer clean re-install, re-make hoses, install using new orings, install new receiver/dryer, pressure test system to 350 psi, vac down, install 15mL of oil re-charge system.	16/12/2017	
	111720 Air cond not working. Check gas pressure in system not pressure found, check hoses/connection found 2x hoses leaking to condenser, remove hoses, need to be replaced, remove & clean quick connectors at dryer, check fan operation	16/12/2017	
	111796 Down on power, water spray weak. #1 cylinder injector u/s, fit CAT reman # injector a/s, clean & inspect inlet for water pump in body, fit 3 valve & spray & new HRC130 rubber, blow out a/c condenser.	28/11/2017	
	116486 Checked out and cleaned out evaporator and blew out tested a lil better	23/11/2017	
	112834 Pre release check list Put water tank in truck body Fabbbed up spray bar 2 new rear brake line	21/11/2017	
	110066 Seat down on one side Install new seat pan and cushion assembly	13/11/2017	
	109768 LH rear wheel leaking	13/11/2017	
	109092 500 Hour Earthmoving Service	12/10/2017	
	109116 Change fan belt and pulley	12/09/2017	

Asset	W/O No	Description	Finished	Done Reading
		cover on engine with new one		
	108561	Checked out all lights replaced globes all functional working and A/C cold	30/08/2017	
	108341	Left hand body cylinder leaking replace left hand body lift cylinder with stock one	9/08/2017	
	106360	250 Hour Earthmoving service	17/07/2017	
	106338	Water leaking Replace hose clamps	10/07/2017	
	105297	Trans light flashing	8/05/2017	
	107841	Oil leak Repair 2 x hydraulic oil leaks, tested OK	20/04/2017	
	104749	Bonnet actuator U/S#Fit new accuator and relay	13/02/2017	
	103858	500 Hour Earthmoving Service	1/02/2017	
	102150	250 Hour Earthmoving service	12/10/2016	
	102034	Replaced reverse camera	13/09/2016	
	101341	500 Hour Earthmoving Service	9/08/2016	
	100066	250 Hour Earthmoving service	20/05/2016	
	108809	Replace wheel guard trap door shape panel to trap door dimensions cut hinge to suit and drill holes rivet new door hinge to the main frame paint any work	22/03/2016	