

Work Order History Report

Asset	W/O No	Description	Finished	Done Reading
P0689		CAT D6T Dozer (GPS)		
	193436	Pre hire repairs as per HME inspection, W/O 192544 - Mount am/fm radio - Grease machine - Replace slides in seat - Check GPS - Unblock rear window washer - Fix mex prestart stickers - Diagnose intake sensor code, found broken wire in harness - Fit ripper bolts - Repair & fit wiring harness - Remove belly guards - Reseal ripper cylinder	2/07/2026	11144 Hours
	54959	CMC Lake Cowal, Pre hire repairs and fit for purpose. Pre hire repairs as per HME inspection. w/o 54730 Install fire suppression system. * Loose bolts push arm to blade - Both sides ordered * Horn button missing - Ordered * Bolt down GPS unit on cab * Remove broken bolts on GPS mount for blade sensor - underneath pole, fit & test * Heater tap RHS near turbo replace * Reseal RH cannon key retainer plate	29/05/2026	
	192544	HME Inspection - Bulldozer Quote #:	13/04/2026	11142 Hours
	191555	March Monthly WO: * Diagnose hydraulic leak * Pull 2x hose to gain access, replace o-ring, put back together * Fill hyd Diagnose where hydraulic leak coming from had to pull out seat, floor pans in order to access hose pull x2 hose to gain access, replace oring, put back together, fill hyd up - run up Diagnose and repair oil leak and top up oil Diagnose/repair oil leak under floor Start pulling steer motor hoses out Pull off steer motor hoses ready for new ones but realised I order the wrong size clamp Finish pulling steer motor hoses off ready for new ones and drop belly pans Replace steer motor hoses and pilot pressure hose, put everything back together, test run, pull back off hell hose cover check for leaks then re-fit	26/03/2026	Hours
	60492	Pre Hire Repairs as per WO 60458	6/02/2026	11088 Hours

Asset	W/O No	Description	Finished	Done Reading
		11088hrs - check oil levels, run up and test machine for oil leaks. Remove floor panels. No leaks found residual oil in belly guards from previous blown hose - wash machine and re-install floor panels - remove/replace light mounting rubbers - clean cabin/blow out		
	60458	Offhire A1 fires Inspect oil leak, repair minor orfs o ring link. Remove/replace RHS light mounting rubbers, tension fan belts 11088hrs Fit GPS to machine	5/02/2026	Hours
	60297	R&M Monthly January Find oil, travel to site, diagnose and repair oil leaks. Put seat base and seat back in, put flooring and floor mat back in Plant shut down on side of hill, blown o-ring and loose hose and lost all hydraulic oil, replaced o-ring and tighten hose and fill with oil and move off hill	27/01/2026	Hours
	59888	Prehire repairs as per WO59823 Remove UHF and stereo antenea, repair front grill and test GPS Tap out grill treads and helicoil, bolt front grill Remove stereo antena and UHF aerial, start repairing front grill, test GPS system fault Repair front grill broken bolts Diagnose/repair GPS system fault Refit grill after repairs Replace UHF antenna Install stereo antenna, assemble cab, on hire Install new UHF antenna Assemble cab	23/01/2026	Hours
	59823	Offhire Licoln place Builders	18/12/2025	Hours
	59770	December R&M Monthly WO: - battery cable and accessories at Lincoln place 11/12 Diagnose machine no start, wiring burnt out, high resistance in wires. Remove starter isolater and re-wire main isolator. Repair electrical wiring in battery box Clean out battery box - build up of dirt. Repair E-stop wiring. Repair wire to ECM and test. Test operation after repairs.	18/12/2025	Hours
	59544	Pre hire repairs as per WO 59470 11071hrs	9/12/2025	Hours
	58190	October R&M -Seat collapsed 08.10.2025	2/12/2025	Hours

Asset	W/O No	Description	Finished	Done Reading
	59447	Oil leak at Elong fire 28.11.2025 Replace blown hose	2/12/2025	Hours
	59470	Offhire Elong 11071	1/12/2025	11071 Hours
	59277	Fit guards, diagnose/repair hydraulic leak, carry out on hire inspection	21/11/2025	Hours
	59117	November R&M Monthly WO: - travel to Lue station for breakdown Shut down, check fuses and circuit breaker everything tested fine, still no cab power, remove battery to get fuse panel out, put all back together, dozer started, had operator to rattle dozer around to work it, to see if fault came back, which it did not, return to workshop pack away tooling, wash ute Remove, re-seal and refit tilt cylinder, finish last part of service 11029hr Remove strip inspect blade tilt cylinder, reseal cylinder fit back to machine, pump up hoses. Remove pos 4 and 5 load rollers LH, remove broken roller cap bolts, fit new rollers, remove seat and repair, put seat slide blocks onto base, re-install seat. Drop all belly plates and clean refit belly plates Complete repairs, clean work area, scrap out rollers and bolts	20/11/2025	Hours
	58702	P0689 - Bulldozer - 1000hr Service 11029hrs	18/11/2025	11029 Hours
	58918	GET - Ripper tips	5/11/2025	Hours
	58703	OFF HIRE INSPECTION 11005hrs	4/11/2025	Hours
	56803	August Monthly R&M Re-gas A/C. 10881hrs -- repair fire supp fault - Remove mast from dozer - Fit new bolts & tighten	3/11/2025	Hours
	57880	Off hire/Pre hire repairs Bonnet loose Rhs door hinges missing bolts Bolt holes damaged Hose intake - exhaust damaged replace Tilt cyl bolt guard bent needs replacing	26/09/2025	Hours

Asset	W/O No	Description	Finished	Done Reading
	57298	September R&M Remove tilt hose - leaking Broke tranny screen bolts - Removed bolts Get hyd hose made, refit to machine	3/09/2025	Hours
	56459	July Monthly R&M - Lake Cowal Remove broken bolts from GPS. Pole mount, refit GPS Pole with new bolts	27/07/2025	Hours
	54730	HME Inspection - Bulldozer Quote #: 362 *Finish 10,855hrs *	8/05/2025	10855 Hours
	15401	Replace Floor mat	1/05/2024	
	11167	Inspection	24/04/2024	10851 Hours
	8775	* Blown hydraulic hose on tilt ram * Blade re-skin, remove & replace wear skin * Cutting edges change out * GPS pole fell off. Repair base of it & remount to blade.	11/02/2024	10844 Hours
	8330	Bulldozer - 250hr Service Found hose steering valve was leaking. Replaced Oring and refitted seat and floor. Replace wiper blade front & rear. Tightened push arm to blade bolts. Tested UHF tightened antenna cable	18/01/2024	10841 Hours
	8614	Grease & Mechanical Checks Reverse squawker not working - repair broken wire at unit. Mount GPS pole back on machine due to broken missing bolts. Found oil leak from oil under machine - hose o-ring on pump in hell hole leaking. Disassembled cab to access hose replace o-ring, confirmed leak and stopped. Put back together and sent back to work.	10/01/2024	10820 Hours
	8403	Check and adjust track tension on both sides of machine. Inspect reported UHF fault. Power seems to be cutting in and out intermittently. Diagnose radio, antenna unplugged and loose connection on power circuit. Checked fluids topped up coolant.	6/01/2024	10807 Hours
	8322	Attend machine, and tension tracks as requested. Checked for report of engine getting hot. Cleaned out air filters. Checked cooling pack- all OK. Seems to be OK now. Machine still overheating. Fitted new air filter and cleaned out cooler pack. Working OK now. Diagnose hydraulic Leak for steering	27/12/2023	10735 Hours
	8177	Carried out pre-shift check over	17/12/2023	10651 Hours
	7756	Daily machine and GET inspections	5/12/2023	10571 Hours
	7683	Daily machine checks. Grease machine Cleaned out RH track area. Pump track tension up correctly and record measurement.	1/12/2023	10560 Hours

Asset	W/O No	Description	Finished	Done Reading
	7419	Carried out mechanical checks. Cleaned out all filters. Fitted new exhaust stack.	23/11/2023	10541 Hours
	7202	Carried out daily plant inspection as required. UHF not working. Picked up new voltage reducer. Fitted as required and tested - all OK.	19/11/2023	10530 Hours
	7244	Remove and replace GET as required.	18/11/2023	10530 Hours
	6930	Bulldozer - 500hr Service	17/11/2023	10525 Hours
	6925	Adjust seat and rescue Assist with hydraulic leak. order required parts Check fault code on machine. Coming up with high air filter restriction code. Cleaned air filter and sent back to work. Inspect oil leak. Remove belly gaurd and floor to investigate where leak is coming from. Remove hydraulic hose and swash plate from Aux pump. replace O rings and re assemble. refit cab floor and belly guards.	11/11/2023	10465 Hours
	6741	Attempt to refit draft arm. Found bolts to be incorrect. Check over machine and clean air filter Re-fir LHS draft arm assembly. replace broken bolts and re-shim as required	5/11/2023	10456 Hours
	6431	LH draught arm came off. Bolts loose. Trunion damaged. Got bolts locally to get machine going. Genuine parts, including shims, have been ordered. Oil leak at tilt cylinder. Beed dodged up. Leaking from where only half the flange clamp had been fitted. Hose previously repairs, badly. Removed hose. Picked up new hose from Curry. returned to site and fitted, with new clamps. Refitted and secured hose guard- bolts also missing from guard. Topped up hydraulic oil- All OK	25/10/2023	10401 Hours
	6012	Adjust fan belt, refit belly plate and fit new GPS antenna Carried out machine check over after repairs had been carried out. Continue with hydraulic pump removal Continue with rework. Checked A/C operation. Bolt broken in A/C filter cover- could not remove. Cleaned out blocked evaporator. Resealed A/C box. Engine cover bracket not fitted properly- rectified. Reset all engine intake hoses and clamps. Drain hydraulic oil and drop belly plate Drain overfull transmission oil and top up hydraulic level Finish plumbing hydraulics. Fill with hydraulic oil. Bleed pumps. Test run. Refit belly plates. Fit steering pump. Changed o'ring seals, and new front seal. Investigate possible oil trasnfer from Hydraulic tank to convertor. Mount GPS bracket and check operation Refitted implement pump, and plumbed. Remove cab floor, seat. Check all hydraulic hoses are correct. Start removing hydraulic pump. Remove convertor driveshaft to inspect oil leak Repair fan shroud- fit missing bolts. Check over and tightened heater hose clamps, and refitted P clamps where required. Repaired and refitted side panels. Realigned and secured air intake pipe. Check/top up oils as required. Run and test machine. Replace blown hydraulic hose Rework- Hose clamps not correctly into implement valve bank. Bolts damaged. O-ring blew out. Fitted new o-ring, and refitted line and clamps with new bolts. Topped up hydraulic oil- all OK for now.	24/10/2023	10400 Hours
	5899	Dropped belly gaurd to investigate oil leak Hydraulic hose leak, difficult hose to remove Replace lower radiator hose. Repair engine oil leak. replace blown o ring on cooler pack.	8/10/2023	10372 Hours

Asset	W/O No	Description	Finished	Done Reading
	2783	Capital Works - Rebuild engine. Blade repairs. Pre hire repairs. Remove engine @ JNS, send to Dubbo - rebuild and return to JNS. Rebuild Engine Rebuild Torque Convertor Repairs to blade & push arms, Re-bush linkages Reskin blade & fit wear package. Replace hydraulic hoses in chassis while engine/torque convertor out Reseal lift cylinders and overhaul lift cylinder yokes Rebush nose cone Belly plates- fit correctly Tilt cylinder- reassemble and fit Corner tips- rotate and fit correctly GPS bracket- repair Radiator guard- repair mount Starter isolator- replace AM/FM radio- repair GPS antennas- refit and secure Ripper cylinder hoses- replace Hydraulic suction hose- replace Hand-rail- repair Clean out cabin	2/10/2023	10366 Hours
	3904	D6 Dozer engine stand fabrication	2/07/2023	
	4083	Removed belly guards. Cleaned belly plates. Made pressure cleaner hose extension. Degreased and washed around engine and transmission. Tagged out machine. Set up board under machine, drained sump, removed brakers. Removed sump bolts and oil pick up tube. Removed sump. Inspected bottom end. Found #2 piston crown to skirt bush to have failed, showed Sean. Put sump back up with four bolts to keep dust out. Looked at parts list.	20/06/2023	
	4022	Rotate corner tips for demob	14/06/2023	
	4018	Reassemble after valve set	11/06/2023	
	4016	Reassemble after valve set	11/06/2023	
	2788	Continue looking for fault	30/05/2023	
	2786	Remove intake and exhaust to gain better access. Talk to Scott and Sean.	29/05/2023	
	2170	Remove tappet cover to try and get photos	27/05/2023	

Asset	W/O No	Description	Finished	Done Reading	
	2160	Move machine out of the way. Remove oil filter cut open send photos to Sean	25/05/2023		
	2159	Assess engine rattle, removed rocker cover. Checked top end - look ok, possible cam hard face or lifter failure	22/05/2023		
	3945	Fitted new muffler for exhaust	13/05/2023	10303	Hours
	2302	Carried out repairs to machine fitting new exhaust system to engine	13/05/2023		
	2396	Make profile for new skin to be pressed	11/05/2023		
	3925	Replaced draft arm bolt as bolt had fallen out	6/05/2023		
	1888	Refit new draft arm bolt	6/05/2023		
	755	Inspect broken exhaust stack Remove muffler & refit pipe	2/05/2023	10090	Hours
	1123	250hr service	1/05/2023		
	1085	250hr service	1/05/2023		
	756	Inspect loose exhaust and tighten stack. Inspect and rectify no power to UHF.	29/04/2023	10090	Hours
	705	Inspection. Replace locking pin on push arm. Straighten ears & refit pin	11/04/2023	10090	Hours
	6019	track group replacement ITR track groups fitted with discount as the previous chains only did 2000hrs.	5/04/2023	10090	Hours
	676	Carried out repairs to machine removed both sets of old tracks and fitted 2 new sets of tracks and tested machine - all ok.	5/04/2023	10090	Hours
	720	Weld up tilt ram fitting	3/04/2023	10090	Hours
	672	Carried out repairs to machine, damaged hyd fitting was repaired by welding it and a new one is on order	3/04/2023	10084	Hours
	2345	Fitted side panel as bolt snapped	19/03/2023		
	804	Inspect & repair split oring on cylinder lines	18/03/2023	10084	Hours
	801	Fill coolant and hydraulic oil. Connect grease lines. Grease EQ bar. Test operate & check for leaks. Bolt up belly plates.	17/03/2023	10084	Hours
	599	Carried out repairs to machine refitting repaired radiator.	16/03/2023	9980	Hours
	799	Press new bushes into nose cone. Prep unit to refit cone. Fit all new pins, connect hoses, mount brackets, shroud, grill.	16/03/2023	1	Hours
	856	Strip nose cone. Press seized pins out. Remove lift cylinders and inspect bushes. Replace tilt cylinder valve block. Clean up parts.	15/03/2023	1	Hours
	902	Tried to remove nose cone - one pin stuck may need lancing otherwise it is ready to come off.	14/03/2023	9978	Hours
	798	Prep for nose cone pm & bush replacement. Remove bonnet, hoses, harness, drain coolant, belly guards, lift cylinders	14/03/2023	1	Hours

Asset	W/O No	Description	Finished	Done Reading	
	874	Help to remove nose cone on D6 to do bushes. Blow bolts on belly guards, drive loader to remove parts.	14/03/2023		
	899	Remove EQ bar end are worn bushes loose - reassemble	13/03/2023		
	873	Remove broken bolts in belly guards	13/03/2023		
	770	Replace hydraulic cooler. Degrease and pressure wash cooler pack	12/03/2023	1	Hours
	992	Repair coolant system after overheating	7/03/2023	9971	Hours
	994	Remove heater tank and repair cracks - pressure test and put back together	7/03/2023		
	936	Coolant leak fault find - broken bolts on GPS pole. Remove GPS and weld nuts onto GPS pole bracket.	5/03/2023		
	979	Repair loose engine cover	3/03/2023	9943	Hours
	975	1000hr service	2/03/2023	9939	Hours
	913	GPS pole repairs - crack in bucket New bolts - removed snapped bolt in housing	2/03/2023		
	908	Blade works chockie bars & crack repairs	1/03/2023		
	962	Check why engine light is on - will need to go over it on wednesday service day.	27/02/2023	9923	Hours
	954	Top up hyd oil	25/02/2023	9904	Hours
	946	replace broken hose at tilt cyl fitting - broken from rock strike Rock guards need modification	24/02/2023	9904	Hours