

Work Order History Report

Asset	W/O No	Description	Finished	Done Reading
CB1232		Cat D8R Dozer #5 (D85)		
	194944	Replace coolant hose - Wash machine	31/08/2026	Hours
	194671	Low engine oil check tracks. Replace cracked sump	26/08/2026	Hours
	195051	Remove GPS	24/08/2026	Hours
	194539	500 Hour Earthmoving Service Done No longer on site 21/09/26	27/07/2026	Hours
	194418	Order sump D/F Roller us	24/07/2026	Hours
	194030	C/O cutting edges	16/07/2026	Hours
	193307	(PlantHire BlueScope) order air filters	19/06/2026	Hours
	193337	D8#5 Replace shin guard and ripper boot	20/05/2026	Hours
	191925	250 Hour Earthmoving service done @ 21000hrs order air filters	23/04/2026	21000 Hours
	192419	Repair engine guard	8/04/2026	Hours
	60916	D8#5 fit GPS screen pole cables	18/02/2026	Hours
	60466	Check over machine, remove GPS pole, repaired fuel leak	16/02/2026	Hours
	190031	Fire Extinguisher - Tag fire extinguisher as required - Fit UHF antenna - Tighten cab strikers	18/12/2025	

Asset	W/O No	Description	Finished	Done Reading
	189984	Dig clay out of track frames ready for transport	17/12/2025	
	189425	ECM Issue, Derate and cutting out - Found JPS & disconnected from machine 3/12 - Comm's issue data link - 4/12 - Removed ECM dropped off at westrac - 12/12 - Fitted new ECM	10/12/2025	
	189372	Brake warning light on dash - Adjust service brake position sw test OK	26/11/2025	
	189357	A/C not cold CONT. - Fuse blowing (A/C fans) further investigation required - Repaired wiring at A/C fan test OK	26/11/2025	
	188678	Data link fault - Inspected and tested harness - Repaired wire on transmission	24/10/2025	
	188655	Coolant flow switch - Replaced	21/10/2025	
	188449	Tested Engine ECU Continued - Repaired ECU Connector - Tested machine	21/10/2025	
	188630	Derate - Checked harness - Found broken ECU connector	18/10/2025	
	181586	A/C KEEPS ON ICING UP - Unblock AC drain hoses to stop icing up test ok	17/10/2025	
	187420	Machine cutting out = Inspected/OK Replaced batteries	30/09/2025	
	187545	Repaired reverse alarm and LH wiper wiring and lights	19/09/2025	
	185482	2000 Hour earthmoving service	18/09/2025	

Asset	W/O No	Description	Finished	Done Reading
	183364	Replaced coolant bleeder hose	25/03/2025	
	183363	Hydraulic oil hose replaced	22/03/2025	
	182745	250 Hour Earthmoving service	12/03/2025	
	183219	Replaced main battery relay and repaired wiring in fuse panel	13/02/2025	
	182212	Replaced brake solenoid valve	30/01/2025	
	181087	Replaced tracks, rollers, idlers Re-sealed blade tilt ram, RH ripper tilt and RH ripper lift Re-built RH final drive	8/11/2024	
	180367	Replaced A/C hose	26/10/2024	
	179571	500 Hour Earthmoving Service	11/10/2024	
	179550	Repaired guard	11/09/2024	
	178712	250 Hour Earthmoving service	20/08/2024	
	173350	Replaced o-ring seal at transmission fitting	1/08/2024	
	174027	SEAT BELT REPLACEMENT	16/07/2024	
	174002	500 Hour Earthmoving Service	27/03/2024	
	174126	A/C filters and condenser cleaned out	26/02/2024	
	173271	Replaced A/C receiver dryer.	31/01/2024	
	173049	Replaced priority valve and cleaned out transmission shift solenoid valve	22/01/2024	
	172801	GPS setup	11/01/2024	
	172137	Installed ripper tine	6/12/2023	
	168555	Engine rebuild SEE DOCUMENTS FOR FULL LIST OF REPAIRS	27/11/2023	
	165708	250 Hour Earthmoving service	27/11/2023	

Asset	W/O No	Description	Finished	Done Reading
	171739	Re-skin blade Replaced trunnions on draft arms	1/10/2023	
	168316	Removed blade	14/08/2023	
	168073	Clean valves	7/08/2023	
	168077	Wash machine and drop belly guards	2/08/2023	
	167826	Swapped third gear for reverse transmission solenoids Installed battery isolator	31/07/2023	
	166180	Repair/replaced lights, grease nipples and put belly guards up and wash Replaced starter, trans cooler hose	8/06/2023	
	166181	R&R starter Repair oil leaks Flip edges	7/06/2023	
	162827	Coolant system = Inspected/OK Cleaned bleeder hoses = OK Replaced RH cowl keeper bolts	15/04/2023	
	164055	500 Hour Earthmoving Service	1/04/2023	
	164460	Replaced all belts Cleaned out belly guard	30/03/2023	
	163980	Jump started	29/03/2023	
	163690	Transmission filter housing seals replaced	9/03/2023	
	162916	250 Hour Earthmoving service	2/03/2023	
	163225	Installed boot	22/02/2023	
	160272	A/C drain un-blocked	31/01/2023	
	162275	Radiator cleaned out	30/01/2023	
	161820	2000 Hour earthmoving service	27/01/2023	
	160907	A/C compressor replaced and re-gassed Muffler replaced	6/12/2022	
	161271	Replaced segments Repaired starter earth cable	5/12/2022	

Asset	W/O No	Description	Finished	Done Reading
	160712	250 Hour Earthmoving service	30/11/2022	
	161236	Oil leak = Replaced oil feed hose to AUX water pump	28/11/2022	
	161241	Water temp hot = Replaced belts	23/11/2022	
	159028	500 Hour Earthmoving Service	14/10/2022	
	158932	Starter motor cabling repaired	28/09/2022	
	158475	Replaced hose between hydraulic pump and control valve Pumped up tracks Re-secured muffler	15/09/2022	
	158250	Inspect starting system and replaced fuel filter = OK Replaced music player and aerial	30/08/2022	
	157946	Dash lights wiring repaired	30/08/2022	
	157725	Wiper wiring repaired and fuse replaced Flashing light replaced	24/08/2022	
	153948	250 Hour Earthmoving service	28/07/2022	
	154342	Replaced drain plug o-ring - Gent Industries	19/04/2022	
	151907	500 Hour Earthmoving Service	23/02/2022	
	152189	A/C condensor replaced	22/02/2022	
	152188	RH track adjusted seals replaced	22/02/2022	
	152261	Replaced blown hose as needed	21/02/2022	
	151818	Power loss/Limp mode = Inspected/ok	11/02/2022	
	152016	Re-bolted muffler as needed = OK	8/02/2022	
	151892	Replaced radiator core and water pump	3/02/2022	
	151900	Repaired O-ring under floor	18/01/2022	
	151462	A/C fittings and receiver dryer replaced as needed	22/12/2021	
	148143	UHF bracket missing Install new UHF bracket Ben P	6/10/2021	
	148043	Top lights bolts replaced	30/09/2021	
	147977	Oil leak	29/09/2021	

Asset	W/O No	Description	Finished	Done Reading
		~~Removed seat etc to gain access to blown hose~~		
		Replaced by Pirtek tested-ok top up oils Reeve F		
	140864	Fuel gauge not working, oil leak PKWS all leaks repaired hoses replaced, all other repairs etc(see attachments)	27/09/2021	
	147638	Radiator rebuild PKWS repairs on radiator (see attachments)	27/09/2021	
	147629	Respray motor and cab doors	17/09/2021	
	147041	Metal in power train Removed torque convertor Replaced idler gears Carried out repairs at PKWS(see attachments)	2/09/2021	
	146792	Front wiper n/w Repl. front wiper motor & arm-test Ok	25/08/2021	
	146748	Wipers not working Repl. blown fuse. Check wipers. Front wiper seized. Ordered new front wiper assy(Tony)	24/08/2021	
	145519	250 Hour Earthmoving service	11/08/2021	
	146218	Exhaust loose Removed snapped bolts from muffler bracket. Fit new with anti-seize & secured	3/08/2021	
	144888	Flashing light not working Replaced blown fuse Reeve F	23/06/2021	
	144380	Ripper boot pin falling out Replaced pin, replaced leaking O-ring on ripper lift cylinder, topped up oil Reeve F	7/06/2021	
	143862	250 Hour Earthmoving service	25/05/2021	
	142793	Oil leak Hydraulic oil cooler leaking-repair Engine sump gasket needs replacing Ripper hose needs replacing Replaced ripper hose, repair lights, repair hyd cooler, reseal sump and dip stick gaskets, repaired water separator filter PKWS Scot A(see attachments)	19/05/2021	
	140440	Transmission temperature gauge not working Remove and replace trans temp sender	23/02/2021	

Asset	W/O No	Description	Finished	Done Reading
	140419	500 Hour Earthmoving Service	22/02/2021	
	140611	Water leak fixed aux water pump hose	12/02/2021	
	140609	Blown hose Replaced blown hose	9/02/2021	
	138236	Initial Plant Safety Audit completed	22/10/2020	
	137579	Front blade peeling up Replaced 2 bottom sections of wear plates on blade	21/10/2020	
	137151	Fire extinguisher out of date Fitted new fire extinguisher	14/10/2020	
	133493	Plant inspection and repairs Fitted spacer to seat belt,ordered door latch and striker, Replaced door striker and latch,put on crush zone stickers	3/07/2020	
	132306	250 Hour Earthmoving service	1/06/2020	
	130568	Gear shift lever spins around, flashing light not working Parts ordered Fixed forward and reverse lever	27/05/2020	
	129230	door latch fallen off Replaced RHS door latch	25/05/2020	
	132072	battery us/smoking On arrival batteries,hot smelly,swollen,removed batteries. Run continuity test on main circuit and cables to see if shorted to ground-OK Visual inspec. of cables including under cab floor-ok Pick up battereis from Frankies Warehouse and install them,tested alternator 27.99v,R terminal 13.98v-good	20/05/2020	
	131959	Wont start Jump started	18/05/2020	
	130710	2000 Hour earthmoving service	21/04/2020	

Asset	W/O No	Description	Finished	Done Reading
	130073	operator complaining about seat Removed seat and repaired the base so it would pump up	25/03/2020	
	130034	No flashing light, warning light on Replaced flashing light Cleaned connection to R terminal on alternator- light went out	23/03/2020	
	129109	250 Hour Earthmoving service	28/02/2020	
	129034	Door latch loose / Alternator light on Alternator charging at time of inspection No light present Repair door latch mounting bolts	20/02/2020	
	128865	Need ripper tyn Fitted long ripper tyn	30/01/2020	
	127870	Tilt ram leaking Order blade cylinder seal kit	20/01/2020	
	127560	Wont start Replaced starter motor	13/01/2020	
	126174	500 Hour Earthmoving Service	14/11/2019	
	124369	Air cond See air cond service sheet #1864	5/09/2019	
	124034	250 Hour Earthmoving service	29/08/2019	
	123996	door handle keeps falling off Replaced LHS handle with a new one	22/08/2019	
	123838	Wont start Re crimped battery cable to starter	14/08/2019	
	123295	Diesel leak Removed and replaced blown fuel hose from filter to the back of the head	26/07/2019	

Asset	W/O No	Description	Finished	Done Reading
	123203	No A/C (job no.01189)	23/07/2019	
		A/c not cold .A/c belt missing & a/c compressor seized,Fit new a/c belt & compressor(see a/c repair sheet 1189) Compressor clutch seized.Recover gas.R&r compressor & belt pressure test to 3000psi,vac system & test ok .Charge system Glen Windle		
	122513	500 Hour Earthmoving Service	3/07/2019	
	121305	250 Hour Earthmoving service	20/05/2019	
	121176	belts slipping tightened alternator belt	7/05/2019	
	121601	uhf not working altered Arial plug	1/05/2019	
		Fixed blown hose and replaced water pump filled with CAT coolant Washed radiator		
		Replace and rewire reverse screen and made new bracket		
	120246	Resealed all lift rams replaced all track frame rollers Replaced idlers Replaced all track guides Replaced converter yoke seal Resealed transmission pump suction hoses replaced pivot shaft bushes Equaliser bar outer bearings	13/03/2019	

Asset	W/O No	Description	Finished	Done Reading
	117580	500 Hour Earthmoving Service	3/01/2019	
	118563	Diesel leak	15/12/2018	
		Replaced fuel line supply/return hoses		
	118144	Engine oil leak	24/11/2018	
		Tighten sump bolts replace missing bolts		
		Fuel hose lift rams leaking		
	118328	Blown hyd hose	22/11/2018	
		Replace blown hyd hose (pump to implement valve)		
		Hose made by pirtek campelltown		
	117301	Flahing light not working and wiper blade arm U/S	17/10/2018	
		Ordered flashing light cover and new wiper blade arm		
	117050	Fan hub bearings U/S	3/10/2018	
		RnR jockey puller dampener and shaft		
		Remount A/C compressor tight		
		Re grease and tension main centre bolt for fan bearings		
		RnR cat grease line for fan bearing		
		Tension all belts test OK		
	116504	Bad Hyd oil leak	12/09/2018	
		RnR blown hose ass		
		Refill 50lt in hyd tank		
	115531		29/08/2018	
	116102	Tighten A/C belt alt belt	28/08/2018	
		Exhaust stack broken installed bolt in tilt cylinder guard needs new hose		
	115796	250 Hour Earthmoving service	27/08/2018	

Asset	W/O No	Description	Finished	Done Reading
	115694	blown transmission hose Replaced hose going from trans pump to filter housing Removed and replaced tracks and segments with genuine OEM caterpillar tracks	22/08/2018	
	116086	Removed and flipped cutting edges and replaced corner tips and bolts	17/08/2018	
	115879	Exhaust broken,A/C belt slipping RnR turbo manifold gasket, nuts and bolts RnR muffler clamps RnR a/c condenser filter lid bolts	8/08/2018	
	114392	Possible manifold gasket leaking RnR turbo manifold gasket nuts and bolts RnR muffler clamp RnR A/C condenser filter lid bolts	8/08/2018	
	115254	No flashung light Replaced old one with a new one	30/07/2018	
	115109	wont start Replace 3x batteries checked charge rate 27.4V Adjusted track track chains worn Replace blown fuse for flashing light	23/07/2018	
	115188	2000 Hour earthmoving service	20/07/2018	
	116035	RnR starter motor	6/07/2018	
	116025	Repair wiring to front lights Adjust and tighten all light brackets	21/06/2018	
	115177	250 Hour Earthmoving service	13/06/2018	
	113967	Bad trans oil leak Dropped belly guard and replaced blown hose from convertor to trans mission	13/06/2018	
	113762	using water Replaced top radiator hose and replaced clamps	5/06/2018	
	113030	250 Hour Earthmoving service	29/05/2018	
	112982	Bad Hyd oil leak / replace leaking o,ring fit new muffler ass repair engine bay door latch	26/04/2018	

Asset	W/O No	Description	Finished	Done Reading
	112575	Change ripper	16/04/2018	
	112635	No wipers and no flash check fuses, blown fuse. replace fuse check for cause, front wiper arm loose and jammed tight/ajust front arm, exhaust rattle muffler broken	5/04/2018	
	112876	Ripper tyne too long Fit multi shank ripper tyne & new ripper boot	4/04/2018	
	112768	Engine and trans leak Removed rocker cover and replaced seal and bolts. Replaced orings under seat for the transmission oil leak.	15/03/2018	
	111528	Leaking ripper lift ram Removed LHS ripper lift cylinder rod end from cylinder barrel. Resealed cylinder head and piston. Put cylinder back together with new orings in hoses.	6/02/2018	
	111040	500 Hour Earthmoving Service	23/01/2018	
	109095	250 Hour Earthmoving service	28/09/2017	
	109184	Flashing light not working & fire extinguisher empty Replaced blown fuse and inspect wiring fit new fire extinguisher	21/09/2017	
	107675	WONT START Checked batteries, they had no charge connected jumper leads and left to charge up batteries then started and all tested fine	25/08/2017	
	107621	Need grouser bolts Track grouser plate broken at track joining link fitted new grouser plate and 4 x new bolts Tension to spec and adjust track	23/08/2017	
	108378	Cutting edges need to be replaced Replace full set of edges/bolts corner tips center edge aftermarket (BYG) other 2 x CAT	5/08/2017	
	108377	Replaced alternator pulley, turn off heater taps. need to replace hoses, ripper cylinders leaking	4/08/2017	
	108495	wipers not working repair short circuit and replace blown fuse Tested OK	2/08/2017	
	106614	Alternator light on and buzzer going Replace alternator and belt, need new pulley	24/07/2017	

Asset	W/O No	Description	Finished	Done Reading
	106568	Hydraulic leak under floor Blown hose under floor removed and replaced hose	20/07/2017	
	108496	Fitted new flashing light	14/07/2017	
	106062	500 Hour Earthmoving Service	28/06/2017	
	107733	Won't drive Install new transmission valve, calibrated and adjusted. Stopped driving again, clean valves, changed filters, shimmed out bypass valves. Changed filter again and test drive	30/05/2017	
	107734	Install transmission Test, gear oil, pressure keeps dropping off, clean valve get correct pressure then drops off again, order in new valves	29/05/2017	
	107735	Won't drive Replace T/C output speed sensor, replace uni joints put belly guards up (dig out), remove and clean transmission valves	24/05/2017	
	107736	Won't drive, bad transmission oil leak Dig out tracks, drop belly guards Install new proportional valve, repaired wiring, removed starter motor, Plug had fallen out of the front, install new starter, fill up transmission oil.	23/05/2017	
	108092	Not driving Checked speed sensor checked transmission sensors all good cleaned out valves then got gears all good after testing	23/05/2017	
	108091	Traveled to machine Still not in operation was unable to repair	22/05/2017	
	104992	250 Hour Earthmoving service	21/04/2017	
	105030	Fan belts u.s. Only 1 left on machine replace belts R&R hose clamps for heater hose R&R 2x o rings for trans pump	11/04/2017	
	104429	Air con working Complete	14/02/2017	
	108873	Electrical problems	3/02/2017	
	102632	500 Hour Earthmoving Service	16/01/2017	
	102948	Wont start# Tightened alt belt	11/11/2016	
	108000	Checked and had no gas, found worn hose Fitted joiner, re tested and tested OK re gassed system and tested OK	11/11/2016	

Asset	W/O No	Description	Finished	Done Reading
	102679	Won't start#Replaced alternator OR CAT	22/10/2016	
	101994	250 Hour Earthmoving service	30/09/2016	
	101989	R/H CNR tip LOOSE Blade cross brace bolt missing and flashing light U/S# Tightened corner tip and replaced flashing light	14/09/2016	
	101547	Fuse box U/S# Replaced fuse box	17/08/2016	
	101420	2000 Hour earthmoving service	11/08/2016	
	100773	Wont start# Found problem wit park brake switch	30/07/2016	
	100445	250 Hour Earthmoving service	15/06/2016	
	100250	Fitted new CD player and new areial	6/05/2016	