

Work Order History Report

Asset	W/O No	Description	Finished	Done Reading
P0543		CAT D9T Dozer (GPS)		
	192191	HME Inspection - Bulldozer Quote #:	26/03/2026	Hours
	58157	October R&M -Replace hyd hose - Hydralink 07/10 -load bucket 07/10 - Cut off fitting from old tail and braize onto new tail - Remove blown steer hose - Top up hyd oil - Fix fire extinguisher bracket - Pump up tracks - Sterring fault - R&R steering speed sensor	30/01/2026	Hours
	60005	January R&M - Grease machine - Replace reverse camera & dash cam - Blow out air filter & cab filter - 6-month Fire Suppression service - Replace brake pedal position sensor - Replace steer speed sensor, assemble joystick, calibrate steering. - Change cab filters - Repair air seat, broken wiring - Grease machine. - 6 MONTH FIRE SUPPRESSION SERVICE	29/01/2026	Hours
	59808	Cat D9T Bulldozer - 2000hr Service and to do list 25969hrs - 26001 hrs	22/12/2025	26001 Hours
	59419	December R&M Weld up exhaust Harness repairs Fit new operator seat, wire up air seat Pump up tracks Drop belly guards. Inspect for oil leak - repair. Remove and replace LH blade cylinder Wash tracks and rollers Replace steer hose/ red lightening	22/12/2025	Hours

Asset	W/O No	Description	Finished	Done Reading
	58806	Cat D9T Bulldozer - 250hr Service 25701 hrs - 25844 hrs - Secured loose electrical harness - Fixed work light x 2 - Blow out cooler packs	23/11/2025	25701 Hours
	58765	November R&M GPS issues fix reverse camera Fit mushroom head (trimble) Adjust door Blade sensor fault Inspect and order seat Gas fire suppression with bottle supplied by T.Somers and test for leaks	21/11/2025	Hours
	59199	GET - In preparation to change not yet due	18/11/2025	Hours
	57785	Cat D9T Bulldozer - 500hr Service 25558hrs	10/10/2025	25558 Hours
	57432	Cat D9T Bulldozer - 250hr Service. Lake Cowal Asses trimble issue, trimble unit broken. Remove and bring to workshop	1/10/2025	Hours
	57297	September R&M Powertrain code diagnostics Pump up tracks Draft arm bolts Ac regas -inspect a/c system 18/09 - RH equaliser bar grease nipple, A/C blocked cab filters 26/09 - Track adjustment 30/09	30/09/2025	Hours
	57130	August Work Order R&M - steer fault, found faulty steer sensor 25/08	18/09/2025	Hours
	53845	Inspect, diagnose engine oil leak.	4/09/2025	Hours
	54958	Pre hire repairs as per HME inspection. w/o 54699 25168 hrs - remove ripper bed - drain oil and coolant	15/07/2025	Hours

Asset	W/O No	Description	Finished	Done Reading
		- Carry out 12 monthly fire suppression service - Extra hours done on diagnostics for communication wiring between ECM'S - Had issue with A/C hose and repair - Regassed		
	54699	HME Inspection - Bulldozer Quote #: 359. *Finish 25,179hrs	7/05/2025	25179 Hours
	53756	Diagnose and repair engine oil leak 25070hrs - replace sump front section due to crack	9/04/2025	Hours
	53943	HME inspection MCO 25114.7HRS	4/04/2025	25115 Hours
	52736	Cat D9T Bulldozer - 1000hr Service Re-chrome 1 x lift rod. 24970hrs	13/03/2025	25000 Hours
		4/03: Remove damaged grease lose take to pirtek to get made 5/03: Carry out 1000hr service, change all oils trans & final oil. 1000hr service, fit grease lose, segregate hoses back in clamps on ripper, pump up tracker, clean belly guard		
	51930	"Steer motor sensor fault intermittent Remove and test harness, clean sensor, clean plugs. Diagnose Replace sensor " 24807hrs	4/03/2025	Hours
		- Investigate steer fault - Replace steer motor sensor & tidy up wiring under cab		
	51726	Cat D9T Bulldozer - 250hr Service 24759hrs	3/02/2025	Hours
	51495	Top up engine oil Top up coolant Top up trans Repair loose fire extinguisher bracket Repair leaking ripper hose " 24720hrs	7/01/2025	Hours
	50065	Track roller squeaking. Remove #7 load roller. Remove broken bolts. Install new roller and tension cap bolts.	26/11/2024	Hours
	49817	Cat D9T Bulldozer - 500hr Service	19/11/2024	Hours

Asset	W/O No	Description	Finished	Done Reading
		Hours: 24444 24533 19/11/24 Only one sample bottle supplied		
49897		Repair wiring to failed beacon Hrs: 24600	5/11/2024	Hours
49026		Hours: 24285 Yancoal introduction to site compliance inspection	4/10/2024	Hours
48473		Operator complaining about aircon not hot or cold. Checked over system, unable to fault - possible thermostat required. Contact Keevils auto - replaced thermostat.	1/10/2024	24262 Hours
20905		Cat D9T Bulldozer - 4000hr Service	24/09/2024	24235 Hours
48590		Inspected & repaired harness for plant tracker Carried out testing & found module working correctly but need relocation for service. Hours	8/09/2024	Hours
21044		Re seal heater taps slowly leaking. 24,025hrs Diagnose and repair heater not working Repair radio wiring causing radio to not work.	19/08/2024	Hours
19594		Radiator core failed leaking, not holding coolant. Inspect/replace cores, re seal.	22/07/2024	23888 Hours
17506		Repair engine, pressurising and engine oil in the radiator. ENGINE in frame overhaul. Rings. Bearings inspected Replace oil cooler. Check tracker wiring	20/06/2024	Hours
17708		Fire Suppression service	4/06/2024	Hours
49504		Troubleshoot cooling system. Replace damaged/worn hoses	16/05/2024	23741 Hours
14543		Replace outer radiator core with spare due to engine breather pipe retaining clamp breaking and allowing the breather pipe to rub against the core, resulting in coolant leak.	16/04/2024	23560 Hours
15844		Overhaul returned blade tilt cylinder from A1. (Supplied cylinder from P0947 to keep machine running). #Major damage. Cost compared available options. Re-barrel, replace flange, replace piston and piston inserts.	23/02/2024	23450 Hours
7747		DIAGNOSE & REPAIR BLADE TILT ISSUE	13/02/2024	23457 Hours
7748		Minor R&M Monday to Sunday - CHANGEOUT R/H BLADE LIFT CYLINDER Rebuild Lift cylinder	18/12/2023	23273 Hours
11235		250 Hour service	7/12/2023	23227 Hours
7370		Diagnose SMU meter loosing hours	22/11/2023	23197 Hours

Asset	W/O No	Description	Finished	Done Reading
	7404	DIAGNOSE & REPAIR START ISSUES - A1 EARTHWORX	31/10/2023	Hours
	2711	HME inspection. Remove belly plates Wash machine Repair/Replace damaged tilt cylinder components 1000HR service replace floor mat replace lower driveshaft cover repair rear bent/broken rear platform hand rails replace missing fire extinguisher & stamp the other re commission fire suppression re mount F/R inner lift cylinder light, repair R/H platform, R/H rear outer & 3 rear lower lights replace front wiper arm replace R/H mirror & tighten L/H side replace timer relay (bypasses) & test A/C replace 3rd switch from the front on the R/H console as the decal is missing replace globe in action alarm needs AM/FM radio fitted (needs to be fitted very securely or it will fall out) wiring needs tidying up to UHF & under R/H console reverse camera screen needs to be re mounted (might be a mount in the cupboard) replace grease lines to R/H ripper lift & tilt barell end of cylinders fit Thinksafe & QR code stickers remove client stickers from L/H ROPS & windows re seal R/H Aux. drive plate on rear structure re seal both ends of trans cooler & top pipe replace damaged radiator core (nosecone removed) replace missing clip off air filter housing replace engine camshaft & rockers (hood and exhaust removed) re seal tranny input seal re seal R/H side pump control under floor re seal R/H ripper tilt cylinder re seal L/H blade lift cylinder replace L & R track groups & segments replace quick fill nozzle remove trunnions to be machined. Machine trunnions in fab shop and re-fit. replace GET on blade (check stock out the back) check pivot shaft circuit for leaks (no visable leaks but oil was low) track guide housings need building up & track guides replaced. Completed by boilies. replace the 4 centre suspension pads on both sides L & R pusharms have cracks at the bottom of each side where the wear package is welded on. Re-welded check movement in R/H blade knuckle Vertical movement shim ripper bed to frame replace ripper boot Complete site requirements - fab roof top light mount, fit muffler blanket, lights on with key on, fire suppression service.	6/10/2023	22945 Hours
	4050	Grease and top up coolants	20/06/2023	22970 Hours
	4047	Check a/c adjust gas levels	19/06/2023	

Asset	W/O No	Description	Finished	Done Reading	
	4034	Top up fluids. Mobilise dozer for use while D8 down	16/06/2023	22916	Hours
	867	Fabricate new sump gaurd, clean out area to install it. needs new weld in nuts.	18/05/2023		
	3950	Tried to pull belly guards down but they were full of med and not wanting to come down.	16/05/2023		
	2316	Carried out repairs to machine, remove belly pans and clean for transport	16/05/2023		
	2264	Drop belly plates - well try to	16/05/2023		
	3926	Check machine as prestart fault report	7/05/2023	22874	Hours
	1893	Fill out defects	7/05/2023		
	838	Replace seized idler and fit new belt. Operate and check functions.	26/04/2023	1	Hours
	945	Seized idler pulley for alt/ac , need new belt + pulleys- parts rek supplied	25/04/2023		
	2374	Tighten middle cutting edge bolts	24/04/2023		
	923	Finish off service and do a defect report	21/04/2023		
	2369	Carry out 250hr service on machine	20/04/2023		
	831	Inspect prestart defects	11/04/2023	1	Hours
	2363	Topped up coolant and checked oils	5/04/2023		
	645	Cutting edge change out & weld in B25 to stop the wear on the bolts	25/03/2023	1	Hours
	884	Top up trans level	11/03/2023		
	964	Change dual tilt hose	27/02/2023	22298	Hours
	1240	Fuel hose blown from fuel filter into engine. Replaced hose and orings	21/02/2023		