

Work Order History Report

Asset	W/O No	Description	Finished	Done Reading
P1036		Komatsu PC300-8 Excavator		
	18195	P1036, Disposal	23/07/2024	Hours
	17047	HME Inspection - Excavator Quote #: 105	28/05/2024	11412 Hours
	15461	Replace broken bucket cylinder.	3/05/2024	11344 Hours
	15421	Repair quick hitch cylinder - live end retainers.	1/05/2024	11344 Hours
	15168	HME Inspection - Excavator. 11331hrs Fit tilt bucket.	29/04/2024	Hours
	12703	Replace head gasket (parts only)	26/03/2024	Hours
	12700	Excavator - 250hr service	20/03/2024	11332 Hours
	9555	Hours: 11258 Coolant Leak - Failed water pump Water pump needs replacement	13/02/2024	Hours
	8146	Pre hire repairs as per HME inspection. Replace belly guards, straighten/replace mounts Clean cab Check and tag fire extinguishers First aid kit Repair rear work light Repair/replace beacon Top up washer bottle, replace wiper blade Replace mirror Grease machine Replace stickers Replace plant stickers Replace head gasket Replace a/c belt Check all levels Replace bushes and pins in both lift cylinders both ends Replace bucket cylinder rod end to h link pins and bushes Replace h link pins and bushes Bucket repairs Straighten up battery box Clamp down batteries Replace RHS e stop	7/02/2024	11234 Hours

Asset	W/O No	Description	Finished	Done Reading
		Weld up gps pole mount		
	8564	Repair B83 sieve bucket. Replace floor and sides. Fit chock blocks Pad weld teeth adaptors Fit 4 x lip protectors	15/01/2024	Hours
	7831	HME Inspection - Excavator Quote #: 38	7/12/2023	11234 Hours
	6605	Excavator - 1000hr service 11000 HRS	31/10/2023	Hours
	6377	Minor R&M Monday 16-10-23 to Sunday 22-10-23 Fitted new pin retaining bolt to quick hitch. Removed teeth from GP bucket to change. Wrong teeth ordered. Had to refit old teeth. New ones to be ordered.	22/10/2023	Hours
	19065	Carried out 1000hr service.	16/10/2023	Hours
	5354	Excavator - 250hr service	6/09/2023	10776 Hours
	4659	Supply cutting edges for mud bucket	21/08/2023	Hours
	4523	Minor R&M Grease machine and clean air filter	11/08/2023	10600 Hours
	3661	Excavator - 500hr service	10/08/2023	10590 Hours
	3308	Excavator - 250hr service and repairs Changed out quick hitch after crack was repaired in stick. Changed cutting edge on mud bucket - Faults listed in To Do list	11/07/2023	10400 Hours
	3125	July - Minor R&M	8/07/2023	
	4045	Grease machine	18/06/2023	10221 Hours
	4039	Grease machine	17/06/2023	Hours
	4032	Fit new bolt for bucket pin retainer.	16/06/2023	10251 Hours
	4021	Repair battery neg terminal, pump out tracks, grease machine.	14/06/2023	Hours
	2793	Grease and check over	8/06/2023	
	2171	1000hr service	28/05/2023	Hours
	2265	Chase up parts in container for 1000hr service	16/05/2023	
	3931	Changed front windscreen with P1033	9/05/2023	Hours

Asset	W/O No	Description	Finished	Done	Reading
	757	Inspect bucket and hitch. Tighten GET bolts	29/04/2023	1	Hours
	1035	Push dog bone pin in replace retainer bolt	26/04/2023		
	2376	Changed out bucket wiring for trimble	25/04/2023		
	921	Reseal bucket cylinder and fit to machine in pit	21/04/2023		
	1060	Started rebuild lift ram. Carried out repairs to machine removed windscreen to be fitted to P1033	15/04/2023	10251	Hours
	713	Dipper arm ram clean up	15/04/2023	1	Hours
	817	Inspect hydraulic leak on bucket cylinder	4/04/2023	1	Hours
	19034	Finish off rebuilding tilt bucket and new cutting edge, take bucket to machine onsite, test functions.	1/04/2023		Hours
	2360	Tighten up quick hitch fitting/ fitted tilt bucket	1/04/2023		
	19035	Carry out tilt bucket rebuild, fit new shims, take play out of the rams and man pivot pin.	31/03/2023		Hours
	19040	Change over GP bucket to tilt bucket.	21/03/2023		Hours
	19050	C/O bucket teeth.	16/03/2023		Hours
	1010	GP bucket crack repairs completed	12/03/2023		
	915	Paint hitch Tilt bucket itself degrease and weld up cracks and install new heel blocks Put all rams and hoses into a container.	3/03/2023		
	914	Tilt bucket repairs - crack repairs stiffen up hitch with fish plates Measure up pins for shims	2/03/2023		
	944	Change out tracks and 2 x carrier rollers	24/02/2023	8750	Hours
	19059	Grouser plate bolts missing - tracks changed. Cab seat adjuster broken - inspected, seat adjuster working.	24/02/2023		Hours
	19036	Carry out tilt bucket repairs on hitch.	21/02/2023		Hours
	19037	Prep for welding repairs.	20/02/2023		Hours
	483	Tilt bucket clean prep for pulling apart	19/02/2023	1	Hours
	1235	Tilt bucket main pin and pin walking out and damaged GPS cable	18/02/2023		
	462	GP bucket wear plates weld out	15/02/2023	1	Hours
	459	GP bucket weld out. Cut & install wear plates	14/02/2023	1	Hours

Asset	W/O No	Description	Finished	Done	Reading
	458	34T mud bucket floor weld out. Found crack on R/H side adapter. Floor and side all welded out	13/02/2023	1	Hours
	19060	Carried out 500hr service.	1/02/2023		Hours
	19038	Take one bolt from RHS track to put in LHS track. Tracks U/, change nipple on tilt bucket and grease. Remove one pin to inspect why so short.	30/01/2023		Hours
	19039	Swap hoses on tilt cylinders and grease all pins.	29/01/2023		Hours
	19044	Install floor into GP bucket.	29/01/2023		Hours
	19064	Changed out teeth on GP bucket.	29/01/2023		Hours
	19045	Install tilt bucket pins take bucket to machine and check tilt works. Check tracks on the machine.	28/01/2023		Hours
	19066	Works to be completed at next service interval: Track plate is missing bolts - chasing parts, WO 4826. Offside mirror is missing. Check all light work operations. Hydro hose leak, check over machine for hyd leaks - replaced drive motor hoses. Check damage to belly plate - minor. Checked fire extinguishers - replace fire extinguisher. Cracked windscreen, broken mirror - minor. Amber beacon light not working - repaired. No belt - replaced.	28/01/2023		Hours
	19046	Prepare bucket for welding.	25/01/2023		Hours
	19047	Pin walked out on other side - bash pin back into place and weld up, tighten up both track bolts. Top corner roller broken. Mud bucket in workshop, add wear strips.	24/01/2023		Hours
	19048	Master link walked out, place back in and weld up.	23/01/2023		Hours
	19049	Cut biz wear strips.	23/01/2023		Hours
	19041	Check track grazers loose, tighten both sides.	22/01/2023		Hours
	19042	Tighten grouser bolts.	18/01/2023		Hours
	19043	Check A/C - all ok.	17/01/2023		Hours
	19058	Prepare bucket for new floor.	13/12/2022		Hours
	19051	Replace missing grazer bolts.	25/11/2022		Hours
	19052	clean out A/C filters and check gas.	24/11/2022		Hours
	19057	Replaced 45 degree oil fitting on the tilt bucket.	23/11/2022		Hours

Asset	W/O No	Description	Finished	Done Reading
	19222	Fix grazers.	23/10/2022	Hours
	19221	Check GPS fault, bucket sensor u/s. Fit sensor off tilt bucket and learn position - check, ok.	24/09/2022	Hours
	19220	Fit new bucket teeth. Change out GET.	20/09/2022	Hours
	19067	Offside mirror missing - refer to WO 2417. Window cracked - noted.	16/09/2022	Hours
	19069	Currently out of date. One front light is not working. RHS mirror is missing. Front cab windows have crack. Hydro hose leak. -- Refer to WO 2417.	16/09/2022	Hours
	19070	Cracked window - noted, sent back to work.	16/09/2022	Hours
	19068	Topped up hydro oil.	11/09/2022	Hours
	19218	Digger GPS pole repairs. Weld up cracks on LHS pole - will need to remove wires to fix properly.	5/09/2022	Hours
	19216	Repair hydraulic leak.	4/09/2022	Hours
	19214	Check GPS and measure up buckets with Sitech.	15/08/2022	Hours
	19210	Broken bucket, broken/missing cutting edge bolts.	13/08/2022	Hours
	19209	Broken hydraulic fittings.	12/08/2022	Hours
	19208	LH outer cylinder broken - don't have correct fittings in stock. Drill and tap fittings to makeup and fit to machine, check - ok.	5/08/2022	Hours
	19206	Investigate steering fault.	31/07/2022	Hours
	19205	Fit new cutting edge to bucket.	30/07/2022	Hours
	19204	Carry out 500hr service.	29/07/2022	Hours
	19202	RHS GET bolts broken. Clean between bucket and edges. Fit new bolts and tighten - all ok.	25/07/2022	Hours
	19201	Carry out bucket repairs.	25/07/2022	Hours
	19200	Assist with refitting and reassembly of tilt hitch.	20/07/2022	Hours

Asset	W/O No	Description	Finished	Done Reading
	19199	Cut edge bolts broken.	16/07/2022	Hours
	19198	Broken bucket cylinder fitting replaced and modified.	15/07/2022	Hours
	19197	Change cutting edge. Change hydraulic hoses and grease lines.	13/07/2022	Hours
	19196	Change over batteries.	8/07/2022	Hours
	19195	Fixed hydraulic leak. Drained water out of fly separator. Greased. Blew out air filter. Flipped cutting edge on blade.	5/07/2022	Hours
	19194	Repair wiring to GPS bucket sensor. Investigate lane guidance fault with GPS.	25/06/2022	Hours
	19192	Finish fitting quick hitch and fit tilt bucket. Replaced cutting edge on tilt bucket, fitted bucket. Fit new hitch, carried out repairs to gas cables. Take GP bucket to workshop. Replace tilt hoses on bucket.	23/06/2022	Hours
	19191	Pick up repaired quick hitch. Remove quick hitch pins. Unload hitch and ute. Remove bucket from digger. Blow out air filters. Greased, topped up hydraulic oil and engine oil.	22/06/2022	Hours
	19189	Fit divets plug to repair broken GPS cable.	14/06/2022	Hours
	19188	Remove and replace blow hydraulic hose.	13/06/2022	Hours
	19187	Replaced GET on bucket.	12/06/2022	Hours
	19186	Greased, topped up engine oil, blew out air filters, topped up hydraulic oil.	11/06/2022	Hours
	19185	Quick hitch cracked. Removed quick hitch and direct pin bucket.	29/05/2022	Hours
	19184	assist with tilt bucket fitting and made selection.	22/05/2022	Hours
	19183	Greased, blew out air filters, carried out machine check over.	21/05/2022	Hours
	19182	Greased machine, blew out filters. topped up hydraulic oil, carried out check over.	16/05/2022	Hours
	19181	Greased machine.	14/05/2022	Hours
	19180	Check engine overheating - radiator screen blocked, removed screens, cleaned and refit. Replaced flashing light bulb.	3/05/2022	Hours

Asset	W/O No	Description	Finished	Done Reading
	19176	Replaced damaged hose on tilt bucket, made new hose, fit hose from hitch to tilt cylinder on bucket.	9/04/2022	Hours
	19173	Carried out machine check over, greased, blew out air filters, tightened up tracks, blew out cab and radiator.	5/04/2022	Hours
	19171	Repaired hitch hydraulic leak. Carried out machine check over, blew out air filters and greased.	1/04/2022	Hours
	19168	Carried out machine check over, greased, blew out air filter, topped up hydraulic oil.	18/03/2022	Hours
	19167	Carry out machine check over, greased, blew out air filters.	15/03/2022	Hours
	19166	Carried out machine check over, greased, topped up hydraulic oil, blew out filters.	9/03/2022	Hours
	19165	Carried out machine inspection. Greased, blew out radiator and oil filters. Topped up hydraulic oil and checked over other oils.	31/01/2022	Hours
	19163	Carried out machine check over. Greased and blew out oil.	17/01/2022	Hours
	19161	Greased machine, blew out air filter, carried out machine check over.	14/12/2021	Hours
	19158	Clean mud off track frames	27/11/2021	Hours
	19153	Check top light and flash light not working. Rubbed wire, repaired and tested.	24/11/2021	Hours
	19151	Clean tracks and adjust door.	21/11/2021	Hours
	19150	Check coolant leak - faulty clamp	20/11/2021	Hours
	19146	Replaced damaged hitch tilt hydraulic line o-ring. Carried out machine check over. Blew out machine filters. Grease and blew out radiator.	13/11/2021	Hours
	19144	Carry out machine check over. Blow out air filters. Grease and blow out radiator.	11/11/2021	Hours
	19142	Start on track removal, start removing grouser plates.	7/11/2021	Hours
	19141	Grease and blow down, adjust belt.	6/11/2021	Hours
	19139	Grease and blow down, adjust belt.	5/11/2021	Hours
	19138	Grease and blow down, adjust belt.	3/11/2021	Hours
	19136	Blow down all filters, top up hyd oil, check GET and adjust track.	1/11/2021	Hours

Asset	W/O No	Description	Finished	Done Reading
	19135	Fit new bucket teeth.	30/10/2021	Hours
	19127	Check over A/C system while packed up, pump up track, grease.	29/10/2021	Hours
	19126	Weld side, pin retainer in bucket. Blow down and grease.	28/10/2021	Hours
	19125	Grease, blow out intercooler and radiator.	27/10/2021	Hours
	19124	Grease machine. Blow down. Pump up track. Change out GET. Carry out GP bucket repairs - excessive wear.	9/10/2021	Hours
	19121	Remove old LH track, sprocket segment. Clean all surfaces, fit and tension. Sprocket. Clean & fit grouser plates to new chain. Adjust track, tested - ok.	23/09/2021	Hours
	19120	Set up job for track change. Move parts. Remove LH track. Heat and remove grouse plates.	22/09/2021	Hours
	19119	Blow out cooler, cab filters.	20/09/2021	Hours
	19117	Blow down and grease. Hitch wiring - make up a new cable. Re-wire GPS wiring. Pulled wire out.	19/09/2021	Hours
	19114	Move mud bucket to workshop for repairs, grease machine.	17/09/2021	Hours
	19110	Carried out pre start. Refilled hydraulic oil. Checked engine oil and greased.	7/08/2021	Hours
	19109	Blow out cooler pack, top up engine oil.	31/07/2021	Hours
	19108	A/C not blowing cold air, checked pressures, test system hose fitting on pump, tightened up and re gas.	30/07/2021	Hours
	19107	Pre-start machine. Grease machine. A/C not cold - topped up with gas.	29/07/2021	Hours
	19106	Weld up cracks on bucket. Grease machine and blow filters.	26/07/2021	Hours
	19105	Removed dirt and rocks out of tracks. Washed down and refilled water truck.	13/07/2021	Hours

Asset	W/O No	Description	Finished	Done Reading
		Loaded buckets and machine on float. Diagnose petrol engine and replace. Drake float.		
	19104	Repair flashing light. Place buckets with machine. Clean out operator cab. Carry out inspection of machine and on site inspection.	8/07/2021	Hours
	19102	Weld up buckets, add wear strips between teeth, add wear strips to sides of buckets, go through machine checklist.	7/07/2021	Hours
	19101	Inspect machine, check e-stop.	6/07/2021	Hours
	19100	Broken fire extinguisher bracket.	10/05/2021	Hours
	19099	Adjust tracks and grease machine.	29/04/2021	Hours
	19098	Fit new wiper blade. Check e-stop fault in cab - loose terminal. Check all outer e-stops.	3/03/2021	Hours
	19097	Collect filter numbers and order 1000hr kit.	1/03/2021	Hours
	19096	Repaired oil leak - cooler hose on cooler.	18/02/2021	Hours
	19095	Replaced cutting edge on tilt bucket and refitted new cutting edge to bucket.	16/02/2021	Hours
	19094	Replaced trimble sensor on bucket. Met up with truck driver - cut edge off crusher to allow dolly to clear on hard turns.	18/01/2021	Hours
	19093	Replaced o-rings.	7/01/2021	Hours
	19092	Repaired cutting edge.	6/01/2021	Hours
	19091	Hydraulic leak, found a split steel pipe. Sourced parts, fitted new steel pipe. Filled with hydraulic oil, tested - ok.	16/12/2020	Hours
	19090	Removed hyd pipe at valve bank, braised crack, refit and tested.	10/12/2020	Hours
	19089	Turned cutting edge and replaced bolts.	4/12/2020	Hours
	19088	Fitted up rock breaker, tested and adjusted flows again. Lasted twenty minutes before it stopped working. Requires overhaul/service.	2/12/2020	Hours
	19087	Organise and sort fittings for rock breaker fitment. Fitted up and tested. Adjusted flow rates. Rock breaker will need servicing.	30/11/2020	Hours
	19086	Investigate UHF issues. Trimmed and reconnected aerial plug.	3/11/2020	Hours

Asset	W/O No	Description	Finished	Done Reading
		Adjusted track tension.		
	19085	Continue completing 1000hr service. Grease machine - ensure all points are greased. Test GPS - all systems oil. Clean out cab and complete pre hire paperwork.	29/10/2020	Hours
	19083	Check over and organise parts. Tidy wiring in cab. Repair box lid. Carry out 1000hr service - replace fuel filters missed at last service. Bring pre hire paperwork up to date.	28/10/2020	Hours
	19082	Segregate tilt bucket hoses.	28/09/2020	Hours
	19081	Carried out engine service - replace ripper boot, pin struck in ripper.	21/08/2020	Hours
	19080	Cleaned quick hitch solenoid valve.	29/06/2020	Hours
	19079	Carried out 250hr service.	23/06/2020	Hours
	19078	Replace teeth, topped up hydro oil.	6/04/2020	Hours
	19077	Tightened hammer fitting. Removed front windscreen door.	3/12/2019	Hours
	19074	Drain engine oil, drain coolant, fill cooler system with water, wash.	28/10/2019	Hours
	19076	Carried out 1000hr service. Replaced hydraulic filters, air filters - inner & outer, engine oil & filter, grease, final drive oil, slew box oil, pump drive box oil. Adjusted track. Removed stickers. Fit new stickers - MAAS and P number. Carried out paperwork on hire/site. Coolant flush, filled with CAT ELC. Fit heater hose taps.	28/10/2019	Hours