

Work Order History Report

Asset	W/O No	Description	Finished	Done Reading
P1022		Komatsu PC300-8 Excavator		
	194428	Remove and replace hydraulic hose on site	20/07/2026	Hours
	58847	GET changeout	6/05/2026	Hours
	60963	Pre hire repairs as per HME inspection, W/O 60690 IPAS removed Engine diagnosed to be injectors - not quoted. Replace injectors. Tracks were not quoted for - replace link sections as required. Replace hi-vis tape, wash, FULCRUM photos, Maas paperwork, topped up hyd oil, fit safety stickers as required Fit e-stop on LHS, removed rock guard bolts, replaced oil filter hoses, completed paperwork Assist with belly plate, removing ipas	30/04/2026	Hours
	56967	Replace GET 5719hrs	15/04/2026	Hours
	60529	Excavator - 500hr service 7434hrs	12/02/2026	7434 Hours
	60690	HME Inspection - Excavator 7429 hrs Quote #: Oil leak on rh side engine Bent groover LH Bucket repairs, bolt missing cutting edge	10/02/2026	Hours
	60610	February R&M Monthly WO: Pull pins out, remove snapped and rusted bolts, Clean face surfaces, tap holes, reinstall tension studs, inspect machine for leaks all oils	6/02/2026	Hours
	60062	January R&M Monthly WO: REZ OIL CHANGE OUT	31/01/2026	Hours
	59619	December Monthly R&M - Diagnose GPS not working, cable broken for ipas	31/12/2025	Hours
	58232	October R&M. Repair cracks in hitch bosses. Replace mud bucket cutting edge, assist Bailey with bucket repairs	17/12/2025	Hours

Asset	W/O No	Description	Finished	Done Reading
		Weld cracks on hitch and put gussets to the hitch to the bucket x 2		
	58043	Excavator - 1000hr service and repairs 7100hrs	8/11/2025	7100 Hours
	58943	November R & M Monthly WO: PIRTEK hose replacement. Replace UHF handpiece mount.	5/11/2025	Hours
	58021	September R & M - Replace safety latch pin and install lock bolts and check over machine	30/09/2025	Hours
	55975	AUGUST R & M Clean out TFO defect on machine & fix broken 2 way bracket Fault gps not working, replace gps cab;e. Install oring Leaking seal, took old fitting to Pirtek	17/09/2025	Hours
	57114	Excavator - 250hr service and repairs from to do list 6749hrs Replace hyd fittings, and e-stop	26/08/2025	6749 Hours
	55867	Excavator - 500hr service and to do list 6673hrs	26/07/2025	6673 Hours
	54698	Excavator - 250hr service 6366hrs	4/06/2025	Hours
	54301	Replace tilt hose VECTON 15W-40 Oil stock charge out Rez - replace tilt hose that has failed and test to ensure no leak	17/04/2025	Hours
	53324	Excavator - 2000hr service 5954hrs	2/04/2025	Hours
	53362	- Flashing light not working - Broken wire under cab liner	14/03/2025	Hours
	52829	Intermittent GPS fault. Replace sensor. Given the wrong sensor first time. Return to site and fit correct sensor.	24/02/2025	Hours
	51871	check over from hire and get ready for hire. ACEREZ	24/01/2025	Hours
	50111	HME Inspection - Excavator Diagnose and repair no start fault. Wash machine	23/01/2025	5773 Hours
	48245	Pre hire repairs as per HME inspection, w/o 48068 Weld mounts as required for GPS install.	13/11/2024	5735 Hours

Asset	W/O No	Description	Finished	Done Reading
		BACKCHARGE Replace cutting edge on mud bucket BACKCHARGE Repair/replace damaged belly guards and frame, BACKCHARGE Replace spider belly guards, straighten guard mounts, Clean cab Check and tag fire extinguishers Replace missing cab lights Fill washer bottle, replace wiper blade Straighten LH track frame step Grease machine Fit safety stickers as required Remove Maas stickers Replace hi vis tape as required 250hr service (separate w/o) Clean cooler pack Top up RH final drive Clean out battery box Tighten e stops Fit GPS system Fit tilt hitch		
48705		Capital Repairs - Supply & fit tilt hitch	18/10/2024	5731 Hours
48956		Excavator - 250hr service Hours: 5729 03/10/24	3/10/2024	Hours
48068		HME Inspection - Excavator Quote #: 189 Middle belly guards under track frame bent GET bucket still in orange.	6/09/2024	5727 Hours
17931		P1022, Pre hire repairs as per HME inspection. W/O 17747. 5507hr BACKCHARGE- Remove floor mat, clean cab, BACKCHARGE- Fit first aid kit BACKCHARGE- Straighten lip on B254 bucket BACKCHARGE- Wash machine Check and tag fire extinguisher Repair rear worklight on back of cab Fill washer bottle Replace wiper blades, clean glass Replace missing RH mirror Fit uhf bracket Grease machine Fit QR, Maas and thinksafe stickers Fit hi vis tape Clean cooler pack Replace all belts Check tensioner and pulleys while belts removed Repair oil leak on quick hitch cylinder (o ring)	17/06/2024	Hours

Asset	W/O No	Description	Finished	Done Reading
		Top up LHS final drive oil, check for leak Turn cutting edge on B254 bucket Clean out battery box Fulcrum photos Pre hire paperwork		
	17979	Excavator - 500hr service	13/06/2024	5507 Hours
	17747	HME Inspection - Excavator Quote #: 123	5/06/2024	5507 Hours
	16921	Diagnose/repair tracker not working - replace Repair bent grouser plate	27/05/2024	5490 Hours
	15133	Replace failed flashing light	12/04/2024	5300 Hours
	13025	asset inspection	22/03/2024	Hours
	15175	Hydraulic level topped up	22/03/2024	Hours
	4889	Excavator - 250hr service	12/12/2023	4754 Hours
	7333	Excavator - 1000hr service	8/12/2023	Hours
	5268	Minor R&M Remove / replace carrier roller	12/09/2023	Hours
	4926	Minor R&M Repair Bucket Grouser Bars / Domite Plow Bolts 4.08.23-10.08.23	31/08/2023	Hours