

Work Order History Report

Asset	W/O No	Description	Finished	Done Reading
P1027		Komatsu PC300-8 Excavator		
	194463	Pre Hire Repairs as Per WO194455 Operators Manual Trashed Back Charge Missing First aid Kit \$50.00 Back Charge Wash and cab Clean \$630.00 Back Charge Adjust Tracks \$52.50 Replace Missing Bally Plate Bolts \$105.00	3/08/2026	Hours
	194455	Off hire Bellambie (trazibat ?)	21/07/2026	Hours
	194128	July R&M Remove and replace remote oil filter lines due to leaking and perished done @8145 on 16/07/2026 17/7/26 hours 8145 remove and replace remote engine oil filter hoses, replace blown o ring on quick hitch lock cylinder	17/07/2026	8145 Hours
	194669	14.07.2026 supply 4 x Hensley style XS30 teeth and retainers	14/07/2026	Hours
	193926	June R&M No heater, founds hoses looped at engine, rejoin hose pressure test, found split coolant hose at back of cab. Run new heater hose fill with coolant and test	22/06/2026	Hours
	193323	Excavator - 2000hr service Repair/oil leak in hitch, replace o ring	18/06/2026	8003 Hours
	192997	GET CO: GET changed out on 7/05/2026 Remove and replace 4 x bucket teeth and adapters	7/05/2026	Hours
	60286	Pre hire repairs as per HME inspection, W/O 60140 Quick hitch cylinder to be resealed due to internal leakage Replaced batteries Reseal quick hitch cylinder Cleaned cooler pack Safety stickers Remove client stickers Tensioned tracks Replaced cutting edge bolt Seg tied hoses from rubbing	10/04/2026	Hours
	60140	HME Inspection - Excavator Quote #: 7805 hrs - Wash - Clean cab - Charge& load test batteries	15/01/2026	7805 Hours

Asset	W/O No	Description	Finished	Done Reading
		- Repair front window wiper - Grease machine - Put Gp bucket with machine if not ddr		
	59519	Excavator - 250hr service Top up hyd oil Clean out cooler pack Blow out air filter Top up water in batteries	5/12/2025	7776 Hours
	58038	Excavator - 500hr service	22/10/2025	7550 Hours
	57261	Excavator - 250hr service Clean GPS connection plugs and inspect wiring Refit pin & new locking bolt Test & Diagnose intermittent GPS faults	21/08/2025	7250 Hours
	57195	Replace GET. Southlakes. A1. Go to Southlakes measure for required edge. cut edge to suit. Grind all nuts off (mushroomed) replace cutting edge	20/08/2025	Hours
	54890	Pre hire repairs as per HME inspection. w/o 54841 Put on belly plates and spin tracks Weld the eye back onto the cylinder Fulcrum inspection, tension tracks, clean cab Fit GPS radio and check working	6/08/2025	Hours
	54819	CMC Lake Cowal, fit fire suppression.	24/06/2025	Hours
	54897	Excavator - 1000hr service	29/05/2025	Hours
	54841	HME Inspection - Excavator Quote #: 364. *Finish 6980hrs	13/05/2025	6980 Hours
	52658	Reseal Tilt hitch cylinder, check over. *Finish 6886hrs *Reseal tilt hatch cylinder. *Window washer. *Sort GPS. *Paperwork. *Pump up tracks. *Wash machine. *Fulcrum photos.	11/04/2025	6886 Hours
	53278	Excavator - 250hr service.	20/03/2025	6798 Hours
	52698	Seat has collapsed. Repair. River St. #If unserviceable, contact Pete - send pics.	20/02/2025	Hours

Asset	W/O No	Description	Finished	Done Reading
	52042	Excavator - 500hr service. 6,545hrs 29.01. River St Complete 6583hrs 05.02 Seat has come loose from base - repair.	14/02/2025	Hours
	50748	Replace damaged quickhitch hose at river st.	30/01/2025	Hours
	51463	Diagnose fuel filter light on - Fit new filter - Lean filler cap - Fix fuel sender plug	8/01/2025	6448 Hours
	50978	Weld on plates around GPS sensor on tilt hitch	9/12/2024	Hours
	50108	HME Inspection - Excavator	13/11/2024	6342 Hours
	17718	Repairs as per HME inspection, W/O 13123 wash machine clean cab repair lights and beacon repair wiper blades replace mirrors replace missing reverse camera repair/replace damaged hand rails repair/replace grease lines replace damaged safety stickers fit hi vis tape damaged grouser plates LHS damage to LH and RH lift cylinder oil tubes and hosing GP bucket pins bent bucket damage lip bent bolts missing mud bucket replace broken E stops x2 Broken front windscreen repair bent access steps on track frames repair bent track base in slew area repair bent access cover LHS drive motor replace bent grease line at slew bearing repair/replace underside of body both sides major damage replace broken washer bottle cap replace cab door impact damage repair windscreen protection guard replace missing catch hydraulic pump access door repair impact damage to counter weight repair bent access step diesel tank replace bent fire extinguisher bracket impact damage to underside of boom grind and pad weld replace damaged hosing ab bucket replace damaged /broken bolts in bucket tilt pivot retaining plate inspect weep at pump suction	17/10/2024	6307 Hours

Asset	W/O No	Description	Finished	Done Reading
		repair leak at AUX tap on boom worn teeth on GP bucket ? complete service 250h \$500 P&L clean radiator core fit fist aid kit top up hydraulic oil movement in tilt pivot 5mm Inspect repair leaking tilt cylinder cracked roller LHS Clean out battery box reseal bucket swing cylinders inspect chrome		
48556		Excavator - 250hr service Repair hyd oil leak and re-fill hyd tank.	20/09/2024	6305 Hours
13123		HME Inspection - Excavator Quote #: 97	25/05/2024	6277 Hours
9825		Diagnose and repair A/C at Carroll Quarry.	23/02/2024	Hours
3782		Supply and deliver water pump to site	1/08/2023	5465 Hours
18769		Carried out movement checks, mounted UHF hand piece holder, blow out all air cleaners, replaced and tightened bolts on GP's on bucket. Removed lift cylinders from boom, removed all hoses near foot pin, disconnected wiring. Replaced bushes in boom and cleaned frame. Capped all hydraulic lines. Drive franna and fit boom. Installed boom foot pin and shims, fitted all hoses, greased foot pin and topped up hydraulic oil, fitted bucket. Completed Cloncurry paperwork, tagged extinguishers, fitted pre start stickers. Fixed leak in tiltinh hitch area.	27/02/2023	Hours
18772		Removed hitch. Created defects list, checked fire extinguishers, checked e-stops, fixed work lights, finished assembling hitch cylinders. Removed damaged belly guards to be repaired, flushed cooling system and filled with CAT ELC, assembled tilting quick hitch - to be fitted to machine, Straightened belly guard bosses, fit belly guards. Replaced bucket cylinder rod end bush and seals, plumbed up tilt hitch, straightened bent cab door. Carried out pre hire and washed machine.	19/01/2023	Hours
18770		Cut out bent side, fitted new piece and fitted.	7/11/2022	Hours