

Work Order History Report

Asset	W/O No	Description	Finished	Done Reading
P1031		Komatsu PC200-8 Excavator		
	193401	Replace broken hydraulic hose at attachment - damage. Snapped ferrule.	26/08/2026	Hours
	194200	Replace broken tilt bucket bucket hose. (replaced by Jonsey) Supply bolts - Jonsey.	25/08/2026	Hours
	194325	Replace broken tilt bucket hose - damage. Invoice the job to A1. #Advised Rob Kinsella to ensure hose routed properly to avoid another broken hose.	24/08/2026	Hours
	194338	22.07.2026 replace damaged tilt cyl hyd hose - charge site, TC	22/07/2026	Hours
	194228	Excavator - 1000hr service	13/07/2026	Hours
	193677	Excavator - 250hr service	12/06/2026	6859 Hours
	192863	May R&M * Weld the spiders guard back on, drive back to Dubbo	8/05/2026	Hours
	192669	April R&M Replace tilt bucket coupler	30/04/2026	6687 Hours
	60966	Pre hire repairs as per HME inspection, W/O 60714 wash machine clean cab bucket repairs repair all belly guards and spider guards undercarriage repairs chains, sprockets and carrier rollers repair first aid compartment lid repair window washers (blocked line) replace hi vis as required fit pre start sticker wash out radiator replace tilt cylinder hoses x2 replace bolts in cutting edge wash out battery box replace emergency stop on cab fit fuel separator filter (on in bench) paint counter weight Hyd oil is black needs to be changed (took sample) 17.06.25 Belly guard (swivel) is completely missing 17.06.25 All boom & stick & quick hitch pins & bushes are completed flogged 17.06.25 Quick hitch looks bent 17.06.25 Main frame bent 17.06.25	8/04/2026	Hours

Asset	W/O No	Description	Finished	Done Reading
		Track chain & plate damaged 28/01 Paperwork Fulcrum on hire replaced damaged Remove and drill holes in rockguard		
	58324	October R&M repair e stop Fit window guard	12/02/2026	Hours
	60714	HME Inspection - Excavator Quote #: 6566 hrs - Track chains & plates bent/worn - Top rollers U/S rhs - E stop missing outside of cabin - Need to replace fuel separator filter - Fit new tilt hose	9/02/2026	6550 Hours
	60311	Accident damage to bucket hose. Uungala (reported by Heath Crockett) Replace hose	27/01/2026	Hours
	60147	Excavator - 500hr service 6545 hrs	21/01/2026	6545 Hours
	49345	Quick latch not releasing need to remove top pin to inspect further. Top pin is bent so need to cut and remove and replace with new one. Replacement pin ordered. Hours: 5570	31/10/2025	Hours
	56486	Pre hire 6244 hrs	23/07/2025	6244 Hours
	55622	Excavator - 2000hr service 6243 hrs	23/07/2025	6243 Hours
	55229	Excavator - 250hr service 6011 hrs	11/06/2025	6011 Hours
	54329	Diagnose loss of hydraulic implement functions. Repair lockout wiring - broken wire	16/04/2025	Hours

Asset	W/O No	Description	Finished	Done Reading
	51009	HME Inspection - Excavator Quote #: 262	11/12/2024	5686 Hours
	48615	Excavator - 500hr service	11/10/2024	5548 Hours
	20630	Replace leaking hydraulic hose on quick hitch Hours 5288	5/08/2024	5288 Hours
	49486	Replace cutting edge P1031	5/08/2024	Hours
	18785	Very small hydraulic leak from seal on tilt bucket arm.	31/05/2024	Hours
	16114	Excavator - 1000hr service	18/05/2024	5021 Hours
	13024	asset inspection	22/03/2024	Hours
	9553	Install tracker	16/02/2024	4668 Hours
	9038	Top up Hydraulic oil & check for any external leaks Hours: 4567	25/01/2024	4567 Hours
	18786	Repaired loose connections on horn.	8/01/2024	Hours
	8143	Excavator - 500hr service remove broken bolts from belly plates Repair horn Repair minor leaks around control valve Repair handrail	28/12/2023	4479 Hours
	5370	MINOR R&M 4228 Hours failed load roller	22/09/2023	Hours
	3831	Excavator - 1000hr service	26/07/2023	4021 Hours
	3122	July - Minor R&M	8/07/2023	
	18787	Carried out 500hr service.	27/02/2023	Hours
	18792	Carried out 250 hour service.	17/10/2022	Hours

Asset	W/O No	Description	Finished	Done Reading
-------	--------	-------------	----------	--------------