

Work Order History Report

Asset	W/O No	Description	Finished	Done Reading
P1126		Cat 745 ADT		
	194739	off hire inspection Pump out fuel Remove tailgate Reseal steer cylinder Remove 2 way clean cab Remove old client stickers Check for leaks Check all fluids	4/08/2026	Hours
	193597	June R&M Blown coolant hose. R&R clamps. Jump start Blown heat exchanger hose transmission coolers Remove and replace hose with new clamps. Fill with 60L of coolant Jump start truck and run up to temperature (test ok)	6/07/2026	Hours
	192843	May R&M Fill out oil samples Take off RHS wheel arch panel Swap over rear radiator op cover, one repair at JVC Grease fault	1/06/2026	Hours
	192234	April R&M Lagging supplied from Dubbo W/shop Remove steering cylinder rods and reseal.reinstall and test (test ok) Fill steering tank 20L of HYD 46 Steering cylinder rebuild and testing completed 8/04/2026 Fault 20/4/26 tidy up exhaust lagging for iTS inspection 24/4/26 coolant leak, split heater hose, get hose from Pirtek and replace on Tuesday 28th and fill with coolant 28/04/2026 repair blow heater hose.clamp and cable tie.fill with 40L of coolant. Run up and test truck (test ok)	30/04/2026	Hours
	192706	Cat 745 ADT - 250hr Service SWC, LH strut 23/02 Check trans oil hot & running, it is a long way over full cold safe start level- Scott Monitor Pos 3 has a shoulder split- Scott replace broken hinges on R/H cab compartment to refit lid- Scott	29/04/2026	12242 Hours

Asset	W/O No	Description	Finished	Done Reading
		Monitor HMU slight leak- Scott re seal Starter motor- Scott replace oring on Aux drive cover leaking on L/H front structure- Scott re seal Breather/tappet cover leaking- Scott replace Both mirror hinges that are broken R/H side, Workshop has stock- Scott Cab pin retainer loop missing L/H rear- Scott Monitor Steer cylinder weeping- Scott replace diff breather hose on front axle- Scott Broken/missing bolt in exhaust stack & other bolts loose- Scott replace R/H broken fender- Scott refit/replace circlip that has come off lower lift cylinder bearing R/H & L/H sides- Scott Front park brake pad worn more than the rear- Scott monitor Centre axle output yoke seal weeping- Scott Monitor L/H center suspension pad cracking around the top- Scott Replace R/H body mudflap- Scott Order required parts to carry out defect repairs Parts order 31/04/2026		
	192516	RE-INTRODUCTION TO SITE - MOOLARBEN - ANNUAL	21/04/2026	Hours
	192089	HME 12059.8HRS MCO	18/03/2026	12060 Hours
	191733	March Monthly R&M WO: Horn not working. Remove parts out of truck at w/s Fit used steering/ horn parts back into truck at w/S	15/03/2026	Hours
	191189	Cat 745 ADT - 4000hr Service and to do list 11945hrs 12015 hrs Replace drives side mirror hinges Repair radiator cover	6/03/2026	12015 Hours
	60050	February R&M Monthly WO: 11921 hrs -Prestart, travel to MCO find and replace coolant hose once able to gain access to truck 11921hrs 09/02 -Coolant leak from split hose, remove guarding and fan cowl, remove hose and order parts 11921hrs 10/02	12/02/2026	Hours
	60036	Cat 745 ADT - 250hr Service and to do list 11852hrs - repair wipers - repair grease fault	23/01/2026	11852 Hours
	59548	December R&M Monthly WO: -Replace engine oil drain Replace park brake pads Replace wiper washer motors 0312.	15/12/2025	Hours

Asset	W/O No	Description	Finished	Done Reading
	59794	Side mirror damaged	12/12/2025	Hours
	59008	Cat 745 ADT - 500hr Service/ to do list 11606hrs - service and complete to do list, order required parts LHF strut 17/09/2025 LH mirror arm broken 24/09/2025 Seat rails need replacing 01/10/2025 Window seals need replacing 02/10/2025 Auto retard locked on momentum traveling, down grades are slow and jerky 07/10 POS 2 strut compressed, oil discharge from centre diff, truck parked up 07/10 POS 5 minor split 05/11 Possibly missing cab pin 05/11	2/12/2025	11606 Hours
	58906	November Monthly R & M WO: Hyd oil leak Remove brake hose and take to pirtek	7/11/2025	Hours
	58062	October Monthly R & M WO MCO: 11394 hrs Diff 2 oil leak Remove drive shaft, remove bearing carrier strip down and order parts	28/10/2025	Hours
	57714	September R & M Monthly WO: Park brake fault, replace timer relay for after market seat/park brake switch	29/09/2025	Hours
	55453	NDT of all rims.	17/09/2025	Hours
	55820	JUNE R&M Parts 10934 hrs "LHS mirrors bracket hinges U/S Worn mirror bracket hinge Replace mirror bracket hinges Replace greaser	17/09/2025	Hours
	57511	Cat 745 ADT - 250hr Service and repair list 11278hrs	15/09/2025	Hours
	56724	August R&M Monthly work order: 11209hrs - oil leak on hoist hose from perished o ring, replace o ring and test. 11147hrs 08.08 - install new grease pump and harness 11152hrs 12.08 - Diagnose horn staying on CBM electrical 14/08 - Pos 2 strut low 11209hrs 29/08 - Replace valve, check oil height on strut and adjust to spec 30/08	31/08/2025	11209 Hours
	56141	Cat 745 ADT - 1000hr Service (kit from CCH assets stock in Mudgee) 10990hrs - change steer pins - change A frame bearings - adjust tyre pressures	9/07/2025	10990 Hours

Asset	W/O No	Description	Finished	Done Reading
		- repair both park lights in bonnet(replace bulbs and repair wiring for LHS bulb) - replace rod end steer bearings and seals - repair grease hose		
	55968	JULY R&M - 9541hrs Front a frame excessive movement, remove and replace 02/07 - remove and replace diff 1 A frame bearings 09.07 10990hrs	9/07/2025	Hours
	55814	Tyre change out Pos 3 and Pos 5 Side wall cuts Pos 3 is XXX, been repaired 3 times +R&M 10937hrs - put 3,5 on truck , torque to spec 350ftlb put retorque tag in cab -locate machine, re torque wheels, fit indicators 10953hrs	2/07/2025	10951 Hours
	55354	POS 3 tyre repair/ slow leak Remove tyre from P1138 and fit to pos 3 Send pos3 from P1126 to town for repairs and refit to P1138 10888hr	5/06/2025	10888 Hours
	55302	Damaged tyre CO Float back to Mudgee WS and remove Pos 1	28/05/2025	Hours
	55125	Found Pos 1 Lower Suspension Bearing U/S R&R -replace POS 1 strut -lower strut bearing has collapsed- bearing failure from wear and tear - remove strut, requires strut pins to be pulled out , had to use hydraulic puller to remove pins - on removal it was found the lower bearing bore was damaged, exchange suspension cylinder was fitted and damage cylinder sent back to Dubbo for bearing bore to be rcovered. - exchange cylinder was fitted with new pins, spacers and seals, oiled and gassed, tyre refitted.	28/05/2025	Hours
	53635	Cat 745 ADT - 250hr Service 10709hrs Prestart travel to MCO. Fit guard RHS, rewire E stop, temporary repair fiberglass fender Test grease system	16/04/2025	Hours
	54237	RHS wheel fender damaged, remove, repair and refit 10831hrs	15/04/2025	10831 Hours
	53612	Replacing POS 2 tyre -damaged MCO 10709hrs - remove and replace damaged tyre POS 2	26/03/2025	Hours
	52240	Cat 745 ADT - 500hr Service 10467hrs 10543hrs - inspected defects -park brake pads u/s - 3rd axle A frame u/s - front diff 1 unis u/s	13/03/2025	Hours

Asset	W/O No	Description	Finished	Done Reading
		- remove front unis and replace - remove park brake pads and free up caliper - fit park loratue? pads, free up caliper		
	53150	Low fuel pressure event code E198 Diagnose and repair 10625hrs	6/03/2025	Hours
	52786	Horn staying on, diagnose and repair 10572hrs	24/02/2025	Hours
		- locate maclire? and reset horn contacts		
	51223	Cat 745 ADT - 250hr Service. 10,250hrs -fill grease tank	8/01/2025	Hours
	49818	Cat 745 ADT - 2000hr Service Hours: 10037 10116 14/11/24 Repair and purge auto grease system	16/12/2024	Hours
	49905	CVA Agreement - Westrac	2/12/2024	Hours
	50205	Diff 2 a frame U/S remove and replace bearing Hrs: 10116	20/11/2024	Hours
	49509	Left hand mirror hinges cracked. Unable to lock in place. Remove and replace mirror bracket Temp repaired until brackets arrive from Vietnam factory. 10,008	24/10/2024	Hours
	20897	Remove and replace broken reverse camera Replace missing reverse light, repair wiring Remove and replace peeled off fleet ID sticker Park Brake applying whilst driving Replace rear asset decal. # possible site damage.	1/10/2024	9896 Hours
	21487	Transmission line hose adapter fitting leaking. Remove and replace o ring	6/09/2024	9827 Hours
	20906	Cat 745 ADT - 250hr Service	15/08/2024	9752 Hours
	20662	Bonnet lift tripping circuit breaker when trying to open up. Diagnose electrical fault in bonnet raise/lower circuit. Tested lift actuator motor & switch, both working correctly. Tested circuit harness, found to have a dead short in bonnet loft circuit. Traced & tested harness from cab along to bonnet, found section at fault. Cut out faulty section & replaced with new wiring. Tested circuit working correctly. Job complete.	7/08/2024	9717 Hours
	20401	Insp oil leaking onto exhaust at R/H/S of engine. Found new steering hose fitting leaking. Tightened fitting. Ran and checked, leaked fixed. Fabricate engine bay handrail Hours: 9690	31/07/2024	9690 Hours
	19670	Transmission change out - Westrac	16/07/2024	9644 Hours

Asset	W/O No	Description	Finished	Done Reading
	48611	Cat 745 ADT - 9,500hr Service	16/06/2024	9524 Hours
	14095	Hydraulic tank repairs. Repairs carried out without consultation or approval. Negotiated suitable invoice amount with Mudgee area manager - Nathan Ramsland. 9000hrs	21/12/2023	Hours
	7368	Articulated Dump Truck - 1000hr Service - WESTRAC BATHURST	3/12/2023	9059 Hours
	7251	Minor R&M Monday to Sunday 17/11/2023 Check parkbrake for serviceability Remove parkbrake from P190 Strap to pallet	17/11/2023	Hours
	7369	3 x DIFF LOCK MODIFICATIONS AS PER CAT SERVICE LETTER - WESTRAC BATHURST	27/10/2023	9038 Hours
	9230	Capital Repairs - Costs not covered by service letter - axle groups. Westrac Bathurst. Repairs carried out without consultation or approval. Negotiated suitable invoice amount with Bathurst customer coordinator.	27/10/2023	9038 Hours
	4929	Minor R&M Repair & Seal through shaft seal CVA monthly	31/08/2023	Hours
	51923	8000hr service	2/08/2023	8100 Hours
	428	A1 Earthworx - Fit cab pin replaced coolant hose, topped up coolant repaired grease line Speed limited by Westrac - 25km/h	16/03/2023	8088 Hours