

Work Order History Report

Asset	W/O No	Description	Finished	Done Reading
A1-416		Cat 20T Excavator		
	194809	Pre hire repairs as per Off hire inspection W/O 194682 BACKCHARGE - wash machine = 10hrs @ \$90 = \$900 reseal bucket cylinder replace batteries BACKCHARGE - clean cab = 1hr @ \$90 = \$90	10/09/2026	Hours
	194682	off hire inspection Disposal Oil leaks Quick hitch leak	13/08/2026	Hours
	192245	May R&M Replace leaking hose (A1 to replace). Diagnose and repair A/C not working. Replace fuse and repair wiring short found in the engine bay Go through list of defects and check required repairs for Lake Cargelligo	8/05/2026	Hours
	191938	Smashed Lower front cab glass - damage by operator. Lake Cargelligo.	6/05/2026	Hours
	192638	Excavator - 500hr service. One defect to assess - last on the task list. Question: Reverse camera working? Answer: FAIL Comment: Poor visibility	24/04/2026	12611 Hours
	192119	March R&M Repair camera Travelled out to inspect a/c, recovered gas, all seemed well. Suspected might be getting high head pressure at heat of day so took a little bit of gas out.	31/03/2026	12433 Hours
	191656	Excavator - 250hr service	5/03/2026	12211 Hours
	60890	February R&M Repair A/C - not cold. LAT320E VN: #A1416 Checked a/c, low on gas. Changed service valves, cleaned cabin filter and added correct quantity of gas - all good. A/C repairs. Clean blocked evaporator. #Cut hole at seat base to access and flush.	28/02/2026	12190 Hours
	60657	Excavator - 2000hr service	11/02/2026	12051 Hours

Asset	W/O No	Description	Finished	Done Reading
		Stick cylinder need reseal leaking 28/01 Cylinder pins bushes, H link pin bushes, movement monitor 28/01 Top up hyd daily 28/01		
	59503	January R&M Oil leak on stick cylinder- Reseal stick cylinder Bucket cylinder hose (still waiting on invoice, allocate to the next R&M WO)	22/01/2026	Hours
	60113	Excavator - 250hr service - Repair bent Wiper arm	15/01/2026	11892 Hours
	58846	November R&M Window blade fixed Fire extinguisher tagged and new bag Repair oil leak on boom - stick cylinder hose o'ring leaking. (Bendalls). Replace battery isolator	29/11/2025	Hours
	58415	Excavator - 500hr service 11435 hrs	24/10/2025	11435 Hours
	57868	October R&M. Diagnose and repair oil leak in quick hitch (relief cartridge leaking) Josh Bendall. Check relief valve by passing on quick hitch. Suspect quick hitch lock cylinder by passing internally. Remove and replace oring on fitting for quick hitch. Replace quick hitch lock cylinder.	30/09/2025	Hours
	56223	On hire inspection 11271hrs Pre hire inspection - change out stick cylinder - repaired LH cooler door, install new lock and latch - replace window assembly - carryout weed and seed and complete paperwork - replace broken emergency exit latch - repair broken kick rail	7/08/2025	11271 Hours
	56307	Excavator - 250hr service 11269hrs - carry out service - replace grease line - inspect pin retaining bolt must have been previously as no signs of being flogged out - replaced cab door latch	17/07/2025	11269 Hours
	54741	Supply and Fit GET and hardware to mud bucket - Travel to Stubbo, find GET and bolts in cycrid, replace GET, cut old bolts off	12/05/2025	Hours
	54151	Oil leak in quick hitch area, diagnose and repair. DAMAGE - Stubbo. 11002hrs	30/04/2025	Hours

Asset	W/O No	Description	Finished	Done Reading
		Prestart. Travel to stubbo. Oil leak in quick hitch. Found damaged fittings. Travel into underground hydraulics gulgong, get new fitting. Travel back to stubbo. Fit parts and test		
54495		GET Flip on Sieve bucket and Hardware change out 11053- travel to site and remove old bolts and GET - Flip GET, clean surfaces and put back on bucket. - put new bolts in and tighten with gun, go over bolts again with 3/4 rachet to ensure bolts are tight.	29/04/2025	11053 Hours
54083		Excavator - 1000hr service #Stick cylinder re-seal kit ordered on this job. 11053hrs - Temporary repair on hydraulic sensor wires - Cab door latches but new latch ordered - Grease line ordered - Work light has been ordered	28/04/2025	11053 Hours
53960		HME Inspection Stubbo 10969.5 HRS	7/04/2025	10970 Hours
53339		"Diagnose and repair stalling fault Replace failed fuel pump" 10883hrs - test machine low fuel rail pressure code, check rail pressure sensor, tested ok - test electric fuel supply pump and found faulty, replaced and tested ok	14/03/2025	10883 Hours
53230		Supply quick coupler fittings	10/03/2025	Hours
52021		Quick hitch oil leak, relief system pressure, remove hose and fitting, replace blown o-ring Hours: 10758	30/01/2025	Hours
51899		Replace failed track roller (Mudgee stock) 10747hrs	24/01/2025	Hours
51672		"machine shutting down alternator only charging at 10.4 volts replace alternator " 10747hrs	22/01/2025	Hours
51730		Excavator - 250hr service 10748hrs	20/01/2025	Hours
49953		Excavator - 500hr service	25/11/2024	Hours

Asset	W/O No	Description	Finished	Done Reading
		Hours: 10520 COMPLETE		
	49322	Fit and test hammer	14/10/2024	Hours
	48525	Turn cutting edge on B88	19/09/2024	Hours
	21472	HME Inspection - Excavator. #MUST NOTE DAMAGE AND GET WEAR ON THE HME. Fulcrum. Quote #: 198 Re-seal loose fittings on stick for vibe Wash machine, shovel/chisel undercarriage. Clean cab.	6/09/2024	Hours
	21163	Replace hoses on Vibe Plate Replace washer bottle	26/08/2024	Hours
	20515	Excavator - 250hr service. 10250hrs #SERVICE KIT IN THE MUDGE PARTS AREA. - Repair starter hyd lock lever	23/08/2024	Hours
	21081	Repair Defects	21/08/2024	Hours
	20165	Coolant leak at cylinder head to water pump pipe. Change coolant. Diagnose quick hitch leak found fitting was loose and seal perished - removed & replaced Refit seat cover Install rotating beacon Straighten RH cab light cover Tighten clamp on header tank Tighten bolts on belly plate under cab Replace exhaust tip Hours: 10326 26/07/24	26/07/2024	Hours
	18672	HME inspection, could not get hours due to breakdown.	8/07/2024	Hours
	18578	DIAGNOSE & REPAIR STARTING FAULT Check wiring for tracker - not recording hours	8/07/2024	Hours
	48039		27/06/2024	Hours
	47899	TORQUE TRACK BOLTS 180DEG, TURN GROUZER PLATES, RESEAL BOOM TO STICK CYLINDER, TENSION TRACKS, FIT FRONT WINDOW, CHANGE FINAL DRIVE OIL, PUT TRACKS BACK ON, RE-BUILD L/H ADJUSTER, UNDERCARRIAGE RE-BUILD - 32949,31195,32948,34584,34721,32947,34583,32946,34719 -ALEX, ABBY, BOWEN, PETER	17/05/2024	Hours

Asset	W/O No	Description	Finished	Done	Reading
	47717	2000hr Service	14/05/2024	10136	Hours
	47875	UNDER CARRIAGE REBUILD, INSTALL GROUSER PLATES ON L AND R CHAINS (BOLTS NOT TORQUED), RE-ASSEMBLE TRACK ADJUSTERS - 32943,34717,32829 - ALEX, PETER, FRANK	10/05/2024		Hours
	47807	CLEAN UP NEW CHAINS, GROUZERS, BOLT DOWN NEW NUTS AND BOLTS, UNDER CARRIAGE REBUILD, CLEAR GROUZER PLATES - 34577,32934,34576,32153,32149,30984 - BOWEN, ALEX, DAVID, RORY	8/05/2024		Hours
	47750	STRIP UNDERCARRIAGE, REASSEMBLE SLIP JOINT AND FINAL, REMOVE TRACKS - 32139,32140,33332,33330,33331,32142 - DAVE, JAYSON	29/04/2024		Hours
	47683	SET-UP PRESS AND PRESS OLD PIECES OF PIN OUT OF TRACK, TRACK THE CHAIN BACK ON PROPERLY, PRESS NEW PIN AND SEALS BACK IN - 34556 - BOWEN	16/04/2024		Hours
	47687	INSPECTION FOR SERVICE/LIST PROBLEMS - 30945 - RORY	9/04/2024		Hours
	47608	RE-INTRODUCTION TO SITE - MOOLARBEN - ANNUAL	28/03/2024		Hours
	47571	SIEV BUCKET REBUILD, INSPECT TRACK - 32019,32020,32022,34533,31993,33403,33405 - 22.3.2024 - WILL, DAVID, BOWEN	22/03/2024		Hours
	47539	SIEV BUCKET REBUILD - 32018,32014,32015,32016,32017 - WILLIAM	15/03/2024		Hours
	47527	DIAGNOSE A/C FAULT - FAILED SENSORS - KEEVILS	13/03/2024	10072	Hours
	47180	250hr Service, REPLACE CUTTING EDGE, CHECK BUCKET TEETH, REPAIR UHF MOUNT, CHECK A/C - JACK	5/03/2024	10035	Hours
	46957	TIGHTEN UP LOOSE HOSE ON TILT BUCKET, JUMP START - 0051 - JACK	11/12/2023	9642	Hours
	46917	REPLACE HYD TANK O-RING, REPLACE CABIN FILTER COVER, REPLACE BEACON, REMOVE & REPLACE HEADLIGHT - 25330, 28942 - RORY, ALEX	6/12/2023		Hours
	46656	500hr Service, REPAIR TRAVEL ALARM, REPAIR R/H E-STOP, REPAIR DOOR LATCH, REPLACE MISSING PIN ON HITCH PIN - JESSE LLOYD	23/11/2023	9612	Hours
	46736	FIT HOSE FOR BUCKET CYLINDER - 0093 - DANNY	13/11/2023		Hours
	46745	CHANGE OUT BUCKET CYLINDER - 0092 - DANNY	10/11/2023		Hours
	46699	STRIP DOWN HYD CYLINDER READY FOR RE-BUILD - 31732 - JAYSON	7/11/2023		Hours
	46603	REMOVE BROKEN H-LINK & BENT CYLINDER AND SWAP WITH 414 - 0082 - DANNY	24/10/2023		Hours
	46602	REMOVE & REPLACE ENGINE ECM - 0076, 3 - DANNY, JACK	16/10/2023		Hours
	46319	REPLACE SEAT, REPLACE WATER/FUEL SENSOR, DIAGNOSE ENGINE FAULT - FAULTY ECM - 0054, 93 - DANNY, JACK	30/08/2023	9474	Hours
	46275	FIT FINAL DRIVE ASSY, TRAVEL MOTOR & VALVE BODY, JOIN TRACK, FILL WITH OIL, TEST - 89 - JACK	23/08/2023	9462	Hours
	46237	REMOVE OUTER GEAR RING & BEARINGS, CLEAN SPINDLE & TORRIE RING GROOVE, CLEAN UP NEW HUB & FIT OLD BEARINGS, FIT DUO SEALS, FIT HUB TO SPINDLE, MEASURE CLEARANCES FOR PRE-LOAD SHIMS, BOLT	18/08/2023		Hours

Asset	W/O No	Description	Finished	Done	Reading
		RETAINER DOWN, REBUILD & RESEAL FINAL DRIVE, TORQUE ALL BOLTS TO SPEC, ADJUST BEARING PRE-LOAD - 29005, 29007, 28478 - DAVID, ALEX			
	46178	DISASSEMBLE FINAL DRIVE TO ASSESS PARTS REQUIRED - 28277, 28691 - BOWEN, DAVID	8/08/2023		Hours
	46118	TOP UP LEAKING FINAL DRIVE - 0042 - DANNY	31/07/2023		Hours
	46082	REPAIR DAMAGED RETAINER PIN, FIT NEW RETAINER - 39 - DANNY	25/07/2023	9422	Hours
	46002	REPLACE MISSING QUICK HITCH RETAINER PIN, DIAGNOSE ENGINE SHUTTING DOWN WITH ECM & WATER SEPERATOR FAULT, REMOVE SENSOR & CLEAN - 0036 - DANNY	19/07/2023	9396	Hours
	45965	RE-INSTALL BUCKET PIN & FIT NEW BOLT - 72 - JACK	14/07/2023	9376	Hours
	45964	FIT NEW QUICK HITCH - 0033 - DANNY	12/07/2023		Hours
	45730	REGISTRATION RENEWAL - ANNUAL	26/06/2023		Hours
	45773	REMOVE SNAPPED DOG BONE - 29600, 28503 - DAVID, RORY	20/06/2023		Hours
	45634	250hr Service, REPAIR OIL LEAK ON TILT BUCKET, PUMP UP L/H TRACK, REPLACE MISSING BOLTS IN PUMP ROOM - DAVE, JACK	5/06/2023	9307	Hours
	45590	DIS-ASSEMBLE FINAL DRIVE & ASSESS, REBUILD FINAL DRIVE & RE-FIT, ADJUST TRACK TENSION & TEST FOR LEAKS - 29531, 29534, 27581, 26563, 29552 - DAVID, BROCK, ALEX, JB MECHANICAL	25/05/2023		Hours
	45495	DIAGNOSE OIL ON TRACKS - R/H FINAL LEAKING FROM DUO SEAL (SEAL COMPLETELY FAILED) - 29518 - DAVID	12/05/2023		Hours
	45928	REPAIR TRACK ROLLER & BEACON - JB MECHANICAL	2/05/2023		Hours
	45456	SWAP BUCKETS BACK OVER WITH 417 - 26287 - DAVID	1/05/2023		Hours
	45380	REPLACE BOTH FRONT CARRIER ROLLERS, REPAIR OIL LEAK ON TILT BUCKET AND FIT, CLEAN & INSPECT CRACK ON TOP OF STICK, GREASE MACHINE - 51 - JACK LEESON	5/04/2023		Hours
	45272	RE-SHIM & RE-BUSH QUICK HITCH TO STICK - 0014, 27691 - DANNY, PETER	4/04/2023		Hours
	45134	1000hr Service - 0014, 26511 - DANNY, ALEX	4/04/2023	9109	Hours
	44730	FIT UHF HANDPIECE HOLDER, REMOVE & REPLACE ENGINE HATCH STRUT, REMOVE & REPLACE REVERSE BUZZER, FIT EMERGENCY EXIT STICKERS - 26752 - PETER	21/12/2022		Hours
	44663	RE-INTRODUCTION TO SITE - MOOLARBEN - ANNUAL	16/12/2022		Hours
	44807	FIT EXHAUST LAGGING - ADVANCE GLOBAL	8/12/2022		Hours
	44629	MINE SPEC - FIT SAFETY STICKERS, FIT ID NUMBER, FIT REFLECTIVE TAPE, INSPECT - 26827 - BEN	8/12/2022		Hours
	44555	FIT NEW TFO TRACKER, MINE SPEC FOR SITE - FIT MINE STICKERS, INSPECT FIRE EXTINGUISHER, REPAIR WIRING, CONDUIT BATTERY & GPS CABLES, RE-TIGHTEN BUCKET EDGE, INSPECT HORN & FLASHING LIGHT - 26813, 26814, 26815 - BEN	25/11/2022		Hours

Asset	W/O No	Description	Finished	Done	Reading
	43977	250hr Service - CHRIS	7/09/2022	8801	Hours
	44157	SEAL IN RETAINER COLLARS & GREASE HAMMER - 21644 - PETER	6/09/2022		Hours
	44067	REPAIRS - REPLACE MISSING BOLTS ON CUTTING EDGE ON GP BUCKET - BEN	22/08/2022		Hours
	43970	REPAIRS - REPAIR GREASE NIPPLES ON GRABS - SPIDER	5/08/2022		Hours
	43962	REMOVE TILT BUCKET WITH WORN HITCH, CHANGE HOSES OVER TO RECONDITIONED BUCKET & FIT TO MACHINE, TEST OPERATION - 24315 - DAVID	3/08/2022		Hours
	43854	REPLACE PINS, REBUSH & REASSEMBLE TILT BUCKET, REPLACE BUCKET TEETH, REPLACE HOSE & FITTINGS ON BUCKET - 22304, 22309, 21707, 22314 - TIM, BEN	15/07/2022		Hours
	43821	REPLACE TILT PIN BOSSES ON BUCKET - 0926 - BCB ENGINEERING	8/07/2022		Hours
	43731	REGISTRATION RENEWAL - ANNUAL	27/06/2022		Hours
	43571	500hr Service, REPLACE FIRE EXTINGUISHER, REPAIR FRONT WINDOW SEAL, REPAIR MAIN PIN ON MUD BUCKET, CHECK FOR LEAKING TRACK ROLLER - ALEX	21/06/2022	8499	Hours
	43542	HARD FACE TILT BUCKET, REMOVE PINS ON ATTACHMENT, LINE BORE QUICK HITCH - 0718, 0719 - BCB ENGINEERING	14/05/2022		Hours
	43460	REPLACE CUTTING EDGE & BOLTS ON TILT BUCKET, REMOVE & REPLACE TILT CYLINDER BUSHES - 24905, 24643 - DAVID, PETER	5/05/2022		Hours
	43431	SWAP OUT PIVOT PIN BOSSES ON TILT BUCKET - BCB ENGINEERING	29/04/2022		Hours
	43143	250hr Service - BEN	12/03/2022	8226	Hours
	43189	REPAIR FINAL DRIVE & INSTALL, TEST FINAL DRIVE, INSTALL TRACK & TENSION - 24222, 23490 - CHRIS, BEN	11/03/2022		Hours
	43158	REPAIR L/H FINAL DRIVE LEAK - 23484, 24217 - BEN, CHRIS	4/03/2022		Hours
	43120	DIAGNOSE FINAL DRIVE OIL LEAK - 24512 - DAVID	25/02/2022		Hours
	42982	REPLACE & ADJUST L/H ENGINE BAY DOOR HANDLE - 23579 - DAVID	7/02/2022		Hours
	42848	REMOVE TILT BUCKET-BUCKET PIN HANGING OUT, STRIP DOWN & INSPECT ALL PARTS - 23634, 23286 - PETER, CHRIS	18/01/2022		Hours
	42790	REPAIR CAB DOOR LATCH, REPLACE BOTH BATTERIES, REPLACE WINDSCREEN - 23540, 23541, 20795, 20796 - DAVID, ALEX	6/01/2022	8030	Hours
	42470	2000hr Service, CLEAN COOLER OUT, DEGREASE & CLEAN PUMP ROOM, DEGREASE & CLEAN QUICK HITCH, DISASSEMBLE QUICK HITCH CYLINDER, CLEAN THREADS & APPLY LOCTITE TO PISTON BOLT AND TIGHTEN, RE-ASSEMBLE & TEST - 23616, 23531, 23534, 23535, 23617, 23620, 20901 - PETER, DAVID, TIM	30/12/2021	8029	Hours
	42788	JUMP START ONSITE - 20782 - ALEX	20/12/2021		Hours
	42459	JUMP START ONSITE - 20849 - DAVID	1/11/2021	7781	Hours

Asset	W/O No	Description	Finished	Done Reading
	42372	REPAIR BUCKET - REMOVE L/H TILT CYLINDER, DRILL OUT, TAP NEW THREAD, FIT NEW ELBOW, REASSEMBLE CYLINDER, ROTATE CUTTING EDGE & REPLACE ALL BOLTS & NUTS, CLEAN ALL SURFACE AREA OF RUST, REPAIR BUCKET TILT STOPS - 20828, 20721, 20832 - DAVID, ALEX	22/10/2021	Hours
	42159	250hr Service - 18985, 18991- CHRIS	1/10/2021	7627 Hours
	42016	UNBLOCK GREASE NIPPLES, GREASE QUICK HITCH, REPLACE CUTTING EDGE, ADJUST TRACKS, GREASE BOOM, REPLACE BATTERIES, CLEAN MUD FROM SIDE COMPARTMENT - 18938, 18939, 10480, 18852, 18854 - CHRIS, TIM, BLAKE	27/08/2021	Hours
	41841	REPLACE HYD HOSE, FILL HYD OIL - 19862 - GABI	22/07/2021	7439 Hours
	41560	500hr Service - GABI	5/07/2021	7375 Hours
	41592	REGISTRATION RENEWAL - ANNUAL	22/06/2021	Hours
	41547	DIAGNOSE/SET UP HYDRAULICS FOR AUGER DRIVE - 10370 - BEN	1/06/2021	Hours
	41449	REPAIRS - INSPECT L/H TRACK BEING PUMPED OUT - JOHN	14/05/2021	Hours
	41372	REPLACE WATER PUMP, RE-FILL COOLANT, TEST - 19599, 10343 - NATHAN, BEN	3/05/2021	Hours
	41345	DIAGNOSE COOLANT LEAK, REMOVE WATER PUMP & INPSECT - 10336, 10339 - BEN	29/04/2021	Hours
	41286	DIAGNOSE/TEST GPS SYSTEM FAULT - 10333 - BEN	24/04/2021	7155 Hours
	41256	REPAIR BUCKET TILT SENSOR HARNESS, TEST/DIAGNOSE BUCKET SENSOR WIRING, FIT NEW CABLE TO BUCKET SENSOR, TEST & REPAIR MUSHROOM HARNESS, TEST HARNESS FROM MUSHROOM TO CONTROL SCREEN, TEST/INSPECT ELECTRICAL CONNECTIONS - 10318, 10319, 10322 - BEN	16/04/2021	Hours
	41230	REPAIR GPS CABLES/PLUGS - 10308 - BEN	9/04/2021	Hours
	41179	IDENTIFY & REPLACE MISSING BUCKET TOOTH - 20395 - BEN	25/03/2021	Hours
	41121	DIAGNOSE & REPAIR MOVEMENT ALARM, REPLACE SEAT BELT, REMOVE & REPLACE HAND RAIL - 20379, 0191 - BEN, BCB	19/03/2021	Hours
	40971	250hr Service, REPLACE BULBS, FILL HYD OIL, CLEAN FUEL TANK FILTER, REPAIR DAMAGED COUNTER WEIGHT - 18513, 10205 - GABI, JOHN	13/03/2021	7063 Hours
	40252	1000hr Service, DIAGNOSE & REPAIR LEAKING HYD TANK, RE-SEAL HYD CYLINDER, REPAIR LEAKING R/H TRACK ROLLER, CHECK TILT BUCKET, CHECK BELLY PLATES - 20305, 20306, 20307, 22756 - BEN, KELDAN	31/12/2020	6778 Hours
	40854	REPAIR BUCKET - 0039, 0099 - BCB ENGINEERING	30/12/2020	Hours
	40500	REPAIRS - REPLACE FIRE EXT STRAPS - JOHN	4/12/2020	Hours
	40366	REPLACE TEETH ON GP BUCKET, REPAIR OIL LEAK - 20021 - TIM	20/11/2020	Hours

Asset	W/O No	Description	Finished	Done Reading
	39931	250hr Service, CHECK/REPAIR REVERSE BEEPER, GREASE TRACK, CHECK FIRE EXTINGUISHER - JOHN	19/10/2020	6421 Hours
	40086	REPAIRS - REPLACE BUCKET TEETH, CHECK CENTRE PIN ON TILT BUCKET, TIGHTEN CUTTING EDGE BOLTS - JOHN	12/10/2020	Hours
	39872	CHECK FIRE EXTINGUISHERS - TOTAL FIRE SOLUTIONS	25/08/2020	Hours
	39494	500hr service, REPLACE WINDOW, REPAIR HITCH LEAK - JOHN	21/08/2020	6074 Hours
	38611	250hr service	25/06/2020	5734 Hours
	39277	REGISTRATION RENEWAL - ANNUAL	22/06/2020	Hours
	38917	REPLACE ENGINE OIL PIPES TO FILTER, DIAGNOSE FAULTY REVERSE ALARM, GREASE TILT BUCKET - 17449 - JOHN	16/04/2020	5310 Hours
	38617	REMOVE & REPLACE FRONT WINDOW GLASS, REPAIR GPS, REPAIR OIL LEAK IN QUICK HITCH, GREASE TILT BUCKET, REPAIR REAR CAMERA - 18383, 18099, 17407 - CHRIS, JOHN	25/02/2020	5076 Hours
	38693	INSPECT HYD LEAK FROM BUCKET, ADJUST HOSE FITTING, INSPECT TILT BUCKET CENTRE PIN TO GREASE - 18152, 18155 - DANNY	11/02/2020	Hours
	38480	FIT UP GPS SYSTEM, DIAGNOSE & REPAIR FAULTS, CHANGE BOOM LIGHT, REPAIR SENSORS IN CAB, GREASE - 19128, 91921 - BEN, JARROD	30/01/2020	Hours
	38274	REPAIRS - GREASE TILT BUCKET, COMPARTMENT DOOR ALIGNMENT - STEVE	3/01/2020	Hours
	38157	2000hr service - WESTRAC	23/12/2019	4840 Hours
	37724	250hr service, REPAIR TURN BUCKET CUTTING EDGE	16/10/2019	4488 Hours
	37601	REPAIRS - SEAT - STEVE	6/09/2019	Hours
	37274	500hr service	12/08/2019	4161 Hours
	37251	REPAIRS - SEAT, LEAKING RAM ON QUICK HITCH, GREASE NIPPLES - STEVE	5/07/2019	Hours
	37544	REGISTRATION RENEWAL - ANNUAL	27/06/2019	Hours
	37221	REPAIR SIEVE BUCKET, FIT GPS - 76926, 17252 - JOHN, BEN	27/06/2019	Hours
	36912	REPLACE WINDOW - 17096 - RYAN	10/05/2019	3813 Hours
	36372	250hr service	7/05/2019	3813 Hours
	35851	SET UP GPS, REPLACE BATTERY - 11252 - J HODGES	12/11/2018	Hours
	35374	1000hr service	9/11/2018	3425 Hours
	35791	GPS-11244/11409/11243 J.HODGES R.INNES	6/11/2018	Hours

Asset	W/O No	Description	Finished	Done Reading
	35829	FIT GPS, MAKE BRACKETS-11242 J.HODGES	2/11/2018	Hours
	35772	FIT GPS-11238/11237 J.HODGES	1/11/2018	Hours
	35760	FIT GPS-11236 J.HODGES	30/10/2018	Hours
	35659	HYD OIL AND CLEAN-11169 C.DARCEY	16/10/2018	Hours
	35219	250hr service	31/07/2018	2994 Hours
	35014	500hr service	15/06/2018	2837 Hours
	35025	REPAIR WINDSCREEN-REPAIR TO BOOM- 16587- K BOUCHER 12053- J HODGES	14/06/2018	Hours
	34845	REPAIRS TO EXCAVATOR DOOR- 16706- D JACKSON	17/05/2018	Hours
	34659	250hr service	4/04/2018	2625 Hours
	34175	2000hr service	7/02/2018	Hours
	34479	QUICK HITCH REPAIR- 16826- B SWARBRICK	5/02/2018	Hours
	34390	REPAIR OIL LEAK- 10582- J HODGES	23/01/2018	Hours
	34319	REPAIR LATCH HANDLE- 14287- B SWARBICK	17/01/2018	Hours
	34313	FITTED LOCKING CYCLINDER- 10756- J COLLINS	10/01/2018	Hours
	34288	REPAIRS TO QUICK HITCH- 14280- 5/1/18- BEN SWARBRICK	5/01/2018	Hours
	33725	250hr service	13/11/2017	2135 Hours
	33959	BLOW CAB AND AIR FILTERS OUT, ROTATE CUTTING EDGE ON TILT BUCKET - JASON COLLINS - 10704	13/11/2017	Hours
	33602	INSPECT RIPPER BOOT AND HITCH - JASON COLLINS - 16319	20/09/2017	Hours
	33398	500hr service	15/09/2017	1876 Hours
	33153	250hr service	14/07/2017	1602 Hours
	32822	CHANGE FITTING TO TILT BUCKET, PAINT GRAB HITCH AND AROUND HITCH, CLEAN OFF BUILD UP ON BOOM - JASON COLLINS 15772	8/05/2017	Hours